

# Local Notice to Mariners for District 14 03/11/2025

## Ala Wai Boat Harbor

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ala Wai Boat Harbor Channel Range Front Light	29100	Status Unreported	PA
Ala Wai Boat Harbor Channel Range Rear Light	29105	LT EXT	PA
Ala Wai Boat Harbor Channel Buoy 3	29110	Status Unreported	PA
Ala Wai Boat Harbor Channel Buoy 4	29115	OFF STA/SINKING	PA
Ala Wai Boat Harbor Channel Daybeacon 6	29125	DAYMK DMGD	PA
Ala Wai Boat Harbor Channel Daybeacon 8	29135	DAYMK DMGD	PA

## Barbers Point

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barbers Point Harbor Entrance Channel Lighted Buoy 2	29651	SINKING/TRLB	FD
Barbers Point Harbor Entrance Channel Lighted Buoy 3	29651.5	LT EXT	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barbers Point Anchorage Area Bravo Tank Terminal Lighted Buoy A	29600	LT EXT	PA
West Beach Marina Light 2	29656	LT EXT	PA

## Hickam Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hickam Harbor Channel Light 6	29365	BUOY DMGD	FD

## Hilo Harbor

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Island Of Hawaii - Hilo Harbor/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	HI ISLANDS - HAWAII – WAILOA BASIN SHOALING There has been a report of increased shoaling at the entrance to Wailoa River. The shoaling is most severe between Wailoa Basin Channel Lights 1 and 2 (Light List numbers 28120 and 28125) and at low tides. All mariners are advised to use caution when transiting the channel. Reported by: Wailoa River and Reeds Bay Boating and Users Association	Lat: 19° 43' 21" Lon: -155° 04' 13"

## Honolulu Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Honolulu Harbor Entrance Lighted Buoy H	29175	SINKING/TRLB	FD

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Honolulu Harbor Buoy 10	29230	DISCONTINUED FOR DREDGING	FD

## Island Of Hawaii

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ka Lae Light	28140	LT EXT	FD

### Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Ka Lae Light	28140	WATCHING PROPERLY	FD	2025-03-10

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Honolulu, Territorial Sea - Island Of Hawaii/General/Hazards To Navigation/Wrecks	Hazards To Navigation	A wreck is reported off South Point in position 18-92.71N 155-68.34W approximately 100 ft from the cliff resting on the ocean floor in about 35 ft of water. All mariners are to proceed with caution.	Lat: 18° 55' 35" Lon: -155° 41' 08"
------------------------------------------------------------------------------------------	-----------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------

## Kahului Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kahului Harbor Entrance Range Front Light	28340	LT IMCH	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kahului Boat Ramp Buoy 1	28381.100000000002	MISSING	PA
Kahului Boat Ramp Buoy 2	28381.2	MISSING	PA
Kahului Boat Ramp Buoy 3	28381.3	MISSING	PA
Kahului Boat Ramp Buoy 4	28381.4	MISSING	PA
Kahului Boat Ramp Buoy 5	28381.5	MISSING	PA
Kahului Boat Ramp Buoy 6	28381.600000000002	MISSING	PA
Kahului Boat Ramp Buoy 8	28381.8	MISSING	PA
Kahului Boat Ramp Buoy 9	28381.9	MISSING	PA

## Kalihi Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Keehi Lagoon Barge Turning Channel Range Front	29315	REDUCED INT	PA

## Kaneohe Bay

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kaneohe Bay Channel Daybeacon 5	28700	DAYMK IMCH	FD

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Honolulu, Territorial Sea - Kaneohe Bay/General/Hazards To Navigation/Hazards	Hazards To Navigation	Oscilla Power will install the Triton-C Wave Energy Converter (WEC) at the WETS site, off of Marine Corps Base Hawaii. This installation consists of 3 subsurface buoys, and 1 surface buoy. All mariners should keep at least 500 feet away from position 21° 27.942'N 157° 45.039'W. The subsurface buoys are at water depths noted below. The AB subsurface float is at a depth of -2ft which poses a collision risk to vessels of all drafts. All subsurface floats are marked with an orange hard float and flasher. AB: 21-27.9167'N / 157-45.0475'W MC: 21-27.9586'N / 157-45.0593'W MK: 21-27.9489'N / 157-45.0081'W WEC: 21-27.9419'N / 157-45.0362'W	Lat: 21° 27' 55" Lon: -157° 45' 02"
Sector Honolulu, Territorial Sea - Kaneohe Bay/General/Naval Activity/Military Operations	Naval Activity	Military amphibious and search and rescue operations may be underway at any time, day or night, within Kaneohe Bay in the vicinity of 21-26-06.83N/157-46-11.00W and 21-26-45.00N/157-46-55.00W (approximately .5 NM south of Mokapu Peninsula). Support surface craft will be equipped with appropriate day/night signals and markings and can be reached on VHF-Ch 82. In the interest of safety, it is requested that all vessels that use Sonar contact Water Front Operations on VHF-Ch 82A or by phone at (808) 257-2941 to avoid injury to divers that may be in the area.	

## Kauai Island

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Makahuena Point Light	29850	LT IMCH	FD

### Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Makahuena Point Light	29850	WATCHING PROPERLY	FD	2025-03-10

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kikiaola Boat Harbor Range Front Light	29900	DAYMK DMGD	PA
Kikiaola Boat Harbor Range Rear Light	29901	DAYMK DMGD	PA

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Honolulu, Territorial Sea - Kauai Island/General/Naval Activity/Military Operations	Naval Activity	The following area is established as a safety zone during launch operations at PMRF, Kauai, Hawaii: The waters bounded by the following coordinates: (22°01.2' N, 159°47.3' W), (22°01.2' N, 159°50.7' W), (22°06.3' N, 159°50.7' W), (22°06.3' N, 159°44.8' W). (Datum: OHD) The above safety zone will be activated during launch operations at PMRF, Kauai, Hawaii. The Coast Guard will provide notice that the safety zone will be activated through published and broadcast local notice to mariners prior to scheduled launch dates. The area described of this section will be closed to all vessels and persons, except those vessels and persons authorized by the Commander, Fourteenth Coast Guard District, or the Captain of the Port (COTP) Honolulu, Hawaii, whenever Strategic Target System (STARS) vehicles are to be launched by the United States Government from the PMRF, Barking Sands, Kauai, Hawaii. The general regulations governing safety zones contained in 33 CFR 165.23 apply. Nomenclature changes to part 165 appear by USCG-2006-25556, 72 FR 36328, 36329 preview citation details, July 2, 2007 and by USCG-2018-1049, 84 FR 7813, Mar. 5, 2019.	
Sector Honolulu, Territorial Sea - Kauai Island/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	Intermittent missile firing operations are conducted by the Pacific Missile Range Facility (PMRF), Barking Sands, Kauai, in the Whiskey 188 (W-188) operating area. Operations are conducted periodically throughout each week in an area bound by the following coordinates: 22:00N/159:51W, 22:00N/160:00W, 22:04N/160:06W, 21:59.5N/160:21W, 22:05N/161:35W, 22:45N/161:25W, 22:56N/161:49W, 23:34N/161:18.6W, 23:57N/160:41W, 25:41N/161:36W, 26:00N/159:58W, 25:47N/158:15W, 23:54N/158:15W, 22:20N/159:09W, 22:21N/159:30W, 22:13N/159:42W, 22:00N/159:51W Intermittent high power radar operations are conducted by PMRF at the following position: 22:03N/159:47W Request all mariners remain at least one mile off the coastline between Kokole Point and Nohili Point. Vessels may be requested to alter course due to firing operations and are requested to contact "Pacific Missile Range Facility" on VHF-Ch 16 prior to entering the above boundaries. If unable to contact the PMRF prior to entering or while in the warning area, relay messages through U.S. Coast Guard Honolulu. Vessels inbound and outbound for Hawaiian ports will create the least interference to firing operations as well as enhance vessel's safety by passing South of the Islands of Kauai and Niihau during the specified times. Federal law provides for civil penalties of \$40,000 and/or criminal penalties of 6 years in prison for each violation of the PMRF safety zone during the schedule of designated activity (33CFR 165.1406). The following are hazardous operations to mariners for March 03, 2025 through March 12, 2025: 03 MAR 0930-1700 KAULAKAHI CHANNEL AND NOHILI POINT TO 50 NM WEST THROUGH NORTH. 04 MAR NO HAZARDOUS OPERATIONS SCHEDULED. 05 MAR 0930-1700 KAULAKAHI CHANNEL AND NOHILI POINT TO 50 NM WEST THROUGH NORTH. 06 MAR NO HAZARDOUS OPERATIONS SCHEDULED. 07 MAR 0930-1700 KAULAKAHI CHANNEL AND NOHILI POINT TO 50 NM WEST THROUGH NORTH. 08 MAR NO HAZARDOUS OPERATIONS SCHEDULED. 09 MAR NO HAZARDOUS OPERATIONS SCHEDULED. 10 MAR NO HAZARDOUS OPERATIONS SCHEDULED. 11 MAR NO HAZARDOUS OPERATIONS SCHEDULED. 12 MAR NO HAZARDOUS OPERATIONS SCHEDULED.	

## Kaunakakai Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kaunakakai Harbor Lighted Buoy 2	28600	OFF STATION	FD

## Kaunakakai Small Boat Harbor

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kaunakakai Small Boat Harbor Buoy 1	28630	SINKING	PA

## Kawaihae Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kawaihae Harbor Channel South Breakwater Light 6	28310	LT EXT	FD

### Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Kawaihae Harbor Channel South Breakwater Light 6	28310	WATCHING PROPERLY	FD	2025-03-10

## Kawaihae Light Draft Harbor

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kawaihae LT Draft Harbor Buoy 2	28271	MISSING	PA
Kawaihae LT Draft Harbor Buoy 3	28271.100000000002	MISSING	PA
Kawaihae LT Draft Harbor Buoy 6	28271.3	MISSING	PA

## Lahaina Boat Basin

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lahaina Boat Basin Range Front Light	28470	STRUCT DEST	FD
Lahaina Boat Basin Range Rear Light	28475	STRUCT DMGD	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lahaina Boat Basin Lighted Buoy 3	28480	MISSING	PA
Lahaina Boat Basin Lighted Buoy 6	28495	OFF STA	PA
Lahaina Boat Basin Lighted Buoy 7	28500	MISSING	PA
Lahaina Boat Basin Lighted Buoy 8	28505	OFF STA	PA

## Maalaea Basin

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Maalaea Basin Channel Lighted Buoy 1	28427	ADRIFT/LT EXT	PA
Maalaea Basin Channel Lighted Buoy 2	28430	LT EXT	PA

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Maui Island - Maalaea Basin/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	HI ISLANDS - MAUI - MAALAEA HARBOR SHOALING Report of shoaling within Maalaea Harbor, Maui. The shoaling berm, which runs parallel to the Southern seawall may pose a significant impact to the charted draft. All vessels transiting in and out of the harbor are advised to do so with caution.	Lat: 20° 47' 27" Lon: -156° 30' 37"

## Makai Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Makai Channel Daybeacon 3	28895	DAYMK MISSING	PA
Makai Channel Daybeacon 4	28900	MISSING	PA

## Maui Island

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hanamanioa Point Light	28405	LT EXT	FD
Haweia Point Light	28510	DAYMK MISSING	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hana Bay Daybeacon	28395	DAYMK DMGD/STRUCT DMGD	PA
Mala Channel Light 5	28507.5	LT EXT	PA
Mala Channel Light 6	28507.600000000002	LT EXT	PA

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Honolulu, Territorial Sea - Maui Island/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	HI ISLANDS - MAUI - LAHAINA AND MALA WHARF SHOALING There have been numerous reports of shoaling around Lahaina Harbor including increased shoaling around Mala Wharf. At low tide, the Mala Wharf Boat Ramp also becomes dangerously shallow with waters less than 03 feet. All mariners are requested to use caution while loading and unloading at Mala Wharf Boat Ramp and when transiting the channel. Report any observed changes in shoaling conditions to DLNR DOBOR at (808) 243-5824 and Marine Safety Team Maui at MSTMaui@uscg.mil	Lat: 20° 53' 08" Lon: -156° 41' 11"

## Maunalua Bay

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Maunalua Bay Daybeacon 16	29010	HAZ NAV/DAYMK DMGD	PA

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Honolulu, Territorial Sea - Maunalua Bay/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	HI ISLANDS - OAHU - MAUNALUA BAY SHOALING There has been a report of increased shoaling in Maunalua Bay, between Maunalua Bay Daybeacon 1A (LLNR 28935) and Maunalua Bay Daybeacon 2 (LLNR 28940) when transiting to and from Hawaii Kai. At mean low tide, the Maunalua Bay Boat Ramp also becomes dangerously shallow. All mariners are requested to use caution while loading and unloading at Maunalua Bay Boat Ramp and when transiting the channel. POC: DLNR DOBOR at (808) 587-1966 / (808) 832-3520 or website listing: <a href="https://dlnr.hawaii.gov/dobor/contact/">https://dlnr.hawaii.gov/dobor/contact/</a>	Lat: 21° 17' 01" Lon: -157° 43' 07"

## Mokapu Peninsula

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
WETS 4	28674.04	MISSING	PA
WETS 5	28674.05	MISSING	PA

## Pago Pago Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

Pago Pago Harbor Range Front Light	30190	DBD DMGD	FD
------------------------------------	-------	----------	----

## Pearl Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pearl Harbor Light 6	29405	BUOY DMGD	FD
Pearl Harbor Light 16	29440	LT EXT	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
PacIOOS Wave Lighted Buoy Pearl Harbor	29368	MISSING	PA

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Pearl Harbor Light 17	29445	DISCONTINUED FOR DREDGING	FD

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Honolulu, Territorial Sea - Pearl Harbor/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	HI ISLANDS - OAHU - PEARL HARBOR DREDGE PROJECT Dredging operations will commence on or about April 22, 2024, in Pearl Harbor around Light 17. Our Operations Manager Mr. Tas Bangash can be reached at (808) 979-6751. Mariners are advised to use extreme caution while transiting the dredge area. Request mariners to transit at their slowest safe speed to minimize wake when in the vicinity of a dredge and proceed with caution after passing arrangements have been made. The following Aid to Navigation will be affected as temporary disestablished: Pearl Harbor Light 17 (29445)	Lat: 21° 21' 02" Lon: -157° 58' 17"
Sector Honolulu, Territorial Sea - Pearl Harbor/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	The Puuloa Danger Zone is located in ocean waters as described by the below coordinates and is closed at all times to surface craft, swimmers, and divers, with the exception of authorized personnel. Mark B.J. Edmonson at mark.bj.edmonson@usmc.mil. The Danger Zone is bound by the following coordinates from Keahi Point to: 21.2622N / -157.9832W 21.2727N / -157.9526W The following are hazardous operations to mariners for March 05 through March 11, 2025: Wed 05 Mar 0700-1700 Thu 06 Mar 0700-1700 Fri 07 Mar 0700-1700 Sat 08 Mar N/A Sun 09 Mar N/A Mon 10 Mar 0700-1700 Tue 11 Mar 0700-1700	

## Pearl Harbor North Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pearl Harbor North Channel Light 4	29490	LT EXT	FD
Pearl Harbor North Channel Lighted Buoy 8	29500	SINKING	FD

## Sampan Channel

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kaneohe Bay - Sampan Channel/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	The Pyramid Rock / Fort Hase / Kaneohe Bay Danger Zone is located in ocean waters as described by the below coordinates and is closed at all times to surface craft, swimmers, and divers, with the exception of authorized personnel. Mark B.J. Edmonson at mark.bj.edmonson@usmc.mil. The Danger Zone surrounding Mokapu Peninsula at various coordinates: KBay: 21.4398 / -157.7844 to 21.4354 / -157.7730 Hale Koa / Pyramid Rock: 21.4459 / -157.7824 to 21.4664 / -157.7689 to 21.46229 / -157.7569 Fort Hase: 21.4402 / -157.7332 to 21.4396 / -157.7332 The following are hazardous operations to mariners for March 05 through March 11, 2025: Wed 05 Mar 1500-2100 KBAY, SAR TRAINING Thu 06 Mar 1400-2130 KBAY, SAR TRAINING Fri 07 Mar N/A Sat 08 Mar N/A Sun 09 Mar N/A Mon 10 Mar N/A Tue 11 Mar N/A	

## Sector Forces Micronesia/Guam Exclusive Economic Zone (EEZ)

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cabras Island Channel Light 4	30745	LT EXT	FD
Piti Channel Entrance Light 1	30751	STRUCT DEST/HAZ NAV	FD
Piti Channel Entrance Light 2	30752	STRUCT DEST	FD
Apra Outer Harbor Lighted Buoy 7	30765	LT EXT	FD
Rota West Harbor Range Rear Light	30850	LT EXT	FD
Managaha Island Light	30865	LT IMCH	FD
Tinian Harbor Channel Lighted Buoy 1	30920	LT EXT	FD
Tinian Harbor Channel Lighted Buoy 3	30930	LT EXT	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
PacIOOS Wave Lighted Buoy Ipan	30602	MISSING	PA
FAD Site "Cocos" - Guam	30603	LT EXT	PA
FAD Site "FACPI 2" - Guam	30612	MISSING	PA
FAD Site "Number 1" - Guam	30621	Status Unreported	PA

FAD Site "Number 3"	30631	MISSING	PA
FAD Site "Number 4"	30634	MISSING	PA
FAD Site GF1	30637.100000000002	MISSING	PA
FAD Site "Number 5"	30640	LT EXT	PA
Agat Small Boat Harbor Light 3	30811.3	LT EXT	PA
Agat Small Boat Harbor Daybeacon 9	30811.9	DAYMK IMCH	PA
FAD Site EE - Rota	30851.100000000002	MISSING	PA
FAD Site DD - Rota	30851.2	MISSING	PA
FAD Site DE - Rota	30851.3	MISSING	PA

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Piti Channel Entrance Light 2	30752	TRLB	FD

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
District 7, Oceanic boundary to EEZ - Sector Forces Micronesia/Guam Exclusive Economic Zone (EEZ)/General/Marine Events/Other	Marine Events	CABLE RECOVERY OPERATIONS - WESTERN PACIFIC OCEAN M/V Layla is engaged in cable recovery operations and expects to complete this section by 26 February, 23:00 LT (GMT -10). During operations, LAYLA is restricted in maneuverability and requests nearby ships keep a distance of at least 1 nautical mile away.	

## Sector Honolulu, Exclusive Economic Zone (EEZ)

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
NOAA Data Lighted Buoy 51003	28005.7	Status Unreported	PA

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Honolulu, Exclusive Economic Zone (EEZ) /General/Hazards To Navigation/Obstructions	Hazards To Navigation	HI ISLANDS - KAUAI - HAZARD TO NAVIGATION Aerial target last known position 22-24N 160-13W on 14 July at 2220Z. This target is orange, 16 feet long, weighing approximately 1000 pounds, and may be floating on the surface. Mariners are requested to use caution when operating in this area. If this target is found, please contact the Pacific Missile Range Facility at (808) 335-4301. Do not attempt to recover this device due to risk of injury or property damage because of its size and weight.	Lat: 22° 24' 00" Lon: -160° 13' 00"
Sector Honolulu, Exclusive Economic Zone (EEZ) /General/Naval Activity/Naval Gunnery Exercises	Naval Activity	FACSFAC Pearl Harbor established Special Operating Areas Four (SOA-4) as a permanent "HOT AREA" named "KAPU" on April 15, 1995. FACSFAC effective hours are 0700W to 2300W (Monday - Saturday from 1700Z - 0900Z) Monday - Friday, and on weekend's 0800W - 1600W (Weekends from 1800Z - 0200Z) or by request. Activities include intermittent naval gunnery exercises and airborne ordnance drops. "KAPU" is also designated as the emergency jettison area for aircraft with hung stores, etc. Hot area "KAPU" is bounded by the following coordinates 20-46N/158-16W, 20-42 N/158-04W, 20-13N/158-36W and 20-04N/158-11W. Scheduling authority is FACSFAC Pearl Harbor call-sign "HULA DANCER". "HULA DANCER" can be reached on primary 266.4/127.0 MHz, or secondary 336.8/132.4 MHz or telephone (808) 472-7333/7337 and may authorize transits through these areas on a case by-case basis.	

## Sector Honolulu, Territorial Sea

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
FAD Site G - Pepeekeo, Hawaii	28007.010000000002	MISSING	PA
FAD Site WH1	28007.22	MISSING	PA
FAD Site F - Kailua Kona, Hawaii	28007.25	OFF STA	PA
FAD Site XX - Puako, Hawaii	28007.29	MISSING	PA
FAD Site DD - Opana Point, Maui	28007.33	MISSING	PA
FAD SITE MTBC 1	28007.4	MISSING	PA
FAD SITE MTBC 2	28007.420000000002	MISSING	PA
FAD Site M - Hana Bay, Maui	28008.010000000002	MISSING	PA
FAD Site NL - Nuu Landing, Maui	28008.03	MISSING	PA
FAD Site GG - Nakaohu Point, Maui	28008.05	MISSING	PA
FAD Site SO - Kahoolawe	28008.11	MISSING	PA
FAD Site K - Palaoa, Lanai	28008.15	STRUCT MISSING	PA
FAD Site CC - Kaena Point, Lanai	28008.190000000002	MISSING	PA
FAD site LL Hauula - Oahu	28008.25	Status Unreported	PA
FAD Site P - Penguin Bank, Oahu	28008.33	MISSING	PA
FAD Site HH - Pearl Harbor, Oahu	28008.350000000002	MISSING	PA
FAD Site BO - Barbers Point, Oahu	28008.37	MISSING	PA
FAD Site R - Makaha, Oahu	28009.010000000002	MISSING	PA
FAD Site CO - Kaena Point, Oahu	28009.05	MISSING	PA
FAD Site J - Wailalee, Oahu	28009.09	MISSING	PA
FAD Site BB - Moloaa, Kauai	28009.13	MISSING	PA
FAD Site DK - Anahola, Kauai	28009.15	OFF STA	PA

FAD Site WK - Wailua, Kauai	28009.170000000002	MISSING	PA
FAD Site PP - Koloa, Kauai	28009.23	MISSING	PA

### Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Honolulu, Exclusive Economic Zone (EEZ) - Sector Honolulu, Territorial Sea/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	All vessels/watercraft operating within the Mokapu Peninsula near the Ulupau Crater located on Marine Corps Base Hawaii shall vacate the danger zone at the best speed and by the most direct route. Danger zone will include areas from (Zone 1 NE) 21°30'59.66"N /157°44'05.97"W to 21°29'16.58"N /157°40'30.19"W to (Zone 2 SE) 21°25'01.79"N/157°40'33.70"W to 21°27'11.84"N/157°43'53.83"W, forming a triangular figure. The following are hazardous operations to mariners for March 05 through March 11, 2025: Zone 1: Wed 05 Mar 0700-1700 Thu 06 Mar 0600-2300 Fri 07 Mar 0600-2300 Sat 08 Mar N/A Sun 09 Mar N/A Mon 10 Mar 0600-2359 Tue 11 Mar 0000-0200 & 0600-2359 Zone 2: Wed 05 Mar 0700-1700 Thu 06 Mar 0600-2300 Fri 07 Mar 0600-2300 Sat 08 Mar 0700-1700 Sun 09 Mar N/A Mon 10 Mar 0600-2359 Tue 11 Mar 0000-0200 & 0600-2359	
Sector Honolulu, Exclusive Economic Zone (EEZ) - Sector Honolulu, Territorial Sea/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	The Waimanalo Bay Danger Zone is located in ocean waters as described by the below coordinates and is closed at all times to surface craft, swimmers, and divers, with the exception of authorized personnel. Mark B.J. Edmonson at mark.bj.edmonson@usmc.mil. The Danger Zone is bounded by the following coordinates: 21.3680N / -157.6954W 21.3559N / -157.6921W The following are hazardous operations to mariners for March 05 through March 11, 2025: Wed 05 Mar N/A Thu 06 Mar N/A Fri 07 Mar N/A Sat 08 Mar N/A Sun 09 Mar N/A Mon 10 Mar N/A Tue 11 Mar N/A	

## Tutuila Island

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Breakers Point Light	30185	LT EXT	FD

## Unknown

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Drydock Point West Entrance Daybeacon 1	30787	DAYMK MISSING	PA
Mamaon Channel Lighted Buoy 1	30815	OFF STA	PA
Mamaon Channel Lighted Buoy 2	30820	OFF STA	PA
Fad Site FF - Saipan	30852.16	MISSING	PA
FAD Site GG - Saipan	30852.170000000002	MISSING	PA
Fad Site HH - Saipan	30852.18	MISSING	PA
FAD Site II - Saipan	30852.190000000002	MISSING	PA
Fad Site LL - Saipan	30852.22	MISSING	PA
Smiling Cove Lighted Buoy 1	30913	MISSING	PA