

U.S. Department of Homeland Security

United States Coast Guard

LOCAL NOTICE TO MARINERS

District: 17 Week: 40/24

58-Navigation Information Service (NIS)-Watchstander, 24 hours a day at (703) 313-5900 ~Navcen Internet Address~ https://www.navcen.uscg.gov -Local Notice to Marinershttps://www.navcen.uscg.gov/-pageName=InmMain

Issued by: Commander (DPW) Telephone: (907) 463-2269 (0800-1600) Seventeenth Coast Guard District After Hours: (907) 463-2000 (1600-0800) PO Box 25517, Juneau, AK 99802-5517

Questions, comments, or additional information on this Local Notice to Mariners should be sent to the address above or by E-mail to: SMB-D17Juneau-LNM@uscg.mil. You can get the U.S. Coast Guard 17th District Local Notice to Mariners via the Internet directly from the U.S. Coast Guard Navigation

Center web site at https://www.navcen.uscg.gov/-pageName=InmDistrict®ion=17.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands (COMDTPUB P16502.6).
U.S. Coast Pilot 8, Pacific Coast Alaska: Dixon Entrance to Cape Spencer, 46th Edition.
U.S. Coast Pilot 9, Pacific and Arctic Coasts Alaska: Cape Spencer to Beaufort Sea, 41st Edition.

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by CG Sector Southeast Alaska Broadcast Notice to Mariners through SEAK332-24 and CG Sector Anchorage Broadcast Notice to Mariners through A167-24 that are still in effect are included in this notice.

Chart Corrections https://nauticalcharts.noaa.gov/charts/chart-updates.html

Dates of Latest Editions, Nautical Charts, and Miscellaneous Maps https://nauticalcharts.noaa.gov/charts/list-of-latest-editions.html

Light List/ Summary of Corrections https://www.navcen.uscg.gov/-pageName=lightListCorrections

NOAA Chart Viewer (Posting of all up to date NOAA charts for viewing on Internet browser to be used for ready reference or planning) https://nauticalcharts.noaa.gov/

NOAA Booklet Charts https://nauticalcharts.noaa.gov/charts/noaa-raster-charts.html#booklet-charts

Coast Pilots, along with corrections, are available at: https://nauticalcharts.noaa.gov/publications/coast-pilot/index.html

NOAA Weather Buoy Sites http://www.ndbc.noaa.gov/

Tides online https://tidesandcurrents.noaa.gov/

Tides, Currents, PORTS https://tidesandcurrents.noaa.gov/noaacurrents/Stations-g=693

Weather https://www.weather.gov/marine/alaskatext

Vessel Traffic System Prince William Sound (VTSPWS) Users Manual https://homeportr.uscg.mil/Lists/Content/DispForm.aspx-ID=2205&Source=https:

ABBREVIATIONS

A through H

I through O

P through Z

ADRIFT - Buoy Adrift AICW - Atlantic Intracoastal Waterway I - Interrupted ICW - Intracoastal Waterway

PRIV - Private Aid Q - Quick

Al - Alternating B - Buoy BKW - Breakwater

bl - Blast

BNM - Broadcast Notice to Mariner

bu - Blue C - Canadian CHAN - Channel

CGD - Coast Guard District

C/O - Cut Off CONT - Contour CRK - Creek CONST - Construction

DAYMK/Daymk - Daymark DBN/Dbn - Daybeacon DBD/DAYBD - Dayboard DEFAC - Defaced DEST - Destroyed

DISCON - Discontinued DMGD/DAMGD - Damaged ec - eclipse

EST - Established Aid

ev - every EVAL - Evaluation EXT - Extinguished

F - Fixed fl - flash FI - Flashing G - Green

GIWW - Gulf Intracoastal Waterway

HAZ - Hazard to Navigation HBR - Harbor

HOR - Horizontal Clearance

HT - Height

IMCH - Improper Characteristic

INL - Inlet INOP - Not Operating INT - Intensity ISL - Islet

Iso - Isophase kHz - Kilohertz LAT - Latitude LB - Lighted Buoy LBB - Lighted Bell Buoy LHB - Lighted Horn Buoy LGB - Lighted Gong Buoy LONG - Longitude

LNM - Local Notice to Mariners

LT - Light

LT CONT - Light Continuous

LTR - Letter LWB - Lighted Whistle Buoy LWP - Left Watching Properly MHz - Megahertz

MISS/MSNG - Missing Mo - Morse Code

MRASS - Marine Radio Activated Sound Signal

MSLD - Misleading N/C - Not Charted

NGA - National Geospatial-Intelligence Agency

NO/NUM - Number

NOS - National Ocean Service

NW - Notice Writer **OBSCU - Obscured OBST** - Obstruction **OBSTR** - Obstruction Oc - Occulting

ODAS - Anchored Oceanographic Data Buoy

R - Red

RACON - Radar Transponder Beacon

Ra ref - Radar reflector RBN - Radio Beacon REBUILT - Aid Rebuilt RECOVERED - Aid Recovered

RED - Red Buoy REFL - Reflective RRL - Range Rear Light RELIGHTED - Aid Relit

RELOC - Relocated RESET ON STATION - Aid Reset on Station

RFL - Range Front Light

RIV - River

RRASS - Remote Radio Activated Sound Signal

s - seconds SEC - Section SHL - Shoaling si - silent SIG - Signal SND - Sound

SPM - Single Point Mooring Buoy

SS - Sound Signal STA - Station STRUCT - Structure St M - Statute Mile

TEMP - Temporary Aid Change

TMK - Topmark

TRLB - Temporarily Replaced by Lighted Buoy TRLT - Temporarily Replaced by Light

TRUB - Temporarily Replaced by Unlighted Buoy

USACE - Army Corps of Engineers

W - White Y - Yellow

Additional Abbreviations Specific to this LNM Edition: None

SECTION I - SPECIAL NOTICES

This section contains information of special concern to the Mariner.

842 **ALASKA**

The Coast Guard's VHF-FM Remote Fixed Facility (RFF) reception capabilities on the following site is degraded and calls on VHF-FM Channel 16 may not be received by the responsible Coast Guard Sector Communication Center within the stated coverage area: PILLAR MOUNTAIN - Eastern Kodiak Island, Afognak Island, Chiniak Bay, and Womens Bay.

COLD BAY – The area around Cold Bay, Izembek Lagoon, Northeastern Morzhovoi Bay, King Cove, and the Shumagin Islands.

If unable to reach the Coast Guard on VHF-FM Channel 16, mariners that are equipped with capable radios can contact the Coast Guard through Communications Detachment Kodiak via high frequency (HF) 4125Khz. Mariners can also contact the Coast Guard via cellular or satellite phone by calling JRCC Juneau at 907-463-2000, Sector Southeast Alaska Command Center at (907) 463-2980 or Sector Western Alaska and U.S. Arctic Command Center at (907) 428-4100. Mariners are reminded that Western and Northern Alaska have no VHF-FM coverage. Contact in areas without VHF/FM coverage to the Coast Guard is via Communications Detachment Kodiak on HF or JRCC Juneau by phone. Mariners are requested to relay any unanswered calls for assistance to the Coast Guard.

LNM: 40/24

843 **ALASKA**

Changes to the USCG Local Notice to Mariners (LNM) and Light Lists

This Notice announces upcoming changes to the Local Notice to Mariners (LNM) and Light Lists as part of the U.S. Coast Guard Navigation Center efforts to modernize and improve the accessibility, accuracy, and overall user experience for mariners and other stakeholders. Transition to the new system will be occurring in October, 2024, and be available at the CG Navigation Center's LNM site.

- 1. Overview: The Coast Guard will be transitioning to a modernized geospatial notice to mariners replacing weekly LNMs, weekly Light List Correction Files, Daily Discrepancy Files, and the Summary of Light List Changes. The new format will allow mariners to visualize information interactively on a map/chart, and also use a fillable form via the Navigation Center website (https://www.navcen.uscg.gov/) to select a waterway by name from the Light List and generate LNM or Light List information. Information in the modernized LNM will be updated on a daily basis, Monday through Friday, at a minimum, and will eventually be updated every 15 minutes, 24 hours a day and 7 days a week. This system is designed to enhance efficiency and improve safety during route planning and transits and will give mariners more up-to-date information than
- 2. When the transition to the modernized LNM and Light List platform occurs in mid-October, 2024, legacy versions of these products will still be updated and downloadable as they have been for three weeks, after which only the interactive, geospatial interface format will be available and

Page 2 of 20 Coast Guard District 17 Weekly LNMs, Weekly Light List Correction Files, Daily Discrepancy Files, and the Summary of Light List Changes will no longer be published.

3. For any questions, assistance or feedback regarding this LNM delivery change, please visit the NAVCEN contact us page:

https://navcen.uscg.gov/contact/contact-us, select 'LNMs or Light Lists' from the Subject dropdown, or contact Todd Buck, Waterways

Management at Seventeenth Coast Guard District, by email to todd.r.buck@uscg.mil.

LNM: 40/24

844 ALASKA

845

888

898

The Alaska Marine Safety Education Association is offering a number of classes in U.S. Coast Guard District 17 that may be of interest to Mariners. Many of these workshops are offered at a reduced cost to commercial fishermen, thanks to support from the U.S. Coast Guard, the National Institute for Occupational Safety and Health, the Alaska Department of Commerce, Community and Economic Development, and AMSEA members

AMSEA Workshops of Interest to Mariners in District 17:

Marine Safety Instructor Training – 9/30/24-10/5/24 – Sitka, AK

Recreational Boating Safety Class - 10/26/24-10/26/24 - Sitka, AK

Additional information can be found online at www.amsea.org. Questions/concerns should be directed to Kiley Prinz at 907-747-3287 or by email to kiley@amsea.org.

LNM: 40/24

ALASKA – SOUTHEAST – GULF OF ALASKA NEAR YAKUTAT

Maintenance is being conducted on the following Coast Guard VHF/FM Hi-site and may cause intermittent coverage lapses from 030730-031400 UTC which is 2330 Alaska time on October 2nd, through 0600 on October 3rd, 2024
YAKUTAT – Gulf of Alaska near Yakutat

Mariners are requested to relay any unanswered distress calls to the Coast Guard Sector Southeast Alaska Command Center at 907-463-2980 or the nearest Coast Guard Unit.

LNM: 40/24

846 ALASKA – SOUTHCENTRAL – CHUGACH PASSAGE

Chugach Passage LB 2, LLNR 26075, has been relocated to 59°09′02.070″N, 151°45′16.060″W. Mariners are requested to transit the area with caution. Chart/Light List corrections will be issued once the verification process has been completed. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

I NM · 40/24

847 ALASKA – WESTERN – UNALKLEET

The Unalakleet River Buoys (About 6), LLNR 27915, have been decommissioned for the 2024 season. These buoys should be commissioned again by June 1st, 2025. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 40/24

887 ALASKA – SOUTHEAST – STEPHENS PASSAGE

Sub-surface operations occasionally including divers will be conducted twenty-four hours a day, seven days a week beginning at 1700 UTC which is 0900 Alaska time on September 5th, 2024 in Stephens Passage between Tantallon Point and Green Cove. The sub-surface operations will continue until 1700 UTC which is 0900 Alaska time on October 5th, 2024. Vessels on scene will monitor VHF/FM channel 16 and respond to calls to "PACIFIC LIFTER" for communication with transiting vessels. DB PACIFIC LIFTER is restricted in ability to maneuver. Mariners are requested to transit the area with caution, maintain a 500 yard CPA and minimize wake when transiting nearby. Questions/concerns should be directed to Mr. Brad Pace at (415) 323-4466 or brad.pace@kennedyslaw.com.

LNM: 36/24

ALASKA – SOUTHEAST – GASTINEAU CHANNEL – AURORA HARBOR

A floating dock measuring 180'X24' is being temporarily moored in Gastineau channel adjacent to the Aurora Harbor breakwater. Two white quick flashing lights have been attached to the dock in the following approximate positions:

58°18′20.4962″N, 134°26′12.2197″W

58°18′18.4802″N, 134°26′10.4467″W

Mariners are requested to transit the area with caution. Questions/concerns should be directed to Jeremy Norbryhn, Deputy Harbormaster, at 907-586-0395 or by email to jeremy.norbryhn@juneau.gov.

LNM: 36/24

ALASKA – SOUTHEAST – SAGINAW CHANNEL – FAVORITE REEF

Favorite Reef B 2, LLNR 23945.1 has been re-established in position 58°22′47.514″N, 134°51′46.790″W, and upgraded to a lighted buoy with a flash characteristic of Fl R 4s. Mariners are requested to transit the area with caution.

LNM: 34/24

911 ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – ORCA INLET

Orca Inlet LT 12, LLNR 25575, has been replaced with a temporary replacement lighted buoy in position 60°37′35.256″N, 145°41′22.268″W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 30/24

919 ALASKA – SOUTHEAST – CRAIG

A 32 foot troller has sunk SE of Madre De Dios Island in position 55°23.6′N, 133°06.98′W. Debris including an inflatable skiff have been reported in the vicinity. Mariners are requested to transit the area with caution. Questions/concerns should be directed to the Sector Southeast Alaska Command Center at 907-463-2980.

LNM: 28/24

922 ALASKA – SOUTHEAST – ANNETTE ISLAND – CANOE COVE

The F/V JACI GRACE has sunk in Canoe Cove in position 55°03.00′N, 131°38.93′W. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Mariners are advised to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center at 907-463-2980.

LNM: 27/24

927 ALASKA – NORTHWESTERN – KOTZEBUE SOUND

HYDROGRAPHIC SURVEY: TerraSond, under contract to NOAA's Office of Coast Survey, will be conducting a hydrographic survey in the vicinity of Kotzebue Sound, from approximately July 1 through October 15. The work is being done for the purpose of updating nautical charts in the region. The survey areas are distributed in Kotzebue Sound, from Kotzebue to Good Hope Bay, as well as the general area from Cape Espenberg to Kivalina. The survey will be accomplished by the R/V POSEIDON, a 135' vessel blue and white in color. A 25' vessel called the "ASV-LR1", red in color, will be also be deployed and will be operated primarily unmanned, remote controlled and monitored from the POSEIDON. Both vessels will work in close proximity to each other and will have limited maneuverability during survey operations. Mariners are requested to remain clear of the vessels while surveying is in progress. Any immediate navigation concerns should be directed to the POSEIDON, which will be monitoring VHF channel 16. General questions can be directed to the TerraSond Charting Program Manager, Andrew Orthmann, by email at andrew.orthmann@terrasond.com.

LNM: 27/24

930 ALASKA – SOUTHEAST – ANITA BAY

The F/V PAMELA RAE LADY has sunk in position 56°12.10′N, 132°29.68′W. The F/V PAMELA RAE LADY is a 58ft seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Mariners are advised to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 26/24

932 ALASKA – SOUTHEAST – SITKA – SILVER BAY – HERRING COVE

The F/V DRAGON LADY, a 79' wooden fishing vessel, has sunk in approximate position 57°02.607'N, 135°12.358'W. Fishing gear and other debris may be attached to or in the vicinity of the wreck. Mariners are advised to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 26/24

944 ALASKA – SOUTHWESTERN – ALEUTIAN PENINSULA – SHUMAGIN ISLANDS

Bluff point Shoal LGB 1 (LLNR 27140) has been relocated to 55°11′25.315″N, 161°52′25.171″W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 24/24

945 ALASKA – SOUTHEAST – WRANGELL NARROWS

An 18ft aluminum skiff has sunk in the Wrangell Narrows near Wrangell Narrows Channel LB 26 (LLNR 22995) and Wrangell Narrows Channel LT 27 (LLNR 23000) in position 56°38.868′N, 132°55.258′W. All vessels are requested to transit this area with caution and account for the reduced depth of the channel due to the wreck. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 24/24

948 ALASKA – SOUTHEAST – DUNCAN CANAL – WHISKEY PASS

A skiff was reported sunk in Whiskey Pass, Duncan Canal, in approximate position 56°32.586′N, 133°03.855′W. Mariners are requested to transit or anchor in the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 22/24

949 ALASKA – SOUTHEAST – FOGGY BAY

An uncharted dangerous rock has been reported in Foggy Bay in approximate position 54°57.501′N, 130°57.267′W. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 21/24

951 ALASKA – SOUTHEAST – ICY STRAIT/ICY PASSAGE

Dangerous shoaling was reported in position 58°18′08.1″N, 135°22′22.5″W. Mariners are advised to transit the area with caution.

Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 19/24

952 ****CANCELLATION OF NOAA PAPER AND RASTER NAUTICAL CHARTS****

Originally published in LNM 09/21 and updated in LNM 18/24 The National Oceanic and Atmospheric Administration (NOAA) is undertaking a multi-year program to end production and maintenance of its suite of over 1,000 traditional paper nautical charts and all associated raster chart products and services, including: Print-on-Demand (POD) paper nautical charts, Full-size chart PDF files, BookletChartTM PDF files, NOAA raster navigational charts (NOAA RNC®), the NOAA RNC tile service, and the online RNC viewer. Six months notice of the intent to cancel a specific chart is provided in a "Last Edition" notice. The final cancellation of a chart is made in a "Canceled" notice. Both types of notices will appear in LNM Section IV, "Chart Correction." Canceled charts do not meet USCG carriage requirements. A comprehensive list of all canceled NOAA charts is available at: http://www.charts.noaa.gov/MCD/Dole.shtml. Traditional paper nautical chart production is ending to enable the creation and maintenance of larger scale, more up-to-date, higher quality coverage of NOAA's electronic navigational chart (NOAA ENC®) product. This will significantly enhance the amount of charted detail available to mariners. More information about NOAA's program to sunset traditional paper charts is on the NOAA Coast Survey website at: https://nauticalcharts.noaa.gov/charts/farewell-to-traditional-nautical-charts.html An online NOAA Custom Chart application at: https://devgis.charttools.noaa.gov/pod is available to create chart images from ENC data, which may then be printed. Notices to Mariners will not be issued for NOAA Custom Charts.

LNM: 09/21

ALASKA - SOUTHCENTRAL - COOK INLET - ANCHORAGE

Dredging, pile driving and other miscellaneous marine construction will be conducted at the Port of Alaska from April 1st through October 31st, 2024. Three mooring buoys with quick flashing white lights will be established northwest of Terminal 3 in positions 61°15'3.25"N, 149°53'39.45"W; 61°15'14.56"N, 149°53'31.58"W; and 61°15'25.56"N, 149°53'33.24"W. During operations VHF/FM channel 8 will be monitored. Derrick barges will have anchors deployed and submerged anchor cables will be marked by crown buoys over each submerged anchor. Mariners are requested to maintain a minimum 1,000 foot CPA. Mariners should proceed with caution and are requested to operate at a slow speed when transiting in this area.

LNM: 13/24

ALASKA - SOUTHCENTRAL - ORCA BAY

The Coast Guard has temporarily established Orca Inlet Channel LB 12 to temporarily replace Orca Inlet Channel LT 12 in position 60°37′34.074″N, 145°41′27.078″W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 12/24

955 ALASKA – SOUTHEAST – WESTERN CHANNEL

Makhnati Rock LWB 2 (LLNR 25000) is missing. A red temporary replacement lighted buoy has been established in position 57°02.170′N, 135°23.759′W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 04/24

956 ALASKA – SOUTHEAST – GASTINEAU CHANNEL – DOUGLAS

OBSTRUCTION TO NAVIGATION: A 22' white sailboat has sunk in Gastineau Channel off of Sandy Beach on Douglas in approximate position 58°16.259'N, 134°22.227'W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to the Coast Guard Sector Southeast Alaska Command Center on VHF/FM channel 16 or by phone to 907-463-2980.

LNM: 01/24

957 ALASKA – SOUTHEAST

953

954

958

The U.S. Coast Guard has VHF Digital Selective Calling (DSC) capability with limited coverage in Southeast Alaska. The initial coverage areas are Ketchikan, Juneau and Yakutat. Mariners are reminded to ensure that they have properly connected their GPS units to their DSC equipped marine VHF radios and registered for their Maritime Mobile Service Identity (MMSI) to utilize the DSC distress function. Additional information is available through the Alaska Outdoors Forum at

https://forums.outdoorsdirectory.com/threads/digital-selective-calling-dsc.140270/ or by contacting Mike Folkerts with the Coast Guard District 17 Boating Safety Office at (907) 463-2297 or by email to Michael.r.folkerts@uscg.mil.

LNM: 51/23

ALASKA – ALEUTIAN ISLANDS – ADAK – SWEEPER COVE

The East side of the Pier 5 Dock located in Sweeper Cove is closed to moorage without prior approval from the Adak Harbormaster due to loose and missing pilings. Questions/concerns should be directed to Jim Fleming at (907) 277-7527 or the Port of Adak office at (907) 592-0185. The Adak harbormaster can also be contacted on VHF/FM channel 16.

LNM: 20/13

959 ALASKA – SOUTHCENTRAL – KODIAK

OBSTRUCTION TO NAVIGATION: A submerged rock has been reported approximately 20' off of the K&I Pier, which is located just South of the Star of Kodiak Pier, in approximate position 57°47.150'N, 152°24.341'W. The rock was reported struck by a vessel with a 16' draft at low tide, approximately +.085'. Mariners are requested to transit the area with extreme caution. Questions/concerns should be directed to the Sector

LNM: 47/23

960 ALASKA – SOUTHEAST – HAINES – CHILKOOT INLET

961

962

963

OBSTRUCTION TO NAVIGATION: An anchor and 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor in Chilkoot Inlet in position 59°14.420'N, 135°25.852'W. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor. Questions/concerns should be directed to the Coast Guard Sector Juneau Command Center at 907-463-2980 or on VHF/FM channel 16.

LNM: 27/23

ALASKA – SOUTHWESTERN – ALASKA PENINSULA – BECHEVIN BAY

Bechevin Bay B 8 (LLNR 27290) has been relocated 136 yards to position 55°03′09.590″N, 163°25′26.656″W to best mark the channel. Mariners are requested to transit the area with caution. Chart and Light List corrections will be issued once the verification process has been completed. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 26/23

ALASKA - SOUTHEAST - WRANGELL - STIKINE RIVER ENTRANCE

The Coast Guard received a report of a grounding due to uncharted shoaling in the vicinity of the Stikine River entrance. The grounding occurred on June 17th, 2023, in the vicinity of position 56°30.01′N, 132°27.28′W with an approximate charted depth of 140′. Mariners are advised to transit the area with extreme caution and report any observed uncharted shoaling. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 26/23

ALASKA - SOUTHEAST - AUKE BAY/AUK REC

The U.S. Coast Guard has established a temporary mooring buoy in the cove where the Auk Recreation area is located between Point Louisa and Auke Bay in position 58°22′34.114″N, 134°43′23.448″W. The mooring buoy has been established for official use and should not be used without authorization from the Coast Guard. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 23/23

964 ALASKA – SOUTHEAST – FREDERICK SOUND

A 47 foot wood fishing vessel has been reported sunk in position 56°54.68′N, 132°56.69′W. Mariners are requested to transit the area with caution. Questions/concerns should be directed to the Sector Juneau Command Center at 907-463-2980.

LNM: 21/23

965 ALASKA – SOUTHEAST – SITKA SOUND – DOROTHY NARROWS

Elovoi Island Rock DBN 1 (LLNR 24900) has been rebuilt in position 56°49′17.695″N, 135°22′43.882″W and is watching properly. The temporary buoy marking the rock has been removed. Chart and Light List corrections will be issued once the verification process has been completed. Mariners are advised to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 17/23

966 ALASKA – PRINCE WILLIAM SOUND – CAPE HINCHINBROOK

A submerged mooring has been reported lost in 315 feet of water in position 60°30.224′N, 146°30.821′W. This mooring may be an obstruction to operations on the sea floor. Questions/concerns should be directed to Todd Buck at the Coast Guard District 17 Waterways Management Office at 907-463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 6/23

967 ALASKA – SOUTHEAST – STEPHENS PASSAGE – HORSE ISLAND

Sea Quester Farms has established an aquatic farm just South of Horse Island in Stephens Passage. The aquatic farm is marked by buoys and three of the buoys are currently lighted with plans to add lights to two additional buoys. The extent of the aquatic farm is:

 $SSW - 58^{\circ}14.575' N, 134^{\circ}43.980' W \hspace{0.2cm} \text{(Lighted buoy)}$

WSW - 58°14.587'N, 134°44.040'W (Lighted buoy)

WNW - 58°14.648'N, 134°44.077'W (Lighted buoy)

NNW - 58°14.684'N, 134°44.025'W (Light will be added to buoy)

ENE - 58°14.674'N, 134°43.888'W

ESE - 58°14.639'N, 134°43.862'W

SSE - 58° 14.597'N 134° 43.887'W (Light will be added to buoy)

Mariners are advised to transit the area with caution. Questions/concerns should be directed to Ilivia Duner at 530-414-3632 or by email to info@seaquesterfarms.com.

LNM: 05/23

ALASKA – SUBSURFACE AND SURFACE BUOYS

Locations of all subsurface and surface oceanographic moorings that have been reported to the U.S. Coast Guard District 17 Waterways Branch

968

are included in an enclosure to the Local Notice to Mariners. The name, type, location, depth, water depth, and a Point of Contact for all data buoys, surface and subsurface, shall be reported as quickly as is practical if they are placed within the navigable waters (within 200 nm) of the United States. Data buoys placed in the Arctic region but outside of 200 nm of the United States may be reported and will be included in this compilation (for informational purposes only). This notification process is for inclusion in the Local Notice to Mariners to provide navigational information to mariners and does not supersede any permission or permitting requirements. Any notifications, corrections, additions, deletions, or comments for the Alaska region (Coast Guard District 17) or the Arctic region should submitted via e-mail to D17-PF-D17-LNM@uscg.mil or to Todd Buck, USCG D17(dpw), at (907) 463-2269 or by email to todd.r.buck@uscg.mil. This compilation is as current as the Local Notice to Mariners (LNM) as included in an enclosure. The referenced LNM may have additional information and indicates the last time an entry was updated.

LNM: 38/11

ALASKA - SOUTHCENTAL - COOK INLET NAVIGATION CHANNEL

The U.S. Army Corps of Engineers (USACE), Alaska District conducted a project condition survey for Cook Inlet Navigation Channel on May 13th, 2022 in which the following controlling depths in feet (FT) mean lower low water (MLLW) were recorded:

Left Outside Quarter 61°12'30.93"N, 150°03'54.55"W, -39.5 FT MLLW

Left Inside Quarter 61°11'39.75"N, 150°07'00.55"W, -38.6 FT MLLW

Right Inside Quarter 61°11'37.86"N, 150°06'57.61"W, -39.4 FT MLLW

Right Outside Quarter 61°12'13.42"N, 150°04'19.01"W, -41.8 FT MLLW

A chartlet of the controlling depths as well as survey data are available on the U.S. Army Corps of Engineers (USACE) Navigation Portal website at: http://navigation.usace.army.mil/Survey/Hydro. The Cook Inlet Navigation Channel was dredged during the summer of 2014 to a project depth of -38 FT MLLW. At this time, no maintenance dredging is scheduled for this channel during 2022. The next project condition survey for this channel is tentatively scheduled for May 2023. BE ADVISED: The information depicted on maps, charts, drawings, navigation notices, etc., for the subject project, represents the results of a survey conducted on the date(s) indicated and can only be considered to represent the general condition existing at that time. The survey data was collected under a USACE contract for the purpose of characterizing the condition of the navigation channel, and the area for placement of dredged material for future channel maintenance operations. As such, the information is only valid for its intended use. This information can be used to supplement existing published navigation charts. The user is responsible for the results of any application of the survey data for other than its intended purpose and should consider the contents, timeframe of data collection, and accuracy specifications for survey data

collection/processing. Additionally, bathymetry in Cook Inlet is subject to drastic and continuing change. Prudent mariners should not rely solely upon this information. Questions/concerns should be directed to Jeremy Allen, Operations Project Manager at 907-753-2753 or by email to jeremy.m.allen@usace.army.mil.

LNM: 02/23

970 ALASKA – SOUTHEAST – TENAKEE INLET

969

Tenakee Inlet Entrance LT 1 (LLNR 24065) is destroyed and has been temporarily decommissioned and Tenakee Inlet Entrance LB 1 (LLNR 24065.1) has been established in position 57°46′19.284″N, 134°55′36.987″W. Tenakee Inlet Entrance LB 1 is a green can buoy with a green light flashing every 4 seconds. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 49/22

971 ALASKA – SOUTHEAST – FRESHWATER INLET – PAVLOF HARBOR

The F/V BAILEY BAY has sunk in position 57°50.985′N, 135°01.725′W in approximately 30 feet of water. The F/V BAILEY BAY is a 33′ fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Mariners are advised to transit the area with caution.

LNM: 43/22

972 ALASKA – SOUTHEAST – ICY STRAIT – ICY PASSAGE

A kelp farm has been established in Icy Passage along the North shore of Pleasant Island in approximate position 58°21′30″N, 135°32′32″W. The kelp farm is marked with two private lighted buoys. Aquatic Plant Farm LB A (LLNR 24177) is a yellow buoy with a FI 4 second light and is located in position 58°21′16.980″N, 135°32′32.700″W. Aquatic Plant Farm LB B (LLNR 24278) is a yellow buoy with a FI 6 second light and is located in position 58°21′47.580″N, 135°32′32.500″W. Chart and Light List corrections will be published in a subsequent LNM. Questions/concerns should be directed to Brian Delay at 907-321-1952 or by email to rainydawnfarms@gmail.com.

LNM: 42/22

973 ALASKA – SOUTHCENTRAL – PRINCE WILLIAM SOUND – BARRY ARM

The State of Alaska is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm, Northwestern Prince William Sound, and has the potential to create a tsunami when it falls into the water. It is uncertain if and when this might occur, but if it occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following this event. The geologic makeup of the area is similar to Alaskan locations where two previous landslide caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of the potential results of a slide. Additional information is available at the following website: https://dggs.alaska.gov/hazards/barry-arm-landslide.html.

LNM: 40/22

974 SAFETY NOTICE - NAVIGATIONAL RANGE AND SECTOR LIGHTS ON ELECTRONIC CHARTS

The U.S. Coast Guard has become aware that the Range and Sector Light Characteristic labels are not displayed on Electronic Navigational Charts (ENCs) when used in an Electronic Chart Display and Information System (ECDIS) due to limitations of the S-52 ECDIS display specification. Mariners may query the ENC data directly within ECDIS or refer to the Light List for complete information on Range and Sector Light Characteristics.

LNM: 39/22

ALASKA - SOUTHEAST - NECKER ISLANDS - HOT SPRINGS BAY

A 32' Sailboat has been reported sunk in Hot Springs Bay in approximate position 56°50.252'N, 135°23.574'W in approximately 84 feet of water. The sailboat has an estimated mast height of up to 50'. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

I NM: 36/22

ALASKA - SOUTHEAST - DUNCAN CANAL - BUTTERWORTH ISLAND

OBSTRUCTION TO NAVIGATION: A 94 foot tug has been reported sunk in the vicinity of Butterworth Island in approximate position 56°32.586′N, 133°03.855′W. Vessels transiting in the vicinity are requested to remain clear of the reported wreck. Questions/concerns should be directed to the Coast Guard Sector Juneau Command Center at 907-463-2980 or on VHF/FM channel 16.

LNM: 34/22

ALASKA - U.S. COAST GUARD MEDIUM FREQUENCY (MF) AND HIGH FREQUENCY (HF) DISTRESS WATCHKEEPING

Mariners are advised that calls to the U.S. Coast Guard on the international radiotelephone distress frequency 2182 kHz or the Digital Selective Calling (DSC) frequency 2187.5 kHz may not be heard or may be severely degraded. Instead of using 2182 kHz for distress calls, mariners may use high frequency (HF) radiotelephone or DSC in the 4, 6, 8, and 12 MHz distress or calling bands. On February 7th, 2022, the U.S. Coast Guard will discontinue monitoring high frequency (HF) voice for all existing regions with the exception of Kodiak, Alaska, and Guam. All existing regions will also continue monitoring high frequency (HF) DSC in the 4, 6, 8, and 12 MHz distress or calling bands. Mariners may also use cellular, satellite or other methods of communications to speak directly to the nearest Coast Guard Command Center. Additional information concerning U.S. Coast Guard HF watchkeeping is posted on the U.S. Coast Guard's Navigation Center website

(https://www.navcen.uscg.gov/?pageName=cgcommsCall). The three U.S. Coast Guard Command Centers (CC) located in Alaska are: CG Sector Juneau CC, 907-463-2980; CG Sector Anchorage CC, 907-428-4100; CG District 17 CC, 907-463-2000. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

I NM: 50/21

978 ALASKA – SOUTHCENTRAL – KODIAK ISLAND

975

976

977

981

982

A Waverider buoy approximately 29 nautical miles southeast of the City of Kodiak, Alaska in position 57° 28.8′ N, 151° 42.0′ W, has been decommissioned. The mooring remains on site and is marked with a cluster of unlit white floats. The mooring will be removed as operations permit. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 40/21

979 ALASKA – SOUTHEAST – BEHM CANAL – MOSER BAY

The Moser Bay Coast Guard Mooring Buoy (LLNR 22329) is missing and may be submerged and attached/entangled with a sunken vessel in the vicinity of its charted position. Mariners should transit the area with extreme caution because it may be suspended subsurface at an unknown depth. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 38/21

980 ALASKA – SOUTHEAST – KLAG BAY

Klag Bay Entrance DBN 1 (LLNR 25335) has been rebuilt in position 57°36′42.318″N, 136°06′08.130″W and is watching properly. Chart and Light List corrections will be issued once the verification process has been completed. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 37/21

ALASKA – WESTERN – YUKON RIVER

OBSTRUCTION TO NAVIGATION: A 6' by 6' by 15' metal tower is partially submerged in the Yukon River in position 62°35.55'N, 164°54.48'W. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 with any updated positions.

LNM: 28/21

ALASKA – BRISTOL BAY – NORTHEAST KVICHAK BAY – NAKNEK RIVER

A potential obstruction to navigation exists in the Naknek River in position: 58°42.772'N, 157°02.045'W. A large metal ramp has been reported to be visible during low tide and completely submerged during high tide. All mariners should utilize caution and avoid transiting in close proximity to the object. Questions/concerns should be directed to Sector Anchorage Command Center at (907) 428-4100.

LNM: 27/21

ALASKA – ALEUTIAN ISLANDS – UNALASKA – CAPTAIN'S BAY

983 Bailey Ledge LT (LLNR 27505) in Captain's Bay has been temporarily replaced with an unlit red buoy in position 53°51.603'N, 166°33.103'W.

Mariners are requested to transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17

Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 23/21

ALASKA – COOK INLET

The BAKER OIL PLATFORM warning lights (LLNR 26361) in position 60°49'45.390"N, 151°29'00.010"W and the DILLION OIL PLATFORM warning lights (LLNR 26361.5) in position 60°44'07.340"N, 151°30'42.610"W are experiencing intermittent outages. Mariners are requested to transit the area with caution. Questions/concerns should be directed to Sector Anchorage Waterways Management at anchorage.waterways@uscg.mil or (907) 428-4189.

LNM: 08/21

985 ALASKA

984

986

987

989

The Coast Guard will be using AIS Broadcasts to relay some marine information, primarily ATON Discrepancies, VHF/FM Hi-site outages, active subsistence whaling, Gunnery and Pyrotechnics Exercises, and similar Notices directly relating to safe navigation. The Coast Guard's access to AIS transmitters is limited so not all areas might be covered at any given time and the locations of the active transmitters will be determined by the priority of the messages being broadcast from them. All information broadcast by AIS will also be published by the more conventional methods of BNM and LNM. Feedback is desired and should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 43/20

ALASKA - SOUTHEAST - DIXON ENTRANCE

Tree Point LT (LLNR 21840) has been relocated to a new steel structure approximately 100 yards Southeast of the existing lighthouse structure. The approximate position for the new light is 54°48′10″N, 130°56′04″W. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 11/20

ALASKA – GULF OF ALASKA

NOAA DLB 46085 (LLNR 984.15) has been replaced with a 3-meter buoy and relocated to 55°53′18.000″N, 142°50′48.000″W. Chart and Light List corrections have been issued. The previous 6-meter buoy was not recovered and remains in position 55°52′05.000″N, 142°33′31.000″W. Mariners are requested to transit the area with caution until the previous buoy is recovered. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 33/19

988 ALASKA – SOUTHCENTRAL

The U.S. Coast Guard has VHF Digital Selective Calling (DSC) capability with limited coverage in Southcentral Alaska. The initial coverage areas are Upper Cook Inlet, Kodiak and Valdez Arm. Mariners are reminded to ensure that they have properly connected their GPS units to their DSC equipped marine VHF radios and registered for their Maritime Mobile Service Identity (MMSI) to utilize the DSC distress function. Additional information is available through the Alaska Outdoors Forum at https://forums.outdoorsdirectory.com/threads/digital-selective-calling-dsc.140270/ or by contacting Mike Folkerts with the Coast Guard District 17 Boating Safety Office at (907) 463-2297 or by email to Michael.r.folkerts@uscg.mil.

LNM: 51/23

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND - UNAKWIK INLET

An uncharted and dangerous rock has been reported in Unakwik Inlet in approximate position 61°08.045′N, 147°32.665′W. Mariners should transit the area with caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 25/19

990 ALASKA

Coast Guard District 17 is using AIS broadcasts to notify mariners of CG VHF/FM Hi-Site outages. These are geographic broadcasts that should display on properly configured, AIS equipped, chart plotters. The broadcast will display with a 40NM range ring surrounding the inoperative Hi-Site and a message stating the name of the site, it's latitude/longitude, and the telephone number of the nearest CG Command Center. An example broadcast message is "CG DECEPTION HILLS VHF SITE AT 59-05N 138-13W INOP-RELAY DISTRESS CALLS TO 9074632980". The purpose of this notification is to ensure mariners are aware of problematic VHF/FM coverage and to encourage them to relay information to the nearest CG Command Center. When relaying a distress call the most critical piece of information is an accurate position. Additional valuable information is: Nature of distress; Number of persons on board; Vessel name; On scene weather; Crew's intentions (I.E. Abandon ship, Fight the fire, ETC.). The CG Command Center may request additional information depending on the specific situation. CG VHF/FM Hi-Site outages will also be listed in each weekly Local Notice to Mariners, announced over nearby Hi-Sites by Broadcast Notice to Mariners, listed on the Coast Guard NAVCEN website at https://www.navcen.uscg.gov/broadcast-notice-to-mariners. BNM texts can also be emailed to people who request it through the NAVCEN website. Sector Juneau Command Center is 907-463-2980. Sector Anchorage Command Center is 907-428-4100. Questions/concerns should be directed to Todd Buck with the CG District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscq.mil.

LNM: 04/23

ALASKA - SOUTHEAST - FRESHWATER BAY

An uncharted rock shoal has been reported in Cedar Cove centered in approximate position 57°52.405′N, 135°03.694′W with an approximate 75 foot radius. The rocks were approximately 1 foot below a 0′ tide. The location of the reported shoal has a charted depth of 12 fathoms. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 24/19

992 ALASKA – SOUTHEAST – FARRAGUT BAY – FRANCIS ANCHORAGE

Uncharted shoaling was observed in Francis Anchorage on February 14th, 2019 in position 57°08.95′N, 133°10.03′W. The charted depth for this location is 15 fathoms and the observed depths rapidly shallowed from 120 feet and ranged from 8 to 10 feet. The navigational charts for Francis Anchorage are based on pre-1900 Partial Bottom Coverage Surveys and in 1976 'shoaling to bare' was reported further into the anchorage. Mariners should transit this area with extreme caution and be aware of areas that may not be adequately charted. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 08/19

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND - ESTHER ISLAND

OBSTRUCTION TO NAVIGATION: The 32' F/V SONG II has been reported sunk in position 60°47.76'N, 148°03.31'W. Mariners are requested to transit the area with caution and report any sightings to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 34/18

994 ALASKA - CENTRAL – BETHEL

993

995

996

999

OBSTRUCTION: The barge SHANKS ARK has been reported sunken and abandoned in Steamboat Slough on the Kuskokwim River, approximate position 60°47'15"N, 161°41'52"W. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no hazards exists. The Coast Guard has actively monitored the proper marking of the vessel by the vessel's owner and operator since September 10, 2016. Coast Guard pollution investigators confirmed the vessel does not pose a substantial pollution threat to the environment. Mariners are requested to transit the area with caution and report any discrepancies with the vessel's marking to the Coast Guard. Questions/concerns should be directed to LT David Parker, Sector Anchorage Waterways Management, at (907) 428-4189.

LNM: 11/17

ALASKA – ALEUTIAN ISLANDS – AKUTAN ISLAND – AKUTAN HARBOR

UNKNOWN MARINE ANOMALY: An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in position 54°07.70889′N, 165°46.38298W on the sea floor at a depth of 138 feet. This anomaly has not been positively identified. Mariners are requested to transit the area with caution. Questions/concerns should be directed to LT David Parker with the Coast Guard Sector Anchorage Waterways Management Branch at (907) 428-4189 or by email to david.n.parker@uscq.mil.

LNM: 03/18

ALASKA – SOUTHWESTERN – ALEUTIAN PENINSULA – BECHEVIN BAY

Shoaling has been reported at the bar along the Northern entrance to Bechevin Bay by a vessel with a draft of 10 feet that reported briefly grounding in seas running 6-8 feet. Mariners should take into account their vessel's draft, charted depth of water, tides and sea state when determining an appropriate under-keel clearance for a safe transit of this waterway. Mariners are requested to report any future groundings or significant variations from charted depth to the Coast Guard Sector Anchorage Command Center at (907) 428-4100 or on VHF/FM channel 16.

LNM: 17/18

997 ALASKA – SOUTHEAST – ICY STRAIT – NORTH INIAN PASSAGE

The currents in North Inian Passage and Glacier Bay have been observed at up to 3 knots above the NOAA published current predictions. Mariners should exercise caution when transiting the area. Questions/concerns should be directed to LT Bart Buesseler at (907) 271-3327 or by email to bart.o.buesseler@noaa.gov.

LNM: 36/17

998 ALASKA – SOUTHCENTRAL – SHELIKOF STRAIT – KINAK BAY

An uncharted rock has been reported in Kinak Bay in position 58°03.8′N, 154°25.3′W at a depth of approximately 3 fathoms. Mariners are advised to transit the area with extreme caution. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 28/19

ALASKA – SOUTHEAST – WRANGELL NARROWS

OSTRUCTION TO NAVIGATION: The P/C HEATHER ANN has sunk in Wrangell Narrows on the East side of the channel approximately 330 yards South of Wrangell Narrows Channel LT 16 (LLNR 22955). The most recent reported position was 56°37.25′N, 132°57.64′W. The P/C HEATHER ANN is a 52′ wood vessel and may be awash and barely visible at higher tides, exposed at lower tides, or relocated by the extreme current in the area. The vessel was marked with a single orange float. Mariners are requested to transit the area with extreme caution and report any changes in position to the Coast Guard Sector Juneau on VHF/FM channel 16 or by phone to (907) 463-2980.

LNM: 25/19

SECTION II - DISCREPANCIES

This section lists all reported and corrected discrepancies related to Aids to Navigation in this edition. A discrepancy is a change in the status of an aid to navigation that differs from what is published or charted.

DISCREPANCIES (FEDERAL AIDS)

| 2025 Point McCartey Buoy 3 MISSING 17420 SEAK220-24 25/24 22040 Nichols Passage East Channel Daybeacon 2 Daybeacon 3 DAYMK DMGD 17420 1299-23 42/23 22070 Metlakatla Inner Harbor Daybeacon 3 DAYMK DMGD 17420 1299-23 42/23 22125 Walden Rock Light 6 REDUCED INT/STRUCT DMGD 17420 1299-23 42/23 22155 Idaho Rock Lighted Buoy 3 LT EXT 1335-23 47/23 22155 Idaho Rock Lighted Buoy 4 LT EXT 1335-23 47/23 22150 Pennock Island Reef Lighted Buoy PR LT EXT 1339-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT 1339-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy PR LT EXT 1740 SEAK239-24 27/24 2220 Refuge Cove Daybeacon 3 STRUCT DEST 1143-22 43/22 22430 Meyers Chuck Buoy 1 SINKING EAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD EAK235-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 SEAK248-24 28/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 1174-22 51/22 22735 Mc Arthur Reef Lighted Bil Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST 113-21 41/21 22875 Wrangell Narrows Daybeacon 10A STRUCT DEST 17360 SEAK001-24 21/24 172 2305 Wrangell Narrows Orth Entrance LT EXT 17360 SEAK001-24 39/24 23206 Caperal Narrows North Entrance LT EXT 17360 3010-23 30/23 23280 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK296-24 34/24 23290 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK296-24 34/24 23290 The Eye Opener Light LT EXT LT EXT 17360 SEAK296-24 34/24 23290 The Eye Opener | LLNR | Aid Name | Status | Chart No. | BNM Ref. | LNM St | LNM End |
|---|----------|-------------------------------------|-------------------------|-----------|------------|--------|---------|
| 985 Cape Muzon Light LT EXT 17400 329-23 46/23 1030 Cape Edgecumbe Light LT EXT 17320 J099-23 14/23 1105 Cape St. Elias Buoy 2 MISSING 16016 A175-23 41/23 1131 NOAA Deta Lighted Buoy 46061 MISSING 16700 A234-23 52/23 1150 Seal Rocks Light DAYMK MISSING 16680 44/21 1260 Cape Greig Light LT EXT A076-22 33/22 1315 Poirt Romanor Light LT EXT A076-22 33/22 1315 Poirt Romanor Light DAYMK DMGD 17420 J095-22 31/22 21205 Poirt McCartey Buoy 3 MISSING 17420 J095-22 31/22 22005 Poirt McCartey Buoy 3 MISSING 17420 J095-22 41/22 22005 Poirt McCartey Buoy 3 MISSING 17420 J092-23 42/23 22006 Mayleacon 2 AUA J094-24 41/22 J092-23 42/23 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | | | | |
| 1030 Cape Edgecumbe Light | | | | | | | |
| 1105 | | , , | | | | | |
| 1131 NOAA Data Lighted Buoy 46061 MISSING 16700 A234-23 52/23 1150 Seal Rocks Light DAYMK MISSING 16680 44/21 1260 Cape Greig Light LT EXT/DAYMK DMGD A100-21 37/21 1285 Cape Mohican Light LT EXT A076-22 33/22 1315 Point Romanof Light DAYMK DMGD 17420 A153-24 36/24 21850 Cape Chacon Light DAYMK DMGD 17420 596-22 31/22 22005 Point McCartey Buoy 3 MISSING 17420 58AX220-24 25/24 22005 Nichole Passage East Channel STRUCT DEST 1130-22 41/22 22006 Metlakatia Data Harbor Light 2 DAYMK DMGD 17420 299-23 42/23 22007 Metlakatia Chantel Habor Daybeacon 3 DAYMK DMGD 17420 299-23 42/23 22150 Walden Rock Lighted Buoy 4 LT EXT 3335-23 47/23 22150 California Rock Lighted Buoy 5 LT EXT 3335-23 47/23 | | | | | | | |
| 1150 Seal Rocks Light | 1105 | Cape St. Elias Buoy 2 | MISSING | | A175-23 | 41/23 | |
| 1260 Cape Greig Light | 1131 | NOAA Data Lighted Buoy 46061 | | 16700 | A234-23 | 52/23 | |
| 1285 Cape Mohican Light LT EXT A076-22 33/22 1315 Point Romanof Light STRUCT DEST 16240 A153-24 36/24 21850 Cape Chacon Light DAYMK DMGD 17420 5095-22 31/22 22025 Point McCartey Buoy 3 MISSING 17420 SEAk220-24 25/24 22040 Nichols Passage East Channel Daybeacon 2 STRUCT DEST 1130-22 41/22 22065 Mediakatla Boat Harbor Light 2 DAYMK DMGD 17420 1299-23 42/23 22070 Mediakatla Bork Harbor Light 2 DAYMK DMGD 17420 1299-23 42/23 221150 California Rock Lighted Buoy 3 LT EXT 1335-23 47/23 22150 California Rock Lighted Buoy 4 LT EXT 3339-23 47/23 22150 Tongass Narrows Wreck Lighted Buoy PR LT EXT 3339-23 47/23 22150 Refuge Cove Daybeacon 3 STRUCT DEST 1143-22 43/22 22240 Meyers Chuck Buoy 1 SINKIMG SEAK248-24 28/24 <td>1150</td> <td>Seal Rocks Light</td> <td>DAYMK MISSING</td> <td>16680</td> <td></td> <td>44/21</td> <td></td> | 1150 | Seal Rocks Light | DAYMK MISSING | 16680 | | 44/21 | |
| 1315 Point Romanof Light STRUCT DEST 16240 A153-24 36/24 21850 Cape Chaoon Light DAYMK DMGD 17420 3095-22 31/22 22025 Point McCartey Buoy 3 MISSING 17420 5EAK220-24 25/24 22065 Nichols Passage East Channel STRUCT DEST 130-22 41/22 22065 Metlakatla Boat Harbor Daybeacon 3 DAYMK DMGD 17420 1299-23 42/23 22070 Metlakatla Inner Harbor Daybeacon 3 DAYMK DMGD 17420 1299-23 42/23 22150 California Rock Lighted Buoy 3 LT EXT 3335-23 47/23 22150 California Rock Lighted Buoy 4 LT EXT 3339-23 47/23 22150 Pennock Island Reef Lighted Buoy PR LT EXT 3339-23 47/23 22190 Pennock Island Reef Lighted Buoy SP LT EXT 3339-23 47/23 22270 Refuge Cove Daybeacon 3 STRUCT DEST 143-22 27/24 22250 Buy Shy Island Light BAYMK DMGD 5EAK235-24 27/2 | 1260 | Cape Greig Light | LT EXT/DAYMK DMGD | | A100-21 | 37/21 | |
| 22205 | 1285 | Cape Mohican Light | LT EXT | | A076-22 | 33/22 | |
| Point McCartey Buoy 3 MISSING 17420 SEAK220-24 25/24 22040 Nichols Passage East Channel Daybeacon 2 Metiakatla Boat Harbor Light 2 DAYMK DMGD 17420 2299-23 42/23 42/23 22070 Metiakatla Inner Harbor Daybeacon 3 DAYMK DMGD 17420 2299-23 42/23 42/23 22125 Walden Rock Light 6 REDUCED INT/STRUCT DMGD 17420 2292-23 42/23 42/23 22150 California Rock Lighted Buoy 3 LT EXT 3335-23 47/23 22155 Idaho Rock Lighted Buoy 4 LT EXT 3336-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT 3339-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT 3339-23 47/23 22190 Refuge Cove Daybeacon 3 STRUCT DEST 3143-22 43/22 27/24 WR6 22270 Refuge Cove Daybeacon 3 STRUCT DEST 3143-22 43/22 22730 Meyers Chuck Buoy 1 SINKING SEAK239-24 27/24 22510 Bushy Island Light DAYMK DMGD TEXT TAVE SEAK239-24 27/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 31/4-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 31/4-22 81/24 222735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 31/4-22 28/24 222863 Wrangell Narrows Daybeacon 4 STRUCT DEST 1130-21 41/21 41/21 22285 Wrangell Narrows Daybeacon 4 STRUCT DEST 1130-21 41/21 41/21 22205 Wrangell Narrows Channel Light 2 MISSING SEAK245-24 28/24 22260 Cape Fanshaw Light STRUCT DEST 17360 SEAK004-24 02/24 22260 Cape Fanshaw Light LT EXT 17360 SEAK092-24 24/24 22260 Cape Fanshaw Light LT EXT 17360 SEAK092-24 24/24 22260 Five Finger Light LT EXT 17360 SEAK092-24 24/24 22260 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK092-24 24/24 22260 Five Finger Light LT EXT 17360 SEAK092-24 24/24 22260 Five Finger Light LT EXT 17360 SEAK092-24 24/24 22260 Five Finger Light LT EXT LT EXT 17360 SEAK092-24 24/24 22260 | 1315 | Point Romanof Light | STRUCT DEST | 16240 | A153-24 | 36/24 | |
| 22040 | 21850 | Cape Chacon Light | DAYMK DMGD | 17420 | J095-22 | 31/22 | |
| Daybeacon 2 Daybeacon 3 DAYMK DMGD 17420 J299-23 42/23 22070 Metlakatla Boat Harbor Light 2 DAYMK DMGD 17420 J299-23 42/23 22125 Walden Rock Light 6 REDUCED INT/STRUCT DMGD 17420 J292-23 42/23 22150 California Rock Lighted Buoy 4 LT EXT J335-23 47/23 22155 Idaho Rock Lighted Buoy 4 LT EXT J336-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT J339-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy OFF STA SEAK239-24 27/24 22195 Tongass Narrows Wreck Lighted Buoy STRUCT DEST J143-22 43/22 22270 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 43/22 22271 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 42/24 22270 Refuge Cove Daybeacon 3 STRUCT DEST J147-20 48/24 22510 Bush J Island Light DAYMK DMGD 17360 114-22 28/24 | 22025 | Point McCartey Buoy 3 | MISSING | 17420 | SEAK220-24 | 25/24 | |
| 22070 Metlakatla Inner Harbor Daybeacon 3 DAYMK DMGD 17420 299-23 42/23 22125 Walden Rock Light 6 REDUCED INT/STRUCT DMGD 17420 299-23 42/23 22150 California Rock Lighted Buoy 3 LT EXT 3335-23 47/23 22150 Pennock Island Reef Lighted Buoy PR LT EXT 3339-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT 3339-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy PR LT EXT 5EAK239-24 27/24 22270 Refuge Cove Daybeacon 3 STRUCT DEST 1143-22 43/22 22270 Refuge Cove Daybeacon 3 STRUCT DEST 1143-22 42/24 22270 Meyers Chuck Buoy 1 SINKING SEAK239-24 27/24 22210 Meyers Chuck Buoy 1 SINKING SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 SEAK248-24 28/24 22515 Snow Passage Lighted Bell Buoy MR LT EXT 17360 1124-20 48/20 | | Daybeacon 2 | | | | • | |
| 22125 Walden Rock Lighte 6 REDUCED INT/STRUCT DMGD 17420 292-23 42/23 22150 California Rock Lighted Buoy 3 LT EXT 3335-23 47/23 22155 Idaho Rock Lighted Buoy 4 LT EXT 3336-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT 3336-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy OFF STA SEAK239-24 27/24 22270 Refuge Cove Daybeacon 3 STRUCT DEST 5EAK235-24 27/24 222430 Meyers Chuck Buoy 1 SINKING 5EAK248-24 28/24 22510 Bushy Island Light DAYMK DMGD 5EAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 5EAK201-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 5EAK201-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 1740 5EAK201-24 28/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 114-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT | | Metlakatla Boat Harbor Light 2 | DAYMK DMGD | 17420 | J299-23 | | |
| 22150 California Rock Lighted Buoy 3 LT EXT J335-23 47/23 22155 Idaho Rock Lighted Buoy 4 LT EXT J336-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT J339-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy PR LT EXT J339-23 47/23 22270 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 43/22 222430 Meyers Chuck Buoy 1 SINKING SEAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Channel Lighted Missing SEAK325-24 28/24 22916 <td< td=""><td>22070</td><td>Metlakatla Inner Harbor Daybeacon 3</td><td>DAYMK DMGD</td><td>17420</td><td>J299-23</td><td>42/23</td><td></td></td<> | 22070 | Metlakatla Inner Harbor Daybeacon 3 | DAYMK DMGD | 17420 | J299-23 | 42/23 | |
| 22155 Idaho Rock Lighted Buoy 4 LT EXT J336-23 47/23 22190 Pennock Island Reef Lighted Buoy PR LT EXT J339-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy WR6 OFF STA SEAK239-24 27/24 22270 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 43/22 22430 Meyers Chuck Buoy 1 SINKING SEAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Tow Channel Buoy ITC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Channel Lighted MISSING SEAK327-24 39/24 23205 Wrangell Narrows North Entrance Light LT EXT 17360< | 22125 | Walden Rock Light 6 | REDUCED INT/STRUCT DMGD | 17420 | J292-23 | 42/23 | |
| 22190 Pennock Island Reef Lighted Buoy PR LT EXT J339-23 47/23 22195 Tongass Narrows Wreck Lighted Buoy WR6 OFF STA SEAK239-24 27/24 22270 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 43/22 222430 Meyers Chuck Buoy 1 SINKING SEAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD SEAK001 01/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted LT EXT | 22150 | California Rock Lighted Buoy 3 | LT EXT | | J335-23 | 47/23 | |
| 22195 Tongass Narrows Wreck Lighted Buoy WR6 OFF STA SEAK239-24 27/24 22270 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 43/22 22430 Meyers Chuck Buoy 1 SINKING SEAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Tow Channel Buoy ITC MISSING SEAK105-24 12/24 22875 Wrangell Narrows Tow Channel Buoy ITC STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Light LT EXT 17360 SEAK004-2 | 22155 | Idaho Rock Lighted Buoy 4 | LT EXT | | J336-23 | 47/23 | |
| WR6 22270 Refuge Cove Daybeacon 3 STRUCT DEST J143-22 43/22 22430 Meyers Chuck Buoy 1 SINKING SEAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 J124-20 48/20 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy MI MISSING SEAK105-24 12/24 22916 Wrangell Narrows Channel Lighted MISSING SEAK327-24 39/24 23205 Wrangell Narrows North Entrance Light LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST <t< td=""><td>22190</td><td>Pennock Island Reef Lighted Buoy PR</td><td>LT EXT</td><td></td><td>J339-23</td><td>47/23</td><td></td></t<> | 22190 | Pennock Island Reef Lighted Buoy PR | LT EXT | | J339-23 | 47/23 | |
| 22430 Meyers Chuck Buoy 1 SINKING SEAK235-24 27/24 22510 Bushy Island Light DAYMK DMGD SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 1174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 1124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST 1113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy ITC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST 1128-21 47/21 23005 Wrangell Narrows Channel Lighted Busy 62 MISSING SEAK004-24 39/24 23210 Wrangell Narrows North Entrance Lighted Busy F LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 SEAK189-24 21/24 23285 Fiv | | WR6 | | | SEAK239-24 | • | |
| 22510 Bushy Island Light DAYMK DMGD SEAK248-24 28/24 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy ITC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy Expensive Mineral Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Light STRUCT DEST 17360 SEAK004-24 02/24 23220 Five Finger Light LT EXT 17360 J081-22 26/22 23280 Five Fathom Shoal Lighted Buoy | 22270 | Refuge Cove Daybeacon 3 | STRUCT DEST | | J143-22 | 43/22 | |
| 22515 Snow Passage Lighted Buoy SP LT EXT 17420 SEAK001 01/24 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 5EAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 2305 Wrangell Narrows Channel Lighted MISSING SEAK327-24 39/24 2310 Wrangell Narrows North Entrance LT EXT 17360 SEAK004-24 02/24 23210 Wrangell Narrows North Entrance LT EXT 17360 SEAK109-24 02/22 23280 Five Finger Light LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light <td< td=""><td>22430</td><td>Meyers Chuck Buoy 1</td><td>SINKING</td><td></td><td>SEAK235-24</td><td>27/24</td><td></td></td<> | 22430 | Meyers Chuck Buoy 1 | SINKING | | SEAK235-24 | 27/24 | |
| 22525 Bay Point Daybeacon BP DAYMK DMGD 17360 J174-22 51/22 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy 1TC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted STRUCT DEST 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J010-23 02/23 23280 Five Finger Light LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 | 22510 | Bushy Island Light | DAYMK DMGD | | SEAK248-24 | 28/24 | |
| 22670 Blake Channel Light 1 STRUCT DEST/LT EXT 17360 J124-20 48/20 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy 1TC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Daybeacon 4 STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 10 MISSING J148-13 32/13 2305.9 K | 22515 | Snow Passage Lighted Buoy SP | LT EXT | 17420 | SEAK001 | 01/24 | |
| 22735 Mc Arthur Reef Lighted Bell Buoy MR LT EXT 17360 SEAK245-24 28/24 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy ITC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy Korth Entrance Lighted Buoy 62 LT EXT 17360 SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 J010-23 02/23 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 10 MISSING J148-13 32/13 | 22525 | Bay Point Daybeacon BP | DAYMK DMGD | 17360 | J174-22 | 51/22 | |
| 22863 Wrangell Narrows Daybeacon 4 STRUCT DEST J113-21 41/21 22875 Wrangell Narrows Tow Channel Buoy 1TC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 J010-23 02/23 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 22670 | Blake Channel Light 1 | STRUCT DEST/LT EXT | 17360 | J124-20 | 48/20 | |
| 22875 Wrangell Narrows Tow Channel Buoy 1TC MISSING SEAK105-24 12/24 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.7 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 32/13 | 22735 | Mc Arthur Reef Lighted Bell Buoy MR | LT EXT | 17360 | SEAK245-24 | 28/24 | |
| 1TC 22916 Wrangell Narrows Daybeacon 10A STRUCT DEST J128-21 47/21 23205 Wrangell Narrows Channel Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 J010-23 02/23 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 2305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 22863 | Wrangell Narrows Daybeacon 4 | STRUCT DEST | | J113-21 | 41/21 | |
| 23205 Wrangell Narrows Channel Lighted Buoy 62 MISSING SEAK327-24 39/24 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 22875 | | MISSING | | SEAK105-24 | 12/24 | |
| Buoy 62 23210 Wrangell Narrows North Entrance Lighted Bell Buoy WN LT EXT 17360 SEAK004-24 02/24 23260 Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 J010-23 02/23 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 22916 | Wrangell Narrows Daybeacon 10A | STRUCT DEST | | J128-21 | 47/21 | |
| Lighted Bell Buoy WN Cape Fanshaw Light STRUCT DEST 17360 J081-22 26/22 23280 Five Finger Light LT EXT 17360 J010-23 02/23 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 23205 | 5 | MISSING | | | 39/24 | |
| 23280 Five Finger Light LT EXT 17360 J010-23 02/23 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | | Lighted Bell Buoy WN | | | | • | |
| 23285 Five Fathom Shoal Lighted Buoy F LT EXT 17360 SEAK189-24 21/24 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | | • | STRUCT DEST | | | | |
| 23290 The Eye Opener Light LT EXT 17360 SEAK296-24 34/24 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 23280 | Five Finger Light | LT EXT | 17360 | J010-23 | | |
| 23305.1 Keku Strait Entrance Light STRUCT DEST J069-19 38/19 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 23285 | Five Fathom Shoal Lighted Buoy F | LT EXT | 17360 | SEAK189-24 | 21/24 | |
| 23305.3 Keku Strait Daybeacon 4 STRUCT DEST SEAK217-24 25/24 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 23290 | The Eye Opener Light | LT EXT | 17360 | SEAK296-24 | 34/24 | |
| 23305.7 Keku Strait Daybeacon 10 MISSING J148-13 32/13 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 23305.1 | Keku Strait Entrance Light | STRUCT DEST | | J069-19 | 38/19 | |
| 23305.9 Keku Strait Daybeacon 13 STRUCT DEST J103-15 23/15 | 23305.3 | Keku Strait Daybeacon 4 | STRUCT DEST | | SEAK217-24 | 25/24 | |
| · | 23305.7 | Keku Strait Daybeacon 10 | MISSING | | J148-13 | 32/13 | |
| 23305.95 Keku Strait Buoy 14 MISSING J288-23 41/23 | 23305.9 | Keku Strait Daybeacon 13 | STRUCT DEST | | J103-15 | 23/15 | |
| | 23305.95 | Keku Strait Buoy 14 | MISSING | | J288-23 | 41/23 | |

| 23306 | Keku Strait Daybeacon 15 | STRUCT DEST | | J288-23 | 41/23 |
|---|--|---|-------------------------|---|--|
| 23306.2 | Keku Strait Daybeacon 18 | STRUCT DEST | | J288-23 | 41/23 |
| 23306.3 | Keku Strait Daybeacon 19 | STRUCT DEST | | SEAK217-24 | 25/24 |
| 23306.7 | Keku Strait Daybeacon 25 | STRUCT DEST | | J071-20 | 28/20 |
| 23306.8 | Keku Strait Daybeacon 26 | STRUCT DEST | | SEAK217-24 | 25/24 |
| 23306.85 | Keku Strait Daybeacon 27 | STRUCT DEST | | SEAK217-24 | 25/24 |
| 23307.05 | Keku Strait Daybeacon 31 | STRUCT DEST | | J072-20 | 28/20 |
| 23307.6 | Keku Strait Daybeacon 37 | STRUCT DEST | | J288-23 | 41/23 |
| 23307.7 | Keku Strait Daybeacon 39 | STRUCT DEST | | J074-21 | 26/21 |
| 23307.8 | Keku Strait Daybeacon 41 | STRUCT DEST | | SEAK217-24 | 25/24 |
| 23355 | Portage Pass Daybeacon 11 | STRUCT DEST | 17360 | J077-18 | 26/18 |
| 23465 | Port Alexander Light | REDUCED INT | 17320 | SEAK315-24 | 37/24 |
| 23510 | Point Ellis Light | LT EXT | 17320 | J028-21 | 08/21 |
| 23530 | Point Gardner Light | LT EXT | 17320 | | 34/24 |
| 23595 | Hobart Bay Light 2 | DAYMK MISSING | 17360 | J247-23 | 34/23 |
| 23600 | Point Gambier Light | LT EXT | 17360 | J362-23 | 51/23 |
| 23785 | Middle Point Light | LT EXT | 17300 | SEAK309-24 | 36/24 |
| 23945.1 | Favorite Reef B 2 | MISSING | 17300 | SEAK281-24 | 33/24 |
| 23960 | False Point Retreat Light 4 | Status Unreported | 17300 | SEAK330-24 | 40/24 |
| 24260 | Elfin Cove Daybeacon 5 | STRUCT DEST | | J017-18 | 36/19 |
| 24300 | Lisianski Inlet Daybeacon 4 | STRUCT DEST | 17300 | J272/23 | 39/23 |
| 24330 | Cape Muzon Light | LT EXT | 17400 | J329-23 | 46/23 |
| 24445 | Tlevak Narrows Buoy 4 | MISSING | 17400 | SEAK244-24 | 28/24 |
| 24545 | Hermanos Islands Reef Lighted Buoy 8 | LT EXT | 17400 | SEAK302-24 | 35/24 |
| 24575 | Klawock Reef Lighted Buoy 1 | LT EXT | 17400 | J017-23 | 03/23 |
| 24790 | Dry Pass Daybeacon 3 | STRUCT DEST | | J072-18 | 23/18 |
| 24910 | Cape Edgecumbe Light | LT EXT | 17320 | J099-23 | 14/23 |
| 24915 | Vitskari Island Light | RAC INOP | 17320 | J211-23 | 29/23 |
| 24948 | Indian River Flats Lighted Buoy 2 | LT EXT | | J032-20 | 09/20 |
| 25025 | Sitka Breakwater Light 7 | LT EXT | | SEAK249-24 | 28/24 |
| 25205 | Wayanda Ledge Buoy 10 | MISSING | | SEAK328-24 | 39/24 |
| 25205 | Wayanda Ledge Buoy 10 | Status Unreported | | | 39/24 |
| 25355 | Dippy Island Rock Daybeacon 3 | STRUCT DEST | | J112-22 | 35/22 |
| 25525 | Schooner Rock Light 1 | LT EXT | 16700 | A164-24 | 40/24 |
| 25535 | Johnstone Point Light | LT EXT | | A073-23 | 17/23 |
| 25550 | Hanks Island Rock Light 5 | STRUCT DEST | | A233-23 | 52/23 |
| 25575 | 0 7 1 1 01 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | | | 06/24 |
| | Orca Inlet Channel Light 12 | STRUCT DEST | 16700 | A020-24 | 06/24 |
| 25646 | NOAA Data Lighted Buoy 46060 | STRUCT DEST ADRIFT | 16700 16700 | A020-24 A009-23 | 04/23 |
| 25646 25662 | | | | | |
| | NOAA Data Lighted Buoy 46060 | ADRIFT | | A009-23 | 04/23 |
| 25662 | NOAA Data Lighted Buoy 46060 Bligh Reef Light | ADRIFT DAYMK DMGD | | A009-23 A071-24 | 04/23 17/24 |
| 25662 25662 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light | ADRIFT DAYMK DMGD LT EXT | | A009-23 A071-24 A150-24 | 04/23 17/24 36/24 |
| 25662 25662 25725 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light Entrance Point Light 12 | ADRIFT DAYMK DMGD LT EXT LT EXT | 16700 | A009-23 A071-24 A150-24 A144-24 | 04/23 17/24 36/24 32/24 |
| 25662 25662 25725 25735 25823 25824 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light Entrance Point Light 12 Entrance Island Light 14 Valdez Security Zone Lighted Buoy A Valdez Security Zone Lighted Buoy B | ADRIFT DAYMK DMGD LT EXT LT EXT LT EXT LT EXT LT EXT | 16700 | A009-23 A071-24 A150-24 A144-24 A124-24 A230-23 A231-23 | 04/23 17/24 36/24 32/24 28/24 01/23 52/23 |
| 25662 25662 25725 25735 25823 25824 25982 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light Entrance Point Light 12 Entrance Island Light 14 Valdez Security Zone Lighted Buoy A Valdez Security Zone Lighted Buoy B NOAA Data Lighted Buoy 46076 | ADRIFT DAYMK DMGD LT EXT LT EXT LT EXT LT EXT LT EXT LT EXT OFF STA | 16700 16700 | A009-23 A071-24 A150-24 A144-24 A124-24 A230-23 A231-23 A 023-24 | 04/23 17/24 36/24 32/24 28/24 01/23 52/23 07/24 |
| 25662 25662 25725 25735 25823 25824 25982 25982 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light Entrance Point Light 12 Entrance Island Light 14 Valdez Security Zone Lighted Buoy A Valdez Security Zone Lighted Buoy B NOAA Data Lighted Buoy 46076 NOAA Data Lighted Buoy 46076 | ADRIFT DAYMK DMGD LT EXT LT EXT LT EXT LT EXT LT EXT OFF STA OFF STA | 16700 | A009-23 A071-24 A150-24 A144-24 A124-24 A230-23 A231-23 A 023-24 A060-20 | 04/23 17/24 36/24 32/24 28/24 01/23 52/23 07/24 23/20 |
| 25662 25662 25725 25735 25823 25824 25982 25982 26020 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light Entrance Point Light 12 Entrance Island Light 14 Valdez Security Zone Lighted Buoy A Valdez Security Zone Lighted Buoy B NOAA Data Lighted Buoy 46076 NOAA Data Lighted Buoy 46076 Seward East Breakwater Light 2 | ADRIFT DAYMK DMGD LT EXT LT EXT LT EXT LT EXT LT EXT OFF STA DAYMK DMGD | 16700 16700 16700 | A009-23 A071-24 A150-24 A144-24 A124-24 A230-23 A231-23 A 023-24 A060-20 A146-24 | 04/23 17/24 36/24 32/24 28/24 01/23 52/23 07/24 23/20 34/24 |
| 25662 25662 25725 25735 25823 25824 25982 25982 | NOAA Data Lighted Buoy 46060 Bligh Reef Light Bligh Reef Light Entrance Point Light 12 Entrance Island Light 14 Valdez Security Zone Lighted Buoy A Valdez Security Zone Lighted Buoy B NOAA Data Lighted Buoy 46076 NOAA Data Lighted Buoy 46076 | ADRIFT DAYMK DMGD LT EXT LT EXT LT EXT LT EXT LT EXT OFF STA OFF STA | 16700 16700 | A009-23 A071-24 A150-24 A144-24 A124-24 A230-23 A231-23 A 023-24 A060-20 | 04/23 17/24 36/24 32/24 28/24 01/23 52/23 07/24 23/20 |

| 26560 | Hanin Rock Light | LT EXT | | 16580 | A035-23 | 10/23 | |
|---|---|---|----------|------------------|---|--|----------------|
| 26665 | Woody Island Channel Buoy 6 | MISSING | | | A142-24 | 30/24 | |
| 26910 | Aiaktalik Island Light 5 | DAYMK DMGD | | 16580 | A133-20 | 49/20 | |
| 26960 | Harvester Island Spit Light 2 | DAYMK DMGD | | 16580 | A159-23 | 37/23 | |
| 27000 | Northeast Arm Light 1 | STRUCT DEST | | 16580 | A143-21 | 50/21 | |
| 27025 | Dry Spruce Island Rock Light 7 | LT EXT | | 16580 | A008-22 | 06/22 | |
| 27155 | Goloi Sandspit Light 3 | LT EXT/STRUCT DMGD | | 16540 | A177-23 | 41/23 | |
| 27250 | Bechevin Bay Entrance Buoy BB | MISSING | | 16520 | A130-21 | 43/21 | |
| 27410 | Isanotski Strait Light 3 | LT EXT | | 16520 | A222-23 | 50/23 | |
| 27465 | Rocky Point Shoal Lighted Buoy RP | LT EXT | | | A120-24 | 25/24 | |
| 27500.75 | Eider Point Lighted Buoy EP | LT EXT | | 16500 | A-157-24 | 37/24 | |
| 27505 | Bailey Ledge Light | LT EXT/STRUCT DMGD | | 16520 | A122-20 | 43/20 | |
| 27542 | Sweeper Cove Range Front Light | DAYMK DMGD | | | A223-23 | 50/23 | |
| 27827 | St. George Harbor Entrance Light 1 | STRUCT DEST | | | A118-22 | 42/22 | |
| 27872 | Okwega Pass Light OP | STRUCT DEST | | 16240 | A149-23 | 36/23 | |
| 27895 | Point Romanof Light | STRUCT DEST | | 16240 | A153-24 | 36/24 | |
| 27972 | Nome Harbor Range Front Light | LT EXT | | 16200 | A145-24 | 33/24 | |
| ISCREPANCIES | (FEDERAL AIDS) CORRECTED | | | | | | |
| LLNR | Aid Name | Status | | Chart No. | BNM Ref. | LNM St | LNM End |
| | | | | 47000 | CEAL(220.24 | 34/24 | 40/24 |
| 23455 | Point Crowley Light | WATCHING PROPERLY | | 17320 | SEAK329-24 | 37/27 | , |
| 23455 26075 | Point Crowley Light Chugach Passage Lighted Buoy 2 | WATCHING PROPERLY WATCHING PROPERLY | | 1/320 16640 | A166-24 | 13/24 | 40/24 |
| 26075 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) | | | 16640 | A166-24 | 13/24 | |
| 26075 ISCREPANCIES LLNR | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name | WATCHING PROPERLY Status | | | A166-24 BNM Ref. | 13/24 LNM St | 40/24 |
| 26075 SCREPANCIES LLNR 22201 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light | WATCHING PROPERLY Status STRUCT DEST | | 16640 | BNM Ref. J202-15 | 13/24 LNM St 47/15 | 40/24 |
| 26075 SCREPANCIES LLNR 22201 22202 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light | Status STRUCT DEST STRUCT DEST | | 16640 | BNM Ref. J202-15 J203-15 | 13/24 LNM St 47/15 47/15 | 40/24 |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light | Status STRUCT DEST STRUCT DEST STRUCT DEST | | 16640 | BNM Ref. J202-15 J203-15 J204-15 | 13/24 LNM St 47/15 47/15 47/15 | 40/24 |
| 26075 SCREPANCIES LLNR 22201 22202 22203 23908 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 | 13/24 LNM St 47/15 47/15 47/15 38/14 | 40/24 |
| 26075 SCREPANCIES LLNR 22201 22202 22203 23908 25822 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA | | 16640 | BNM Ref. J202-15 J203-15 J204-15 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 | 40/24 |
| 26075 SCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 | 40/24 |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 | LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 | 40/24 |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 | 40/24 |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 | LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 | 40/24 |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 | 40/24 |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 Seward Marine Dock Light | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST | | 16640 | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 | 40/24 LNM Enc |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 Seward Marine Dock Light (PRIVATE AIDS) CORRECTED | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST LT EXT | | 16640 Chart No. | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 A097-23 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 20/22 | 40/24 LNM Enc |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 ISCREPANCIES LLNR | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 Seward Marine Dock Light (PRIVATE AIDS) CORRECTED Aid Name | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST LT EXT | | 16640 Chart No. | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 A097-23 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 20/22 | 40/24 LNM Enc |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 ISCREPANCIES LLNR | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 Seward Marine Dock Light (PRIVATE AIDS) CORRECTED Aid Name | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST LT EXT | Position | 16640 Chart No. | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 A097-23 | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 20/22 LNM St | LNM End |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 ISCREPANCIES LLNR PLATFORM DISC | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 Seward Marine Dock Light (PRIVATE AIDS) CORRECTED Aid Name | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST LT EXT | Position | 16640 Chart No. | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 A097-23 BNM Ref. | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 20/22 LNM St | LNM End |
| 26075 ISCREPANCIES LLNR 22201 22202 22203 23908 25822 25823.1 25893 26005 26010 ISCREPANCIES LLNR One PLATFORM DISC Name One | Chugach Passage Lighted Buoy 2 (PRIVATE AIDS) Aid Name Bar Harbor Breakwater East Light Bar Harbor Breakwater Middle Light Bar Harbor Breakwater West Light Port Chilkoot Mooring Dolphin Lights (2) Port Valdez Servs Dock Lights (2) Valdez Security Zone Daybeacon A Whittier Passenger Dock Lights (2) 4th of July Channel LT 1 Seward Marine Dock Light (PRIVATE AIDS) CORRECTED Aid Name | Status STRUCT DEST STRUCT DEST STRUCT DEST LT EXT OFF STA DAYMK MISSING LT EXT STRUCT DEST LT EXT | Position | 16640 Chart No. | BNM Ref. J202-15 J203-15 J204-15 J175-14 A067-19 A031-10 A097-23 BNM Ref. | 13/24 LNM St 47/15 47/15 47/15 38/14 24/19 34/24 20/10 23/23 20/22 LNM St | |

SECTION III - TEMPORARY CHANGES and TEMPORARY CHANGES CORRECTED

This section contains temporary changes and corrections to Aids to Navigation for this edition. When charted aids are temporarily relocated for dredging, testing, evaluation, or marking an obstruction, a temporary correction shall be listed in Section IV giving the

None

new position.

| LLNR | Aid Name | Status | Chart No. | BNM Ref. | LNM St | LNM End |
|-----------|---|--------------|-----------|----------|--------|---------|
| 22329 | Moser Bay Coast Guard Lighted Mooring Buoy | DISCONTINUED | 17420 | | 14/24 | |
| 23355 | Portage Pass Daybeacon 11 | TRUB | 17360 | J093-18 | 30/18 | |
| 23790 | Horse Shoal Light 1 | DISCONTINUED | 17300 | J102-19 | 51/19 | |
| 23945 | Favorite Reef Light 2 | DISCONTINUED | 17300 | J152-23 | 24/23 | |
| 24065 | Tenakee Inlet Entrance Light 1 | DISCONTINUED | 17300 | J172-22 | 50/22 | |
| 24957 | Mitchell Rock Daybeacon | DISCONTINUED | | J022-17 | 04/17 | |
| 25025.5 | Japonski Island Daybeacon 2 | DISCONTINUED | 17320 | J196-16 | 49/16 | |
| 25575 | Orca Inlet Channel Light 12 | TRLB | 16700 | A138-24 | 30/24 | |
| 25647 | NOAA Data Lighted Buoy 46081 | DISCONTINUED | 16700 | A126-19 | 46/19 | |
| 25805 | Port Valdez Coast Guard Mooring Buoy | DISCONTINUED | | A095-18 | 33/18 | |
| RARY CHAN | GES CORRECTED | | | | | |

TEMPORARY CHANGES CORRECTED

| LLNR | Aid Name | Status | Chart No. | BNM Ref. | LNM St | LNM End |
|------|-----------------|--------|-------------|---------------|--------|---------|
| | / II a i tairic | Status | Citat Citot | Ditti i itcii | | |

None

PLATFORM TEMPORARY CHANGES

| Name Status Position Binim Ref. Linim St | Name | Status | Position | BNM Ref. | LNM St | LNM End |
|--|------|--------|----------|----------|--------|---------|
|--|------|--------|----------|----------|--------|---------|

None

PLATFORM TEMPORARY CHANGES CORRECTED


| Name Status Position BNM Ref. LNM St LNM | M End |
|--|-------|
|--|-------|

None

SECTION IV - CHART CORRECTIONS

This section contains corrections to federally and privately maintained Aids to Navigation, as well as NOS corrections.

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. It is up to the mariner to decide which chart(s) are to be corrected. The following example explains individual elements of a typical chart correction.



(Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (NM) unless otherwise noted.

513 10th Ed. 01-NOV-18 Last LNM: 26/22 NAD 83 40/24

ChartTitle: Bering Sea Southern Part

Main Panel 2403 BERING SEA SOUTHERN PART - -. Page/Side: -

RELOCATE NOAA Tsunami Warning Lighted Buoy 21414 CGD17

RELOCATE NOAA Tsunami Warning Lighted Buoy 21414 from 48-56-17.000N to 48-58-12.000N 178-09-54.000E

530 35th Ed. 01-DEC-15 Last LNM: 34/22 NAD 83 40/24

ChartTitle: North America West Coast San Diego to Aleutian Islands and Hawai'ian Islands Main Panel 2405 SAN DIEGO TO ALEUTIAN ISLANDS AND HAWAIIAN ISLANDS. Page/Side: A CGD17 RELOCATE NOAA Tsunami Warning Lighted Buoy 21414 from 48-56-17,000N 178-16-52,000E 48-58-12.000N 178-09-54.000E 16012 24th Ed. 01-DEC-15 Last LNM: 26/22 **NAD 83** 40/24 ChartTitle: Aleutian Islands Amukta Island to Attu Island Main Panel 2416 AMUKTA ISLAND TO ATTU ISLAND. Page/Side: A CGD17 from 48-56-17.000N 178-16-52.000E RELOCATE NOAA Tsunami Warning Lighted Buoy 21414 48-58-12.000N 178-09-54.000E 16013 31st Ed. 01-JUN-15 40/24 Last LNM: 34/22 **NAD 83** ChartTitle: Cape St. Elias to Shumagin Islands; Semidi Islands Main Panel 2417 CAPE ST. ELIAS TO SHUMAGIN ISLANDS. Page/Side: A NOS LAST EDITION No new editions of chart 16013 will be published. It will be canceled on 02-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16016 22nd Ed. 40/24 01-AUG-12 Last LNM: 22/22 **NAD 83** ChartTitle: Dixon Entrance to Cape St. Elias Main Panel 2419 DIXON ENTRANCE TO CAPE ST. ELIAS. Page/Side: N/A NOS LAST EDITION No new editions of chart 16016 will be published. It will be canceled on 02-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16200 40/24 16th Ed. 01-DEC-18 Last LNM: 51/19 **NAD 83** ChartTitle: Norton Sound:Golovnin Bay Main Panel 2449 NORTON SOUND TO BERING STRAIT - -. Page/Side: -NOS LAST EDITION No new editions of chart 16200 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16220 40/24 7th Fd 01-DEC-18 Last LNM: 51/18 **NAD 83** ChartTitle: Bering Sea St. Lawrence Island to Bering Strait Main Panel 2571 BERING SEA ST. LAWRENCE ISLAND TO BERING STRAIT - -. Page/Side: -NOS LAST EDITION No new editions of chart 16220 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16240 Last LNM: 38/21 40/24 01-MAY-15 **NAD 83** ChartTitle: Cape Ramonzof to St. Michael; St. Michael Bay; Approaches to Cape Ramanzof Main Panel 2454 CAPE ROMANZOF TO ST. MICHAEL. Page/Side: A NOS LAST EDITION No new editions of chart 16240 will be published. It will be canceled on 30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml. 16300 10th Ed. 01-NOV-13 Last LNM: 38/21 **NAD 83** 40/24 ChartTitle: Kuskokwim Bay; Goodnews Bay Main Panel 2457 KUSKOKWIM BAY. Page/Side: N/A

LAST EDITION No new editions of chart 16300 will be published. It will be canceled on

30-Oct-24. Comparable or larger scale Electronic Navigational Chart (ENC) coverage is available. See "Cancellation of NOAA Paper and Raster Nautical Charts" in Section I of this LNM for details. A list of all canceled NOAA charts is at https://www.charts.noaa.gov/MCD/Dole.shtml.

NOS

Page 15 of 20 Coast Guard District 17

| 16380 Chart | 16th E Title: Pribilof Isla | | 01-FEB-15 | Last LNM: 05/15 | NAD 83 | | 40/24 |
|-----------------------------|------------------------------------|--|--|--|---|-------------|-------|
| | Main Panel 246 | 5 PRIB | ILOF ISLANDS. | Page/Side: A | | NOS | |
| | LAST EDITION | 30-Oct- (ENC) c Nautica | 24. Comparable c overage is availat l Charts" in Sectic | 16380 will be published. In larger scale Electronic Noble. See "Cancellation of Non I of this LNM for details/www.charts.noaa.gov/Mo | avigational Chart OAA Paper and Raster . A list of all canceled | | |
| 16420 Chart 7 | | s Buldir | 01-DEC-15 | | NAD 83 | | 40/24 |
| | Main Panei 246 | 8 NEA | RISLANDS BUL | DIR ISLAND TO ATTU IS | SLAND. Page/Side: A | NOS | |
| | LAST EDITION | 30-Oct- (ENC) c Nautica | 24. Comparable c overage is availat I Charts" in Sectic | 16420 will be published. I or larger scale Electronic Nole. See "Cancellation of Non I of this LNM for details /www.charts.noaa.gov/Mo | avigational Chart OAA Paper and Raster . A list of all canceled | | |
| 16421 Chart | 11th E Title: Ingenstrem | | 01-MAY-15 to Attu Island | Last LNM: 22/16 | NAD 83 | | 40/24 |
| | • | | | ENSTREM ROCKS TO AT | TU I. Page/Side: A | NOC | |
| | LAST EDITION | 30-Oct- (ENC) c Nautica | 24. Comparable c overage is availat I Charts" in Sectic | 16421 will be published. In larger scale Electronic Noble. See "Cancellation of Non I of this LNM for details/www.charts.noaa.gov/Mo | avigational Chart OAA Paper and Raster . A list of all canceled | NOS | |
| 16440 Chart 7 | | Semiso | 01-DEC-15 pochnoi Island t ISLANDS. Page | | NAD 83 | No. | 40/24 |
| | LAST EDITION | 30-Oct- (ENC) c Nautica | 24. Comparable c overage is availat I Charts" in Sectic | 16440 will be published. In larger scale Electronic Noble. See "Cancellation of Non I of this LNM for details/www.charts.noaa.gov/Mo | avigational Chart OAA Paper and Raster . A list of all canceled | NOS | |
| 16460 Chart 7 | 17th E | Semiso | • | Last LNM: 49/15 | NAD 83 | | 40/24 |
| | | | | SEMISOPOCHNOI ISLAN | • | NOS | |
| | LAST EDITION | 30-Oct- (ENC) c Nautica | 24. Comparable c overage is availat I Charts" in Sectic | 16460 will be published. I or larger scale Electronic Nole. See "Cancellation of Non I of this LNM for details /www.charts.noaa.gov/Mo | avigational Chart OAA Paper and Raster . A list of all canceled | | |
| 16480 Chart 7 | | nd to Igit | • | Last LNM: 29/16 Cove Seguam Island;S IGITKIN ISLAND. Page/ | • | ilia Island | 40/24 |
| | | No new 30-Oct- (ENC) c Nautical | editions of chart 24. Comparable c overage is availab I Charts" in Sectio | 16480 will be published. I or larger scale Electronic N ole. See "Cancellation of N on I of this LNM for details /www.charts.noaa.gov/M | it will be canceled on avigational Chart OAA Paper and Raster . A list of all canceled | NOS | |
| 16500 <i>Chart</i> 7 | 12th E Title: Unalaska I. | to Amul | | Last LNM: 49/15 | NAD 83 | | 40/24 |
| | | No new 30-Oct- (ENC) c Nautical | editions of chart 24. Comparable c overage is availab I Charts" in Sectio | JKTA I. Page/Side: A 16500 will be published. I or larger scale Electronic N ole. See "Cancellation of N on I of this LNM for details /www.charts.noaa.gov/M | avigational Chart OAA Paper and Raster . A list of all canceled | NOS | |
| 16520 Chart 7 | 25th E <i>Title:</i> Unimak and | | 01-DEC-15 Passes and ap | Last LNM: 51/19 proaches;Amak Island | NAD 83 | | 40/24 |

| Main Panel 2518 UNIMAK A | ND AKUTAN PASSES. Page/Side | e: A | | |
|---|--|---|---------|-------|
| 04-Dec-24. Co (ENC) covera <u>c</u> Nautical Chart | ns of chart 16520 will be published emparable or larger scale Electronic ge is available. See "Cancellation of s" in Section I of this LNM for detai s at https://www.charts.noaa.gov/l | November 1 November 1 November 1 November 2 | NOS | |
| ChartTitle: Shumagin Islands to San | CT-10 Last LNM: 34/17 ak Islands;Mist Harbor I ISLANDS TO SANAK ISLANDS. | NAD 83 Page/Side: N/A | | 40/24 |
| 04-Dec-24. Co (ENC) covera <u>c</u> Nautical Chart | ns of chart 16540 will be published omparable or larger scale Electronic ge is available. See "Cancellation of s" in Section I of this LNM for detai s at https://www.charts.noaa.gov/l | November 1 November 1 November 1 November 2 | NOS | |
| ChartTitle: Wide Bay to Cape Kumlik | | NAD 83 | | 40/24 |
| Main Panel 2544 WIDE BAY | TO CAPE KUMLIK. Page/Side: A | 1 | NOS | |
| 04-Dec-24. Co (ENC) coverag Nautical Chart | ns of chart 16568 will be published, omparable or larger scale Electronic ge is available. See "Cancellation of s" in Section I of this LNM for detai s at https://www.charts.noaa.gov/l | Navigational Chart NOAA Paper and Raster ils. A list of all canceled | | |
| 16580 15th Ed. 01-M ChartTitle: Kodiak Island;Southwest Main Panel 2546 KODIAK IS | • . | NAD 83 | Nos | 40/24 |
| 04-Dec-24. Co (ENC) covera <u>c</u> Nautical Chart | ns of chart 16580 will be published omparable or larger scale Electronic ge is available. See "Cancellation of s" in Section I of this LNM for detai s at https://www.charts.noaa.gov/N | November 1 November 1 November 1 November 2 | NOS | |
| ChartTitle: Cook Inlet-southern part | CT-11 Last LNM: 07/20 ET SOUTHERN PART. Page/Side | NAD 83 e: N/A | | 40/24 |
| 04-Dec-24. Co (ENC) covera <u>c</u> Nautical Chart | ns of chart 16640 will be published omparable or larger scale Electronic pe is available. See "Cancellation of s" in Section I of this LNM for details at https://www.charts.noaa.gov/N | November 1 November 1 November 1 November 2 | NOS | |
| 16660 31st Ed. 01-A ChartTitle: Cook Inlet-northern part | PR-12 Last LNM: 07/20 | NAD 83 | | 40/24 |
| • | ET NORTHERN PART. Page/Side | e: N/A | | |
| 04-Dec-24. Co (ENC) covera <u>c</u> Nautical Chart | ns of chart 16660 will be published omparable or larger scale Electronic ge is available. See "Cancellation of is" in Section I of this LNM for detaits at https://www.charts.noaa.gov/N | November 1 November 1 November 1 November 2 | NOS | |
| ChartTitle: Point Elrington to East C | JN-15 Last LNM: 23/15 hugach Island HNGTON TO EAST CHUGACH ISI | NAD 83 | | 40/24 |
| LAST EDITION No new editio 04-Dec-24. Co | | | NOS | |
| Nautical Chart | ns of chart 16680 will be published imparable or larger scale Electronic ge is available. See "Cancellation of is" in Section I of this LNM for detaits at https://www.charts.noaa.gov/l | November 1 November 1 November 1 November 2 | | |
| Nautical Chart NOAA charts i | omparable or larger scale Electronic ge is available. See "Cancellation of s" in Section I of this LNM for detai | November 1 November 1 November 1 November 2 | | 40/24 |

NOS

| LAST EDITION | 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect | rt 16700 will be published. : e or larger scale Electronic N able. See "Cancellation of N ion I of this LNM for details :://www.charts.noaa.gov/M | Navigational Chart NOAA Paper and Raster s. A list of all canceled | | |
|--|--|--|---|---------------------------|--------------------|
| 16760 11th ChartTitle: Cross Sou | ınd to Yakutat Bay | Last LNM: 34/20 YAKUTAT BAY. Page/Sid | NAD 83 | | 40/24 |
| Walli Fallel 20 | 13 CKO33 300ND 10 | TAROTAT BAT. Page/Sit | ue. A | NOS | |
| LAST EDITION | 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect | rt 16760 will be published. It is a relation of National See "Cancellation of Nation I of this LNM for details://www.charts.noaa.gov/Moterational.com/Moteratio | Navigational Chart NOAA Paper and Raster s. A list of all canceled | | |
| ChartTitle: Stephens | • | Last LNM: 29/21 d, including Lynn Canal GE TO CROSS SOUND IN | NAD 83 CLUDING LYNN CANA | AL. Page/Side: N/A | 40/24 |
| | | | | NOS | |
| LAST EDITION | 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect | rt 17300 will be published. It is a relation of Name or larger scale Electronic Nable. See "Cancellation of Nation I of this LNM for details://www.charts.noaa.gov/Materials.relations | Navigational Chart NOAA Paper and Raster s. A list of all canceled | | |
| 7320 20th ChartTitle: Coronatio | Ed. 01-FEB-17 n Island to Lisianski Str | Last LNM: 09/22 ait | NAD 83 | | 40/24 |
| Main Panel 26 | 344 CORONATION ISLA | ND TO LISIANSKI STRAI | T. Page/Side: A | NOC | |
| LAST EDITION | 04-Dec-24. Comparable (ENC) coverage is avail | rt 17320 will be published. : e or larger scale Electronic N able. See "Cancellation of N tion I of this LNM for details | Navigational Chart NOAA Paper and Raster | NOS | |
| | | ://www.charts.noaa.gov/M | CD/Dole.shtml. | | |
| ChartTitle: Etolin Isla Main Panel 26 | NOAA charts is at https Ed. 01-JUN-15 nd to Midway Islands, ir 379 ETOLIN ISL TO MID | ://www.charts.noaa.gov/M Last LNM: 31/22 ncluding Sumner Strait;Ho WAY ISL INCLUDING SUI | NAD 83 olkham Bay;Big Castle MNER STRAIT. Page/S | Side: A NOS | 40/24 |
| ChartTitle: Etolin Isla Main Panel 26 | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir TO ETOLIN ISL TO MID I No new editions of char O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect | ://www.charts.noaa.gov/M Last LNM: 31/22 ncluding Sumner Strait;Ho | NAD 83 blkham Bay;Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled | Side: A | 40/24 |
| ChartTitle: Etolin Isla Main Panel 26 LAST EDITION 7400 19th ChartTitle: Dixon Ent | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir FO ETOLIN ISL TO MID No new editions of char 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-JUL-20 rance to Chatham Strait | Last LNM: 31/22 ncluding Sumner Strait;Ho WAY ISL INCLUDING SUI rt 17360 will be published. e or larger scale Electronic N able. See "Cancellation of N cion I of this LNM for details:://www.charts.noaa.gov/Mi Last LNM: 28/20 | NAD 83 clkham Bay;Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster s. A list of all canceled CD/Dole.shtml. NAD 83 | Side: A NOS | 40/24 40/24 |
| ChartTitle: Etolin Isla Main Panel 26 LAST EDITION 7400 19th ChartTitle: Dixon Ent Main Panel 27 | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir 179 ETOLIN ISL TO MID I No new editions of char 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-JUL-20 I arace to Chatham Strait 15 DIXON ENTRANCE I No new editions of char 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect | Last LNM: 31/22 ncluding Sumner Strait;Ho WAY ISL INCLUDING SUI rt 17360 will be published. e or larger scale Electronic N able. See "Cancellation of N cion I of this LNM for details:://www.charts.noaa.gov/Mi Last LNM: 28/20 | NAD 83 bikham Bay;Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 Page/Side: - It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled | Side: A NOS | |
| ChartTitle: Etolin Isla Main Panel 26 LAST EDITION 7400 19th ChartTitle: Dixon Ent Main Panel 27 LAST EDITION 7420 29th ChartTitle: Hecate Str | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir INO new editions of char 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-JUL-20 Indicate to Chatham Strait INOAD ENTRANCE INO New editions of char 04-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-FEB-13 Indicate to Etolin Island, inclination | Last LNM: 31/22 ncluding Sumner Strait;Ho WAY ISL INCLUDING SUI rt 17360 will be published. e or larger scale Electronic N able. See "Cancellation of N cion I of this LNM for details: //www.charts.noaa.gov/Mi Last LNM: 28/20 TO CHATHAM STRAIT rt 17400 will be published. e or larger scale Electronic N able. See "Cancellation of N cion I of this LNM for details | NAD 83 bikham Bay;Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 Page/Side: - It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 I Canals | Side: A NOS NOS | |
| ChartTitle: Etolin Isla Main Panel 26 LAST EDITION 7400 19th ChartTitle: Dixon Ent Main Panel 27 LAST EDITION 7420 29th ChartTitle: Hecate Str Main Panel 27 | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir INO new editions of chart O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-JUL-20 Indicate to Chatham Strait INO new editions of chart O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-FEB-13 Indicate to Etolin Island, incluing INO new editions of chart INO new editions of chart INO NOAA charts is at https Ed. 01-FEB-13 Indicate STRAIT TO INO new editions of chart INO new editions of cha | Last LNM: 31/22 ncluding Sumner Strait;Ho WAY ISL INCLUDING SUI rt 17360 will be published. e or larger scale Electronic N able. See "Cancellation of N cion I of this LNM for details: ://www.charts.noaa.gov/Mc Last LNM: 28/20 TO CHATHAM STRAIT rt 17400 will be published. e or larger scale Electronic N able. See "Cancellation of N cion I of this LNM for details: ://www.charts.noaa.gov/Mc Last LNM: 34/18 uding Behm and Portland | NAD 83 bilkham Bay;Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 Page/Side: - It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 I Canals Side: N/A It will be canceled on Navigational Chart NOAA Paper and Raster Side: N/A It will be canceled on Navigational Chart NOAA Paper and Raster Side: N/A | Side: A NOS NOS | 40/24 |
| ChartTitle: Etolin Isla Main Panel 26 LAST EDITION 17400 19th ChartTitle: Dixon Ent Main Panel 27 LAST EDITION 17420 29th ChartTitle: Hecate Str Main Panel 27 | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir INO new editions of chart O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-JUL-20 Indicate to Chatham Strait INO new editions of chart O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-FEB-13 Indicate to Etolin Island, incluing INO new editions of chart INO new editions of chart INO NOAA charts is at https Ed. 01-FEB-13 Indicate STRAIT TO INO new editions of chart INO new editions of cha | Last LNM: 31/22 ncluding Sumner Strait; Howay ISL INCLUDING SUI rt 17360 will be published. e or larger scale Electronic Nable. See "Cancellation of Notion I of this LNM for details://www.charts.noaa.gov/Mr Last LNM: 28/20 TO CHATHAM STRAIT rt 17400 will be published. e or larger scale Electronic Nable. See "Cancellation of Notion I of this LNM for details://www.charts.noaa.gov/Mr Last LNM: 34/18 uding Behm and Portland DETOLIN ISLAND. Page/ rt 17420 will be published. e or larger scale Electronic Nable. See "Cancellation of Notion I of this LNM for details://www.charts.noaa.gov/Mr to r larger scale Electronic Nable. See "Cancellation of Notion I of this LNM for details://www.charts.noaa.gov/Mr | NAD 83 bilkham Bay;Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 Page/Side: - It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 I Canals Side: N/A It will be canceled on Navigational Chart NOAA Paper and Raster Side: N/A It will be canceled on Navigational Chart NOAA Paper and Raster Side: N/A | NOS NOS | 40/24 |
| ChartTitle: Etolin Isla Main Panel 26 LAST EDITION 17400 19th ChartTitle: Dixon Ent Main Panel 27 LAST EDITION 17420 29th ChartTitle: Hecate Str Main Panel 27 | NOAA charts is at https Ed. 01-JUN-15 Ind to Midway Islands, ir INO new editions of chart O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-JUL-20 Indicate to Chatham Strait INO new editions of chart O4-Dec-24. Comparable (ENC) coverage is avail Nautical Charts" in Sect NOAA charts is at https Ed. 01-FEB-13 Indicate to Etolin Island, incluing INO new editions of chart INO new editions of chart INO NOAA charts is at https Ed. 01-FEB-13 Indicate STRAIT TO INO new editions of chart INO new editions of cha | Last LNM: 31/22 Including Sumner Strait; Howay ISL INCLUDING SUP Int 17360 will be published. It is a publi | NAD 83 colkham Bay; Big Castle MNER STRAIT. Page/S It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 Page/Side: - It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. NAD 83 I Canals Side: N/A It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. It will be canceled on Navigational Chart NOAA Paper and Raster S. A list of all canceled CD/Dole.shtml. | NOS NOS | 40/24 |

None

Drill Rigs/Vessels Established

Latitude Longitude Block Rigs/Vessel Chart Type Status

None

SECTION V - ADVANCE NOTICES

This section contains advance notice of approved projects, changes to aids to navigation, or upcoming temporary changes such as dredging, etc.

Mariners are advised to use caution while transiting these areas.

SUMMARY OF ADVANCED APPROVED PROJECTS

Approved Project(s) Project Date Ref. LNM

None

Advance Notice(s)

690 ALASKA – SOUTHEAST – SITKA

The Coast Guard intends to rename and upgrade Japonski Island Buoy 2 (LLNR 25025.51) to Japonski Island Lighted Buoy 2 (LLNR 25025.51) with a red flash every 4 seconds (R 4s). Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 38/20

ALASKA - SOUTHEAST - STEPHENS PASSAGE

The Coast Guard is intends to publish on charts and in the Light List an obscured sector for Five Finger Light (LLNR 23280). The obscured sector is from 332° – 352° true. This obscured sector currently exists for the aid. Mariners with comments or concerns are requested to contact Todd Buck with the Coast Guard District 17 Waterways Management Office at 907-463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 24/24

SECTION VI - PROPOSED CHANGES

Periodically, the Coast Guard evaluates its system of aids to navigation to determine whether the conditions for which the aids to navigation were established have changed. When changes occur, the feasibility of improving, relocating, replacing, or discontinuing aids are considered. This section contains notice(s) of non-approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to the District office unless otherwise noted (see banner page for address).

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

Proposed Project(s) <u>Closing</u> <u>Docket No.</u> <u>Ref. LNM</u>

None

Proposed Change Notice(s)

ALASKA - WESTERN - NORTON SOUND - GOLOVIN BAY

The Coast Guard is proposing adding navigational aids within Golovin Bay. These aids may include Lights, Daybeacons, or buoys. Mariners are requested to provide recommendations on locations that would facilitate safe navigation within Golovin Bay. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

LNM: 26/18

SECTION VII - GENERAL

This section contains information of general concern to the Mariners. Mariners are advised to use caution while transiting these areas.

ALASKA – SOUTHCENTRAL – COOK INLET – HOMER HARBOR

Alaska Marine Excavation, LLC. will be conducting dredging operations in the Homer Harbor Entrance and USCG Hickory berth starting April 15 2024 thru May 1st 2024 and resuming on September 1st 2024 thru October 11th, 2024. Dredging operations will continue 24 hours a day. The dredge COMMANDER is a 58' cutter head suction dredge, red and yellow in color, with a partially submerged pipeline. The pipeline will be marked where it exits the harbor on the beach and the pipeline's anchors will be marked by buoys. The dredge COMMANDER and tug Growler will be working on VHF/FM channel 79 and monitoring VHF/FM channels 13 and 16. Questions/concerns can also be directed to Brok Shafer with Alaska Marine Excavation, LLC at (907) 399-4549 or by email to brok@akmx.com.

LNM: 13/24

159 ALASKA - SOUTHEASTERN - LISIANSKI INLET

The Lisianski Inlet Daybeacon 4 was destroyed. A temporary Unlighted Buoy has been relocated to 58° 02-06.520N 136° 21-54.860W to best mark waterway. Unit will plan for permanaent correction weather and operations permitting. All mariners are reminded to exercise caution when transiting the area. Questions/concerns should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.

Chart 17300 LNM: BNM J

Page 19 of 20 Coast Guard District 17

LNM: 40/24

159

273-23

SECTION VIII - LIGHT LIST CORRECTIONS

An Asterisk *, indicates the column in which a correction has been made to new information

| (1) | (2) | (3) | (4) | (5) | (6) | (7) | (8) | |
|-------|--|---------------------------------|----------------|--------|-------|--------------------------|---|-------|
| No. | Name and Location | Position | Characteristic | Height | Range | Structure | Remarks | |
| 984.8 | NOAA Tsunami Warning Lighted Buoy 21414 | 48-58-12.000N 178-09-54.000E | FI (4)Y 20s | | | Yellow disc shaped hull. | Aid maintained by National Oceanic and Atmospheric Administration. | 40/24 |

*

PUBLICATION CORRECTIONS

None

ENCLOSURES

ALASKA

3924 Subsurface Buoys.pdf

Compilation of Subsurface and Surface oceanography moorings properly reported to U.S. Coast Guard District 17.

LNM: 39/24

Daniel A. Davis
Waterways Management Branch
Seventeenth Coast Guard District
OPERATIONAL EXCELLENCE THROUGH LEADERSHIP, TEAMWORK, AND INNOVATION.

Page 20 of 20 Coast Guard District 17 This is the current compilation of all subsurface and surface oceanographic moorings that have been reported to the U.S. Coast Guard District 17 Waterways Branch. The name, type, location, depth, water depth, and a Point of Contact for all data buoys, surface and subsurface, shall be reported as quickly as is practical if they are placed within the navigable waters (within 200 nm) of the United States. Data buoys placed in the Arctic region but outside of 200 nm of the United States may be reported and will be included in this compilation (for informational purposes only). This notification process is for inclusion in the Local Notice to Mariners to provide navigational information to mariners and does not supersede any permission or permitting requirements. Any notifications, corrections, additions, deletions, or comments for the Alaska region (Coast Guard District 17) or the Arctic region should be submitted via e-mail to smb-d17juneau-lnm@uscg.mil or to Todd Buck, USCG D17(dpw), at 907-463-2269 or by email to todd.r.buck@uscg.mil. This compilation is as current as the Local Notice to Mariners (LNM) included in as an enclosure. The referenced LNM may have additional information and indicates the last time an entry was updated.

ALASKA – ARCTIC – ARCTIC OCEAN

| TYPE/NAME: | POSITION: | WATER DEPTH: | TOP FLOAT DEPTH: | Ref. LNM: | POC: |
|------------|---------------------------|--------------|------------------|-----------|----------------------------------|
| AIM16-1 | 75°06.003'N, 168°00.004'W | 535 feet | 142 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| AMOS-VLF-1 | 77°29.600'N, 140°10.800'W | 12,264 feet | 230 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-C | 76°24.800'N, 142°28.200'W | 12,326 feet | 131 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-NW | 76°08.800'N, 145°17.000'W | 12,441 feet | 328 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-NE | 75°46.400'N, 141°30.800'W | 12,251 feet | 328 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-B | 75°30.000'N, 144°08.400'W | 12,379 feet | 328 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-SE | 74°52.500'N, 143°05.200'W | 12,241 feet | 328 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-SW | 75°13.000'N, 146°40.600'W | 12,464 feet | 328 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| AMOS-A | 74°35.300'N, 145°32.700'W | 12,339 feet | 131 feet | 35/22 | Craig Lee, craiglee@uw/edu |
| NAP-23t | 74°31.375'N, 161°56.536'W | 5,528 feet | 115 feet | 36/24 | Motoyo ITOH +81-46-867-9488 |

CANADA - ARCTIC - BEAUFORT SEA

| TYPE/NAME: | POSITION: | WATER DEPTH: | TOP FLOAT DEPTH: | Ref. LNM: | POC: |
|------------|---------------------------|--------------|------------------|-----------|----------------------------------|
| ACW16-30 | 68°59.173'N, 105°53.030'W | 242 feet | 231 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| CB12 | 70°33.770'N, 127°41.710'W | 125 feet | 116 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| IBO16-1a | 70°20.031'N, 133°44.369'W | 180 feet | 171 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| IBO16-1b | 70°20.035'N, 133°44.452'W | 180 feet | 171 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| IBO16-2 | 70°59.359'N, 133°44.636'W | 365 feet | 146 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| IBO16-9a | 70°03.534'N, 133°42.918'W | 116 feet | 106 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| IBO16-9b | 70°03.501'N, 133°42.937'W | 116 feet | 106 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| SIC16-11 | 69°46.483'N, 137°02.757'W | 117 feet | 107 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |
| HI16 | 69°39.284'N, 138°55.279'W | 134 feet | 125 feet | 44/16 | Dr. Humfrey Melling 250-363-6552 |

ALASKA – ARTCIC – BEAUFORT SEA

| TYPE/NAME: | POSITION: | WATER DEPTH: | TOP FLOAT DEPTH: | Ref. LNM: | POC: |
|--------------|----------------------------|--------------|------------------|-----------|---------------------------------|
| N/A | 71°35.980'N, 161°30.3221'W | 151 feet | 111 feet | 48/14 | David Leech 907-224-4319 |
| BCE-22 | 71°40.385'N, 154°59.988'W | 384 feet | 62 feet | 36/24 | Motoyo ITOH +81-46-867-9488 |
| BCC-22 | 71°44.067'N, 155°09.840'W | 951 feet | 66 feet | 36/24 | Motoyo ITOH +81-46-867-9488 |
| BCW-22 | 71°47.781'N, 155°20. 812'W | 554 feet | 115 feet | 36/24 | Motoyo ITOH +81-46-867-9488 |
| AL24-AU-IC01 | 70°50.040'N, 163°07.560'W | 148 feet | 121 feet | 36/24 | Catherine Berchok 206-526-6331 |
| AL24-AU-BF02 | 71°45.240'N, 154°28.500'W | 344 feet | 312 feet | 36/24 | Catherine Berchok 206-526-6331 |
| AON-BS1 | 71°18.494'N, 152°08.144'W | 187 feet | 115 feet | 37/24 | Dr. Robert Pickart 508-289-2858 |
| AON-BS3a | 71°23.646'N, 152°03.071'W | 479 feet | 115 feet | 37/24 | Dr. Robert Pickart 508-289-2858 |
| AON-BS3b | 71°23.808'N, 152°00.192'W | 502 feet | 115 feet | 37/24 | Dr. Robert Pickart 508-289-2858 |

ALASKA - ARCTIC - CHUKCHI SEA

| TYPE/NAME: | POSITION: | WATER DEPTH: | TOP FLOAT DEPTH: | Ref. LNM: | POC: |
|--------------|---------------------------|--------------|------------------|-----------|--------------------------------|
| AL23-AU-IC02 | 71°12.880'N, 164°14.910'W | 141 feet | 108 feet | 40/23 | Catherine Berchok 206-526-6331 |
| 23CKP-1A | 50°50.230'N, 163°07.521'W | 144 feet | 115 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-2A | 71°12.934'N, 164°15.024'W | 144 feet | 118 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-3A | 71°49.656'N, 166°01.127'W | 144 feet | 121 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-4A | 71°02.700'N, 160°29.404'W | 167 feet | 135 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-5A | 71°12.500'N, 158°00.000'W | 161 feet | 141 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-9A | 72°28.201'N, 15634.203'W | 3,018 feet | 886 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-12A | 67°54.348'N, 168°10.853'W | 190 feet | 148 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKV-12A | 67°54.624'N, 168°10.875'W | 190 feet | 108 feet | 41/23 | David Strausz 206-526-4510 |
| 23CKP-15A | 72°18.590'N, 167°16.250'W | 157 feet | 128 feet | 41/23 | David Strausz 206-526-4510 |
| AL24-AU-IC03 | 71°49.860'N, 166°01.080'W | 148 feet | 121 feet | 36/24 | Catherine Berchok 206-526-6331 |
| AL24-AU-PB01 | 71°12.240'N, 157°59.940'W | 157 feet | 131 feet | 36/24 | Catherine Berchok 206-526-6331 |
| CEM1-24 | 71°35.971'N, 161°30.419'W | 154 feet | 108 feet | 37/24 | Peter Shipton 907-224-4319 |
| CEM2-24 | 71°35.979'N, 161°31.648'W | 154 feet | 108 feet | 37/24 | Peter Shipton 907-224-4319 |
| CEO1-24 | 71°35.024'N, 161°29.969'W | 154 feet | 111 feet | 37/24 | Peter Shipton 907-224-4319 |
| CEO2-24 | 71°36.038'N, 161°32.448'W | 151 feet | 108 feet | 37/24 | Peter Shipton 907-224-4319 |

ALASKA – WESTERN – KOTZEBUE SOUND

| TYPE/NAME: XA23-ST-KS01 XA23-ST-KS03 XA23-ST-KS02 XA23-ST-KS04 XA23-ST-KS07 Sofar WB-24 | POSITION: 67°04.230'N, 163°46.369'W 66°41.012'N, 164°27.292'W 66°46.881'N, 163°45.100'W 66°36.608'N, 163°38.050'W 66°13.734'N, 162°09.781'W 66°54.328'N, 162°35.437'W | WATER DEPTH: 55 feet 59 feet 80 feet 49 feet 46 feet 59 feet | TOP FLOAT DEPTH: 48 feet 52 feet 73 feet 42 feet 39 feet Surface | Ref. LNM: 37/24 37/24 37/24 37/24 37/24 38/24 | POC: Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866 Dr. Manuel Castellote 206-526-6866 Dana Brunswick 907-562-2000 | |
|--|--|--|--|--|---|--|
| ALASKA – WES | ΓERN – BERING STRAIT | | | | | |
| TYPE/NAME: A2-24 A3-24 A4-24 | POSITION: 65°46.830'N, 168°34.080'W 66°19.620'N, 168°56.940'W 65°44.760'N, 168°15.750'W | WATER DEPTH: 184 feet 190 feet 161 feet | TOP FLOAT DEPTH: 49 feet 23 feet 49 feet | Ref. LNM: 38/24 38/24 38/24 | POC: Rebecca Woodgate 206-221-3268 Rebecca Woodgate 206-221-3268 Rebecca Woodgate 206-221-3268 | |
| ALASKA – SOUT | THWESTERN – BERING SEA | | | | | |
| TYPE/NAME: AL23-AU-M08 23BSP-14A 23BSITAER-8A 23BS-8A 23BSST-8A 23BSV-8A AL24-AU-PC01 SPOT-32004C AL24-AU-NM01 AL24-AU-BS10 AL24-AU-BS11 24BS-2C 24BS-4A 24BSP-4A 24BSP-5A | POSITION: 62°12.286'N, 174°40.585'W 64°00.251'N, 167°55.150'W 62°12.107'N, 174°39.660'W 62°11.895'N, 174°39.760'W 62°12.002'N, 174°40.782'W 62°12.339'N, 174°40.558'W 62°12.339'N, 174°40.558'W 62°12.339'N, 174°39.890'W 56°07.762'N, 168°18.780'W 60°31.139'N, 165°05.293'W 64°51.480'N, 168°26.880'W 56°09.600'N, 166°34.920'W 61°05.040'N, 170°15.840'W 56°51.612'N, 164°03.317'W 57°52.239'N, 168°53.196'W 59°55.689'N, 171°42.129'W 59°55.172'W, 171°42.865'W | WATER DEPTH: 230 feet 138 feet 240 feet 240 feet 240 feet 240 feet 240 feet 240 feet 12 feet 144 feet 384 feet 161 feet 240 feet 236 feet 233 feet 226 feet 230 feet | TOP FLOAT DEPTH: 197 feet 92 feet 66 feet 43 feet 197 feet 203 feet 154 feet 535 feet Surface, FL Y 2.5s 118 feet 358 feet 135 feet 25 feet 16 feet 197 feet 33 feet 194 feet | Ref. LNM: 40/23 41/23 41/23 41/23 41/23 41/23 25/24 35/24 36/24 36/24 39/24 39/24 39/24 39/24 39/24 | POC: Catherine Berchok 206-526-6331 David Strausz 206-526-4510 Catherine Berchok 206-526-6331 Roderick Atti 907-427-2296 Catherine Berchok 206-526-6331 Catherine Berchok 206-526-6331 Catherine Berchok 206-526-6331 Catherine Berchok 206-526-6331 David Strausz 206-526-4510 | |
| ALASKA – SOUTHWESTERN – UNIMAK PASS | | | | | | |
| | IIIWESTEKN – UMIMAK FASS | | | | | |
| TYPE/NAME: AL24-AU-UN01 | POSITION: 54°26.220'N, 165°10.200 | WATER DEPTH: 518 feet | TOP FLOAT DEPTH: 492 feet | Ref. LNM: 36/24 | POC: Catherine Berchok 206-526-6331 | |
| TYPE/NAME: AL24-AU-UN01 | POSITION: | 518 feet | 492 feet | | | |
| TYPE/NAME: AL24-AU-UN01 ALASKA – SOUT TYPE/NAME: GA23-AU-SU01 | POSITION: 54°26.220'N, 165°10.200 FHCENTRAL – GULF OF ALAS POSITION: 56°35.990'N, 157°00.000'W | 518 feet KA – ALEUTIAN WATER DEPTH: 427 feet | 492 feet PENINSULA TOP FLOAT DEPTH: 400 feet | 36/24 | | |
| TYPE/NAME: AL24-AU-UN01 ALASKA – SOUT TYPE/NAME: GA23-AU-SU01 ALASKA – SOUT | POSITION: 54°26.220'N, 165°10.200 THCENTRAL – GULF OF ALAS POSITION: 56°35.990'N, 157°00.000'W THCENTRAL – GULF OF ALAS | 518 feet KA – ALEUTIAN WATER DEPTH: 427 feet KA – STEVENSO | 492 feet PENINSULA TOP FLOAT DEPTH: 400 feet N ENTRANCE | 36/24 Ref. LNM: 41/23 | POC: Catherine Berchok 206-526-6331 | |
| TYPE/NAME: AL24-AU-UN01 ALASKA – SOUT TYPE/NAME: GA23-AU-SU01 | POSITION: 54°26.220'N, 165°10.200 FHCENTRAL – GULF OF ALAS POSITION: 56°35.990'N, 157°00.000'W | 518 feet KA – ALEUTIAN WATER DEPTH: 427 feet KA – STEVENSO | 492 feet PENINSULA TOP FLOAT DEPTH: 400 feet | 36/24 Ref. LNM: | Catherine Berchok 206-526-6331 POC: | |
| TYPE/NAME: AL24-AU-UN01 ALASKA – SOUT TYPE/NAME: GA23-AU-SU01 TYPE/NAME: GA23-AU-SE01 | POSITION: 54°26.220'N, 165°10.200 FHCENTRAL – GULF OF ALAS POSITION: 56°35.990'N, 157°00.000'W FHCENTRAL – GULF OF ALAS POSITION: | 518 feet KA – ALEUTIAN WATER DEPTH: 427 feet KA – STEVENSO! WATER DEPTH: 430 feet | 492 feet PENINSULA TOP FLOAT DEPTH: 400 feet N ENTRANCE TOP FLOAT DEPTH: | 36/24 Ref. LNM: 41/23 Ref. LNM: | POC: Catherine Berchok 206-526-6331 POC: Catherine Berchok 206-526-6331 POC: | |
| TYPE/NAME: AL24-AU-UN01 ALASKA – SOUT TYPE/NAME: GA23-AU-SU01 TYPE/NAME: GA23-AU-SE01 ALASKA – SOUT TYPE/NAME: GA23-AU-ST01 CA23-AU-ST01 CA23-A | POSITION: 54°26.220'N, 165°10.200 FHCENTRAL – GULF OF ALAS POSITION: 56°35.990'N, 157°00.000'W FHCENTRAL – GULF OF ALAS POSITION: 58°42.540'N, 152°12.530'W | 518 feet KA – ALEUTIAN WATER DEPTH: 427 feet KA – STEVENSO! WATER DEPTH: 430 feet KA WATER DEPTH: 253 feet 1,375 feet 1,375 feet 1,319 feet 433 feet 2,438 feet 545 feet 256 feet 243 feet | 492 feet PENINSULA TOP FLOAT DEPTH: 400 feet N ENTRANCE TOP FLOAT DEPTH: | 36/24 Ref. LNM: 41/23 Ref. LNM: 41/23 | POC: Catherine Berchok 206-526-6331 POC: Catherine Berchok 206-526-6331 POC: | |
| TYPE/NAME: AL24-AU-UN01 ALASKA – SOUT TYPE/NAME: GA23-AU-SU01 TYPE/NAME: GA23-AU-SE01 ALASKA – SOUT TYPE/NAME: GA23-AU-SE01 GA23-AU-SN01 | POSITION: 54°26.220'N, 165°10.200 FHCENTRAL – GULF OF ALAS POSITION: 56°35.990'N, 157°00.000'W FHCENTRAL – GULF OF ALAS POSITION: 58°42.540'N, 152°12.530'W FHCENTRAL – GULF OF ALAS POSITION: 57°01.760'N, 152°59.690'W 53°58.360'N, 161°40.070'W 55°34.340'N, 154°58.460'W 53°07.960'N, 168°55.210'W 54°38.200'N, 150°21.160'W 57°43.456'N, 152°17.001'W 54°51.177'N, 158°59.481'W 54°18.400'N, 164°45.100'W 50°02'30.000'N, 145°10'12.000'W 59°01.602'N, 148°40.242'W | 518 feet KA – ALEUTIAN WATER DEPTH: 427 feet KA – STEVENSO! WATER DEPTH: 430 feet KA WATER DEPTH: 253 feet 1,375 feet 1,375 feet 1,319 feet 433 feet 2,438 feet 2,438 feet 2545 feet 256 feet 243 feet UNK 758 feet 754 feet | 492 feet PENINSULA TOP FLOAT DEPTH: 400 feet N ENTRANCE TOP FLOAT DEPTH: 404 feet TOP FLOAT DEPTH: 230 feet 243 feet 243 feet 243 feet 233 feet 400 feet 233 feet 472 feet 203 feet 217 feet Surface 82 feet 164 feet | 36/24 Ref. LNM: 41/23 Ref. LNM: 41/23 Ref. LNM: 34/23 34/23 34/23 34/23 38/23 41/23 41/23 24/24 26/24 37/24 | POC: Catherine Berchok 206-526-6331 POC: Catherine Berchok 206-526-6331 POC: Catherine Berchok 206-526-6331 POC: Catherine Berchok 206-526-6331 David Strausz 206-526-4510 David Strausz 206-526-4510 David Strausz 206-526-4510 Joe Talbert 206-409-4627 Peter Shipton 907-224-4319 | |

ALASKA - SOUTHCENTRAL - PRINCE WILLIAM SOUND

| TYPE/NAME: | POSITION: | WATER DEPTH | H: TOP FLOAT DEPTH: | Ref. LNM: | POC: |
|------------|---------------------------|-------------|-----------------------------|------------|------------------------------------|
| PWSSC-15 | 60°36.791'N, 147°11.996'W | 722 feet 1 | 97 feet (Surfacing 2X per d | lay) 15/16 | R. W. Campbell 907-424-5800 x241 |
| H01 | 60°20.550'N, 146°43.824'W | 98 feet | 66 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| HA | 60°20.274'N, 146°43.248'W | 591 feet | 532 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H02 | 60°20.400'N, 146°44.520'W | 879 feet | 791 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| HB | 60°20.094'N, 146°43.974'W | 830 feet | 747 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H04 | 60°20.112'N, 146°45.966'W | 886 feet | 797 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H05 | 60°19.968'N, 146°46.710'W | 886 feet | 797 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H06 | 60°19.812'N, 146°47.418'W | 896 feet | 806 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H07 | 60°19.668'N, 146°48.138'W | 909 feet | 818 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H08 | 60°19.470'N, 146°48.954'W | 935 feet | 842 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H09 | 60°19.320'N, 146°49.782'W | 1007 feet | 906 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H10 | 60°19.188'N, 146°50.508'W | 1060 feet | 954 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H13 | 60°18.738'N, 146°52.656'W | 909 feet | 818 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H14 | 60°18.588'N, 146°53.340'W | 522 feet | 470 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H15 | 60°18.468'N, 146°53.994'W | 276 feet | 244 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| HC | 60°18.120'N, 146°53.568'W | 449 feet | 404 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H11 | 60°19.008'N, 146°51.228'W | 1135 feet | 1022 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| H16 | 60°18.540'N, 146°54.552'W | 85 feet | 53 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| HD | 60°17.982'N, 146°54.336'W | 151 feet | 119 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M01 | 59°55.482'N, 147°48.630'W | 295 feet | 263 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M02 | 59°55.848'N, 147°49.074'W | 446 feet | 401 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M03 | 59°56.178'N, 147°49.518'W | 509 feet | 458 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M04 | 59°56.556'N, 147°49.956'W | 577 feet | 519 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M05 | 59°56.886'N, 147°50.382'W | 640 feet | 576 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M07 | 59°57.546'N, 147°51.234'W | 741 feet | 667 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| MC | 59°58.182'N, 147°52.872'W | 745 feet | 671 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| M11 | 59°58.842'N, 147°52.866'W | 472 feet | 425 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| MD | 59°58.518'N, 147°53.352'W | 614 feet | 553 feet | 09/17 | Mary Anne Bishop 907-424-5800 x228 |
| BP07 | 60°06.894'N, 148°14.118'W | 171 feet | 154 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| POWP05 | 60°02.784'N, 148°07.482'W | 315 feet | 299 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| POWP06 | 60°02.790'N, 148°07.789'W | 154 feet | 138 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| EP03 | 59°59.466'N, 148°05.778'W | 207 feet | 190 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| EP04 | 59°59.706'N, 148°06.060'W | 276 feet | 259 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| LP01 | 59°58.848'N, 148°01.914'W | 112 feet | 95 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| LP02 | 59°59.082'N, 148°02.219'W | 144 feet | 128 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| M06 | 59°57.222'N, 147°50.838'W | 702 feet | 686 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| M08 | 59°57.858'N, 147°51.630'W | 758 feet | 741 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| M09 | 59°58.146'N, 147°52.008'W | 643 feet | 617 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| M10 | 59°58.512'N, 147°52.434'W | 784 feet | 768 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| H03 | 60°20.256'N, 146°45.264'W | 876 feet | 860 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| H12 | 60°18.888'N, 146°51.918'W | 1194 feet | 1079 feet | 36/24 | Mary Anne Bishop 907-424-5800 x228 |
| | | | | | |

${\bf ALASKA-SOUTHEAST}$

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: Ref. LNM: POC:

20CSP-4A 58°07.363'N, 136°35.604'W 1,099 feet 1,060 feet 06/20 David Strausz 206-526-4510

ALASKA – NORTH PACIFIC OCEAN

TYPE/NAME: POSITION: WATER DEPTH: TOP FLOAT DEPTH: Ref. LNM: POC:

FLMA 50°01.393'N, 144°21.669'W 9,361 feet 68 feet 37/24 Derek Buffitt dbuffitt@whoi.edu 50°22.565'N, 144°30.838'W 50°06.858'N, 144°55.046'W 68 feet 37/24 Derek Buffitt dbuffitt@whoi.edu FLMB 9,523 feet 37/24 HYPM 9,664 feet 342 feet Derek Buffitt dbuffitt whoi.edu