

Local Notice to Mariners for District 17 09/10/2025

Alaska Peninsula

Additional MSI Categories

| TITLE                                                                                                    | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | LOCATION |
|----------------------------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| Sector Anchorage, Submerged Land Act (SLA) - Alaska Peninsula/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2025-06-25 To: 2025-12-22 A newly installed fiber optic submarine cable by GCI has been laid from Chignik Lagoon to Chignik Bay, Alaska. This cable is an extension to an already charted cable. Mariners are advised to avoid anchoring in the middle of the channel to prevent entanglements. Any concerned traffic can contact Coast Guard Sector Western Alaska and US Arctic Command Cetner at 9074284100. All vessels are requested to transit the area with caution and report all sightings to the Coast Guard. |          |

Bar Harbor

Private Discrepancies

| NAME                               | LLNR  | STATUS      | AID TYPE |
|------------------------------------|-------|-------------|----------|
| Bar Harbor Breakwater East Light   | 22201 | STRUCT DEST | PA       |
| Bar Harbor Breakwater Middle Light | 22202 | STRUCT DEST | PA       |
| Bar Harbor Breakwater West Light   | 22203 | STRUCT DEST | PA       |

Bechevin Bay.

Federal Discrepancies

| NAME                          | LLNR  | STATUS  | AID TYPE |
|-------------------------------|-------|---------|----------|
| Bechevin Bay Entrance Buoy BB | 27250 | MISSING | FD       |
| Isanotski Strait Light 3      | 27410 | LT EXT  | FD       |

Bering Sea Eastern Part

Additional MSI Categories

| TITLE                                                                                                           | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                    | LOCATION                            |
|-----------------------------------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 62.5925° N / 164.908° W A 6' by 6' by 15' metal tower was destroyed and partially submerged in this position in June of 2021. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Western Alaska and U.S. Arctic at 907-428-4100. | Lat: 62° 35' 33" Lon: -164° 54' 29" |
| Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.15927° N / 166.58292° E Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                                                                                                    | Lat: 56° 09' 33" Lon: 166° 34' 59"  |

Captains Bay.

Federal Discrepancies

| NAME                        | LLNR  | STATUS             | AID TYPE |
|-----------------------------|-------|--------------------|----------|
| Bailey Ledge Light          | 27505 | Status Unreported  | FD       |
| Bailey Ledge Light          | 27505 | LT EXT/STRUCT DMGD | FD       |
| Swallow Reef Lighted Buoy 6 | 27508 | MISSING            | FD       |

Chatham Strait

Federal Discrepancies

| NAME               | LLNR  | STATUS | AID TYPE |
|--------------------|-------|--------|----------|
| Cape Ommaney Light | 23460 | LT EXT | FD       |

Additional MSI Categories

| TITLE                                                                                                   | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                          | LOCATION                            |
|---------------------------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Southeast Alaska, Submerged Land Act (SLA) - Chatham Strait/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 57.84975° N / 135.02875° W The F/V BAILEY BAY sank in this position in approximately 30 feet of water in October of 2022. The F/V BAILEY BAY is a 33' fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. | Lat: 57° 50' 59" Lon: -135° 01' 44" |

Chilkoot Inlet

Additional MSI Categories

| TITLE                                                                 | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                     | LOCATION                            |
|-----------------------------------------------------------------------|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| LynnCanal - Chilkoot Inlet/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 59.24033° N / 135.43087° W An anchor and 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor. | Lat: 59° 14' 25" Lon: -135° 25' 51" |

Clarence Strait

Federal Discrepancies

| NAME                         | LLNR  | STATUS     | AID TYPE |
|------------------------------|-------|------------|----------|
| Snow Passage Lighted Buoy SP | 22515 | LT EXT     | FD       |
| Bay Point Daybeacon BP       | 22525 | DAYMK DMGD | FD       |

CopperRiverBay.

Federal Discrepancies

| NAME                                                | LLNR  | STATUS            | AID TYPE |
|-----------------------------------------------------|-------|-------------------|----------|
| Strawberry Channel Entrance Lighted Whistle Buoy SC | 25485 | Status Unreported | FD       |
| Strawberry Channel Entrance Lighted Whistle Buoy SC | 25485 | Status Unreported | FD       |

Cross Sound

Federal Discrepancies

| NAME               | LLNR  | STATUS            | AID TYPE |
|--------------------|-------|-------------------|----------|
| Cape Spencer Light | 24240 | Status Unreported | FD       |

Dry Pass

Federal Discrepancies

| NAME                  | LLNR  | STATUS      | AID TYPE |
|-----------------------|-------|-------------|----------|
| Dry Pass Daybeacon 3  | 24790 | STRUCT DEST | FD       |
| Dry Pass Daybeacon 25 | 24880 | STRUCT DEST | FD       |

Eastern Channel

Federal Discrepancies

| NAME                              | LLNR  | STATUS      | AID TYPE |
|-----------------------------------|-------|-------------|----------|
| Indian River Flats Lighted Buoy 2 | 24948 | LT EXT      | FD       |
| Mitchell Rock Daybeacon           | 24957 | STRUCT DEST | FD       |

El Capitan Passage

Federal Discrepancies

| NAME                   | LLNR  | STATUS         | AID TYPE |
|------------------------|-------|----------------|----------|
| North Island Daybeacon | 24777 | STRUCT MISSING | FD       |

Elfin Cove

Federal Discrepancies

| NAME                   | LLNR  | STATUS      | AID TYPE |
|------------------------|-------|-------------|----------|
| Elfin Cove Daybeacon 5 | 24260 | STRUCT DEST | FD       |

Elrington Passage

Additional MSI Categories

| TITLE                                      | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                     | LOCATION                            |
|--------------------------------------------|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9911° N / 148.0963° W Submerged Data Mooring Name: EP03 Water Depth: 207' Top Float Depth: 190' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org | Lat: 59° 59' 28" Lon: -148° 05' 47" |
|                                            |                       |                                                                                                                                                                                                                                                                 |                                     |

Frederick Sound

Federal Discrepancies

| NAME               | LLNR  | STATUS      | AID TYPE |
|--------------------|-------|-------------|----------|
| Cape Fanshaw Light | 23260 | STRUCT DEST | FD       |

Additional MSI Categories

| TITLE                                                                 | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                         | LOCATION                            |
|-----------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Chatham Strait - Frederick Sound/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 56.91133° N / 132.94483° W A 47 foot wood fishing vessel was reported sunk in this position in 2023. | Lat: 56° 54' 41" Lon: -132° 56' 41" |

Gastineau Channel

Federal Discrepancies

| NAME                         | LLNR  | STATUS  | AID TYPE |
|------------------------------|-------|---------|----------|
| Douglas Boat Harbor Light 1D | 23680 | LT EXT  | FD       |
| Rock Dump Lighted Buoy 2A    | 23685 | LT IMCH | FD       |
| Rock Dump Lighted Buoy 2A    | 23685 | LT IMCH | FD       |
| Lawson Creek Bar Light 3     | 23690 | LT EXT  | FD       |

Additional MSI Categories

| TITLE                                                                     | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                             | LOCATION                            |
|---------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Stephens Passage - Gastineau Channel/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 58.27098° N / 134.37045° W A 22' white sailboat sank in this position. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980. | Lat: 58° 16' 16" Lon: -134° 22' 14" |

Glacier Bay

Additional MSI Categories

| TITLE                                                               | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                | LOCATION                            |
|---------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Icy Strait - Glacier Bay/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-11-12 To: 2026-11-12 Location: 58.67719° N / 136.16049° W Submerged Data Mooring Name: Glacier Bay Oceanographic Mooring Water Depth: 1017' Top Float Depth: 82' POC: Mathew Cahill Phone: 907-697-2230 Email: mathew_cahill@nps.gov | Lat: 58° 40' 38" Lon: -136° 09' 38" |

Hawk Inlet

Federal Discrepancies

| NAME                         | LLNR  | STATUS  | AID TYPE |
|------------------------------|-------|---------|----------|
| Hawk Inlet East Shoal Buoy 8 | 24115 | HAZ NAV | FD       |

Icy Strait

Temporary Changes

| NAME                           | LLNR  | STATUS | AID TYPE |
|--------------------------------|-------|--------|----------|
| Pinta Rock Lighted Bell Buoy 2 | 24165 | TRLB   | FD       |

Additional MSI Categories

| TITLE                                                                    | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                | LOCATION                            |
|--------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Cross Sound - Icy Strait/General/Hazards To Navigation/Shoaling Reported | Hazards To Navigation | General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 58.30225° N / 135.37292° W A dangerous rock was reported in this position. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil. | Lat: 58° 18' 08" Lon: -135° 22' 23" |

Kachemak Bay

Federal Discrepancies

| NAME                    | LLNR  | STATUS      | AID TYPE |
|-------------------------|-------|-------------|----------|
| Sixty Foot Rock Light   | 26190 | DAYMK DMGD  | FD       |
| Halibut Point Daybeacon | 26245 | STRUCT DEST | FD       |

Additional MSI Categories

| TITLE                                                                                                              | SUBCATEGORY                             | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | LOCATION |
|--------------------------------------------------------------------------------------------------------------------|-----------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| Sector Anchorage, Submerged Land Act (SLA) - Kachemak Bay/General/Marine Construction (Excluding Bridges)/Dredging | Marine Construction (Excluding Bridges) | General/Marine Construction (Excluding Bridges)/Dredging From: 2025-04-01 To: 2025-05-04 Alaska Marine Excavation, LLC. will be conducting dredging operations in the Homer Harbor Entrance and USCG Hickory berth starting April 15 2025 thru May 1st 2025 and resuming on September 1st 2025 thru October 11th, 2025. Dredging operations will continue 24 hours a day. The dredge COMMANDER is a 58' cutter head suction dredge, red and yellow in color, with a partially submerged pipeline. The pipeline will be marked where it exits the harbor on the beach and the pipeline's anchors will be marked by buoys. The dredge COMMANDER and tug Growler will be working on VHF/FM channel 79 and monitoring VHF/FM channels 13 and 16. Questions/concerns can also be directed to Brok Shafer with Alaska Marine Excavation, LLC at (907) 399-4549 or by email to brok@akmx.com. |          |

Karheen Passage

Federal Discrepancies

| NAME                         | LLNR  | STATUS   | AID TYPE |
|------------------------------|-------|----------|----------|
| Tonowek Narrows Daybeacon 2T | 24680 | RAC IMCH | FD       |

Keku Strait

Federal Discrepancies

| NAME                       | LLNR               | STATUS      | AID TYPE |
|----------------------------|--------------------|-------------|----------|
| Keku Strait Entrance Light | 23305.100000000002 | STRUCT DEST | FD       |
| Keku Strait Daybeacon 4    | 23305.3            | STRUCT DEST | FD       |
| Keku Strait Buoy 14        | 23305.95           | MISSING     | FD       |
| Keku Strait Daybeacon 15   | 23306              | STRUCT DEST | FD       |
| Keku Strait Daybeacon 18   | 23306.2            | STRUCT DEST | FD       |
| Keku Strait Daybeacon 19   | 23306.3            | STRUCT DEST | FD       |
| Keku Strait Daybeacon 25   | 23306.7            | STRUCT DEST | FD       |
| Keku Strait Daybeacon 26   | 23306.8            | STRUCT DEST | FD       |
| Keku Strait Daybeacon 27   | 23306.850000000002 | STRUCT DEST | FD       |
| Keku Strait Daybeacon 31   | 23307.05           | STRUCT DEST | FD       |
| Keku Strait Daybeacon 37   | 23307.600000000002 | STRUCT DEST | FD       |
| Keku Strait Daybeacon 39   | 23307.7            | STRUCT DEST | FD       |
| Keku Strait Daybeacon 41   | 23307.8            | STRUCT DEST | FD       |

Klawock Inlet

Federal Discrepancies

| NAME                        | LLNR  | STATUS | AID TYPE |
|-----------------------------|-------|--------|----------|
| Klawock Reef Lighted Buoy 1 | 24575 | LT EXT | FD       |

Kupreanof Strait

Federal Discrepancies

| NAME                           | LLNR  | STATUS        | AID TYPE |
|--------------------------------|-------|---------------|----------|
| Dry Spruce Island Rock Light 7 | 27025 | LT EXT        | FD       |
| Last Timber Point Light 6      | 27030 | DAYMK MISSING | FD       |

Kuskokwim River

Federal Discrepancies

| NAME                    | LLNR    | STATUS            | AID TYPE |
|-------------------------|---------|-------------------|----------|
| Kuskokwim River Buoy 36 | 27849.7 | Status Unreported | FD       |
| Okwega Pass Light OP    | 27872   | STRUCT DEST       | FD       |

Additional MSI Categories

| TITLE                                                                                             | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | LOCATION                            |
|---------------------------------------------------------------------------------------------------|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.78583° N / 161.692° W The barge SHANKS ARK was reported sunk and abandoned in this position in March of 2017. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no maritime traffic is present. | Lat: 60° 47' 09" Lon: -161° 41' 31" |

|                                                                                    |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |  |
|------------------------------------------------------------------------------------|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-28 To: 2025-11-24 The following Kuskokwim Bay Buoys have been established for the season: A. Kuskokwim Bay Buoy 2 (LLNR 27835) B. Kuskokwim Bay Buoy 3 (LLNR 27836) C. Kuskokwim Bay Buoy 4 (27837) D. Kuskokwim Bay Buoy 5 (LLNR 27838)                                                                                                                                                                                         |  |
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-28 To: 2025-11-24 Location: The following Kuskokwim Bay and River Buoys have been established for the season: Kuskokwim Bay Buoys 6, 8, 9, 10, 12, 15, 16, 18, 20, 22 (LLNR 27839, 27840, 27841, 27842, 27843, 27844.5, 27844.7, 27845.2, 27845.7, 27846.2)                                                                                                                                                                      |  |
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-28 To: 2025-11-24 The following Kuskokwim River Buoys have been established for the season: Kuskokwim River Buoys 23-51 (LLNRs 27846.5-27853.5)                                                                                                                                                                                                                                                                                  |  |
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-29 To: 2025-11-25 The following Kuskokwim River Buoys have been established for the season: Kuskokwim River Buoys: 50, 52, 53, 55, 56, 56, 57, 58, 60, 62, 63, 65, 66 (LLNR 27853.2-27857)                                                                                                                                                                                                                                       |  |
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-29 To: 2025-11-25 The following Kuskokwim River Buoys have been established for the season: A. Kuskokwim River Buoy 29 (LLNR 27848) B. Kuskokwim River Buoy 36 (LLNR 27849.9) C. Kuskokwim River Buoy 37 (LLNR 27850) D. Kuskokwim River Buoy 45 (LLNR 27852) E. Kuskokwim River Buoy 13 (LLNR 27844)                                                                                                                            |  |
| Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-06-04 To: 2025-12-01 The Kwigillingok Water Buoys have been commissioned for the season on June 1, 2025. Buoy Positions are as follows: Buoy 1 - N 59°51.0418 W 163°07.2280 Buoy 2 - N 59°50.7120 W 163°07.4363 Buoy 3 - N 59°50.0614 W 163°06.4928 Buoy 4 - N 59°49.6795 W 163°06.5144 Buoy 5 - N 59°49.2769 W 163°06.3849 Buoy 6 - N 59°48.9255 W 163°05.7493 2 Bouy 7 - N 59°48.2362 W 163°05.3509 POC: John Darrel 907-588-2133 |  |

Lisianski Inlet

Federal Discrepancies

| NAME                        | LLNR  | STATUS      | AID TYPE |
|-----------------------------|-------|-------------|----------|
| Lisianski Inlet Daybeacon 4 | 24300 | STRUCT DEST | FD       |

LynnCanal

Federal Discrepancies

| NAME                  | LLNR  | STATUS     | AID TYPE |
|-----------------------|-------|------------|----------|
| Tee Harbor Light      | 23825 | DAYMK DMGD | FD       |
| Vanderbilt Reef Light | 23860 | SS IMCH    | FD       |

Additional MSI Categories

| TITLE                           | SUBCATEGORY   | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | LOCATION |
|---------------------------------|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| LynnCanal/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-07-18 To: 2026-01-14 DUE TO SCHEDULED MAINTENANCE THE COAST GUARD MAY BE UNABLE TO LISTEN OR RESPOND TO DISTRESS CALLS ON CH16 STARTING JULY 21ST THROUGH JULY 22ND FROM 0600 TO 1400Z OR 2200 TO 0600 AKST IN THE FOLLOWING AREAS: LYNN CANAL, CHILKOOT INLET, AND CHILKAT INLET. ALL MARINERS ARE REQUESTED TO RELAY ANY UNANSWERED DISTRESS CALLS IN THESE AREAS TO THE NEAREST COAST GUARD UNIT OR CONTACT COAST GUARD SEAK AT 907-463-2980. |          |

Marmot Bay

Federal Discrepancies

| NAME             | LLNR  | STATUS | AID TYPE |
|------------------|-------|--------|----------|
| Hanin Rock Light | 26560 | LT EXT | FD       |

Additional MSI Categories

| TITLE                                                                                                   | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | LOCATION                            |
|---------------------------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/ATON/ATON Changes                               | ATON Changes          | ATON/ATON Changes From: 2025-09-05 To: 2025-09-30 Location: 57.91704° N / 152.54885° W Aid Name: Low Island Reef Buoy 7 LLNR: 26485 Action: RELOCATE                                                                                                                                                                                                                                                                                                                                                                                           | Lat: 57° 55' 01" Lon: -152° 32' 56" |
| Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/General/Hazards To Navigation/Shoaling Reported | Hazards To Navigation | General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 57.78583° N / 152.40568° W A dangerous rock was reported in this position approximately 20' off of the K&I Pier. This rock was reported struck by a vessel with a 16' draft at low tide, approximately -.085'. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil. | Lat: 57° 47' 09" Lon: -152° 24' 20" |

Mendenhall Bar

Federal Discrepancies

| NAME                   | LLNR     | STATUS            | AID TYPE |
|------------------------|----------|-------------------|----------|
| Mendenhall Bar Buoy 8B | 23735.25 | Status Unreported | FD       |

Naknek River

Additional MSI Categories

| TITLE | SUBCATEGORY | DESCRIPTION | LOCATION |
|-------|-------------|-------------|----------|
|-------|-------------|-------------|----------|

|                                                                       |                       |                                                                                                                                                                                                                          |                                        |
|-----------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Kvichak Bay - Naknek River/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2025-04-26 Location: 58.71287° N / 157.03408° W A large metal ramp was reported to be visible during low tide and completely submerged during high tide. | Lat: 58° 42' 46"<br>Lon: -157° 02' 03" |
|-----------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|

Nichols Passage

Additional MSI Categories

| TITLE                                                                  | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                   | LOCATION                               |
|------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Clarence Strait - Nichols Passage/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 55.05° N / 131.64883° W The F/V JACI GRACE sank in Canoe Cove in this position. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980. | Lat: 55° 03' 00"<br>Lon: -131° 38' 56" |

Ogden Passage

Federal Discrepancies

| NAME                          | LLNR  | STATUS      | AID TYPE |
|-------------------------------|-------|-------------|----------|
| Dippy Island Rock Daybeacon 3 | 25355 | STRUCT DEST | FD       |

Orca Bay

Federal Discrepancies

| NAME                      | LLNR  | STATUS      | AID TYPE |
|---------------------------|-------|-------------|----------|
| Hanks Island Rock Light 5 | 25550 | STRUCT DEST | FD       |

Additional MSI Categories

| TITLE                                       | SUBCATEGORY   | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | LOCATION |
|---------------------------------------------|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| Orca Inlet - Orca Bay/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-14 To: 2025-11-10 The Orca Inlet South Channel Buoys have been commissioned for the season. Positions are as follows: ORCA INLET SOUTH CHANNEL BUOY 1 (LLNR 25615) HAS BEEN COMMISSIONED IN POSITION 60-27-33.293N, 145-59-04.763W. ORCA INLET SOUTH CHANNEL BUOY 1A (LLNR 25615.15) HAS BEEN COMMISSIONED IN POSITION 60-27-44.847N, 145-58-39.614W. ORCA INLET SOUTH CHANNEL BUOY 2 (LLNR 25615.1) HAS BEEN COMMISSIONED IN POSITION 60-27-30.370N, 145-58-56.514W. ORCA INLET SOUTH CHANNEL BUOY 2A (LLNR 25615.2) HAS BEEN COMMISSIONED IN POSITION 60-27-58.080N, 145-58-25.829W. ORCA INLET SOUTH CHANNEL BUOY 3 (LLNR 25615.25) HAS BEEN COMMISSIONED IN POSITION 60-27-59.438N, 145-58-31.601W. ORCA INLET SOUTH CHANNEL BUOY 4 (LLNR 25615.3) HAS BEEN COMMISSIONED IN POSITION 60-28-04.831N, 145-58-13.394W. ORCA INLET SOUTH CHANNEL BUOY 5 (LLNR 25615.35) HAS BEEN COMMISSIONED IN POSITION 60-28-23.763N, 145-57-18.216W. ORCA INLET SOUTH CHANNEL BUOY 6 (LLNR 25615.4) HAS BEEN COMMISSIONED IN POSITION 60-28-25.587N, 145-57-10.332W. ORCA INLET SOUTH CHANNEL BUOY 7 (LLNR 25615.45) HAS BEEN COMMISSIONED IN POSITION 60-28-58.177N, 145-56-03.356W. ORCA INLET SOUTH CHANNEL BUOY 8 (LLNR 25615.5) HAS BEEN COMMISSIONED IN POSITION 60-28-50.607N, 145-56-13.743W. ORCA INLET SOUTH CHANNEL BUOY 9 (LLNR 25615.55) HAS BEEN COMMISSIONED IN POSITION 60-29-28.840N, 145-55-25.332W. ORCA INLET SOUTH CHANNEL BUOY 10 (LLNR 25615.6) HAS BEEN COMMISSIONED IN POSITION 60-29-29.157N, 145-55-16.690W. ORCA INLET SOUTH CHANNEL BUOY 11 (LLNR 25615.65) HAS BEEN COMMISSIONED IN POSITION 60-30-00.568N, 145-54-46.815W. ORCA INLET SOUTH CHANNEL BUOY 12 (LLNR 25615.7) HAS BEEN COMMISSIONED IN POSITION 60-30-00.059N, 145-54-43.855W. ORCA INLET SOUTH CHANNEL BUOY 13 (LLNR 25615.75) HAS BEEN COMMISSIONED IN POSITION 60-30-38.012N, 145-54-22.081W. ORCA INLET SOUTH CHANNEL BUOY 14 (LLNR 25615.8) HAS BEEN COMMISSIONED IN POSITION 60-30-54.388N, 145-54-00.756W. ORCA INLET SOUTH CHANNEL BUOY 16 (LLNR 25615.85) HAS BEEN COMMISSIONED IN POSITION 60-31-46.408N, 145-52-49.531W. ORCA INLET SOUTH CHANNEL BUOY 18 (LLNR 25615.9) HAS BEEN COMMISSIONED IN POSITION 60-32-38.259N, 145-50-36.742W. |          |

Orca Inlet

Federal Discrepancies

| NAME                         | LLNR  | STATUS             | AID TYPE |
|------------------------------|-------|--------------------|----------|
| Orca Inlet Channel Light 12  | 25575 | STRUCT DEST        | FD       |
| NOAA Data Lighted Buoy 46060 | 25646 | ADRIFT             | FD       |
| Glacier Island Light         | 25665 | VEGETATION/MISSING | FD       |

Temporary Changes

| NAME                        | LLNR  | STATUS | AID TYPE |
|-----------------------------|-------|--------|----------|
| Orca Inlet Channel Light 12 | 25575 | TRLB   | FD       |

Peril Strait

Federal Discrepancies

| NAME                   | LLNR  | STATUS     | AID TYPE |
|------------------------|-------|------------|----------|
| Sergius Narrows Buoy 8 | 25195 | DAYMK DMGD | FD       |
| Wayanda Ledge Buoy 10  | 25205 | MISSING    | FD       |

Port Alexander

Federal Discrepancies

| NAME                 | LLNR  | STATUS      | AID TYPE |
|----------------------|-------|-------------|----------|
| Port Alexander Light | 23465 | REDUCED INT | FD       |

Port Chester

Federal Discrepancies

| NAME                           | LLNR  | STATUS | AID TYPE |
|--------------------------------|-------|--------|----------|
| Metlakatla Boat Harbor Light 2 | 22065 | LT EXT | FD       |

Port Graham

Additional MSI Categories

| TITLE                                                                                               | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                             | LOCATION                            |
|-----------------------------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Port Graham/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2025-04-18 To: 2025-10-15 Location: 59.37319° N / 151.87585° W An unmarked, semi-submerged steel pile visible at +3' tide has been observed in this position. Mariners are requested to transit the area with caution. | Lat: 59° 22' 23" Lon: -151° 52' 33" |

Port Valdez

Federal Discrepancies

| NAME                                | LLNR  | STATUS | AID TYPE |
|-------------------------------------|-------|--------|----------|
| Valdez Security Zone Lighted Buoy A | 25823 | LT EXT | FD       |
| Valdez Security Zone Lighted Buoy B | 25824 | LT EXT | FD       |

Private Discrepancies

| NAME                              | LLNR  | STATUS  | AID TYPE |
|-----------------------------------|-------|---------|----------|
| Port Valdez Servs Dock Lights (2) | 25822 | OFF STA | PA       |

Portage Pass

Federal Discrepancies

| NAME                      | LLNR  | STATUS      | AID TYPE |
|---------------------------|-------|-------------|----------|
| Portage Pass Daybeacon 11 | 23355 | STRUCT DEST | FD       |

Prince William Sound

Federal Discrepancies

| NAME                  | LLNR  | STATUS   | AID TYPE |
|-----------------------|-------|----------|----------|
| Seal Rocks Light      | 25515 | DBD DMGD | FD       |
| Schooner Rock Light 1 | 25525 | LT EXT   | FD       |
| Johnstone Point Light | 25535 | LT EXT   | FD       |

Additional MSI Categories

| TITLE                                                                                                        | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                   | LOCATION                            |
|--------------------------------------------------------------------------------------------------------------|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.61318° N / 147.19993° W Submerged Data Mooring Name: PWSSC-15 Water Depth: 722' Top Float Depth: 197' ***Surfaces twice daily*** POC: Dr. Rob Campbell Phone: 907-424-5800 Email: rcampbell@pwssc.org | Lat: 60° 36' 47" Lon: -147° 11' 60" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3425° N / 146.7304° W Submerged Data Mooring Name: H01 Water Depth: 98' Top Float Depth: 66' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                  | Lat: 60° 20' 33" Lon: -146° 43' 49" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.34° N / 146.742° W Submerged Data Mooring Name: H02 Water Depth: 879' Top Float Depth: 791' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                   | Lat: 60° 20' 24" Lon: -146° 44' 31" |

|                                                                                                              |                       |                                                                                                                                                                                                                                                                    |                                        |
|--------------------------------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3349° N / 146.7329° W Submerged Data Mooring Name: HB Water Depth: 830' Top Float Depth: 747' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org      | Lat: 60° 20' 06"<br>Lon: -146° 43' 58" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3352° N / 146.7661° W Submerged Data Mooring Name: H04 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 20' 07"<br>Lon: -146° 45' 58" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3328° N / 146.7785° W Submerged Data Mooring Name: H05 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 19' 58"<br>Lon: -146° 46' 43" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3302° N / 146.7903° W Submerged Data Mooring Name: H06 Water Depth: 896' Top Float Depth: 806' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 19' 49"<br>Lon: -146° 47' 25" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3278° N / 146.8023° W Submerged Data Mooring Name: H07 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 19' 40"<br>Lon: -146° 48' 08" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3245° N / 146.8159° W Submerged Data Mooring Name: H08 Water Depth: 935' Top Float Depth: 842' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 19' 28"<br>Lon: -146° 48' 57" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.322° N / 146.8297° W Submerged Data Mooring Name: H09 Water Depth: 1,007' Top Float Depth: 906' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org    | Lat: 60° 19' 19"<br>Lon: -146° 49' 47" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3198° N / 146.8418° W Submerged Data Mooring Name: H10 Water Depth: 1,060' Top Float Depth: 954' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org   | Lat: 60° 19' 11"<br>Lon: -146° 50' 30" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3123° N / 146.8776° W Submerged Data Mooring Name: H13 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 18' 44"<br>Lon: -146° 52' 39" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3098° N / 146.889° W Submerged Data Mooring Name: H14 Water Depth: 522' Top Float Depth: 470' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org      | Lat: 60° 18' 35"<br>Lon: -146° 53' 20" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3078° N / 146.8999° W Submerged Data Mooring Name: H15 Water Depth: 276' Top Float Depth: 244' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org     | Lat: 60° 18' 28"<br>Lon: -146° 53' 60" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.302° N / 146.8928° W Submerged Data Mooring Name: HC Water Depth: 449' Top Float Depth: 404' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org       | Lat: 60° 18' 07"<br>Lon: -146° 53' 34" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3168° N / 146.8538° W Submerged Data Mooring Name: H11 Water Depth: 1,135' Top Float Depth: 1,022' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org | Lat: 60° 19' 00"<br>Lon: -146° 51' 14" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.309° N / 146.9092° W Submerged Data Mooring Name: H16 Water Depth: 85' Top Float Depth: 53' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org        | Lat: 60° 18' 32"<br>Lon: -146° 54' 33" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.2997° N / 146.9056° W Submerged Data Mooring Name: HD Water Depth: 151' Top Float Depth: 119' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org      | Lat: 60° 17' 59"<br>Lon: -146° 54' 20" |

|                                                                                                                   |                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                     |
|-------------------------------------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions      | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3376° N / 146.7544° W Submerged Data Mooring Name: H03 Water Depth: 876' Top Float Depth: 860' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Lat: 60° 20' 15" Lon: -146° 45' 16" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions      | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3148° N / 146.8653° W Submerged Data Mooring Name: H12 Water Depth: 1,194' Top Float Depth: 1,079' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | Lat: 60° 18' 53" Lon: -146° 51' 55" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions      | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 60.50373° N / 146.51368° W A submerged mooring was reported lost in 315 feet of water in this position in 02/23. This mooring may be an obstruction to operations on the sea floor.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Lat: 60° 30' 13" Lon: -146° 30' 49" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Shoaling Reported | Hazards To Navigation | General/Hazards To Navigation/Shoaling Reported From: 2024-10-28 To: 2026-10-28 Location: 61.13408° N / 147.54442° W An uncharted and dangerous rock was reported in this position in June or 2019.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | Lat: 61° 08' 03" Lon: -147° 32' 40" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Wrecks            | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.796° N / 148.05517° W The F/V SONG II sank in this position in August 2018.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Lat: 60° 47' 46" Lon: -148° 03' 19" |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Hazards           | Hazards To Navigation | General/Hazards To Navigation/Hazards From: 2024-10-28 To: 2029-10-27 Location: 61.17206° N / 148.475° W 61.17074° N / 148.05752° W 61.03802° N / 148.05752° W 60.93011° N / 148.48324° W 61.17206° N / 148.475° W The State of Alaska is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm and has the potential to create a tsunami if/when a landslide is generated that impacts the water in Barry Arm. If/when this occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following an event. The geologic makeup of the area is similar to Alaskan locations where two previous landslide caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of the potential results of a slide. Additional information is available at <a href="https://dggs.alaska.gov/hazards/barry-arm-landslide.html">https://dggs.alaska.gov/hazards/barry-arm-landslide.html</a> . |                                     |
| Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Miscellaneous                           | Miscellaneous         | General/Miscellaneous From: 2025-06-13 To: 2025-12-10 Location: 60°47.243'N 147°40.0'W Scuttling of a Barge was conducted on 1/24/2025 at 60°47.243'N 147°40.0'W in a depth of 252 fathoms.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Lat: 60° 51' 03" Lon: -147° 40' 00" |

**Resurrection Bay**

**Federal Discrepancies**

| NAME                       | LLNR  | STATUS | AID TYPE |
|----------------------------|-------|--------|----------|
| Seward Boat Harbor Light 1 | 26015 | LT EXT | FD       |

**Private Discrepancies**

| NAME                     | LLNR  | STATUS      | AID TYPE |
|--------------------------|-------|-------------|----------|
| 4th of July Channel LT 1 | 26005 | STRUCT DEST | PA       |
| Seward Marine Dock Light | 26010 | LT EXT      | PA       |

**Additional MSI Categories**

| TITLE                                                                                                    | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                   | LOCATION                            |
|----------------------------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Submerged Land Act (SLA) - Resurrection Bay/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.85045° N / 149.50063° W Submerged Data Mooring Name: GAK1-24 Water Depth: 860' Top Float Depth: 65' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu | Lat: 59° 51' 02" Lon: -149° 30' 02" |

**San Christoval Channel**

**Federal Discrepancies**

| NAME                                 | LLNR  | STATUS | AID TYPE |
|--------------------------------------|-------|--------|----------|
| Hermanos Islands Reef Lighted Buoy 8 | 24545 | LT EXT | FD       |

**Sector Anchorage, Exclusive Economic Zone (EEZ)**

**Federal Discrepancies**

| NAME                               | LLNR  | STATUS      | AID TYPE |
|------------------------------------|-------|-------------|----------|
| Cape Hinchinbrook Light            | 1125  | LT EXT      | FD       |
| St. George Harbor Entrance Light 1 | 27827 | STRUCT DEST | FD       |

## Additional MSI Categories

| TITLE                                                                                      | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                | LOCATION                               |
|--------------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 75.10005° N / 168.00007° W<br>Submerged Data Mooring Name: AIM16-1 Water Depth: 535' Top Float Depth: 142' POC: Dr. Humfrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca                          | Lat: 75° 06' 00"<br>Lon: -168° 00' 00" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2025-04-01 Location: 66.61013° N / 164.63417° W<br>Submerged Data Mooring Name: XA23-ST-KS04 Water Depth: 49' Top Float Depth: 42' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov                        | Lat: 66° 36' 36"<br>Lon: -164° 38' 03" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 62.20477° N / 174.67642° W<br>Submerged Data Mooring Name: AL23-AU-M08 Water Depth: 230' Top Float Depth: 197' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                           | Lat: 62° 12' 17"<br>Lon: -174° 40' 35" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 56.86777° N / 164.05852° W<br>Submerged Data Mooring Name: 24BSPR-2A Water Depth: Unknown Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov | Lat: 56° 52' 04"<br>Lon: -164° 03' 31" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 58.26188° N / 163.55735° W<br>Submerged Data Mooring Name: 24KUM-2A Water Depth: 131' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov     | Lat: 58° 15' 43"<br>Lon: -163° 33' 26" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2025-04-13 Location: 71.67308° N / 154.9998° W<br>Submerged Data Mooring Name: BCE-22 Water Depth: 384' Top Float Depth: 62' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp                                           | Lat: 71° 40' 23"<br>Lon: -154° 59' 59" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.73445° N / 155.164° W<br>Submerged Data Mooring Name: BCC-22 Water Depth: 951' Top Float Depth: 66' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp                                            | Lat: 71° 44' 04"<br>Lon: -155° 09' 50" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.79635° N / 155.34687° W<br>Submerged Data Mooring Name: BCW-22 Water Depth: 554' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp                                         | Lat: 71° 47' 47"<br>Lon: -155° 20' 49" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 70.834° N / 163.126° W<br>Submerged Data Mooring Name: AL24-AU-IC01 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                              | Lat: 70° 50' 02"<br>Lon: -163° 07' 34" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.754° N / 154.475° W<br>Submerged Data Mooring Name: AL24-AU-BF02 Water Depth: 344' Top Float Depth: 312' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                              | Lat: 71° 45' 14"<br>Lon: -154° 28' 30" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.30823° N / 152.13573° W<br>Submerged Data Mooring Name: AON-B51 Water Depth: 554' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu                                       | Lat: 71° 18' 30"<br>Lon: -152° 08' 09" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3941° N / 152.05118° W<br>Submerged Data Mooring Name: AON-B53a Water Depth: 479' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu                                       | Lat: 71° 23' 39"<br>Lon: -152° 03' 04" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3968° N / 152.0032° W<br>Submerged Data Mooring Name: AON-B53b Water Depth: 502' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu                                        | Lat: 71° 23' 48"<br>Lon: -152° 00' 12" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.21467° N / 164.2485° W<br>Submerged Data Mooring Name: AL23-AU-IC02 Water Depth: 141' Top Float Depth: 108' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                           | Lat: 71° 12' 53"<br>Lon: -164° 14' 55" |

|                                                                                            |                       |                                                                                                                                                                                                                                                                                 |                                        |
|--------------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.831° N / 166.018° W<br>Submerged Data Mooring Name: AL24-AU-IC03 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov   | Lat: 71° 49' 52"<br>Lon: -166° 01' 05" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.204° N / 157.999° W<br>Submerged Data Mooring Name: AL24-AU-PB01 Water Depth: 157' Top Float Depth: 131' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov   | Lat: 71° 12' 14"<br>Lon: -157° 59' 56" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59952° N / 161.50698° W<br>Submerged Data Mooring Name: CEM1-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu               | Lat: 71° 35' 58"<br>Lon: -161° 30' 25" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59965° N / 161.52747° W<br>Submerged Data Mooring Name: CEM2-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu               | Lat: 71° 35' 59"<br>Lon: -161° 31' 39" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.58373° N / 161.49948° W<br>Submerged Data Mooring Name: CEO1-24 Water Depth: 154' Top Float Depth: 111' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu               | Lat: 71° 35' 01"<br>Lon: -161° 29' 58" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.60063° N / 161.5408° W<br>Submerged Data Mooring Name: CEO2-24 Water Depth: 151' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu                | Lat: 71° 36' 02"<br>Lon: -161° 32' 27" |
| General/Hazards To Navigation/Obstructions                                                 | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 66.327° N / 168.949° W<br>Submerged Data Mooring Name: A3-24 Water Depth: 190' Top Float Depth: 23' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu                       | Lat: 66° 19' 37"<br>Lon: -168° 56' 56" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.746° N / 168.2625° W<br>Submerged Data Mooring Name: A4-24 Water Depth: 161' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu                      | Lat: 65° 44' 46"<br>Lon: -168° 15' 45" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.12937° N / 168.313° W<br>Submerged Data Mooring Name: AL24-AU-PC01 Water Depth: 561' Top Float Depth: 535' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov | Lat: 56° 07' 46"<br>Lon: -168° 18' 47" |
| General/Hazards To Navigation/Obstructions                                                 | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 64.858° N / 168.448° W<br>Submerged Data Mooring Name: AL24-AU-NM01 Water Depth: 144' Top Float Depth: 118' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov   | Lat: 64° 51' 29"<br>Lon: -168° 26' 53" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.16° N / 166.582° W<br>Submerged Data Mooring Name: AL24-AU-BS10 Water Depth: 384' Top Float Depth: 358' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov    | Lat: 56° 09' 36"<br>Lon: -166° 34' 55" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 61.084° N / 170.264° W<br>Submerged Data Mooring Name: AL24-AU-BS11 Water Depth: 161' Top Float Depth: 135' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov   | Lat: 61° 05' 02"<br>Lon: -170° 15' 50" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.92815° N / 171.274° W<br>Submerged Data Mooring Name: 24BS-5A Water Depth: 226' Top Float Depth: 33' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov               | Lat: 59° 55' 41"<br>Lon: -171° 16' 26" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.91953° N / 171.71442° W<br>Submerged Data Mooring Name: 24BSP-5A Water Depth: 230' Top Float Depth: 194' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov           | Lat: 59° 55' 10"<br>Lon: -171° 42' 52" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.702° N / 152.187° W<br>Submerged Data Mooring Name: GA24-AU-SE01 Water Depth: 423' Top Float Depth: 384' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov   | Lat: 58° 42' 07"<br>Lon: -152° 11' 13" |

|                                                                                            |                       |                                                                                                                                                                                                                                                                                     |                                        |
|--------------------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.04167° N / 145.17° W<br>Submerged Data Mooring Name: UWAPL24 Water Depth: Unknown Top Float Depth: Surface POC: Joe Talbert Phone: 907-409-4627 Email: talbertj@uw.edu                      | Lat: 50° 02' 30"<br>Lon: -145° 10' 12" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.0267° N / 148.6707° W<br>Submerged Data Mooring Name: GEO2-24 Water Depth: 758' Top Float Depth: 82' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu                      | Lat: 59° 01' 36"<br>Lon: -148° 40' 15" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.02322° N / 144.36115° W<br>Submerged Data Mooring Name: FLMA Water Depth: 9,361' Top Float Depth: 68' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu                       | Lat: 50° 01' 24"<br>Lon: -144° 21' 40" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.37608° N / 144.51397° W<br>Submerged Data Mooring Name: FLMB Water Depth: 9,523' Top Float Depth: 68' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu                       | Lat: 50° 22' 34"<br>Lon: -144° 30' 50" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.1143° N / 144.91743° W<br>Submerged Data Mooring Name: HYPM Water Depth: 9,664' Top Float Depth: 342' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu                       | Lat: 50° 06' 51"<br>Lon: -144° 55' 03" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 77.49333° N / 140.18° W<br>Submerged Data Mooring Name: AMOS-VLF-1 Water Depth: 12,264' Top Float Depth: 230' POC: Craig Lee Email: craiglee@uw.edu                                            | Lat: 77° 29' 36"<br>Lon: -140° 10' 48" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.41333° N / 142.47° W<br>Submerged Data Mooring Name: AMOS-C Water Depth: 12,326' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu                                                | Lat: 76° 24' 48"<br>Lon: -142° 28' 12" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.14667° N / 145.28333° W<br>Submerged Data Mooring Name: AMOS-NW Water Depth: 12,441' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu                                            | Lat: 76° 08' 48"<br>Lon: -145° 16' 60" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 75.77333° N / 141.51333° W<br>Submerged Data Mooring Name: AMOS-NE Water Depth: 12,251' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu                                            | Lat: 75° 46' 24"<br>Lon: -141° 30' 48" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-04-16 Location: 75.5° N / 144.14° W Submerged Data Mooring Name: AMOS-B Water Depth: 12,379' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu                                                       | Lat: 75° 30' 00"<br>Lon: -144° 08' 24" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.875° N / 143.08667° W<br>Submerged Data Mooring Name: AMOS-SE Water Depth: 12,241' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu                                              | Lat: 74° 52' 30"<br>Lon: -143° 05' 12" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-04-16 Location: 75.21667° N / 146.67667° W<br>Submerged Data Mooring Name: AMOS-SW Water Depth: 12,464' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu                                            | Lat: 75° 13' 00"<br>Lon: -146° 40' 36" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.58833° N / 145.545° W<br>Submerged Data Mooring Name: AMOS-A Water Depth: 12,339' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu                                               | Lat: 74° 35' 18"<br>Lon: -145° 32' 42" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.52292° N / 161.94227° W<br>Submerged Data Mooring Name: NAP-23t Water Depth: 5,528' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp               | Lat: 74° 31' 23"<br>Lon: -161° 56' 32" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 68.98622° N / 105.88383° W<br>Submerged Data Mooring Name: ACW16-30 Water Depth: 242' Top Float Depth: 231' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca | Lat: 68° 59' 10"<br>Lon: -105° 53' 02" |

|                                                                                            |                       |                                                                                                                                                                                                                                                                                     |                                        |
|--------------------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-04-16 Location: 70.56283° N / 127.69517° W<br>Submerged Data Mooring Name: CB12 Water Depth: 125' Top Float Depth: 116' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca     | Lat: 70° 33' 46"<br>Lon: -127° 41' 43" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33385° N / 133.73948° W<br>Submerged Data Mooring Name: IBO16-1a Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca | Lat: 70° 20' 02"<br>Lon: -133° 44' 22" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33392° N / 133.74087° W<br>Submerged Data Mooring Name: IBO16-1b Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca | Lat: 70° 20' 02"<br>Lon: -133° 44' 27" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.98932° N / 133.74393° W<br>Submerged Data Mooring Name: IBO16-2 Water Depth: 365' Top Float Depth: 146' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca  | Lat: 70° 59' 22"<br>Lon: -133° 44' 38" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.0589° N / 133.7153° W<br>Submerged Data Mooring Name: IBO16-9a Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca   | Lat: 70° 03' 32"<br>Lon: -133° 42' 55" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.05835° N / 133.71562° W<br>Submerged Data Mooring Name: IBO16-9b Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca | Lat: 70° 03' 30"<br>Lon: -133° 42' 56" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.77472° N / 137.04595° W<br>Submerged Data Mooring Name: SIC16-11 Water Depth: 117' Top Float Depth: 107' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca | Lat: 69° 46' 29"<br>Lon: -137° 02' 45" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.65473° N / 138.92132° W<br>Submerged Data Mooring Name: HI16 Water Depth: 134' Top Float Depth: 125' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca     | Lat: 69° 39' 17"<br>Lon: -138° 55' 17" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.198° N / 174.663° W<br>Submerged Data Mooring Name: 24BS-8A Water Depth: 242' Top Float Depth: 59' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                     | Lat: 62° 11' 53"<br>Lon: -174° 39' 47" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.205° N / 174.676° W<br>Submerged Data Mooring Name: 24BSP-8A Water Depth: 242' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                   | Lat: 62° 12' 18"<br>Lon: -174° 40' 34" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.2012° N / 174.6819° W<br>Submerged Data Mooring Name: 24BSST-8A Water Depth: 242' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                | Lat: 62° 12' 04"<br>Lon: -174° 40' 55" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.202° N / 174.66° W<br>Submerged Data Mooring Name: 24BSITAER-8A Water Depth: 242' Top Float Depth: 66' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                 | Lat: 62° 12' 07"<br>Lon: -174° 39' 36" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.206° N / 174.665° W<br>Submerged Data Mooring Name: 24BSV-8A Water Depth: 242' Top Float Depth: 157' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                   | Lat: 62° 12' 22"<br>Lon: -174° 39' 54" |
| General/Hazards To Navigation/Obstructions                                                 | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 63.987° N / 168.052° W<br>Submerged Data Mooring Name: 24BSP-14A Water Depth: 118' Top Float Depth: 92' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                   | Lat: 63° 59' 13"<br>Lon: -168° 03' 07" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 70.837° N / 163.126° W<br>Submerged Data Mooring Name: 24CKP-1A Water Depth: 148' Top Float Depth: 115' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                   | Lat: 70° 50' 13"<br>Lon: -163° 07' 34" |

|                                                                                            |                       |                                                                                                                                                                                                                                                                                                      |                                     |
|--------------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2157° N / 164.2494° W Submerged Data Mooring Name: 24CKP-2A Water Depth: 148' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                     | Lat: 71° 12' 57" Lon: -164° 14' 58" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.831° N / 166.0145° W Submerged Data Mooring Name: 24CKP-3A Water Depth: 144' Top Float Depth: 121' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                      | Lat: 71° 49' 52" Lon: -166° 00' 52" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.0453° N / 160.48823° W Submerged Data Mooring Name: 24CKP-4A Water Depth: 167' Top Float Depth: 135' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                    | Lat: 71° 02' 43" Lon: -160° 29' 18" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2082° N / 158° W Submerged Data Mooring Name: 24CKP-5A Water Depth: 167' Top Float Depth: 144' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                          | Lat: 71° 12' 30" Lon: -158° 00' 00" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.47007° N / 156.5697° W Submerged Data Mooring Name: 24CKP-9A Water Depth: 3,054' Top Float Depth: 886' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                  | Lat: 72° 28' 12" Lon: -156° 34' 11" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 67.91° N / 168.181° W Submerged Data Mooring Name: 24CKP-12A Water Depth: 190' Top Float Depth: 141' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                       | Lat: 67° 54' 36" Lon: -168° 10' 52" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.3099° N / 167.272° W Submerged Data Mooring Name: 24CKP-15A Water Depth: 161' Top Float Depth: 131' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                     | Lat: 72° 18' 36" Lon: -167° 16' 19" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 56.87615° N / 164.05434° W Submerged Data Mooring Name: 25BSPR-2A Water Depth: 71 m Top Float Depth: Surface POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov Yellow Surface Buoy with light: Flashing Yellow 4s | Lat: 56° 52' 34" Lon: -164° 03' 16" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 56.86657° N / 164.06136° W Submerged Data Mooring Name: 25BS-2A Water Depth: 72 m Top Float Depth: 10 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                                         | Lat: 56° 51' 60" Lon: -164° 03' 41" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 56.86687° N / 164.04302° W Submerged Data Mooring Name: 25BSP-2A Water Depth: 72 m Top Float Depth: 62 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                                        | Lat: 56° 52' 01" Lon: -164° 02' 35" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.08299° N / 163.50042° W Submerged Data Mooring Name: AL25_AU_UN04 Water Depth: 100 m Top Float Depth: 87 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                           | Lat: 54° 04' 59" Lon: -163° 30' 02" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-06 To: 2027-05-06 Location: 57.87733° N / 168.88367° W Submerged Data Mooring Name: 25BSP-4A Water Depth: 72 m Top Float Depth: 61 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                                        | Lat: 57° 52' 38" Lon: -168° 53' 01" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.12698° N / 168.31173° W Submerged Data Mooring Name: AL25_AU_PC01 Water Depth: 169 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                           | Lat: 56° 07' 37" Lon: -168° 18' 42" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 55.572° N / 154.975° W Submerged Data Mooring Name: GA24_AU_CR01 Water Depth: 400 m Top Float Depth: 70 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                               | Lat: 55° 34' 19" Lon: -154° 58' 30" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 53.971° N / 161.663° W Submerged Data Mooring Name: GA24-AU-SN01 Water Depth: 436 m Top Float Depth: 86 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                               | Lat: 53° 58' 16" Lon: -161° 39' 47" |

|                                                                       |               |                                                                                                                                                                                                                                                             |                                     |
|-----------------------------------------------------------------------|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 56.15927° N / 166.58292° W Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov | Lat: 56° 09' 33" Lon: -166° 34' 59" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous | Miscellaneous | Submerged Data Mooring Name: GA25-AU-PO01 Water Depth: 116 m Top Float Depth: 105 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                                                                            | Lat: 58° 33' 59" Lon: -149° 59' 28" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous | Miscellaneous | Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 64.85793° N / 168.44803° W Name: AL25_AU_NM01 Water Depth: 44 m Top Float Depth: 34 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                         | Lat: 64° 51' 29" Lon: -168° 26' 53" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.75395° N / 154.47518° W Name: AL25_AU_BF02 Water Depth: 105 m Top Float Depth: 99 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                         | Lat: 71° 45' 14" Lon: -154° 28' 31" |
| Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous | Miscellaneous | Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 71.83082° N / 166.01868° W Name: AL25_AU_IC03 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                         | Lat: 71° 49' 51" Lon: -166° 01' 07" |

**Sector Anchorage, Submerged Land Act (SLA)**

**Federal Discrepancies**

| NAME                             | LLNR  | STATUS            | AID TYPE |
|----------------------------------|-------|-------------------|----------|
| Sealion Rocks Light              | 1245  | LT EXT            | FD       |
| Kalgin Island Light              | 26300 | LT EXT            | FD       |
| Unalakleet River Buoys (About 6) | 27915 | Status Unreported | FD       |

**Additional MSI Categories**

| TITLE                                                                                                                     | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                    | LOCATION                            |
|---------------------------------------------------------------------------------------------------------------------------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.2289° N / 162.16302° W Submerged Data Mooring Name: XA23-ST-KS07 Water Depth: 46' Top Float Depth: 39' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov                | Lat: 66° 13' 44" Lon: -162° 09' 47" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 57.72427° N / 152.28335° W Submerged Data Mooring Name: 23CB-1A Water Depth: 545' Top Float Depth: 472' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                              | Lat: 57° 43' 27" Lon: -152° 17' 00" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.91099° N / 149.3493° W Submerged Data Mooring Name: GAKOA Water Depth: 171' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: Natalie Monacci Phone: 907-474-7956 Email: nmonacci@alaska.edu | Lat: 59° 54' 40" Lon: -149° 20' 57" |
| General/Hazards To Navigation/Obstructions                                                                                | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9247° N / 147.8105° W Submerged Data Mooring Name: M01 Water Depth: 295' Top Float Depth: 263' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                 | Lat: 59° 55' 29" Lon: -147° 48' 38" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9308° N / 147.8179° W Submerged Data Mooring Name: M02 Water Depth: 446' Top Float Depth: 401' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                 | Lat: 59° 55' 51" Lon: -147° 49' 04" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9363° N / 147.8253° W Submerged Data Mooring Name: M03 Water Depth: 509' Top Float Depth: 458' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                 | Lat: 59° 56' 11" Lon: -147° 49' 31" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9426° N / 147.8326° W Submerged Data Mooring Name: M04 Water Depth: 577' Top Float Depth: 519' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                 | Lat: 59° 56' 33" Lon: -147° 49' 57" |
|                                                                                                                           |                       |                                                                                                                                                                                                                                                                                                |                                     |

|                                                                                                                           |                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                     |
|---------------------------------------------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9481° N / 147.8397° W Submerged Data Mooring Name: M05 Water Depth: 640' Top Float Depth: 576' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 56' 53" Lon: -147° 50' 23" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-04-15 Location: 59.9591° N / 147.8539° W Submerged Data Mooring Name: M07 Water Depth: 741' Top Float Depth: 667' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 57' 33" Lon: -147° 51' 14" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9807° N / 147.8811° W Submerged Data Mooring Name: M11 Water Depth: 472' Top Float Depth: 425' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 58' 51" Lon: -147° 52' 52" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9753° N / 147.8892° W Submerged Data Mooring Name: MD Water Depth: 614' Top Float Depth: 553' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                    | Lat: 59° 58' 31" Lon: -147° 53' 21" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.1149° N / 148.2353° W Submerged Data Mooring Name: BP07 Water Depth: 171' Top Float Depth: 154' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                  | Lat: 60° 06' 54" Lon: -148° 14' 07" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0464° N / 148.1247° W Submerged Data Mooring Name: POWP05 Water Depth: 315' Top Float Depth: 299' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                | Lat: 60° 02' 47" Lon: -148° 07' 29" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0465° N / 148.12982° W Submerged Data Mooring Name: POWP06 Water Depth: 154' Top Float Depth: 138' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                               | Lat: 60° 02' 47" Lon: -148° 07' 47" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9808° N / 148.0319° W Submerged Data Mooring Name: LP01 Water Depth: 112' Top Float Depth: 95' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 58' 51" Lon: -148° 01' 55" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9847° N / 148.03698° W Submerged Data Mooring Name: LP02 Water Depth: 144' Top Float Depth: 128' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                 | Lat: 59° 59' 05" Lon: -148° 02' 13" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9537° N / 147.8473° W Submerged Data Mooring Name: M06 Water Depth: 702' Top Float Depth: 686' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 57' 13" Lon: -147° 50' 50" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9643° N / 147.8605° W Submerged Data Mooring Name: M08 Water Depth: 758' Top Float Depth: 741' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 57' 51" Lon: -147° 51' 38" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9691° N / 147.8668° W Submerged Data Mooring Name: M09 Water Depth: 643' Top Float Depth: 617' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 58' 09" Lon: -147° 52' 00" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9752° N / 147.8739° W Submerged Data Mooring Name: M10 Water Depth: 784' Top Float Depth: 768' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                                                                                                                                                                                                                                                                                   | Lat: 59° 58' 31" Lon: -147° 52' 26" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 54.12848° N / 165.77305° W An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in this position on the sea floor in approximately 138 feet. This anomaly has not been positively identified and mariners are requested to transit the area with caution.                                                                                                                                                          | Lat: 54° 07' 43" Lon: -165° 46' 23" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Hazards      | Hazards To Navigation | General/Hazards To Navigation/Hazards From: 2025-05-15 To: 2025-10-15 Western Marine Construction will be performing work on the Kenai River in the vicinity of Old Town Park downtown from May 16th – October 15th. Vessels transiting the area should give work barges a wide berth. Anchor lines from barges, marked with crown buoys, will extend into the channel creating a hazard. During low tides certain vessels may not be able to transit depending on draft. For more information, please contact Western Marine at (206) 622-9161. |                                     |

|                                                                                                                                         |                                         |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                        |
|-----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging | Marine Construction (Excluding Bridges) | General/Marine Construction (Excluding Bridges)/Dredging From: 2025-03-31 To: 2025-09-27 Dredging and other miscellaneous marine construction will be conducted at the Port of Alaska from April 7th through October 31st, 2025. Two mooring buoys with quick flashing white lights will be established northwest of Terminal 3 in positions 61°15'17.51" N, 149°53'31.57" and 61°25'05.67" N, 149°53'31.78" W. During operations VHF/FM channel 8 will be monitored. Derrick barges will have anchors deployed and submerged anchor cables will be marked by crown buoys over each submerged anchor. Mariners are requested to maintain a minimum 1,000-foot CPA, proceed with caution and to operate at a slow speed when transiting in this area.                                                                                            |                                        |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging | Marine Construction (Excluding Bridges) | General/Marine Construction (Excluding Bridges)/Dredging From: 2025-09-01 To: 2026-02-06 Alaska Marine Excavation, LLC. will be conducting dredging operations at the Cruise Ship Terminal Dock starting September 15th, 2025 thru January 31st 2026. Dredging operations will continue 24 hours a day. The dredge COMMANDER is a 58' cutter head suction dredge, red and yellow in color, with a partially submerged pipeline. The pipeline will extend approx. 3000ft South and terminate in open water. Dredge pipeline will be marked with yellow buoys and termination scow. The dredge COMMANDER and tug Growler will be working on VHF/FM channel 79 and monitoring VHF/FM channels 13 and 16. Questions/concerns can also be directed to Brok Shafer with Alaska Marine Excavation, LLC at (907) 399-4549 or by email to brok@akmx.com. |                                        |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: <a href="https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n">https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n</a> This pipeline is the Sagavanirktok River-Main Channel (Sag), mile 8.9, approximately 9.5 miles east of Deadhorse, Alaska (70.224550°N, -147.955285°W)                                                                                                                                                                                                                      | Lat: 70° 13' 28"<br>Lon: -147° 57' 19" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | "A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: <a href="https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n">https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n</a> This pipeline is the Tolovana River, mile 143.4, approximately 5 miles southwest of Livengood, Alaska (65.461173°N, -148.633068°W).                                                                                                                                                                                                                                       | Lat: 65° 27' 40"<br>Lon: -148° 37' 59" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | ""A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: <a href="https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n">https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n</a> This pipeline is the Middle Fork Chulitna River, mile 11.2, approximately 17 miles southwest of Cantwell, Alaska (63.211826°N, -149.326663°W).                                                                                                                                                                                                                           | Lat: 63° 12' 43"<br>Lon: -149° 19' 36" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | "A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: <a href="https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n">https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n</a> This pipeline is the East Fork Chulitna River, mile 8.3, approximately 19.8 miles southwest of Cantwell, Alaska (63.172206°N, -149.360919°W).                                                                                                                                                                                                                             | Lat: 63° 10' 20"<br>Lon: -149° 21' 39" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | "A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: <a href="https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n">https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&amp;subdistrict=n</a> This pipeline is the Deshka River, 8.9, approximately 10.6 miles northwest of Willow, Alaska (61.793293°N, -150.34713°W).                                                                                                                                                                                                                                                 | Lat: 61° 47' 36"<br>Lon: -150° 20' 50" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | From: 2025-07-28 To: 2026-01-24 A wave buoy which is marked with a white spar buoy was deployed at the following location: 70.53277° N / 149.8656° W POC: Geoff Kany (alt. Ryan Childs)   Willow Field Environmental Coordinator   Williwaw Environmental Consulting, LLC. on assignment at ConocoPhillips wil0015@conocophillips.com O: 907-659-1412, M: 907-341-9760                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Lat: 70° 31' 58"<br>Lon: -149° 51' 56" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | General/Miscellaneous From: 2025-07-28 To: 2027-07-28 A wave buoy was deployed and marked with a white spar buoy at the following location: 70.56618° N / 149.998° W POC: Geoff Kany (alt. Ryan Childs)   Willow Field Environmental Coordinator Williwaw Environmental Consulting, LLC. on assignment at ConocoPhillips wil0015@conocophillips.com O: 907-659-1412, M: 907-341-9760                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Lat: 70° 33' 58"<br>Lon: -149° 59' 53" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | General/Miscellaneous From: 2025-07-28 To: 2027-07-28 A wave buoy was deployed and marked with a white spar buoy at the following location: 70.52362° N / 150.08078° W POC: Geoff Kany (alt. Ryan Childs)   Willow Field Environmental Coordinator   Williwaw Environmental Consulting, LLC. on assignment at ConocoPhillips wil0015@conocophillips.com O: 907-659-1412   M: 907-341-9760                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Lat: 70° 31' 25"<br>Lon: -150° 04' 51" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 70.83413° N / 154.47628° W Name: AL25_AU_IC01 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | Lat: 70° 50' 03"<br>Lon: -154° 28' 35" |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | General/Miscellaneous From: 2025-04-30 To: 2025-10-27 Location: South Central Cook Inlet The following aids have been established for the season: Kenai Entrance Channel LB "1KE" LLNR 26320, East Foreland Buoy 2 LLNR 26360, Kasilof Entrance Channel Buoy 2-13 LLNR 26315-26319.9, Middle Ground Shoal LB 3 LLNR 26367, Cook Inlet LBB 6 LLNR 26384, Knik Arm Shoal LB 7 LLNR 26420                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                        |
| Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous                                    | Miscellaneous                           | Ocean Renewable Power Company (ORPC) will be conducting work near Stebbins, AK at two pre-selected sites: Site A. Latitude 63.5441, Longitude -162.3295 ; Site B. Latitude 63.5426, Longitude -162.322. The area will be marked by dual high-visibility orange buoys. The work should be completed by 09/26/2025. Mariners should transit the area with caution. POC: Luke Graham lgraham@orpc.co (907) 227 9861                                                                                                                                                                                                                                                                                                                                                                                                                                |                                        |

Sector Anchorage, Territorial Sea

Federal Discrepancies

| NAME             | LLNR  | STATUS   | AID TYPE |
|------------------|-------|----------|----------|
| Stag Point Light | 27180 | DBD DMGD | FD       |

Additional MSI Categories

| TITLE | SUBCATEGORY | DESCRIPTION | LOCATION |
|-------|-------------|-------------|----------|
|-------|-------------|-------------|----------|

|                                                                                                                                |                       |                                                                                                                                                                                                                                                                                  |                                     |
|--------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 67.0705° N / 164.2485° W Submerged Data Mooring Name: ZA23-ST-KS01 Water Depth: 55' Top Float Depth: 48' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov   | Lat: 67° 04' 14" Lon: -164° 14' 55" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.68353° N / 164.45487° W Submerged Data Mooring Name: XA23-ST-KS03 Water Depth: 59' Top Float Depth: 52' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov | Lat: 66° 41' 01" Lon: -164° 27' 18" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.78135° N / 163.75167° W Submerged Data Mooring Name: XA23-ST-KS02 Water Depth: 80' Top Float Depth: 73' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov | Lat: 66° 46' 53" Lon: -163° 45' 06" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.7805° N / 168.568° W Submerged Data Mooring Name: A2-24 Water Depth: 184' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu                          | Lat: 65° 46' 50" Lon: -168° 34' 05" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.434° N / 165.274° W Submerged Data Mooring Name: AL24-AU-UN01b Water Depth: 528' Top Float Depth: 502' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov      | Lat: 54° 26' 02" Lon: -165° 16' 26" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.6° N / 156.999° W Submerged Data Mooring Name: GA24-AU-SU01 Water Depth: 469' Top Float Depth: 443' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov         | Lat: 56° 36' 00" Lon: -156° 59' 56" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.85295° N / 158.99135° W Submerged Data Mooring Name: 23SH-1A Water Depth: 256' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                | Lat: 54° 51' 11" Lon: -158° 59' 29" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9697° N / 146.8812° W Submerged Data Mooring Name: MC Water Depth: 745' Top Float Depth: 671' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org                    | Lat: 59° 58' 11" Lon: -146° 52' 52" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.30669° N / 164.75179° W Submerged Data Mooring Name: 25UPP-3A Water Depth: 74 m Top Float Depth: 66 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov                                    | Lat: 54° 18' 24" Lon: -164° 45' 06" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.43427° N / 165.2728° W Submerged Data Mooring Name: AL25_AU_UN01 Water Depth: 160 m Top Float Depth: 146 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                       | Lat: 54° 26' 03" Lon: -165° 16' 22" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 53.63045° N / 167.40012° W Submerged Data Mooring Name: AL25_AU_UM01 Water Depth: 89 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                        | Lat: 53° 37' 50" Lon: -167° 24' 00" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 57.023° N / 152.999° W Submerged Data Mooring Name: GA24-AU-BT01 Water Depth: 84 m Top Float Depth: 74 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                            | Lat: 57° 01' 23" Lon: -152° 59' 56" |
| Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous                      | Miscellaneous         | General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.20405° N / 154.48198° W Name: AL25_AU_PB01 Water Depth: 49 m Top Float Depth: 41 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov                                               | Lat: 71° 12' 15" Lon: -154° 28' 55" |

**Sector Southeast Alaska, Submerged Land Act (SLA)**

**Federal Discrepancies**

| NAME                | LLNR | STATUS              | AID TYPE |
|---------------------|------|---------------------|----------|
| Lowrie Island Light | 995  | DAYMK MISSING       | FD       |
| Lowrie Island Light | 995  | DBD DMGD/DAYMK DMGD | FD       |

**Additional MSI Categories**

| TITLE | SUBCATEGORY | DESCRIPTION | LOCATION |
|-------|-------------|-------------|----------|
|-------|-------------|-------------|----------|

|                                                                                              |                       |                                                                                                                                                                                                                                                                       |                                     |
|----------------------------------------------------------------------------------------------|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.93223° N / 139.60566° W Submerged Data Mooring Name: DB1-24 Water Depth: 754' Top Float Depth: 164' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu         | Lat: 59° 55' 56" Lon: -139° 36' 20" |
| Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions | Hazards To Navigation | General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.12272° N / 136.5934° W Submerged Data Mooring Name: 20CSP-4A Water Depth: 1,099' Top Float Depth: 1,069' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov | Lat: 58° 07' 22" Lon: -136° 35' 36" |

Sitka Sound

Federal Discrepancies

| NAME                  | LLNR  | STATUS   | AID TYPE |
|-----------------------|-------|----------|----------|
| Vitskari Island Light | 24915 | RAC INOP | FD       |

Additional MSI Categories

| TITLE                                                                                                | SUBCATEGORY           | DESCRIPTION                                                                                                                                                                                                                                                                                                                                                                                                                       | LOCATION                            |
|------------------------------------------------------------------------------------------------------|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Sector Southeast Alaska, Submerged Land Act (SLA) - Sitka Sound/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 57.04345° N / 135.20597° W The F/V DRAGON LADY sank in Canoe Cove in this position. The F/V DRAGON LADY is a 76 foot wooden fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980. | Lat: 57° 02' 36" Lon: -135° 12' 21" |

St Paul Harbor

Federal Discrepancies

| NAME                           | LLNR  | STATUS                  | AID TYPE |
|--------------------------------|-------|-------------------------|----------|
| St. Paul Harbor Entrance Light | 26680 | STRUCT DMGD/REDUCED INT | FD       |

Stephens Passage

Federal Discrepancies

| NAME               | LLNR  | STATUS            | AID TYPE |
|--------------------|-------|-------------------|----------|
| Five Finger Light  | 23280 | LT EXT            | FD       |
| Hobart Bay Light 2 | 23595 | DAYMK MISSING     | FD       |
| Holkham Bay Buoy 1 | 23631 | Status Unreported | FD       |
| Holkham Bay Buoy 1 | 23631 | Status Unreported | FD       |
| Holkham Bay Buoy 1 | 23631 | MISSING           | FD       |
| Holkham Bay Buoy 2 | 23632 | Status Unreported | FD       |
| Holkham Bay Buoy 2 | 23632 | MISSING           | FD       |
| Tracy Arm Light    | 23635 | MISSING           | FD       |
| Middle Point Light | 23785 | LT EXT            | FD       |

Additional MSI Categories

| TITLE                                                    | SUBCATEGORY   | DESCRIPTION                                                                                                                                                                                                                                                                                           | LOCATION                            |
|----------------------------------------------------------|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Frederick Sound - Stephens Passage/General/Miscellaneous | Miscellaneous | General/Miscellaneous From: 2024-10-28 To: 2026-10-28 Location: 58.37614° N / 134.72318° W The U.S. Coast Guard has established a temporary mooring buoy in this location. This mooring buoy has been established for official use and should not be used without authorization from the Coast Guard. | Lat: 58° 22' 34" Lon: -134° 43' 23" |

Sukkwān Strait

Federal Discrepancies

| NAME                | LLNR  | STATUS                 | AID TYPE |
|---------------------|-------|------------------------|----------|
| Turn Rock Daybeacon | 24415 | DBD DMGD/DAYMK MISSING | FD       |

Sumner Strait

Federal Discrepancies

| NAME                             | LLNR  | STATUS            | AID TYPE |
|----------------------------------|-------|-------------------|----------|
| Mitchell Point Lighted Buoy 9    | 22740 | Status Unreported | FD       |
| Five Fathom Shoal Lighted Buoy F | 23285 | LT EXT            | FD       |
| The Eye Opener Light             | 23290 | LT EXT            | FD       |

Sweeper Cove

Federal Discrepancies

| NAME                           | LLNR  | STATUS     | AID TYPE |
|--------------------------------|-------|------------|----------|
| Sweeper Cove Range Front Light | 27542 | DAYMK DMGD | FD       |

Tlevak Narrows

Federal Discrepancies

| NAME                   | LLNR  | STATUS        | AID TYPE |
|------------------------|-------|---------------|----------|
| Tlevak Narrows Light 2 | 24440 | DAYMK MISSING | FD       |
| Tlevak Narrows Buoy 4  | 24445 | MISSING       | FD       |

Tongass Narrows

Federal Discrepancies

| NAME                    | LLNR  | STATUS        | AID TYPE |
|-------------------------|-------|---------------|----------|
| Refuge Cove Daybeacon 3 | 22270 | DAYMK MISSING | FD       |

Uganik Bay.

Federal Discrepancies

| NAME                  | LLNR  | STATUS      | AID TYPE |
|-----------------------|-------|-------------|----------|
| Northeast Arm Light 1 | 27000 | STRUCT DEST | FD       |

Unalaska Bay.

Federal Discrepancies

| NAME                        | LLNR     | STATUS | AID TYPE |
|-----------------------------|----------|--------|----------|
| Eider Point Lighted Buoy EP | 27500.75 | LT EXT | FD       |

Western Channel

Federal Discrepancies

| NAME                     | LLNR  | STATUS | AID TYPE |
|--------------------------|-------|--------|----------|
| Sitka Breakwater Light 7 | 25025 | LT EXT | FD       |

Whitestone Narrows

Federal Discrepancies

| NAME                                 | LLNR  | STATUS | AID TYPE |
|--------------------------------------|-------|--------|----------|
| Whitestone Narrows Range Front Light | 25120 | LT EXT | FD       |

Wrangell Narrows

Federal Discrepancies

| NAME                              | LLNR  | STATUS     | AID TYPE |
|-----------------------------------|-------|------------|----------|
| Wrangell Narrows Daybeacon 10A    | 22916 | VEGETATION | FD       |
| Wrangell Narrows Channel Light 51 | 23120 | DBD DMGD   | FD       |

Yakutat Bay.

Federal Discrepancies

| NAME                                        | LLNR  | STATUS | AID TYPE |
|---------------------------------------------|-------|--------|----------|
| Yakutat Bay Entrance Lighted Whistle Buoy 2 | 25420 | LT EXT | FD       |

Zimovia Strait

Additional MSI Categories

| TITLE | SUBCATEGORY | DESCRIPTION | LOCATION |
|-------|-------------|-------------|----------|
|       |             |             |          |

|                                                                     |                       |                                                                                                                                                                                                                                                                                                                                                                                                                            |                                        |
|---------------------------------------------------------------------|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|
| Sumner Strait - Zimovia Strait/General/Hazards To Navigation/Wrecks | Hazards To Navigation | General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 56.19921° N / 132.49282° W The F/V PAMELA RAE LADY sank in Canoe Cove in this position. The F/V PAMELA RAE LADY is a 58 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980. | Lat: 56° 11' 57"<br>Lon: -132° 29' 34" |
|---------------------------------------------------------------------|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|