



U.S. Department of Homeland Security

United States Coast Guard

LOCAL NOTICE TO MARINERS

District: 17

Week: 45/24

58-Navigation Information Service (NIS)-
Watchstander, 24 hours a day at (703) 313-5900
~Navcen Internet Address~
<https://www.navcen.uscg.gov>

-Local Notice to Mariners <https://www.navcen.uscg.gov/-pageName=InmMain>
Issued by: Commander (DPW) Telephone: (907) 463-2269 (0800-1600)
Seventeenth Coast Guard District After Hours: (907) 463-2000 (1600-0800)
PO Box 25517, Juneau, AK 99802-5517

Questions, comments, or additional information on this Local Notice to Mariners should be sent to the address above or by E-mail to: SMB-D17Juneau LNM@uscg.mil. You can get the U.S. Coast Guard 17th District Local Notice to Mariners via the Internet directly from the U.S. Coast Guard Navigation Center web site at <https://www.navcen.uscg.gov/-pageName=InmDistrict@ion=17>.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands (COMDTPUB P16502.6).

U.S. Coast Pilot 8, Pacific Coast Alaska: Dixon Entrance to Cape Spencer, 46th Edition.

U.S. Coast Pilot 9, Pacific and Arctic Coasts Alaska: Cape Spencer to Beaufort Sea, 41st Edition.

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by CG Sector Southeast Alaska Broadcast Notice to Mariners through SEAK359-24 and CG Sector Anchorage Broadcast Notice to Mariners through A181-24 that are still in effect are included in this notice.

Chart Corrections

<https://nauticalcharts.noaa.gov/charts/chart-updates.html>

Dates of Latest Editions, Nautical Charts, and Miscellaneous Maps

<https://nauticalcharts.noaa.gov/charts/list-of-latest-editions.html>

Light List/ Summary of Corrections

<https://www.navcen.uscg.gov/-pageName=lightListCorrections>

NOAA Chart Viewer (Posting of all up to date NOAA charts for viewing on Internet browser to be used for ready reference or planning)

<https://nauticalcharts.noaa.gov/>

NOAA Booklet Charts

<https://nauticalcharts.noaa.gov/charts/noaa-raster-charts.html#booklet-charts>

Coast Pilots, along with corrections, are available at:

<https://nauticalcharts.noaa.gov/publications/coast-pilot/index.html>

NOAA Weather Buoy Sites

<http://www.ndbc.noaa.gov/>

Tides online

<https://tidesandcurrents.noaa.gov/>

Tides, Currents, PORTS

<https://tidesandcurrents.noaa.gov/noaacurrents/Stations-g=693>

Weather

<https://www.weather.gov/marine/alaskatext>

Vessel Traffic System Prince William Sound (VTSPWS) Users Manual

<https://homeport.uscg.mil/Lists/Content/DispForm.aspx-ID=2205&Source=https://>

Abbreviations

ADRIFT - Buoy Adrift	ICW - Intracoastal Waterway	R - Red
AICW - Atlantic Intracoastal Waterway	IMCH - Improper Characteristic	RACON - Radar Transponder Beacon
AI - Alternating	INL - Inlet	Ra ref - Radar reflector
B - Buoy	INOP - Not Operating	RBN - Radio Beacon
BKW - Breakwater	INT - Intensity	REBUILT - Aid Rebuilt
bl - Blast	ISL - Islet	RECOVERED - Aid Recovered
BNM - Broadcast Notice to Mariner	Iso - Isophase	RED - Red Buoy
bu - Blue	kHz - Kilohertz	REFL - Reflective
C - Canadian	LAT - Latitude	RRL - Range Rear Light
CHAN - Channel	LB - Lighted Buoy	RELIGHTED - Aid Relit
CGD - Coast Guard District	LBB - Lighted Bell Buoy	RELOC - Relocated
C/O - Cut Off	LHB - Lighted Horn Buoy	RESET ON STATION - Aid Reset on Station
CONT - Contour	LGB - Lighted Gong Buoy	RFL - Range Front Light
CRK - Creek	LONG - Longitude	RIV - River
CONST - Construction	LNM - Local Notice to Mariners	RRASS - Remote Radio Activated
DAYMK/Daymk - Daymark	LT - Light	Sound Signal
DBN/Dbn - Daybeacon	LT CONT - Light Continuous	s - seconds
DBD/DAYBD - Dayboard	LTR - Letter	SEC - Section
DEFAC - Defaced	LWB - Lighted Whistle Buoy	SHL - Shoaling
DEST - Destroyed	LWP - Left Watching Properly	si - silent
DISCON - Discontinued	MHz - Megahertz	SIG - Signal
DMGD/DAMGD - Damaged	MISS/MSNG - Missing	SND - Sound
ec - eclipse	Mo - Morse Code	SPM - Single Point Mooring Buoy
EST - Established Aid	MRASS - Marine Radio Activated Sound Signal	SS - Sound Signal
ev - every	MSLD - Misleading	STA - Station
EVAL - Evaluation	N/C - Not Charted	STRUCT - Structure
EXT - Extinguished	NGA - National Geospatial Intelligence Agency	St M - Statute Mile
F - Fixed	NO/NUM - Number	TEMP - Temporary Aid Change
fl - flash	NOS - National Ocean Service	TMK - Topmark
Fl - Flashing	NW - Notice Writer	TRLB - Temporarily Replaced by Lighted Buoy
G - Green	OBSCU - Obscured	TRLT - Temporarily Replaced by Light
GIWW - Gulf Intracoastal Waterway	OBST - Obstruction	
HAZ - Hazard to Navigation		

HBR - Harbor
I - Interrupted

OBSTR - Obstruction
PRIV - Private Aid
Q - Quick

TRUB - Temporarily Replaced
by Unlighted Buoy
USACE - Army Corps of
Engineers

Bar Harbor

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bar Harbor Breakwater East Light	22201	STRUCT DEST	PA
Bar Harbor Breakwater Middle Light	22202	STRUCT DEST	PA
Bar Harbor Breakwater West Light	22203	STRUCT DEST	PA

Bechevin Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bechevin Bay Entrance Buoy BB	27250	MISSING	FD
Isanotski Strait Light 3	27410	LT EXT	FD

Behm Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Moser Bay Coast Guard Lighted Mooring Buoy	22329	MISSING	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Moser Bay Coast Guard Lighted Mooring Buoy	22329	DISCONTINUED	FD

Bering Sea Eastern Part

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024- 10-28	2026- 10-28	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 62.5925° N / 164.908° W A 6' by 6' by 15' metal tower was destroyed and partially submerged in this position in June of 2021. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Western Alaska and U.S. Arctic at 907- 428-4100.	POINT [Latitude: 62.5925, Longitude: -164.908]

Blake Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blake Channel Light 1	22670	STRUCT DEST/LT EXT	FD

Captains Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bailey Ledge Light	27505	LT EXT/STRUCT DMGD	FD

Chatham Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Ommaney Light	23460	LT EXT	FD
Point Ellis Light	23510	LT EXT	FD
Point Gardner Light	23530	LT EXT	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Dixon Entrance To Cape St Elias - Chatham Strait/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-08-23	2025-02-19		POINT [Latitude: 57.01005, Longitude: -134.61606]
Dixon Entrance To Cape St Elias - Chatham Strait/General/Miscellaneous	General	Miscellaneous	2024-08-22	2025-02-18	General/Miscellaneous From: 2024-08-22 To: 2025-02-18 Location: 57.35802° N / 134.63806° W 57.34524° N / 134.64184° W 57.3458° N / 134.6566° W 57.3575° N / 134.65282° W 57.35802° N / 134.63806° W	POLYGON [Latitude: 57.35802, Longitude: -134.63806] [Latitude: 57.34524, Longitude: -134.64184] [Latitude: 57.3458, Longitude: -134.6566] [Latitude: 57.3575, Longitude: -134.65282] [Latitude: 57.35802, Longitude: -134.63806]
Sector Southeast Alaska, Submerged Land Act (SLA) - Chatham Strait/General/Hazards To Navigation/Wrecks	General	Hazards To Navigation	2024-10-28	2026-10-28	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 57.84975° N / 135.02875° W The F/V BAILEY BAY sank in this position in approximately 30 feet of water in October of 2022. The F/V BAILEY BAY is a 33' fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel.	POINT [Latitude: 57.84975, Longitude: -135.02875]

Chilkoot Inlet

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Lynn Canal - Chilkoot Inlet/General To Navigation/Obstructions	General	Hazards To Navigation	2024-10-28	2026-10-28	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 59.24033° N / 135.43087° W An anchor an 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor.	POINT [Latitude: 59.24033, Longitude: -135.43087]

Clarence Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bushy Island Light	22510	DAYMK DMGD	FD
Snow Passage Lighted Buoy SP	22515	LT EXT	FD
Bay Point Daybeacon BP	22525	DAYMK DMGD	FD

Dixon Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Chacon Light	21850	DAYMK DMGD	FD

Dry Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Pass Daybeacon 3	24790	STRUCT DEST	FD
Dry Pass Daybeacon 25	24880	STRUCT DEST	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Shakan Bay - Dry Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-04	2025- 04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 56.15574° N / 133.45397° W Aid Name: Dry Pass Daybeacon 25 LLNR: 24880 Discrepancy Information: Initial Report DTG: 041834Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 56.15574, Longitude: -133.45397]

East Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Nichols Passage East Channel Daybeacon 2	22040	STRUCT DEST	FD

Eastern Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River Flats Lighted Buoy 2	24948	LT EXT	FD
Mitchell Rock Daybeacon	24957	STRUCT DEST	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sitka Sound - Eastern Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-17	2025-04-15	ATON/Federal Discrepancies From: 2024-10-17 To: 2025-04-15 Location: 57.03268° N / 135.25012° W Aid Name: Entry Point Light 1 LLNR: 24945 Discrepancy Information: Initial Report DTG: 171720Z OCT 2024 Summary: LT EXT	POINT [Latitude: 57.03268, Longitude: -135.25012]
Sitka Sound - Eastern Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-24	2024-11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 57.03268° N / 135.25012° W Aid Name: Entry Point Light 1 LLNR: 24945 Discrepancy Information: Initial Report DTG: 171720Z OCT 2024 Summary: LT EXT Correction DTG: 241933Z OCT 2024 Cause: OTHER CAUSES Cause Comments: OTHER-DOC IN FID Correction Status: WATCHING PROPERLY Sector Southeast Alaska BNM 357-24	POINT [Latitude: 57.03268, Longitude: -135.25012]

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Entry Point Light 1	24945	WATCHING PROPERLY	FD	2024-10-24
Entry Point Light 1	24945	WATCHING PROPERLY	FD	2024-10-24

El Capitan Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Island Daybeacon	24777	STRUCT MISSING	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - El Capitan Passage/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-04	2025- 04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 55.96635° N / 133.32419° W Aid Name: North Island Daybeacon LLNR: 24777 Discrepancy Information: Initial Report DTG: 041837Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 55.96635, Longitude: -133.32419]

Elfin Cove

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elfin Cove Daybeacon 5	24260	STRUCT DEST	FD

Elrington Passage

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024- 10-17	2026- 10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9911° N / 148.0963° W Submerged Data Mooring Name: EP03 Water Depth: 207' Top Float Depth: 190' POC: Mary Anne Bishop Phone: 907-424- 5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 59.9911, Longitude: -148.0963]
Sector Anchorage, Submerged Land Act (SLA) - Elrington Passage/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024- 10-17	2026- 10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9951° N / 148.101° W Submerged Data Mooring Name: EP04 Water Depth: 276' Top Float Depth: 259' POC: Mary Anne Bishop Phone: 907-424- 5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 59.9951, Longitude: -148.101]

Frederick Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Fanshaw Light	23260	STRUCT DEST	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Chatham Strait - Frederick Sound/General To Navigation/Wrecks	General Hazards	Hazards To Navigation	2024-10-28	2026-10-28	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 56.91133° N / 132.94483° W A 47 foot wood fishing vessel was reported sunk in this position in 2023.	POINT [Latitude: 56.91133, Longitude: -132.94483]

Gastineau Channel

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Stephens Passage - Gastineau Channel/ To Navigation/Wrecks	General	Hazards To Navigation	2024- 10-25	2026- 10-25	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 58.27098° N / 134.37045° W A 22' white sailboat sank in this position. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	POINT [Latitude: 58.27098, Longitude: -134.37045]

Geese Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aiaktalik Island Light 5	26910	DAYMK DMGD	FD

Icy Strait

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Sound - Icy Strait/General/Hazards To Navigation/Shoaling Reported	General	Hazards To Navigation	2024-10-25	2029-10-24	<p>General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24</p> <p>Location: 58.30225° N / 135.37292° W A dangerous rock was reported in this position. Mariners are advised to transit the area with caution.</p> <p>Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.</p>	POINT [Latitude: 58.30225, Longitude: -135.37292]

Kachemak Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halibut Point Daybeacon	26245	STRUCT DEST	FD

Keku Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Keku Strait Entrance Light	23305.1	STRUCT DEST	FD
Keku Strait Daybeacon 4	23305.3	STRUCT DEST	FD
Keku Strait Daybeacon 13	23305.9	STRUCT DEST	FD
Keku Strait Buoy 14	23305.95	MISSING	FD
Keku Strait Daybeacon 15	23306	STRUCT DEST	FD
Keku Strait Daybeacon 18	23306.2	STRUCT DEST	FD
Keku Strait Daybeacon 19	23306.3	STRUCT DEST	FD
Keku Strait Daybeacon 25	23306.7	STRUCT DEST	FD
Keku Strait Daybeacon 26	23306.8	STRUCT DEST	FD
Keku Strait Daybeacon 27	23306.85	STRUCT DEST	FD
Keku Strait Daybeacon 31	23307.05	STRUCT DEST	FD
Keku Strait Daybeacon 37	23307.6	STRUCT DEST	FD
Keku Strait Daybeacon 39	23307.7	STRUCT DEST	FD
Keku Strait Daybeacon 41	23307.8	STRUCT DEST	FD

Klawock Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Klawock Reef Lighted Buoy 1	24575	LT EXT	FD

Kupreanof Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Spruce Island Rock Light 7	27025	LT EXT	FD

Kuskokwim River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Okwega Pass Light OP	27872	STRUCT DEST	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Hazards To Navigation/Wrecks	General	Hazards To Navigation	2024- 10-28	2026- 10-28	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.78583° N / 161.692° W The barge SHANKS ARK was reported sunk and abandoned in this position in March of 2017. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no maritime traffic is present.	POINT [Latitude: 60.78583, Longitude: -161.692]

Lisianski Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lisianski Inlet Daybeacon 4	24300	STRUCT DEST	FD

Marmot Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Low Island Reef Buoy 7	26485	SINKING	FD
Hanin Rock Light	26560	LT EXT	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-09	2025-04-07	ATON/Federal Discrepancies From: 2024-10-09 To: 2025-04-07 Location: 57.91704° N / 152.54887° W Aid Name: Low Island Reef Buoy 7 LLNR: 26485 Discrepancy Information: Initial Report DTG: 091944Z OCT 2024 Summary: SINKING	POINT [Latitude: 57.91704, Longitude: -152.54887]
Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/General/Hazards To Navigation/Shoaling Reported	General	Hazards To Navigation	2024-10-25	2029-10-24	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 57.78583° N / 152.40568° W A dangerous rock was reported in this position approximately 20' off of the K&I Pier. This rock was reported struck by a vessel with a 16' draft at low tide, approximately +.085'. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	POINT [Latitude: 57.78583, Longitude: -152.40568]

Mendenhall Bar

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mendenhall Bar Buoy 10B	23735.55	OFF STATION	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Gastineau Channel - Mendenhall Bar/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 58.33716° N / 134.50283° W Aid Name: Mendenhall Bar Buoy 10B LLNR: 23735.55 Discrepancy Information: Initial Report DTG: 212322Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 58.33716, Longitude: -134.50283]

Naknek River

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Kvichak Bay - Naknek River/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024- 10-28	2026- 10-28	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2025-04-26 Location: 58.71287° N / 157.03408° W A large metal ramp was reported to be visible during low tide and completely submerged during high tide.	POINT [Latitude: 58.71287, Longitude: -157.03408]

Nichols Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Muzon Light	24330	LT EXT	FD

Nichols Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Walden Rock Light 6	22125	REDUCED INT/STRUCT DMGD	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clarence Strait - Nichols Passage/General To Navigation/Wrecks	General/Hazards	Hazards To Navigation	2024- 10-25	2026- 10-25	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 55.05° N / 131.64883° W The F/V JACI GRACE sank in Canoe Cove in this position. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	POINT [Latitude: 55.05, Longitude: -131.64883]

Nome Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Nome Harbor Range Front Light	27972	LT EXT	FD

Ogden Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dippy Island Rock Daybeacon 3	25355	STRUCT DEST	FD

Orca Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hanks Island Rock Light 5	25550	STRUCT DEST	FD
Hanks Island Rock Light 5	25550	STRUCT DMGD	FD
North Island Rock Light 10	25570	Status Unreported	FD
North Island Rock Light 10	25570	Status Unreported	FD

Orca Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

NAME	LLNR	STATUS	AID TYPE
Orca Inlet Channel Light 12	25575	STRUCT DEST	FD
NOAA Data Lighted Buoy 46060	25646	ADRIFT	FD
Bligh Reef Light	25662	LT EXT	FD
Bligh Reef Light	25662	DAYMK DMGD	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Orca Inlet Channel Light 12	25575	TRLB	FD
Orca Inlet Channel Light 12	25575	TRLB	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Prince William Sound - Orca Inlet/ATON/Temporary Changes	ATON	Temporary Changes	2024-10-25	2026-10-25	ATON/Temporary Changes From: 2024-10-25 To: 2026-10-25 Location: 60.6254° N / 145.69157° W Aid Name: Orca Inlet Channel Light 12 LLNR: 25575 Temporary Aid Change Information: Status: Temporary Replacement Lighted Buoy Old Latitude: 60-37-31.440N New Latitude: 60-37-35.256N Old Longitude: 145-41-29.635W New Longitude: 145-41-22.268W	POINT [Latitude: 60.6254, Longitude: -145.69157]

--

Peril Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wayanda Ledge Buoy 10	25205	Status Unreported	FD
Wayanda Ledge Buoy 10	25205	MISSING	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Salisbury Sound - Peril Strait/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 09-23	2025- 03-22	ATON/Federal Discrepancies From: 2024-09-23 To: 2025-03-22 Location: 57.40687° N / 135.62875° W Aid Name: Wayanda Ledge Buoy 10 LLNR: 25205 Discrepancy Information: Initial Report DTG: 231513Z SEP 2024 Reported Missing.	POINT [Latitude: 57.40687, Longitude: -135.62875]

Port Alexander

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Alexander Light	23465	REDUCED INT	FD

Port Chester

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Metlakatla Inner Harbor Daybeacon 3	22070	DAYMK DMGD	FD

Port Valdez

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Entrance Island Light 14	25735	LT EXT	FD
Valdez Security Zone Lighted Buoy A	25823	LT EXT	FD
Valdez Security Zone Lighted Buoy B	25824	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Valdez Servs Dock Lights (2)	25822	OFF STA	PA
Valdez Security Zone Daybeacon A	25823.1	DAYMK MISSING	PA

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Valdez Arm - Port Valdez/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024- 08-22	2025- 02-18	ATON/PATON Discrepancies From: 2024-08-22 To: 2025-02-18 Location: 61.08433° N / 146.42833° W Aid Name: Valdez Security Zone Daybeacon A LLNR: 25823.1 Discrepancy Information: Initial Report DTG: 221329Z AUG 2024 Summary: DAYMK MISSING	POINT [Latitude: 61.08433, Longitude: -146.42833]

Portage Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Portage Pass Daybeacon 11	23355	STRUCT DEST	FD

Prince William Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Schooner Rock Light 1	25525	LT EXT	FD
Johnstone Point Light	25535	LT EXT	FD
Smith Island Lighted Buoy 1	25830	LT EXT	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-24	2025-04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 60.53372° N / 147.28753° W Aid Name: Smith Island Lighted Buoy 1 LLNR: 25830 Discrepancy Information: Initial Report DTG: 241613Z OCT 2024 Summary: LT EXT Sector Western Alaska and U.S. Arctic BNM 181-24	POINT [Latitude: 60.53372, Longitude: -147.28753]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3148° N / 146.8653° W Submerged Data Mooring Name: H12 Water Depth: 1,194' Top Float Depth: 1,079' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3148, Longitude: -146.8653]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-28	2026-10-28	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 60.50373° N / 146.51368° W A submerged mooring was reported lost in 315 feet of water in this position in 02/23. This mooring may be an obstruction to operations on the sea floor.	POINT [Latitude: 60.50373, Longitude: -146.51368]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.61318° N / 147.19993° W Submerged Data Mooring Name: PWSSC-15 Water Depth: 722' Top Float Depth: 197' ***Surfaces twice daily*** POC: Dr. Rob Campbell Phone: 907-424-5800 Email: rcampbell@pwssc.org	POINT [Latitude: 60.61318, Longitude: -147.19993]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3278° N / 146.8023° W Submerged Data Mooring Name: H07 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3278, Longitude: -146.8023]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.322° N / 146.8297° W Submerged Data Mooring Name: H09 Water Depth: 1,007' Top Float Depth: 906' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.322, Longitude: -146.8297]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3078° N / 146.8999° W Submerged Data Mooring Name: H15 Water Depth: 276' Top Float Depth: 244' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3078, Longitude: -146.8999]
Sector Anchorage, Submerged	General	Hazards To Navigation	2024-10-28	2029-10-27	General/Hazards To Navigation/Obstructions From: 2024-10-28	POLYGON [Latitude: 61.17206, Longitude: -148.475]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Hazards				2029-10-27	<p>To: 2029-10-27</p> <p>Location: 61.17206° N / 148.475° W 61.17074° N / 148.05752° W 61.03802° N / 148.05752° W 60.93011° N / 148.48324° W 61.17206° N / 148.475° W</p> <p>The State of Alaska is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm and has the potential to create a tsunami if/when a landslide is generated that impacts the water in Barry Arm. If/when this occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following an event. The geologic makeup of the area is similar to Alaskan locations where two previous landslides caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of</p>	<p>[Latitude: 61.17074, Longitude: -148.05752] [Latitude: 61.03802, Longitude: -148.05752] [Latitude: 60.93011, Longitude: -148.48324] [Latitude: 61.17206, Longitude: -148.475]</p>

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					the potential results of a slide. Additional information is available at https://dggs.alaska.gov/hazards/barry-arm-landslide.html .	
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Shoaling Reported	General	Hazards To Navigation	2024-10-28	2026-10-28	General/Hazards To Navigation/Shoaling Reported From: 2024-10-28 To: 2026-10-28 Location: 61.13408° N / 147.54442° W An uncharted and dangerous rock was reported in this position in June or 2019.	POINT [Latitude: 61.13408, Longitude: -147.54442]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.34° N / 146.742° W Submerged Data Mooring Name: H02 Water Depth: 879' Top Float Depth: 791' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.34, Longitude: -146.742]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3376° N / 146.7544° W Submerged Data Mooring Name: H03 Water Depth: 876' Top Float Depth: 860' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3376, Longitude: -146.7544]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3123° N / 146.8776° W Submerged Data Mooring Name: H13 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3123, Longitude: -146.8776]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3168° N / 146.8538° W Submerged Data Mooring Name: H11 Water Depth: 1,135' Top Float Depth: 1,022' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3168, Longitude: -146.8538]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3245° N / 146.8159° W Submerged Data Mooring Name: H08 Water Depth: 935' Top Float Depth: 842' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3245, Longitude: -146.8159]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3198° N / 146.8418° W Submerged Data Mooring Name: H10 Water Depth: 1,060' Top Float Depth: 954' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3198, Longitude: -146.8418]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3098° N / 146.889° W Submerged Data Mooring Name: H14 Water Depth: 522' Top Float Depth: 470' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3098, Longitude: -146.889]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.309° N / 146.9092° W Submerged Data Mooring Name: H16 Water Depth: 85' Top Float Depth: 53' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.309, Longitude: -146.9092]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3425° N / 146.7304° W Submerged Data Mooring Name: H01 Water Depth: 98' Top Float Depth: 66' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3425, Longitude: -146.7304]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.302° N / 146.8928° W Submerged Data Mooring Name: HC Water Depth: 449' Top Float Depth: 404' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.302, Longitude: -146.8928]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.2997° N / 146.9056° W Submerged Data Mooring Name: HD Water Depth: 151' Top Float Depth: 119' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.2997, Longitude: -146.9056]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Wrecks	General	Hazards To Navigation	2024-10-28	2026-10-28	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.796° N / 148.05517° W The F/V SONG II sank in this position in August 2018.	POINT [Latitude: 60.796, Longitude: -148.05517]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3352° N / 146.7661° W Submerged Data Mooring Name: H04 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3352, Longitude: -146.7661]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3349° N / 146.7329° W Submerged Data Mooring Name: HB Water Depth: 830' Top Float Depth: 747' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3349, Longitude: -146.7329]
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024-10-17	2026-10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3328° N / 146.7785° W Submerged Data Mooring Name: H05 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3328, Longitude: -146.7785]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024- 10-17	2026- 10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3302° N / 146.7903° W Submerged Data Mooring Name: H06 Water Depth: 896' Top Float Depth: 806' POC: Mary Anne Bishop Phone: 907-424- 5800 x228 Email: mbishop@pwssc.org	POINT [Latitude: 60.3302, Longitude: -146.7903]

Resurrection Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Seward East Breakwater Light 2	26020	DAYMK DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
4th of July Channel LT 1	26005	STRUCT DEST	PA
Seward Marine Dock Light	26010	LT EXT	PA

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Resurrection Bay/General/Hazards To Navigation/Obstructions	General	Hazards To Navigation	2024- 10-17	2026- 10-17	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.85045° N / 149.50063° W Submerged Data Mooring Name: GAK1-24 Water Depth: 860' Top Float Depth: 65' POC: Peter Shipton Phone: 907-224- 4319 Email: pshipton@alaska.edu	POINT [Latitude: 59.85045, Longitude: -149.50063]

San Christoval Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hermanos Islands Reef Lighted Buoy 8	24545	LT EXT	FD

Sitka Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Edgecumbe Light	24910	LT EXT	FD
Vitskari Island Light	24915	RAC INOP	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - Sitka Sound/General/ To Navigation/Wrecks	General	Hazards To Navigation	2024- 10-25	2026- 10-25	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 57.04345° N / 135.20597° W The F/V DRAGON LADY sank in Canoe Cove in this position. The F/V DRAGON LADY is a 76 foot wooden fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	POINT [Latitude: 57.04345, Longitude: -135.20597]

Stephens Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Five Finger Light	23280	LT EXT	FD
Hobart Bay Light 2	23595	DAYMK MISSING	FD
Point Gambier Light	23600	LT EXT	FD
Middle Point Light	23785	LT EXT	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Frederick Sound - Stephens Passage/General/Miscellaneous	General	Miscellaneous	2024-10-28	2026-10-28	General/Miscellaneous From: 2024-10-28 To: 2026-10-28 Location: 58.37614° N / 134.72318° W The U.S. Coast Guard has established a temporary mooring buoy in this location. This mooring buoy has been established for official use and should be used without authorization from the Coast Guard.	POINT [Latitude: 58.37614, Longitude: -134.72318]

Light List Corrections

NAME	LLNR	AID TYPE	ACTION TYPE	ACTION DATE
HORSE ISLAND AQUATIC FARM LIGHTED BUOY A	23788	PA	I	2024-10-28
HORSE ISLAND AQUATIC FARM LIGHTED BUOY B	23788.1	PA	I	2024-10-28
HORSE ISLAND AQUATIC FARM LIGHTED BUOY C	23788.2	PA	I	2024-10-28
HORSE ISLAND AQUATIC FARM LIGHTED BUOY D	23788.3	PA	I	2024-10-28

Sumner Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Vichnefski Rock Light	22745	STRUCT DMGD	FD
Five Fathom Shoal Lighted Buoy F	23285	LT EXT	FD

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - Sumner Strait/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 56.43839° N / 133.01552° W Aid Name: Vichnefski Rock Light LLNR: 22745 Discrepancy Information: Initial Report DTG: 151935Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 56.43839, Longitude: -133.01552]

Sweeper Cove

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sweeper Cove Range Front Light	27542	DAYMK DMGD	FD

Tlevak Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tlevak Narrows Buoy 4	24445	MISSING	FD

Tongass Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
California Rock Lighted Buoy 3	22150	LT EXT	FD
Idaho Rock Lighted Buoy 4	22155	LT EXT	FD
Pennock Island Reef Lighted Buoy PR	22190	LT EXT	FD
Refuge Cove Daybeacon 3	22270	STRUCT DEST	FD

Uganik Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Northeast Arm Light 1	27000	STRUCT DEST	FD

Unalaska Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Eider Point Lighted Buoy EP	27500.75	LT EXT	FD

Valdez Arm

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Entrance Point Light 12	25725	LT EXT	FD

Western Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sitka Breakwater Light 7	25025	LT EXT	FD

Woody Island

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Woody Island Channel Buoy 6	26665	MISSING	FD

Wrangell Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wrangell Narrows Daybeacon 4	22863	STRUCT DEST	FD
Wrangell Narrows Tow Channel Buoy 1TC	22875	MISSING	FD
Wrangell Narrows Daybeacon 10A	22916	STRUCT DEST	FD
Wrangell Narrows North Entrance Lighted Bell Buoy WN	23210	LT EXT	FD

Zimovia Strait

Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sumner Strait - Zimovia Strait/General/Hazards To Navigation/Wrecks	General	Hazards To Navigation	2024- 10-25	2026- 10-25	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 56.19921° N / 132.49282° W The F/V PAMELA RAE LADY sank in Canoe Cove in this position. The F/V PAMELA RAE LADY is a 58 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	POINT [Latitude: 56.19921, Longitude: -132.49282]

LNМ Footer Editable in USAIMS Online