



U.S. Department of Homeland Security

**United States Coast Guard**

## **LOCAL NOTICE TO MARINERS**

District: 7

Week: 45/24

LITTLE RIVER, SOUTH CAROLINA TO ECONFINA RIVER, FLORIDA (INCLUDES PUERTO RICO AND THE U.S. VIRGIN ISLANDS)

Questions or inquiries concerning the Seventh Coast Guard District Local Notice to Mariners should be directed to:

Commander, Seventh Coast Guard District (dpw)  
Brickell Plaza Federal Building  
909 SE 1st Avenue, Room 406  
Miami, Florida 33131-3028  
Telephone: (786) 498-8529

Email LNM Article Entry Requests and Updates to: D07-SMB-D7-LNM@uscg.mil  
Email Proposed Changes Comments to: D07-SMB-DPWPublicComments@uscg.mil

### **NOTIFICATIONS:**

Aids to Navigation discrepancies (change in the status of an aid to navigation that differs from what is published or charted), shoaling or hazard to navigation and Bridge discrepancies (including lighting) report to the nearest Coast Guard unit.

- DISTRICT 7: (305) 415-6800
- SECTOR CHARLESTON: (843) 740-7050
- SECTOR JACKSONVILLE: (904) 714-7557
- SECTOR MIAMI: (305) 535-4472
- SECTOR KEY WEST: (305) 292-8727
- SECTOR ST PETERSBURG: (727) 824-7506
- SECTOR SAN JUAN: (787) 729-2041

### **BROADCAST NOTICE TO MARINERS:**

Broadcast Notice to Mariners (BMN) is the method by which important navigation safety information is disseminated in the most expedient manner.

BNMs are intended to inform the mariner of important changes that affect the safety of navigation via VHF-FM voice broadcasts by Coast Guard

Sectors covering local broadcast areas. Active BNM broadcast information is subsequently accessed when drafting the weekly Local Notice to Mariners (LNM) and may be included if practical.

The LNM is the primary means for disseminating navigation safety information concerning aids to navigation, hazards to navigation, and other items of interest to mariners navigating the waters of the United States, its territories, and possessions. Care is taken to include the most up-to-date information at time of release, however local BNM broadcasts should also be consulted for the timeliest information between LNM release dates.

### **NAVIGATION INTERNET SITES:**

USCG Navigation Information Service (NIS): <https://www.navcen.uscg.gov>

Local Notice to Mariners (LNM) are published weekly and are available on the USCG Navigation Center website:

<https://www.navcen.uscg.gov/?pageName=lnmDistrict@ion=7>

Public Notices for Bridges: <https://www.navcen.uscg.gov/?pageName=pnBridges>

Light List and weekly updates: <https://www.navcen.uscg.gov/index.php?pageName=lightLists>

USCG Auxiliary Public Education Classes: [https://www.cgaux.org/boatinged/class\\_finder/index.php](https://www.cgaux.org/boatinged/class_finder/index.php)

U.S. Coast Pilot: <https://nauticalcharts.noaa.gov/publications/coast-pilot/index.html>

NOAA Chart Corrections and Chart Viewer: <https://www.nauticalcharts.noaa.gov>

National Geospatial-Intelligence Agency Notice to Mariners: <https://msi.nga.mil/NTM>

# Abbreviations

ADRIFT - Buoy Adrift	ICW - Intracoastal Waterway	R - Red
AICW - Atlantic Intracoastal Waterway	IMCH - Improper Characteristic	RACON - Radar Transponder Beacon
AI - Alternating	INL - Inlet	Ra ref - Radar reflector
B - Buoy	INOP - Not Operating	RBN - Radio Beacon
BKW - Breakwater	INT - Intensity	REBUILT - Aid Rebuilt
bl - Blast	ISL - Islet	RECOVERED - Aid Recovered
BNM - Broadcast Notice to Mariner	Iso - Isophase	RED - Red Buoy
bu - Blue	kHz - Kilohertz	REFL - Reflective
C - Canadian	LAT - Latitude	RRL - Range Rear Light
CHAN - Channel	LB - Lighted Buoy	RELIGHTED - Aid Relit
CGD - Coast Guard District	LBB - Lighted Bell Buoy	RELOC - Relocated
C/O - Cut Off	LHB - Lighted Horn Buoy	RESET ON STATION - Aid Reset on Station
CONT - Contour	LGB - Lighted Gong Buoy	RFL - Range Front Light
CRK - Creek	LONG - Longitude	RIV - River
CONST - Construction	LNM - Local Notice to Mariners	RRASS - Remote Radio Activated
DAYMK/Daymk - Daymark	LT - Light	Sound Signal
DBN/Dbn - Daybeacon	LT CONT - Light Continuous	s - seconds
DBD/DAYBD - Dayboard	LTR - Letter	SEC - Section
DEFAC - Defaced	LWB - Lighted Whistle Buoy	SHL - Shoaling
DEST - Destroyed	LWP - Left Watching Properly	si - silent
DISCON - Discontinued	MHz - Megahertz	SIG - Signal
DMGD/DAMGD - Damaged	MISS/MSNG - Missing	SND - Sound
ec - eclipse	Mo - Morse Code	SPM - Single Point Mooring Buoy
EST - Established Aid	MRASS - Marine Radio Activated Sound Signal	SS - Sound Signal
ev - every	MSLD - Misleading	STA - Station
EVAL - Evaluation	N/C - Not Charted	STRUCT - Structure
EXT - Extinguished	NGA - National Geospatial Intelligence Agency	St M - Statute Mile
F - Fixed	NO/NUM - Number	TEMP - Temporary Aid Change
fl - flash	NOS - National Ocean Service	TMK - Topmark
Fl - Flashing	NW - Notice Writer	TRLB - Temporarily Replaced by Lighted Buoy
G - Green	OBSCU - Obscured	TRLT - Temporarily Replaced by Light
GIWW - Gulf Intracoastal Waterway	OBST - Obstruction	
HAZ - Hazard to Navigation		

HBR - Harbor  
I - Interrupted

OBSTR - Obstruction  
PRIV - Private Aid  
Q - Quick

TRUB - Temporarily Replaced  
by Unlighted Buoy  
USACE - Army Corps of  
Engineers

## Alafia River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Alafia River Light 7	23275	STRUCT DEST/TRLB	FD

## Altamaha Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Altamaha Sound Daybeacon 197	36887	STRUCT DEST/TRUB	FD
Altamaha Sound Light 201	36905	STRUCT DEST/TRLB	FD
Altamaha Sound Light 202	36910	STRUCT DEST/TRLB	FD
Altamaha Sound Light 209	36930	STRUCT DEST/TRLB	FD
Altamaha Sound Range Front Light C	36935	STRUCT DEST	FD

## Anclote Anchorage North Entrance

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage North Entrance Light 7	26130	HAZ NAV/STRUCT DEST/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gulf Harbors South Channel Light 1	26410	LT EXT	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Sea Forest Cut Channel Daybeacon 9	26451.8	STRUCT DEST/HAZ NAV	PA
Upper Cross Bayou Daybeacon 1	26453	STRUCT DEST	PA
Gulf Harbors North Channel Light 2	26460	STRUCT DEST	PA
Gulf Harbors North Channel Daybeacon 10	26500	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Anclote Anchorage North Entrance/ATON Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.19388° N / 82.81894° W Aid Name: Anclote Anchorage North Entrance Light 7 LLNR: 26130</p> <p>Discrepancy Information: Initial Report DTG: 291634Z SEP 2024 Summary: STRUCT DEST/HAZ NAV Correction DTG: 291305Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.19388, Longitude: -82.81894]
Anclote Anchorage North Entrance/ATON Discrepancies	ATON	Federal Discrepancies	2024-10-29	2025-04-27	<p>ATON/Federal Discrepancies From: 2024-10-29 To: 2025-04-27</p> <p>Location: 28.19388° N / 82.81894° W Aid Name: Anclote Anchorage North Entrance Light 7 LLNR: 26130</p> <p>Discrepancy Information: Initial Report DTG: 291307Z OCT 2024 Summary: HAZ NAV/STRUCT DEST/TRLB Temporary Response DTG: 291307Z OCT 2024 Temporary Response: TLB MARKED WR7, 8 YDS FROM AP FL 2.5s</p>	POINT [Latitude: 28.19388, Longitude: -82.81894]

## Federal Discrepancies Corrected

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>	<b>CORRECTION DATE</b>
Anclote Anchorage North Entrance Light 7	26130	WATCHING PROPERLY	FD	2024-10-29

# Anclote Anchorage South Entrance

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Anclote Anchorage South Entrance/ATON Discrepancies Corrected	ATON/Federal	Federal Discrepancies Corrected	2024-11-01	2024-11-15	ATON/Federal Discrepancies Corrected From: 2024-11-01 To: 2024-11-15 Location: 28.13864° N / 82.83828° W Aid Name: Anclote Anchorage South Entrance Light 3 LLNR: 26075 Discrepancy Information: Initial Report DTG: 011542Z NOV 2024 Summary: DBD DEST Correction DTG: 011543Z NOV 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.13864, Longitude: -82.83828]
Anclote Anchorage South Entrance/ATON Discrepancies	ATON/Federal	Federal Discrepancies	2024-11-01	2025-04-30	ATON/Federal Discrepancies From: 2024-11-01 To: 2025-04-30 Location: 28.13864° N / 82.83828° W Aid Name: Anclote Anchorage South Entrance Light 3 LLNR: 26075 Discrepancy Information: Initial Report DTG: 011542Z NOV 2024 Summary: DBD DEST	POINT [Latitude: 28.13864, Longitude: -82.83828]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Anclote Anchorage South Entrance Light 3	26075	WATCHING PROPERLY	FD	2024-11-01
Anclote Anchorage South Entrance Light 3	26075	WATCHING PROPERLY	FD	2024-11-01

## Anclote River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Village Marina Daybeacon 7	26233.7	DAYMK MISSING	PA



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.17492° N / 82.82008° W Aid Name: Anclote River Entrance Daybeacon 3 LLNR: 26150 Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: DAYMK MISSING Correction DTG: 291221Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.17492, Longitude: -82.82008]
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.17443° N / 82.81988° W Aid Name: Anclote River Entrance Daybeacon 4 LLNR: 26155 Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: DAYMK MISSING Correction DTG: 291221Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.17443, Longitude: -82.81988]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.17921° N / 82.80481° W Aid Name: Anclote River Entrance Daybeacon 8 LLNR: 26175 Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: STRUCT DMGD Correction DTG: 291224Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.17921, Longitude: -82.80481]
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.16123° N / 82.77018° W Aid Name: Anclote River Light 39 LLNR: 26310 Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: HAZ NAV/DAYMK MISSING Correction DTG: 291226Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.16123, Longitude: -82.77018]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.16096° N / 82.771° W Aid Name: Anclote River Daybeacon 38 LLNR: 26305 Discrepancy Information: Initial Report DTG: 271433Z OCT 2024 Summary: STRUCT DEST Correction DTG: 291303Z OCT 2024 Cause: FALSE REPORT Cause Comments: FALSE REPORT Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.16096, Longitude: -82.771]
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-27	2025-04-25	ATON/Federal Discrepancies From: 2024-10-27 To: 2025-04-25 Location: 28.16096° N / 82.771° W Aid Name: Anclote River Daybeacon 38 LLNR: 26305 Discrepancy Information: Initial Report DTG: 271433Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.16096, Longitude: -82.771]
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.17651° N / 82.8136° W Aid Name: Anclote River Entrance Daybeacon 6 LLNR: 26165 Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: DAYMK DMGD Correction DTG: 291223Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.17651, Longitude: -82.8136]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.17582° N / 82.79129° W Aid Name: Anclote River Daybeacon 16 LLNR: 26200</p> <p>Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: DAYMK MISSING Correction DTG: 291225Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.17582, Longitude: -82.79129]
Anclote Anchorage North Entrance - Anclote River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	<p>ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12</p> <p>Location: 28.17264° N / 82.82485° W Aid Name: Anclote River Entrance Daybeacon 2 LLNR: 26140</p> <p>Discrepancy Information: Initial Report DTG: 301435Z SEP 2024 Summary: HAZ NAV/DAYMK MISSING/STRUCT DMGD Correction DTG: 291227Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY</p>	POINT [Latitude: 28.17264, Longitude: -82.82485]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Anclote River Entrance Daybeacon 2	26140	WATCHING PROPERLY	FD	2024-10-29
Anclote River Entrance Daybeacon 3	26150	WATCHING PROPERLY	FD	2024-10-29
Anclote River Entrance Daybeacon 4	26155	WATCHING PROPERLY	FD	2024-10-29
Anclote River Entrance Daybeacon 6	26165	WATCHING PROPERLY	FD	2024-10-29
Anclote River Entrance Daybeacon 8	26175	WATCHING PROPERLY	FD	2024-10-29
Anclote River Daybeacon 16	26200	WATCHING PROPERLY	FD	2024-10-29
Anclote River Daybeacon 38	26305	WATCHING PROPERLY	FD	2024-10-29
Anclote River Daybeacon 38	26305	WATCHING PROPERLY	FD	2024-10-29
Anclote River Light 39	26310	WATCHING PROPERLY	FD	2024-10-29

## Angelfish Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Angelfish Creek Daybeacon 1	11185	STRUCT DEST/HAZ NAV/TRLB	FD
Angelfish Creek Daybeacon 4	11205	STRUCT DEST/TRUB	FD
Angelfish Creek Light 6	11215	STRUCT DEST/TRLB	FD
Angelfish Creek Light 14	11235	STRUCT DMGD	FD

## Army Terminal Channel

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Army Terminal Channel Lighted Buoy 2	30850	RELOCATED FOR DREDGING	FD
Army Terminal Channel Lighted Buoy 3	30855	RELOCATED FOR DREDGING	FD
Army Terminal Channel Lighted Buoy 4	30860	RELOCATED FOR DREDGING	FD
Army Terminal Channel Lighted Buoy 5	30875	RELOCATED FOR DREDGING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De San Juan - Army Terminal Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 18.42462° N / 66.10764° W Aid Name: Army Terminal Channel Range Rear Light LLNR: 30870 Discrepancy Information: Initial Report DTG: 151219Z OCT 2024 Summary: LT EXT	POINT [Latitude: 18.42462, Longitude: -66.10764]
Bahia De San Juan - Army Terminal Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-10	2025-04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 18.42462° N / 66.10764° W Aid Name: Army Terminal Channel Range Rear Light LLNR: 30870 Discrepancy Information: Initial Report DTG: 101318Z OCT 2024 Summary: LT EXT	POINT [Latitude: 18.42462, Longitude: -66.10764]
Bahia De San Juan - Army Terminal Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-19	2025-04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 18.43283° N / 66.10431° W Aid Name: Army Terminal Channel Turning Basin Lighted Buoy 9 LLNR: 30890 Discrepancy Information: Initial Report DTG: 191727Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 18.43283, Longitude: -66.10431]

## Ashepoo-Coosaw Cut-Off

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Ashepoo-Coosaw Cutoff Daybeacon 170	35165	STRUCT MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Helena Sound - Ashepoo- Coosaw Cut- Off/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 11-04	2025- 05-03	ATON/Federal Discrepancies From: 2024-11-04 To: 2025-05-03 Location: 32.52219° N / 80.46064° W Aid Name: Ashepoo- Coosaw Cutoff Daybeacon 170 LLNR: 35165 Discrepancy Information: Initial Report DTG: 042206Z NOV 2024 Summary: STRUCT MISSING	POINT [Latitude: 32.52219, Longitude: -80.46064]





# Ashley River

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Charleston Harbor South Channel - Ashley River/ATON/ATON Changes	ATON	ATON Changes	2024-10-22	2025-04-20	ATON/ATON Changes From: 2024-10-22 To: 2025-04-20 Location: 32.77916° N / 79.95575° W Aid Name: Charleston City Marina Dock Light A LLNR: 3593 Action: ESTABLISH	POINT [Latitude: 32.77916, Longitude: -79.95575]
Charleston Harbor South Channel - Ashley River/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 32.79511° N / 79.97078° W Maintenance dredging is being conducted within The Citadel Marina in Charleston with an estimated completion date of December 31, 2024. The ONEISCAU will perform minor maintenance dredging within the Marina basin and does not anticipate encroaching upon the navigation waters of the Ashley River. The vessel plans to remain at least 0.5 mile to 1 mile away from any channel markers. For further information, contact: Richard Spelman, Save The Sea Islands, (843) 870-7074.	POINT [Latitude: 32.79511, Longitude: -79.97078]

## **Bahia De Boqueron**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bajo Enmedio South Lighted Buoy 1	32325	SINKING/TRLB	FD

## **Bahia De Guayanilla**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bahia De Guayanilla Entrance Range Rear Light	32075	LT EXT	FD

## **Bahia De Jobos**

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Aguirre Power Plant Lighted Buoy 1	31890	OFF STA	PA
Aguirre Power Plant Lighted Buoy 2	31895	OFF STA	PA
Aguirre Power Plant Lighted Buoy 3	31900	OFF STA	PA
Aguirre Power Plant Lighted Buoy 4	31905	OFF STA	PA
Aguirre Power Plant Lighted Buoy 5	31910	OFF STA	PA
Aguirre Power Plant Lighted Buoy 6	31915	OFF STA	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Aguirre Power Plant Lighted Buoy 8	31920	OFF STA	PA

# Bahia De Mayaguez

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De Mayaguez/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-07	2025-04-05	ATON/Federal Discrepancies From: 2024-10-07 To: 2025-04-05 Location: 18.21669° N / 67.15962° W Aid Name: Bahia De Mayaguez Buoy 10 LLNR: 32390 Discrepancy Information: Initial Report DTG: 072310Z OCT 2024 Summary: MISSING	POINT [Latitude: 18.21669, Longitude: -67.15962]

## Bahia De Ponce

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Isla De Cardona Light	31950	STRUCT DEST	FD
Isla De Cardona Light	31950	STRUCT DEST	FD

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Ponce Harbor Pier Obstruction Lights (4)	31985	STRUCT DMGD	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De Ponce/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	<p>ATON/Federal Discrepancies            From: 2024-10-01            To: 2025-03-30            Location:            17.95678° N / 66.63504° W Aid            Name: Isla De Cardona Light            LLNR: 31950            Discrepancy Information: Initial Report DTG: 011737Z OCT            2024 Summary: STRUCT DEST</p>	<p>POINT            [Latitude: 17.95678,            Longitude: -66.63504]</p>
Bahia De Ponce/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	<p>ATON/Federal Discrepancies            From: 2024-10-01            To: 2025-03-30            Location:            17.97952° N / 66.62031° W Aid            Name: Bahia De Ponce Range Rear Light            LLNR: 31965            Discrepancy Information: Initial Report DTG: 011612Z OCT            2024 Summary: LT EXT</p>	<p>POINT            [Latitude: 17.97952,            Longitude: -66.62031]</p>
Bahia De Ponce/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-03	2025-04-01	<p>ATON/Federal Discrepancies            From: 2024-10-03            To: 2025-04-01            Location:            17.95678° N / 66.63504° W Aid            Name: Isla De Cardona Light            LLNR: 31950            Discrepancy Information: Initial Report DTG: 032115Z OCT            2024 Summary: STRUCT DEST</p>	<p>POINT            [Latitude: 17.95678,            Longitude: -66.63504]</p>

## **Bahia De Ponce And Approaches**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Isla Caja De Muertos Light	31925	LT EXT	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Ponce Yacht & Fishing Club Special Purpose Buoy A	31927	MISSING	PA
Rio Bucana East Jetty Light	31940	STRUCT DEST	PA

## **Bahia De San Juan**

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bahia De San Juan FAD Lighted Buoy E	30736.4	MISSING	PA
Bahia De San Juan FAD Lighted Buoy F	30736.5	OFF STA	PA

### **Temporary Changes**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bahia De San Juan Lighted Buoy 9	30795.1	RELOCATED FOR DREDGING	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De San Juan/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-23	2025-04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 18.45709° N / 66.12845° W Aid Name: Bahia De San Juan Range Front Light LLNR: 30745 Discrepancy Information: Initial Report DTG: 232028Z OCT 2024 Summary: LT EXT	POINT [Latitude: 18.45709, Longitude: -66.12845]
Bahia De San Juan/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 18.45709° N / 66.12845° W Aid Name: Bahia De San Juan Range Front Light LLNR: 30745 Discrepancy Information: Initial Report DTG: 232028Z OCT 2024 Summary: LT EXT Correction DTG: 232029Z OCT 2024 Cause: POWER,SOLAR/BATT Cause Comments: SOLAR BATT MALF Correction Status: RELIGHTED	POINT [Latitude: 18.45709, Longitude: -66.12845]
Bahia De San Juan/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-29	2025-04-27	ATON/Federal Discrepancies From: 2024-10-29 To: 2025-04-27 Location: 18.45708° N / 66.12845° W Aid Name: Bahia De San Juan Range Front Passing Light LLNR: 30745.5 Discrepancy Information: Initial Report DTG: 300046Z OCT 2024 Summary: LT EXT	POINT [Latitude: 18.45708, Longitude: -66.12845]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De San Juan/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-30	2024-11-13	ATON/Federal Discrepancies Corrected From: 2024-10-30 To: 2024-11-13 Location: 18.45708° N / 66.12845° W Aid Name: Bahia De San Juan Range Front Passing Light LLNR: 30745.5 Discrepancy Information: Initial Report DTG: 300046Z OCT 2024 Summary: LT EXT Correction DTG: 301909Z OCT 2024 Cause: FALSE REPORT Cause Comments: FALSE REPORT Correction Status: WATCHING PROPERLY	POINT [Latitude: 18.45708, Longitude: -66.12845]
Bahia De San Juan/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-30	2025-04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 18.45709° N / 66.12845° W Aid Name: Bahia De San Juan Range Front Light LLNR: 30745 Discrepancy Information: Initial Report DTG: 301910Z OCT 2024 Summary: LT EXT	POINT [Latitude: 18.45709, Longitude: -66.12845]
Bahia De San Juan/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-30	2024-11-13	ATON/Federal Discrepancies Corrected From: 2024-10-30 To: 2024-11-13 Location: 18.45709° N / 66.12845° W Aid Name: Bahia De San Juan Range Front Light LLNR: 30745 Discrepancy Information: Initial Report DTG: 301910Z OCT 2024 Summary: LT EXT Correction DTG: 301911Z OCT 2024 Cause: POWER,SOLAR/BATT Cause Comments: SOLAR BATT MALF Correction Status: RELIGHTED	POINT [Latitude: 18.45709, Longitude: -66.12845]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Bahia De San Juan Range Front Light	30745	RELIGHTED	FD	2024-10-23
Bahia De San Juan Range Front Light	30745	RELIGHTED	FD	2024-10-23
Bahia De San Juan Range Front Light	30745	RELIGHTED	FD	2024-10-30
Bahia De San Juan Range Front Light	30745	RELIGHTED	FD	2024-10-30
Bahia De San Juan Range Front Passing Light	30745.5	WATCHING PROPERLY	FD	2024-10-30
Bahia De San Juan Range Front Passing Light	30745.5	WATCHING PROPERLY	FD	2024-10-30

## Banana River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Banana River Daybeacon 7A	42490	STRUCT DEST/TRUB	FD
Banana River Daybeacon 12	42545	DBD DEST	FD
Banana River Daybeacon 15	42555	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tortoise Island Ctr Channel Daybeacon 2	42450	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 4	42460	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 5	42460.1	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 6	42460.2	DAYMK MISSING	PA
Tortoise Island Center Channel Daybeacon 7	42460.3	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 8	42460.4	DAYMK IMCH	PA
Tortoise Island Channel Daybeacon 1	42463	STRUCT DEST/HAZ NAV	PA
Manatee Cove Marina Daybeacon 1	42490.1	STRUCT DEST/HAZ NAV	PA
Manatee Cove Marina Daybeacon 4	42490.4	STRUCT DMGD	PA
Hospital Cut Daybeacon 6	42611.5	DAYMK MISSING	PA
Pelican Creek Light 2	42615	STRUCT DEST	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Central Avenue Entrance Channel Light 2	42830	LT EXT	PA
Kelly Park Channel Daybeacon 3	43040	STRUCT DEST/HAZ NAV	PA
Kelly Park Channel Daybeacon 4	43045	STRUCT DEST	PA
Kelly Park Channel Daybeacon 5	43050	STRUCT DEST/HAZ NAV	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Canaveral Barge Canal - Banana River/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 28.2669° N / 80.6097° W 28.17191° N / 80.61245° W 28.25602° N / 80.6612° W 28.2669° N / 80.6097° W Gator Dredging will continue muck removal operations within the Grand Canal and adjacent canals within a subdivision, north of Samson Island Park and south of Patrick Air Force Base. Operations will begin on or about March 15, 2022 until approximately November 30, 2025 - Monday through Saturday, 30 minutes after sunrise until 30 minutes before sunset. The dredge DANI L will monitor VHF-FM channels 16 and 68. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene pipeline associated with the hydraulic dredging operations of the canals will be utilized. Pipeline, work vessels, dredge barge, booster pump barges and buoys	POLYGON [Latitude: 28.2669, Longitude: -80.6097] [Latitude: 28.17191, Longitude: -80.61245] [Latitude: 28.25602, Longitude: -80.6612] [Latitude: 28.2669, Longitude: -80.6097]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					will be visibly lighted and will be in the area until all work is complete. The configuration will change daily and Vessels and/or equipment will be in multiple locations at the same time. For further information, contact: Charlie Gertz (727) 902-6055.	
Canaveral Barge Canal - Banana River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 28.36485° N / 80.64901° W Aid Name: Banana River Daybeacon 28 LLNR: 42610 Discrepancy Information: Initial Report DTG: 121915Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.36485, Longitude: -80.64901]
Canaveral Barge Canal - Banana River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 28.29206° N / 80.64918° W Aid Name: Banana River Daybeacon 12 LLNR: 42545 Discrepancy Information: Initial Report DTG: 121913Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.29206, Longitude: -80.64918]
Canaveral Barge Canal - Banana River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 28.21836° N / 80.62784° W Aid Name: Banana River Daybeacon 6A LLNR: 42495 Discrepancy Information: Initial Report DTG: 121914Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.21836, Longitude: -80.62784]

## **Banana River North**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Banana River North Daybeacon 15A	41740	DBD DEST	FD
Banana River North Daybeacon 34	41920	STRUCT DEST/TRUB	FD
Banana River North Light 35	41925	STRUCT DEST/TRLB	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Canaveral Barge Canal - Banana River North/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-12	2025- 04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 28.42576° N / 80.64398° W Aid Name: Banana River North Daybeacon 15A LLNR: 41740 Discrepancy Information: Initial Report DTG: 121914Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.42576, Longitude: -80.64398]

## Barron River Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barron River Channel Daybeacon 37	16180	STRUCT DEST/TRUB	FD

## Bear Cut

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bear Cut Daybeacon 2	10790	DAYMK MISSING	FD

## Beaufort River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Broad Creek Daybeacon 13	4490	STRUCT DEST	PA
Broad Creek Daybeacon 19	4510	DAYMK IMCH	PA
Broad Creek Daybeacon 21	4515	DAYMK IMCH	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Port Royal Sound - Beaufort River/General/Temp Deviation	General	Bridges	2024-10-29	2024-11-29	<p>General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-11-29</p> <p>Location: 32.42753° N / 80.66921° W</p> <p>Bridge Name: Lady's Island Woods Memorial Bridge</p> <p>The Coast Guard has authorized a temporary deviation to the operating schedule to the Lady's Island Bridge across the Atlantic Intracoastal Waterway mile 536.0, Beaufort, South Carolina. The bridge need not open for navigation, including tugs with tows during the following:</p> <p>November 2, 2024, from 7:15 a.m. until 9:45 a.m. to facilitate the Holy Trinity School Swing Bridge Run.</p> <p>November 28, 2024, from 7:15 a.m. until 9:45 a.m. to facilitate the Habitat for Humanity Turkey Trot 5K. Public Vessels, vessels in emergency situations, and vessels that may pass through the bridge without an opening should be passed at any time.</p> <p>For waterways questions or drawbridge operating issues, contact Sector Charleston Waterways Management Division at <a href="mailto:charlestonwaterways@uscg.mil">charlestonwaterways@uscg.mil</a> or the Sector's 24-hour Command Center Line at (843) 740-7050.</p>	POINT [Latitude: 32.42753, Longitude: -80.66921]



## Big Bend Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Bend Pilot Channel Range Front Light	23028	LT IMCH	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Apollo Beach Daybeacon 4	24675	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.80992° N / 82.44541° W Aid Name: Big Bend Channel Lighted Buoy 2 LLNR: 23045 Discrepancy Information: Initial Report DTG: 222018Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.80992, Longitude: -82.44541]
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.81031° N / 82.43868° W Aid Name: Big Bend Channel Light 3 LLNR: 23050 Discrepancy Information: Initial Report DTG: 221111Z OCT 2024 Summary: LT EXT Correction DTG: 232032Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RELIGHTED	POINT [Latitude: 27.81031, Longitude: -82.43868]
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.80919° N / 82.43883° W Aid Name: Big Bend Channel Light 4 LLNR: 23055 Discrepancy Information: Initial Report DTG: 221111Z OCT 2024 Summary: LT EXT Correction DTG: 232033Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RELIGHTED	POINT [Latitude: 27.80919, Longitude: -82.43883]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.80825° N / 82.41659° W Aid Name: Big Bend Channel Lighted Buoy 9 LLNR: 23080 Discrepancy Information: Initial Report DTG: 222019Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.80825, Longitude: -82.41659]
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.80919° N / 82.43883° W Aid Name: Big Bend Channel Light 4 LLNR: 23055 Discrepancy Information: Initial Report DTG: 221111Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.80919, Longitude: -82.43883]
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.81031° N / 82.43868° W Aid Name: Big Bend Channel Light 3 LLNR: 23050 Discrepancy Information: Initial Report DTG: 221111Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.81031, Longitude: -82.43868]
Gadsden Point Cut - Big Bend Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.81072° N / 82.4453° W Aid Name: Big Bend Channel Lighted Buoy 1 LLNR: 23040 Discrepancy Information: Initial Report DTG: 222016Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.81072, Longitude: -82.4453]





## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Big Bend Channel Lighted Buoy 1	23040	WATCHING PROPERLY	FD	2024-10-22
Big Bend Channel Lighted Buoy 2	23045	WATCHING PROPERLY	FD	2024-10-22
Big Bend Channel Light 3	23050	RELIGHTED	FD	2024-10-23
Big Bend Channel Light 3	23050	RELIGHTED	FD	2024-10-23
Big Bend Channel Light 4	23055	RELIGHTED	FD	2024-10-23
Big Bend Channel Light 4	23055	RELIGHTED	FD	2024-10-23
Big Bend Channel Lighted Buoy 9	23080	WATCHING PROPERLY	FD	2024-10-22

## Big Marco Pass Gordon Pass

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Marco Pass-Gordon Pass Daybeacon 2	17095	STRUCT DEST/TRUB/OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 1A	17100	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 2A	17160	STRUCT MISSING/TRUB/OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 3	17165	STRUCT MISSING	FD
Big Marco Pass-Gordon Pass Buoy 3A	17167	OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 17	17210	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 18A	17220	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 26	17255	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 28A	17275	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 33	17300	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 36	17310	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 40	17320	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 46	17335	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 53	17370	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 54	17375	STRUCT DMGD	FD
Big Marco Pass-Gordon Pass Daybeacon 56	17385	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 60	17400	STRUCT DEST/TRUB	FD

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Big Marco Pass-Gordon Pass Daybeacon 65	17415	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 66	17420	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 67	17420.5	STRUCT DEST/TRUB	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Big Marco Pass Obstruction Daybeacon A	17087	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon B	17087.1	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon C	17087.2	STRUCT DEST	PA
Big Marco Pass Obstruction Light E	17087.4	STRUCT DEST	PA
Isles Of Capri Daybeacon 2	17105	STRUCT DEST	PA
Isles Of Capri Daybeacon 4	17115	STRUCT DEST	PA
Isles Of Capri Daybeacon 5	17120	STRUCT DEST	PA
Isles Of Capri Daybeacon 8	17135	STRUCT DEST	PA
Isles Of Capri Daybeacon 11	17150	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Capri Pass - Big Marco Pass Gordon Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2022-10-04	2025-03-31	ATON/Federal Discrepancies From: 2022-10-04 To: 2025-03-31 Location: 25.97656° N / 81.7411° W Aid Name: Big Marco Pass-Gordon Pass Daybeacon 2 LLNR: 17095 Discrepancy Information: Initial Report DTG: 040203Z OCT 2022 Summary: STRUCT DEST/TRUB/OFF STATION Temporary Response DTG: 021446Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 25.97656, Longitude: -81.7411]
Capri Pass - Big Marco Pass Gordon Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 25.97896° N / 81.73916° W Aid Name: Big Marco Pass-Gordon Pass Daybeacon 3 LLNR: 17165 Discrepancy Information: Initial Report DTG: 021523Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 25.97896, Longitude: -81.73916]
Capri Pass - Big Marco Pass Gordon Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 25.97996° N / 81.7385° W Aid Name: Big Marco Pass-Gordon Pass Buoy 3A LLNR: 17167 Discrepancy Information: Initial Report DTG: 021531Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 25.97996, Longitude: -81.7385]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Capri Pass - Big Marco Pass Gordon Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-01	2025- 03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 26.01079° N / 81.7419° W Aid Name: Big Marco Pass-Gordon Pass Daybeacon 18A LLNR: 17220 Discrepancy Information: Initial Report DTG: 011904Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 011904Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 26.01079, Longitude: -81.7419]
Capri Pass - Big Marco Pass Gordon Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 25.97991° N / 81.73822° W Aid Name: Big Marco Pass-Gordon Pass Daybeacon 2A LLNR: 17160 Discrepancy Information: Initial Report DTG: 231744Z APR 2021 Summary: STRUCT MISSING/TRUB/OFF STATION Temporary Response DTG: 021525Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 25.97991, Longitude: -81.73822]

## Biscayne Bay

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Bay Daybeacon 35	48340	STRUCT DEST/TRUB	FD
Biscayne Bay Daybeacon 41	48360	STRUCT DEST/TRUB	FD
Biscayne Bay Daybeacon 57	48490	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bakers Haulover Smallboat Channel Daybeacon 2	47795	STRUCT DEST	PA
Miami Seaquarium Inlet Pipe Obstruction Light	48600	STRUCT DEST/HAZ NAV	PA
Coral Gables Waterway Light 1	49285	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 3	49295	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 4	49300	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 6	49310	DAYMK IMCH	PA
Matheson Hammock South Channel Range Front Light	49445	DAYMK MISSING/STRUCT DMGD	PA
Matheson Hammock South Channel Range Rear Light	49450	DAYMK MISSING	PA
Matheson Hammock South Channel Light 2	49455	LT EXT	PA
Matheson Hammock South Channel Daybeacon 9	49485	DAYMK MISSING	PA
Black Point Channel Daybeacon 6	49760	STRUCT DEST	PA
Adams Key Light	50105	LT EXT/DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Biscayne Bay/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	<p>General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 25.6632° N / 80.24784° W</p> <p>Fincantieri Infrastructure Florida &amp; GLF USA will be conducting pile driving, dredging and water sampling in the vicinity of Biscayne Bay Aquatic Preserve and Government Cut at future MSC berths 8 and 9 (25-46-21.1332N/080-9-25.5348W to 25-46-9.1848N/080-8-57.0084W). The estimated completion date is December 15, 2025, hours of operation are 6:30 a.m. to 6:30 p.m., 7 days a week. GLF Construction Corporation will be mobilizing a Crane Barge (54 feet x 150 feet), Service Barge (30 feet X 150 feet), and a Push Boat (15 feet x 25 feet) to the project site on or around June 16, 2022. The equipment is being mobilized to install and maintain the turbidity control system required to perform both land and water-based dredging works. During the installation of the system the above equipment will be operating in the area south of the north navigation channel adjacent to Port Miami. If and when necessary, the equipment will be</p>	POINT [Latitude: 25.6632, Longitude: -80.24784]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>moved along the southern edge of the north navigation channel to perform any maintenance. Upon arrival at the site the GLF equipment will be positioned inside the Turbidity Control System south of the Navigation Channel and will not move out until completion of the work. GLF will continuously monitor VHF-FM channel 16 and use Channel 9 to maneuver barge and vessels. For further information contact: Alejandro Brito (786) 821-4587 or <a href="mailto:Alejandro.brito@fl.fcinfrastructure.com">Alejandro.brito@fl.fcinfrastructure.com</a>.</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Biscayne Bay/General/Bridges/Repairs, Painting, Or Fender Replacement	General	Bridges	2024- 10-30	2025- 01-01	<p>General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-10-30 To: 2025-04-28 Location: 25.886861° N / 80.128164° W Bridge Name: Kane Concourse Bridge LEAD-EC, on behalf of the bridge owner, Town of Bay Harbor, will be conducting repairs to the Kane Concourse (96th Street) Bridge over Indian Creek beginning April 8, 2024. The project will consist of concrete repair on the deck as well as work on the underside using skiffs during daylight hours. There are not expected to be any impacts to the waterway. The project is expected to be completed in December 2024. Mariners are strongly advised to exercise extreme caution when navigating in the area and to proceed at the slowest safe speed to minimize wake and reduce danger to working personnel. For further information about this project, please contact: George Pardo at (786) 295-3553. For waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil</p>	POINT [Latitude: 25.886861, Longitude: -80.128164]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Biscayne Bay/General/Bridges/Repairs, Painting, Or Fender Replacement	General	Bridges	2024- 10-29	2024- 12-01	<p>General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-10-29 To: 2024-12-01 Location: 25.746515° N / 80.183737° W Bridge Name: Rickenbacker Causeway Bridge P&amp;P Contracting, Inc. will be conducting repair work at the Bear Cut Bridge, beginning November 6, 2023, with an anticipated completion date prior to November 2024. Work will consist of rehabilitation of the bridge, which includes pile jacket installation and concrete repairs utilizing a floating work platform and small vessel. Navigation is not expected to be impacted during the repairs. All in- water equipment is required to be lighted at night in accordance with Inland Navigation Rules and will require 72 hours' notice for removal. Mariners are advised to use caution when transiting the area. For further information, contact P&amp;P Contracting at (786) 259-7534.</p>	POINT [Latitude: 25.746515, Longitude: -80.183737]

## Biscayne Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Channel Light 1	10810	DAYMK MISSING	FD
Biscayne Channel Light 3	10820	STRUCT DEST/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Springs Boat Club Shoal Buoy West	10886	MSLD SIG	PA
Miami Springs Boat Club Shoal Buoy North	10887	MISSING	PA
Miami Springs Boat Club Shoal Buoy South	10889	MISSING	PA

## Blackwater Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater Sound Light 38	50365	LT EXT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tarpon Basin - Blackwater Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-23	2025- 04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 25.17655° N / 80.393° W Aid Name: Blackwater Sound Light 38 LLNR: 50365 Discrepancy Information: Initial Report DTG: 232036Z OCT 2024 Summary: LT EXT	POINT [Latitude: 25.17655, Longitude: -80.393]

## **Bloody Point Range**

### **Temporary Changes**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bloody Point Range Lighted Bell Buoy 8	4580	RELOCATED FOR DREDGING	FD
Bloody Point Range Lighted Buoy 13	4615	RELOCATED FOR DREDGING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Bloody Point Range/ATON/Temporary Changes	ATON	Temporary Changes	2024-10-23	2025-04-21	<p>ATON/Temporary Changes From: 2024-10-23 To: 2025-04-21</p> <p>Location: 31.9961° N / 80.78319° W</p> <p>Aid Name: Bloody Point Range Lighted Bell Buoy 8 LLNR: 4580</p> <p>Temporary Aid Change Information:</p> <p>Status: RELOCATED FOR DREDGING Old Latitude: 31-59-45.959N New Latitude: 31-59-46.000N Old</p> <p>Longitude: 080-46-59.478W New Longitude: 080-47-00.000W</p>	POINT [Latitude: 31.9961, Longitude: -80.78319]
Sector Charleston, Submerged Land Act (SLA) - Bloody Point Range/ATON/Temporary Changes	ATON	Temporary Changes	2024-10-23	2025-04-21	<p>ATON/Temporary Changes From: 2024-10-23 To: 2025-04-21</p> <p>Location: 32.03026° N / 80.82065° W</p> <p>Aid Name: Bloody Point Range Lighted Buoy 13 LLNR: 4615</p> <p>Temporary Aid Change Information:</p> <p>Status: RELOCATED FOR DREDGING Old Latitude: 32-01-48.945N New Latitude: 32-01-48.099N Old</p> <p>Longitude: 080-49-14.351W New Longitude: 080-49-15.181W</p>	POINT [Latitude: 32.03026, Longitude: -80.82065]



## Blount Island

### Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fulton Cutoff - Blount Island/General Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 30.4182° N / 81.5341° W 30.40857° N / 81.51367° W 30.39184° N / 81.50131° W 30.38325° N / 81.55607° W 30.39984° N / 81.55161° W 30.41331° N / 81.54474° W 30.4182° N / 81.5341° W Gator Dredging will be dredging in the Blount Island Support Facility Port. Dredging is expected to begin on or about September 19, 2004, with an estimated completion date of December 31, 2024. Operations will be conducted 24 hours per day, 7 days per week basis. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Dredge BRITTYN B will be monitoring VHF-FM channel 16. Floating and submerged high density polyethylene (HDPE) and steel pipeline associated with the hydraulic dredging operations of the channel will be	POLYGON [Latitude: 30.4182, Longitude: -81.5341] [Latitude: 30.40857, Longitude: -81.51367] [Latitude: 30.39184, Longitude: -81.50131] [Latitude: 30.38325, Longitude: -81.55607] [Latitude: 30.39984, Longitude: -81.55161] [Latitude: 30.41331, Longitude: -81.54474] [Latitude: 30.4182, Longitude: -81.5341]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>utilized. Pipeline, work vessels, dredge barge, booster pump barge(s) and buoys will be visibly lighted and marked according to coast guard regulations and will be in the area until all work is complete and can change configuration daily. Vessels and/or equipment will be in multiple locations at the same time. For further information contact: Keith Ayers (815) 315-3255.</p>	

---



## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Blount Island Turning Basin Lighted Buoy 45	RELOCATE	Blount Island Turning Basin LB 45 (LLNR 7395) will be permanently relocated to 30-23-08.280N/081-32-35.920W. The flash characteristic will remain a FL G 4s, but the nominal range will be reduced from 5NM to 4NM.

## Boca Chita Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Featherbeds Obstruction Daybeacon A	49703	DAYMK MISSING	PA
East Featherbed North Obstruction Daybeacon	49703.1	DAYMK MISSING	PA
East Featherbed West Obstruction Daybeacon	49703.3	STRUCT DEST	PA
East Featherbed Northeast Obstruction Daybeacon	49703.5	STRUCT DEST	PA
East Featherbed Southeast Obstruction Daybeacon	49703.6	DAYMK IMCH	PA
East Featherbed NNE Obstruction Daybeacon	49703.7	STRUCT DEST	PA
Middle Featherbeds North Obstruction Daybeacon	49704	DAYMK MISSING	PA
Middle Featherbed NNE Obstruction Daybeacon	49704.3	DAYMK MISSING	PA
Featherbed Bank Shoal Daybeacon X	49725	STRUCT DEST/HAZ NAV	PA

## Boca Ciega Bay

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Pasadena Marina Daybeacon 4	60980	Status Unreported	PA
South Pasadena Marina Daybeacon 4	60980	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.69533° N / 82.63544° W Aid Name: Boca Ciega Bay Light 6 LLNR: 60545 Discrepancy Information: Initial Report DTG: 021548Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.69533, Longitude: -82.63544]
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.69457° N / 82.65039° W Aid Name: Boca Ciega Bay Daybeacon 8 LLNR: 60560 Discrepancy Information: Initial Report DTG: 021551Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.69457, Longitude: -82.65039]
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.69407° N / 82.65028° W Aid Name: Boca Ciega Bay Daybeacon 7A LLNR: 60555 Discrepancy Information: Initial Report DTG: 021555Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.69407, Longitude: -82.65028]
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.69427° N / 82.65731° W Aid Name: Boca Ciega Bay Daybeacon 10 LLNR: 60570 Discrepancy Information: Initial Report DTG: 021559Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.69427, Longitude: -82.65731]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.692° N / 82.68288° W Aid Name: Boca Ciega Bay Daybeacon 13A LLNR: 60585 Discrepancy Information: Initial Report DTG: 021601Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.692, Longitude: -82.68288]
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.69566° N / 82.61393° W Aid Name: Boca Ciega Bay Light 1 LLNR: 60530 Discrepancy Information: Initial Report DTG: 232038Z OCT 2024 Summary: DBD DEST Correction DTG: 232039Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.69566, Longitude: -82.61393]
Pass-A-Grille - Boca Ciega Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-23	2025-04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 27.69566° N / 82.61393° W Aid Name: Boca Ciega Bay Light 1 LLNR: 60530 Discrepancy Information: Initial Report DTG: 232038Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.69566, Longitude: -82.61393]

## Federal Discrepancies Corrected

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>	<b>CORRECTION DATE</b>
Boca Ciega Bay Light 1	60530	WATCHING PROPERLY	FD	2024-10-23
Boca Ciega Bay Light 1	60530	WATCHING PROPERLY	FD	2024-10-23

# Boca Ciega Bay To Anclote Anchorage

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - Boca Ciega Bay To Anclote Anchorage/General/Bridges/Temp Deviation	General	Bridges	2024-10-30	2024-12-23	<p>General/Bridges/Temp Deviation From: 2024-10-30 To: 2024-12-23</p> <p>Location: 27.843941° N / 82.838253° W</p> <p>Bridge Name: Park Blvd Bridge Pinellas County is authorized to temporarily deviate from drawbridge operation regulation 33 CFR 117.5 that governs the Park Blvd (CR 694) Bridge, mile 126.0, across the Gulf Intracoastal Waterway, at Saint Petersburg, Florida. Under this temporary deviation, the Park Blvd (CR 694) Bridge need not open to navigation including tugs and tugs with tows, from 7:15 a.m. until 8:15 a.m. on Sunday December 22, 2024, to facilitate the Holiday Distance Classic. Public vessels of the United States and vessels in distress shall be passed as soon as safely possible. Vessels which can safely pass without an opening shall be passed at any time. For waterway questions please contact USCG Sector Saint Petersburg Waterways Management Division; telephone 727-824-7506, e-mail D07-SMB-Tampa-WWM@uscg.mil.</p>	POINT [Latitude: 27.843941, Longitude: -82.838253]



## Boca Ciega Key

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Boca Ciega Bay Daybeacon 39	61040	STRUCT DEST/HAZ NAV/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Boca Ciega Bay - Boca Ciega Key/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-11-01	2025-04-30	ATON/Federal Discrepancies From: 2024-11-01 To: 2025-04-30 Location: 27.74394° N / 82.73996° W Aid Name: Boca Ciega Bay Daybeacon 39 LLNR: 61040 Discrepancy Information: Initial Report DTG: 012103Z NOV 2024 Summary: STRUCT DEST/HAZ NAV/TRUB Temporary Response DTG: 040105Z NOV 2024 Temporary Response: TUB	POINT [Latitude: 27.74394, Longitude: -82.73996]



## **Bowlegs Cut**

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bay Harbour Light	12378	LT EXT	PA

## **Brunswick River**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Brunswick Point Cut Range Front Light 2	6230	REDUCED INT	FD
Brandy Point Jetty Daybeacon	6290	STRUCT DEST/HAZ NAV/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
ATON/ATON Changes	ATON	ATON Changes	2024-10-13	2025-04-11	ATON/ATON Changes From: 2024-10-13 To: 2025-04-11 Location: 31.14358° N / 81.49733° W Aid Name: East River Wreckage Temporary Buoy LLNR: Not Provided Action: DISCONTINUE	POINT [Latitude: 31.14358, Longitude: -81.49733]
St Simons Sound - Brunswick River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-10	2025-04-11	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-11 Location: 31.13193° N / 81.528° W Aid Name: Turtle River Lower Range Front Light LLNR: 6240 Discrepancy Information: Initial Report DTG: 131528Z OCT 2024 Summary: LT EXT	POINT [Latitude: 31.13193, Longitude: -81.528]
St Simons Sound - Brunswick River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-10	2025-04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 31.1336° N / 81.53257° W Aid Name: Turtle River Lower Range Rear Light LLNR: 6245 Discrepancy Information: Initial Report DTG: 102007Z OCT 2024 Summary: LT EXT	POINT [Latitude: 31.1336, Longitude: -81.53257]

## **Butchers Bend**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Butchers Bend Light 109	9200	STRUCT DEST/TRLB	FD

## **Buttermilk Sound**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Buttermilk Sound Daybeacon 217	36967	STRUCT DEST/TRUB	FD

## **Caesar Creek**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Caesar Creek Daybeacon 5A	11005	STRUCT DEST	FD
Caesar Creek Daybeacon 9	11025	STRUCT DEST	FD
Caesar Creek Buoy 29	11125	MISSING	FD
Caesar Creek Buoy 30	11130	MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Elliott Key - Caesar Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-10	2025- 04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 25.38349° N / 80.21018° W Aid Name: Caesar Creek Daybeacon 9 LLNR: 11025 Discrepancy Information: Initial Report DTG: 102000Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 25.38349, Longitude: -80.21018]
Elliott Key - Caesar Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-10	2025- 04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 25.3842° N / 80.20417° W Aid Name: Caesar Creek Daybeacon 5A LLNR: 11005 Discrepancy Information: Initial Report DTG: 101959Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 25.3842, Longitude: -80.20417]

## Calibogue Sound

### Proposed Notice of Change

NAME	ACTION TYPE	DESCRIPTION
Calibogue Sound Light 32	CHANGE	The U.S. Coast Guard is proposing a change to the Aid to Navigation system in the Intracoastal Waterway Calibogue Sound, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or andrew.m.ingle@uscg.mil with ICW Nominal Range Change as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by October 9, 2024.

## Caloosahatchee River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Caloosahatchee River Daybeacon 34	52475	DBD DEST/STRUCT DMGD	FD
Caloosahatchee River Daybeacon 35	52595	DBD DEST	FD
Caloosahatchee River Daybeacon 38	52610	DBD DEST	FD
Caloosahatchee River Light 56	52895	DBD DEST	FD
Caloosahatchee River Daybeacon 69	53525	DBD DEST	FD
Caloosahatchee River Buoy 93A	54755	OFF STATION	FD
Caloosahatchee River Daybeacon 94	54760	STRUCT MISSING	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ft Myers Yacht Basin Breakwater Light	52640	STRUCT DEST	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Caloosahatchee River Mooring Channel Daybeacon 1	52641	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 2	52642	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 4	52644	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 6	52644.2	DAYMK MISSING	PA
Ft Myers Yacht Basin Breakwater West Light	52645	STRUCT DEST	PA
Marinatown Daybeacon 4	52670	DAYMK MISSING	PA
Marinatown Daybeacon 7	52685	DAYMK MISSING	PA
Marinatown Daybeacon 12	52710	STRUCT DMGD	PA
Marinatown Daybeacon 22	52760	STRUCT DEST	PA
Marinatown Daybeacon 23	52765	DAYMK MISSING	PA
Marinatown Daybeacon 24	52770	DAYMK MISSING	PA
Gulf Acres Channel Daybeacon 1	52825	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 4	52840	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 5	52845	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 9	52870	STRUCT DEST	PA
Cape Coral Rim Channel Daybeacon 23	53070	HAZ NAV/DAYMK MISSING	PA
Cape Coral Rim Channel Daybeacon 39	53110	STRUCT DEST	PA
Van Riper Channel Daybeacon 2	54296	DAYMK MISSING	PA
Van Riper Channel Daybeacon 4	54296.5	DAYMK MISSING	PA
Van Riper Channel Daybeacon 6	54297	DAYMK MISSING	PA
Van Riper Channel Daybeacon 8	54297.5	DAYMK MISSING	PA
Van Riper Channel Daybeacon 10	54298	DAYMK MISSING	PA
Van Riper Channel Daybeacon 12	54298.5	DAYMK MISSING	PA
Bimini Entrance Channel Daybeacon 2	54305	STRUCT DMGD	PA
Redfish Cove Channel Daybeacon 18	54445	STRUCT DEST	PA
Redfish Cove Channel Daybeacon 20	54455	STRUCT DEST	PA
Shell Point Obstruction Daybeacon A	54763	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-19	2025-04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 26.62951° N / 81.89282° W Aid Name: Caloosahatchee River Light 56 LLNR: 52895 Discrepancy Information: Initial Report DTG: 192025Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.62951, Longitude: -81.89282]
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-19	2025-04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 26.66571° N / 81.85448° W Aid Name: Caloosahatchee River Daybeacon 35 LLNR: 52595 Discrepancy Information: Initial Report DTG: 192027Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.66571, Longitude: -81.85448]
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-19	2025-04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 26.67086° N / 81.84858° W Aid Name: Caloosahatchee River Daybeacon 34 LLNR: 52475 Discrepancy Information: Initial Report DTG: 192029Z OCT 2024 Summary: DBD DEST/STRUCT DMGD	POINT [Latitude: 26.67086, Longitude: -81.84858]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-19	2025- 04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 26.66207° N / 81.85919° W Aid Name: Caloosahatchee River Daybeacon 38 LLNR: 52610 Discrepancy Information: Initial Report DTG: 192026Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.66207, Longitude: -81.85919]
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 26.52541° N / 82.00319° W Aid Name: Caloosahatchee River Daybeacon 94 LLNR: 54760 Discrepancy Information: Initial Report DTG: 151719Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 26.52541, Longitude: -82.00319]
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-19	2025- 04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 26.5262° N / 81.99996° W Aid Name: Caloosahatchee River Buoy 93A LLNR: 54755 Discrepancy Information: Initial Report DTG: 192024Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 26.5262, Longitude: -81.99996]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pine Island Sound - Caloosahatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-25	2025- 04-23	ATON/Federal Discrepancies From: 2024-10-25 To: 2025-04-23 Location: 26.56758° N / 81.92339° W Aid Name: Caloosahatchee River Daybeacon 69 LLNR: 53525 Discrepancy Information: Initial Report DTG: 251210Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.56758, Longitude: -81.92339]

## Canaveral Harbor

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Canaveral Harbor Entrance Channel Lighted Buoy 12	9645	MISSING	FD

## Cape Florida Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Florida Channel Light 4	10800	STRUCT DMGD	FD

## Cape Haze Shoal

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Burnt Store Marina Light 2	20000	LT EXT	PA
Burnt Store Marina Daybeacon 5	20015	STRUCT DEST	PA
Alligator Creek Daybeacon 23	20305	STRUCT DMGD	PA
Alligator Creek Daybeacon 24	20310	STRUCT DEST	PA
Pine Island West Channel Daybeacon 5	56510.1	STRUCT DEST/HAZ NAV	PA

## Capri Pass

## Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Capri Pass Light 3	16955	STRUCT DEST/TRUB	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD
Capri Pass Daybeacon C	16980	OFF STATION	FD
Capri Pass Daybeacon C	16980	STRUCT DEST/TRUB	FD
Capri Pass Shoal Daybeacon B	17050	STRUCT DEST/TRUB	FD

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Addison Bay Daybeacon 1	16901.1	STRUCT DEST	PA
Addison Bay Daybeacon 2	16901.2	STRUCT DEST	PA
Addison Bay Daybeacon 4	16901.4	STRUCT DEST/HAZ NAV	PA
Addison Bay Daybeacon 5	16901.5	STRUCT DEST	PA
South Point North Obstruction Daybeacon	16961	STRUCT DEST/HAZ NAV	PA
South Point S. Obstruction Daybeacon	16962	STRUCT DEST/HAZ NAV	PA
Royal Marco Point North Obstruction Daybeacon	16986	STRUCT DEST	PA
Royal Marco Point S. Obst. Daybeacon	16987	STRUCT DEST	PA
Collier Bay Daybeacon 2	17010	DAYMK DMGD	PA
Collier Bay Daybeacon 6	17014	STRUCT DEST/HAZ NAV	PA
Factory Bay E Channel Daybeacon 2	17070	DBD DMGD	PA
Factory Bay E Channel Daybeacon 4	17075	DBD DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Capri Pass/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-13	2025-04-11	ATON/PATON Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 25.96806° N / 81.72222° W Aid Name: Factory Bay E Channel Daybeacon 2 LLNR: 17070 Discrepancy Information: Initial Report DTG: 131627Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 25.96806, Longitude: -81.72222]
Capri Pass/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-13	2025-04-11	ATON/PATON Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 25.96528° N / 81.72389° W Aid Name: Factory Bay E Channel Daybeacon 4 LLNR: 17075 Discrepancy Information: Initial Report DTG: 131627Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 25.96528, Longitude: -81.72389]
Capri Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 25.97312° N / 81.74412° W Aid Name: Capri Pass Daybeacon C LLNR: 16980 Discrepancy Information: Initial Report DTG: 021258Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 25.97312, Longitude: -81.74412]
Capri Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 25.97089° N / 81.77129° W Aid Name: Capri Pass Light 1 LLNR: 16945 Discrepancy Information: Initial Report DTG: 030146Z OCT 2024 Summary: DBD DEST/LT EXT	POINT [Latitude: 25.97089, Longitude: -81.77129]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Capri Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 25.97117° N / 81.7563° W Aid Name: Capri Pass Light 4 LLNR: 16960 Discrepancy Information: Initial Report DTG: 021644Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 021645Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 25.97117, Longitude: -81.7563]
Capri Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 25.97117° N / 81.7563° W Aid Name: Capri Pass Light 4 LLNR: 16960 Discrepancy Information: Initial Report DTG: 041300Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 041300Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 25.97117, Longitude: -81.7563]
Capri Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-13	2025-04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 25.97374° N / 81.75615° W Aid Name: Capri Pass Light 3 LLNR: 16955 Discrepancy Information: Initial Report DTG: 132228Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 132228Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 25.97374, Longitude: -81.75615]



# Cats Point Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Boca Ciega Bay - Cats Point Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.69331° N / 82.6839° W Aid Name: Cats Point Channel Daybeacon 2 LLNR: 60590 Discrepancy Information: Initial Report DTG: 021604Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 27.69331, Longitude: -82.6839]

## Caxambas Bay

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater River Daybeacon 10	16505	DAYMK MISSING	PA
Blackwater River Daybeacon 11	16510	STRUCT DEST/HAZ NAV	PA
Blackwater River Daybeacon 13	16520	STRUCT DEST	PA
Blackwater River Daybeacon 15	16530	STRUCT DEST	PA
Blackwater River Daybeacon 22	16555	STRUCT DEST	PA
Blackwater River Daybeacon 24	16565	STRUCT DEST/HAZ NAV	PA
Caxambas Bay South Approach Daybeacon 2	16675	STRUCT DEST	PA
Caxambas Bay Daybeacon 11	16715	DAYMK MISSING	PA
Horr's Island North Channel Daybeacon 8	16790	STRUCT DEST/HAZ NAV	PA
Snook Hole Channel Daybeacon 1	16790.01	STRUCT DEST	PA
Snook Hole Channel Daybeacon 4	16790.04	STRUCT DEST/HAZ NAV	PA
Big Marco River Daybeacon 3	16800	STRUCT DEST	PA
Big Marco River Daybeacon 4	16805	STRUCT DEST/HAZ NAV	PA
Big Marco River Daybeacon 12	16830	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 1	16835	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 2	16840	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 3	16845	DAYMK MISSING	PA
Big Marco River Daybeacon 15	16855	STRUCT DEST/DAYMK MISSING	PA
Big Marco River Daybeacon 16	16860	STRUCT DEST	PA
Big Marco River Daybeacon 17	16865	DAYMK MISSING	PA
Big Marco River Daybeacon 18	16870	DAYMK MISSING	PA
Big Marco River Daybeacon 20	16875	DAYMK MISSING	PA
Big Marco River Daybeacon 21	16880	DAYMK MISSING	PA
Big Marco River Daybeacon 22	16885	DAYMK MISSING	PA
Big Marco River Daybeacon 26	16900	STRUCT DEST/HAZ NAV	PA



## Cedar Keys Main Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Cedar Keys Main Channel Daybeacon 8	29770	STRUCT MISSING/TRUB	FD
Cedar Keys Main Channel Light 14	29790	STRUCT MISSING/TRLB	FD
Cedar Keys Main Channel Light 18	29800	STRUCT MISSING/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.10963° N / 83.04675° W Aid Name: Cedar Keys Main Channel Light 18 LLNR: 29800 Discrepancy Information: Initial Report DTG: 211834Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 211835Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.10963, Longitude: -83.04675]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11188° N / 83.04512° W Aid Name: Cedar Keys Main Channel Daybeacon 19 LLNR: 29805 Discrepancy Information: Initial Report DTG: 211755Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.11188, Longitude: -83.04512]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11678° N / 83.03872° W Aid Name: Cedar Keys Main Channel Light 23 LLNR: 29820 Discrepancy Information: Initial Report DTG: 211753Z OCT 2024 Summary: DBD DEST/LT EXT	POINT [Latitude: 29.11678, Longitude: -83.03872]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-21	2025- 04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.09609° N / 83.05644° W Aid Name: Cedar Keys Main Channel Daybeacon 10 LLNR: 29780 Discrepancy Information: Initial Report DTG: 211759Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.09609, Longitude: -83.05644]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-21	2025- 04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.10156° N / 83.05704° W Aid Name: Cedar Keys Main Channel Daybeacon 12 LLNR: 29785 Discrepancy Information: Initial Report DTG: 211757Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.10156, Longitude: -83.05704]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-21	2025- 04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.09174° N / 83.05898° W Aid Name: Cedar Keys Main Channel Light 9 LLNR: 29775 Discrepancy Information: Initial Report DTG: 211801Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.09174, Longitude: -83.05898]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-21	2025- 04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.08368° N / 83.06557° W Aid Name: Cedar Keys Main Channel Light 7 LLNR: 29765 Discrepancy Information: Initial Report DTG: 211804Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.08368, Longitude: -83.06557]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.07515° N / 83.06707° W Aid Name: Cedar Keys Main Channel Daybeacon 4 LLNR: 29760.5 Discrepancy Information: Initial Report DTG: 211806Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.07515, Longitude: -83.06707]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.07422° N / 83.07334° W Aid Name: Cedar Keys Main Channel Daybeacon 3 LLNR: 29760 Discrepancy Information: Initial Report DTG: 211807Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.07422, Longitude: -83.07334]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11961° N / 83.03799° W Aid Name: Cedar Keys Main Channel Daybeacon 24 LLNR: 29825 Discrepancy Information: Initial Report DTG: 211525Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.11961, Longitude: -83.03799]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11413° N / 83.04032° W Aid Name: Cedar Keys Main Channel Light 21 LLNR: 29810 Discrepancy Information: Initial Report DTG: 211521Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.11413, Longitude: -83.04032]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.12306° N / 83.03885° W Aid Name: Cedar Keys Main Channel Daybeacon 26 LLNR: 29835 Discrepancy Information: Initial Report DTG: 211519Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.12306, Longitude: -83.03885]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11403° N / 83.04028° W Aid Name: Cedar Key Main Channel Temporary Lighted Buoy 19A LLNR: Not Provided Discrepancy Information: Initial Report DTG: 211527Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 29.11403, Longitude: -83.04028]
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.08707° N / 83.05867° W Aid Name: Cedar Keys Main Channel Daybeacon 8 LLNR: 29770 Discrepancy Information: Initial Report DTG: 211547Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 211547Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.08707, Longitude: -83.05867]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Main Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.10421° N / 83.0559° W Aid Name: Cedar Keys Main Channel Light 14 LLNR: 29790 Discrepancy Information: Initial Report DTG: 211835Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 211835Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.10421, Longitude: -83.0559]

## Cedar Keys Northwest Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Cedar Keys Northwest Channel Daybeacon 14	29965	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Daybeacon 17	29980	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Light 18	29990	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Light 19	29995	STRUCT DEST/HAZ NAV/TRLB	FD
Cedar Keys Northwest Channel Daybeacon 21	30005	STRUCT MISSING/TRUB	FD
Cedar Key Northwest Channel Daybeacon 22	30010	STRUCT MISSING/TRUB	FD
Cedar Key Northwest Channel Daybeacon 22	30010	STRUCT DEST/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.11891° N / 83.05175° W Aid Name: Cedar Keys Northwest Channel Light 19 LLNR:	POINT [Latitude: 29.12668, Longitude: -83.0613]
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	29995 Discrepancy Information: Initial Report DTG: 141902Z OCT 2024 Summary: STRUCT DEST/HAZ NAV/TRLB Temporary Response DTG: 141902Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.11891, Longitude: -83.05175]
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.12116° N / 83.05694° W Aid Name: Cedar Keys Northwest Channel Daybeacon 17 LLNR: 29980	POINT [Latitude: 29.12116, Longitude: -83.05694]
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	Discrepancy Information: Initial Report DTG: 141903Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141903Z OCT 2024 Temporary Response: TUB	



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.11931° N / 83.04989° W Aid Name: Cedar Keys Northwest Channel Daybeacon 21 LLNR: 30005 Discrepancy Information: Initial Report DTG: 141901Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141901Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.11931, Longitude: -83.04989]
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11893° N / 83.04965° W Aid Name: Cedar Key Northwest Channel Daybeacon 22 LLNR: 30010 Discrepancy Information: Initial Report DTG: 211549Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 211549Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.11893, Longitude: -83.04965]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cedar Keys Northwest Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 29.11898° N / 83.05424° W Aid Name: Cedar Keys Northwest Channel Light 18 LLNR: 29990 Discrepancy Information: Initial Report DTG: 211548Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 211549Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.11898, Longitude: -83.05424]

## Charleston Harbor

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Charleston Entrance Lighted Buoy C	200	RAC INOP	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 32.67984° N / 79.71672° W Aid Name: Charleston Harbor Channel Lighted Buoy 10 LLNR: 2380 Discrepancy Information: Initial Report DTG: 151103Z OCT 2024 Summary: LT EXT	POINT [Latitude: 32.67984, Longitude: -79.71672]

## Advanced Notice of Changes

<b>NAME</b>	<b>ACTION TYPE</b>	<b>DESCRIPTION</b>
Charleston Harbor Channel Lighted Bell Buoy 18	CHANGE	Charleston Harbor Channel LB 18 (LLNR 2420) will have the bell permanently removed.
Charleston Harbor Channel Lighted Bell Buoy 22	CHANGE	Charleston Harbor Channel LB 22 (LLNR 2440) will have the bell permanently removed.

# Charleston Harbor North Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Charleston Harbor - Charleston Harbor North Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-27	2025-04-25	ATON/Federal Discrepancies From: 2024-10-27 To: 2025-04-25 Location: 32.77136° N / 79.88878° W Aid Name: Charleston Harbor North Channel Lighted Buoy 27 LLNR: 2500 Discrepancy Information: Initial Report DTG: 271437Z OCT 2024 Summary: BUOY DMGD	POINT [Latitude: 32.77136, Longitude: -79.88878]
Charleston Harbor - Charleston Harbor North Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 32.77136° N / 79.88878° W Aid Name: Charleston Harbor North Channel Lighted Buoy 27 LLNR: 2500 Discrepancy Information: Initial Report DTG: 271437Z OCT 2024 Summary: BUOY DMGD Correction DTG: 291206Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 32.77136, Longitude: -79.88878]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Charleston Harbor North Channel Lighted Buoy 27	2500	WATCHING PROPERLY	FD	2024-10-29
Charleston Harbor North Channel Lighted Buoy 27	2500	WATCHING PROPERLY	FD	2024-10-29

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Bennis Reach Range Front Light	RELOCATE	Bennis Reach RFL (LLNR 2505.5) will be relocated to approximate position 32-47-15.433N/079-55-25.965W with an approximate focal height of 29'. The flash characteristics of the optic will remain a Q R. Two passing lights displaying a FI W 2.5s will be mounted on opposite corners of the platform with both lights synchronized.
Bennis Reach Range Rear Light	RELOCATE	Bennis Reach RRL (LLNR 2506) will be relocated to approximate position 32-47-22.658N/079-55-42.841W with an approximate focal height of 71 feet. The new position will keep the RRL on land, located on the top level of a parking garage in downtown Charleston. The flash characteristics of the optic will remain a R Iso 6s.

## Charleston Harbor Savannah River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parris Island Fish Haven Buoy	35600	MISSING	PA
Braddock Cove Creek Jetty Light	35815.5	LT IMCH	PA

## Chokoloskee Bay Channel

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
National Park Service Boat Basin South Channel Daybeacon 1	16105	STRUCT DEST	PA
National Park Service Boat Basin South Channel Daybeacon 5	16125	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 1	16135	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 2	16140	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 5	16150	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 6	16155	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 7	16160	STRUCT DEST	PA

## Christiansted Harbor Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Christiansted Schooner Channel Lighted Buoy 5	32950	OFF STA/LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 6	32955	LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 7	32965	BUOY DMGD	PA
Christiansted Schooner Channel Lighted Buoy 10	32980	LT EXT	PA
Christiansted Schooner Lighted Buoy 11	32985	LT EXT	PA

## Clarks Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------



<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Clarks Creek Lighted Buoy 2	2230	OFF STA	FD
Five Fathom Creek Daybeacon 11	2310	STRUCT DEST	FD

## **Clearwater Harbor**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Clearwater Harbor Light 4	61725	STRUCT MISSING/TRLB	FD
Clearwater Wreck Light WR14A	61805	STRUCT MISSING/TRLB	FD
Clearwater Harbor Daybeacon 20	61847	STRUCT DEST/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Pass Channel - Clearwater Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.92413° N / 82.82745° W Aid Name: Clearwater Harbor Daybeacon 2 LLNR: 61715 Discrepancy Information: Initial Report DTG: 011703Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.92413, Longitude: -82.82745]
Clearwater Pass Channel - Clearwater Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-29	2025-04-27	ATON/Federal Discrepancies From: 2024-10-29 To: 2025-04-27 Location: 27.97914° N / 82.80307° W Aid Name: Clearwater Harbor Daybeacon 17 LLNR: 61835 Discrepancy Information: Initial Report DTG: 291415Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.97914, Longitude: -82.80307]
Clearwater Pass Channel - Clearwater Harbor/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.97914° N / 82.80307° W Aid Name: Clearwater Harbor Daybeacon 17 LLNR: 61835 Discrepancy Information: Initial Report DTG: 291415Z OCT 2024 Summary: DBD DEST Correction DTG: 291430Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.97914, Longitude: -82.80307]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Pass Channel - Clearwater Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.9281° N / 82.82565° W Aid Name: Clearwater Harbor Light 4 LLNR: 61725 Discrepancy Information: Initial Report DTG: 301732Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 301732Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.9281, Longitude: -82.82565]
Clearwater Pass Channel - Clearwater Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.9707° N / 82.80395° W Aid Name: Clearwater Wreck Light WR14A LLNR: 61805 Discrepancy Information: Initial Report DTG: 301735Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 301735Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.9707, Longitude: -82.80395]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Clearwater Harbor Daybeacon 17	61835	WATCHING PROPERLY	FD	2024-10-29
Clearwater Harbor Daybeacon 17	61835	WATCHING PROPERLY	FD	2024-10-29

## Clearwater Pass

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Causeway Channel Daybeacon 4	25835	DBD DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - Clearwater Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.96922° N / 82.81386° W Aid Name: Causeway Channel Daybeacon 6 LLNR: 25845 Discrepancy Information: Initial Report DTG: 030024Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.96922, Longitude: -82.81386]
Clearwater Harbor - Clearwater Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.96922° N / 82.81386° W Aid Name: Causeway Channel Daybeacon 6 LLNR: 25845 Discrepancy Information: Initial Report DTG: 011702Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.96922, Longitude: -82.81386]
Clearwater Harbor - Clearwater Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.967° N / 82.80956° W Aid Name: Causeway Channel Daybeacon 4 LLNR: 25835 Discrepancy Information: Initial Report DTG: 030024Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.967, Longitude: -82.80956]
Clearwater Harbor - Clearwater Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.96645° N / 82.80832° W Aid Name: Causeway Channel Daybeacon 2 LLNR: 25830 Discrepancy Information: Initial Report DTG: 011700Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.96645, Longitude: -82.80832]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - Clearwater Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-01	2025- 03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.967° N / 82.80956° W Aid Name: Causeway Channel Daybeacon 4 LLNR: 25835 Discrepancy Information: Initial Report DTG: 011701Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.967, Longitude: -82.80956]



# Clearwater Pass Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.9668° N / 82.83451° W Aid Name: Clearwater Pass Channel Light 4 LLNR: 25690 Discrepancy Information: Initial Report DTG: 011652Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.9668, Longitude: -82.83451]
Clearwater Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.96929° N / 82.83843° W Aid Name: Clearwater Pass Channel Daybeacon 3 LLNR: 25685 Discrepancy Information: Initial Report DTG: 011655Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.96929, Longitude: -82.83843]
Clearwater Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.96583° N / 82.83004° W Aid Name: Clearwater Pass Channel Light 7 LLNR: 25700 Discrepancy Information: Initial Report DTG: 011658Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.96583, Longitude: -82.83004]



## Clewiston Channel Route 1B

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clewiston Channel (Rt 1B) Daybeacon 5	51275	STRUCT DEST/TRLB	FD
Clewiston Channel (Rt 1B) Daybeacon 9	51295	STRUCT DEST	FD
Clewiston Channel (Rt 1B) Daybeacon 14	51350	STRUCT DEST/TRUB	FD

## Cooper River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
U.S. South Navy Pier P Light (1)	2815	LT EXT	PA
U.S. South Navy Pier North Light (1)	2825	LT EXT	PA
U.S. South Navy Pier M Light	2830	LT EXT	PA
Don Holt I-526 Bridge Racon	2905.5	RAC INOP	PA
Cooper River Ammunition Pier Light	3015	LT EXT	PA
South Carolina Gas & Elec North Pier Light	3260	LT EXT	PA
South Carolina Gas & Elec South Pier Light	3265	LT EXT	PA
Upper Cooper River Daybeacon 12	3287.8	STRUCT DEST	PA
Upper Cooper River Daybeacon 22	3288.5	DAYMK DMGD	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025-04-18 Location: 32.85289° N / 79.94381° W The USCG will be demolishing, rebuilding and dredging pier november in approximate position 32-51-09.7N/079-56-48.8W. Operations are expected to commence January 15, 2024, with an estimated completion date of December 31, 2026. During the construction phase operations will be conducted Monday-Friday 7 a.m. to 7 p.m., during dredging operations may be continuous 24 hours a day/ 7 days a week. For further information contact: LCDR John Houk at John.R.Houk@uscg.mil.	POINT [Latitude: 32.85289, Longitude: -79.94381]
Charleston Harbor - Cooper River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 32.86877° N / 79.96469° W Aid Name: Cooper River Light 53 LLNR: 2869 Discrepancy Information: Initial Report DTG: 120016Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 32.86877, Longitude: -79.96469]

## Coosaw River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parrot Creek Daybeacon 3	35235	STRUCT DEST	PA

## Cowpens

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cowpens Daybeacon 73A	50605	STRUCT DEST/HAZ NAV/TRLB	FD

## Cross Florida Greenway

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cross Florida Greenway Light 22	29240	DBD DEST	FD
Cross Florida Greenway Daybeacon 23	29245	DBD DEST	FD
Cross Florida Greenway Daybeacon 24	29250	DBD DEST	FD
Cross Florida Greenway Daybeacon 25	29255	DBD DEST	FD
Cross Florida Greenway Daybeacon 27	29265	STRUCT DEST	FD
Cross Florida Greenway Daybeacon 27	29265	STRUCT DEST/TRUB	FD
Cross Florida Greenway Daybeacon 28	29270	DBD DEST	FD
Cross Florida Greenway Daybeacon 29	29275	DBD DEST	FD
Cross Florida Greenway Daybeacon 30	29280	DBD DEST	FD
Cross Florida Greenway Daybeacon 31	29285	DBD DEST	FD

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Cross Florida Greenway Daybeacon 32	29290	DBD DEST	FD
Cross Florida Greenway Daybeacon 33	29295	STRUCT DEST	FD
Cross Florida Greenway Daybeacon 33	29295	STRUCT DEST	FD
Cross Florida Greenway Daybeacon 35	29305	DBD DEST	FD
Cross Florida Greenway Daybeacon 36	29310	STRUCT DEST	FD
Cross Florida Greenway Daybeacon 37	29315	DBD DEST	FD
Cross Florida Greenway Daybeacon 38	29320	DBD DEST	FD
Cross Florida Greenway Daybeacon 39	29325	DBD DEST	FD
Cross Florida Greenway Daybeacon 41	29335	DBD DEST	FD
Cross Florida Greenway Daybeacon 43	29345	DBD DEST	FD
Cross Florida Greenway Daybeacon 45	29355	DBD DEST	FD
Cross Florida Greenway Daybeacon 46	29360	DBD DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/ATON Discrepancies	Federal	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.96653° N / 82.81795° W Aid Name: Cross Florida Greenway Daybeacon 28 LLNR: 29270 Discrepancy Information: Initial Report DTG: 042051Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.96653, Longitude: -82.81795]
Cross Florida Greenway/ATON/ATON Discrepancies	Federal	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.97618° N / 82.79379° W Aid Name: Cross Florida Greenway Daybeacon 33 LLNR: 29295 Discrepancy Information: Initial Report DTG: 042132Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.97618, Longitude: -82.79379]
Cross Florida Greenway/ATON/ATON Discrepancies	Federal	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.99385° N / 82.7436° W Aid Name: Cross Florida Greenway Daybeacon 45 LLNR: 29355 Discrepancy Information: Initial Report DTG: 042137Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.99385, Longitude: -82.7436]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.98125° N / 82.77665° W Aid Name: Cross Florida Greenway Daybeacon 38 LLNR: 29320 Discrepancy Information: Initial Report DTG: 042135Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.98125, Longitude: -82.77665]
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.98511° N / 82.76854° W Aid Name: Cross Florida Greenway Daybeacon 39 LLNR: 29325 Discrepancy Information: Initial Report DTG: 042135Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.98511, Longitude: -82.76854]
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.99297° N / 82.74359° W Aid Name: Cross Florida Greenway Daybeacon 46 LLNR: 29360 Discrepancy Information: Initial Report DTG: 042138Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.99297, Longitude: -82.74359]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.95701° N / 82.8458° W Aid Name: Cross Florida Greenway Light 22 LLNR: 29240 Discrepancy Information: Initial Report DTG: 042049Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.95701, Longitude: -82.8458]
Cross Florida Greenway/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.96467° N / 82.82708° W Aid Name: Cross Florida Greenway Daybeacon 25 LLNR: 29255 Discrepancy Information: Initial Report DTG: 042051Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.96467, Longitude: -82.82708]
Cross Florida Greenway/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.96777° N / 82.81831° W Aid Name: Cross Florida Greenway Daybeacon 27 LLNR: 29265 Discrepancy Information: Initial Report DTG: 042052Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 211544Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.96777, Longitude: -82.81831]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/ATON/Discrepancies	Federal	Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.9701° N / 82.80799° W Aid Name: Cross Florida Greenway Daybeacon 30 LLNR: 29280 Discrepancy Information: Initial Report DTG: 042053Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.9701, Longitude: -82.80799]
Cross Florida Greenway/ATON/ATON/Discrepancies	Federal	Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.97249° N / 82.80167° W Aid Name: Cross Florida Greenway Daybeacon 32 LLNR: 29290 Discrepancy Information: Initial Report DTG: 042131Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.97249, Longitude: -82.80167]
Cross Florida Greenway/ATON/ATON/Discrepancies	Federal	Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.97841° N / 82.78493° W Aid Name: Cross Florida Greenway Daybeacon 36 LLNR: 29310 Discrepancy Information: Initial Report DTG: 042133Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.97841, Longitude: -82.78493]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.97907° N / 82.7856° W Aid Name: Cross Florida Greenway Daybeacon 35 LLNR: 29305 Discrepancy Information: Initial Report DTG: 042133Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.97907, Longitude: -82.7856]
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.98217° N / 82.77675° W Aid Name: Cross Florida Greenway Daybeacon 37 LLNR: 29315 Discrepancy Information: Initial Report DTG: 042134Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.98217, Longitude: -82.77675]
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.9617° N / 82.83581° W Aid Name: Cross Florida Greenway Daybeacon 23 LLNR: 29245 Discrepancy Information: Initial Report DTG: 042049Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.9617, Longitude: -82.83581]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.96069° N / 82.83508° W Aid Name: Cross Florida Greenway Daybeacon 24 LLNR: 29250 Discrepancy Information: Initial Report DTG: 042050Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.96069, Longitude: -82.83508]
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.97123° N / 82.80851° W Aid Name: Cross Florida Greenway Daybeacon 29 LLNR: 29275 Discrepancy Information: Initial Report DTG: 042054Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.97123, Longitude: -82.80851]
Cross Florida Greenway/ATON/Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.97325° N / 82.80228° W Aid Name: Cross Florida Greenway Daybeacon 31 LLNR: 29285 Discrepancy Information: Initial Report DTG: 042054Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.97325, Longitude: -82.80228]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cross Florida Greenway/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.9879° N / 82.7605° W Aid Name: Cross Florida Greenway Daybeacon 41 LLNR: 29335 Discrepancy Information: Initial Report DTG: 042136Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.9879, Longitude: -82.7605]
Cross Florida Greenway/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.99072° N / 82.75255° W Aid Name: Cross Florida Greenway Daybeacon 43 LLNR: 29345 Discrepancy Information: Initial Report DTG: 042136Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.99072, Longitude: -82.75255]

## Cruz Bay

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cruz Bay Light	32775	LT EXT/DAYMK MISSING	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cruz Bay Buoy 2	32785	OFF STA	PA

## Crystal River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Entrance Daybeacon 14	28855	STRUCT DEST	FD
Crystal River Entrance Daybeacon 14	28855	STRUCT MISSING/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Daybeacon 25	28952.6	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92589° N / 82.69837° W Aid Name: Crystal River Entrance Daybeacon 20 LLNR: 28885 Discrepancy Information: Initial Report DTG: 041953Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92589, Longitude: -82.69837]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92574° N / 82.70718° W Aid Name: Crystal River Entrance Daybeacon 15 LLNR: 28860 Discrepancy Information: Initial Report DTG: 041951Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92574, Longitude: -82.70718]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92547° N / 82.70701° W Aid Name: Crystal River Entrance Daybeacon 16 LLNR: 28865 Discrepancy Information: Initial Report DTG: 041951Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92547, Longitude: -82.70701]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92614° N / 82.6984° W Aid Name: Crystal River Entrance Daybeacon 19 LLNR: 28880 Discrepancy Information: Initial Report DTG: 041952Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92614, Longitude: -82.6984]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92458° N / 82.72464° W Aid Name: Crystal River Entrance Daybeacon 8 LLNR: 28815 Discrepancy Information: Initial Report DTG: 041947Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92458, Longitude: -82.72464]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.91771° N / 82.73819° W Aid Name: Crystal River Entrance Daybeacon 3 LLNR: 28795 Discrepancy Information: Initial Report DTG: 041944Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.91771, Longitude: -82.73819]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92521° N / 82.70889° W Aid Name: Crystal River Entrance Daybeacon 14 LLNR: 28855 Discrepancy Information: Initial Report DTG: 041959Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.92521, Longitude: -82.70889]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.921° N / 82.73427° W Aid Name: Crystal River Entrance Daybeacon 4 LLNR: 28800 Discrepancy Information: Initial Report DTG: 041945Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.921, Longitude: -82.73427]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92506° N / 82.72169° W Aid Name: Crystal River Entrance Daybeacon 9 LLNR: 28825 Discrepancy Information: Initial Report DTG: 041948Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92506, Longitude: -82.72169]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92537° N / 82.71366° W Aid Name: Crystal River Entrance Daybeacon 11 LLNR: 28840 Discrepancy Information: Initial Report DTG: 041949Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92537, Longitude: -82.71366]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.9121° N / 82.74764° W Aid Name: Crystal River Entrance Light 1 LLNR: 28775 Discrepancy Information: Initial Report DTG: 041943Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.9121, Longitude: -82.74764]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92442° N / 82.73009° W Aid Name: Crystal River Entrance Daybeacon 5 LLNR: 28805 Discrepancy Information: Initial Report DTG: 041945Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92442, Longitude: -82.73009]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92409° N / 82.73061° W Aid Name: Crystal River Entrance Daybeacon 6 LLNR: 28810 Discrepancy Information: Initial Report DTG: 041946Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92409, Longitude: -82.73061]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92478° N / 82.72169° W Aid Name: Crystal River Entrance Daybeacon 10 LLNR: 28830 Discrepancy Information: Initial Report DTG: 041948Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92478, Longitude: -82.72169]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92491° N / 82.71765° W Aid Name: Crystal River Entrance Daybeacon 10A LLNR: 28835 Discrepancy Information: Initial Report DTG: 041949Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92491, Longitude: -82.71765]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92549° N / 82.70893° W Aid Name: Crystal River Entrance Daybeacon 13 LLNR: 28850 Discrepancy Information: Initial Report DTG: 041950Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92549, Longitude: -82.70893]
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.92636° N / 82.69379° W Aid Name: Crystal River Entrance Daybeacon 21 LLNR: 28890 Discrepancy Information: Initial Report DTG: 041954Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92636, Longitude: -82.69379]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.91771° N / 82.73819° W Aid Name: Crystal River Entrance Daybeacon 3 LLNR: 28795 Discrepancy Information: Initial Report DTG: 041944Z OCT 2024 Summary: DBD DEST Correction DTG: 311203Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.91771, Longitude: -82.73819]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-31	2025-04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 28.91726° N / 82.73752° W Aid Name: Crystal River Entrance Daybeacon 2B LLNR: 28790 Discrepancy Information: Initial Report DTG: 311312Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.91726, Longitude: -82.73752]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.921° N / 82.73427° W Aid Name: Crystal River Entrance Daybeacon 4 LLNR: 28800 Discrepancy Information: Initial Report DTG: 041945Z OCT 2024 Summary: DBD DEST Correction DTG: 311205Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.921, Longitude: -82.73427]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92442° N / 82.73009° W Aid Name: Crystal River Entrance Daybeacon 5 LLNR: 28805 Discrepancy Information: Initial Report DTG: 041945Z OCT 2024 Summary: DBD DEST Correction DTG: 311206Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92442, Longitude: -82.73009]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92409° N / 82.73061° W Aid Name: Crystal River Entrance Daybeacon 6 LLNR: 28810 Discrepancy Information: Initial Report DTG: 041946Z OCT 2024 Summary: DBD DEST Correction DTG: 311208Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92409, Longitude: -82.73061]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92506° N / 82.72169° W Aid Name: Crystal River Entrance Daybeacon 9 LLNR: 28825 Discrepancy Information: Initial Report DTG: 041948Z OCT 2024 Summary: DBD DEST Correction DTG: 311214Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92506, Longitude: -82.72169]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92614° N / 82.6984° W Aid Name: Crystal River Entrance Daybeacon 19 LLNR: 28880 Discrepancy Information: Initial Report DTG: 041952Z OCT 2024 Summary: DBD DEST Correction DTG: 311226Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92614, Longitude: -82.6984]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92458° N / 82.72464° W Aid Name: Crystal River Entrance Daybeacon 8 LLNR: 28815 Discrepancy Information: Initial Report DTG: 041947Z OCT 2024 Summary: DBD DEST Correction DTG: 311210Z OCT 2024 Cause: WEATHER Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92458, Longitude: -82.72464]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.91726° N / 82.73752° W Aid Name: Crystal River Entrance Daybeacon 2B LLNR: 28790 Discrepancy Information: Initial Report DTG: 311312Z OCT 2024 Summary: DBD DEST Correction DTG: 311313Z OCT 2024 Cause: WEATHER Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.91726, Longitude: -82.73752]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92636° N / 82.69379° W Aid Name: Crystal River Entrance Daybeacon 21 LLNR: 28890 Discrepancy Information: Initial Report DTG: 041954Z OCT 2024 Summary: DBD DEST Correction DTG: 311229Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92636, Longitude: -82.69379]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92491° N / 82.71765° W Aid Name: Crystal River Entrance Daybeacon 10A LLNR: 28835 Discrepancy Information: Initial Report DTG: 041949Z OCT 2024 Summary: DBD DEST Correction DTG: 311218Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92491, Longitude: -82.71765]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.9121° N / 82.74764° W Aid Name: Crystal River Entrance Light 1 LLNR: 28775 Discrepancy Information: Initial Report DTG: 041943Z OCT 2024 Summary: DBD DEST Correction DTG: 311202Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.9121, Longitude: -82.74764]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92478° N / 82.72169° W Aid Name: Crystal River Entrance Daybeacon 10 LLNR: 28830 Discrepancy Information: Initial Report DTG: 041948Z OCT 2024 Summary: DBD DEST Correction DTG: 311212Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92478, Longitude: -82.72169]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-31	2025-04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 28.92414° N / 82.6886° W Aid Name: Crystal River Entrance Daybeacon 24 LLNR: 28905 Discrepancy Information: Initial Report DTG: 311314Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.92414, Longitude: -82.6886]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92537° N / 82.71366° W Aid Name: Crystal River Entrance Daybeacon 11 LLNR: 28840 Discrepancy Information: Initial Report DTG: 041949Z OCT 2024 Summary: DBD DEST Correction DTG: 311220Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92537, Longitude: -82.71366]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
-------	----------	--------------	------------	----------	-------------	----------

Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92549° N / 82.70893° W Aid Name: Crystal River Entrance Daybeacon 13 LLNR: 28850 Discrepancy Information: Initial Report DTG: 041950Z OCT 2024 Summary: DBD DEST Correction DTG: 311221Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92549, Longitude: -82.70893]
--	------	---------------------------------	------------	------------	---	---

Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92589° N / 82.69837° W Aid Name: Crystal River Entrance Daybeacon 20 LLNR: 28885 Discrepancy Information: Initial Report DTG: 041953Z OCT 2024 Summary: DBD DEST Correction DTG: 311227Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92589, Longitude: -82.69837]
--	------	---------------------------------	------------	------------	---	---

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-31	2025-04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 28.92521° N / 82.70889° W Aid Name: Crystal River Entrance Daybeacon 14 LLNR: 28855 Discrepancy Information: Initial Report DTG: 311309Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 311309Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.92521, Longitude: -82.70889]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92574° N / 82.70718° W Aid Name: Crystal River Entrance Daybeacon 15 LLNR: 28860 Discrepancy Information: Initial Report DTG: 041951Z OCT 2024 Summary: DBD DEST Correction DTG: 311223Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92574, Longitude: -82.70718]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92547° N / 82.70701° W Aid Name: Crystal River Entrance Daybeacon 16 LLNR: 28865 Discrepancy Information: Initial Report DTG: 041951Z OCT 2024 Summary: DBD DEST Correction DTG: 311224Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92547, Longitude: -82.70701]
Crystal River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 28.92414° N / 82.6886° W Aid Name: Crystal River Entrance Daybeacon 24 LLNR: 28905 Discrepancy Information: Initial Report DTG: 311314Z OCT 2024 Summary: DBD DEST Correction DTG: 311314Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.92414, Longitude: -82.6886]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Crystal River Entrance Light 1	28775	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Light 1	28775	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 2B	28790	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 2B	28790	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 3	28795	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 3	28795	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 4	28800	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 4	28800	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 5	28805	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 5	28805	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 6	28810	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 6	28810	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 8	28815	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 8	28815	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 9	28825	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 9	28825	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 10	28830	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 10	28830	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 10A	28835	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 10A	28835	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 11	28840	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 11	28840	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 13	28850	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 13	28850	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 15	28860	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 15	28860	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 16	28865	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 16	28865	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 19	28880	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 19	28880	WATCHING PROPERLY	FD	2024-10-31

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Crystal River Entrance Daybeacon 20	28885	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 20	28885	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 21	28890	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 21	28890	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 24	28905	WATCHING PROPERLY	FD	2024-10-31
Crystal River Entrance Daybeacon 24	28905	WATCHING PROPERLY	FD	2024-10-31

## Cumberland River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland River Light 33	37390	STRUCT DEST/TRLB	FD
Cumberland River Daybeacon 51	37560	STRUCT DEST/TRUB	FD
Cumberland River Daybeacon 58A	37603	STRUCT DEST/HAZ NAV/TRLB	FD
Cumberland River Daybeacon 59A	37607	STRUCT DEST/TRUB	FD
Cumberland River Light 60	37610	STRUCT DEST/TRLB	FD
Cumberland River Daybeacon 63	37623	STRUCT DEST/TRUB	FD

### Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Cumberland River Light 35	RELOCATE	Cumberland River LT 35 (LLNR 37405) will be relocated due to the water depth at current location being too deep for CG assets to effect repairs. The aid will be relocated approximately 453 yards south of its current location in a depth of 15 feet. This change will ensure safe navigation and keep the same alignment with the surrounding aids in the Cumberland River. Cumberland River LT 35 (LLNR 37405) will be relocated to approximate position 30-57-14.700N/081-25-44.460W.

## Cumberland Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland Sound Upper Range A Rear Light	6695	STRUCT DEST	FD
Cumberland Sound Shoal Light A	6773	STRUCT DEST	FD
Cumberland Sound Shoal Light B	6837	STRUCT DEST	FD
Cumberland Sound Shoal Light D	6867	STRUCT DEST	FD
Cumberland Sound Shoal Light G	6892	STRUCT DEST	FD
Cumberland Sound Shoal Light H	6894	STRUCT DEST/TRLB	FD
Cumberland Sound Range D Front Light	6905	LT IMCH	FD
Cumberland Sound Shoal Light I	6927	STRUCT DEST	FD
Cumberland Sound Range F Front Light	37645	LT EXT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cumberland Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 30.74361° N / 81.48739° W Aid Name: Cumberland Sound Range B Range Rear Light LLNR: 6785 Discrepancy Information: Initial Report DTG: 120105Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 30.74361, Longitude: -81.48739]
Cumberland Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-25	2024-11-08	ATON/Federal Discrepancies Corrected From: 2024-10-25 To: 2024-11-08 Location: 30.77919° N / 81.48827° W Aid Name: Cumberland Sound Range D Front Light LLNR: 6905 Discrepancy Information: Initial Report DTG: 271722Z SEP 2024 Summary: STRUCTURE DEST/TRLB Temporary Response DTG: 301930Z SEP 2024 Temporary Response: TLB Correction DTG: 251358Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: REBUILT/RECOVERED	POINT [Latitude: 30.77919, Longitude: -81.48827]
Cumberland Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-25	2025-04-23	ATON/Federal Discrepancies From: 2024-10-25 To: 2025-04-23 Location: 30.77919° N / 81.48827° W Aid Name: Cumberland Sound Range D Front Light LLNR: 6905 Discrepancy Information: Initial Report DTG: 251359Z OCT 2024 Summary: LT IMCH	POINT [Latitude: 30.77919, Longitude: -81.48827]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cumberland Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 30.74045° N / 81.4867° W Aid Name: Cumberland Sound Range B Front Light LLNR: 6780 Discrepancy Information: Initial Report DTG: 182030Z OCT 2022 Summary: LT EXT Correction DTG: 312301Z OCT 2024 Cause: ATON EQUIPMENT Cause Comments: LED/COMP Correction Status: RELIGHTED	POINT [Latitude: 30.74045, Longitude: -81.4867]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Cumberland Sound Range B Front Light	6780	RELIGHTED	FD	2024-10-31
Cumberland Sound Range D Front Light	6905	REBUILT/RECOVERED	FD	2024-10-25

## Cut A Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Skyway Pier Southeast Light	22425	LT EXT	PA
Tampa Bay Skyway Pier Northeast Light	22430	LT EXT	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Cut A Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-19	2025-04-17	ATON/Federal Discrepancies From: 2024-10-19 To: 2025-04-17 Location: 27.64751° N / 82.59663° W Aid Name: Tampa Bay Cut A Channel Range Rear Light LLNR: 22410 Discrepancy Information: Initial Report DTG: 191725Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.64751, Longitude: -82.59663]
Mullet Key Channel - Cut A Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-24	2024-11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 27.64751° N / 82.59663° W Aid Name: Tampa Bay Cut A Channel Range Rear Light LLNR: 22410 Discrepancy Information: Initial Report DTG: 191725Z OCT 2024 Summary: LT EXT Correction DTG: 242117Z OCT 2024 Cause: ATON EQUIPMENT Cause Comments: WIRING Correction Status: RELIGHTED	POINT [Latitude: 27.64751, Longitude: -82.59663]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut A Channel Range Rear Light	22410	RELIGHTED	FD	2024-10-24
Tampa Bay Cut A Channel Range Rear Light	22410	RELIGHTED	FD	2024-10-24

## Cut G Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut G Channel Lighted Buoy 8G	23700	OFF STATION	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Smacks Bayou Daybeacon 1	25025	STRUCT DEST	PA
Smacks Bayou Daybeacon 3	25025.2	STRUCT DEST	PA
Smacks Bayou Daybeacon 6	25025.5	DAYMK MISSING	PA
Smacks Bayou Daybeacon 8	25025.6	STRUCT DEST	PA
Smacks Bayou Daybeacon 10	25025.7	STRUCT DEST/HAZ NAV	PA
Smacks Bayou Daybeacon 13	25025.9	STRUCT DEST	PA
Smacks Bayou Daybeacon 14	25026	HAZ NAV/DAYMK MISSING	PA
Smacks Bayou Daybeacon 15	25026.1	DAYMK MISSING	PA
Smacks Bayou Daybeacon 16	25026.2	DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut F Channel - Cut G Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-22	2025- 04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.79302° N / 82.58715° W Aid Name: Tampa Bay Cut G Channel Range Front Light LLNR: 23665 Discrepancy Information: Initial Report DTG: 222109Z OCT 2024 Summary: TRLT Temporary Response DTG: 222110Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.79302, Longitude: -82.58715]
Tampa Bay Cut F Channel - Cut G Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-24	2024- 11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 27.79302° N / 82.58715° W Aid Name: Tampa Bay Cut G Channel Range Front Light LLNR: 23665 Discrepancy Information: Initial Report DTG: 222109Z OCT 2024 Summary: TRLT Temporary Response DTG: 222110Z OCT 2024 Temporary Response: TL Correction DTG: 241903Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: REBUILT/RECOVERED	POINT [Latitude: 27.79302, Longitude: -82.58715]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut F Channel - Cut G Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-24	2025- 04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 27.79302° N / 82.58715° W Aid Name: Tampa Bay Cut G Channel Range Front Light LLNR: 23665 Discrepancy Information: Initial Report DTG: 241904Z OCT 2024 Summary: LT EXT/TRLT Temporary Response DTG: 241904Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.79302, Longitude: -82.58715]
Tampa Bay Cut F Channel - Cut G Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-22	2025- 04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.78906° N / 82.55524° W Aid Name: Tampa Bay Cut G Channel Lighted Buoy 6G LLNR: 23690 Discrepancy Information: Initial Report DTG: 222055Z OCT 2024 Summary: SINKING	POINT [Latitude: 27.78906, Longitude: -82.55524]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut F Channel - Cut G Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	<p>ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.79302° N / 82.58715° W Aid Name: Tampa Bay Cut G Channel Range Front Light LLNR: 23665 Discrepancy Information: Initial Report DTG: 241904Z OCT 2024 Summary: LT EXT/TRLT Temporary Response DTG: 241904Z OCT 2024 Temporary Response: TL Correction DTG: 311423Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RELIGHTED</p>	POINT [Latitude: 27.79302, Longitude: -82.58715]
Tampa Bay Cut F Channel - Cut G Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-11-02	2025-05-01	<p>ATON/Federal Discrepancies From: 2024-11-02 To: 2025-05-01 Location: 27.79061° N / 82.56668° W Aid Name: Tampa Bay Cut G Channel Lighted Buoy 8G LLNR: 23700 Discrepancy Information: Initial Report DTG: 022236Z NOV 2024 Summary: OFF STATION</p>	POINT [Latitude: 27.79061, Longitude: -82.56668]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut G Channel Range Front Light	23665	REBUILT/RECOVERED	FD	2024-10-24
Tampa Bay Cut G Channel Range Front Light	23665	REBUILT/RECOVERED	FD	2024-10-24
Tampa Bay Cut G Channel Range Front Light	23665	RELIGHTED	FD	2024-10-31
Tampa Bay Cut G Channel Range Front Light	23665	RELIGHTED	FD	2024-10-31
Tampa Bay Cut G Channel Lighted Buoy 6G	23690	RESET ON STATION	FD	2024-10-22

## Cut K Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut K Channel Upper Range Front Light	23780	LT IMCH	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rattlesnake Channel Daybeacon A	23814	DAYMK IMCH	PA
Westshore Yacht Club Light 2	23814.1	STRUCT DEST	PA
Westshore Yacht Club Daybeacon 4	23814.2	STRUCT DEST	PA
Old Tampa Bay Pipeline West Light	23950.5	STRUCT DEST/HAZ NAV	PA
Culbreath Bayou North Daybeacon 3	24070	DAYMK MISSING	PA
Bay Crest Daybeacon 5	24275	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 2	25040	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 3	25045	DAYMK DMGD	PA
Bayou Grande Channel Daybeacon 9	25065	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 21	25105	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 30	25150	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 31	25155	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 41	25200	STRUCT DEST	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Mobel Americana Channel Daybeacon 3	25260.2	DAYMK MISSING	PA
Tanglewood Channel Daybeacon 1	25265	STRUCT DEST	PA

## **Darien River**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Darien River Daybeacon 17	36826.7	STRUCT DEST/TRUB	FD

## **Derrick Key Gap Channel**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Derrick Key Gap Channel Daybeacon 2	30055	STRUCT MISSING	FD
Derrick Key Gap Channel Daybeacon 3	30060	STRUCT MISSING	FD
Derrick Key Gap Channel Daybeacon 3	30060	STRUCT DEST/TRLB	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Suwannee Sound South Entrance - Derrick Key Gap Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-14	2025- 04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.19155° N / 83.08084° W Aid Name: Derrick Key Gap Channel Daybeacon 2 LLNR: 30055 Discrepancy Information: Initial Report DTG: 141940Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.19155, Longitude: -83.08084]
Suwannee Sound South Entrance - Derrick Key Gap Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-14	2025- 04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.19332° N / 83.0808° W Aid Name: Derrick Key Gap Channel Daybeacon 3 LLNR: 30060 Discrepancy Information: Initial Report DTG: 141941Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.19332, Longitude: -83.0808]

## Doboy Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Buoy 2	5920	OFF STA	FD
Doboy Sound Buoy 3	5925	MISSING	FD
Doboy Sound Buoy 4	5930	OFF STA	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Island LT	5946	LT EXT	PA

## Drummond Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Range Front Light	7515	STRUCT DEST/TRLB	FD

### Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Drummond Creek Range Front Light	RELOCATE	Drummond Creek RFL (LLNR 7515) will be permanently relocated to approximate position 30-24-45.104N / 081-35-35.319W. The RFL will remain a nighttime optic only and flash characteristic will remain as a Q R. The RFL will continue to display daymarks for the day-time signal. Both Drummond Creek RFL and RRL will be upgraded with LED light signals to provide a much more reliable signal when using this channel. An additional light will be established and mounted on top of the Drummond Creek RFL optic and synchronized with the RFL to display a Q R flash characteristics during nighttime hours only, with a nominal range of 3NM.

## Elba Island Cut

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elba Island Cut Light 10	35900	REDUCED INT	FD

### Proposed Notice of Change

NAME	ACTION TYPE	DESCRIPTION
Elba Island Cut Light 10	CHANGE	<p>The U.S. Coast Guard is proposing a change to the Aid to Navigation system in the Intracoastal Waterway Elba Island Cut Channel, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or andrew.m.engle@uscg.mil with ICW Nominal Range Change as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by October 9, 2024.</p>

## Elliott Key

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elliott Key Light 16	10940	DAYMK MISSING/STRUCT DMGD/TRLB	FD
Elliott Key Daybeacon 19	10955	STRUCT DEST/HAZ NAV/TRLB	FD
Pacific Reef Daybeacon 3	10965	STRUCT DEST/TRUB	FD
Pacific Reef Daybeacon 3	10965	MISSING/TRUB	FD

## Entrada Channel

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Entrada Channel Daybeacon 1	49240	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 3	49245	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 5	49250	DAYMK MISSING	PA
Entrada Channel Daybeacon 7	49255	DAYMK MISSING	PA
Entrada Channel Daybeacon 9	49260	DAYMK MISSING	PA
Entrada Channel Daybeacon 11	49265	DAYMK MISSING	PA
Entrada Channel Daybeacon 13	49270	DAYMK MISSING	PA

## **Featherbed Bank**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Featherbed Bank Daybeacon 5	49715	STRUCT DEST/HAZ NAV/TRLB	FD

## **Fishermans Channel**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Fishermans Channel Light 11	10685	STRUCT DEST/TRLB	FD
Dodge Island Turning Basin Daybeacon A	10700	STRUCT DEST/TRUB	FD
Dodge Island Turning Basin Daybeacon B	10705	STRUCT DEST	FD
Fishermans Channel Daybeacon 16	10710	STRUCT DEST/TRUB	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Dodge Island Mooring Obstruction Light	10692	STRUCT DEST	PA

## Florida Bay

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Long Key Light 44	13495	STRUCT DEST/HAZ NAV/TRLB	FD
East Turtle Shoal Light 45	13610	STRUCT DEST/HAZ NAV/TRLB	FD

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Flamingo Channel Light 9	15680	DAYMK MISSING	PA
Flamingo Channel Light 15	15710	DAYMK MISSING	PA
Flamingo Channel Daybeacon 16	15715	DAYMK MISSING	PA
Coot Bay Daybeacon 2	15730	STRUCT DEST	PA
Coot Bay Daybeacon 8	15755	DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Florida Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 24.88882° N / 80.60418° W Aid Name: Upper Matecumbe Daybeacon 41 LLNR: 12800 Discrepancy Information: Initial Report DTG: 211020Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 24.88882, Longitude: -80.60418]
Florida Bay/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-24	2024-11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 24.88882° N / 80.60418° W Aid Name: Upper Matecumbe Daybeacon 41 LLNR: 12800 Discrepancy Information: Initial Report DTG: 211020Z OCT 2024 Summary: STRUCT MISSING Correction DTG: 241454Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 24.88882, Longitude: -80.60418]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Upper Matecumbe Daybeacon 41	12800	WATCHING PROPERLY	FD	2024-10-24
Upper Matecumbe Daybeacon 41	12800	WATCHING PROPERLY	FD	2024-10-24

## Floyd Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Floyd Creek Daybeacon A27	37496	STRUCT DEST/TRUB	FD

# Folly River

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Folly River/ATON/Temp Changes Corrected	ATON	Temp Changes Corrected	2024-10-24	2024-11-07	ATON/Temp Changes Corrected From: 2024-10-24 To: 2024-11-07 Location: 32.64732° N / 79.96816° W Aid Name: Folly River Buoy 17A LLNR: 3750.9 Temporary Aid Change Information: Status: RELOCATED FOR DREDGING Correction Date: 2024-09-26T00:00:00 Corrective Action: Returned to Assigned Position	POINT [Latitude: 32.64732, Longitude: -79.96816]



## Fort Gates

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Fort Gates Light 67	8525	STRUCT DEST/TRLB	FD

# Fort Pierce Inlet

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Fort Pierce Inlet/General/MSIB	General	MSIB	2024- 10-20	2025- 04-18	<p>General/MSIB From: 2024-10-20 To: 2025-04-18</p> <p>Location: 27.47158° N / 80.29093° W The Port of Fort Pierce is open with restrictions by order of the Captain of the Port (COTP) effective immediately: All transiting vessel draft is limited to 20 feet or less.</p> <p>These requirements will remain in effect until further notice. This notice applies to the Port of Fort Pierce only.</p> <p>Questions regarding this notice or required actions should be directed to the Maritime Transportation System Recovery Unit at (786) 295- 9051. Marine Safety Information Bulletin updates are available on Homeport at <a href="http://homeport.uscg.mil/miami">http://homeport.uscg.mil/miami</a> under "Port Conditions". The COTP may be reached at telephone (833) 642-7271 or via VHF-FM channel 16 through Coast Guard Sector Miami.</p>	POINT [Latitude: 27.47158, Longitude: -80.29093]



## Fort Pierce Inlet Inner Harbor

### Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Pierce Inlet - Fort Pierce Inlet Inner Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.46067° N / 80.31803° W Aid Name: Fort Pierce Inlet Inner Harbor Light 17 LLNR: 9975 Discrepancy Information: Initial Report DTG: 120020Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.46067, Longitude: -80.31803]

## Frederica River

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Fredericka Yacht Club Obstruction Light	6170	LT EXT	PA

## Fulton Cutoff

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Fulton Cutoff Range Rear Light	7355	DBD DEST	FD
Fulton Cutoff Light 36	7360	STRUCT DEST/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Johns River - Fulton Cutoff/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-21	2025- 04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 30.3949° N / 81.4933° W Aid Name: Fulton Cutoff Range Rear Light LLNR: 7355 Discrepancy Information: Initial Report DTG: 211157Z OCT 2024 Summary: LT EXT/DBD DEST	POINT [Latitude: 30.3949, Longitude: -81.4933]

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Fulton Cutoff Lighted Buoy 35	RELOCATE	Fulton Cutoff LB 35 (LLNR 7345) will be permanently relocated to 30-23-24.090N/081-30-22.230W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.
Blount Island Turning Basin Lighted Buoy 43	RELOCATE	Blount Island Turning Basin LB 43 (LLNR 7385) will be permanently relocated to 30-23-13.450N/081-32-05.380W. The flash characteristic will remain a Fl G 6s, but the nominal range will be reduced from 5NM to 4NM.

## Gables Estates

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gables Estates Daybeacon 2A	49345	STRUCT DEST/HAZ NAV	PA

# Gadsden Point Cut

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-25	2024- 11-08	ATON/Federal Discrepancies Corrected From: 2024-10-25 To: 2024-11-08 Location: 27.79727° N / 82.48608° W Aid Name: Gadsden Point Cut Lighted Buoy 5 LLNR: 22880 Discrepancy Information: Initial Report DTG: 241356Z OCT 2024 Summary: OFF STATION Correction DTG: 251111Z OCT 2024 Cause: FALSE REPORT Cause Comments: FALSE REPORT Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.79727, Longitude: -82.48608]
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-24	2025- 04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 27.7918° N / 82.50249° W Aid Name: Gadsden Point Cut Lighted Buoy 3 LLNR: 22870 Discrepancy Information: Initial Report DTG: 241353Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.7918, Longitude: -82.50249]
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-24	2025- 04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 27.79018° N / 82.50171° W Aid Name: Gadsden Point Cut Lighted Buoy 4 LLNR: 22875 Discrepancy Information: Initial Report DTG: 241355Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.79018, Longitude: -82.50171]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-24	2025-04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 27.79727° N / 82.48608° W Aid Name: Gadsden Point Cut Lighted Buoy 5 LLNR: 22880 Discrepancy Information: Initial Report DTG: 241356Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.79727, Longitude: -82.48608]
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.78743° N / 82.51452° W Aid Name: Gadsden Point Cut Lighted Buoy 1 LLNR: 22860 Discrepancy Information: Initial Report DTG: 222021Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.78743, Longitude: -82.51452]
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-24	2024-11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 27.7918° N / 82.50249° W Aid Name: Gadsden Point Cut Lighted Buoy 3 LLNR: 22870 Discrepancy Information: Initial Report DTG: 241353Z OCT 2024 Summary: OFF STATION Correction DTG: 241855Z OCT 2024 Cause: FALSE REPORT Cause Comments: FALSE REPORT Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.7918, Longitude: -82.50249]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut F Channel - Gadsden Point Cut/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-24	2024- 11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 27.79018° N / 82.50171° W Aid Name: Gadsden Point Cut Lighted Buoy 4 LLNR: 22875 Discrepancy Information: Initial Report DTG: 241355Z OCT 2024 Summary: OFF STATION Correction DTG: 241856Z OCT 2024 Cause: FALSE REPORT Cause Comments: FALSE REPORT Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.79018, Longitude: -82.50171]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Gadsden Point Cut Lighted Buoy 1	22860	WATCHING PROPERLY	FD	2024-10-22
Gadsden Point Cut Lighted Buoy 3	22870	WATCHING PROPERLY	FD	2024-10-24
Gadsden Point Cut Lighted Buoy 3	22870	WATCHING PROPERLY	FD	2024-10-24
Gadsden Point Cut Lighted Buoy 4	22875	WATCHING PROPERLY	FD	2024-10-24
Gadsden Point Cut Lighted Buoy 4	22875	WATCHING PROPERLY	FD	2024-10-24
Gadsden Point Cut Lighted Buoy 5	22880	WATCHING PROPERLY	FD	2024-10-25
Gadsden Point Cut Lighted Buoy 5	22880	WATCHING PROPERLY	FD	2024-10-25

## Gasparilla Sound Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gasparilla Sound Channel Daybeacon 21	56650	DBD DEST	FD
Gasparilla Sound Channel Light 23	57030	DBD DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gasparilla Island South Obstruction Light	1305.2	LT EXT	PA
Gasparilla Island West Obstruction Light	1305.4	LT EXT	PA
Gasparilla Island North Obstruction Light	1305.6	LT EXT	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pine Island Sound - Gasparilla Sound Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-27	2025-04-25	ATON/Federal Discrepancies From: 2024-10-27 To: 2025-04-25 Location: 26.82772° N / 82.2732° W Aid Name: Gasparilla Sound Channel Light 23 LLNR: 57030 Discrepancy Information: Initial Report DTG: 271439Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.82772, Longitude: -82.2732]
Pine Island Sound - Gasparilla Sound Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.82508° N / 82.26588° W Aid Name: Gasparilla Sound Channel Daybeacon 21 LLNR: 56650 Discrepancy Information: Initial Report DTG: 041804Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.82508, Longitude: -82.26588]

## Gordon Pass Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Gordon Pass Channel Light 3	17460	STRUCT MISSING/MISSING/TRLB	FD
Gordon Pass Channel Light 4	17465	DBD DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Gordon Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.09159° N / 81.80459° W Aid Name: Gordon Pass Channel Light 4 LLNR: 17465 Discrepancy Information: Initial Report DTG: 121423Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.09159, Longitude: -81.80459]
Gordon Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 26.09169° N / 81.80738° W Aid Name: Gordon Pass Channel Buoy 1 LLNR: 17453 Discrepancy Information: Initial Report DTG: 011732Z OCT 2024 Summary: MISSING	POINT [Latitude: 26.09169, Longitude: -81.80738]
Gordon Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 26.09217° N / 81.80491° W Aid Name: Gordon Pass Channel Light 3 LLNR: 17460 Discrepancy Information: Initial Report DTG: 011917Z OCT 2024 Summary: STRUCT MISSING/MISSING/TRLB Temporary Response DTG: 011917Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 26.09217, Longitude: -81.80491]



# Graving Dock Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De San Juan - Graving Dock Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-24	2025-04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 18.44314° N / 66.08619° W Aid Name: Graving Dock Channel Turning Basin Light 5 LLNR: 31085.5 Discrepancy Information: Initial Report DTG: 241134Z OCT 2024 Summary: LT EXT	POINT [Latitude: 18.44314, Longitude: -66.08619]
Bahia De San Juan - Graving Dock Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-24	2024-11-07	ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07 Location: 18.44314° N / 66.08619° W Aid Name: Graving Dock Channel Turning Basin Light 5 LLNR: 31085.5 Discrepancy Information: Initial Report DTG: 241134Z OCT 2024 Summary: LT EXT Correction DTG: 241500Z OCT 2024 Cause: POWER,SOLAR/BATT Cause Comments: SOLAR BATT MALF Correction Status: RELIGHTED	POINT [Latitude: 18.44314, Longitude: -66.08619]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Graving Dock Channel Turning Basin Light 5	31085.5	RELIGHTED	FD	2024-10-24
Graving Dock Channel Turning Basin Light 5	31085.5	RELIGHTED	FD	2024-10-24

---

--

---

## Great Pocket

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Great Pocket Daybeacon 7	45955	DBD DEST	FD
Great Pocket Daybeacon 13	46025	STRUCT DEST/HAZ NAV/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie River - Great Pocket/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-11-01	2025-04-30	ATON/Federal Discrepancies From: 2024-11-01 To: 2025-04-30 Location: 27.15595° N / 80.17172° W Aid Name: Great Pocket Daybeacon 7 LLNR: 45955 Discrepancy Information: Initial Report DTG: 011725Z NOV 2024 Summary: DBD DEST	POINT [Latitude: 27.15595, Longitude: -80.17172]

# Halifax River

## Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax River Daybeacon 18	39905	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 20	39955	STRUCT DEST/TRUB	FD
Halifax River Light 26	39985	STRUCT DEST/TRLB	FD
Halifax River Daybeacon 29	39995	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 30	40000	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 48	40215	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 60	40435	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 72	40490	STRUCT DEST/TRUB	FD

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax Harbor Daybeacon 1	40055	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 4	40365	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 6	40375	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 8	40385	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 9	40390	DAYMK MISSING	PA
Adventure Yacht Harbor Junction Daybeacon	40410	DAYMK IMCH	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Ponce De Leon Cut - Halifax River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-16	2025- 04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 29.20596° N / 81.00746° W Aid Name: Halifax River Daybeacon 39A LLNR: 40125 Discrepancy Information: Initial Report DTG: 161420Z OCT 2024 Summary: STRUCT DEST/HAZ NAV	POINT [Latitude: 29.20596, Longitude: -81.00746]
Ponce De Leon Cut - Halifax River/General/Bridges/Maintenance	General	Bridges	2024- 10-29	2025- 04-27	General/Bridges/Maintenance From: 2024-10-29 To: 2025-04-27 Location: 29.22316° N / 81.0176° W Bridge Name: Main Street Bridge Seacoast INC on behalf of the bridge owner, FDOT, has been contracted to conduct maintenance and repairs on Main Street Bridge across the AICW (Halifax River), mile 829.7, at Daytona Beach, FL. For waterways related questions, contact Coast Guard Sector Jacksonville Waterways Management Division at (904)714-7631 or via email at D07- DG-SECJAX- WATERWAYS@uscg.mil.	POINT [Latitude: 29.22316, Longitude: -81.0176]

## Hampton River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hampton River Daybeacon 12	5975	STRUCT DEST/TRUB	FD

## Hillsboro Inlet

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Inlet Entrance Light 2	10293	DBD DEST	FD
Hillsboro Inlet Entrance Daybeacon 5	10303	STRUCT DEST/HAZ NAV/TRLB	FD
Hillsboro Inlet Entrance Daybeacon 5	10303	MISSING/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Hillsboro Inlet/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-13	2025- 04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 26.2564° N / 80.07888° W Aid Name: Hillsboro Inlet Entrance Light 2 LLNR: 10293 Discrepancy Information: Initial Report DTG: 132221Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.2564, Longitude: -80.07888]

## Hillsboro River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pompano Beach Light 76	47235	STRUCT DEST/HAZ NAV/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Moran Dock North Light	47175	LT IMCH	PA
Moran Dock Center Light	47180	LT IMCH	PA
Moran Dock South Light	47185	LT EXT	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Hillsboro Inlet - Hillsboro River/General/Bridges/Temp Deviation	General	Bridges	2024-10-29	2025-04-27	General/Bridges/Temp Deviation From: 2024-10-29 To: 2025-04-27 Location: 26.250268° N / 80.090035° W Bridge Name: NE 14th St Bridge The Florida Department of Transportation (FDOT) is authorized to temporarily deviate from drawbridge operation regulation 33 CFR 117.261(bb-2) that governs the NE 14th Street Drawbridge, mile 1055.0, and 33 CFR 117.261(bb-3) which governs the E. Atlantic Boulevard (SR 814) Drawbridge, mile 1056.0, across the Atlantic Intracoastal Waterway (AICW), at Pompano Beach, Florida. Under this temporary deviation, the NE 14th Street and the E. Atlantic Blvd Drawbridges need not open to navigation including tugs and tugs with tows, from 7:00 p.m. to 9:30 p.m. on Saturday November 9, 2024, to facilitate the City of Pompano Beach Veteran's Day Drone Show Extravaganza. Public vessels of the United States, vessels in distress, and vessels that may pass through the bridge without an opening may do so at any time. For waterways questions, please contact USCG Sector Miami Waterways Division	POINT [Latitude: 26.250268, Longitude: -80.090035]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	



# Hillsborough Cut A Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Big Bend Channel - Hillsborough Cut A Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.81356° N / 82.44441° W Aid Name: Hillsborough Cut A Channel Range Front Light LLNR: 23010 Discrepancy Information: Initial Report DTG: 151129Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 27.81356, Longitude: -82.44441]
Big Bend Channel - Hillsborough Cut A Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.82154° N / 82.42812° W Aid Name: Hillsborough Cut A Channel Range Rear Light LLNR: 23015 Discrepancy Information: Initial Report DTG: 231601Z OCT 2024 Summary: DBD DMGD Correction DTG: 231602Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.82154, Longitude: -82.42812]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Big Bend Channel - Hillsborough Cut A Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.81356° N / 82.44441° W Aid Name: Hillsborough Cut A Channel Range Front Light LLNR: 23010 Discrepancy Information: Initial Report DTG: 151129Z OCT 2024 Summary: DBD DMGD Correction DTG: 231654Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.81356, Longitude: -82.44441]
Big Bend Channel - Hillsborough Cut A Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-23	2025- 04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 27.82154° N / 82.42812° W Aid Name: Hillsborough Cut A Channel Range Rear Light LLNR: 23015 Discrepancy Information: Initial Report DTG: 231601Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 27.82154, Longitude: -82.42812]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Hillsborough Cut A Channel Range Front Light	23010	WATCHING PROPERLY	FD	2024-10-23
Hillsborough Cut A Channel Range Front Light	23010	WATCHING PROPERLY	FD	2024-10-23
Hillsborough Cut A Channel Range Rear Light	23015	WATCHING PROPERLY	FD	2024-10-23
Hillsborough Cut A Channel Range Rear Light	23015	WATCHING PROPERLY	FD	2024-10-23

## Hillsborough Cut C Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut C Channel Inbound Range Front Light	23435	LT EXT	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Yacht & Country Club Daybeacon 4	23454	STRUCT DEST	PA
Hookers Point North Warning Daybeacon	23515	STRUCT DEST/HAZ NAV	PA

## Hillsborough Cut D Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut D Channel Outbound Range Front Light	23500	LT IMCH	FD
Hillsborough Cut D Channel Outbound Range Rear Light	23505	LT EXT	FD

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Bulk Liquid Cargo Dolphin 4 Obstruction Light	23530	STRUCT DEST	PA

# Hillsborough River

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Hillsborough Cut C Channel - Hillsborough River/General/Bridges/Temp Deviation	General	Bridges	2024-10-30	2024-12-17	General/Bridges/Temp Deviation From: 2024-10-30 To: 2024-12-17 Location: 27.94174° N / 82.45855° W Bridge Name: Platt Street Bridge The City of Tampa is authorized to temporarily deviate from drawbridge operation regulation 33 CFR 117.291 (a) that governs the Platt Street Bridge, mile 0.0, and the Brorein Street Bridge, mile 0.16, across the Hillsborough River, at Tampa, Florida. Under this temporary deviation, the Platt Street and Brorein Street Bridges need not open to navigation including tugs and tugs with tows, during the following events: - November 2, 2024, from 6:30 a.m. to 10 a.m. to facilitate the Bolt Run. - November 3, 2024, from 8 a.m. to 11 a.m. to facilitate the Walk to End Alzheimer's. - November 9, 2024, from 10 a.m. to 5 p.m. to facilitate the Red Bull Flugtag. - November 23, 2024, from 4 a.m. to 11 a.m. to facilitate Miles for Moffitt. - November 28, 2024, from 6 a.m. to 9 a.m. to facilitate the YMCA Turkey Gobble. - December 15, 2024, from 7 a.m.	POINT [Latitude: 27.94174, Longitude: -82.45855]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>to 11 a.m. to facilitate the Hot Chocolate Runs. Public vessels of the United States and vessels in distress shall be passed as soon as safely possible. Vessels which can safely pass without an opening shall be passed at any time. For waterway questions please contact USCG Sector Saint Petersburg Waterways Management Division; telephone 727-824-7506, e-mail D07-SMB-Tampa-WWM@uscg.mil.</p>	

---





# Hollywood Beach

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.03767° N / 80.1166° W Ahtna Marine and Construction Company will be mechanically dredging approximately 12,000 cy of material from the North Cove area near Loggerhead Park at the Hollywood North Beach Park Mooring Fields. The material will be transported by barge approximately 2 nautical miles and offloaded at Berth 33 at Port Everglades. Operations are expected to begin on or around June 17, 2024, with an estimated completion date of October 31, 2024. Barges will be marked with flashing lights at night. Boaters are urged to maintain a safe distance from the barges to avoid potential interference with the hauling operations. Dredging will only take place on the North side of Sheridan Street. Mariners are urged to transit at their slowest safe speed to minimize wake and proceed with caution after arrangements have been made. Barges	POINT [Latitude: 26.03767, Longitude: -80.1166]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					will be monitoring VHF-FM channels 16 and 79. For further information contact: Ahtna Marine and Construction Company at (954) 568-0007.	
Port Everglades - Hollywood Beach/General Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.03806° N / 80.11733° W Continental Heavy Civil Corp. will be conducting dredging in the vicinity of West Lake Park Segment 4 along the FL ICW, approximately 1,600 feet South of Dania Boulevard Bridge. Dredging is anticipated to begin September 15, 2023, to July 15, 2025. There will be a 30 foot by 90 foot barge spud down and a 100 foot by 30 foot wide material barge moored on each side anchor lights will be marking the 4 corners. Four Buoys with Danger Keep out labels to be installed outlining the four corners of the mooring area. Buoy 1: 26-02-54.44N/080-07-02.33W Buoy 2: 26-02-55.15N/080-06-58.49W Buoy 3: 26-02-56.78N/080-06-59.21W Buoy 4: 26-02-56.31N/080-07-02.62W For further information contact: Jose Galicia, project manager jgalicia@chcivil.com.	POINT [Latitude: 26.03806, Longitude: -80.11733]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Port Everglades - Hollywood Beach/General/ Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.07538° N / 80.11411° W Continental Heavy Civil Corp. will be conducting marine construction, dredging, barge operations and pile driving in the ICW from 1,300 feet south of the Dania Beach Cutoff Channel to Sheridan Street west of the ICW. From 26-03- 37.17N/080-06- 53.74W to 26-03- 37.17N/080-06- 53.74W. Operations are expected to commence July 3, 2023 with an estimated completion date of July 3, 2025. Operations will be conducted Monday through Saturday 6 a.m. to 7 p.m. Navigation will not be impeded. Mariners are urged to proceed with caution while operating in the vicinity of the vessels. There will be multiple vessels onscene and they will be monitoring VHF-FM channel 69. For further information contact: Jose Galiccia, project manager jgalicia@chcivil.com	POINT [Latitude: 26.07538, Longitude: -80.11411]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025-04-18 Location: 26.05735° N / 80.11538° W Continental Heavy Civil Corp. will be Installing wood piles and rip-rap stone to protect mangroves and the shoreline from erosion. Land clearing and removal of invasive trees of the islands. Work is scheduled to commence February 5, 2024, Monday to Friday from 6 a.m. to 6 p.m. with an estimated completion date of July 1, 2025. Work will be done approximately 1,300 feet South of Dania Boulevard Bridge on the West side of the ICWW limits, adjacent to the West Lake Park Islands. Northern point of work: 26- 03-08.73N/80-06- 56.33W Southern point of work: 26- 02-55.31N/80-06- 57.51W For further information contact the project manager: Jose Galia at Jgalicia@chcivil.com.	POINT [Latitude: 26.05735, Longitude: -80.11538]

## Homosassa Bay

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Homosassa Bay Buoy 5	28373	OFF STATION	FD
Homosassa Bay Buoy 9	28383	OFF STATION	FD
Homosassa Bay Lighted Buoy 10	28385	OFF STATION	FD
Homosassa Bay Buoy 15	28397	OFF STATION	FD
Homosassa Bay Buoy 16	28400	OFF STATION	FD
Homosassa Bay Buoy 19	28410	OFF STATION	FD
Homosassa Bay Buoy 20	28415	OFF STATION	FD
Homosassa Bay Buoy 23	28423	OFF STATION	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.75671° N / 82.71797° W Aid Name: Homosassa Bay Buoy 19 LLNR: 28410 Discrepancy Information: Initial Report DTG: 041838Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.75671, Longitude: -82.71797]
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.76451° N / 82.71251° W Aid Name: Homosassa Bay Buoy 23 LLNR: 28423 Discrepancy Information: Initial Report DTG: 041840Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.76451, Longitude: -82.71251]
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.73168° N / 82.76001° W Aid Name: Homosassa Bay Buoy 5 LLNR: 28373 Discrepancy Information: Initial Report DTG: 041834Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.73168, Longitude: -82.76001]
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.74334° N / 82.74501° W Aid Name: Homosassa Bay Buoy 9 LLNR: 28383 Discrepancy Information: Initial Report DTG: 041835Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.74334, Longitude: -82.74501]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.75432° N / 82.72665° W Aid Name: Homosassa Bay Buoy 16 LLNR: 28400 Discrepancy Information: Initial Report DTG: 041837Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.75432, Longitude: -82.72665]
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.75501° N / 82.72717° W Aid Name: Homosassa Bay Buoy 15 LLNR: 28397 Discrepancy Information: Initial Report DTG: 041836Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.75501, Longitude: -82.72717]
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.75632° N / 82.71793° W Aid Name: Homosassa Bay Buoy 20 LLNR: 28415 Discrepancy Information: Initial Report DTG: 041839Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.75632, Longitude: -82.71793]
Homosassa Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.74536° N / 82.74068° W Aid Name: Homosassa Bay Lighted Buoy 10 LLNR: 28385 Discrepancy Information: Initial Report DTG: 041835Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.74536, Longitude: -82.74068]



## Homosassa River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Homosassa River Buoy 31	28445	OFF STATION	FD
Homosassa River Buoy 31	28445	MISSING	FD
Homosassa River Buoy 32	28450	OFF STATION	FD
Homosassa River Buoy 34	28460	OFF STATION	FD
Homosassa River Buoy 37	28475	MISSING	FD
Homosassa River Buoy 40	28490	MISSING	FD
Homosassa River Buoy 41	28495	MISSING	FD
Homosassa River Buoy 45A	28517	OFF STATION	FD
Homosassa River Buoy 45B	28519	OFF STATION	FD
Homosassa River Buoy 46	28520	OFF STATION	FD
Homosassa River Buoy 47	28525	OFF STATION	FD
Homosassa River Buoy 47A	28527	OFF STATION	FD
Homosassa River Buoy 54	28550	OFF STATION	FD
Homosassa River Buoy 55A	28557	OFF STATION	FD
Homosassa River Buoy 56	28560	OFF STATION	FD
Homosassa River Buoy 57	28565	OFF STATION	FD
Homosassa River Daybeacon 57A	28570	DBD DMGD	FD
Homosassa River Buoy 62	28595	OFF STATION	FD
Homosassa River Buoy 64	28610	MISSING	FD
Homosassa River Buoy 66	28620	MISSING	FD
Homosassa River Buoy 68	28625	OFF STATION	FD
Homosassa River Buoy 69	28630	OFF STATION	FD
Homosassa River Buoy 69A	28635	MISSING	FD
Homosassa River Buoy 70	28640	OFF STATION	FD
Homosassa River Buoy 71	28643	MISSING	FD
Homosassa River Buoy 72	28645	MISSING	FD

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Homosassa River Buoy 74A	28648	OFF STATION	FD
Homosassa River Buoy 74	28685	OFF STATION	FD
Homosassa River Buoy 81	28705	MISSING	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Homosassa River Daybeacon 2	28715	STRUCT DEST/HAZ NAV	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77135° N / 82.69733° W Aid Name: Homosassa River Buoy 31 LLNR: 28445 Discrepancy Information: Initial Report DTG: 041843Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77135, Longitude: -82.69733]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77101° N / 82.69419° W Aid Name: Homosassa River Buoy 37 LLNR: 28475 Discrepancy Information: Initial Report DTG: 041845Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.77101, Longitude: -82.69419]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.7703° N / 82.6916° W Aid Name: Homosassa River Buoy 40 LLNR: 28490 Discrepancy Information: Initial Report DTG: 041846Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.7703, Longitude: -82.6916]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77059° N / 82.69622° W Aid Name: Homosassa River Buoy 32 LLNR: 28450 Discrepancy Information: Initial Report DTG: 041842Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77059, Longitude: -82.69622]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77117° N / 82.68317° W Aid Name: Homosassa River Buoy 45A LLNR: 28517 Discrepancy Information: Initial Report DTG: 041847Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77117, Longitude: -82.68317]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78042° N / 82.64811° W Aid Name: Homosassa River Buoy 68 LLNR: 28625 Discrepancy Information: Initial Report DTG: 041859Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.78042, Longitude: -82.64811]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78032° N / 82.64672° W Aid Name: Homosassa River Buoy 69A LLNR: 28635 Discrepancy Information: Initial Report DTG: 041902Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.78032, Longitude: -82.64672]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78322° N / 82.64069° W Aid Name: Homosassa River Buoy 70 LLNR: 28640 Discrepancy Information: Initial Report DTG: 041903Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.78322, Longitude: -82.64069]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77099° N / 82.66812° W Aid Name: Homosassa River Buoy 54 LLNR: 28550 Discrepancy Information: Initial Report DTG: 041852Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77099, Longitude: -82.66812]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77305° N / 82.66474° W Aid Name: Homosassa River Buoy 56 LLNR: 28560 Discrepancy Information: Initial Report DTG: 041853Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77305, Longitude: -82.66474]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78418° N / 82.63999° W Aid Name: Homosassa River Buoy 71 LLNR: 28643 Discrepancy Information: Initial Report DTG: 041904Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.78418, Longitude: -82.63999]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78374° N / 82.63036° W Aid Name: Homosassa River Buoy 74A LLNR: 28648 Discrepancy Information: Initial Report DTG: 041908Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.78374, Longitude: -82.63036]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78304° N / 82.62365° W Aid Name: Homosassa River Buoy 81 LLNR: 28705 Discrepancy Information: Initial Report DTG: 041909Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.78304, Longitude: -82.62365]
Homosassa Bay - Homosassa River/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-03	2025-04-01	ATON/PATON Discrepancies From: 2024-10-03 To: 2025-04-01 Location: 28.78887° N / 82.61232° W Aid Name: Homosassa River Daybeacon 2 LLNR: 28715 Discrepancy Information: Initial Report DTG: 031604Z OCT 2024 Summary: STRUCT DEST/HAZ NAV	POINT [Latitude: 28.78887, Longitude: -82.61232]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77135° N / 82.69733° W Aid Name: Homosassa River Buoy 31 LLNR: 28445 Discrepancy Information: Initial Report DTG: 041840Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77135, Longitude: -82.69733]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77028° N / 82.69581° W Aid Name: Homosassa River Buoy 34 LLNR: 28460 Discrepancy Information: Initial Report DTG: 041843Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77028, Longitude: -82.69581]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.76999° N / 82.68926° W Aid Name: Homosassa River Buoy 41 LLNR: 28495 Discrepancy Information: Initial Report DTG: 041846Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.76999, Longitude: -82.68926]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77203° N / 82.68287° W Aid Name: Homosassa River Buoy 45B LLNR: 28519 Discrepancy Information: Initial Report DTG: 041848Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77203, Longitude: -82.68287]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77196° N / 82.68242° W Aid Name: Homosassa River Buoy 46 LLNR: 28520 Discrepancy Information: Initial Report DTG: 041849Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77196, Longitude: -82.68242]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77391° N / 82.67825° W Aid Name: Homosassa River Buoy 47 LLNR: 28525 Discrepancy Information: Initial Report DTG: 041850Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77391, Longitude: -82.67825]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77496° N / 82.6758° W Aid Name: Homosassa River Buoy 47A LLNR: 28527 Discrepancy Information: Initial Report DTG: 041851Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77496, Longitude: -82.6758]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77468° N / 82.66363° W Aid Name: Homosassa River Buoy 57 LLNR: 28565 Discrepancy Information: Initial Report DTG: 041854Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77468, Longitude: -82.66363]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.77287° N / 82.6651° W Aid Name: Homosassa River Buoy 55A LLNR: 28557 Discrepancy Information: Initial Report DTG: 041852Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.77287, Longitude: -82.6651]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.7751° N / 82.66189° W Aid Name: Homosassa River Daybeacon 57A LLNR: 28570 Discrepancy Information: Initial Report DTG: 041855Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 28.7751, Longitude: -82.66189]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78011° N / 82.6551° W Aid Name: Homosassa River Buoy 62 LLNR: 28595 Discrepancy Information: Initial Report DTG: 041856Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.78011, Longitude: -82.6551]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78189° N / 82.6505° W Aid Name: Homosassa River Buoy 64 LLNR: 28610 Discrepancy Information: Initial Report DTG: 041857Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.78189, Longitude: -82.6505]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78171° N / 82.64945° W Aid Name: Homosassa River Buoy 66 LLNR: 28620 Discrepancy Information: Initial Report DTG: 041859Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.78171, Longitude: -82.64945]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78032° N / 82.64727° W Aid Name: Homosassa River Buoy 69 LLNR: 28630 Discrepancy Information: Initial Report DTG: 041901Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.78032, Longitude: -82.64727]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-04	2025- 04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78577° N / 82.63719° W Aid Name: Homosassa River Buoy 72 LLNR: 28645 Discrepancy Information: Initial Report DTG: 041905Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.78577, Longitude: -82.63719]
Homosassa Bay - Homosassa River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-04	2025- 04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 28.78544° N / 82.63532° W Aid Name: Homosassa River Buoy 74 LLNR: 28685 Discrepancy Information: Initial Report DTG: 041907Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.78544, Longitude: -82.63532]

---

## Horseshoe Beach

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Horseshoe Beach Approach Daybeacon 4	30365	STRUCT MISSING/TRUB	FD
Horseshoe Beach Approach Daybeacon 4	30365	STRUCT DEST/TRUB	FD
Horseshoe Beach Approach Light 7	30375	STRUCT MISSING/TRLB	FD
Horseshoe Beach Approach Light 9	30380	STRUCT DEST/TRLB	FD
Horseshoe Beach Approach Light 9	30380	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Light 10	30385	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Daybeacon 12	30395	STRUCT MISSING/TRUB	FD
Horseshoe Beach Channel Daybeacon 12	30395	STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 13	30400	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 13	30400	STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 13	30400	MISSING/TRLB	FD
Horseshoe Beach Channel Daybeacon 14	30410	STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 14	30410	HAZ NAV/STRUCT DEST/TRUB	FD

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Horseshoe Beach Channel Daybeacon 14	30410	OFF STA/TRUB	FD
Horseshoe Beach Channel Light 16A	30425	STRUCT DEST/TRLB	FD
Horseshoe Beach Channel Light 16A	30425	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Daybeacon 21	30445	STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 21	30445	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 23	30450	STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 23	30450	STRUCT MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.43663° N / 83.29402° W Aid Name: Horseshoe Beach Channel Daybeacon 23 LLNR: 30450 Discrepancy Information: Initial Report DTG: 052141Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.43663, Longitude: -83.29402]
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.42256° N / 83.30144° W Aid Name: Horseshoe Beach Channel Daybeacon 13 LLNR: 30400 Discrepancy Information: Initial Report DTG: 052141Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.42256, Longitude: -83.30144]
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.43669° N / 83.29291° W Aid Name: Horseshoe Beach Channel Daybeacon 21 LLNR: 30445 Discrepancy Information: Initial Report DTG: 052143Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.43669, Longitude: -83.29291]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.42251° N / 83.30107° W Aid Name: Horseshoe Beach Channel Daybeacon 12 LLNR: 30395 Discrepancy Information: Initial Report DTG: 052150Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 052150Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.42251, Longitude: -83.30107]
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.40982° N / 83.30746° W Aid Name: Horseshoe Beach Approach Light 9 LLNR: 30380 Discrepancy Information: Initial Report DTG: 052152Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 052152Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.40982, Longitude: -83.30746]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.40306° N / 83.31505° W Aid Name: Horseshoe Beach Approach Light 7 LLNR: 30375 Discrepancy Information: Initial Report DTG: 052153Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 052153Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.40306, Longitude: -83.31505]
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.43531° N / 83.29215° W Aid Name: Horseshoe Beach Channel Light 16A LLNR: 30425 Discrepancy Information: Initial Report DTG: 052147Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 052147Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.43531, Longitude: -83.29215]
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.41624° N / 83.30544° W Aid Name: Horseshoe Beach Channel Light 10 LLNR: 30385 Discrepancy Information: Initial Report DTG: 052151Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 052151Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.41624, Longitude: -83.30544]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.39441° N / 83.32924° W Aid Name: Horseshoe Beach Approach Daybeacon 4 LLNR: 30365 Discrepancy Information: Initial Report DTG: 052153Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 052154Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.39441, Longitude: -83.32924]
Horseshoe Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 29.42894° N / 83.29658° W Aid Name: Horseshoe Beach Channel Daybeacon 14 LLNR: 30410 Discrepancy Information: Initial Report DTG: 052149Z OCT 2024 Summary: HAZ NAV/STRUCT DEST/TRUB Temporary Response DTG: 052149Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.42894, Longitude: -83.29658]



## Indian Key Pass

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Indian Key Pass Light 4	15980	LT EXT	FD
Indian Key Pass Daybeacon 13	16020	STRUCT DEST/TRUB	FD

## Indian River Lagoon

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Indian River (North Section) Daybeacon 23	41190	STRUCT DEST/TRUB/MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Indian River North Section - Indian River Lagoon/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-13	2025- 04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 28.64342° N / 80.80681° W Aid Name: Indian River (North Section) Daybeacon 23 LLNR: 41190 Discrepancy Information: Initial Report DTG: 131603Z OCT 2024 Summary: STRUCT DEST/TRUB/MISSING Temporary Response DTG: 131603Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.64342, Longitude: -80.80681]

## Indian River North Section

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River (North Section) Light 7	41130	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 34	41315	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 44	41415	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 71	42090	STRUCT DEST/TRUB/OFF STATION	FD
Indian River (North Section) Daybeacon 74	42105	DBD DEST	FD
Indian River (North Section) Daybeacon 81	42185	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 91	42270	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 94	42280	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jones Point Channel Buoy 1	41495	MISSING	PA
Jones Point Channel Buoy 2	41500	MISSING	PA
POW-MIA Channel Danger Daybeacon A	42254	DAYMK MISSING	PA
POW-MIA Channel Danger Daybeacon D	42254.3	DAYMK MISSING	PA
POW-MIA Channel Danger Daybeacon E	42254.4	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 1	42286	DAYMK DMGD	PA
Grills Riverside Marina Daybeacon 3	42286.2	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 4	42286.3	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 5	42286.4	HAZ NAV/DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Banana River - Indian River North Section/General Painting, Or Fender Replacement	General	Bridges	2024-10-29	2024-11-30	<p>General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-10-29 To: 2024-11-30</p> <p>Location: 28.206379° N / 80.650141° W</p> <p>Bridge Name: Pineda Causeway</p> <p>Oceanik.US has been contracted by the Florida Department of Transportation (FDOT) to conduct repairs to the SR 404 Pineda Causeway Bridge, across the Banana River, mile 5.0, at Satellite Beach, FL, and across the AICW, mile 908.6, at Palm Shores, FL.</p> <p>The project is scheduled to begin October 26, 2022, and end November 2024. The contractor will have floating construction equipment, small work platforms and support vessels, in and around the bridge structure.</p> <p>All in-water equipment is required to be lighted at night and located outside of the navigational channel during non-working hours. All boaters are advised to transit the area with caution and at a slow speed. For waterways related questions, contact Coast Guard Sector Jacksonville Waterways Management Division at (904) 714-7631 or via email at D07-DG-SECJAX-WATERWAYS@uscg.mil.</p>	POINT [Latitude: 28.206379, Longitude: -80.650141]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 28.37574° N / 80.72602° W Aid Name: Indian River (North Section) Light 73 LLNR: 42100 Discrepancy Information: Initial Report DTG: 052202Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 28.37574, Longitude: -80.72602]
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 28.32932° N / 80.70572° W Aid Name: Indian River (North Section) Daybeacon 79 LLNR: 42175 Discrepancy Information: Initial Report DTG: 052207Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 28.32932, Longitude: -80.70572]
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-13	2025-04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 28.69893° N / 80.79737° W Aid Name: Indian River (North Section) Light 7 LLNR: 41130 Discrepancy Information: Initial Report DTG: 131515Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 161355Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.69893, Longitude: -80.79737]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-13	2025-04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 28.31395° N / 80.69824° W Aid Name: Indian River (North Section) Light 83 LLNR: 42190 Discrepancy Information: Initial Report DTG: 131515Z OCT 2024 Summary: LT EXT	POINT [Latitude: 28.31395, Longitude: -80.69824]
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 28.37554° N / 80.72678° W Aid Name: Indian River (North Section) Daybeacon 74 LLNR: 42105 Discrepancy Information: Initial Report DTG: 052200Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.37554, Longitude: -80.72678]
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 28.54506° N / 80.76944° W Aid Name: Indian River (North Section) Light 41 LLNR: 41400 Discrepancy Information: Initial Report DTG: 052201Z OCT 2024 Summary: LT EXT	POINT [Latitude: 28.54506, Longitude: -80.76944]
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 28.47887° N / 80.754° W Aid Name: Indian River (North Section) Light 55 LLNR: 41485 Discrepancy Information: Initial Report DTG: 052201Z OCT 2024 Summary: LT EXT	POINT [Latitude: 28.47887, Longitude: -80.754]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-13	2025-04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 28.3913° N / 80.73096° W Aid Name: Indian River (North Section) Daybeacon 71 LLNR: 42090 Discrepancy Information: Initial Report DTG: 131605Z OCT 2024 Summary: STRUCT DEST/TRUB/OFF STATION Temporary Response DTG: 131605Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.3913, Longitude: -80.73096]
Banana River - Indian River North Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-16	2025-04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 28.59151° N / 80.79032° W Aid Name: Indian River (North Section) Daybeacon 34 LLNR: 41315 Discrepancy Information: Initial Report DTG: 161404Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 161404Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.59151, Longitude: -80.79032]

## Indian River South Section

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River (South Section) Daybeacon 17	43290	DAYMK MISSING	FD
Indian River (South Section) Daybeacon 32	43415	STRUCT DEST/TRUB	FD
Indian River (South Section) Light 53	43520	STRUCT DEST/TRLB	FD
Indian River (South Section) Light 112	43920	DAYMK DMGD	FD
Indian River (South Section) Daybeacon 132	44150	STRUCT DEST	FD
Indian River (South Section) Daybeacon 144	44385	STRUCT DEST	FD
Indian River (South Section) Daybeacon 170	44830	STRUCT DMGD	FD
Indian River (South Section) Light 187	45115	STRUCT DEST/TRLB	FD
Indian River (South Section) Light 209	45375	DBD DEST	FD
Indian River (South Section) Daybeacon 219	45475	DBD DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turkey Creek Daybeacon 22	43272.2	STRUCT DEST	PA
River Run Daybeacon 5	43720	DAYMK MISSING	PA
Queens Cove Daybeacon 10	44945	STRUCT DEST/HAZ NAV	PA
Rigels Cove Channel Daybeacon 7	45615	DAYMK IMCH	PA
Outrigger Harbour Daybeacon 1	45710	STRUCT DEST	PA
Indian River Plantation Marina Channel Daybeacon 1	45820	STRUCT DEST/HAZ NAV	PA
Ind River Plantation Marina Channel Daybeacon 2	45825	STRUCT DMGD	PA
Breakwater Danger Daybeacon A	45863	DAYMK MISSING	PA
Breakwater Danger Daybeacon B	45863.1	DAYMK MISSING	PA



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Repairs, Painting, Or Fender Replacement	General	Bridges	2024-10-29	2028-01-31	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-10-29 To: 2028-01-31 Location: 27.632319° N / 80.371113° W Bridge Name: 17th St Bridge Vecellio Grogan, on behalf of the bridge owner, Florida Department of Transportation, will be conducting bridge repairs on the 17th street (SR 656) Bridge over the AICW (Indian River) mile marker 952.9 at Vero Beach, FL beginning November 13, 2023, with an estimated completion during January 2028. The project will remove and replace 400 feet of the eastern portion of the bridge beginning with the north section before continuing with the south section. The contractor will utilize in water equipment which will remain on site, all vessels are advised to transit the area with caution. For further information, contact: Kyle Tatum at (407) 361-6506. For waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil.	POINT [Latitude: 27.632319, Longitude: -80.371113]
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Conversion	General	Bridges	2024-10-29	2025-04-27	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 27.47199° N / 80.32452° W	POINT [Latitude: 27.47199, Longitude: -80.32452]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>Bridge Name: A1A State Route Bridge Vecellio &amp; Grogan, Inc. ("V&amp;G"), on behalf of the bridge owner, FDOT, are conducting construction operations for the replacement of the A1A North Causeway Drawbridge across the AICW, mile 964.8, at Ft. Pierce, FL. A temporary work trestle (platform) has been installed on the northeast side of the existing A1A North Causeway Bridge. In water work will continue directly adjacent to, and at times partially restrict, the navigable waterway with barge(s) in order to perform maintenance work on the bascules of the existing bridge and perform other associated construction activities until September 2027. At least 45 feet width of the channel shall remain open at all times. Vessels needing a full channel passage are required to provide the bridge tender with a 30-minute advance notice to allow for the barge to clear the channel. During the evening/overnight hours the channel will be unobstructed. All in-water equipment is required to be properly lighted. All mariners are requested to use caution and transit the area at a slow speed. For</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					waterways questions or drawbridge operating issues, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.74343° N / 80.40037° W Aid Name: Indian River (South Section) Light 96 LLNR: 43860 Discrepancy Information: Initial Report DTG: 120034Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.74343, Longitude: -80.40037]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.62373° N / 80.36859° W Aid Name: Indian River (South Section) Daybeacon 149 LLNR: 44480 Discrepancy Information: Initial Report DTG: 120026Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 27.62373, Longitude: -80.36859]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.61876° N / 80.36635° W Aid Name: Indian River (South Section) Daybeacon 151 LLNR: 44490 Discrepancy Information: Initial Report DTG: 120029Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.61876, Longitude: -80.36635]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-10	2025-04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 27.32152° N / 80.25571° W Aid Name: Indian River (South Section) Light 209 LLNR: 45375 Discrepancy Information: Initial Report DTG: 102316Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.32152, Longitude: -80.25571]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.54961° N / 80.34625° W Aid Name: Indian River (South Section) Daybeacon 170 LLNR: 44830 Discrepancy Information: Initial Report DTG: 120033Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.54961, Longitude: -80.34625]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-10	2025-04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 27.26077° N / 80.2228° W Aid Name: Indian River (South Section) Daybeacon 219 LLNR: 45475 Discrepancy Information: Initial Report DTG: 102317Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.26077, Longitude: -80.2228]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.64153° N / 80.37228° W Aid Name: Indian River (South Section) Daybeacon 144 LLNR: 44385 Discrepancy Information: Initial Report DTG: 120024Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.64153, Longitude: -80.37228]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.58421° N / 80.35433° W Aid Name: Indian River (South Section) Daybeacon 160 LLNR: 44595 Discrepancy Information: Initial Report DTG: 120031Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.58421, Longitude: -80.35433]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 27.89833° N / 80.50122° W Aid Name: Indian River (South Section) Daybeacon 52 LLNR: 43510 Discrepancy Information: Initial Report DTG: 121918Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.89833, Longitude: -80.50122]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.89833° N / 80.50122° W Aid Name: Indian River (South Section) Daybeacon 52 LLNR: 43510 Discrepancy Information: Initial Report DTG: 121918Z OCT 2024 Summary: DBD DEST Correction DTG: 232044Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.89833, Longitude: -80.50122]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.87748° N / 80.48861° W Aid Name: Indian River (South Section) Daybeacon 55 LLNR: 43535 Discrepancy Information: Initial Report DTG: 232045Z OCT 2024 Summary: DBD DEST Correction DTG: 232046Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.87748, Longitude: -80.48861]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-23	2025-04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 27.94673° N / 80.52672° W Aid Name: Indian River (South Section) Daybeacon 32 LLNR: 43415 Discrepancy Information: Initial Report DTG: 232042Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 012100Z NOV 2024 Temporary Response: TUB	POINT [Latitude: 27.94673, Longitude: -80.52672]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-23	2025-04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 27.87748° N / 80.48861° W Aid Name: Indian River (South Section) Daybeacon 55 LLNR: 43535 Discrepancy Information: Initial Report DTG: 232045Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.87748, Longitude: -80.48861]
Fort Pierce Inlet Inner Harbor - Indian River South Section/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.74343° N / 80.40037° W Aid Name: Indian River (South Section) Light 96 LLNR: 43860 Discrepancy Information: Initial Report DTG: 120034Z OCT 2024 Summary: DBD DEST Correction DTG: 232047Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.74343, Longitude: -80.40037]





## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Indian River (South Section) Daybeacon 52	43510	WATCHING PROPERLY	FD	2024-10-23
Indian River (South Section) Daybeacon 52	43510	WATCHING PROPERLY	FD	2024-10-23
Indian River (South Section) Daybeacon 55	43535	WATCHING PROPERLY	FD	2024-10-23
Indian River (South Section) Daybeacon 55	43535	WATCHING PROPERLY	FD	2024-10-23
Indian River (South Section) Light 96	43860	WATCHING PROPERLY	FD	2024-10-23
Indian River (South Section) Light 96	43860	WATCHING PROPERLY	FD	2024-10-23

## Intracoastal Waterway Florida Seventh District

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Okeechobee (Rt 2) Daybeacon 13	51445	STRUCT MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Lake Okeechobee Route 2 - Intracoastal Waterway Florida Seventh District/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-30	2025-04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.95714° N / 80.61231° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 13 LLNR: 51445 Discrepancy Information: Initial Report DTG: 310019Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 26.95714, Longitude: -80.61231]



# Isla De Vieques

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Isla De Vieques/General To Navigation/Hazards	General Hazards	Hazards To Navigation	2024-09-26	2025-03-25	<p>The U.S. NAVY is advising all mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to Punta Este and on the Southeast on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041.</p> <p>For more information, contact Mrs. Maria Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.</p>	<p>POLYGON            [Latitude: 18.15206,            Longitude: -65.28248]            [Latitude: 18.12971,            Longitude: -65.25605]            [Latitude: 18.11927,            Longitude: -65.31064]            [Latitude: 18.15092,            Longitude: -65.33244]            [Latitude: 18.15206,            Longitude: -65.28248]</p>

## Isla Magueyes

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Isla De Mona Light	32295	LT EXT/STRUCT DMGD	FD

## Jekyll Creek

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Jekyll Creek Jetty Warning Daybeacon 8	37305	DAYMK MISSING	FD
Jekyll Creek Light 20A	37346	STRUCT DEST/TRLB	FD
Jekyll Creek Light 20A	37346	STRUCT DEST	FD
Jekyll Creek Light 29	37370	STRUCT DEST/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Satilla River - Jekyll Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 31.05165° N / 81.42334° W Aid Name: Jekyll Creek Light 20A LLNR: 37346 Discrepancy Information: Initial Report DTG: 021740Z OCT 2024 Summary: STRUCT DEST/TRLB Temporary Response DTG: 021740Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 31.05165, Longitude: -81.42334]

## Johns Pass Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johns Pass Channel Daybeacon 1	25580	STRUCT DEST/TRUB	FD
Johns Pass Channel Daybeacon 1	25580	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Treasure Island North Terminal Groin Obstruction Light	25600.01	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.79961° N / 82.77694° W Aid Name: Johns Pass Channel Daybeacon 14 LLNR: 25645 Discrepancy Information: Initial Report DTG: 011707Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.79961, Longitude: -82.77694]
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.77549° N / 82.79318° W Aid Name: Johns Pass Channel Light 2 LLNR: 25585 Discrepancy Information: Initial Report DTG: 011715Z OCT 2024 Summary: DBD DEST/LT EXT	POINT [Latitude: 27.77549, Longitude: -82.79318]
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.77862° N / 82.78666° W Aid Name: Johns Pass Channel Light 4 LLNR: 25600 Discrepancy Information: Initial Report DTG: 011710Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 27.77862, Longitude: -82.78666]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.79546° N / 82.77857° W Aid Name: Johns Pass Channel Light 10 LLNR: 25630 Discrepancy Information: Initial Report DTG: 011709Z OCT 2024 Summary: DBD DEST/HAZ NAV/LT EXT	POINT [Latitude: 27.79546, Longitude: -82.77857]
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.7759° N / 82.788° W Aid Name: Johns Pass Channel Lighted Buoy 2A LLNR: 25585.2 Discrepancy Information: Initial Report DTG: 011713Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.7759, Longitude: -82.788]
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.77702° N / 82.79481° W Aid Name: Johns Pass Channel Daybeacon 1 LLNR: 25580 Discrepancy Information: Initial Report DTG: 041245Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 041246Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 27.77702, Longitude: -82.79481]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Johns Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.77926° N / 82.78727° W Aid Name: Johns Pass Channel Buoy 5 LLNR: 25610 Discrepancy Information: Initial Report DTG: 011711Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.77926, Longitude: -82.78727]
Johns Pass Channel/ATON/PATON Discrepancies	PATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.78044° N / 82.78372° W Aid Name: Treasure Island North Terminal Groin Obstruction Light LLNR: 25600.01 Discrepancy Information: Initial Report DTG: 302206Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.78044, Longitude: -82.78372]

## Jones Island Range

### Temporary Changes

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Jones Island Range Lighted Bell Buoy 17	4640	RELOCATED FOR DREDGING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Jones Island Range/ATON/Temporary Changes	ATON	Temporary Changes	2024- 10-23	2025- 04-21	ATON/Temporary Changes From: 2024-10-23 To: 2025-04-21 Location: 32.0367° N / 80.84193° W Aid Name: Jones Island Range Lighted Bell Buoy 17 LLNR: 4640 Temporary Aid Change Information: Status: RELOCATED FOR DREDGING Old Latitude: 32-02- 12.121N New Latitude: 32-02- 10.943N Old Longitude: 080-50- 30.945W New Longitude: 080-50- 30.965W	POINT [Latitude: 32.0367, Longitude: -80.84193]

## Jug Creek Shoal

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Jug Creek Shoal Daybeacon 9	56375	STRUCT DEST/TRUB	FD

# Jupiter Inlet

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Jupiter Inlet/General/Bridges/Conversion	General	Bridges	2024-10-29	2024-12-31	<p>General/Bridges/Conversion            From: 2024-10-29            To: 2024-12-31            Location:            26.947554° N /            80.084948° W            Bridge Name: Hwy            1 Jupiter Federal            Bridge Johnson            Brothers Corp, on            behalf of Florida            Department of            Transportation            (FDOT) will begin            construction            activities for the            replacement of the            US1 Jupiter Federal            Bridge across the            Atlantic            Intracoastal            Waterway mile            1004.8, Jupiter.            The old US1 /            Jupiter Federal            Bridge with            existing bascule            piers has been            removed, but            equipment will            continue to be            present in the            vicinity of            construction of the            new bridge            through the end of            2024. All vessels            are advised to            transit the area            with caution.            Please notify Clay            Bores (407)-488-            0738 for concerns,            or for waterways            questions or issues,            call or e-mail Coast            Guard Sector            Miami, FL,            Waterways            Management            Division, telephone            305-535-4317,            email            SectorMiamiWaterways@uscg.mil.</p>	POINT [Latitude: 26.947554, Longitude: -80.084948]

## Keaton Beach

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Keaton Beach Daybeacon 2	30600	HAZ NAV/STRUCT DEST/TRLB	FD
Keaton Beach Light 5	30620	STRUCT MISSING/TRLB	FD
Keaton Beach Light 11	30640	STRUCT DEST/TRLB	FD
Keaton Beach Daybeacon 18	30675	STRUCT DEST/HAZ NAV/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Keaton Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 29.81428° N / 83.62259° W Aid Name: Keaton Beach Daybeacon 2 LLNR: 30600 Discrepancy Information: Initial Report DTG: 041620Z OCT 2024 Summary: HAZ NAV/STRUCT DEST/TRLB Temporary Response DTG: 041620Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.81428, Longitude: -83.62259]
Keaton Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 29.81592° N / 83.6099° W Aid Name: Keaton Beach Light 5 LLNR: 30620 Discrepancy Information: Initial Report DTG: 041622Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 041622Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.81592, Longitude: -83.6099]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Keaton Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 29.81478° N / 83.59691° W Aid Name: Keaton Beach Light 11 LLNR: 30640 Discrepancy Information: Initial Report DTG: 041625Z OCT 2024 Summary: STRUCT DEST/TRLB Temporary Response DTG: 041625Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.81478, Longitude: -83.59691]

## Key Biscayne Yacht Club

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Key Biscayne Yacht Club Light 4	49085	DAYMK MISSING	PA

## Kings Bay

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Bay Light 48	7000	STRUCT DEST/TRLB	FD
Kings Bay Light 50	7005	STRUCT DEST	FD
Kings Bay Light 52	7010	STRUCT DEST	FD
Kings Bay Light 53	7015	STRUCT DMGD	FD
Kings Bay Light 54	7020	STRUCT DEST	FD
Kings Bay Light 56	7025	STRUCT DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Kings Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 30.76779° N / 81.48257° W Aid Name: Kings Bay Lower Range E Rear Light LLNR: 6940 Discrepancy Information: Initial Report DTG: 120107Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 30.76779, Longitude: -81.48257]

## Lake Boca Raton

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Mile Daybeacon 1	47151	STRUCT DEST	PA
Hillsboro Mile Daybeacon 3	47152	STRUCT DEST	PA
Hillsboro Mile Daybeacon 7	47153	STRUCT DEST	PA

## Lake George

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Silver Glen Springs Run Buoy 1	8595	MISSING	PA
Silver Glen Springs Run Buoy 24	8695	MISSING	PA
Silver Glen Springs Run Buoy 25	8700	OFF STA	PA
Silver Glen Springs Run Buoy 2A	8715	SINKING/BUOY DMGD	PA
Silver Glen Springs Run Buoy 9A	8740	MISSING	PA
Silver Glen Springs Run Pref Buoy A	8750	MISSING	PA

## Lake Monroe

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Monroe Bar Light 1	9240	STRUCT DEST/HAZ NAV/TRLB	FD

# Lake Okeechobee Route 1

## Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Lake Okeechobee (Rt 1) Daybeacon 3	51195	DBD DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Lake Okeechobee Route 2 - Lake Okeechobee Route 1/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.98286° N / 80.62649° W Aid Name: Lake Okeechobee (Rt 1) Daybeacon 3 LLNR: 51195 Discrepancy Information: Initial Report DTG: 121919Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.98286, Longitude: -80.62649]

## Lake Okeechobee Route 2

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Lake Okeechobee (Rt 2) Daybeacon 6	51425	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 12	51440	DAYMK IMCH	FD
Lake Okeechobee (Rt 2) Daybeacon 14	51450	DAYMK IMCH	FD
Lake Okeechobee (Rt 2) Daybeacon 16	51455	DAYMK IMCH	FD
Lake Okeechobee (Rt 2) Daybeacon 20	51470	DAYMK IMCH	FD
Lake Okeechobee (Rt 2) Daybeacon 22	51480	DAYMK IMCH	FD
Lake Okeechobee (Rt 2) Daybeacon 23	51485	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 24	51490	DAYMK IMCH	FD
Lake Okeechobee (Rt 2) Daybeacon 28	51510	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 30	51520	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 35	51540	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 36	51545	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 40	51560	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 42	51570	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 46	51575	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 67	51680	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 70	51695	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 74	51710	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 80	51770	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 91	51800	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 94	51820	DBD DEST	FD
Lake Okeechobee (Rt 2) Daybeacon 94	51820	DBD DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-12	2025- 04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.97218° N / 80.615° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 6 LLNR: 51425 Discrepancy Information: Initial Report DTG: 121920Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.97218, Longitude: -80.615]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-12	2025- 04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.91699° N / 80.61645° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 23 LLNR: 51485 Discrepancy Information: Initial Report DTG: 121921Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.91699, Longitude: -80.61645]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-12	2025- 04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.72119° N / 80.84232° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 94 LLNR: 51820 Discrepancy Information: Initial Report DTG: 121921Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.72119, Longitude: -80.84232]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 26.91341° N / 80.61704° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 24 LLNR: 51490 Discrepancy Information: Initial Report DTG: 311551Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 26.91341, Longitude: -80.61704]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 26.94854° N / 80.6136° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 16 LLNR: 51455 Discrepancy Information: Initial Report DTG: 311549Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 26.94854, Longitude: -80.6136]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 26.9366° N / 80.61493° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 20 LLNR: 51470 Discrepancy Information: Initial Report DTG: 311550Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 26.9366, Longitude: -80.61493]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 26.95651° N / 80.61315° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 14 LLNR: 51450 Discrepancy Information: Initial Report DTG: 311547Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 26.95651, Longitude: -80.61315]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 26.96024° N / 80.61291° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 12 LLNR: 51440 Discrepancy Information: Initial Report DTG: 311549Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 26.96024, Longitude: -80.61291]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 26.92559° N / 80.6162° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 22 LLNR: 51480 Discrepancy Information: Initial Report DTG: 311550Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 26.92559, Longitude: -80.6162]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.72119° N / 80.84232° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 94 LLNR: 51820 Discrepancy Information: Initial Report DTG: 310034Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.72119, Longitude: -80.84232]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.90194° N / 80.61516° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 28 LLNR: 51510 Discrepancy Information: Initial Report DTG: 310025Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.90194, Longitude: -80.61516]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.88254° N / 80.62269° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 36 LLNR: 51545 Discrepancy Information: Initial Report DTG: 310027Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.88254, Longitude: -80.62269]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.89711° N / 80.61559° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 30 LLNR: 51520 Discrepancy Information: Initial Report DTG: 310025Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.89711, Longitude: -80.61559]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.87279° N / 80.62967° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 40 LLNR: 51560 Discrepancy Information: Initial Report DTG: 310027Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.87279, Longitude: -80.62967]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.86874° N / 80.63249° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 42 LLNR: 51570 Discrepancy Information: Initial Report DTG: 310028Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.86874, Longitude: -80.63249]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.81997° N / 80.67904° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 67 LLNR: 51680 Discrepancy Information: Initial Report DTG: 310030Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.81997, Longitude: -80.67904]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.88417° N / 80.62052° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 35 LLNR: 51540 Discrepancy Information: Initial Report DTG: 310026Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.88417, Longitude: -80.62052]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.86119° N / 80.63802° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 46 LLNR: 51575 Discrepancy Information: Initial Report DTG: 310030Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.86119, Longitude: -80.63802]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.81473° N / 80.68876° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 70 LLNR: 51695 Discrepancy Information: Initial Report DTG: 310031Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.81473, Longitude: -80.68876]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.80576° N / 80.69764° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 74 LLNR: 51710 Discrepancy Information: Initial Report DTG: 310032Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.80576, Longitude: -80.69764]
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.79118° N / 80.69794° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 80 LLNR: 51770 Discrepancy Information: Initial Report DTG: 310033Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.79118, Longitude: -80.69794]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Canal - Lake Okeechobee Route 2/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 26.75184° N / 80.68425° W Aid Name: Lake Okeechobee (Rt 2) Daybeacon 91 LLNR: 51800 Discrepancy Information: Initial Report DTG: 310033Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.75184, Longitude: -80.68425]

---

## Lake Worth Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth Creek Daybeacon 7	46375	STRUCT DEST/TRUB	FD
Lake Worth Creek Light 25	46430	STRUCT DMGD/TRLB	FD

## Lake Worth Inlet

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth Inlet Light 13	10255	LT IMCH	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Lake Worth Inlet/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-10	2025- 04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 26.76535° N / 80.04653° W Aid Name: Lake Worth Inlet Light 13 LLNR: 10255 Discrepancy Information: Initial Report DTG: 102004Z OCT 2024 Summary: LT IMCH	POINT [Latitude: 26.76535, Longitude: -80.04653]

## Lake Worth Inlet Hillsboro Inlet

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Delray Beach Shoal Buoy	47113	MISSING	FD

## Lake Worth North

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Lake Worth North Daybeacon 37	46605	STRUCT DEST/TRUB	FD
Lake Worth North Daybeacon 37	46605	DBD DEST	FD
Lake Worth North Daybeacon 41	46700	STRUCT DEST/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Lake Worth North/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.78601° N / 80.04528° W Aid Name: Lake Worth North Daybeacon 37 LLNR: 46605 Discrepancy Information: Initial Report DTG: 121427Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.78601, Longitude: -80.04528]
Lake Worth North/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-24	2025-04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 26.77473° N / 80.04881° W Aid Name: Lake Worth North Daybeacon 41 LLNR: 46700 Discrepancy Information: Initial Report DTG: 241709Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 251950Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 26.77473, Longitude: -80.04881]

## Lake Worth South

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Lake Worth South Daybeacon 3	46730	STRUCT DEST/TRUB	FD
Lake Worth South Daybeacon 4	46740	STRUCT DEST/TRLB	FD
Lake Worth South Light 29	46945	STRUCT DEST/TRLB	FD
Lake Worth South Daybeacon 34	46965	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Light 49	47085	STRUCT DEST/TRLB	FD
Lake Worth South Daybeacon 51	47090	STRUCT DEST/TRLB/HAZ NAV	FD
Delray Beach Daybeacon 52A	47105	STRUCT DEST/TRUB	FD

### Temporary Changes

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Lake Worth South Daybeacon 14	46880	TRLT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Lake Worth North/General/MSIB	General	MSIB	2024- 09-26	2025- 03-25	There are three temporary security zones in the vicinity of the Mar-a-Lago Resort in Palm Beach, Florida from August 19, 2024 until November 30, 2024. The west zone will consist of waters of Lake Worth Lagoon from surface to bottom including the Intracoastal Waterway from the southern tip of Everglades Island to approximately 1000 yards south of the Southern Boulevard Bridge and from the western shoreline to Fisherman Island. All vessels transiting the west zone shall maintain a steady speed and shall not slow or stop in the zone. The center zone will consist of waters of Lake Worth Lagoon from surface to bottom, starting from the southern tip of Everglades Island to approximately 1000 yards south of the Southern Boulevard Bridge and the eastern shoreline out to Fisherman Island. No vessel or person will be permitted to enter the center zone without obtaining permission from the Coast Guard or a designated representative. The east zone will consist of waters of the Atlantic Ocean from surface to bottom, from Banyan Road in the north to Ocean View Road in the	POLYGON [Latitude: 26.78854, Longitude: -80.03875] [Latitude: 26.66772, Longitude: -80.03704] [Latitude: 26.66741, Longitude: -80.05317] [Latitude: 26.787, Longitude: -80.05214] [Latitude: 26.78854, Longitude: -80.03875]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					south and from shore to approximately 1000 yards east. All vessels transiting the east zone shall maintain a steady speed and shall not slow or stop in the zone. For further information contact: the Captain of the Port Miami (305) 535-4313 or VHF-FM channel 16.	
Lake Worth Inlet - Lake Worth South/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-28	2025-04-26	ATON/Federal Discrepancies From: 2024-10-28 To: 2025-04-26 Location: 26.7597° N / 80.04856° W Aid Name: Lake Worth South Daybeacon 3 LLNR: 46730 Discrepancy Information: Initial Report DTG: 281502Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 282135Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 26.7597, Longitude: -80.04856]
Lake Worth Inlet - Lake Worth South/General/Bridges/Temp Deviation	General	Bridges	2024-10-29	2025-04-27	General/Bridges/Temp Deviation From: 2024-10-29 To: 2025-04-27 Location: 26.70595° N / 80.04641° W Bridge Name: Royal Park Westbound Bridge The U. S. Coast Guard has issued a temporary deviation to drawbridge operation regulation, 33 CFR §117.261(v) that governs the Royal Park (SR 704) Bridge, across Atlantic Intracoastal Waterway (AICW), mile 1022.6, at West Palm Beach, Florida. Under this temporary deviation, the Royal Park Bridge will	POINT [Latitude: 26.70595, Longitude: -80.04641]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>operate as follows:            (1) The draw will open on the hour and half hour, except that Monday through Friday (except Federal holidays) from 7:30 a.m. to 9:00 a.m. and from 4:00 p.m. to 6:00 p.m., the draw need only open on the half-hour. (2) When the security zone is enforced, the draw shall operate as follows:            (i) Monday through Friday (except on Federal holidays)            (A) 7:30 a.m. to 9:00 a.m., the draw need only open on the half-hour. (B) 9:00 a.m. to 2:15 p.m., the draw need only open on the hour and half-hour. (C) 2:15 p.m. to 6:00 p.m., the draw need only open on the half-hour. (D) 6:00 p.m. to 7:30 a.m., the draw need only open on the hour and half-hour. (ii) Saturday, Sunday, and Federal holidays the draw need only open on the hour and half hour. This temporary deviation is effective from 8:00 p.m. on August 19, 2024, through 11:59 p.m. on November 30, 2024. This action is necessary to allow for continuity in drawbridge operations with adjacent drawbridges during federal rulemaking and during Coast Guard enforcement of the security zone. For further information contact Coast Guard Sector Miami, FL, Waterways</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					Management Division, (305) 535-4317, SectorMiamiWaterways@uscg.mil	
Lake Worth Inlet - Lake Worth South/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 26.53722° N / 80.05109° W Aid Name: Lake Worth South Daybeacon 51 LLNR: 47090 Discrepancy Information: Initial Report DTG: 211018Z OCT 2024 Summary: STRUCT DEST/TRLB/HAZ NAV Temporary Response DTG: 222030Z OCT 2024 Temporary Response: TLB Location: 26-32-14.022N / 080-03-04.148W.	POINT [Latitude: 26.53722, Longitude: -80.05109]
Lake Worth Inlet - Lake Worth South/General/Bridges/Temp Deviation	General	Bridges	2024-10-29	2024-12-01	General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-12-01 Location: 26.71807° N / 80.04704° W Bridge Name: Flagler Memorial Westbound Bridge The U. S. Coast Guard has issued a temporary deviation to drawbridge operation regulation, 33 CFR §117.261(u) that governs the Flagler Memorial Bridge, across Atlantic Intracoastal Waterway (AICW), mile 1021.8, at West Palm Beach, Florida. Under this temporary deviation, the Flagler Memorial Bridge will operate as follows: (1) The draw will open on the quarter and three-quarter hour, except that Monday through Friday (except	POINT [Latitude: 26.71807, Longitude: -80.04704]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>Federal holidays) from 7:30 a.m. to 9:00 a.m. and from 4:00 p.m. to 6:00 p.m., the draw need only open on the quarter hour. (2) When the security zone is enforced, the draw shall operate as follows: (i) Monday through Friday (except on Federal holidays) (A) 7:30 a.m. to 9:00 a.m., the draw need only open on the quarter hour. (B) 9:00 a.m. to 2:15 p.m., the draw need only open on the quarter and three-quarter hour. (C) 2:15 p.m. to 6:00 p.m., the draw need only open on the quarter hour. (D) 6:00 p.m. to 7:30 a.m., the draw need only open on the quarter and three-quarter hour. (ii) Saturday, Sunday, and Federal holidays the draw need only open on the quarter and three-quarter hour. This temporary deviation is effective from 8:00 p.m. on August 19, 2024, through 11:59 p.m. on November 30, 2024. This action is necessary to allow for continuity in drawbridge operations with adjacent drawbridges during federal rulemaking and during Coast Guard enforcement of the security zone. For further information contact Coast Guard Sector Miami, FL, Waterways Management Division, (305)</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					535-4317, SectorMiamiWaterways@uscg.mil	
Lake Worth Inlet - Lake Worth South/General/Bridges/Temp Deviation	General	Bridges	2024-10-29	2024-12-01	General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-12-01 Location: 26.67542° N / 80.04684° W Bridge Name: Southern Boulevard Bridge The U. S. Coast Guard has issued a temporary deviation to drawbridge operation regulation, 33 CFR §117.261(w) that governs the Southern Boulevard (SR 700/80) Bridge, across the AICW, mile 1024.7, at West Palm Beach, Florida. Under this temporary deviation, the Southern Boulevard Bridge will operate as follows: (1) The draw will open on the quarter and three-quarter hour, except that Monday through Friday (except Federal holidays) from 7:30 a.m. to 9:00 a.m. and from 4:00 p.m. to 6:00 p.m., the draw need only open on the quarter hour. (2) When the security zone is enforced, the draw may be closed without advance notice to permit uninterrupted transit of dignitaries across the bridge. Unless otherwise directed by the onscene designated representative, the draw will operate as follows: (i) Monday through Friday (except on Federal holidays) (A) 7:30 a.m. to	POINT [Latitude: 26.67542, Longitude: -80.04684]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>9:00 a.m., the draw need only open on the quarter hour. (B) 9:00 a.m. to 2:15 p.m., the draw need only open on the quarter and three-quarter hour. (C) 2:15 p.m. to 6:00 p.m., the draw need only open on the quarter hour. (D) 6:00 p.m. to 7:30 a.m., the draw need only open on the quarter and three-quarter hour. (ii) Saturday, Sunday, and Federal holidays the draw need only open on the quarter and three-quarter hour. This temporary deviation is effective from 8:00 p.m. on August 19, 2024, through 11:59 p.m. on November 30, 2024. This action is necessary to allow for continuity in drawbridge operations with adjacent drawbridges during federal rulemaking and during Coast Guard enforcement of the security zone. For further information contact Coast Guard Sector Miami, FL, Waterways Management Division, (305) 535-4317 SectorMiamiWaterways@uscg.mil</p>	
Lake Worth Inlet - Lake Worth	General	Bridges	2024-10-29	2024-12-01	<p>General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-12-01 Location: 26.70595° N / 80.04641° W Bridge Name: Royal Park Eastbound Bridge The U. S. Coast Guard has issued a temporary deviation to drawbridge</p>	<p>POINT [Latitude: 26.70595, Longitude: -80.04641]</p>
South/General/Bridges/Temp Deviation						

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>operation regulation, 33 CFR §117.261(v) that governs the Royal Park (SR 704) Bridge, across Atlantic Intracoastal Waterway (AICW), mile 1022.6, at West Palm Beach, Florida. Under this temporary deviation, the Royal Park Bridge will operate as follows: (1) The draw will open on the hour and half hour, except that Monday through Friday (except Federal holidays) from 7:30 a.m. to 9:00 a.m. and from 4:00 p.m. to 6:00 p.m., the draw need only open on the half-hour. (2) When the security zone is enforced, the draw shall operate as follows: (i) Monday through Friday (except on Federal holidays) (A) 7:30 a.m. to 9:00 a.m., the draw need only open on the half-hour. (B) 9:00 a.m. to 2:15 p.m., the draw need only open on the hour and half-hour. (C) 2:15 p.m. to 6:00 p.m., the draw need only open on the half-hour. (D) 6:00 p.m. to 7:30 a.m., the draw need only open on the hour and half-hour. (ii) Saturday, Sunday, and Federal holidays the draw need only open on the hour and half hour. This temporary deviation is effective from 8:00 p.m. on August 19, 2024, through 11:59 p.m. on November 30, 2024. This action is</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>necessary to allow for continuity in drawbridge operations with adjacent drawbridges during federal rulemaking and during Coast Guard enforcement of the security zone. For further information contact Coast Guard Sector Miami, FL, Waterways Management Division, (305) 535-4317, SectorMiamiWaterways@uscg.mil</p>	

---

## Lake Wyman

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Wyman Daybeacon 60	47135	STRUCT DEST/HAZ NAV/TRLB	FD

## Largo Sound Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Newport Bay Daybeacon 7	11851.6	HAZ NAV/STRUCT DMGD	PA

## Lemon Bay Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lemon Bay Channel Daybeacon 26	57420	STRUCT DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gottfried Creek Daybeacon 5	57357.4	DAYMK DMGD	PA
Forked Creek Daybeacon 1	57617	STRUCT DEST/HAZ NAV	PA
Forked Creek West Obstruction Daybeacon	57618.9	STRUCT DEST	PA
Forked Creek North Obstruction Daybeacon	57619	STRUCT DEST	PA
Forked Creek East Obstruction Daybeacon	57619.3	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Gasparilla Sound Channel - Lemon Bay Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.90945° N / 82.33385° W Aid Name: Lemon Bay Channel Daybeacon 18 LLNR: 57320 Discrepancy Information: Initial Report DTG: 041803Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.90945, Longitude: -82.33385]
Gasparilla Sound Channel - Lemon Bay Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.04145° N / 82.42976° W Aid Name: Lemon Bay Channel Buoy 50A LLNR: 57672 Discrepancy Information: Initial Report DTG: 041803Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.04145, Longitude: -82.42976]
Gasparilla Sound Channel - Lemon Bay Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 26.95066° N / 82.3648° W Aid Name: Lemon Bay Channel Daybeacon 26 LLNR: 57420 Discrepancy Information: Initial Report DTG: 222229Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 26.95066, Longitude: -82.3648]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Lemon Bay Channel Daybeacon 26	57420	WATCHING PROPERLY	FD	2024-10-22

## Little Lake George

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Lake George Light 53	8435	LT EXT	FD
Little Lake George Daybeacon 54	8450	STRUCT DEST/TRLB	FD

## Little Manatee River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Shell Point Daybeacon 3	22698.2	STRUCT DEST	PA
Shell Point Daybeacon 7	22698.6	STRUCT DEST	PA

## Little Mud River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Mud River Daybeacon 189	36855	STRUCT DEST/TRUB	FD
Little Mud River Light 190	36865	STRUCT DEST/TRLB	FD
Little Mud River Daybeacon 192	36867.1	MSLD SIG/DBD DMGD/TRUB	FD
Little Mud River Light 196	36880	STRUCT DEST/TRLB	FD





## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Little Mud River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 06-20	2025- 03-19		POINT [Latitude: 31.35723, Longitude: -81.33695]

## Little River Winyah Bay

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Little River-Winyah Bay Obstruction Daybeacon B	33647	STRUCT DEST/TRUB	FD
Little River-Winyah Bay Obstruction Daybeacon D	33693	STRUCT MISSING/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Winyah Bay Channel - Little River Winyah Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-17	2025-04-15	ATON/Federal Discrepancies From: 2024-10-17 To: 2025-04-15 Location: 33.81365° N / 78.72571° W Aid Name: Little River-Winyah Bay Obstruction Daybeacon D LLNR: 33693 Discrepancy Information: Initial Report DTG: 172140Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 172140Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 33.81365, Longitude: -78.72571]
Winyah Bay Channel - Little River Winyah Bay/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-28	2024-11-11	ATON/Federal Discrepancies Corrected From: 2024-10-28 To: 2024-11-11 Location: 33.85442° N / 78.54783° W Aid Name: Little River Inlet Temporary Buoy 7A LLNR: Not Provided Discrepancy Information: Initial Report DTG: 282140Z OCT 2024 Summary: MISSING Correction DTG: 282142Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 33.85442, Longitude: -78.54783]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Winyah Bay Channel - Little River Winyah Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-28	2025- 04-26	ATON/Federal Discrepancies From: 2024-10-28 To: 2025-04-26 Location: 33.85442° N / 78.54783° W Aid Name: Little River Inlet Temporary Buoy 7A LLNR: Not Provided Discrepancy Information: Initial Report DTG: 282140Z OCT 2024 Summary: MISSING	POINT [Latitude: 33.85442, Longitude: -78.54783]

## Little Shark River Entrance

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Cormorant Pass Daybeacon 48	15870	DAYMK IMCH	PA
Oyster Bay Daybeacon 53	15885	DAYMK MISSING	PA
Oyster Bay Daybeacon 63	15915	DAYMK MISSING	PA
Little Shark River Daybeacon 69	15940	DAYMK IMCH	PA

— —

\_\_\_\_\_

\_\_\_\_\_

# Long Island Crossing

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tybee Knoll Cut Range - Long Island Crossing/ATON/ Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 32.03018° N / 80.91414° W Aid Name: Long Island Crossing Lower Range Rear Light LLNR: 4795 Discrepancy Information: Initial Report DTG: 271951Z SEP 2024 Summary: DAYMK MISSING Correction DTG: 232056Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 32.03018, Longitude: -80.91414]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Long Island Crossing Lower Range Rear Light	4795	WATCHING PROPERLY	FD	2024-10-23

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Long Island Crossing Range Lighted Buoy 28	RENAME	Long Island Crossing LB 28 (LLNR 4785) will be renamed Long Island Crossing LB 26A (LLNR 4785) and the nominal range of the light characteristics will be reduced from 5 NM to a nominal range of 4 NM. The renumbering of the aid to navigation will ensure the entire channel aligns in numerical order.
Long Island Crossing Range Lighted Buoy 30	RENAME	Long Island Crossing LB 30 (LLNR 4810) will be renamed Long Island Crossing LB 28 (LLNR 4810) and the nominal range of the light characteristics will be reduced from 5 NM to a nominal range of 4 NM. The renumbering of the aid to navigation will ensure the entire channel aligns in numerical order.
Long Island Crossing Range Lighted Buoy 32	RENAME	Long Island Crossing LB 32 (LLNR 4815) will be renamed Long Island Crossing LB 30 (LLNR 4815) and the nominal range of the light characteristics will be reduced from 5 NM to a nominal range of 4 NM. The renumbering of the aid to navigation will ensure the entire channel aligns in numerical order.

## Long Key

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Long Key Daybeacon 1X	12385	STRUCT DEST/TRUB	FD

## Long Key Cape Sable

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sprigger Bank Light 5	15605	STRUCT DEST/HAZ NAV/TRLB	FD





# Longboat Pass

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Longboat Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.4376° N / 82.69956° W Aid Name: Longboat Pass Buoy 1 LLNR: 21757 Discrepancy Information: Initial Report DTG: 041743Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.4376, Longitude: -82.69956]
Longboat Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.43719° N / 82.69919° W Aid Name: Longboat Pass Buoy 2 LLNR: 21758 Discrepancy Information: Initial Report DTG: 041757Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.43719, Longitude: -82.69919]
Longboat Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.4396° N / 82.69607° W Aid Name: Longboat Pass Buoy 3 LLNR: 21760 Discrepancy Information: Initial Report DTG: 041759Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.4396, Longitude: -82.69607]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Longboat Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.43857° N / 82.69692° W Aid Name: Longboat Pass Buoy 2A LLNR: 21759 Discrepancy Information: Initial Report DTG: 041758Z OCT 2024 Summary: MISSING	POINT [Latitude: 27.43857, Longitude: -82.69692]
Longboat Pass/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.4376° N / 82.69956° W Aid Name: Longboat Pass Buoy 1 LLNR: 21757 Discrepancy Information: Initial Report DTG: 041743Z OCT 2024 Summary: MISSING Correction DTG: 300054Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 27.4376, Longitude: -82.69956]
Longboat Pass/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.43719° N / 82.69919° W Aid Name: Longboat Pass Buoy 2 LLNR: 21758 Discrepancy Information: Initial Report DTG: 041757Z OCT 2024 Summary: MISSING Correction DTG: 300055Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 27.43719, Longitude: -82.69919]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Longboat Pass/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.4396° N / 82.69607° W Aid Name: Longboat Pass Buoy 3 LLNR: 21760 Discrepancy Information: Initial Report DTG: 041759Z OCT 2024 Summary: MISSING Correction DTG: 300057Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 27.4396, Longitude: -82.69607]
Longboat Pass/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.43857° N / 82.69692° W Aid Name: Longboat Pass Buoy 2A LLNR: 21759 Discrepancy Information: Initial Report DTG: 041758Z OCT 2024 Summary: MISSING Correction DTG: 300058Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 27.43857, Longitude: -82.69692]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Longboat Pass Buoy 1	21757	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 1	21757	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 2	21758	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 2	21758	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 2A	21759	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 2A	21759	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 3	21760	RESET ON STATION	FD	2024-10-30
Longboat Pass Buoy 3	21760	RESET ON STATION	FD	2024-10-30

## Lower Flats Range

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elba Island Light 39	4850	MISSING/TRLB	FD
Elba Island Light 39	4850	STRUCT DEST/TRLB	FD

## Mackay River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mackay River Cutoff Light 229	37090	STRUCT DEST/TRLB	FD
Mackay River Cutoff Light 231	37095	STRUCT DEST/TRLB	FD
Mackay River Light 239	37160	STRUCT DEST/HAZ NAV/TRLB	FD
Mackay River Light 239	37160	BUOY DMGD/TRLB	FD
Mackay River Light 241	37170	STRUCT DEST/TRLB	FD
Mackay River Light 244	37190	STRUCT DEST/TRLB	FD
Mackay River Light 249	37210	DBD DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Simons Sound - Mackay River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-24	2025- 04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 31.13754° N / 81.41617° W Aid Name: Mackay River Light 249 LLNR: 37210 Discrepancy Information: Initial Report DTG: 242113Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 31.13754, Longitude: -81.41617]

## Manatee River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee River Daybeacon 28	22095	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tidewater Preserve Marina Daybeacon 2	22105.2	STRUCT DEST	PA
Colony Cove Daybeacon 2	22110	STRUCT DEST/TRUB	PA

## Matanzas Inlet Mosquito Lagoon

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Silver Lake Daybeacon 9	39745	STRUCT DEST/TRUB	FD

## Matanzas Pass Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas Pass Channel Lighted Buoy 5	18107	OFF STATION	FD
Matanzas Pass Channel Lighted Buoy 7	18120	OFF STATION	FD

## Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Hurricane Bay Marina West Channel Daybeacon 7	18160	STRUCT DEST/HAZ NAV	PA
Siesta Isles Daybeacon 4	18215	STRUCT DEST	PA
Matanzas Harbor Channel Daybeacon 3	18296.1	STRUCT DEST/HAZ NAV	PA
Matanzas Harbor Channel Daybeacon 5	18296.3	STRUCT DEST	PA
North Estero Bay Daybeacon 19	18565	STRUCT DMGD	PA
North Estero Bay Daybeacon 35	18605	STRUCT DEST	PA
North Estero Bay Daybeacon 63	18725	STRUCT DEST/TRUB	PA
Mullock Creek Daybeacon 13	18835	STRUCT DEST/HAZ NAV	PA
Mullock Creek Daybeacon 45	18920	STRUCT DEST	PA



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay - Matanzas Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.46089° N / 81.97466° W Aid Name: Matanzas Pass Channel Light 1 LLNR: 18085 Discrepancy Information: Initial Report DTG: 041630Z OCT 2024 Summary: DBD DEST/LT EXT	POINT [Latitude: 26.46089, Longitude: -81.97466]
San Carlos Bay - Matanzas Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.46676° N / 81.96963° W Aid Name: Matanzas Pass Channel Lighted Buoy 5 LLNR: 18107 Discrepancy Information: Initial Report DTG: 041631Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 26.46676, Longitude: -81.96963]
San Carlos Bay - Matanzas Pass Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.46689° N / 81.96749° W Aid Name: Matanzas Pass Channel Lighted Buoy 7 LLNR: 18120 Discrepancy Information: Initial Report DTG: 041634Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 26.46689, Longitude: -81.96749]

## Matanzas River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas River Light 1	39035	STRUCT DEST/TRLB	FD
Matanzas River Buoy 2	39040	OFF STA	FD
Matanzas River Light 50	39370	DBD DEST	FD
Matanzas River Daybeacon 51	39375	DBD DEST	FD
Matanzas River Daybeacon 68	39480	STRUCT DEST/TRUB	FD
Matanzas River Light 86	39565	STRUCT DEST/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Salt Run Daybeacon 1	38915	STRUCT DEST	PA
Salt Run Daybeacon 3	38925	STRUCT DEST	PA
Salt Run Daybeacon 4	38930	STRUCT DEST	PA
Salt Run Daybeacon 6	38940	DAYMK DMGD	PA
Salt Run Daybeacon 7	38945	STRUCT DMGD	PA
Salt Run Daybeacon 11	38965	STRUCT DEST/HAZ NAV	PA
Fish Island Marina Daybeacon 1	39080	DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.90011° N / 81.30385° W Aid Name: Matanzas River Daybeacon 5 LLNR: 39055 Discrepancy Information: Initial Report DTG: 111116Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.90011, Longitude: -81.30385]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.90011° N / 81.30385° W Aid Name: Matanzas River Daybeacon 5 LLNR: 39055 Discrepancy Information: Initial Report DTG: 111116Z OCT 2024 Summary: DBD DEST Correction DTG: 232302Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.90011, Longitude: -81.30385]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.81172° N / 81.29145° W Aid Name: Matanzas River Daybeacon 33 LLNR: 39290 Discrepancy Information: Initial Report DTG: 111115Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.81172, Longitude: -81.29145]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.79084° N / 81.2759° W Aid Name: Matanzas River Daybeacon 46 LLNR: 39345 Discrepancy Information: Initial Report DTG: 111125Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 29.79084, Longitude: -81.2759]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.78254° N / 81.27465° W Aid Name: Matanzas River Daybeacon 51 LLNR: 39375 Discrepancy Information: Initial Report DTG: 111111Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.78254, Longitude: -81.27465]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.79585° N / 81.27341° W Aid Name: Matanzas River Light 43 LLNR: 39330 Discrepancy Information: Initial Report DTG: 111056Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.79585, Longitude: -81.27341]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.76147° N / 81.25434° W Aid Name: Matanzas River Light 64 LLNR: 39465 Discrepancy Information: Initial Report DTG: 111118Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.76147, Longitude: -81.25434]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.78237° N / 81.27564° W Aid Name: Matanzas River Light 50 LLNR: 39370 Discrepancy Information: Initial Report DTG: 111103Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.78237, Longitude: -81.27564]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.75656° N / 81.24974° W Aid Name: Matanzas River Light 67 LLNR: 39475 Discrepancy Information: Initial Report DTG: 111120Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.75656, Longitude: -81.24974]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.73865° N / 81.246° W Aid Name: Matanzas River Light 74 LLNR: 39500 Discrepancy Information: Initial Report DTG: 111124Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.73865, Longitude: -81.246]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.78822° N / 81.27587° W Aid Name: Matanzas River Daybeacon 47 LLNR: 39350 Discrepancy Information: Initial Report DTG: 111126Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 29.78822, Longitude: -81.27587]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.82537° N / 81.29826° W Aid Name: Matanzas River Daybeacon 28 LLNR: 39270 Discrepancy Information: Initial Report DTG: 111128Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 29.82537, Longitude: -81.29826]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.82537° N / 81.29826° W Aid Name: Matanzas River Daybeacon 28 LLNR: 39270 Discrepancy Information: Initial Report DTG: 111128Z OCT 2024 Summary: DBD DEST Correction DTG: 232303Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.82537, Longitude: -81.29826]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.79585° N / 81.27341° W Aid Name: Matanzas River Light 43 LLNR: 39330 Discrepancy Information: Initial Report DTG: 111056Z OCT 2024 Summary: DBD DEST Correction DTG: 232306Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.79585, Longitude: -81.27341]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.79585° N / 81.27341° W Aid Name: Matanzas River Light 43 LLNR: 39330 Discrepancy Information: Initial Report DTG: 031420Z SEP 2024 Summary: LT IMCH Correction DTG: 232307Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.79585, Longitude: -81.27341]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.78822° N / 81.27587° W Aid Name: Matanzas River Daybeacon 47 LLNR: 39350 Discrepancy Information: Initial Report DTG: 111126Z OCT 2024 Summary: DAYMK IMCH Correction DTG: 232309Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.78822, Longitude: -81.27587]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.73865° N / 81.246° W Aid Name: Matanzas River Light 74 LLNR: 39500 Discrepancy Information: Initial Report DTG: 111124Z OCT 2024 Summary: DBD DEST Correction DTG: 232311Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.73865, Longitude: -81.246]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.81172° N / 81.29145° W Aid Name: Matanzas River Daybeacon 33 LLNR: 39290 Discrepancy Information: Initial Report DTG: 111115Z OCT 2024 Summary: DBD DEST Correction DTG: 232305Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.81172, Longitude: -81.29145]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.79084° N / 81.2759° W Aid Name: Matanzas River Daybeacon 46 LLNR: 39345 Discrepancy Information: Initial Report DTG: 111125Z OCT 2024 Summary: DAYMK IMCH Correction DTG: 232308Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.79084, Longitude: -81.2759]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.76147° N / 81.25434° W Aid Name: Matanzas River Light 64 LLNR: 39465 Discrepancy Information: Initial Report DTG: 111118Z OCT 2024 Summary: DBD DEST Correction DTG: 232309Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.76147, Longitude: -81.25434]
St Augustine Inlet - Matanzas River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.75656° N / 81.24974° W Aid Name: Matanzas River Light 67 LLNR: 39475 Discrepancy Information: Initial Report DTG: 111120Z OCT 2024 Summary: DBD DEST Correction DTG: 232310Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.75656, Longitude: -81.24974]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Matanzas River Daybeacon 5	39055	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 5	39055	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 28	39270	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 28	39270	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 33	39290	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 33	39290	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 43	39330	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 43	39330	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 43	39330	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 46	39345	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 46	39345	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 47	39350	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Daybeacon 47	39350	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 64	39465	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 64	39465	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 67	39475	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 67	39475	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 74	39500	WATCHING PROPERLY	FD	2024-10-23
Matanzas River Light 74	39500	WATCHING PROPERLY	FD	2024-10-23

## Proposed Notice of Change

NAME	ACTION TYPE	DESCRIPTION
Matanzas River Light 1	CHANGE	<p>The U.S. Coast Guard is proposing a change to the Aid to Navigation system in the Matanzas River. Matanzas River Light 1 (LLNR 39035) will permanently be changed to Matanzas River Lighted Buoy 1 (LLNR 39035). Matanzas River Light 1 has been destroyed on a few occasions over the last 10 years and it is currently being advertised as destroyed since 2020. In addition, the water depth at its assigned position is 21 feet making it more difficult for a CG asset to spud and maintain position to rebuild the aid safely. Converting the light to a floating aid will allow for a timelier response and consistent maintenance in the event the aid becomes discrepant.</p> <p>Therefore, this change will provide mariners a more reliable signal while approaching the Matanzas River Channel entrance from the St. Augustine Inlet and while exiting the channel. All comments should be emailed to: D07-SMB-DPWPUBLICComments@uscg.mil or andrew.m.engle@uscg.mil with Matanzas River LB 1 as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by October 23, 2024.</p>

# Matheny Creek

## Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Venice Inlet-Siesta Key Daybeacon 7	57870	STRUCT DEST	FD
Venice Inlet-Siesta Key Light 41	58135	STRUCT MISSING/TRLB	FD
Venice Inlet-Siesta Key Daybeacon 42	58145	STRUCT MISSING/TRUB	FD

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snake Island Daybeacon A	57834	STRUCT DEST	PA
Snake Island Daybeacon B	57834.1	STRUCT DEST	PA
Snake Island Daybeacon C	57834.2	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 5	58190	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 6	58195	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 7	58200	STRUCT DEST	PA
Midnight Pass Daybeacon 13	58205.3	STRUCT DMGD	PA
Matheny Creek Daybeacon 1	58292	STRUCT DMGD	PA
Phillippi Creek Daybeacon 2	58365.2	DAYMK MISSING	PA
Phillippi Creek Daybeacon 7	58365.6	DAYMK MISSING	PA
Phillippi Creek Daybeacon 11	58365.9	STRUCT DEST/HAZ NAV	PA
Phillippi Creek Daybeacon 13	58366	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Venice Inlet - Matheny Creek/General/Bridges/Temp Deviation	General	Bridges	2024-10-29	2025-04-27	General/Bridges/Temp Deviation From: 2024-10-29 To: 2025-04-27 Location: 27.17991° N / 82.49435° W Bridge Name: Blackburn Point Bridge The Coast Guard has issued a temporary deviation from the operating schedule that governs the Blackburn Point Bridge across the Gulf Intracoastal Waterway (GICW), mile 63.1, at Osprey, FL. The Casey Key Association has requested the Coast Guard changing the operating schedule allowing the drawbridge scheduled openings. This deviation will test a change to the drawbridge operation schedule to determine whether a permanent change to the schedule is needed. Under this temporary deviation, from 7 a.m. on August 12, 2024, through 7 p.m. on January 31, 2025, the Blackburn Point Bridge shall open on signal; except that from 7 a.m. to 7 p.m., Monday through Friday, except Federal holidays, the draw need only open on the hour, twenty minutes after the hour, and forty minutes after the hour. Public vessels of the United States and tugs with tows, upon proper signal, will	POINT [Latitude: 27.17991, Longitude: -82.49435]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>be passed through any time. Vessels able to pass without an opening may do so at any time. The public comments period ended on September 20, 2024. If you have questions on this test deviation telephone 571-607-5951, email Jennifer.N.Zercher@uscg.mil</p>	
<p>Venice Inlet - Matheny Creek/General/Bridges/Temp Deviation</p>	<p>General Bridges</p>		<p>2024-10-29</p>	<p>2024-12-31</p>	<p>General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-12-31            Location: 27.254393° N / 82.531651° W            Bridge Name: Stickney Point            Bridge Drax, Inc on behalf of the bridge owner, Florida Department of Transportation (FDOT), is authorized to temporarily deviate from drawbridge operation regulation 33 CFR 117.287 (c)(1) that governs the Stickney Point (SR 72) Drawbridge, mile 68.6 Gulf Intracoastal Waterway (GICW), at Siesta Key Florida. Under this temporary deviation, the Stickney Point Drawbridge is allowed to operate as follows from Monday through Friday June 17, 2024, until November 26, 2024: From 7:00 a.m. until 5:00 p.m., Monday through Friday, the drawbridge will provide single-leaf openings only, and full openings will be provided with a 2-hour advance notice per the operating schedule. In</p>	<p>POINT            [Latitude: 27.254393, Longitude: -82.531651]</p>

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>addition, the channel beneath the drawbridge will be partially obstructed with in-water equipment. The equipment will be moved with a 1-hour advance notice to allow for a full opening and will not be located within the navigational channel during non-working hours. Mariners are strongly advised to exercise extreme caution when navigating in the area and to proceed at the slowest safe speed to minimize wake. All in-water equipment is required to be lighted at night in accordance with Inland Navigation Rules. Public vessels of the United States, and vessels in distress, shall be passed as soon as safely possible. Vessels which can safely pass without an opening shall be passed at any time. The project is expected to be completed December 20, 2024. For further information of this project contact LaVerne Luchsinger, project manager, at (608) 718-4754. For waterway questions please contact USCG Sector Saint Petersburg Waterways Management Division; telephone 727-824-7506, e-mail D07-SMB-Tampa-WWM@uscg.mil.</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Venice Inlet - Matheny Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-16	2025-04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 27.20331° N / 82.50195° W Aid Name: Venice Inlet- Siesta Key Light 41 LLNR: 58135 Discrepancy Information: Initial Report DTG: 161159Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 311944Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.20331, Longitude: -82.50195]
Venice Inlet - Matheny Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-16	2025-04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 27.20869° N / 82.50242° W Aid Name: Venice Inlet- Siesta Key Daybeacon 42 LLNR: 58145 Discrepancy Information: Initial Report DTG: 161159Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.20869, Longitude: -82.50242]
Venice Inlet - Matheny Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-31	2025-04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 27.11481° N / 82.46527° W Aid Name: Venice Inlet- Siesta Key Light 5 LLNR: 57860 Discrepancy Information: Initial Report DTG: 311750Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.11481, Longitude: -82.46527]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Venice Inlet - Matheny Creek/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.12743° N / 82.4694° W Aid Name: Venice Inlet-Siesta Key Light 12 LLNR: 57890 Discrepancy Information: Initial Report DTG: 311749Z OCT 2024 Summary: LT EXT Correction DTG: 311750Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RELIGHTED	POINT [Latitude: 27.12743, Longitude: -82.4694]
Venice Inlet - Matheny Creek/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.11481° N / 82.46527° W Aid Name: Venice Inlet-Siesta Key Light 5 LLNR: 57860 Discrepancy Information: Initial Report DTG: 311750Z OCT 2024 Summary: LT EXT Correction DTG: 311751Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RELIGHTED	POINT [Latitude: 27.11481, Longitude: -82.46527]
Venice Inlet - Matheny Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-31	2025-04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 27.12743° N / 82.4694° W Aid Name: Venice Inlet-Siesta Key Light 12 LLNR: 57890 Discrepancy Information: Initial Report DTG: 311749Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.12743, Longitude: -82.4694]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Venice Inlet-Siesta Key Light 5	57860	RELIGHTED	FD	2024-10-31
Venice Inlet-Siesta Key Light 5	57860	RELIGHTED	FD	2024-10-31
Venice Inlet-Siesta Key Light 12	57890	RELIGHTED	FD	2024-10-31
Venice Inlet-Siesta Key Light 12	57890	RELIGHTED	FD	2024-10-31

## Mayport Basin

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mayport Basin Preferred Channel Lighted Buoy	7165	OFF STATION	FD

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Mayport Basin Channel Lighted Buoy 1	7170	RELOCATED FOR DREDGING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Johns River - Mayport Basin/ATON/Temporary Changes	ATON	Temporary Changes	2024-10-03	2025-04-01	ATON/Temporary Changes From: 2024-10-03 To: 2025-04-01 Location: 30.39754° N / 81.39298° W Aid Name: Mayport Basin Channel Lighted Buoy 1 LLNR: 7170 Temporary Aid Change Information: Status: RELOCATED FOR DREDGING Old Latitude: 30-23- 51.128N New Latitude: 30-23- 50.613N Old Longitude: 081-23- 34.721W New Longitude: 081-23- 38.710W	POINT [Latitude: 30.39754, Longitude: -81.39298]
St Johns River - Mayport Basin/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-21	2025-04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 30.39899° N / 81.39446° W Aid Name: Mayport Basin Preferred Channel Lighted Buoy LLNR: 7165 Discrepancy Information: Initial Report DTG: 212051Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 30.39899, Longitude: -81.39446]

## Miami Beach Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Channel Light 11	48015	STRUCT DEST/TRLB	FD

## Miami Main Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Marina Breakwater North Light	10570	LT EXT	PA

## Miami Turning Basin

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Turning Basin Articulated Light E	10770	Status Unreported	FD
Miami Turning Basin Articulated Light E	10770	STRUCT DEST/TRUB	FD

## Mile Point

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mile Point Lower Range Front Light	7260	REDUCED INT	FD
Mile Point Light A	7281	DAYMK MISSING	FD
Mile Point Light B	7282	OFF STA/TRUB	FD

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Mile Point Light B	7282	STRUCT DEST/TRUB	FD
Mile Point Light C	7283	STRUCT DEST	FD
Mile Point Upper Range Front Light	7287	REDUCED INT	FD
Mile Point Upper Range Rear Light	7290	LT EXT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Johns River - Mile Point/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-21	2025- 04-19	ATON/Federal Discrepancies From: 2024-10-21 To: 2025-04-19 Location: 30.37845° N / 81.45395° W Aid Name: Mile Point Lower Range Rear Light LLNR: 7265 Discrepancy Information: Initial Report DTG: 211157Z OCT 2024 Summary: LT EXT	POINT [Latitude: 30.37845, Longitude: -81.45395]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Mile Point Lower Range Rear Light	7265	RELIGHTED	FD	2024-10-22

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Mile Point Lower Range Front Light	RELOCATE	Mile Point Lower RFL (LLNR 7260) will be relocated to approximate position: 30-22-44.551N/081-27-11.480W to align with the newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.
Mile Point Lower Range Rear Light	RELOCATE	Mile Point Lower RRL (LLNR 7265) will be relocated to approximate position: 30-22-43.316N/081-27-14.558W to align with the newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.
Mile Point Upper Range Front Light	RELOCATE	Mile Point Upper RFL (LLNR 7287) will be relocated to approximate position: 30-22-44.266N/081-27-12.139W to align with the newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.
Mile Point Upper Range Rear Light	RELOCATE	Mile Point Upper RRL (LLNR 7290) will be relocated to approximate position: 30-22-34.772N/081-26-58.725W to align with the newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.



# Mosquito Lagoon

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
New Smyrna Beach - Mosquito Lagoon/ATON/ATON Changes	ATON	ATON Changes	2024- 10-22	2025- 04-20	ATON/ATON Changes From: 2024-10-22 To: 2025-04-20 Location: 28.9372° N / 80.83329° W Aid Name: Bethune Beach Aquaculture Boundary Light A LLNR: 40854 Action: ESTABLISH	POINT [Latitude: 28.9372, Longitude: -80.83329]
New Smyrna Beach - Mosquito Lagoon/ATON/ATON Changes	ATON	ATON Changes	2024- 10-22	2025- 04-20	ATON/ATON Changes From: 2024-10-22 To: 2025-04-20 Location: 28.93626° N / 80.8328° W Aid Name: Bethune Beach Aquaculture Boundary Light B LLNR: 40854.1 Action: ESTABLISH	POINT [Latitude: 28.93626, Longitude: -80.8328]
New Smyrna Beach - Mosquito Lagoon/ATON/ATON Changes	ATON	ATON Changes	2024- 10-22	2025- 04-20	ATON/ATON Changes From: 2024-10-22 To: 2025-04-20 Location: 28.93608° N / 80.83352° W Aid Name: Bethune Beach Aquaculture Boundary Light C LLNR: 40854.2 Action: ESTABLISH	POINT [Latitude: 28.93608, Longitude: -80.83352]
New Smyrna Beach - Mosquito Lagoon/ATON/ATON Changes	ATON	ATON Changes	2024- 10-22	2025- 04-20	ATON/ATON Changes From: 2024-10-22 To: 2025-04-20 Location: 28.93691° N / 80.83401° W Aid Name: Bethune Beach Aquaculture Boundary Light D LLNR: 40854.3 Action: ESTABLISH	POINT [Latitude: 28.93691, Longitude: -80.83401]

## Mount Pleasant Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Mount Pleasant Channel Daybeacon 3	3520	STRUCT MISSING/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Charleston Harbor - Mount Pleasant Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-29	2025-04-27	ATON/Federal Discrepancies From: 2024-10-29 To: 2025-04-27 Location: 32.77508° N / 79.87252° W Aid Name: Mount Pleasant Channel Daybeacon 3 LLNR: 3520 Discrepancy Information: Initial Report DTG: 291624Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 291624Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 32.77508, Longitude: -79.87252]

## Mullet Key Channel

### Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Mullet Key Channel Range Front Light	CHANGE	Mullet Key Channel Range Front Light (LLNR 22355) will change to FI G 2.5s (NIGHT) FI G 2.5s (DAY). All other characteristics will remain the same.
Mullet Key Channel Range Rear Light	CHANGE	Mullet Key Channel Range Rear Light (LLNR 22360) will change to ISO G 6s (NIGHT) ISO G 6s (DAY). All other characteristics will remain the same.

## Murphy Island

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Murphy Island Light 26	8305	DAYMK MISSING	FD

## Myakka River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Gulf Cove Entrance Daybeacon 5	20175	DAYMK MISSING	PA
Upper Myakka River Daybeacon A	20355	STRUCT DEST/HAZ NAV	PA
Upper Myakka River Daybeacon B	20360	HAZ NAV/DAYMK MISSING	PA
Upper Myakka River Daybeacon 1	20365	DAYMK MISSING	PA

## Naples Bay Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Naples Bay Channel Daybeacon 22	17550	STRUCT MISSING	FD
Naples Bay Channel Daybeacon 26	17600	STRUCT MISSING/TRUB	FD

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Naples Yacht Club Daybeacon 5	17667	DAYMK MISSING	PA
Naples Yacht Club Daybeacon 7	17667.1	DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Gordon Pass Channel - Naples Bay Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 26.11589° N / 81.78866° W Aid Name: Naples Bay Channel Daybeacon 26 LLNR: 17600 Discrepancy Information: Initial Report DTG: 021811Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 021812Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 26.11589, Longitude: -81.78866]
Gordon Pass Channel - Naples Bay Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-12	2025- 04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 26.10688° N / 81.78655° W Aid Name: Naples Bay Channel Daybeacon 22 LLNR: 17550 Discrepancy Information: Initial Report DTG: 121432Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 26.10688, Longitude: -81.78655]

## Nassau Cutoff

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Nassau Cutoff Light 47	38175	STRUCT MISSING/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sawpit Creek - Nassau Cutoff/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-23	2025- 04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 30.52223° N / 81.46072° W Aid Name: Nassau Cutoff Light 47 LLNR: 38175 Discrepancy Information: Initial Report DTG: 231424Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 231425Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 30.52223, Longitude: -81.46072]



## New Channel Range

### Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
New Channel Range Front Light	RELOCATE	After completion of dredging and channel re-alignment, the water depth at the current assigned position for New Channel RFL (LLNR 4770), makes it impossible for the Coast Guard to rebuild this range in its advertised position. Therefore, New Channel RFL (LLNR 4770) will be permanently relocated to a new assigned position at approximately 32-02-21.801N/080-55-39.437W.

## New Pass

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
New Pass Interior Shoal Light	21620	DBD DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anglers Club Reef Daybeacon AC	21701	STRUCT DEST	PA
City Island Breakwater Light	21710	STRUCT DEST	PA
Sarasota Basin Obstruction Light A	21752	STRUCT DEST	PA
Sarasota Basin Obstruction Daybeacon B	21754	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
New Pass/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.32803° N / 82.58821° W Aid Name: New Pass Interior Shoal Light LLNR: 21620 Discrepancy Information: Initial Report DTG: 151659Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.32803, Longitude: -82.58821]

## New River Sound

### Temporary Changes

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
New River Sound Lighted Buoy 11	47265	DISCONTINUED	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Stranahan River - New River Sound/ATON/Temporary Changes	ATON	Temporary Changes	2024- 10-03	2025- 04-01	ATON/Temporary Changes From: 2024-10-03 To: 2025-04-01 Location: 26.11697° N / 80.10879° W Aid Name: New River Sound Lighted Buoy 11 LLNR: 47265 Temporary Aid Change Information: Status: DISCONTINUED	POINT [Latitude: 26.11697, Longitude: -80.10879]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Stranahan River - New Sound/General Deviation	General	Bridges	2024- 10-29	2024- 11-11	<p>General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-11-11 Location: 26.11977° N / 80.10904° W Bridge Name: East Las Olas Boulevard Bridge Florida Department of Transportation (FDOT) is authorized to temporarily deviate from drawbridge operation regulation 33 CFR 117.261(bb-7) that governs the East Las Olas Drawbridge mile 1064.0, across the Atlantic Intracoastal Waterway (AICW), Fort Lauderdale, Florida. Under this temporary deviation, the East Las Olas Drawbridge need not open to navigation including tugs and tugs with tows, from 5:50 a.m. to 8 a.m. on Sunday, November 10, 2024, to facilitate the 18th Annual 13.1 Fort Lauderdale Half Marathon &amp; A1A 10K Race. Public vessels of the United States and vessels in distress shall be passed at any time. For waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil.</p>	POINT [Latitude: 26.11977, Longitude: -80.10904]

## New Smyrna Beach

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
New Smyrna Beach Daybeacon 28	40645	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 51	40805	STRUCT DEST/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Ponce De Leon Cut - New Smyrna Beach/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-16	2025- 04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 28.99225° N / 80.90097° W Aid Name: New Smyrna Beach Daybeacon 51 LLNR: 40805 Discrepancy Information: Initial Report DTG: 161942Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 211538Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.99225, Longitude: -80.90097]

## North Edisto River

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
North Edisto River Inner Lighted Buoy 9	3885	MISSING	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - North Edisto River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-07	2025- 04-05	ATON/Federal Discrepancies From: 2024-10-07 To: 2025-04-05 Location: 32.54529° N / 80.16443° W Aid Name: North Edisto River Inner Lighted Buoy 9 LLNR: 3885 Discrepancy Information: Initial Report DTG: 072326Z OCT 2024 Summary: MISSING	POINT [Latitude: 32.54529, Longitude: -80.16443]
Sector Charleston, Submerged Land Act (SLA) - North Edisto River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-04	2025- 04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 32.58253° N / 80.20822° W Aid Name: North Edisto River Entrance Range Front Light LLNR: 3870 Discrepancy Information: Initial Report DTG: 041251Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 32.58253, Longitude: -80.20822]

## North Newport River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Timmons Reef E Obstruction Daybeacon	36500	STRUCT DEST	PA

null

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wexford Harbour Daybeacon 3	4420	MSLD SIG	PA
Wexford Harbour Daybeacon 4	4425	MSLD SIG	PA
Wexford Harbour Daybeacon 8	4445	MSLD SIG	PA
Palmetto Dunes Marina West Light 22	4520	DAYMK IMCH	PA

## Ogeechee River

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Mcallister Fishing Pier Light	36360	LT EXT	PA

## Oglethorpe Range

### Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
-------	----------	-----------------	---------------	-------------	-------------	----------

---

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Fort Jackson - Oglethorpe Range/General/Bridges/Construction	General	Bridges	2024-10-29	2025-02-19	<p>General/Bridges/Construction  From: 2024-10-29  To: 2025-02-19  Location:  32.088908° N /  81.098614° W  Bridge Name:  Talmadge Memorial  SJ Hamill  Construction will be  conducting pile  driving, dredging,  and demolition of  an underwater  bridge footer in the  vicinity of the US  Highway 17  (Eugene Talmadge  Memorial) Bridge in  the Savannah River  mile 14.9 at  Savannah, Georgia  from August 19,  2024, until the  second week of  February 2025.  Work will be  conducted daily  from 7:00 am until  5:00 pm utilizing  barges and  tugboats. No  restrictions or  obstructions to the  channel and bridge  are anticipated.  The contractor will  relocate all  materials to the  Georgia Ocean  Terminal Port when  no work is being  conducted.  Mariners are  advised to exercise  caution while  transiting the area  of construction  equipment and  vessels in  operation. For  further information,  contact: Caleb  Michael, Field  Engineer at (630)  605-4521,  cmichael@sjhamill.com,  or for waterways  questions please  contact the United  States Coast Guard  at (912) 247-0073</p>	POINT [Latitude: 32.088908, Longitude: -81.098614]

## Okeechobee Waterway

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Taylor Creek Bar Light 1	51890	DAYMK MISSING	FD
Taylor Creek Daybeacon 3	51900	DBD DEST	FD
Taylor Creek Daybeacon 4	51905	DBD DEST	FD
Taylor Creek Daybeacon 6	51915	STRUCT DEST/TRUB	FD

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Dyess Canal Safewater Light DC	51980	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Okeechobee Waterway/ATON Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 27.19866° N / 80.79474° W Aid Name: Taylor Creek Daybeacon 4 LLNR: 51905 Discrepancy Information: Initial Report DTG: 121923Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.19866, Longitude: -80.79474]
Okeechobee Waterway/ATON Discrepancies	ATON	Federal Discrepancies	2024-10-12	2025-04-10	ATON/Federal Discrepancies From: 2024-10-12 To: 2025-04-10 Location: 27.19859° N / 80.79563° W Aid Name: Taylor Creek Daybeacon 3 LLNR: 51900 Discrepancy Information: Initial Report DTG: 121922Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.19859, Longitude: -80.79563]

## Old Rhodes Key

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Old Rhodes Key Light 22	11165	STRUCT DEST/DAYMK DMGD/TRLB	FD
Old Rhodes Key Light 22	11165	DBD DEST	FD
Old Rhodes Key Daybeacon 24	11175	STRUCT DEST/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Old Rhodes Key/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 25.34813° N / 80.20561° W Aid Name: Old Rhodes Key Light 22 LLNR: 11165 Discrepancy Information: Initial Report DTG: 120055Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 25.34813, Longitude: -80.20561]



---

  

---

  

## Ossabaw Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ossabaw Sound Preferred Channel Buoy N	5740	MISSING	FD
Ossabaw Sound North Channel Daybeacon 10	5760	STRUCT DEST/TRUB	FD
Ossabaw Sound North Channel Daybeacon 12	5770	STRUCT DEST/TRUB	FD
Ossabaw Sound South Channel Daybeacon 5	5780	STRUCT DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Delegal Creek Channel Light 1	36229	STRUCT DEST	PA
Delegal Creek Channel Buoy 2	36230	MISSING	PA
Delegal Creek Channel Buoy 4	36233	OFF STA	PA
Delegal Creek Channel Light 8	36241.1	LT EXT	PA

## Pablo Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pablo Creek Light 6	38365	STRUCT DEST/TRLB	FD

## Paradise Bay Estates Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sarasota Municipal Pier Channel Daybeacon 2	58495	STRUCT MISSING	FD
Siesta Key-Tampa Bay Light 10	58535	STRUCT MISSING	FD
Siesta Key-Tampa Bay Light 47	59560	STRUCT MISSING	FD
Siesta Key-Tampa Bay Light 48	59565	DBD DEST	FD
Siesta Key-Tampa Bay Daybeacon 49	59570	STRUCT MISSING	FD
Siesta Key-Tampa Bay Daybeacon 49A	59570.5	STRUCT MISSING	FD
Siesta Key-Tampa Bay Light 67	60275	DBD DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Holiday Inn Marina Daybeacon 3	22047.3	STRUCT DEST	PA
Holiday Inn Marina Daybeacon 6	22047.7	STRUCT DEST	PA
Evans Artificial Reef Daybeacon	58480.5	STRUCT DEST/HAZ NAV	PA
Bay Isles Perimeter Channel Daybeacon 2	58667	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 9	58667.25	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 15	58667.45	STRUCT DEST	PA
Bay Isles Perimeter Channel Daybeacon 24	58667.75	DAYMK MISSING	PA
Coral Shores Channel Daybeacon 3	59375	STRUCT DEST	PA
Coral Shores Channel Daybeacon 9	59405	STRUCT DEST	PA
Coral Shores Channel Daybeacon 12	59420	DAYMK MISSING	PA
Coral Shores Channel Daybeacon 30	59510	STRUCT DEST	PA
Mt Vernon & Coral Shores Daybeacon 1N	59535	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 2	59636	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 3	59640	STRUCT DEST	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Palma Sola Bay Channel Daybeacon 3A	59641	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 4	59642	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 5	59645	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 6	59646	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Junction A	59647	STRUCT DEST	PA
Cove Sound Moorings Daybeacon 1	59650	OFF STA/HAZ NAV/DAYMK MISSING	PA
Cove Sound Moorings Daybeacon 2	59655	OFF STA/HAZ NAV/DAYMK MISSING	PA
Cove Sound Moorings Channel Daybeacon 3	59657	DAYMK MISSING	PA
Perico Bayou Channel Daybeacon 9	59720	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 2	59760	DAYMK MISSING	PA
San Remo Shore Channel Daybeacon 8	59785	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 13	59800	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 9	59815	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 10	59820	STRUCT DMGD	PA
Palma Sola Bay Channel Daybeacon 11	59825	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 12	59830	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 15	59845	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 18	59860	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 19	59865	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 21	59870.5	DAYMK MISSING/STRUCT DMGD	PA
Bradenton Beach City Channel Daybeacon 1	59935	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 2	59940	STRUCT DEST	PA
Bradenton Beach City Channel Daybeacon 3	59945	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 5	59955	STRUCT DEST	PA
Bradenton Beach City Channel Junction Daybeacon A	59980	STRUCT DEST	PA
Anna Maria Channel Daybeacon 1	60190	STRUCT DMGD	PA
Anna Maria Channel Daybeacon 2	60195	DAYMK MISSING	PA
Anna Maria Channel Daybeacon 9	60230	STRUCT DEST/HAZ NAV	PA
Anna Maria Channel Daybeacon 11	60240	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.46382° N / 82.68951° W Aid Name: Siesta Key-Tampa Bay Light 48 LLNR: 59565 Discrepancy Information: Initial Report DTG: 041801Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.46382, Longitude: -82.68951]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 27.40986° N / 82.62008° W Aid Name: Siesta Key-Tampa Bay Light 18 LLNR: 58815 Discrepancy Information: Initial Report DTG: 041802Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.40986, Longitude: -82.62008]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.53508° N / 82.70175° W Aid Name: Siesta Key-Tampa Bay Light 67 LLNR: 60275 Discrepancy Information: Initial Report DTG: 151651Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.53508, Longitude: -82.70175]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.47324° N / 82.69423° W Aid Name: Siesta Key-Tampa Bay Daybeacon 49A LLNR: 59570.5 Discrepancy Information: Initial Report DTG: 151652Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.47324, Longitude: -82.69423]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.46562° N / 82.69137° W Aid Name: Siesta Key-Tampa Bay Daybeacon 49 LLNR: 59570 Discrepancy Information: Initial Report DTG: 151653Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.46562, Longitude: -82.69137]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.45572° N / 82.68436° W Aid Name: Siesta Key-Tampa Bay Light 47 LLNR: 59560 Discrepancy Information: Initial Report DTG: 151654Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.45572, Longitude: -82.68436]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.4065° N / 82.63578° W Aid Name: Siesta Key-Tampa Bay Light 23 LLNR: 58840 Discrepancy Information: Initial Report DTG: 151654Z OCT 2024 Summary: DBD DEST/HAZ NAV	POINT [Latitude: 27.4065, Longitude: -82.63578]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-16	2025-04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 27.32873° N / 82.55408° W Aid Name: Siesta Key-Tampa Bay Light 10 LLNR: 58535 Discrepancy Information: Initial Report DTG: 161202Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.32873, Longitude: -82.55408]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.4065° N / 82.63578° W Aid Name: Siesta Key-Tampa Bay Light 23 LLNR: 58840 Discrepancy Information: Initial Report DTG: 151654Z OCT 2024 Summary: DBD DEST/HAZ NAV Correction DTG: 300105Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.4065, Longitude: -82.63578]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-16	2025-04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 27.3281° N / 82.55293° W Aid Name: Sarasota Municipal Pier Channel Daybeacon 2 LLNR: 58495 Discrepancy Information: Initial Report DTG: 161203Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.3281, Longitude: -82.55293]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-30	2025-04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.40715° N / 82.62941° W Aid Name: Siesta Key-Tampa Bay Light 21 LLNR: 58830 Discrepancy Information: Initial Report DTG: 301737Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.40715, Longitude: -82.62941]
Southwest Channel - Paradise Bay Estates Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-30	2024-11-13	ATON/Federal Discrepancies Corrected From: 2024-10-30 To: 2024-11-13 Location: 27.40715° N / 82.62941° W Aid Name: Siesta Key-Tampa Bay Light 21 LLNR: 58830 Discrepancy Information: Initial Report DTG: 301737Z OCT 2024 Summary: DBD DEST Correction DTG: 301738Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.40715, Longitude: -82.62941]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Siesta Key-Tampa Bay Light 21	58830	WATCHING PROPERLY	FD	2024-10-30
Siesta Key-Tampa Bay Light 21	58830	WATCHING PROPERLY	FD	2024-10-30
Siesta Key-Tampa Bay Light 23	58840	WATCHING PROPERLY	FD	2024-10-30
Siesta Key-Tampa Bay Light 23	58840	WATCHING PROPERLY	FD	2024-10-30

## Pass-A-Grille

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pass-A-Grille Channel Daybeacon 1	25460	STRUCT MISSING/TRLB	FD
Pass-A-Grille Channel Daybeacon 2	25465	STRUCT DEST/HAZ NAV/TRLB	FD
Pass-A-Grille Channel Light 10	25505	DBD DEST/LT EXT/HAZ NAV	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dent Channel Daybeacon 2	25510.1	STRUCT DEST	PA
Dent'S Channel Daybeacon 5	25520	STRUCT DEST	PA
Dent'S Channel Daybeacon 6	25525	STRUCT DEST	PA
Dent'S Channel Daybeacon 6	25525	DBD DEST	PA



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pass-A-Grille/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.6755° N / 82.75512° W Aid Name: Pass-A-Grille Channel Daybeacon 3 LLNR: 25470 Discrepancy Information: Initial Report DTG: 021629Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.6755, Longitude: -82.75512]
Pass-A-Grille/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.67754° N / 82.74454° W Aid Name: Pass-A-Grille Channel Daybeacon 7A LLNR: 25485 Discrepancy Information: Initial Report DTG: 021634Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.67754, Longitude: -82.74454]
Pass-A-Grille/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.67542° N / 82.74904° W Aid Name: Pass-A-Grille Channel Light 7 LLNR: 25480 Discrepancy Information: Initial Report DTG: 021631Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.67542, Longitude: -82.74904]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pass-A-Grille/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.67616° N / 82.7588° W Aid Name: Pass-A-Grille Channel Daybeacon 1 LLNR: 25460 Discrepancy Information: Initial Report DTG: 021826Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 291155Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.67616, Longitude: -82.7588]
Pass-A-Grille/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.68125° N / 82.73207° W Aid Name: Pass-A-Grille Channel Light 10 LLNR: 25505 Discrepancy Information: Initial Report DTG: 021828Z OCT 2024 Summary: DBD DEST/LT EXT/HAZ NAV	POINT [Latitude: 27.68125, Longitude: -82.73207]
Pass-A-Grille/ATON/PATON Discrepancies	PATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.67694° N / 82.72944° W Aid Name: Dent'S Channel Daybeacon 6 LLNR: 25525 Discrepancy Information: Initial Report DTG: 302208Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.67694, Longitude: -82.72944]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Pass-A-Grille/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.67833° N / 82.73056° W Aid Name: Dent'S Channel Daybeacon 5 LLNR: 25520 Discrepancy Information: Initial Report DTG: 302207Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.67833, Longitude: -82.73056]

# Peace River

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Park Channel Daybeacon 4	20455	STRUCT DEST	PA
Ponce De Leon Park Channel Light 9	20470	LT EXT	PA
Ponce de Leon Park Channel Daybeacon 18	20474.5	STRUCT DEST	PA
Elkcam Waterway Light 1	20905	LT EXT	PA
Manchester Waterway Daybeacon 14	20981.5	STRUCT DEST	PA
Manchester Waterway Daybeacon 17	20981.9	STRUCT DEST	PA
Countryman Waterway Channel Daybeacon 3	20990	DAYMK MISSING	PA
Countryman Waterway Channel Daybeacon 6	20997	STRUCT DEST	PA
Sunrise Waterway Daybeacon 2	21020	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 21	21056.8	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 23	21056.9	STRUCT DMGD	PA
Spring Lake Waterway Daybeacon 27	21057.2	STRUCT DEST	PA
Peace River (North Section) Daybeacon 7	21210	OFF STA	PA
Peace River (North Section) Daybeacon 9	21215	OFF STA	PA
Peace River (North Section) Daybeacon 10	21220	STRUCT DEST	PA
Peace River (North Section) Daybeacon 11	21225	OFF STA	PA
Peace River (North Section) Daybeacon 14	21235	STRUCT DEST	PA

---

---

---

---

---

---

---

## Peck Lake

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
North Jupiter Narrows Light 15	46035	DAYMK IMCH	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Great Pocket - Peck Lake/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 27.12823° N / 80.15089° W Aid Name: North Jupiter Narrows Light 15 LLNR: 46035 Discrepancy Information: Initial Report DTG: 120045Z OCT 2024 Summary: DAYMK IMCH	POINT [Latitude: 27.12823, Longitude: -80.15089]

## Pine Island Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pine Island Sound Light 11	55295	DBD DEST	FD
Pine Island Sound Daybeacon 13A	55405	DBD DEST	FD
Pine Island Sound Light 20	55425	STRUCT DEST/HAZ NAV/TRLB	FD
Pine Island Sound Daybeacon 34	55590	DBD DEST	FD
Pine Island Sound Light 45A	55900	DBD DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Paradise Canal Daybeacon 1	55310	DAYMK MISSING	PA
Paradise Canal Daybeacon 2	55315	DAYMK MISSING	PA
Paradise Canal Daybeacon 3	55320	STRUCT DEST	PA
Paradise Canal Daybeacon 5	55330	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 1	55915	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 3	55923	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 5	55925	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 4	55930	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 7	55933	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 9	55935	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 11	55940	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 12	55950	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 17	55960	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 19	55965	DAYMK MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.64237° N / 82.21596° W Aid Name: Pine Island Sound Daybeacon 56 LLNR: 56010 Discrepancy Information: Initial Report DTG: 141909Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.64237, Longitude: -82.21596]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.59325° N / 82.19532° W Aid Name: Pine Island Sound Light 45A LLNR: 55900 Discrepancy Information: Initial Report DTG: 141909Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.59325, Longitude: -82.19532]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.57708° N / 82.1845° W Aid Name: Pine Island Sound Daybeacon 44 LLNR: 55895 Discrepancy Information: Initial Report DTG: 141911Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.57708, Longitude: -82.1845]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.57078° N / 82.18033° W Aid Name: Pine Island Sound Daybeacon 42 LLNR: 55885 Discrepancy Information: Initial Report DTG: 141912Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.57078, Longitude: -82.18033]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.53205° N / 82.15673° W Aid Name: Pine Island Sound Daybeacon 34 LLNR: 55590 Discrepancy Information: Initial Report DTG: 141914Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.53205, Longitude: -82.15673]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.65102° N / 82.21832° W Aid Name: Pine Island Sound Daybeacon 58 LLNR: 56025 Discrepancy Information: Initial Report DTG: 141907Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 26.65102, Longitude: -82.21832]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.53777° N / 82.16017° W Aid Name: Pine Island Sound Daybeacon 36 LLNR: 55600 Discrepancy Information: Initial Report DTG: 141912Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 26.53777, Longitude: -82.16017]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.64635° N / 82.21872° W Aid Name: Pine Island Sound Daybeacon 56A LLNR: 56015 Discrepancy Information: Initial Report DTG: 141908Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.64635, Longitude: -82.21872]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.57627° N / 82.18499° W Aid Name: Pine Island Sound Daybeacon 43 LLNR: 55890 Discrepancy Information: Initial Report DTG: 141910Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.57627, Longitude: -82.18499]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.53742° N / 82.16079° W Aid Name: Pine Island Sound Daybeacon 35 LLNR: 55595 Discrepancy Information: Initial Report DTG: 141913Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.53742, Longitude: -82.16079]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.50827° N / 82.14961° W Aid Name: Pine Island Sound Daybeacon 28 LLNR: 55565 Discrepancy Information: Initial Report DTG: 141914Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.50827, Longitude: -82.14961]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.4793° N / 82.11051° W Aid Name: Pine Island Sound Light 20 LLNR: 55425 Discrepancy Information: Initial Report DTG: 141915Z OCT 2024 Summary: STRUCT DEST/HAZ NAV	POINT [Latitude: 26.4793, Longitude: -82.11051]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.47691° N / 82.08557° W Aid Name: Pine Island Sound Daybeacon 13A LLNR: 55405 Discrepancy Information: Initial Report DTG: 141916Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.47691, Longitude: -82.08557]
San Carlos Bay - Pine Island Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 26.48459° N / 82.06469° W Aid Name: Pine Island Sound Light 11 LLNR: 55295 Discrepancy Information: Initial Report DTG: 141917Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.48459, Longitude: -82.06469]

## Pithlachascotee River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pithlachascotee River Light 30	26720	DAYMK MISSING	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pithlachascotee River Daybeacon 43	26765	STRUCT DEST	PA
Pithlachascotee River Daybeacon 48	26780	STRUCT DEST/HAZ NAV	PA
Pithlachascotee River Daybeacon 51	26790	STRUCT DEST	PA
Pithlachascotee River Daybeacon 56	26805	STRUCT DEST	PA

## Point Pinellas Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Point Pinellas Channel Light 2	24705	STRUCT DEST	FD
Point Pinellas Channel Light 6	24725	STRUCT DEST	FD
Point Pinellas Channel Light 6	24725	STRUCT MISSING	FD
Point Pinellas Channel Light 7	24735	DAYMK MISSING/STRUCT DMGD	FD
Point Pinellas Channel Light 7	24735	STRUCT MISSING/TRLB	FD
Point Pinellas Channel Light 9	24735.1	STRUCT MISSING	FD
Point Pinellas Channel Light 10	24735.2	STRUCT MISSING/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Bayou Approach Daybeacon 3	24765	DAYMK MISSING	PA

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Little Bayou Approachroach Daybeacon 9	24780	STRUCT DEST	PA
Coquina Key Cut Daybeacon 3	24835	STRUCT DEST/HAZ NAV	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Point Pinellas Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	<p>ATON/Federal Discrepancies            From: 2024-10-02            To: 2025-03-31            Location:            27.72208° N /            82.60143° W Aid            Name: Point Pinellas Channel Shoal Daybeacon            LLNR: 24730            Discrepancy Information: Initial Report DTG: 021545Z OCT            2024 Summary: DBD DEST</p>	<p>POINT            [Latitude: 27.72208,            Longitude: -82.60143]</p>
Mullet Key Channel - Point Pinellas Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	<p>ATON/Federal Discrepancies            From: 2024-10-14            To: 2025-04-12            Location:            27.71903° N /            82.61067° W Aid            Name: Point Pinellas Channel Light 7            LLNR: 24735            Discrepancy Information: Initial Report DTG: 141927Z OCT            2024 Summary: STRUCT MISSING/TRLB            Temporary Response DTG: 192038Z OCT            2024 Temporary Response: TLB</p>	<p>POINT            [Latitude: 27.71903,            Longitude: -82.61067]</p>
Mullet Key Channel - Point Pinellas Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	<p>ATON/Federal Discrepancies            From: 2024-10-14            To: 2025-04-12            Location:            27.70838° N /            82.60946° W Aid            Name: Point Pinellas Channel Light 6            LLNR: 24725            Discrepancy Information: Initial Report DTG: 141928Z OCT            2024 Summary: STRUCT MISSING</p>	<p>POINT            [Latitude: 27.70838,            Longitude: -82.60946]</p>

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Point Pinellas Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 27.73145° N / 82.61035° W Aid Name: Point Pinellas Channel Light 10 LLNR: 24735.2 Discrepancy Information: Initial Report DTG: 141927Z OCT 2024 Summary: STRUCT MISSING/TRLB Temporary Response DTG: 192039Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.73145, Longitude: -82.61035]
Mullet Key Channel - Point Pinellas Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 27.73143° N / 82.61106° W Aid Name: Point Pinellas Channel Light 9 LLNR: 24735.1 Discrepancy Information: Initial Report DTG: 141926Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.73143, Longitude: -82.61106]
Mullet Key Channel - Point Pinellas Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-25	2025-04-23	ATON/Federal Discrepancies From: 2024-10-25 To: 2025-04-23 Location: 27.70835° N / 82.61041° W Aid Name: Point Pinellas Channel Light 5 LLNR: 24715.5 Discrepancy Information: Initial Report DTG: 251815Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.70835, Longitude: -82.61041]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Point Pinellas Channel/ATON/ Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 11-03	2024- 11-17	ATON/Federal Discrepancies Corrected From: 2024-11-03 To: 2024-11-17 Location: 27.70835° N / 82.61041° W Aid Name: Point Pinellas Channel Light 5 LLNR: 24715.5 Discrepancy Information: Initial Report DTG: 251815Z OCT 2024 Summary: DBD DEST Correction DTG: 040109Z NOV 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.70835, Longitude: -82.61041]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Point Pinellas Channel Light 5	24715.5	WATCHING PROPERLY	FD	2024-11-04
Point Pinellas Channel Light 5	24715.5	WATCHING PROPERLY	FD	2024-11-04

## Ponce De Leon Cut

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Cut Daybeacon 18	40610	STRUCT DEST/TRUB	FD

## Ponce De Leon Inlet

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Inlet North Jetty Light	9520	STRUCT DEST	FD
Ponce De Leon Inlet Light 12	9570	STRUCT DEST/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - Ponce De Leon Inlet/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-11	2025- 04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 29.0786° N / 80.90811° W Aid Name: Ponce De Leon Inlet North Jetty Light LLNR: 9520 Discrepancy Information: Initial Report DTG: 120051Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 29.0786, Longitude: -80.90811]

## Port Everglades

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Port Everglades South Regulatory Light	10349	STRUCT DMGD	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Port Everglades/ATON/Light List Corrections	ATON	Light List Corrections	2024- 10-10	2025- 04-08	ATON/Light List Corrections From: 2024-10-10 To: 2025-04-08 Location: 26.0955° N / 80.09575° W Aid Name: Port Everglades Weather Buoy LLNR: 802	POINT [Latitude: 26.0955, Longitude: -80.09575]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Port Everglades/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	General	Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025-04-18 Location: 26.0961° N / 80.12005° W Orion Marine Construction, Inc. will be starting construction of the above referenced project from the water side using two crane loaded deck barges (999 crane on KS6019 barge and 1250 crane on KS6012 barge) along with four material barges (TBD1 through TBD4); all being serviced by a full-time push boat (TBD5). Orion will be on-site on July 15, 2024, and will start working on all activities related to the replacement of approximately 2300 feet of bulkhead. Hours of operation will be from 7 a.m. to 7 p.m. The estimated completion date is July 1, 2026. All the barges are intended to be spudded around the Port Everglades Berths 1-3 and 1A-1D area (26-05-53.68N / 080-07-12.11W) while working on replacing the bulkhead in those locations. Vessels will be monitoring VHF-FM channel 11.	POINT [Latitude: 26.0961, Longitude: -80.12005]

## Port Manatee Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Port Manatee Channel Outbound Range Rear Light	22558	STRUCT DEST/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Port Manatee Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.63092° N / 82.55918° W Aid Name: Port Manatee Channel Inbound Range Front Light LLNR: 22505 Discrepancy Information: Initial Report DTG: 151116Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.63092, Longitude: -82.55918]
Mullet Key Channel - Port Manatee Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.62702° N / 82.55351° W Aid Name: Port Manatee Channel Inbound Range Rear Light LLNR: 22510 Discrepancy Information: Initial Report DTG: 151117Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.62702, Longitude: -82.55351]
Mullet Key Channel - Port Manatee Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-24	2025-04-22	ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22 Location: 27.6558° N / 82.59682° W Aid Name: Port Manatee Channel Lighted Buoy 6 LLNR: 22527 Discrepancy Information: Initial Report DTG: 241457Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.6558, Longitude: -82.59682]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Port Manatee Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-29	2024- 11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 27.6558° N / 82.59682° W Aid Name: Port Manatee Channel Lighted Buoy 6 LLNR: 22527 Discrepancy Information: Initial Report DTG: 241457Z OCT 2024 Summary: LT EXT Correction DTG: 291327Z OCT 2024 Cause: ATON EQUIPMENT Cause Comments: LED/COMP Correction Status: RELIGHTED	POINT [Latitude: 27.6558, Longitude: -82.59682]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Port Manatee Channel Lighted Buoy 6	22527	RELIGHTED	FD	2024-10-29
Port Manatee Channel Lighted Buoy 6	22527	RELIGHTED	FD	2024-10-29

## Port Royal Sound

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mackay Creek Light 1	4170	LT IMCH/STRUCT DMGD	PA

## Port Sutton Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Sutton Channel Range Front Light	23575	LT IMCH	FD
Port Sutton Channel Range Rear Light	23580	LT IMCH	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Hillsborough Cut D Channel - Port Sutton Channel/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 27.91124° N / 82.42734° W 27.90335° N / 82.42459° W 27.90366° N / 82.43489° W 27.89759° N / 82.43592° W 27.89789° N / 82.44416° W 27.90548° N / 82.44176° W 27.91124° N / 82.42734° W Orion Marine will conduct mechanical clamshell dredge operations at miscellaneous berths and shipping channels within Tampa Harbor, with an anticipated completion date of March 30, 2025. Work hours are 12 hours per day 7 days per week during daylight. Mechanical Clamshell Dredging will be performed within Port Tampa Bay (also inclusive of Port Sutton Channel, Port Sutton Turning Basin, Ybor Channel, Upper and Lower Sparkman Channels, East Bay Channel and Channel Extensions, Port Redwing, and Big Bend Channel). Loaded scow barges will be transported from the dredge areas (above) to the North side of Disposal Island 2D. Material from scow barges will be	POLYGON [Latitude: 27.91124, Longitude: -82.42734] [Latitude: 27.90335, Longitude: -82.42459] [Latitude: 27.90366, Longitude: -82.43489] [Latitude: 27.89759, Longitude: -82.43592] [Latitude: 27.89789, Longitude: -82.44416] [Latitude: 27.90548, Longitude: -82.44176] [Latitude: 27.91124, Longitude: -82.42734]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>slurried and hydraulically pumped to the Disposal Island 2D. via submerged high-density polyethylene pipeline. Approximate Location of Temporary Features North of Disposal Island 2D: BG1A Offloading Barge 230 feet by 60 feet w/ Spuds 27-53-16.90N/82-25-56.78W MP1A Mooring Pile #1A 24 inch Round Steel 27-53-16.65N/082-25-55.62W MP2A Mooring Pile #2A 24 inch Round Steel 27-53-16.45N/082-25-54.78W MP3A Mooring Pile #3A 24 inch Round Steel 27-53-16.31N/082-25-53.88W Pipeline Discharge on 2D 16 inch HDPE Pipe 27-53-00N/082-25-51W Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made on VHF-FM channels 13, 16 or 79 with contact vessel M-1702 (HS Liebherr 895 HD). Floating rubber pipeline and submerged polyethylene pipeline associated with the hydraulic unloading operation(s) at the Disposal Island will be utilized. Pipeline, vessels, and mooring piles will be visibly lighted. For further information contact: Thomas</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					Mitchell at (813) 220-5948 or Brian Yaksh at (904) 236- 0036.	

---



# Port Wentworth Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Kings Island Turning Basin - Port Wentworth Channel/General/Bridges/Conversion	General	Bridges	2024-10-29	2025-02-28	General/Bridges/Conversion From: 2024-10-29 To: 2025-02-28 Location: 32.16542° N / 81.15486° W Bridge Name: 25 State Route Bridge Scott Bridge has been contracted by the Georgia Department of Transportation (GDOT) to replace the SR 25 (Houlihan) Bridge across the Savannah River, mile 21.6, near Port Wentworth, GA. The new bridge will be built upstream of the existing swing bridge. The high- level fixed bridge now spans the navigational channel and provides a fixed vertical clearance 55 feet at Mean Low Water (MLW), 46 feet at Mean High Water (MHW). There will be in- water construction equipment in the vicinity of the bridges 24 hours a day. All in-water equipment is required to be lighted at night. The east channel will be available for navigation unless a channel closure is authorized by the Coast Guard. Mariners will be notified of any future changes to navigation. The project will commence November 1, 2022, and is estimated to be completed February 2025. For	POINT [Latitude: 32.16542, Longitude: -81.15486]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>waterways  questions, please  contact the United  States Coast Guard  at (912) 247-0073.  VHF-FM channel 16  will also be  monitored for any  concerned traffic.  UPDATE 11/5/2024  - The demolition of  existing bridge  substructure and  center pier of the  remaining Houlihan  Bridge is scheduled  to commence from  November 16,  2024, through  January 31, 2024.  During this period,  the river will be  closed for four  hours for  approximately  seven non-  consecutive days.  A safety zone will  be established,  covering all  navigable waters  within a 1,000-yard  radius of the  Houlihan Bridge. If  you plan to  navigate through  this area during  the demolition,  please contact the  Scott Bridge  company and  attending safety  patrol official  Richard Greer at  (334) 740- 0569  for coordination.  Please exercise  extreme caution  while transiting  through the  demolition area as  there will be  construction  equipment in the  vicinity of the  Houlihan Bridge 24  hours a day. All  equipment will be  properly marked  for visibility and  lights will be placed  on the equipment  at night. It is  recommended that  mariners monitor  channels 13, 16,</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					21 and 22a on their VHF radios.	



## Ppg Industries

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ppg Industries Lighted Buoy 1	32150	MISSING	PA
Ppg Industries Lighted Buoy 2	32155	MISSING	PA
PPG Industries Lighted Buoy 3	32160	OFF STA	PA

## Puerto Arecibo

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Puerto Arecibo Buoy 6	30734	OFF STA	FD

## Puerto Del Rey Marina

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bajos Chinchorro Del Sur Light	31380	STRUCT DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Puerto Del Rey Marina/General To Navigation/Hazards	Hazards To General Navigation	Hazards To Navigation	2024-09-26	2025-03-25	<p>The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.</p>	<p>POLYGON            [Latitude: 18.26254, Longitude: -65.60469]            [Latitude: 18.26042, Longitude: -65.57826]            [Latitude: 18.24053, Longitude: -65.57723]            [Latitude: 18.24102, Longitude: -65.60298]            [Latitude: 18.26254, Longitude: -65.60469]</p>

## Puerto Nuevo Channel

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Isla Grande Pier 16 Southeast Light	30920	LT EXT	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Bahia De San Juan - Puerto Nuevo Channel/ATON/Discrepancies Corrected	ATON/Federal	Federal Discrepancies Corrected	2024-10-24	2024-11-07	<p>ATON/Federal Discrepancies Corrected From: 2024-10-24 To: 2024-11-07</p> <p>Location: 18.44379° N / 66.08167° W Aid Name: Puerto Nuevo Channel Range Rear Light LLNR: 30905</p> <p>Discrepancy Information: Initial Report DTG: 241134Z OCT 2024 Summary: LT EXT Correction DTG: 242115Z OCT 2024 Cause: POWER,SOLAR/BATT Cause Comments: SOLAR BATT MALF Correction Status: RELIGHTED</p>	POINT [Latitude: 18.44379, Longitude: -66.08167]
Bahia De San Juan - Puerto Nuevo Channel/ATON/Discrepancies	ATON/Federal	Federal Discrepancies	2024-10-24	2025-04-22	<p>ATON/Federal Discrepancies From: 2024-10-24 To: 2025-04-22</p> <p>Location: 18.44379° N / 66.08167° W Aid Name: Puerto Nuevo Channel Range Rear Light LLNR: 30905</p> <p>Discrepancy Information: Initial Report DTG: 241134Z OCT 2024 Summary: LT EXT</p>	POINT [Latitude: 18.44379, Longitude: -66.08167]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Puerto Nuevo Channel Range Rear Light	30905	RELIGHTED	FD	2024-10-24
Puerto Nuevo Channel Range Rear Light	30905	RELIGHTED	FD	2024-10-24

## Punta Gorda

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Punta Gorda East Jetty Light	31180	STRUCT DEST	PA
Punta Gorda West Jetty Light	31185	STRUCT DEST	PA
Punta Gorda East Seawall Light	31190	STRUCT DEST	PA
Punta Gorda West Seawall Light	31195	STRUCT DEST	PA

## Radas Roosevelt Passage

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Vieques Naval Pier Light (2)	31590	LT EXT	PA
Vieques Naval Breakwater Light	31595	LT EXT	PA

## Redfish Pass

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Boca Grande Light	1305	NIGHT LT BURNING DAY	FD

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redfish Pass Lighted Buoy 1	1255	BUOY DMGD	PA
Redfish Pass Buoy 2	1257	BUOY DMGD	PA
Redfish Pass Buoy 4	1260	BUOY DMGD	PA

## Redhook Bay

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redhook Bay Buoy 2	32425	OFF STA	PA

## Riverside

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Riverside Daybeacon 43	8980	STRUCT DEST/TRUB	FD

## Roberts Bay Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dona Bay Channel Daybeacon 6	21455.6	STRUCT DEST	PA
Dona Bay Channel Daybeacon 9	21455.9	STRUCT DEST	PA
Dona Bay Channel Daybeacon 10	21456	STRUCT DEST/HAZ NAV	PA
Higel Park North Channel Buoy 1	57776	MISSING	PA
Higel Park North Channel Buoy 3	57777	MISSING	PA

## Rockdedundy River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rockdedundy River Daybeacon 188	36850	STRUCT DEST/TRUB	FD

## Rocky Reef

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Reef Daybeacon 12	51235	STRUCT DEST	FD

## San Antonio Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Antonio Channel Pier 3 West Obstruction Light	31110	LT EXT	PA

## San Carlos Bay

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Carlos Bay Light SC	17990	DBD DEST	FD

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
San Carlos Bay Channel Light 10	18035	STRUCT MISSING	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Port Sanibel Marina Daybeacon 12	18068.1	HAZ NAV/DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 26	18069.3	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 30	18069.5	DAYMK DMGD	PA
Port Sanibel Marina Daybeacon 33	18069.7	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 42	18069.98	DAYMK MISSING	PA



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.41896° N / 81.95914° W Aid Name: San Carlos Bay Light SC LLNR: 17990 Discrepancy Information: Initial Report DTG: 041636Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.41896, Longitude: -81.95914]
San Carlos Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.43442° N / 81.96481° W Aid Name: San Carlos Bay Channel Light 2 LLNR: 18000 Discrepancy Information: Initial Report DTG: 041635Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 26.43442, Longitude: -81.96481]
San Carlos Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 26.43226° N / 81.96882° W Aid Name: San Carlos Bay Daybeacon 1 LLNR: 17995 Discrepancy Information: Initial Report DTG: 041636Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 26.43226, Longitude: -81.96882]
San Carlos Bay/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 26.47777° N / 82.01065° W Aid Name: San Carlos Bay Channel Light 10 LLNR: 18035 Discrepancy Information: Initial Report DTG: 151640Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 26.47777, Longitude: -82.01065]



## San Sebastian River

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
San Sebastian River Daybeacon 20	39170	STRUCT DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Matanzas River - San Sebastian River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 29.87913° N / 81.31562° W Aid Name: San Sebastian River Daybeacon 15 LLNR: 39155 Discrepancy Information: Initial Report DTG: 151808Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.87913, Longitude: -81.31562]
Matanzas River - San Sebastian River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 29.88015° N / 81.31849° W Aid Name: San Sebastian River Daybeacon 18 LLNR: 39165 Discrepancy Information: Initial Report DTG: 151806Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.88015, Longitude: -81.31849]
Matanzas River - San Sebastian River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 29.88473° N / 81.32275° W Aid Name: San Sebastian River Daybeacon 30 LLNR: 39195 Discrepancy Information: Initial Report DTG: 151807Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.88473, Longitude: -81.32275]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Matanzas River - San Sebastian River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.88473° N / 81.32275° W Aid Name: San Sebastian River Daybeacon 30 LLNR: 39195 Discrepancy Information: Initial Report DTG: 151807Z OCT 2024 Summary: STRUCT MISSING Correction DTG: 232314Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.88473, Longitude: -81.32275]
Matanzas River - San Sebastian River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.87913° N / 81.31562° W Aid Name: San Sebastian River Daybeacon 15 LLNR: 39155 Discrepancy Information: Initial Report DTG: 151808Z OCT 2024 Summary: STRUCT MISSING Correction DTG: 232312Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.87913, Longitude: -81.31562]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Matanzas River - San Sebastian River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 29.88015° N / 81.31849° W Aid Name: San Sebastian River Daybeacon 18 LLNR: 39165 Discrepancy Information: Initial Report DTG: 151806Z OCT 2024 Summary: STRUCT MISSING Correction DTG: 232313Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 29.88015, Longitude: -81.31849]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
San Sebastian River Daybeacon 15	39155	WATCHING PROPERLY	FD	2024-10-23
San Sebastian River Daybeacon 15	39155	WATCHING PROPERLY	FD	2024-10-23
San Sebastian River Daybeacon 18	39165	WATCHING PROPERLY	FD	2024-10-23
San Sebastian River Daybeacon 18	39165	WATCHING PROPERLY	FD	2024-10-23
San Sebastian River Daybeacon 30	39195	WATCHING PROPERLY	FD	2024-10-23
San Sebastian River Daybeacon 30	39195	WATCHING PROPERLY	FD	2024-10-23

## Sand Key

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sand Key Light 13	61410	DBD DEST/STRUCT DMGD	FD
Sand Key Light 13	61410	DBD DEST	FD
Sand Key Daybeacon 19A	61440.5	DBD DEST	FD
Sand Key Daybeacon 19A	61440.5	DBD DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bay Pines Channel Daybeacon 1	61225	STRUCT DEST	PA
Bay Pines Channel Daybeacon 7	61240	STRUCT DEST	PA
Bay Pines Channel Daybeacon 9	61245	DBD DEST	PA
Bay Pines Channel Daybeacon 15	61260	DBD DEST/STRUCT DMGD	PA
Bay Pines Channel Daybeacon 19	61275	DAYMK MISSING	PA
Bay Pines Channel Daybeacon 19	61275	STRUCT DMGD	PA
Bay Pines Channel Daybeacon 25	61295	DBD DEST	PA
Bay Pines Channel Daybeacon 31	61310	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Johns Pass Channel - Sand Key/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.80868° N / 82.79764° W Aid Name: Sand Key Light 13 LLNR: 61410 Discrepancy Information: Initial Report DTG: 030025Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.80868, Longitude: -82.79764]
Johns Pass Channel - Sand Key/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.82373° N / 82.81301° W Aid Name: Sand Key Daybeacon 19A LLNR: 61440.5 Discrepancy Information: Initial Report DTG: 030026Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.82373, Longitude: -82.81301]
Johns Pass Channel - Sand Key/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.80868° N / 82.79764° W Aid Name: Sand Key Light 13 LLNR: 61410 Discrepancy Information: Initial Report DTG: 011706Z OCT 2024 Summary: DBD DEST/STRUCT DMGD	POINT [Latitude: 27.80868, Longitude: -82.79764]
Johns Pass Channel - Sand Key/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.82373° N / 82.81301° W Aid Name: Sand Key Daybeacon 19A LLNR: 61440.5 Discrepancy Information: Initial Report DTG: 011704Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.82373, Longitude: -82.81301]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.80116° N / 82.76574° W Aid Name: Bay Pines Channel Daybeacon 15 LLNR: 61260 Discrepancy Information: Initial Report DTG: 302203Z OCT 2024 Summary: DBD DEST/STRUCT DMGD	POINT [Latitude: 27.80116, Longitude: -82.76574]
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.79719° N / 82.76427° W Aid Name: Bay Pines Channel Daybeacon 9 LLNR: 61245 Discrepancy Information: Initial Report DTG: 302202Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.79719, Longitude: -82.76427]
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.8028° N / 82.76768° W Aid Name: Bay Pines Channel Daybeacon 19 LLNR: 61275 Discrepancy Information: Initial Report DTG: 302203Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.8028, Longitude: -82.76768]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.81141° N / 82.76438° W Aid Name: Bay Pines Channel Daybeacon 31 LLNR: 61310 Discrepancy Information: Initial Report DTG: 302205Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.81141, Longitude: -82.76438]
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.79303° N / 82.76399° W Aid Name: Bay Pines Channel Daybeacon 1 LLNR: 61225 Discrepancy Information: Initial Report DTG: 302200Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.79303, Longitude: -82.76399]
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.7963° N / 82.76399° W Aid Name: Bay Pines Channel Daybeacon 7 LLNR: 61240 Discrepancy Information: Initial Report DTG: 302201Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.7963, Longitude: -82.76399]
Johns Pass Channel - Sand Key/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.80558° N / 82.76482° W Aid Name: Bay Pines Channel Daybeacon 25 LLNR: 61295 Discrepancy Information: Initial Report DTG: 302204Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.80558, Longitude: -82.76482]





# Sanibel Island

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
San Carlos Bay - Sanibel Island/General/Bridges/Rehabilitation	General	Bridges	2024-10-29	2025-01-31	<p>General/Bridges/Rehabilitation            From: 2024-10-29            To: 2025-01-31            Location:            26.458819° N /            82.03397° W            Bridge Name:            Sanibel Island            Causeway Bridge            "A" Bridge            Superior            Construction on behalf of the bridge owner, Lee County will be performing construction work on the Sanibel Causeway Bridges and surrounding waterway between Fort Myers and Sanibel Island. The scope of work includes driving sheet pile and adding stone at multiple areas to restore the causeway post Hurricane Ian damage. Multiple work barges and smaller vessels will be located in the surrounding area during the course of construction, expected to continue through December 2024. Navigation is not anticipated to be obstructed through the main channels. Punta Rassa Boat Ramp in Fort Myers is closed until further notice and cannot be accessed from the water or roadway.</p>	POINT [Latitude: 26.458819, Longitude: -82.03397]

## Sapelo Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Sound Buoy 2	5840	MISSING	FD
Sapelo Sound Light 138	36630.1	STRUCT DEST/TRLB	FD

## Sheephead Cut

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sheephead Cut Daybeacon 7	40705	STRUCT DEST/TRUB	FD

## Shell Key

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Basin East Daybeacon 1	50540	DAYMK MISSING	PA
Little Basin East Daybeacon 2	50545	STRUCT DEST/HAZ NAV	PA
Little Basin East Daybeacon 4	50555	DAYMK MISSING	PA

## Sherman Cut

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sherman Cut Range Rear Light	7240	STRUCT DEST	FD

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Sherman Cut Range Front Light	RELOCATE	Sherman Cut RFL (LLNR 7235) will be relocated to approximate position: 30-22-44.220N/081-26-46.188W to align with the newly dredged channel. In addition, Sherman Cut RFL will be changed to a 24-hour optic. All day marks will be permanently discontinued.
Sherman Cut Range Rear Light	RELOCATE	Sherman Cut RRL (LLNR 7240) will be relocated to approximate position: 30-22-26.194N/081-27-03.893W to align with the newly dredged channel. In addition Sherman Cut RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.

## Sim-Par Marina Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Marina Bay Channel Daybeacon 4	39715	STRUCT DEST	PA

## Singer Island Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Singer Island Channel Daybeacon 6	10212.3	STRUCT DEST/HAZ NAV/TRLB	FD

## Sisters Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Sisters Creek Daybeacon 80	38320	STRUCT DEST/TRUB	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Johns River - Sisters Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 30.42105° N / 81.45444° W Aid Name: Sisters Creek Daybeacon 80 LLNR: 38320 Discrepancy Information: Initial Report DTG: 152014Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 152014Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 30.42105, Longitude: -81.45444]

-----

--

-----

## Skidaway Narrows

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Skidaway Narrows Daybeacon 60	36140	STRUCT DEST/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Burnside River - Skidaway Narrows/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 31.95518° N / 81.06233° W Aid Name: Skidaway Narrows Daybeacon 60 LLNR: 36140 Discrepancy Information: Initial Report DTG: 011248Z OCT 2024 Summary: STRUCT DEST/TRUB Temporary Response DTG: 011249Z OCT 2024 Temporary Response: TUB BNM 0253-24 CHA	POINT [Latitude: 31.95518, Longitude: -81.06233]



# Skull Creek

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Jenkins Island Flat - Skull Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-16	2025- 04-14	ATON/Federal Discrepancies From: 2024-10-16 To: 2025-04-14 Location: 32.22639° N / 80.77961° W Aid Name: Skull Creek Light 22 LLNR: 35705 Discrepancy Information: Initial Report DTG: 161248Z OCT 2024 Summary: LT EXT	POINT [Latitude: 32.22639, Longitude: -80.77961]
Jenkins Island Flat - Skull Creek/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-30	2024- 11-13	ATON/Federal Discrepancies Corrected From: 2024-10-30 To: 2024-11-13 Location: 32.22639° N / 80.77961° W Aid Name: Skull Creek Light 22 LLNR: 35705 Discrepancy Information: Initial Report DTG: 302128Z OCT 2024 Summary: LT EXT Correction DTG: 302129Z OCT 2024 Cause: POWER,SOLAR/BATT Cause Comments: SOLAR BATT MALF Correction Status: RELIGHTED	POINT [Latitude: 32.22639, Longitude: -80.77961]
Jenkins Island Flat - Skull Creek/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-30	2025- 04-28	ATON/Federal Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 32.22639° N / 80.77961° W Aid Name: Skull Creek Light 22 LLNR: 35705 Discrepancy Information: Initial Report DTG: 302128Z OCT 2024 Summary: LT EXT	POINT [Latitude: 32.22639, Longitude: -80.77961]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Skull Creek Light 22	35705	RELIGHTED	FD	2024-10-30
Skull Creek Light 22	35705	RELIGHTED	FD	2024-10-30

## Snake Creek

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snake Creek Daybeacon 4	12215	STRUCT DEST/TRUB	FD
Snake Creek Daybeacon 5	12225	STRUCT DEST/TRLB	FD
Snake Creek Daybeacon 7	12240	STRUCT DEST/TRUB	FD

## Snapper Creek Marina

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snapper Creek Marina Daybeacon 2	49515	DAYMK MISSING	PA

## Sonde De Vieques

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cayo Lobito Light	31525	STRUCT DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
North St Thomas Lighted Buoy H	31683	OFF STA	PA

## **South Altamaha River**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
South Altamaha River Daybeacon 2A	36990	DBD DEST	FD
South Altamaha River Daybeacon 4	36995	STRUCT MISSING/TRUB/OFF STATION	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Buttermilk Sound - South Altamaha River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 11-04	2025- 05-03	ATON/Federal Discrepancies From: 2024-11-04 To: 2025-05-03 Location: 31.30746° N / 81.41186° W Aid Name: South Altamaha River Daybeacon 2A LLNR: 36990 Discrepancy Information: Initial Report DTG: 041325Z NOV 2024 Summary: DBD DEST	POINT [Latitude: 31.30746, Longitude: -81.41186]
Buttermilk Sound - South Altamaha River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 11-04	2025- 05-03	ATON/Federal Discrepancies From: 2024-11-04 To: 2025-05-03 Location: 31.30664° N / 81.41345° W Aid Name: South Altamaha River Daybeacon 4 LLNR: 36995 Discrepancy Information: Initial Report DTG: 041618Z NOV 2024 Summary: STRUCT MISSING/TRUB/OFF STATION Temporary Response DTG: 041619Z NOV 2024 Temporary Response: TUB	POINT [Latitude: 31.30664, Longitude: -81.41345]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Buttermilk Sound - South Altamaha River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 11-04	2024- 11-18	ATON/Federal Discrepancies Corrected From: 2024-11-04 To: 2024-11-18 Location: 31.30664° N / 81.41345° W Aid Name: South Altamaha River Daybeacon 4 LLNR: 36995 Discrepancy Information: Initial Report DTG: 091707Z JUL 2023 Summary: STRUCT DEST/TRUB Temporary Response DTG: 132106Z JUL 2023 Temporary Response: TUB Correction DTG: 041617Z NOV 2024 Cause: ALLISN/COLLISN Cause Comments: WATERBRN Correction Status: WATCHING PROPERLY	POINT [Latitude: 31.30664, Longitude: -81.41345]

## Federal Discrepancies Corrected

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>	<b>CORRECTION DATE</b>
South Altamaha River Daybeacon 4	36995	WATCHING PROPERLY	FD	2024-11-04

## South Amelia River

### Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Kingsley Creek - South Amelia River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-03	2025- 04-01	ATON/Federal Discrepancies From: 2024-10-03 To: 2025-04-01 Location: 30.53961° N / 81.46536° W Aid Name: South Amelia River Daybeacon 43 LLNR: 38133 Discrepancy Information: Initial Report DTG: 032113Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 30.53961, Longitude: -81.46536]

## South Gandy Channel

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Cross Bayou Daybeacon 2	24430	DBD DEST	PA
Cross Bayou Daybeacon 7	24455	DBD DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cut K Channel - South Gandy Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.93228° N / 82.69383° W Aid Name: Cross Bayou Daybeacon 2 LLNR: 24430 Discrepancy Information: Initial Report DTG: 302212Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.93228, Longitude: -82.69383]
Cut K Channel - South Gandy Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.92433° N / 82.69386° W Aid Name: Cross Bayou Daybeacon 7 LLNR: 24455 Discrepancy Information: Initial Report DTG: 302213Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.92433, Longitude: -82.69386]

## South Newport River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Newport River Daybeacon 136	36625	DAYMK MISSING	FD

## Southwest Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southwest Channel Light 2 (Tampa Bay)	21840	MISSING/TRLB	FD
Southwest Channel Light 2 (Tampa Bay)	21840	STRUCT DEST/TRLB	FD

## St Andrew Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Buoy 29A	37375	MISSING	FD
St Andrew Sound Lighted Buoy 30	37380	OFF STA	FD
St Andrew Sound Lighted Buoy 32	37385	OFF STA	FD

## St Augustine Inlet

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
St Augustine Inlet Buoy 3	9485	MISSING	FD
St Augustine Inlet Buoy 10	9510	OFF STA	FD

## **St Catherines Sound**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
St Catherines Sound Lighted Buoy 2	5795	MISSING	FD
St Catherines Sound Buoy 1	5800	MISSING	FD
St Catherines Sound Buoy 3	5805	MISSING	FD

## **St Helena Sound**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
St Helena Sound Entrance Buoy 4	3965	MISSING	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Hunting Island Pier Light	4070	STRUCT DEST/LT EXT	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - St Helena Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-05	2025-04-03	ATON/Federal Discrepancies From: 2024-10-05 To: 2025-04-03 Location: 32.34008° N / 80.47017° W Aid Name: Old House Creek Buoy 14 LLNR: 4038 Discrepancy Information: Initial Report DTG: 052232Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 32.34008, Longitude: -80.47017]
Sector Charleston, Submerged Land Act (SLA) - St Helena Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-23	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 32.34008° N / 80.47017° W Aid Name: Old House Creek Buoy 14 LLNR: 4038 Discrepancy Information: Initial Report DTG: 052232Z OCT 2024 Summary: OFF STATION Correction DTG: 231532Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 32.34008, Longitude: -80.47017]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Old House Creek Buoy 14	4038	RESET ON STATION	FD	2024-10-23
Old House Creek Buoy 14	4038	RESET ON STATION	FD	2024-10-23

## St Johns River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Johns River Entrance Lighted Buoy 4	7130	OFF STA	FD
St Johns Bluff Light 5	7335	STRUCT DEST/TRLB	FD
Quarantine Island Upper Range Front Light	7450	NIGHT LT BURNING DAY	FD
Winter Point Light 1	7675	STRUCT DEST/TRLB	FD
Winter Point Light 2	7680	STRUCT DEST/TRLB	FD
Ortega River Shoal Daybeacon	7685	STRUCT DEST/TRUB	FD
Red Bay Point Light 22	7895	STRUCT DEST/TRLB	FD
Tocoi Cut Entrance Light 33	7935	HAZ NAV/STRUCT DMGD/TRLB	FD
Forrester Point Upper Range Rear Light	8140	STRUCT DEST	FD
Rivercrest Light 10	8235	LT EXT	FD
Nashua Daybeacon 42A	8390	STRUCT DEST/TRUB	FD
Stephens Point Daybeacon 46	8415	STRUCT DEST/TRUB	FD
Adams Lake Daybeacon 23	8910	STRUCT DEST/HAZ NAV/TRLB	FD
Wekiva Cutoff Daybeacon 95	9155	STRUCT DEST	FD
Wekiva Bend Cutoff Light 96	9160	MISSING/TRLB	FD
Wekiva Bend Cutoff Light 96	9160	STRUCT DEST/HAZ NAV/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ortega River Lighted Buoy 2	7696	MISSING	PA
Ortega River Lighted Buoy 13	7697	MISSING	PA
Goodbys Creek Channel Buoy 4	7765.3	OFF STA	PA
Goodbys Creek Channel Buoy 5	7765.4	OFF STA	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Conversion	General	Bridges	2024-10-29	2025-04-27	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 29.984705° N / 81.618613° W Bridge Name: Shands Bridge FLORIDA - ST JOHNS RIVER - GREEN COVE SPRINGS - SHANDS BRIDGE: Bridge Replacement Johnson Bros. Corporation, on behalf of the bridge owner, Florida Department of Transportation, will be replacing the Shands Bridge (SR 23) across the St. Johns River, mile 50.2, at Green Cove Springs. The project is scheduled to begin on October 2, 2023, and continue until an estimated completion date of September 1, 2030. The new bridge will consist of a vertical clearance of 65 feet and a 150-Ft. horizontal clearance at the navigation channel. Construction will require the use of material storage barges and barge-mounted cranes; all in-water equipment is required to be lighted at night. Work activities on the new bridge will include pier construction, girder erection, fender system installation, and overhead deck operations that could present a hazard to marine traffic. This phase will require periodic	POINT [Latitude: 29.984705, Longitude: -81.618613]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>channel restrictions or short-term closures and is tentatively scheduled to take place in 2027. Short-term channel closures will also be required during the demolition of the existing structure tentatively scheduled to take place in 2029. The existing bridge will be removed except for approximately 800 LF on each end, which will remain and be converted to recreational fishing piers. For further information contact Don Davis, Project Manager at (904) 545-3807 or <a href="mailto:donalddavis@southlandholdings.com">donalddavis@southlandholdings.com</a>. For waterway questions please contact USCG Sector Jacksonville Waterways via email at <a href="mailto:D07-DGSECJAX-WATERWAYS@uscg.mil">D07-DGSECJAX-WATERWAYS@uscg.mil</a></p>	

---

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Temp Deviation	General	Bridges	2024- 10-29	2024- 11-10	<p>General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-11-10 Location: 30.322535° N / 81.65854° W Bridge Name: Main St Bridge Florida Department of Transportation (FDOT) is authorized to temporarily deviate from drawbridge operation regulation 33 CFR 117.325 (a) that governs the Main Street (US1/US90) Drawbridge, mile 24.7 on the St Johns River, at Jacksonville, Florida. Under this temporary deviation, the Main Street (US1/US90) Bridge is allowed to remain closed to navigation including tugs and tugs with tows on Saturday November 9, 2024, from 7:30 a.m. to 8:30 a.m. to facilitate the Armed Forces 10K Tri- Bridge Challenge. Public vessels of the United States and vessels in distress shall be passed at any time. For waterways questions, please contact Coast Guard Sector Jacksonville Waterways Management Division at (904) 714-7631 or via email at D07-DG- SECJAX- WATERWAYS@uscg.mil</p>	POINT [Latitude: 30.322535, Longitude: -81.65854]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Conversion	General	Bridges	2024-10-29	2024-11-16	<p>General/Bridges/Conversion            From: 2024-10-29            To: 2024-11-16            Location:            29.008631° N /            81.382224° W            Bridge Name:            Whitehair Bridge            The new high-level fixed SR 44 / Whitehair Bridge, across the St. Johns River, mile 146.0, near Deland, FL was completed immediately south of the original drawbridge with a vertical clearance is 45.6 feet above normal high water, and horizontal clearance of 115 feet between the fenders. The entire structure is expected to be removed on or about November 4, 2024. A crane barge is on location outside of the navigable channel but will be moved into the channel intermittently. All boaters are advised to transit the area with caution and at a slow speed. For waterways related questions, contact Coast Guard Sector Jacksonville Waterways Management Division at (904)714-7631 or via email at D07-DG-SECJAX-WATERWAYS@uscg.mil</p>	POINT [Latitude: 29.008631, Longitude: -81.382224]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-13	2025-04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 30.40393° N / 81.42768° W Aid Name: St Johns Bar Cut Range Front Light LLNR: 7115 Discrepancy Information: Initial Report DTG: 132225Z OCT 2024 Summary: LT EXT	POINT [Latitude: 30.40393, Longitude: -81.42768]
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 30.39996° N / 81.37366° W Aid Name: St Johns River Lighted Bell Buoy 6 LLNR: 7140 Discrepancy Information: Initial Report DTG: 011229Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 30.39996, Longitude: -81.37366]
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 30.06731° N / 81.68757° W Aid Name: Hibernia Daybeacon 16 LLNR: 7860 Discrepancy Information: Initial Report DTG: 120022Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 30.06731, Longitude: -81.68757]
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 30.39654° N / 81.37388° W Aid Name: St Johns River Lighted Buoy 5 LLNR: 7135 Discrepancy Information: Initial Report DTG: 011220Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 30.39654, Longitude: -81.37388]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-17	2025-04-15	ATON/Federal Discrepancies From: 2024-10-17 To: 2025-04-15 Location: 30.06731° N / 81.68757° W Aid Name: Hibernia Daybeacon 16 LLNR: 7860 Discrepancy Information: Initial Report DTG: 171740Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 30.06731, Longitude: -81.68757]
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-22	2025-04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 30.40393° N / 81.42768° W Aid Name: St Johns Bar Cut Range Front Light LLNR: 7115 Discrepancy Information: Initial Report DTG: 222048Z OCT 2024 Summary: LT EXT	POINT [Latitude: 30.40393, Longitude: -81.42768]
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-22	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-22 To: 2024-11-06 Location: 30.39654° N / 81.37388° W Aid Name: St Johns River Lighted Buoy 5 LLNR: 7135 Discrepancy Information: Initial Report DTG: 011220Z OCT 2024 Summary: OFF STATION Correction DTG: 231106Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 30.39654, Longitude: -81.37388]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-22	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 30.39996° N / 81.37366° W Aid Name: St Johns River Lighted Bell Buoy 6 LLNR: 7140 Discrepancy Information: Initial Report DTG: 011229Z OCT 2024 Summary: OFF STATION Correction DTG: 231110Z OCT 2024 Cause: WEATHER Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 30.39996, Longitude: -81.37366]
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-22	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 30.39654° N / 81.37388° W Aid Name: St Johns River Lighted Buoy 5 LLNR: 7135 Discrepancy Information: Initial Report DTG: 152232Z AUG 2024 Summary: OFF STA Correction DTG: 231108Z OCT 2024 Cause: WEATHER Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 30.39654, Longitude: -81.37388]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Johns Bar Cut Range Front Light	7115	RELIGHTED	FD	2024-10-22
St Johns River Lighted Buoy 5	7135	RESET ON STATION	FD	2024-10-23
St Johns River Lighted Buoy 5	7135	RESET ON STATION	FD	2024-10-23
St Johns River Lighted Buoy 5	7135	RESET ON STATION	FD	2024-10-23
St Johns River Lighted Bell Buoy 6	7140	RESET ON STATION	FD	2024-10-23
St Johns River Lighted Bell Buoy 6	7140	RESET ON STATION	FD	2024-10-23

--

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Training Wall Range Front Light	RELOCATE	Training Wall RFL (LLNR 7295) will be relocated to approximate position: 30-23-48.120N/081-28-41.707W to align with the newly dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.
Training Wall Range Rear Light	RELOCATE	Training Wall RRL (LLNR 7300) will be relocated to approximate position: 30-23-57.479N/081-28-54.848W to align with the newly dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.
St Johns Bluff Lighted Buoy 30	RELOCATE	St. Johns Bluff LB 30 (LLNR 7329) will be permanently relocated to 30-23-32.020N/081-29-29.730W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.

# St Joseph Sound

## Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Joseph Sound Daybeacon 1	61850	STRUCT MISSING	FD
St Joseph Sound Daybeacon 9	61885	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 15	61970	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 21	62035	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 38	62275	STRUCT DEST/HAZ NAV/TRLB	FD
St Joseph Sound Daybeacon 40	62285	STRUCT DEST/HAZ NAV/TRLB	FD

## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Safety Harbor Marina Light 2	24375	DAYMK MISSING	PA
Safety Harbor Marina Daybeacon 3	24380	DAYMK DMGD	PA
Safety Harbor Marina Daybeacon 4	24385	DAYMK MISSING	PA
Hurricane Pass Daybeacon 1	25975	DBD DEST	PA
Hurricane Pass Daybeacon 2	25980	STRUCT DEST	PA
Hurricane Pass Buoy 3	25985	MISSING	PA
Hurricane Pass Daybeacon 4	25990	DBD DEST	PA
Hurricane Pass Daybeacon 5A	25997	STRUCT DEST	PA
Hurricane Pass Daybeacon 7	26005	DBD DEST/STRUCT DMGD	PA
Hurricane Pass Daybeacon 7A	26007	STRUCT DMGD	PA
Hurricane Pass Daybeacon 11	26020	DBD DEST	PA
Caladesi Island Channel Daybeacon 7	61935	DAYMK MISSING	PA
Caladesi Island Channel Daybeacon 12	61955	DAYMK MISSING	PA

## ATON Changes

NAME	ACTION TYPE	DESCRIPTION
St Joseph Sound Lighted Buoy 35B	RELOCATE	ATON/ATON Changes From: 2024-10-29 To: 2025-04-27 Location: 28.13282° N / 82.82389° W Aid Name: St Joseph Sound Lighted Buoy 35B LLNR: 62266 Action: RELOCATE

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05183° N / 82.82922° W Aid Name: Hurricane Pass Daybeacon 4 LLNR: 25990 Discrepancy Information: Initial Report DTG: 302153Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.05183, Longitude: -82.82922]
ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05214° N / 82.8315° W Aid Name: Hurricane Pass Daybeacon 2 LLNR: 25980 Discrepancy Information: Initial Report DTG: 302151Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.05214, Longitude: -82.8315]
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05222° N / 82.82742° W Aid Name: Hurricane Pass Buoy 3 LLNR: 25985 Discrepancy Information: Initial Report DTG: 302153Z OCT 2024 Summary: MISSING	POINT [Latitude: 28.05222, Longitude: -82.82742]
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05278° N / 82.81833° W Aid Name: Hurricane Pass Daybeacon 5A LLNR: 25997 Discrepancy Information: Initial Report DTG: 302154Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.05278, Longitude: -82.81833]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05325° N / 82.80667° W Aid Name: Hurricane Pass Daybeacon 11 LLNR: 26020 Discrepancy Information: Initial Report DTG: 302156Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.05325, Longitude: -82.80667]
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05456° N / 82.83144° W Aid Name: Hurricane Pass Daybeacon 1 LLNR: 25975 Discrepancy Information: Initial Report DTG: 302151Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.05456, Longitude: -82.83144]
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05389° N / 82.81594° W Aid Name: Hurricane Pass Daybeacon 7 LLNR: 26005 Discrepancy Information: Initial Report DTG: 302155Z OCT 2024 Summary: DBD DEST/STRUCT DMGD	POINT [Latitude: 28.05389, Longitude: -82.81594]
Clearwater Harbor - St Joseph Sound/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 28.05525° N / 82.81342° W Aid Name: Hurricane Pass Daybeacon 7A LLNR: 26007 Discrepancy Information: Initial Report DTG: 302155Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 28.05525, Longitude: -82.81342]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.99139° N / 82.80111° W Aid Name: St Joseph Sound Daybeacon 1 LLNR: 61850 Discrepancy Information: Initial Report DTG: 030003Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.99139, Longitude: -82.80111]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.00922° N / 82.79903° W Aid Name: St Joseph Sound Light 4 LLNR: 61865 Discrepancy Information: Initial Report DTG: 030004Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.00922, Longitude: -82.79903]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.03759° N / 82.79697° W Aid Name: St Joseph Sound Light 12 LLNR: 61900 Discrepancy Information: Initial Report DTG: 030006Z OCT 2024 Summary: LT EXT	POINT [Latitude: 28.03759, Longitude: -82.79697]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.05752° N / 82.79625° W Aid Name: St Joseph Sound Daybeacon 19 LLNR: 62030 Discrepancy Information: Initial Report DTG: 030008Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.05752, Longitude: -82.79625]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.08341° N / 82.80772° W Aid Name: St Joseph Sound Daybeacon 27 LLNR: 62100 Discrepancy Information: Initial Report DTG: 030009Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.08341, Longitude: -82.80772]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.10304° N / 82.81404° W Aid Name: St Joseph Sound Daybeacon 30 LLNR: 62115 Discrepancy Information: Initial Report DTG: 030012Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.10304, Longitude: -82.81404]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.10972° N / 82.81692° W Aid Name: St Joseph Sound Light 31 LLNR: 62120 Discrepancy Information: Initial Report DTG: 030013Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.10972, Longitude: -82.81692]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.09594° N / 82.81207° W Aid Name: St Joseph Sound Daybeacon 29 LLNR: 62110 Discrepancy Information: Initial Report DTG: 030011Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.09594, Longitude: -82.81207]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.13282° N / 82.82389° W Aid Name: St Joseph Sound Lighted Buoy 35B LLNR: 62266 Discrepancy Information: Initial Report DTG: 030016Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 28.13282, Longitude: -82.82389]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.15139° N / 82.83109° W Aid Name: St Joseph Sound Daybeacon 40 LLNR: 62285 Discrepancy Information: Initial Report DTG: 030020Z OCT 2024 Summary: STRUCT DEST/HAZ NAV/TRLB Temporary Response DTG: 291202Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 28.15139, Longitude: -82.83109]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.01582° N / 82.799° W Aid Name: St Joseph Sound Daybeacon 7 LLNR: 61875 Discrepancy Information: Initial Report DTG: 030007Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.01582, Longitude: -82.799]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.13765° N / 82.82676° W Aid Name: St Joseph Sound Daybeacon 37 LLNR: 62270 Discrepancy Information: Initial Report DTG: 030015Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.13765, Longitude: -82.82676]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.1515° N / 82.83161° W Aid Name: St Joseph Sound Light 39 LLNR: 62280 Discrepancy Information: Initial Report DTG: 030019Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.1515, Longitude: -82.83161]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.15708° N / 82.83357° W Aid Name: St Joseph Sound Daybeacon 41 LLNR: 62290 Discrepancy Information: Initial Report DTG: 030022Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.15708, Longitude: -82.83357]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 28.16103° N / 82.833° W Aid Name: St Joseph Sound Light 44 LLNR: 62300 Discrepancy Information: Initial Report DTG: 030023Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.16103, Longitude: -82.833]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-25	2024-11-08	ATON/Federal Discrepancies Corrected From: 2024-10-25 To: 2024-11-08 Location: 28.14477° N / 82.82871° W Aid Name: St Joseph Sound Daybeacon 38 LLNR: 62275 Discrepancy Information: Initial Report DTG: 251217Z OCT 2024 Summary: STRUCT DEST Correction DTG: 251230Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.14477, Longitude: -82.82871]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-27	2025-04-25	ATON/Federal Discrepancies From: 2024-10-27 To: 2025-04-25 Location: 28.0219° N / 82.79801° W Aid Name: St Joseph Sound Daybeacon 8 LLNR: 61880 Discrepancy Information: Initial Report DTG: 271445Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.0219, Longitude: -82.79801]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-27	2025-04-25	ATON/Federal Discrepancies From: 2024-10-27 To: 2025-04-25 Location: 28.14477° N / 82.82871° W Aid Name: St Joseph Sound Daybeacon 38 LLNR: 62275 Discrepancy Information: Initial Report DTG: 271452Z OCT 2024 Summary: STRUCT DEST/HAZ NAV/TRLB Temporary Response DTG: 271452Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 28.14477, Longitude: -82.82871]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/ Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-29	2024- 11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.10304° N / 82.81404° W Aid Name: St Joseph Sound Daybeacon 30 LLNR: 62115 Discrepancy Information: Initial Report DTG: 030012Z OCT 2024 Summary: DBD DEST Correction DTG: 291739Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.10304, Longitude: -82.81404]
Clearwater Harbor - St Joseph Sound/ATON/ Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-29	2024- 11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.13765° N / 82.82676° W Aid Name: St Joseph Sound Daybeacon 37 LLNR: 62270 Discrepancy Information: Initial Report DTG: 030015Z OCT 2024 Summary: DBD DEST Correction DTG: 291740Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.13765, Longitude: -82.82676]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.1515° N / 82.83161° W Aid Name: St Joseph Sound Light 39 LLNR: 62280 Discrepancy Information: Initial Report DTG: 030019Z OCT 2024 Summary: DBD DEST Correction DTG: 291741Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.1515, Longitude: -82.83161]
Clearwater Harbor - St Joseph Sound/ATON/Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-27	2024-11-10	ATON/Federal Discrepancies Corrected From: 2024-10-27 To: 2024-11-10 Location: 28.0219° N / 82.79801° W Aid Name: St Joseph Sound Daybeacon 8 LLNR: 61880 Discrepancy Information: Initial Report DTG: 271445Z OCT 2024 Summary: DBD DEST Correction DTG: 271446Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.0219, Longitude: -82.79801]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-27	2024-11-10	ATON/Federal Discrepancies Corrected From: 2024-10-27 To: 2024-11-10 Location: 28.14477° N / 82.82871° W Aid Name: St Joseph Sound Daybeacon 38 LLNR: 62275 Discrepancy Information: Initial Report DTG: 030018Z OCT 2024 Summary: STRUCT DEST Correction DTG: 271455Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.14477, Longitude: -82.82871]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.13282° N / 82.82389° W Aid Name: St Joseph Sound Lighted Buoy 35B LLNR: 62266 Discrepancy Information: Initial Report DTG: 030016Z OCT 2024 Summary: OFF STATION Correction DTG: 291511Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 28.13282, Longitude: -82.82389]
Clearwater Harbor - St Joseph Sound/ATON/ATON Changes	ATON	ATON Changes	2024-10-29	2025-04-27	ATON/ATON Changes From: 2024-10-29 To: 2025-04-27 Location: 28.13282° N / 82.82389° W Aid Name: St Joseph Sound Lighted Buoy 35B LLNR: 62266 Action: RELOCATE	POINT [Latitude: 28.13282, Longitude: -82.82389]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.00922° N / 82.79903° W Aid Name: St Joseph Sound Light 4 LLNR: 61865 Discrepancy Information: Initial Report DTG: 030004Z OCT 2024 Summary: DBD DEST Correction DTG: 291734Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.00922, Longitude: -82.79903]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.01582° N / 82.799° W Aid Name: St Joseph Sound Daybeacon 7 LLNR: 61875 Discrepancy Information: Initial Report DTG: 030007Z OCT 2024 Summary: DBD DEST Correction DTG: 291735Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.01582, Longitude: -82.799]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.03759° N / 82.79697° W Aid Name: St Joseph Sound Light 12 LLNR: 61900 Discrepancy Information: Initial Report DTG: 030006Z OCT 2024 Summary: LT EXT Correction DTG: 291736Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RELIGHTED	POINT [Latitude: 28.03759, Longitude: -82.79697]
Clearwater Harbor - St Joseph Sound/ATON/Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.05752° N / 82.79625° W Aid Name: St Joseph Sound Daybeacon 19 LLNR: 62030 Discrepancy Information: Initial Report DTG: 030008Z OCT 2024 Summary: DBD DEST Correction DTG: 291736Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.05752, Longitude: -82.79625]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.09594° N / 82.81207° W Aid Name: St Joseph Sound Daybeacon 29 LLNR: 62110 Discrepancy Information: Initial Report DTG: 030011Z OCT 2024 Summary: DBD DEST Correction DTG: 291738Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.09594, Longitude: -82.81207]
Clearwater Harbor - St Joseph Sound/ATON/Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.08341° N / 82.80772° W Aid Name: St Joseph Sound Daybeacon 27 LLNR: 62100 Discrepancy Information: Initial Report DTG: 030009Z OCT 2024 Summary: DBD DEST Correction DTG: 291737Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.08341, Longitude: -82.80772]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON/Federal	Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.10972° N / 82.81692° W Aid Name: St Joseph Sound Light 31 LLNR: 62120 Discrepancy Information: Initial Report DTG: 030013Z OCT 2024 Summary: DBD DEST Correction DTG: 291740Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.10972, Longitude: -82.81692]
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON/Federal	Discrepancies Corrected	2024-10-29	2024-11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.15708° N / 82.83357° W Aid Name: St Joseph Sound Daybeacon 41 LLNR: 62290 Discrepancy Information: Initial Report DTG: 030022Z OCT 2024 Summary: DBD DEST Correction DTG: 291742Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.15708, Longitude: -82.83357]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-29	2024- 11-12	ATON/Federal Discrepancies Corrected From: 2024-10-29 To: 2024-11-12 Location: 28.16103° N / 82.833° W Aid Name: St Joseph Sound Light 44 LLNR: 62300 Discrepancy Information: Initial Report DTG: 030023Z OCT 2024 Summary: DBD DEST Correction DTG: 291742Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 28.16103, Longitude: -82.833]

---

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Joseph Sound Light 4	61865	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Light 4	61865	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 7	61875	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 7	61875	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 8	61880	WATCHING PROPERLY	FD	2024-10-27
St Joseph Sound Daybeacon 8	61880	WATCHING PROPERLY	FD	2024-10-27
St Joseph Sound Light 12	61900	RELIGHTED	FD	2024-10-29
St Joseph Sound Light 12	61900	RELIGHTED	FD	2024-10-29
St Joseph Sound Daybeacon 19	62030	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 19	62030	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 27	62100	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 27	62100	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 29	62110	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 29	62110	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 30	62115	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 30	62115	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Light 31	62120	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Light 31	62120	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Lighted Buoy 35B	62266	RESET ON STATION	FD	2024-10-29
St Joseph Sound Lighted Buoy 35B	62266	RESET ON STATION	FD	2024-10-29
St Joseph Sound Daybeacon 37	62270	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 37	62270	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 38	62275	WATCHING PROPERLY	FD	2024-10-25
St Joseph Sound Daybeacon 38	62275	WATCHING PROPERLY	FD	2024-10-27
St Joseph Sound Light 39	62280	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Light 39	62280	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 41	62290	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Daybeacon 41	62290	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Light 44	62300	WATCHING PROPERLY	FD	2024-10-29
St Joseph Sound Light 44	62300	WATCHING PROPERLY	FD	2024-10-29

--

## St Lucie Canal

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Canal Daybeacon 38	51120	DAYMK MISSING	FD
St Lucie Canal Daybeacon 40A	51140	STRUCT DEST/TRUB	FD

## St Lucie Inlet

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Light 3	10000	STRUCT DEST/TRLB	FD
St Lucie Inlet Light 4	10003	LT EXT/DAYMK MISSING/STRUCT DMGD/TRLB	FD
St Lucie Inlet Light 4	10003	MISSING/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southern Port Salerno Daybeacon 2	10177	STRUCT DEST	PA

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Buoy 5	10125	RELOCATED FOR DREDGING	FD
St Lucie Inlet Buoy 6	10130	RELOCATED FOR DREDGING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - St Lucie Inlet/ATON/ATON Changes	ATON	ATON Changes	2024-10-17	2025-04-15	ATON/ATON Changes From: 2024-10-17 To: 2025-04-15 Location: 27.16637° N / 80.15537° W Aid Name: St Lucie Inlet Buoy 5 LLNR: 10125 Action: RELOCATE	POINT [Latitude: 27.16637, Longitude: -80.15537]
Sector Miami, Submerged Land Act (SLA) - St Lucie Inlet/ATON/Light List Corrections	ATON	Light List Corrections	2024-10-17	2025-04-15	ATON/Light List Corrections From: 2024-10-17 To: 2025-04-15 Location: 27.1665° N / 80.15399° W Aid Name: St Lucie Inlet Buoy 5 LLNR: 10125	POINT [Latitude: 27.1665, Longitude: -80.15399]

## St Lucie River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River Daybeacon 5	50675	STRUCT DEST/TRUB	FD
St Lucie River Daybeacon 12A	50725.5	STRUCT DEST	FD
St Lucie River Light 13	50730	LT IMCH	FD
St Lucie River Daybeacon 22A	50780	STRUCT DEST/TRUB	FD
St Lucie River Light 23A	50835	STRUCT DEST/HAZ NAV/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Point Access Channel Daybeacon 1	50641	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 2	50677.1	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 10	50677.5	STRUCT DEST	PA
Manatee Pocket Channel North Extension Daybeacon 5	50678.2	STRUCT DEST	PA
St. Lucie River Stuart Ext Daybeacon 1	50838	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Lucie Inlet - St Lucie River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.18256° N / 80.19534° W Aid Name: St Lucie River Light 17 LLNR: 50750 Discrepancy Information: Initial Report DTG: 021805Z OCT 2024 Summary: DBD DMGD	POINT [Latitude: 27.18256, Longitude: -80.19534]
St Lucie Inlet - St Lucie River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-10	2025- 04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 27.17172° N / 80.19656° W Aid Name: St Lucie River Light 13 LLNR: 50730 Discrepancy Information: Initial Report DTG: 102318Z OCT 2024 Summary: LT IMCH	POINT [Latitude: 27.17172, Longitude: -80.19656]

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Woods Point Daybeacon 1	CHANGE	Woods Point Daybeacon 1 (LLNR 50760) will be changed to Woods Point Buoy 1 (LLNR 50760). This change will give mariners a more reliable signal when transiting this channel.

## St Lucie River North Fork

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (North Fork) Daybeacon 7	50885	STRUCT DEST	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Seagate Harbor Daybeacon 1	50861	STRUCT DEST/HAZ NAV	PA
St. Lucie River (North Fork) Daybeacon 11	50905	STRUCT DEST	PA

## St Lucie River South Fork

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (South Fork) Daybeacon 24	51000	STRUCT DEST/TRUB	FD
St Lucie River (South Fork) Daybeacon 25A	51010	STRUCT DEST	FD

## St Marys Entrance

### Federal Discrepancies

---

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
St Marys South Jetty Buoy B	6615	MISSING	FD
St Marys North Jetty Buoy C	6620	MISSING	FD
St Marys Daybeacon N	6680	STRUCT DEST/HAZ NAV	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Marys Entrance/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-11	2025-04-09	ATON/Federal Discrepancies From: 2024-10-11 To: 2025-04-09 Location: 30.70729° N / 81.48311° W Aid Name: St Marys Entrance Range Rear Light LLNR: 6530 Discrepancy Information: Initial Report DTG: 120109Z OCT 2024 Summary: LT EXT	POINT [Latitude: 30.70729, Longitude: -81.48311]
Sector Jacksonville, Submerged Land Act (SLA) - St Marys Entrance/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-22	2024-11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 30.71163° N / 81.3335° W Aid Name: St Marys Entrance Lighted Buoy 7 LLNR: 6555 Discrepancy Information: Initial Report DTG: 292209Z SEP 2024 Summary: OFF STA Correction DTG: 231112Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: RESET ON STATION	POINT [Latitude: 30.71163, Longitude: -81.3335]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Marys Entrance Lighted Buoy 7	6555	RESET ON STATION	FD	2024-10-23

## St Petersburg Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Petersburg Channel Light 7	24980	STRUCT MISSING	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snell Isle Daybeacon 4	25020.2	STRUCT DEST/HAZ NAV	PA
Coffee Pot Bayou Daybeacon 1	25021	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Point Pinellas Channel - St Petersburg Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 27.75858° N / 82.62608° W Aid Name: St Petersburg Channel Light 11 LLNR: 24990 Discrepancy Information: Initial Report DTG: 141929Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.75858, Longitude: -82.62608]
Point Pinellas Channel - St Petersburg Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 27.76085° N / 82.61476° W Aid Name: St Petersburg Channel Light 4 LLNR: 24965 Discrepancy Information: Initial Report DTG: 141929Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.76085, Longitude: -82.61476]
Point Pinellas Channel - St Petersburg Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 27.75858° N / 82.62107° W Aid Name: St Petersburg Channel Light 7 LLNR: 24980 Discrepancy Information: Initial Report DTG: 141931Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.75858, Longitude: -82.62107]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Point Pinellas Channel - St Petersburg Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.76085° N / 82.61476° W Aid Name: St Petersburg Channel Light 4 LLNR: 24965 Discrepancy Information: Initial Report DTG: 141929Z OCT 2024 Summary: STRUCT DMGD Correction DTG: 232139Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.76085, Longitude: -82.61476]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Petersburg Channel Light 4	24965	WATCHING PROPERLY	FD	2024-10-23
St Petersburg Channel Light 4	24965	WATCHING PROPERLY	FD	2024-10-23

## St Petersburg Yacht Basin

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Petersburg Yacht Basin Light 1	25015	STRUCT DMGD/TRLB	FD
St Petersburg Yacht Basin Light 2	25020	STRUCT DEST/TRLB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. Petersburg Mooring Field Buoy B	25009.1	MISSING	PA
St. Petersburg Mooring Field Buoy C	25009.2	MISSING	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Petersburg Channel - St Petersburg Yacht Basin/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.77165° N / 82.62597° W Aid Name: St Petersburg Yacht Basin Light 2 LLNR: 25020 Discrepancy Information: Initial Report DTG: 021829Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.77165, Longitude: -82.62597]
St Petersburg Channel - St Petersburg Yacht Basin/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 27.77071° N / 82.62601° W Aid Name: St Petersburg Yacht Basin Light 1 LLNR: 25015 Discrepancy Information: Initial Report DTG: 141930Z OCT 2024 Summary: STRUCT DMGD/TRLB Temporary Response DTG: 171505Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.77071, Longitude: -82.62601]
St Petersburg Channel - St Petersburg Yacht Basin/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.77165° N / 82.62597° W Aid Name: St Petersburg Yacht Basin Light 2 LLNR: 25020 Discrepancy Information: Initial Report DTG: 021829Z OCT 2024 Summary: DBD DEST Correction DTG: 311431Z OCT 2024 Cause: FALSE REPORT Cause Comments: FALSE REPORT Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.77165, Longitude: -82.62597]



## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Petersburg Yacht Basin Light 2	25020	WATCHING PROPERLY	FD	2024-10-31
St Petersburg Yacht Basin Light 2	25020	WATCHING PROPERLY	FD	2024-10-31

## St Simons Sound

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Simons Sound Entrance Lighted Buoy 6	6060	OFF STATION	FD
Plantation Creek Range Rear Light	6135	STRUCT DEST	FD
Cedar Hammock Range Front Light	6195	LT IMCH	FD
Cedar Hammock Range Rear Light	6200	STRUCT DEST	FD

### Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Simons Sound Entrance Lighted Buoy 3	6045	RELOCATED FOR DREDGING	FD
St Simons Sound Entrance Lighted Buoy 4	6050	RELOCATED FOR DREDGING	FD

### ATON Changes

NAME	ACTION TYPE	DESCRIPTION
Cedar Hammock Range Front Light	RELOCATE	ATON/ATON Changes From: 2024-10-25 To: 2025-04-23 Location: 31.09954° N / 81.47124° W Aid Name: Cedar Hammock Range Front Light LLNR: 6195 Action: RELOCATE
Cedar Hammock Range Front Light	RELOCATE	ATON/ATON Changes From: 2024-10-25 To: 2025-04-23 Location: 31.10025° N / 81.46808° W Aid Name: Cedar Hammock Range Front Light LLNR: 6195 Action: RELOCATE



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-10	2025-04-08	ATON/Federal Discrepancies From: 2024-10-10 To: 2025-04-08 Location: 31.08633° N / 81.30777° W Aid Name: St Simons Sound Entrance Lighted Buoy 6 LLNR: 6060 Discrepancy Information: Initial Report DTG: 102014Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 31.08633, Longitude: -81.30777]
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Temporary Changes	ATON	Temporary Changes	2024-10-23	2025-04-21	ATON/Temporary Changes From: 2024-10-23 To: 2025-04-21 Location: 31.07776° N / 81.29571° W Aid Name: St Simons Sound Entrance Lighted Buoy 3 LLNR: 6045 Temporary Aid Change Information: Status: RELOCATED FOR DREDGING Old Latitude: 31-04-39.947N New Latitude: 31-04-39.360N Old Longitude: 081-17-44.564W New Longitude: 081-17-45.038W	POINT [Latitude: 31.07776, Longitude: -81.29571]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Temporary Changes	ATON	Temporary Changes	2024-10-23	2025-04-21	ATON/Temporary Changes From: 2024-10-23 To: 2025-04-21 Location: 31.07893° N / 81.29482° W Aid Name: St Simons Sound Entrance Lighted Buoy 4 LLNR: 6050 Temporary Aid Change Information: Status: RELOCATED FOR DREDGING Old Latitude: 31-04-44.159N New Latitude: 31-04-44.735N, Old Longitude: 081-17-41.336W New Longitude: 081-17-40.810W	POINT [Latitude: 31.07893, Longitude: -81.29482]
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-25	2024-11-08	ATON/Federal Discrepancies Corrected From: 2024-10-25 To: 2024-11-08 Location: 31.10025° N / 81.46808° W Aid Name: Cedar Hammock Range Front Light LLNR: 6195 Discrepancy Information: Initial Report DTG: 272049Z SEP 2024 Summary: STRUCT DEST/TRLB Temporary Response DTG: 290257Z SEP 2024 Temporary Response: TLB Correction DTG: 251409Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: REBUILT/RECOVERED	POINT [Latitude: 31.10025, Longitude: -81.46808]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-25	2025-04-23	ATON/Federal Discrepancies From: 2024-10-25 To: 2025-04-23 Location: 31.09954° N / 81.47124° W Aid Name: Cedar Hammock Range Front Light LLNR: 6195 Discrepancy Information: Initial Report DTG: 251412Z OCT 2024 Summary: LT IMCH	POINT [Latitude: 31.09954, Longitude: -81.47124]
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/ATON Changes	ATON	ATON Changes	2024-10-25	2025-04-23	ATON/ATON Changes From: 2024-10-25 To: 2025-04-23 Location: 31.09954° N / 81.47124° W Aid Name: Cedar Hammock Range Front Light LLNR: 6195 Action: RELOCATE	POINT [Latitude: 31.09954, Longitude: -81.47124]
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/ATON Changes	ATON	ATON Changes	2024-10-25	2025-04-23	ATON/ATON Changes From: 2024-10-25 To: 2025-04-23 Location: 31.10025° N / 81.46808° W Aid Name: Cedar Hammock Range Front Light LLNR: 6195 Action: RELOCATE	POINT [Latitude: 31.10025, Longitude: -81.46808]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Cedar Hammock Range Front Light	6195	REBUILT/RECOVERED	FD	2024-10-25

--

--

--

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Cedar Hammock Range Front Light	RELOCATE	Cedar Hammock RFL (LLNR 6195) will be permanently relocated to approximate position 32-06-02.513N/081-27-57.935W. The RFL will be changed to a day/night optic and continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RFL Passing LT (LLNR 6195.1) will be permanently established to display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM.
Cedar Hammock Range Rear Light	RELOCATE	Cedar Hammock RRL (LLNR 6200) will be permanently relocated to approximate position 31-05-58.956N/081-28-13.677W. The RRL will be changed to a day/night optic and continuing to display an Iso G 6s flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RRL Passing Light (LLNR 6200.1) will be permanently established by mounting (2) optics located on the NW and SE corners of the platform for Cedar Hammock RRL (LLNR 6200). The (2) optics will be synchronized and display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM. Due to the current location of Cedar Hammock RRL (LLNR 6200) being inaccessible for a CG asset to effectively repair the structure, it was determined by relocating both range structures it will not only offer an excellent range quality index for all mariners but be accessible to all CG assets to provide consistent maintenance to both structures.

## Steinhatchee River

## Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Steinhatchee River Light 9	30480	DBD DEST/STRUCT DEST/TRLB/HAZ NAV	FD
Steinhatchee River Daybeacon 14	30490.5	STRUCT MISSING/TRUB	FD
Steinhatchee River Daybeacon 34	30570	STRUCT MISSING/HAZ NAV/TRLB	FD
Steinhatchee River Daybeacon 34	30570	STRUCT DEST/TRUB	FD
Steinhatchee River Daybeacon 48	30580.9	STRUCT DEST/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Steinhatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 29.66252° N / 83.42893° W Aid Name: Steinhatchee River Daybeacon 14 LLNR: 30490.5 Discrepancy Information: Initial Report DTG: 030208Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 030208Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 29.66252, Longitude: -83.42893]
Steinhatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 29.66067° N / 83.4383° W Aid Name: Steinhatchee River Light 9 LLNR: 30480 Discrepancy Information: Initial Report DTG: 030206Z OCT 2024 Summary: DBD DEST/STRUCT DEST/TRLB/HAZ NAV Temporary Response DTG: 030207Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.66067, Longitude: -83.4383]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Steinhatchee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 29.67297° N / 83.40084° W Aid Name: Steinhatchee River Daybeacon 34 LLNR: 30570 Discrepancy Information: Initial Report DTG: 030209Z OCT 2024 Summary: STRUCT MISSING/HAZ NAV/TRLB Temporary Response DTG: 030209Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 29.67297, Longitude: -83.40084]

## Stranahan River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stranahan River Daybeacon 25	47410	STRUCT DMGD	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Port Everglades - Stranahan River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-13	2025- 04-11	ATON/Federal Discrepancies From: 2024-10-13 To: 2025-04-11 Location: 26.10727° N / 80.12016° W Aid Name: Stranahan River Daybeacon 25 LLNR: 47410 Discrepancy Information: Initial Report DTG: 132223Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 26.10727, Longitude: -80.12016]

## Sunset Harbour Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Flagler Monument Daybeacon 2	48145	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunset Harbour Channel Light 8	48110	LT EXT	PA

## Sunshine Skyway Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunshine Skyway Channel Daybeacon 2	60320	STRUCT MISSING	FD
Sunshine Skyway Channel Daybeacon 22	60415	STRUCT DEST/TRUB	FD
Sunshine Skyway Channel Daybeacon 23	60420	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mullet Key Bayou East Channel Daybeacon 7	25375	STRUCT DMGD	PA
Mullet Key Bayou East Channel Daybeacon 11	25390	STRUCT DMGD	PA
Bunces Pass Daybeacon 6	25400	STRUCT DMGD	PA
Bunces Pass Daybeacon 9	25415	DBD DEST	PA
Bunces Pass Daybeacon 11	25425	STRUCT DMGD	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Sunshine Skyway Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.6447° N / 82.72296° W Aid Name: Bunces Pass Daybeacon 6 LLNR: 25400 Discrepancy Information: Initial Report DTG: 302210Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.6447, Longitude: -82.72296]
Mullet Key Channel - Sunshine Skyway Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.65565° N / 82.7029° W Aid Name: Bunces Pass Daybeacon 11 LLNR: 25425 Discrepancy Information: Initial Report DTG: 302211Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.65565, Longitude: -82.7029]
Mullet Key Channel - Sunshine Skyway Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.65175° N / 82.71294° W Aid Name: Bunces Pass Daybeacon 9 LLNR: 25415 Discrepancy Information: Initial Report DTG: 302211Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.65175, Longitude: -82.71294]
Mullet Key Channel - Sunshine Skyway Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.63849° N / 82.72319° W Aid Name: Mullet Key Bayou East Channel Daybeacon 7 LLNR: 25375 Discrepancy Information: Initial Report DTG: 302209Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.63849, Longitude: -82.72319]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Sunshine Skyway Channel/ATON/PATON Discrepancies	ATON	PATON Discrepancies	2024-10-30	2025-04-28	ATON/PATON Discrepancies From: 2024-10-30 To: 2025-04-28 Location: 27.63335° N / 82.72449° W Aid Name: Mullet Key Bayou East Channel Daybeacon 11 LLNR: 25390 Discrepancy Information: Initial Report DTG: 302209Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.63335, Longitude: -82.72449]
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.67635° N / 82.68297° W Aid Name: Sunshine Skyway Channel Daybeacon 20 LLNR: 60405 Discrepancy Information: Initial Report DTG: 021609Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.67635, Longitude: -82.68297]
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.63222° N / 82.67297° W Aid Name: Sunshine Skyway Channel Light 1 LLNR: 60315 Discrepancy Information: Initial Report DTG: 021627Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.63222, Longitude: -82.67297]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.68628° N / 82.68347° W Aid Name: Sunshine Skyway Channel Daybeacon 24 LLNR: 60425 Discrepancy Information: Initial Report DTG: 021607Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.68628, Longitude: -82.68347]
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.66095° N / 82.68213° W Aid Name: Sunshine Skyway Channel Daybeacon 14 LLNR: 60375 Discrepancy Information: Initial Report DTG: 021620Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.66095, Longitude: -82.68213]
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.63642° N / 82.67375° W Aid Name: Sunshine Skyway Channel Daybeacon 2 LLNR: 60320 Discrepancy Information: Initial Report DTG: 021833Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.63642, Longitude: -82.67375]
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.64345° N / 82.67729° W Aid Name: Sunshine Skyway Channel Daybeacon 4 LLNR: 60330 Discrepancy Information: Initial Report DTG: 021625Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.64345, Longitude: -82.67729]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.66095° N / 82.68213° W Aid Name: Sunshine Skyway Channel Daybeacon 14 LLNR: 60375 Discrepancy Information: Initial Report DTG: 021612Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.66095, Longitude: -82.68213]
Mullet Key Channel - Sunshine Skyway Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-02	2025- 03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.65088° N / 82.68102° W Aid Name: Sunshine Skyway Channel Daybeacon 8 LLNR: 60345 Discrepancy Information: Initial Report DTG: 021623Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.65088, Longitude: -82.68102]

## Suwannee Sound South Entrance

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Suwannee Sound South Entrance Daybeacon 2	30015	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 7	30030	STRUCT DEST	FD
Suwannee Sound South Entrance Daybeacon 7	30030	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 11	30040	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 11	30040	STRUCT DEST/TRUB	FD
Suwannee Sound South Entrance Daybeacon 15	30050	STRUCT MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Suwannee Sound South Entrance/ATON Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.18672° N / 83.08144° W Aid Name: Suwannee Sound South Entrance Daybeacon 15 LLNR: 30050 Discrepancy Information: Initial Report DTG: 141939Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.18672, Longitude: -83.08144]
Suwannee Sound South Entrance/ATON Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.15476° N / 83.10376° W Aid Name: Suwannee Sound South Entrance Daybeacon 2 LLNR: 30015 Discrepancy Information: Initial Report DTG: 141937Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.15476, Longitude: -83.10376]
Suwannee Sound South Entrance/ATON Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.17674° N / 83.09879° W Aid Name: Suwannee Sound South Entrance Daybeacon 7 LLNR: 30030 Discrepancy Information: Initial Report DTG: 141938Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.17674, Longitude: -83.09879]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Suwannee Sound South Entrance/ATON/ Discrepancies	ATON	Federal Discrepancies	2024- 10-14	2025- 04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.18416° N / 83.08791° W Aid Name: Suwannee Sound South Entrance Daybeacon 11 LLNR: 30040 Discrepancy Information: Initial Report DTG: 141938Z OCT 2024 Summary: STRUCT MISSING	POINT [Latitude: 29.18416, Longitude: -83.08791]

## Tamp Bay Cut C Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Tampa Bay Cut C Channel Outbound Range Front Light	22580	STRUCT DEST	FD
Tampa Bay Cut C Channel Outbound Range Rear Light	22585	STRUCT DEST/TRLT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Tamp Bay Cut C Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.66331° N / 82.61973° W Aid Name: Tampa Bay Cut C Channel Outbound Range Rear Light LLNR: 22585 Discrepancy Information: Initial Report DTG: 151118Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.66331, Longitude: -82.61973]
Mullet Key Channel - Tamp Bay Cut C Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.67055° N / 82.6049° W Aid Name: Tampa Bay Cut C Channel Outbound Range Front Light LLNR: 22580 Discrepancy Information: Initial Report DTG: 151121Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 27.67055, Longitude: -82.6049]
Mullet Key Channel - Tamp Bay Cut C Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-23	2025-04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 27.66331° N / 82.61973° W Aid Name: Tampa Bay Cut C Channel Outbound Range Rear Light LLNR: 22585 Discrepancy Information: Initial Report DTG: 232159Z OCT 2024 Summary: STRUCT DEST/TRLT Temporary Response DTG: 232159Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.66331, Longitude: -82.61973]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Tamp Bay Cut C Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-23	2024- 11-06	ATON/Federal Discrepancies Corrected From: 2024-10-23 To: 2024-11-06 Location: 27.66331° N / 82.61973° W Aid Name: Tampa Bay Cut C Channel Outbound Range Rear Light LLNR: 22585 Discrepancy Information: Initial Report DTG: 151118Z OCT 2024 Summary: STRUCT DEST Correction DTG: 232200Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.66331, Longitude: -82.61973]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut C Channel Outbound Range Rear Light	22585	WATCHING PROPERLY	FD	2024-10-23
Tampa Bay Cut C Channel Outbound Range Rear Light	22585	WATCHING PROPERLY	FD	2024-10-23

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
Tampa Bay Cut C Channel Inbound Range Front Light	CHANGE	Hillsborough Cut C Channel Inbound Range Front Light (LLNR 22600) characteristic will change to Iso W 2s (NIGHT) and Iso W 2s (Day).
Tampa Bay Cut C Channel Inbound Range Rear Light	CHANGE	Hillsborough Cut C Channel Inbound Range Rear Light (LLNR 22605) characteristic will change to Iso W 6s (NIGHT) and Iso W 6s (Day).

## Tampa Bay Cut B Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut B Channel Inbound Range Rear Light	22485	STRUCT DEST/HAZ NAV/TRLT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Tampa Bay Cut B Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.6998° N / 82.56821° W Aid Name: Tampa Bay Cut B Channel Inbound Range Rear Light LLNR: 22485 Discrepancy Information: Initial Report DTG: 151123Z OCT 2024 Summary: STRUCT DEST/HAZ NAV/TRLT Temporary Response DTG: 151123Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.6998, Longitude: -82.56821]

## Tampa Bay Cut D Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Tampa Bay Cut D Channel Outbound Range Front Light	22710	LT IMCH	FD
Tampa Bay Cut D Channel Outbound Range Rear Light	22715	STRUCT DMGD	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Tampa Bay Cut D Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.67076° N / 82.57375° W Aid Name: Tampa Bay Cut D Channel Outbound Range Rear Light LLNR: 22715 Discrepancy Information: Initial Report DTG: 151128Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 27.67076, Longitude: -82.57375]



## Tampa Bay Cut E Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Tampa Bay Cut E Channel Inbound Range Front Light	22760	LT IMCH	FD
Tampa Bay Cut E Channel Inbound Range Rear Light	22765	STRUCT DEST/HAZ NAV/TRLB	FD
Tampa Bay Cut E Channel Lighted Buoy 5E	22785	OFF STATION	FD

### Private Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
North Yacht Basin Daybeacon 2	22786	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Tampa Bay Cut E Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.77355° N / 82.51686° W Aid Name: Tampa Bay Cut E Channel Inbound Range Rear Light LLNR: 22765 Discrepancy Information: Initial Report DTG: 151122Z OCT 2024 Summary: STRUCT DEST/HAZ NAV/TRLB Temporary Response DTG: 151122Z OCT 2024 Temporary Response: TLB	POINT [Latitude: 27.77355, Longitude: -82.51686]
Mullet Key Channel - Tampa Bay Cut E Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-23	2025-04-21	ATON/Federal Discrepancies From: 2024-10-23 To: 2025-04-21 Location: 27.75484° N / 82.52438° W Aid Name: Tampa Bay Cut E Channel Lighted Buoy 5E LLNR: 22785 Discrepancy Information: Initial Report DTG: 232336Z OCT 2024 Summary: OFF STATION	POINT [Latitude: 27.75484, Longitude: -82.52438]

## Tampa Bay Cut F Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut F Channel Inbound Range Front Light	22810	LT IMCH	FD
Tampa Bay Cut F Channel Inbound Range Rear Light	22815	STRUCT DEST/HAZ NAV/TRLT	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Mullet Key Channel - Tampa Bay Cut F Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-15	2025- 04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.80778° N / 82.52329° W Aid Name: Tampa Bay Cut F Channel Inbound Range Rear Light LLNR: 22815 Discrepancy Information: Initial Report DTG: 151119Z OCT 2024 Summary: STRUCT DEST/HAZ NAV/TRLT Temporary Response DTG: 151120Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.80778, Longitude: -82.52329]



# Tampa Bay Cut J Channel

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cut G Channel - Tampa Bay Cut J Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-01	2025-03-30	ATON/Federal Discrepancies From: 2024-10-01 To: 2025-03-30 Location: 27.83278° N / 82.57415° W Aid Name: Tampa Bay Cut J Channel Inbound Range Rear Light LLNR: 23715 Discrepancy Information: Initial Report DTG: 011321Z OCT 2024 Summary: LT EXT	POINT [Latitude: 27.83278, Longitude: -82.57415]
Cut G Channel - Tampa Bay Cut J Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 27.76509° N / 82.57249° W Aid Name: Tampa Bay Cut J Channel Outbound Range Front Light LLNR: 23720 Discrepancy Information: Initial Report DTG: 151124Z OCT 2024 Summary: HAZ NAV/STRUCT DEST/TRLT Temporary Response DTG: 151124Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.76509, Longitude: -82.57249]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Cut G Channel - Tampa Bay Cut J Channel/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024- 10-31	2024- 11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.76509° N / 82.57249° W Aid Name: Tampa Bay Cut J Channel Outbound Range Front Light LLNR: 23720 Discrepancy Information: Initial Report DTG: 151124Z OCT 2024 Summary: HAZ NAV/STRUCT DEST/TRLT Temporary Response DTG: 151124Z OCT 2024 Temporary Response: TL Correction DTG: 311424Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: REBUILT/RECOVERED	POINT [Latitude: 27.76509, Longitude: -82.57249]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut J Channel Outbound Range Front Light	23720	REBUILT/RECOVERED	FD	2024-10-31
Tampa Bay Cut J Channel Outbound Range Front Light	23720	REBUILT/RECOVERED	FD	2024-10-31

## Tampa Bay Cut J-2 Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut J-2 Channel Inbound Range Front Light	23750	TRLT	FD



## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Tampa Bay Cut J Channel - Tampa Bay Cut J-2 Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-22	2025- 04-20	ATON/Federal Discrepancies From: 2024-10-22 To: 2025-04-20 Location: 27.83867° N / 82.56771° W Aid Name: Tampa Bay Cut J-2 Channel Inbound Range Front Light LLNR: 23750 Discrepancy Information: Initial Report DTG: 222115Z OCT 2024 Summary: TRLT Temporary Response DTG: 222115Z OCT 2024 Temporary Response: TL	POINT [Latitude: 27.83867, Longitude: -82.56771]

## Taylor Creek Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Channel Daybeacon 3	45100	STRUCT DEST	FD

## Terminal Channel

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jacksonville Shipyards Pier 6 Light	7655	LT EXT	PA

--

## The Bight Channel

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Bight Channel Light 44	4920	STRUCT MISSING/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Elba Island Basin - The Bight Channel/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-04	2025-04-02	ATON/Federal Discrepancies From: 2024-10-04 To: 2025-04-02 Location: 32.1005° N / 80.99911° W Aid Name: The Bight Channel Light 44 LLNR: 4920 Discrepancy Information: Initial Report DTG: 041427Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 082336Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 32.1005, Longitude: -80.99911]

## Titusville Yacht Basin

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Titusville Yacht Basin Daybeacon 1	41210	STRUCT DEST	FD
Titusville Yacht Basin Daybeacon 3	41220	STRUCT DEST	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Indian River North Section - Titusville Yacht Basin/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2023-05-11	2025-04-11	ATON/Federal Discrepancies From: 2023-05-11 To: 2025-04-11 Location: 28.62367° N / 80.80655° W Aid Name: Titusville Yacht Basin Daybeacon 3 LLNR: 41220 Discrepancy Information: Initial Report DTG: 131547Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.62367, Longitude: -80.80655]
Indian River North Section - Titusville Yacht Basin/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2022-09-26	2025-04-11	ATON/Federal Discrepancies From: 2022-09-26 To: 2025-04-11 Location: 28.62511° N / 80.8053° W Aid Name: Titusville Yacht Basin Daybeacon 1 LLNR: 41210 Discrepancy Information: Initial Report DTG: 131537Z OCT 2024 Summary: STRUCT DEST	POINT [Latitude: 28.62511, Longitude: -80.8053]

## Tolomato River

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Tolomato River Daybeacon 44A	38795	STRUCT DMGD	FD
Tolomato River Lighted Buoy 59	38905.5	MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Matanzas River - Tolomato River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-14	2025- 04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 29.99347° N / 81.33199° W Aid Name: Tolomato River Daybeacon 44A LLNR: 38795 Discrepancy Information: Initial Report DTG: 142022Z OCT 2024 Summary: STRUCT DMGD	POINT [Latitude: 29.99347, Longitude: -81.33199]

## Treasure Island

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jungle Beach Daybeacon 2	61170	STRUCT DEST/HAZ NAV/DAYMK MISSING	PA
Jungle Beach Daybeacon 4	61180	DAYMK DMGD	PA
Jungle Beach Daybeacon 11	61215	STRUCT DEST	PA

## Trout River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Trout River Daybeacon 2	7550	STRUCT DEST/TRUB	FD

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Maxwell Boat Ramp Channel Daybeacon 5	7557.9	STRUCT DEST	PA
Ribault River Channel Lighted Buoy 1	7559	MISSING/HAZ NAV	PA
Ribault River Channel Lighted Buoy 3	7559.15	ADRIFT	PA

## Turtle River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turtle River Light 4	6325	STRUCT DEST/TRLB	FD
Turtle River Light 4	6325	STRUCT DEST	FD
Turtle River Daybeacon 10	6385	STRUCT DEST/TRUB	FD



## Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hermitage Island Plant Outfall Obstruction Light	6395	STRUCT DEST	PA

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
St Simons Sound - Turtle River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	<p>ATON/Federal Discrepancies            From: 2024-10-02            To: 2025-03-31            Location:            31.13385° N /            81.52011° W Aid            Name: Turtle River Light 4 LLNR: 6325            Discrepancy Information: Initial Report DTG: 021738Z OCT            2024 Summary: STRUCT DEST/TRLB            Temporary Response DTG: 021738Z OCT            2024 Temporary Response: TLB</p>	<p>POINT            [Latitude: 31.13385,            Longitude: -81.52011]</p>
St Simons Sound - Turtle River/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	<p>General/Marine Construction (Excluding Bridges)/Dredging            From: 2024-10-20            To: 2025-04-18            Location:            31.15657° N /            81.52431° W            31.15332° N /            81.51763° W            31.15403° N /            81.50664° W            31.15113° N /            81.49788° W            31.14937° N /            81.52345° W            31.15657° N /            81.52431° W            Cottrell Contracting Corporation of Chesapeake, Virginia advises that the dredge NEWMARKET will be conducting dredging operations in the Brunswick Inner Harbor, Glenn County, GA. The work will be ongoing from August 23, 2024, with an estimated completion date of December 31, 2024, from approximately 2,000 feet north of the Colonels Island Range Front Light (LLNR (6330) to St Simons Sound</p>	<p>POLYGON            [Latitude: 31.15657,            Longitude: -81.52431]            [Latitude: 31.15332,            Longitude: -81.51763]            [Latitude: 31.15403,            Longitude: -81.50664]            [Latitude: 31.15113,            Longitude: -81.49788]            [Latitude: 31.14937,            Longitude: -81.52345]            [Latitude: 31.15657,            Longitude: -81.52431]</p>

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>Lighted Buoy 19 (LLNR 6140). The dredge will also continue into the East River on the east side of Andrews Island. The pipeline will extend from the dredge to the Andrews Island Disposal Area. All mariners are requested to stay clear of the dredge, pipelines, barge, derricks, and operating wires about the dredge. All operators should be aware that the dredge and pontoon lines are held in place by cables, which are attached to anchors some distance from the dredge and pontoons. Buoys are attached to the anchors so that they may be moved as the dredge moves. Submerged lines should be avoided. Mariners are requested to exercise extreme caution when approaching, passing, and leaving the dredging plant. The dredge NEWMARKET monitors VHF-FM channels 13 and 16. Mariners are cautioned to strictly comply with the Inland Rules of the Road when approaching, passing and leaving the area of operations, and remain a safe distance away from the dredge, booster, buoys, cables, pipeline, barges, derricks, wires and related equipment. Owners and lessees of</p>	

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>fishnets, crabpots and other structures that may be in the vicinity and that may hinder the free navigation of attending vessels and equipment must remove these from the area where tugs, tender boats and other attendant equipment will be navigating.</p> <p>Dredging operations will be conducted twenty-four hours a day seven, days a week, all fishnets, crab pots and structures in the general area must be removed prior to commencement of any work, a slow NO WAKE speed is requested of transiting vessels. All vessels are requested to contact the dredge prior to passing.</p>	

## **Umbrella Creek**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Umbrella Creek Daybeacon A9	37440	DAYMK MISSING	FD

## **Upper Savannah River**

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Southern Nuclear Operating Co Obstruction Daybeacon A	5295	STRUCT DEST	PA
Southern Nuclear Operating Co Obstruction Daybeacon B	5295.1	STRUCT DEST	PA

## **Venice Inlet**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Venice Inlet Daybeacon 7	21455	STRUCT MISSING	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Venice Inlet/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-02	2025-03-31	ATON/Federal Discrepancies From: 2024-10-02 To: 2025-03-31 Location: 27.11224° N / 82.46986° W Aid Name: Venice Inlet Light 2 LLNR: 21435 Discrepancy Information: Initial Report DTG: 022008Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.11224, Longitude: -82.46986]
Venice Inlet/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-11-03	2025-05-02	ATON/Federal Discrepancies From: 2024-11-03 To: 2025-05-02 Location: 27.11257° N / 82.46351° W Aid Name: Venice Inlet Daybeacon 7 LLNR: 21455 Discrepancy Information: Initial Report DTG: 040101Z NOV 2024 Summary: STRUCT MISSING	POINT [Latitude: 27.11257, Longitude: -82.46351]
Venice Inlet/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.11224° N / 82.46986° W Aid Name: Venice Inlet Light 2 LLNR: 21435 Discrepancy Information: Initial Report DTG: 022008Z OCT 2024 Summary: DBD DEST Correction DTG: 311951Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.11224, Longitude: -82.46986]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Venice Inlet/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-31	2025-04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 27.11267° N / 82.46475° W Aid Name: Venice Inlet Daybeacon 5 LLNR: 21450 Discrepancy Information: Initial Report DTG: 311752Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 27.11267, Longitude: -82.46475]
Venice Inlet/ATON/Federal Discrepancies Corrected	ATON	Federal Discrepancies Corrected	2024-10-31	2024-11-14	ATON/Federal Discrepancies Corrected From: 2024-10-31 To: 2024-11-14 Location: 27.11267° N / 82.46475° W Aid Name: Venice Inlet Daybeacon 5 LLNR: 21450 Discrepancy Information: Initial Report DTG: 311752Z OCT 2024 Summary: DBD DEST Correction DTG: 311752Z OCT 2024 Cause: WEATHER Cause Comments: CYCL/HURR/TOR Correction Status: WATCHING PROPERLY	POINT [Latitude: 27.11267, Longitude: -82.46475]

## Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Venice Inlet Light 2	21435	WATCHING PROPERLY	FD	2024-10-31
Venice Inlet Light 2	21435	WATCHING PROPERLY	FD	2024-10-31
Venice Inlet Daybeacon 5	21450	WATCHING PROPERLY	FD	2024-10-31
Venice Inlet Daybeacon 5	21450	WATCHING PROPERLY	FD	2024-10-31

## Vernon River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Vernon River Light Wreck 86	36260	REDUCED INT	FD

### Proposed Notice of Change

NAME	ACTION TYPE	DESCRIPTION
Vernon River Light Wreck 86	CHANGE	<p>The U.S. Coast Guard is proposing a change to the Aid to Navigation system in the Intracoastal Waterway the Vernon River, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate. All comments should be emailed to: <a href="mailto:D07-SMB-DPWPUBLICCOMMENTS@USCG.MIL">D07-SMB-DPWPUBLICCOMMENTS@USCG.MIL</a> or <a href="mailto:andrew.m.ingle@uscg.mil">andrew.m.ingle@uscg.mil</a> with ICW Nominal Range Change as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by October 9, 2024.</p>

## Villas Continental Club

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Villas Continental Club Daybeacon 2	7790	STRUCT DEST/HAZ NAV	PA



NAME	LLNR	STATUS	AID TYPE
Villas Continental Club Daybeacon 3	7795	STRUCT DEST	PA
Villas Continental Club Daybeacon 4	7800	STRUCT DEST	PA
Villas Continental Club Daybeacon 5	7805	STRUCT DEST	PA

## Virgin Passage And Sonda De Vieques

### Proposed Notice of Change

NAME	ACTION TYPE	DESCRIPTION
Punta Picua Lighted Buoy WR 2	DISCONTINUE	The U.S. Coast Guard is proposing the following change to the Aids to Navigation System in the West Indies: Permanently discontinue Punta Picua Lighted Buoy WR2 (LLNR 31140) in position 18-26-30.577N / 065-45-35.980W. All comments should be emailed to: D07-SMB-DPWPUBLICComments@uscg.mil or jessica.a.wolchak-benggio@uscg.mil with Punta Picua Lighted Buoy WR2 as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL. 33131-3050 to be received by September 27, 2024.

## Volusia

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Volusia Light 23	8820	STRUCT DEST/TRLB	FD

## Wadmalaw River

### Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Wadmalaw River Daybeacon 87	34890	STRUCT DEST/TRUB	FD
Wadmalaw River Daybeacon 96	34920	STRUCT DEST/TRUB	FD

## **Wassaw Sound**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Wassaw Sound Lighted Buoy 8	5595	MISSING	FD

## **Whale Harbor**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Whale Harbor Channel Daybeacon 6	12720	STRUCT DEST/HAZ NAV/TRLB	FD

### **Private Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Holiday Isle Marina Daybeacon 1	12765	STRUCT DEST	PA
Holiday Isle Marina Daybeacon 2	12770	STRUCT DEST	PA

## **White Shells Cut**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
White Shells Cut Range Rear Light	7325	STRUCT DEST	FD

## Advanced Notice of Changes

NAME	ACTION TYPE	DESCRIPTION
White Shells Cut Lighted Buoy 27	RELOCATE	White Shells Cut LB 27 (LLNR 7315) will be permanently relocated to 30-23-36.040N/081-28-48.780W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.
White Shells Cut Lighted Buoy 29	RELOCATE	White Shells Cut LB 29 (LLNR 7316) will be permanently relocated to 30-23-32.900N/081-29-05.750W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.

## Windward Passage

### Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johnson Reef Buoy JA	32680	OFF STA	PA
Johnson Reef Lighted Buoy JD	32680.3	LT EXT	PA

## Winyah Bay Channel

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Winyah Bay Range A Front Light	1875	LT EXT	FD
Winyah Bay Range A Rear Light	1880	LT EXT	FD
Winyah Bay Range B Rear Light	1915	STRUCT DEST/HAZ NAV/TRLT	FD

### **Advanced Notice of Changes**

<b>NAME</b>	<b>ACTION TYPE</b>	<b>DESCRIPTION</b>
Winyah Bay Channel Lighted Bell Buoy 4	CHANGE	Winyah Bay Channel LB 4 (LLNR 1885) will have the bell permanently removed.
Coast Guard Mooring Buoy WB	RELOCATE	The Coast Guard Mooring Buoy WB (LLNR 1958) will be permanently relocated to approximate position 33-14-59.160N/079-12-47.580W. The new location will provide a more protected environment from the previous exposed location for CG assets when moored to this buoy.

## **Winyah Bay Charleston Harbor**

### **Federal Discrepancies**

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Winyah Bay-Charleston Harbor Daybeacon 74	34365	DBD DEST	FD
Winyah Bay-Charleston Harbor Daybeacon 121	34525	STRUCT DEST/TRUB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Winyah Bay Charleston Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-15	2025-04-13	ATON/Federal Discrepancies From: 2024-10-15 To: 2025-04-13 Location: 32.80863° N / 79.75602° W Aid Name: Winyah Bay-Charleston Harbor Lighted Buoy 116 LLNR: 34505 Discrepancy Information: Initial Report DTG: 151215Z OCT 2024 Summary: BUOY DMGD	POINT [Latitude: 32.80863, Longitude: -79.75602]
Sector Charleston, Submerged Land Act (SLA) - Winyah Bay Charleston Harbor/General/Marine Construction (Excluding Bridges)/Dredging	General	Marine Construction (Excluding Bridges)	2024-10-20	2025-04-18	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: No coordinates available Ahtna Marine and Construction Company will be dredging approximately 757,000 cubic yards of unclassified material from Placement Areas 1110S W-C, 1088S W-C, 1056S W-C, and 1028S W-C which shall be placed at Sullivan's Island and Isle of Palms beaches. The estimated completion date is February 28, 2025. The pipeline will start in approximate position 32-47-17.55N / 079-48-28.72W in the vicinity of Winyah Bay-Charleston Harbor Daybeacon 117A (LLNR 34510.5) and be submerged under the channel to approximate position 32-47-09.85N / 079-48-30.52W. The pipeline will be	POINT [Latitude: 32.77603, Longitude: -79.81242]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
					<p>floating to approximate position 32-46-43.83N / 079-48-43.07W. The pipeline will continue by be submerged across the channel to approximate position 32- 46-30.80 N / 079-48-48.24W. All pipelines will be marked per U.S. Coast Guard rules and regulations. Barges will be marked with flashing lights at night. Boaters are urged to maintain safe distance from the barges to avoid potential interference with the hauling operations. Mariners are urged to transit at their slowest safe speed to minimize wake and proceed with caution after arrangements have been made. Barges will be monitoring VHF-FM channels 16 and 79. For further information contact: Ahtna Marine and Construction Company (954) 568-0007.</p>	
Sector Charleston, Submerged Land Act (SLA) - Winyah Bay Charleston Harbor/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-11-02	2025-05-01	<p>ATON/Federal Discrepancies  From: 2024-11-02  To: 2025-05-01  Location:  32.93642° N / 79.65494° W Aid  Name: Winyah Bay-Charleston Harbor Daybeacon 74  LLNR: 34365 Discrepancy  Information: Initial Report DTG: 021450Z NOV 2024 Summary: DBD DEST</p>	POINT [Latitude: 32.93642, Longitude: -79.65494]

## Withlacoochee River

### Federal Discrepancies

<b>NAME</b>	<b>LLNR</b>	<b>STATUS</b>	<b>AID TYPE</b>
Withlacoochee River Entrance Light 1	29370	DBD DEST	FD
Withlacoochee River Entrance Daybeacon 8	29410	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 16	29455	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Light 18A	29470	DBD DEST/LT EXT	FD
Withlacoochee River Entrance Daybeacon 26	29520	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 26	29520	STRUCT DEST/TRLB	FD
Withlacoochee River Entrance Daybeacon 29	29535	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 30	29545	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 30	29545	STRUCT DEST/TRUB	FD
Withlacoochee River Entrance Daybeacon 31	29550	STRUCT DEST/TRUB	FD
Withlacoochee River Entrance Daybeacon 31	29550	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Light 32	29555	STRUCT DEST/TRLB	FD
Withlacoochee River Entrance Light 32	29555	STRUCT MISSING/TRLB	FD

## Additional MSIs

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Withlacochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.98135° N / 82.80761° W Aid Name: Withlacochee River Entrance Daybeacon 8 LLNR: 29410 Discrepancy Information: Initial Report DTG: 141945Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141946Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.98135, Longitude: -82.80761]
Withlacochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.98417° N / 82.79706° W Aid Name: Withlacochee River Entrance Daybeacon 16 LLNR: 29455 Discrepancy Information: Initial Report DTG: 141946Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141946Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.98417, Longitude: -82.79706]



TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Withlacoochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.99019° N / 82.78332° W Aid Name: Withlacoochee River Entrance Daybeacon 26 LLNR: 29520 Discrepancy Information: Initial Report DTG: 141948Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141948Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.99019, Longitude: -82.78332]
Withlacoochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.99367° N / 82.7789° W Aid Name: Withlacoochee River Entrance Daybeacon 30 LLNR: 29545 Discrepancy Information: Initial Report DTG: 141950Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141950Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.99367, Longitude: -82.7789]
Withlacoochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.98411° N / 82.7914° W Aid Name: Withlacoochee River Entrance Light 18A LLNR: 29470 Discrepancy Information: Initial Report DTG: 141947Z OCT 2024 Summary: DBD DEST/LT EXT	POINT [Latitude: 28.98411, Longitude: -82.7914]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Withlacoochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.99296° N / 82.78069° W Aid Name: Withlacoochee River Entrance Daybeacon 29 LLNR: 29535 Discrepancy Information: Initial Report DTG: 141948Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141949Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.99296, Longitude: -82.78069]
Withlacoochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12	ATON/Federal Discrepancies From: 2024-10-14 To: 2025-04-12 Location: 28.99517° N / 82.77742° W Aid Name: Withlacoochee River Entrance Daybeacon 31 LLNR: 29550 Discrepancy Information: Initial Report DTG: 141951Z OCT 2024 Summary: STRUCT MISSING/TRUB Temporary Response DTG: 141951Z OCT 2024 Temporary Response: TUB	POINT [Latitude: 28.99517, Longitude: -82.77742]
Withlacoochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024-10-14	2025-04-12		POINT [Latitude: 28.99475, Longitude: -82.7773]

TITLE	CATEGORY	SUB CATEGORY	BEGIN DATE	END DATE	DESCRIPTION	LOCATION
Withlacochee River/ATON/Federal Discrepancies	ATON	Federal Discrepancies	2024- 10-31	2025- 04-29	ATON/Federal Discrepancies From: 2024-10-31 To: 2025-04-29 Location: 28.96897° N / 82.82871° W Aid Name: Withlacochee River Entrance Light 1 LLNR: 29370 Discrepancy Information: Initial Report DTG: 311722Z OCT 2024 Summary: DBD DEST	POINT [Latitude: 28.96897, Longitude: -82.82871]

LNМ Footer Editable in USAIMS Online