Local Notice to Mariners for District 7 05/13/2025

Alafia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Alafia River Light 7	23275	STRUCT MISSING/TRLB	FD
Alafia River Light 15	23315	STRUCT DEST/TRLB/HAZ NAV	FD

Altamaha Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Altamaha Sound Daybeacon 197	36887	STRUCT DEST/TRUB	FD
Altamaha Sound Light 201	36905	STRUCT DEST/TRLB	FD
Altamaha Sound Light 202	36910	STRUCT DEST/TRLB	FD
Altamaha Sound Light 209	36930	STRUCT DEST/TRLB	FD
Altamaha Sound Range Front Light C	36935	STRUCT DEST	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Altamaha Sound Light 198	36890	RELIGHTED	FD	2025-05-01

Amelia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Amelia River Lighted Buoy 4	37940	ADRIFT	FD

Anclote Anchorage North Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage North Entrance Light 7	26130	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

· ····ate Districtes			
NAME	LLNR	STATUS	AID TYPE
Gulf Harbors South Channel Light 1	26410	LT EXT	PA
Sea Forest Cut Channel Daybeacon 9	26451.8	STRUCT DEST/HAZ NAV	PA
Upper Cross Bayou Daybeacon 1	26453	STRUCT DEST	PA
Gulf Harbors North Channel Light 2	26460	STRUCT DEST	PA
Gulf Harbors North Channel Daybeacon 10	26500	STRUCT DEST	PA

Anclote River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote River Daybeacon 11	26190	STRUCT DEST/TRLB/HAZ NAV	FD
Anclote River Daybeacon 12	26190.5	HAZ NAV/STRUCT DEST/TRLB	FD
Anclote River Turning Basin Shoal Daybeacon A	26360	STRUCT MISSING/TRUB	FD
Anclote River Turning Basin Shoal Daybeacon B	26365	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Village Marina Daybeacon 7	26233.7	DAYMK MISSING	PA

Angelfish Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Angelfish Creek Daybeacon 1	11185	STRUCT DEST/HAZ NAV/TRLB	FD
Angelfish Creek Daybeacon 4	11205	STRUCT DEST/TRUB	FD
Angelfish Creek Light 6	11215	STRUCT DEST/TRLB	FD

Ashepoo-Coosaw Cut-Off

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ashepoo-Coosaw Cutoff Daybeacon 169	35160	STRUCT MISSING/TRUB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Ashepoo-Coosaw Cutoff Lighted Buoy 184	35205	RESET ON STATION	FD	2025-05-07

Ashley River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor South Channel -	Bridges	General/Bridges/Construction From: 2025-02-12 To: 2026-01-30 Location: 32.78257° N / 79.96052° W Bridge Name: Ashley River	Lat:
Ashley		Pedestrian Bridge Construction of the Ashley River Crossing Pedestrian Bridge has begun on the Ashley River, in Charleston, SC. The	32° 46' 57"
River/General/Bridges/Construction		new bridge will be constructed to the southeast (immediately adjacent) of the T. Allen Legare / US 17 Bridge. Construction barges will	Lon:
		be partially obstructing the channel, approximately 65-70 feet of the channel will be available to navigation. Vessels requiring a full	-079° 57'
		channel passage must contact Mr. Sean Lynch, 728-205-1580, at least 24 hours prior to the transit. Construction activities will be 24	38"
		hours a day, seven days a week. The SE section of the fender will be temporarily removed. The remaining section will be properly	
		lighted. Vessels should use caution and maintain safe speeds while transiting the area.	

Atlantic IWW

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sebastian Inlet North Jetty Light	655	LT EXT	PA
Sailfish Point Marina Channel Daybeacon 5	10025	STRUCT DEST/HAZ NAV	PA
Sailfish Point Marina Channel Daybeacon 2	10010	STRUCT DEST	PA
Sailfish Point Marina Channel Daybeacon 7	10035	STRUCT DEST	PA

Bahia De Boqueron

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bajo Enmedio South Lighted Buoy 1	32325	SINKING/TRLB	FD

Bahia De Guayanilla

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De Guayanilla Entrance Range Rear Light	32075	LT EXT	FD

Bahia De Jobos

Private Discrepancies

Trivate Discrepancies			
NAME	LLNR	STATUS	AID TYPE
Aguirre Power Plant Lighted Buoy 1	31890	OFF STA	PA
Aguirre Power Plant Lighted Buoy 2	31895	OFF STA	PA
Aguirre Power Plant Lighted Buoy 3	31900	OFF STA	PA
Aguirre Power Plant Lighted Buoy 4	31905	OFF STA	PA
Aguirre Power Plant Lighted Buoy 5	31910	OFF STA	PA
Aguirre Power Plant Lighted Buoy 6	31915	OFF STA	PA
Aguirre Power Plant Lighted Buoy 8	31920	OFF STA	PA

Bahia De Ponce

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla De Cardona Light	31950	STRUCT DEST	FD
Bahia De Ponce Range Rear Light	31965	REDUCED INT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce Harbor Pier Obstruction Lights (4)	31985	STRUCT DMGD	PA

Bahia De Ponce And Approaches

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla Caja De Muertos Light	31925	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce Yacht & Fishing Club Special Purpose Buoy A	31927	MISSING	PA
Rio Bucana East Jetty Light	31940	STRUCT DEST	PA

Bahia De San Juan

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De San Juan Lighted Buoy 2	30760	BUOY DMGD/OFF STATION	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De San Juan FAD Lighted Buoy E	30736.4	MISSING	PA
Bahia De San Juan FAD Lighted Buoy F	30736.5	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Army Terminal Channel Lighted Buoy 7	30885	RELOCATED FOR DREDGING	FD
Army Terminal Channel Temporary Buoy 7A	null	ESTABLISHED	FD

Additional MSI Categories

	_		
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Bahia De San Juan/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 18.43499° N / 66.10732° W Aid Name: Army Terminal Channel Lighted Buoy 7 LLNR: 30885 Action: RELOCATE Army Terminal Channel Lighted Buoy 7 (LLNR 30885) will be permanently relocated to position 18-26-10.272N/066-06-27.668W. Army Terminal Channel Lighted Buoy 7A (LLNR 30885 .5) will be permanently established in position 18-26-03.650N/066-06-25.656W.	Lat: 18° 26' 06" Lon: -066° 06' 26"
Bahia De San Juan/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 18.43435° N / 66.10713° W Aid Name: Army Terminal Channel Lighted Buoy 7A LLNR: 30885 .5 Action: ESTABLISH Army Terminal Channel Lighted Buoy 7 (LLNR 30885) will be permanently relocated to position 18-26-10.272N/066-06-27.668W. Army Terminal Channel Lighted Buoy 7A (LLNR 30885 .5) will be permanently established in position 18-26-03.650N/066-06-25.656W.	

Banana River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Banana River Daybeacon 7A	42490	STRUCT DEST/TRUB	FD
Banana River Daybeacon 15	42555	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hospital Cut Daybeacon 6	42611.5	DAYMK MISSING	PA
Tortoise Island Ctr Channel Daybeacon 2	42450	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 4	42460	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 5	42460.1	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 6	42460.200000000004	DAYMK MISSING	PA
Tortoise Island Center Channel Daybeacon 7	42460.3	DAYMK IMCH	PA
Tortoise Island Center Channel Daybeacon 8	42460.4	DAYMK IMCH	PA
Tortoise Island Channel Daybeacon 1	42463	STRUCT DEST/HAZ NAV	PA
Manatee Cove Marina Daybeacon 1	42490.1	STRUCT DEST/HAZ NAV	PA
Manatee Cove Marina Daybeacon 4	42490.4	STRUCT DMGD	PA
Pelican Creek Light 2	42615	STRUCT DEST	PA
Central Avenue Entrance Channel Light 2	42830	LT EXT	PA
Kelly Park Channel Daybeacon 3	43040	STRUCT DEST/HAZ NAV	PA
Kelly Park Channel Daybeacon 4	43045	STRUCT DEST	PA
Kelly Park Channel Daybeacon 5	43050	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	
-------	-------------	-------------	----------	--

https://www.navcen.uscg.gov/msi 3/71

Canaveral Barge Canal -	Marine	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 28.2669° N / 80.6097° W 28.17191° N /
Banana	Construction	80.61245° W 28.25602° N / 80.6612° W 28.2669° N / 80.6097° W Gator Dredging will continue muck removal operations within the Grand Canal
River/General/Marine	(Excluding	and adjacent canals within a subdivision, north of Samson Island Park and south of Patrick Air Force Base. Operations will begin on or about
Construction (Excluding	Bridges)	March 15, 2022 until approximately November 30, 2025 - Monday through Saturday, 30 minutes after sunrise until 30 minutes before sunset. The
Bridges)/Dredging		dredge DANI L will monitor VHF-FM channels 16 and 68. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed
		to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene
		pipeline associated with the hydraulic dredging operations of the canals will be utilized. Pipeline, work vessels, dredge barge, booster pump
		barges and buoys will be visibly lighted and will be in the area until all work is complete. The configuration will change daily and Vessels and/or
		equipment will be in multiple locations at the same time. For further information, contact: Charlie Gertz (727) 902-6055.

Banana River North

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Banana River North Daybeacon 34	41920	STRUCT DEST/TRUB	FD
Banana River North Light 35	41925	STRUCT DEST/TRLB	FD

Barnes Sound

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee Creek Daybeacon 5	50255	STRUCT DEST	PA
Manatee Creek Daybeacon 6	50260	STRUCT DEST	PA
Manatee Creek Daybeacon 7	50265	STRUCT DEST	PA
Manatee Creek Daybeacon 8	50270	STRUCT DEST	PA
Manatee Creek Daybeacon 8A	50275	STRUCT DEST	PA
Manatee Creek Daybeacon 9	50280	STRUCT DEST	PA
Manatee Creek Daybeacon 10	50285	STRUCT DEST	PA
Manatee Bay Daybeacon 2	50310	STRUCT DEST	PA
Manatee Bay Daybeacon 3	50315	STRUCT DEST	PA

Barron River Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barron River Channel Daybeacon 37	16180	STRUCT DEST/TRUB	FD

Beaufort River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Broad Creek Daybeacon 13	4490	STRUCT DEST	PA
Broad Creek Daybeacon 19	4510	DAYMK IMCH	PA
Broad Creek Daybeacon 21	4515	DAYMK IMCH	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Royal Sound - Beaufort River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-11-29 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods Memorial Bridge The Coast Guard has authorized a temporary deviation to the operating schedule to the Lady's Island Bridge across the Atlantic Intracoastal Waterway mile 536.0, Beaufort, South Carolina. The bridge need not open for navigation, including tugs with tows during the following: July 4, 2025, from 7:45 a.m. to 9:30 a.m. to facilitate the Help of Beaufort 5k. Public Vessels, vessels in emergency situations, and vessels that may pass through the bridge without an opening should be passed at any time.	Lat: 32° 25' 39" Lon: -080° 40' 09"
Port Royal Sound - Beaufort River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2024-11-05 To: 2024-11-30 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods Memorial Bridge This temporary deviation to the drawbridge operating schedule is effective from 2 p.m. on February 27, 2025, through 11:59 p.m. on May 23, 2025. Under this temporary deviation, the Lady's Island (Woods Memorial) Bridge shall open on signal; except that the draw need not open from 6 a.m. to 9:29 a.m. and 3:31 p.m. to 7 p.m., Monday through Friday, except Federal holidays. Between 9:30 a.m. and 3:30 p.m., Monday through Friday, except Federal holidays, the draw need open only once an hour on the half hour. Public vessels of the United States and tugs with tows, will be passed through anytime.	Lat: 32° 25' 39" Lon: -080° 40' 09"
Port Royal Sound - Beaufort River/General/Bridges/Closure (Scheduled Or Emergency)	Bridges	General/Bridges/Closure (Scheduled Or Emergency) From: 2025-03-11 To: 2025-09-07 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods Memorial Bridge - AICW The southern channel is closed to navigation until further notice. All vessels are advised to transit through the swing bridge using the northern channel only. The northeastern section of the fender system is damaged and missing. There is no pier lighting identifying the northeastern fender. All mariners are advised to use extreme caution when transiting.	32° 25' 39"

Big Bend Channel

Federal Discrepancies

	NAME	LLNR	STATUS	AID TYPE
--	------	------	--------	----------

https://www.navcen.uscg.gov/msi 4/71

Big Bend Channel Lighted Buoy 9 23080 OFF STATION FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Apollo Beach Daybeacon 4	24675	STRUCT DEST	PA

Big Marco Pass Gordon Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Marco Pass-Gordon Pass Daybeacon 2	17095	STRUCT DEST/TRUB/OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 1A	17100	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 2A	17160	STRUCT MISSING/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 2A	17160	STRUCT DEST	FD
Big Marco Pass-Gordon Pass Daybeacon 3	17165	STRUCT MISSING/TRUB/OFF STATION	FD
Big Marco Pass-Gordon Pass Daybeacon 17	17210	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 18A	17220	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 26	17255	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 28A	17275	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 33	17300	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 36	17310	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordan Pass Daybeacon 40	17320	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 46	17335	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 53	17370	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 54	17375	STRUCT DMGD	FD
Big Marco Pass-Gordon Pass Daybeacon 56	17385	STRUCT MISSING/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 60	17400	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 65	17415	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 66	17420	STRUCT DEST/TRUB	FD
Big Marco Pass-Gordon Pass Daybeacon 67	17420.5	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Marco Pass Obstruction Daybeacon A	17087	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon B	17087.1	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon C	17087.2	STRUCT DEST	PA
Big Marco Pass Obstruction Light E	17087.4	STRUCT DEST	PA
Isles Of Capri Daybeacon 6	17125	STRUCT MISSING	PA

Biscayne Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Bay Daybeacon 57	48490	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Seaquarium Inlet Pipe Obstruction Light	48600	STRUCT DEST/HAZ NAV	PA
Bakers Haulover Smallboat Channel Daybeacon 2	47795	STRUCT DEST	PA
Coral Gables Waterway Light 1	49285	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 3	49295	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 4	49300	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 6	49310	DAYMK IMCH	PA
Matheson Hammock South Channel Range Front Light	49445	DAYMK MISSING/STRUCT DMGD	PA
Matheson Hammock South Channel Range Rear Light	49450	DAYMK MISSING	PA
Matheson Hammock South Channel Light 2	49455	LT EXT	PA
Matheson Hammock South Channel Daybeacon 9	49485	DAYMK MISSING	PA
Black Point Channel Daybeacon 1	49735	STRUCT DEST	PA
Black Point Channel Daybeacon 6	49760	STRUCT DEST	PA
Black Point Channel Daybeacon 12	49790	STRUCT DEST	PA
Adams Key Light	50105	LT EXT/DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

https://www.navcen.uscg.gov/msi

Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-08 To: 2027-12-31 Location: 25.80607° N / 80.25855° W Bridge Name: South Florida Rail Corridor Railroad Bridge - Miami River The draw of the FDOT Railroad Bridge, mile 5.3 at Miami, Florida need not open to navigation. This temporary interim rule (TIR) is effective April 4, 2025, through 11:59 p.m. on December 31, 2027. We encourage you to submit comments through the Federal Decision Making Portal at https://www.regulations.gov. To do so, go to https://www.regulations.gov, type USCG-2025-0204 in the search box and click "Search." Next, look for this document in the Search Results column, and click on it. Then click on the Comment option. Comments and related material must reach the Coast Guard on or before July 3, 2025.	Lat: 25° 48' 22" Lon: -080° 15' 31"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-18 To: 2025-06-28 Location: 25.79503° N / 80.24545° W Bridge Name: Tamiami Bridge - Miami River (Tamiami (C-4) Canal The bridge shall open on the quarter and three-quarter hour. Public vessels of the United States, vessels declaring an emergency and tugs with tows shall be passed at any time. This temporary deviation is effective from 8 a.m. on April 18, 2025, until 11:59 p.m. on June 27, 2025. This action is necessary to allow for repairs to machinery components.	Lat: 25° 47' 42" Lon: -080° 14' 44"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-02 To: 2025-05-18 Location: 25.77303° N / 80.20061° W Bridge Name: Southwest 1st Street Bridge - Miami River The bridge will open on the hour and half-hour from 6 a.m. until 10 a.m. on Saturday May 10, 2025, and Saturday May 17, 2025. At all other times the bridges will operate per their normal operating regulation. Public vessels of the United States, tugs and tugs with tow, and vessels in distress shall be passed at any time.	Lat: 25° 46' 23" Lon: -080° 12' 02"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-02 To: 2025-05-18 Location: 25.77419° N / 80.20125° W Bridge Name: West Flagler Street Bridge - Miami River The bridge will open on the hour and half-hour from 6 a.m. until 10 a.m. on Saturday May 10, 2025, and Saturday May 17, 2025. At all other times the bridges will operate per their normal operating regulation. Public vessels of the United States, tugs and tugs with tow, and vessels in distress shall be passed at any time.	
Biscayne Bay/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 25.6632° N / 80.24784° W Fincantieri Infrastructure Florida & GLF USA will be conducting pile driving, dredging and water sampling in the vicinity of Biscayne Bay Aquatic Preserve and Government Cut at furture MSC berths 8 and 9 (25-46-21.1332N/080-9-25.5348W to 25-46-9.1848N/080-8-57.0084W). The estimated completion date is December 15, 2025, hours of operation are 6:30 a.m. to 6:30 p.m., 7 days a week. GLF Construction Corporation will be mobilizing a Crane Barge (54 feet x 150 feet), Service Barge (30 feet X 150 feet), and a Push Boat (15 feet x 25 feet) to the project site on or around June 16, 2022. The equipment is being mobilized to install and maintain the turbidity control system required to perform both land and water-based dredging works. During the installation of the system the above equipment will be operating in the area south of the north navigation channel adjacent to Port Miami. If and when necessary, the equipment will be moved along the southern edge of the north navigation channel to perform any maintenance. Upon arrival at the site the GLF equipment will be positioned inside the Turbidity Control System south of the Navigation Channel and will not move out until completion of the work. GLF will continuously monitor VHF-FM channel 16 and use Channel 9 to maneuver barge and vessels. For further information contact:Alejandro Brito (786) 821-4587 or Alejandro.Drito@fl.fcinfrastructure.com.	Lat: 25° 39' 48" Lon: -080° 14' 52"

Biscayne Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Channel Light 3	10820	STRUCT DEST/TRLB	FD
Biscayne Channel Daybeacon 4	10825	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Springs Boat Club Shoal Buoy West	10886	MSLD SIG	PA
Miami Springs Boat Club Shoal Buoy North	10887	MISSING	PA
Miami Springs Boat Club Shoal Buoy South	10889	MISSING	PA

Blackwater Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater Sound Light 38	50365	LT EXT	FD

Bloody Point Range

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Bloody Point Range Lighted Bell Buoy 8	4580	RELOCATED FOR DREDGING	FD
Bloody Point Range Lighted Buoy 13	4615	RELOCATED FOR DREDGING	FD

Blount Island

Temporary Changes

The state of the s			
NAME	LLNR	STATUS	AID TYPE
Blount Island Turning Basin Lighted Buoy 45	7395	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy A	7396	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy B	7397	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy C	7398	RELOCATED FOR DREDGING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	
11166	JODCALLGOKI	DESCRIPTION	LOCATION	

https://www.navcen.uscg.gov/msi 6/71

Fulton Cutoff - Blount	Advanced Notice of	Blount Island Turning Basin LB 45 (LLNR 7395) will be permanently relocated to 30-23-08.280N/081-32-35.920W. The flash	Lat:
Island/ATON/Advanced Notice of Change	Change	characteristic will remain a FL G 4s, but the nominal range will be reduced from 5NM to 4NM.	30° 23' 08"
			Lon:
			-081° 32' 36"

Boca Chita Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Sands Key Light 3	49695	WATCHING PROPERLY	FD	2025-05-07

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Featherbeds Obstruction Daybeacon A	49703	DAYMK MISSING	PA
East Featherbed North Obstruction Daybeacon	49703.1	DAYMK MISSING	PA
East Featherbed West Obstruction Daybeacon	49703.3	STRUCT DEST	PA
East Featherbed Northeast Obstruction Daybeacon	49703.5	STRUCT DEST	PA
East Featherbed Southeast Obstruction Daybeacon	49703.6	DAYMK IMCH	PA
East Featherbed NNE Obstruction Daybeacon	49703.700000000004	STRUCT DEST	PA
Middle Featherbeds North Obstruction Daybeacon	49704	DAYMK MISSING	PA
Middle Featherbed NNE Obstruction Daybeacon	49704.3	DAYMK MISSING	PA
Featherbed Bank Shoal Daybeacon X	49725	STRUCT DEST/HAZ NAV	PA

Boca Ciega Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Ciega Bay Daybeacon 35	60915	STRUCT DEST	FD

Boca Ciega Bay To Anclote Anchorage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Narrows Daybeacon 14	61535	STRUCT MISSING/TRUB	FD
The Narrows Daybeacon 25	61580	TRUB/STRUCT MISSING	FD
The Narrows Light 27B	61600	STRUCT MISSING/TRLB	FD
The Narrows Daybeacon 38	61660	STRUCT DEST/TRUB	FD

Boca Ciega Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Ciega Bay Daybeacon 39	61040	STRUCT DEST/TRUB	FD

Boca Grande Yacht Basin Channel

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Gasparilla Sound Channel - Boca Grande Yacht	Bridges	General/Bridges/Maintenance From: 2025-01-07 To: 2025-11-03 Location: 26.75371° N / 82.2584° W Bridge Name: Boca Grande	Lat:
Basin Channel/General/Bridges/Maintenance		Bayou Temporary Bridge Temporary Construction Bridge (TCB) across the Boca Grande Bayou is authorized to remain in place	26° 45' 13"
		through April 1, 2026, to allow for the completion of work at the Gasparilla Island Water Association Wastewater Treatment Plant.	Lon:
		Remaining work includes final site work, demolition of existing structures and removal of the TCB. The center span shall be	-082° 15'
		removed to allow for unrestricted boating traffic from January 1, 2025, through May 1, 2025, and again from January 1, 2026,	30"
		through the end of the project. The TCB shall be removed in its entirety by April 1, 2026.	

Bohicket Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bohicket Creek Daybeacon 5	3905	STRUCT MISSING	FD

Bowlegs Cut

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE

Bay Harbour Light	12378	LT EXT	PA
Day Harboar Eight	123.0	ET EXT	

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Florida Bay - Bowlegs	Bridges	General/Bridges/Rehabilitation From: 2024-11-19 To: 2025-05-18 Location: 24.83801° N / 80.77337° W Bridge Name: United States 1	Lat:
Cut/General/Bridges/Rehabilitation		Highway Bridge - Channel Five Freyssinet, Inc on behalf of the bridge owner, Florida Department of Transportation (FDOT) will be	24° 50' 17"
		performing rehab/repair work on the Channel Five Bridge between Lower Matecumbe Key and Long Key Bight from April 19, 2021,	Lon:
		through May 2025. There will be barges, floating work platforms and work boats in the area behind the fender systems, but no	-080° 46'
		obstructions to navigation are expected. All mariners are advised to proceed with caution and transit the area at a minimum wake speed.	24"
		For waterways related questions, contact, Coast Guard Sector Key West Waterways, 305-292-8768 or email: SKWWaterways@uscg.mil.	

Braden River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Braden River Daybeacon 9	22097.8	STRUCT DEST/HAZ NAV	PA
Braden River Daybeacon 11	22098	STRUCT DEST	PA

Brunswick River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Brunswick Point Cut Range Front Light 2	6230	REDUCED INT	FD
Brandy Point Jetty Daybeacon	6290	STRUCT DEST/HAZ NAV/TRUB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Brunswick Harbor Range Front Light	6270	RELIGHTED	FD	2025-05-07

Butchers Bend

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Butchers Bend Light 109	9200	STRUCT DEST/TRLB	FD

Buttermilk Sound

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Buttermilk Sound Daybeacon 217	36967	STRUCT DEST/TRUB	FD
Buttermilk Sound Daybeacon 218	36975	DBD DEST	FD

Caesar Creek

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Caesar Creek Buoy 29	11125	MISSING	FD
Caesar Creek Buoy 30	11130	MISSING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Elliott Key - Caesar	Advanced Notice	ATON/Advanced Notice of Change Location: 25.40402° N / 80.24117° W Aid Name: Caesar Creek Buoy 29 LLNR: 11125 Action: DISCONTINUE	Lat:
Creek/ATON/Advanced Notice of Change	of Change	The following changes have been approved to the aids to navigation system in Caesar Creek. Caesar Creek B 29 (LLNR 11125) and Caesar Creek B 30 (LLNR 11130) will be permanently discontinued. The immediate area surrounding these buoys has significant shoaling which reduces the effectiveness in desired navigational safety. Due to strong currents these buoys are constantly being drug off station. Due to the limitations of CG assets that can service this area, buoy mooring configuration is limited. Mariners have been observed entering or departing the channel in other areas due to the shoaling experienced.	25° 24' 14" Lon: -080° 14' 28"
Elliott Key - Caesar Creek/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 25.40427° N / 80.24105° W Aid Name: Caesar Creek Buoy 30 LLNR: 11130 Action: DISCONTINUE The following changes have been approved to the aids to navigation system in Caesar Creek. Caesar Creek B 29 (LLNR 11125) and Caesar Creek B 30 (LLNR 11130) will be permanently discontinued. The immediate area surrounding these buoys has significant shoaling which reduces the effectiveness in desired navigational safety. Due to strong currents these buoys are constantly being drug off station. Due to the limitations of CG assets that can service this area, buoy mooring configuration is limited. Mariners have been observed entering or departing the channel in other areas due to the shoaling experienced.	Lat: 25° 24' 15" Lon: -080° 14' 28"

Calibogue Sound

Additional MSI Categories

https://www.navcen.uscg.gov/msi

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Calibogue Sound Entrance -	Advanced Notice	ATON/Advanced Notice of Change From: 2024-11-25 To: 2025-05-24 Location: 32.1499° N / 80.83043° W Aid Name: Calibogue Sound Light	Lat:
Calibogue	of Change	32 LLNR: 35800 Action: CHANGE Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation	32° 08' 60"
Sound/ATON/Advanced Notice of		system in the Intracoastal Waterway Calibogue Sound, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced	Lon:
Change		from 5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA),	-080° 49'
		mariners should be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a	50"
		nominal range of 4NM is more than adequate.	

Caloosahatchee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Caloosahatchee River Daybeacon 19	52210	STRUCT MISSING	FD
Caloosahatchee River Light 70	53725	STRUCT DEST/TRLB	FD
Caloosahatchee River Light 72	53790	STRUCT DEST/TRLB/HAZ NAV	FD
Caloosahatchee River Daybeacon 94	54760	STRUCT MISSING/TRUB	FD
Caloosahatchee River Daybeacon 99	54785	TRUB/STRUCT MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
-t Myers Yacht Basin Breakwater Light	52640	STRUCT DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 1	52641	STRUCT DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 2	52642	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 3	52643	DBD DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 4	52644	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 5	52644.1	DBD DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 6	52644.200000000004	DAYMK MISSING	PA
t Myers Yacht Basin Breakwater West Light	52645	STRUCT DEST	PA
Marinatown Daybeacon 1	52655	DBD DEST	PA
Marinatown Daybeacon 3	52665	STRUCT DEST	PA
Marinatown Daybeacon 4	52670	STRUCT DEST	PA
Marinatown Daybeacon 5	52675	DBD DEST	PA
Marinatown Daybeacon 7	52685	DAYMK MISSING	PA
Marinatown Daybeacon 8	52690	DBD DEST	PA
Marinatown Daybeacon 12	52710	STRUCT DMGD	PA
Marinatown Daybeacon 13	52715	DBD DMGD	PA
Marinatown Daybeacon 22	52760	STRUCT DEST	PA
Marinatown Daybeacon 23	52765	DAYMK MISSING	PA
Marinatown Daybeacon 24	52770	DAYMK MISSING	PA
Marinatown Daybeacon 26	52780	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 1	52825	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 4	52840	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 5	52845	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 9	52870	STRUCT DEST	PA
Cape Coral Rim Channel Daybeacon 23	53070	HAZ NAV/DAYMK MISSING	PA
Cape Coral Rim Channel Daybeacon 39	53110	STRUCT DEST	PA
/an Riper Channel Daybeacon 2	54296	DAYMK MISSING	PA
/an Riper Channel Daybeacon 4	54296.5	DAYMK MISSING	PA
/an Riper Channel Daybeacon 6	54297	DAYMK MISSING	PA
/an Riper Channel Daybeacon 8	54297.5	DAYMK MISSING	PA
/an Riper Channel Daybeacon 10	54298	DAYMK MISSING	PA
an Riper Channel Daybeacon 12	54298.5	DAYMK MISSING	PA
Bimini Entrance Channel Daybeacon 2	54305	STRUCT DMGD	PA
Redfish Cove Channel Daybeacon 18	54445	STRUCT DEST	PA
Redfish Cove Channel Daybeacon 20	54455	STRUCT DEST	PA
Shell Point Obstruction Daybeacon A	54763	STRUCT DEST	PA

Canaveral Barge Canal

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sykes Creek Daybeacon 19	41620	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

https://www.navcen.uscg.gov/msi 9/71

Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2024-11-12 To: 2025-10-31 Location: 28.40575° N / 80.69424° W Bridge Name: Sea Ray Drive Bridge SEMA Construction, on behalf of the bridge owner, Brevard County, has commenced the demolition, removal, and replacement of Sea Ray Drive Bridge over Sykes Creek on Merritt Island. The contractor will have a small boat on-site, which will be removed from the water at end-of-day. Temporary work platforms may be utilized at future stages of the project. There are no proposed channel restrictions for the early part of this project but can be expected starting approximately early April 2025. For waterways related questions, contact Coast Guard Sector Jacksonville Waterways Management Division at (904) 714-7631 or via email at D07-DG-SECJAX-WATERWAYS@uscg.mil.	Lat: 28° 24' 21' Lon: -080° 41' 39"
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-03-12 To: 2025-09-29 Location: 28.40925° N / 80.63224° W Bridge Name: 401 State Route Bridges From 7 a.m. on April 2, 2025, through 7 p.m. on September 28, 2025, the drawbridges will provide single-leaf openings with a 4-hour notice for a full opening, per its specific requirements 33 CFR 117.273(b). During this time, the channel will be partially obstructed under the spans painting is occurring. A one-hour advanced notice is required for vessels needing more than 45 feet of horizontal clearance but can safely pass with the spans in the down (closed) position.	Lat: 28° 24' 33' Lon: -080° 37' 56"
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Repairs, Painting, Or Fender Replacement	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2025-03-12 To: 2025-10-18 Location: 28.40925° N / 80.63224° W Bridge Name: 401 State Route Bridges A painting/repair project begins on April 1, 2025, and will be completed on or around October 18, 2025. During the time the bridges will be operating under a temporary deviation to drawbridges operations. The contractor will be on-site 24 hours a day. All in-water equipment should be lighted in accordance with Inland Navigation Rules. Mariners are advised to use caution when transiting through the bridges.	Lat: 28° 24' 33' Lon: -080° 37' 56"
Canaveral Harbor - Canaveral Barge Canal/General/Miscellaneous	Miscellaneous	General/Miscellaneous Cape Canaveral Barge Canal and Banana River: Waterway Analysis and Management System Review. The U.S. Coast Guard is conducting a Waterway Analysis and Management System (WAMS) review of the navigable waters from the Cape Canaveral Barge Canal through the Banana River, Florida. The review focuses on the area's aids to navigation, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routing and emergency communication capabilities, and future development projects. Input regarding the waterway and aids to navigation system must be received by May 23, 2025. Input may be provided using the survey link below or directly to the point of contact listed. https://www.surveymonkey.com/r/X3JMTGY Send comments to: U.S. Coast Guard Sector Jacksonville Waterways Management Division Attn: ATON Officer 10426 Alta Drive Jacksonville, FL 32226-7618 Email: SECJAXWATERWAYS@uscq.mil	

Cape Haze Shoal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Haze Shoal Light 5	19990	HAZ NAV/STRUCT DEST/TRLB	FD
Cape Haze Shoal Light 6	19995	STRUCT MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Burnt Store Marina Light 2	20000	LT EXT	PA
Burnt Store Marina Daybeacon 5	20015	STRUCT DEST	PA
Alligator Creek Daybeacon 23	20305	STRUCT DMGD	PA
Alligator Creek Daybeacon 24	20310	STRUCT DEST	PA
Pine Island West Channel Daybeacon 5	56510.1	STRUCT DEST/HAZ NAV	PA

Capri Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Capri Pass Light 1	16945	DBD DEST/LT EXT	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD
Capri Pass Daybeacon C	16980	TRLB	FD
Capri Pass Shoal Daybeacon B	17050	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Addison Bay Daybeacon 1	16901.1	STRUCT DEST	PA
Addison Bay Daybeacon 2	16901.2	STRUCT DEST	PA
Addison Bay Daybeacon 4	16901.4	STRUCT DEST/HAZ NAV	PA
Addison Bay Daybeacon 5	16901.5	STRUCT DEST	PA
South Point North Obstruction Daybeacon	16961	STRUCT DEST/HAZ NAV	PA
South Point S. Obstruction Daybeacon	16962	STRUCT DEST/HAZ NAV	PA
Royal Marco Point North Obstruction Daybeacon	16986	STRUCT DEST	PA
Royal Marco Point S. Obst. Daybeacon	16987	STRUCT DEST	PA
Collier Bay Daybeacon 13	17021	DAYMK MISSING	PA
Collier Bay Daybeacon 15	17023	DAYMK MISSING	PA
Factory Bay E Channel Daybeacon 2	17070	DBD DMGD	PA
Factory Bay E Channel Daybeacon 4	17075	DBD DEST	PA

Captiva Channel

Private Discrepancies

https://www.navcen.uscg.gov/msi

NAME	LLNR	STATUS	AID TYPE
Captiva Channel Daybeacon 5	55620	STRUCT DEST	PA

Caxambas Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater River Daybeacon 10	16505	DAYMK MISSING	PA
Blackwater River Daybeacon 11	16510	STRUCT DEST/HAZ NAV	PA
Blackwater River Daybeacon 13	16520	STRUCT DEST	PA
Blackwater River Daybeacon 15	16530	STRUCT DEST	PA
Blackwater River Daybeacon 22	16555	STRUCT DEST	PA
Blackwater River Daybeacon 24	16565	STRUCT DEST/HAZ NAV	PA
Caxambas Bay South Approach Daybeacon 2	16675	STRUCT DEST	PA
Caxambas Bay Daybeacon 11	16715	DAYMK MISSING	PA
Horrs Island North Channel Daybeacon 8	16790	STRUCT DEST/HAZ NAV	PA
Snook Hole Channel Daybeacon 1	16790.010000000002	STRUCT DEST	PA
Snook Hole Channel Daybeacon 4	16790.04	STRUCT DEST/HAZ NAV	PA
Big Marco River Daybeacon 3	16800	STRUCT DEST	PA
Moran's Marina Channel Daybeacon 1	16835	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 2	16840	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 3	16845	DAYMK MISSING	PA
Big Marco River Daybeacon 16	16860	STRUCT DEST	PA
Big Marco River Daybeacon 21	16880	STRUCT DMGD	PA
Big Marco River Daybeacon 26	16900	STRUCT DEST/HAZ NAV	PA

Cedar Keys Main Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys Main Channel Daybeacon 8	29770	STRUCT MISSING/TRUB	FD
Cedar Keys Main Channel Light 14	29790	STRUCT MISSING/TRLB	FD
Cedar Keys Main Channel Light 18	29800	STRUCT MISSING/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Cedar Keys Main	Hazards To	General/Hazards To Navigation/Hazards From: 2024-12-06 To: 2025-06-04 Location: 29.11403° N / 83.04028° W Cedar Key Main	Lat:
Channel/General/Hazards To Navigation/Hazards	Navigation	Channel 19A has been temporarily established to guide vessel traffic channel ward and away from submerged wreckage between Cedar Keys Main Channel Daybeacon 19 (LLNR 29805) and Cedar Keys Main Channel Light 21 (LLNR 29810). All mariners are advised to transit	
		the area with caution.	-083° 02'

Cedar Keys Northwest Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys Northwest Channel Daybeacon 14	29965	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Daybeacon 17	29980	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Light 19	29995	STRUCT DEST/HAZ NAV/TRLB	FD
Cedar Keys Northwest Channel Daybeacon 21	30005	TRLB/STRUCT DEST/HAZ NAV	FD
Cedar Key Northwest Channel Daybeacon 22	30010	TRLB/HAZ NAV/STRUCT DEST	FD

Cedar Keys South Bar Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys South Bar Channel Daybeacon 4	29900	STRUCT MISSING/TRUB	FD

Charleston Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charleston Entrance Lighted Buoy C	200	RAC INOP	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Advanced Notice of Change		Charleston Harbor Channel LB 18 (LLNR 2420) will have the bell permanently removed.	Lat: 32° 43' 27" Lon: -079° 48' 37"
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Advanced Notice of Change		Charleston Harbor Channel LB 22 (LLNR 2440) will have the bell permanently removed.	Lat: 32° 44' 26" Lon: -079° 50' 41"
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.75328° N / 79.87473° W 32.75232° N / 79.87355° W 32.75075° N / 79.87546° W 32.75198° N / 79.87705° W 32.75328° N / 79.87473° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 31October 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.	

Charleston Harbor North Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rebellion Reach Range Front Light	2485	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor - Charleston Harbor North Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	Bennis Reach RFL (LLNR 2505.5) will be relocated to approximate position 32-47-15.433N/079-55-25.965W with an approximate focal height of 29°. The flash characteristics of the optic will remain a Q R. Two passing lights displaying a FI W 2.5s will be mounted on opposite corners of the platform with both lights synchronized.	Lat: 32° 47' 18" Lon: -079° 55' 29"
Charleston Harbor - Charleston Harbor North Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	Bennis Reach RRL (LLNR 2506) will be relocated to approximate position 32-47-22.658N/079-55-42.841W with an approximate focal height of 71 feet. The new position will keep the RRL on land, located on the top level of a parking garage in downtown Charleston. The flash characteristics of the optic will remain a R Iso 6s.	Lat: 32° 47' 24" Lon: -079° 55' 43"
Charleston Harbor - Charleston Harbor North Channel/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.78003° N / 79.92337° W 32.77867° N / 79.9233° W 32.77871° N / 79.92452° W 32.77997° N / 79.92455° W 32.78003° N / 79.92337° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 31October 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.	

Charleston Harbor Savannah River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ramshorn Creek Light 39	35825	STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parris Island Fish Haven Buoy	35600	MISSING	PA
Braddock Cove Creek Jetty Light	35815.5	LT IMCH	PA

Charleston Harbor South Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charleston Harbor South Channel Daybeacon 6	2685	STRUCT DEST/TRUB	FD

Charlotte Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charlotte Harbor Channel Lighted Buoy 5	19935	MISSING	FD

Chokoloskee Bay Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
National Park Service Boat Basin South Channel Daybeacon 1	16105	STRUCT DEST	PA
National Park Service Boat Basin South Channel Daybeacon 5	16125	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 1	16135	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 2	16140	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 5	16150	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 6	16155	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 7	16160	STRUCT DEST	PA

Christiansted Harbor Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Christiansted Schooner Channel Lighted Buoy 7	32965	BUOY DMGD	PA
Christiansted Schooner Channel Lighted Buoy 5	32950	OFF STA/LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 6	32955	LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 10	32980	LT EXT	PA
Christiansted Schooner Lighted Buoy 11	32985	LT EXT	PA

Clarks Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clarks Creek Lighted Buoy 6	2247	MISSING	FD

Clearwater Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clearwater Harbor Light 4	61725	STRUCT MISSING/TRLB	FD
Clearwater Wreck Light WR14A	61805	STRUCT MISSING/TRLB	FD
Clearwater Harbor Daybeacon 20	61847	STRUCT DEST/TRUB	FD

Private Discrepancies Corrected

•				
NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Seminole Launch Channel Daybeacon 4	61815	WATCHING PROPERLY	PA	2025-05-08

Clewiston Channel Route 1B

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clewiston Channel (Rt 1B) Daybeacon 5	51275	STRUCT DEST/TRLB	FD
Clewiston Channel (Rt 1B) Daybeacon 9	51295	STRUCT DEST	FD
Clewiston Channel (Rt 1b) Light 12	51340	STRUCT DMGD	FD
Clewiston Channel (Rt 1B) Daybeacon 14	51350	STRUCT DEST/TRUB	FD

Cooper River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cooper River Daybeacon 114	3243	STRUCT DMGD	FD

Private Discrepancies

·			
NAME	LLNR	STATUS	AID TYPE
U.S. South Navy Pier North Light (1)	2825	LT EXT	PA
Don Holt I-526 Bridge Racon	2905.5	RAC INOP	PA
Cooper River Ammunition Pier Light	3015	LT EXT	PA
South Carolina Gas & Elec North Pier Light	3260	LT EXT	PA
South Carolina Gas & Elec South Pier Light	3265	LT EXT	PA
Upper Cooper River Daybeacon 12	3287.8	STRUCT DEST	PA
Upper Cooper River Daybeacon 22	3288.5	DAYMK DMGD	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor - Cooper River/ATON/ATON Changes	ATON Changes	ATON/ATON Changes From: 2025-05-09 To: 2025-11-05 Location: 32.85434° N / 79.94786° W Aid Name: U.S. Coast Guard Pier M Light LLNR: 2830 Action: ESTABLISH Position: 32-51-15.630N, 079-56-52.313W Light: F G	Lat: 32° 51' 16" Lon: -079° 56' 52"
Charleston Harbor - Cooper River/ATON/ATON Changes	ATON Changes	ATON/ATON Changes From: 2025-05-09 To: 2025-11-05 Location: 32.8529° N / 79.94378° W Aid Name: U.S. Coast Guard Pier P Light LLNR: 2815 Action: ESTABLISH Position: 32-51-10.430N, 079-56-37.613W Light: F G	Lat: 32° 51' 10" Lon: -079° 56' 38"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025-04-18 Location: 32.85289° N / 79.94381° W The USCG will be demolishing, rebuilding and dredging pier november in approximate position 32-51-09.7N/079-56-48.8W. Operations are expected to commence January 15, 2024, with an estimated completion date of December 31, 2026. During the construction phase operations will be conducted Monday-Friday 7 a.m. to 7 p.m., during dredging operations may be continuous 24 hours a day/ 7 days a week. For further information contact: LCDR John Houk at John.R.Houk@uscg.mil.	Lat: 32° 51' 12" Lon: -079° 56' 45"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 9392 From: 2025-01-21 To: 2026-10-30 Location: 32.8512° N / 79.94134° W Demolition is now in progress and there are cut piles that may be difficult to see at higher tide within the footprint of the old Pier Romeo. The Manson Construction Team has posted (1) "Danger" Buoy and an Amber Light for demarcation on the outermost submerged piles and obstructions. These markers are attached to a 36-inch diameter steel pile that stands about 20 feet above the water line and among the submerged objects. Beginning October 30, 2024, and ending October 30, 2026, Manson Construction will be performing demolition of the existing pier and construction of a new pier, bulkhead, and shoreline at the Romeo Pier NOAA Facility on the Cooper River. There will be a crane barge, material barges, and support vessels in the area assisting construction operations from 7a.m. to 7p.m., 7 days a week. These activities could pose a hazard to vessels traveling within 900 feet from the bulkhead to the center of the river. Mariners need to take caution when transiting the area. Please watch for dive flags, stay clear of the construction area, and away from any working equipment. Crews will be monitoring VHF-FM channel 61. For more information, please contact Doug Lowe at (904) 465-1762.	Lat: 32° 51' 04" Lon: -079° 56' 29"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging SOUTHERN DREDGING CO. INC. DREDGE BRUNSWICK will be working from the Clouter Creek Reach in the Cooper River to the Ordnance Reach Turning Basin in the Cooper River commencing on or about April 2, 2025. The Dredge will operate on a 24 hour per day, 7 day per week basis until approximately June 1, 2025. Underwater pipeline will be installed outside the RED side of the channel the entire length of Clouter Island. To ensure safe passage in the vicinity of the operation, boaters should establish contact with the dredge on VHF marine channels 13 and 16 or by telephone at 843-729-1691.	
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 18251 Orion Marine Construction, Inc. will begin construction work at the Hugh K. Leatherman, Sr. Terminal located along the western shore of the Cooper River, North Charleston, SC at (32° 50' 28N/079° 55' 58W). Within the scope of the jobsite, there will be temporary steel structures that will be periodically move as the job progresses. The structures will display a FL 2.5 W, 2NM lights. Operations will consist of dredging, armor stone slope protection installation, pile driving, and new wharf construction. Operations at the project site will commence in May 2025 and will extend through December 2026. Tugboats will monitor VHF channel 13. Mariners are urged to use extreme caution when transiting the work area. For more information, contact the Project Superintendent, Dustyn Fields at dfields@orionmarinegroup.com, or Project Manager, Tyler Satterfield at tsatterfield@orionmarinegroup.com.	
Charleston Harbor - Cooper River/General/Marine Events/Swim	Marine Events	General/Marine Events/Swim 18005 The annual "Lowcountry Splash" swim is scheduled for Saturday, May 24, 2025, from 7:30 am to 10:45 am. This event is an open water swim with two starts. The six-mile swim will start under the Wando Bridge on Daniel Island, cross the Wando River near Hobcaw Yacht Club, and will finish at the Charleston Harbor Marina. The 2.4-mile swim will start from the Hobcaw Yacht Club continue along the Mount Pleasant side of the river and finish at the Charleston Harbor Marina. A special local regulation, established in 33 CFR 100.704, Table 1, Item No. 4, will be in effect for a moving safety zone. This safety zone will encompass all waters surrounding event participants and safety vessels extending 50-yards in front and behind, and 100-yards on either side. All mariners are urged to use caution while transiting the area. Concerned vessel traffic should coordinate with on-scene safety boats via VHF-FM channel 16. Any concerns or questions related to the event may be directed to the event organizers at 843-642-9232 or at https://lowcountrysplash.com/.	
Charleston Harbor - Cooper River/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change Location: 32.9403° N / 79.92368° W Aid Name: Cooper River Range D Rear Light LLNR: 3045 Action: RELOCATE The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Cooper River: Cooper River Range D Rear Light (LLNR 3045) will be permanently relocated to approximate position 32-56-27.083N / 079-55-21.194W. Cooper River Range D/F Front Light (LLNR 3040) will have the flash characteristic changed from a Q W to a FL W 2.5s. The light will continue to be an all-around light. Due to the current location of Cooper River Range D Rear Light (LLNR 30465) being inaccessible for a Coast Guard asset to effectively repair the structure, it was determined by relocating the rear range approximately 400 feet further from its current location will offer a much improved range quality and allow CG personnel to service at any tidal state. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with Cooper River Range D/F as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL 33131-3050 to be received by July 31, 2025.	
Charleston Harbor - Cooper River/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change Location: 32.93982° N / 79.92463° W Aid Name: Cooper River Range D/F Front Light LLNR: 3040 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Cooper River: Cooper River Range D Rear Light (LLNR 3045) will be permanently relocated to approximate position 32-56-27.083N / 079-55-21.194W. Cooper River Range D/F Front Light (LLNR 3040) will have the flash characteristic changed from a Q W to a FL W 2.5s. The light will continue to be an all-around light. Due to the current location of Cooper River Range D Rear Light (LLNR 30465) being inaccessible for a Coast Guard asset to effectively repair the structure, it was determined by relocating the rear range approximately 400 feet further from its current location will offer a much improved range quality and allow CG personnel to service at any tidal state. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with Cooper River Range D/F as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL 33131-3050 to be received by July 31, 2025.	Lat: 32° 56' 23" Lon: -079° 55' 29"

Coosaw River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parrot Creek Daybeacon 3	35235	STRUCT DEST	PA

https://www.navcen.uscg.gov/msi

Cowpens

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cowpens Daybeacon 73A	50605	STRUCT DEST/HAZ NAV/TRLB	FD

Cranes Bayou

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dock On The Bay Daybeacon 7	59015	DAYMK MISSING	PA

Cross Florida Greenway

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cross Florida Greenway Daybeacon 27	29265	STRUCT DEST/TRUB	FD
Cross Florida Greenway Daybeacon 33	29295	STRUCT MISSING	FD
Cross Florida Greenway Daybeacon 36	29310	STRUCT DEST	FD

Cruz Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cruz Bay Light	32775	LT EXT/DAYMK MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cruz Bay Buoy 2	32785	OFF STA	PA

Crystal River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Entrance Daybeacon 12	28845	DAYMK MISSING	FD
Crystal River Entrance Daybeacon 14	28855	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Daybeacon 25	28952.600000000002	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Crystal River/General/Bridges/Rehabilitation	J	General/Bridges/Rehabilitation From: 2025-03-11 To: 2025-07-01 Location: 28.91606° N / 82.62775° W Bridge Name: North Museum Point Road Bridge The bridge is under repairs and a rehabilitation. The project is expected to be completed by June 30, 2025. The waterway may be obstructed to navigation; however, the contractor will move to allow for the passage of vessel traffic. All in-water equipment will be lighted. Mariners are advised to use caution when transiting the waterway.	Lat: 28° 54' 58" Lon: -082° 37' 40"

Cumberland River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland River Light 33	37390	STRUCT DEST/TRLB	FD
Cumberland River Light 35	37405	STRUCT MISSING/TRLB	FD
Cumberland River Light 46	37540	STRUCT MISSING/TRLB	FD
Cumberland River Daybeacon 51	37560	STRUCT DEST/TRUB	FD
Cumberland River Daybeacon 58A	37603	STRUCT DEST/HAZ NAV/TRLB	FD
Cumberland River Daybeacon 59A	37607	STRUCT DEST/TRUB	FD
Cumberland River Light 60	37610	STRUCT DEST/TRLB	FD
Cumberland River Daybeacon 63	37623	STRUCT DEST/TRUB	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

St Andrew Sound - Cumberland	Advanced Notice	Cumberland River LT 35 (LLNR 37405) will be relocated due to the water depth at current location being too deep for CG assets to effect	Lat:
River/ATON/Advanced Notice of	of Change	repairs. The aid will be relocated approximately 453 yards south of its current location in a depth of 15 feet. This change will ensure safe	30° 57' 15"
Change		navigation and keep the same alignment with the surrounding aids in the Cumberland River. Cumberland River LT 35 (LLNR 37405) will	Lon:
		be relocated to approximate position 30-57-14.700N/081-25-44.460W.	-081° 25'
			44"

Cumberland Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland Sound Upper Range A Rear Light	6695	STRUCT DEST	FD
Cumberland Sound Shoal Light A	6773	STRUCT DEST	FD
Cumberland Sound Shoal Light B	6837	STRUCT DEST	FD
Cumberland Sound Shoal Light D	6867	STRUCT DEST	FD
Cumberland Sound Shoal Light G	6892	STRUCT DEST	FD
Cumberland Sound Shoal Light H	6894	STRUCT DEST/TRLB/MISSING	FD
Cumberland Sound Shoal Light I	6927	STRUCT DEST	FD
Cumberland Sound Range F Front Light	37645	LT EXT	FD
Cumberland Sound Daybeacon 71	37665	DBD DEST	FD

Cut A Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Skyway Pier Southeast Light	22425	LT EXT	PA
Tampa Bay Skyway Pier Northeast Light	22430	LT EXT	PA

Cut G Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Smacks Bayou Daybeacon 10	25025.7	STRUCT DEST/HAZ NAV	PA
Smacks Bayou Daybeacon 1	25025	STRUCT DEST	PA
Smacks Bayou Daybeacon 3	25025.2	STRUCT DEST	PA
Smacks Bayou Daybeacon 5	25025.4	STRUCT DEST	PA
Smacks Bayou Daybeacon 6	25025.5	DAYMK MISSING	PA
Smacks Bayou Daybeacon 8	25025.600000000002	STRUCT DEST	PA
Smacks Bayou Daybeacon 13	25025.9	STRUCT DEST	PA
Smacks Bayou Daybeacon 14	25026	HAZ NAV/DAYMK MISSING	PA
Smacks Bayou Daybeacon 15	25026.100000000002	DAYMK MISSING	PA
Smacks Bayou Daybeacon 16	25026.2	DAYMK MISSING	PA

Cut K Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut K Channel Lighted Buoy 10K	23930	BUOY DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rattlesnake Channel Daybeacon A	23814	DAYMK IMCH	PA
Westshore Yacht Club Light 2	23814.100000000002	STRUCT DEST	PA
Westshore Yacht Club Daybeacon 4	23814.2	STRUCT DEST	PA
Old Tampa Bay Pipeline West Light	23950.5	STRUCT DEST/HAZ NAV	PA
Culbreath Bayou North Daybeacon 3	24070	DAYMK MISSING	PA
Bay Crest Daybeacon 5	24275	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 2	25040	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 3	25045	DAYMK DMGD	PA
Bayou Grande Channel Daybeacon 9	25065	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 21	25105	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 30	25150	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 31	25155	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 41	25200	STRUCT DEST	PA
Mobel Americana Channel Daybeacon 3	25260.2	DAYMK MISSING	PA
Tanglewood Channel Daybeacon 1	25265	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Tampa Bay Cut J Channel - Cut K	Bridges	General/Bridges/Construction From: 2024-11-19 To: 2025-09-30 Location: 27.92889° N / 82.58725° W Bridge Name: Howard Frankland	Lat:
Channel/General/Bridges/Construction		I-275 Bridges Construction of the new I-275 Howard Frankland Bridge crossing Old Tampa Bay is ongoing. Bridge work will be	27° 55' 44"
		performed 24 hours per day, Monday through Saturday. 3/26/2025 THROUGH 5/31/2025 CHANNEL TRAFFIC WILL BE OBSTRUCTED	Lon:
		NORTH OF THE EXISTING FENDER FOR INSTALLATION OF THE FENDER SYSTEM ON THE NEW HOWARD FRANKLAND BRIDGE. WE	-082° 35'
		WILL HAVE TUGBOATS ACTIVELY WORKING EVERY SHIFT WHILE THE CHANNEL IS OBSTRUCTED AND BARGES CAN BE MOVED OUT	14"
		OF THE CHANNEL WITHIN 30 MINUTES TO AN HOUR. DURING CONSTRUCTION THE CHANNEL WILL BE IMPEDED BY \sim 5'-0" ON	
		BOTH SIDES OF THE CHANNEL FOR INSTALLATION OF A PILE TEMPLATE. THIS IMPEDENCE IS ON THE EAST AND WEST SIDE OF THE	
		FENDER SYSTEM. TEMPLATES MAY BE INSTALLED UP TO 24 HOURS A DAY UNTIL CONSTRUCTION IS COMPLETE. VHF-FM radio	
		channels 13, 22A and 16 are being monitored.	

Darien River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Darien River Daybeacon 17	36826.700000000004	STRUCT DEST/TRUB	FD

Derrick Key Gap Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Derrick Key Gap Channel Daybeacon 2	30055	STRUCT DEST	FD
Derrick Key Gap Channel Daybeacon 3	30060	TRLB/STRUCT MISSING	FD

District 7, Oceanic boundary to EEZ

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Nicolas Point Channel Light 4	33400	STRUCT DEST/HAZ NAV/TRLB	FD
St Nicolas Point Channel Light 7	33415	STRUCT DEST/TRLB	FD
Radio Point Light 1	33490	LT EXT	FD
Evans Point Light 8	33530	DBD DEST	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Nicolas Point Channel Lighted Buoy 6	33410	RELOCATED FOR DREDGING	FD

Doboy Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Buoy 2	5920	OFF STA	FD
Doboy Sound Buoy 3	5925	MISSING	FD
Doboy Sound Buoy 4	5930	OFF STA	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Island LT	5946	LT EXT	PA

Drummond Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Cut Lighted Buoy 59	7500	OFF STATION	FD
Drummond Creek Range Front Light	7515	STRUCT DEST/TRLB	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Lighted Buoy 58	7505	RELOCATED FOR DREDGING	FD
Drummond Creek Lighted Buoy 61	7525	RELOCATED FOR DREDGING	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

St Johns River - Drummond	Advanced Notice	Drummond Creek RFL (LLNR 7515) will be permanently relocated to approximate position 30-24-45.104N / 081-35-35.319W. The RFL will	Lat:	
Creek/ATON/Advanced Notice	of Change	remain a nighttime optic only and flash characteristic will remain as a Q R. The RFL will continue to display daymarks for the day-time signal.	30° 24' 44"	
of Change		Both Drummond Creek RFL and RRL will be upgraded with LED light signals to provide a much more reliable signal when using this channel.	Lon:	
		An additional light will be established and mounted on top of the Drummond Creek RFL optic and synchronized with the RFL to display a QR	-081° 35'	
		flash characteristics during nighttime hours only, with a nominal range of 3NM.	38"	

Duplin River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Light 178	36795	STRUCT DMGD	FD

East Cape

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Cape Daybeacon 1A	15655	STRUCT DEST/HAZ NAV/TRUB	FD

Elba Island Cut

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lower Flats Range - Elba	Advanced Notice	ATON/Advanced Notice of Change From: 2024-11-25 To: 2025-05-24 Location: 32.06387° N / 80.99495° W Aid Name: Elba Island Cut Light 10	Lat:
Island Cut/ATON/Advanced	of Change	LLNR: 35900 Action: CHANGE Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system	32° 03' 50"
Notice of Change		in the Intracoastal Waterway Elba Island Cut Channel, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from	Lon:
		5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should	-080° 59'
		be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is	42"
		more than adequate.	

Elliott Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elliott Key Light 16	10940	DAYMK MISSING/STRUCT DMGD/TRLB	FD
Elliott Key Daybeacon 17	10945	STRUCT DEST	FD
Elliott Key Daybeacon 19	10955	STRUCT DEST/HAZ NAV/TRLB	FD

Entrada Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Entrada Channel Daybeacon 1	49240	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 3	49245	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 5	49250	DAYMK MISSING	PA
Entrada Channel Daybeacon 7	49255	DAYMK MISSING	PA
Entrada Channel Daybeacon 9	49260	DAYMK MISSING	PA
Entrada Channel Daybeacon 11	49265	DAYMK MISSING	PA
Entrada Channel Daybeacon 13	49270	DAYMK MISSING	PA

Fishermans Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fishermans Channel Light 11	10685	STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dodge Island Mooring Obstruction Light	10692	STRUCT DEST	PA

Florida Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Long Key Light 44	13495	STRUCT DEST/HAZ NAV/TRLB	FD
East Turtle Shoal Light 45	13610	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Flamingo Channel Light 9	15680	DAYMK MISSING	PA
Flamingo Channel Light 15	15710	DAYMK MISSING	PA
Flamingo Channel Daybeacon 16	15715	DAYMK MISSING	PA
Coot Bay Daybeacon 2	15730	STRUCT DEST	PA
Coot Bay Daybeacon 8	15755	DAYMK MISSING	PA

Florida Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Florida Passage Daybeacon 102	36385	STRUCT MISSING/TRUB	FD

Floyd Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Floyd Creek Daybeacon A27	37496	STRUCT DEST/TRUB	FD

Folly River

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Folly River Buoy 14	3750.4	RESET ON STATION	FD	2025-05-05
Folly River Buoy 17A	3750.9	RESET ON STATION	FD	2025-05-05

Fort Gates

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Gates Light 67	8525	STRUCT DEST/TRLB	FD

Fort Jackson

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Jackson Inbound Range Front Light	4955	STRUCT MISSING	FD

Fort Pierce Inlet Inner Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Pierce Inlet Inner Harbor Lighted Buoy 9	9840	TRLB/MISSING	FD

Frederica River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fredericka Yacht Club Obstruction Light	6170	LT EXT	PA

Fulton Cutoff

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fulton Cutoff Light 36	7360	STRUCT DEST/TRLB	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Fulton Cutoff Lighted Buoy 37	7365	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Lighted Buoy 43	7385	RELOCATED FOR DREDGING	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Fulton	Advanced Notice	Fulton Cutoff LB 35 (LLNR 7345) will be permanently relocated to 30-23-24.090N/081-30-22.230W. This change calls to relocate (6) lighted	Lat:
Cutoff/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 24"
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe	Lon:
		navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this	-081° 30'
		change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.	22"
St Johns River - Fulton	Advanced Notice	Blount Island Turning Basin LB 43 (LLNR 7385) will be permanently relocated to 30-23-13.450N/081-32-05.380W. The flash characteristic will	Lat:
Cutoff/ATON/Advanced Notice	of Change	remain a FI G 6s, but the nominal range will be reduced from 5NM to 4NM.	30° 23' 13"
of Change			Lon:
			-081° 32'
			05"

Gables Estates

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gables Estates Daybeacon 2A	49345	STRUCT DEST/HAZ NAV	PA

Gadsden Point Cross Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gadsden Point Cross Channel Daybeacon 10	22965	STRUCT MISSING/TRUB	FD

Gadsden Point Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Uddusuen Point Cut Range Real Light Passing Lights	22855.5	LT EXT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Gadsden Point Cut Lighted Buoy 7	23000	RELIGHTED	FD	2025-05-08

Garden Cove

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Garden Cove Daybeacon 3	11550	DAYMK MISSING	PA
Garden Cove Daybeacon 4	11555	DBD DEST	PA
Garden Cove Daybeacon 4	11555	DAYMK IMCH/STRUCT DMGD	PA
Garden Cove Daybeacon 6	11565	STRUCT DEST/HAZ NAV	PA
Garden Cove Daybeacon 8	11575	DAYMK IMCH	PA
Garden Cove Daybeacon 9	11580	DAYMK MISSING	PA
Garden Cove Daybeacon 11	11590	RBN IMCH	PA

Gasparilla Sound Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gasparilla Sound Channel Daybeacon 21	56650	STRUCT MISSING/TRUB	FD

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Gasparilla Island South Obstruction Light	1305.2	LT EXT	PA
Gaparilla Island West Obstruction Light	1305.4	LT EXT	PA
Gasparilla Island North Obstruction Light	1305.60000000001	LT EXT	PA
Gasparilla Marina Channel Daybeacon 6	56715	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Pine Island Sound - Gasparilla Sound	Marine Events	General/Marine Events/Other 17980 A large marine event will be taking place in the vicinity of the Boca Grande Sandbar, adjacent	
Channel/General/Marine Events/Other		to Boca Grande Causeway in Placida, FL. The event will take place on May 24, 2025, from 9 a.m. to 4 p.m. Mariners are advised to exercise caution when transiting this area.	

https://www.navcen.uscg.gov/msi 20/71

Gordon Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gordon Pass Channel Buoy 1	17453	MISSING	FD
Gordon Pass Channel Light 3	17460	STRUCT MISSING/TRLB	FD
Gordon Pass Channel Light 4	17465	DBD DEST	FD

Great Pocket

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Great Pocket Daybeacon 10	45970	STRUCT DEST/TRUB	FD

Grouper Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Grouper Creek Daybeacon 52A	50425	STRUCT DEST/HAZ NAV/TRLB	FD

Halifax Creek

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Halifax River - Halifax Creek/General/Bridges/Maintenance	J	and end approximately 5/13/2025. Work hours will be daily from 8 a.m. to 7 p.m. The channel will be partially obstructed providing for	29° 24' 31"

Halifax River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax River Daybeacon 40	40180	STRUCT DMGD	FD
Halifax River Daybeacon 48	40215	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 53	40235	STRUCT MISSING/TRUB	FD
Halifax River Daybeacon 56	40245	STRUCT MISSING/TRUB	FD
Halifax River Daybeacon 57	40335	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 60	40435	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 72	40490	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax Harbor Daybeacon 1	40055	DAYMK MISSING	PA
Halifax Harbor Daybeacon 4	40070	DAYMK MISSING	PA
Halifax Harbor Daybeacon 6	40080	DAYMK MISSING	PA
Halifax Harbor Daybeacon 8	40090	STRUCT DEST	PA
Halifax Harbor Daybeacon 9	40095	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 4	40365	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 6	40375	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 7	40380	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 8	40385	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 9	40390	DAYMK MISSING	PA
Adventure Yacht Harbor Junction Daybeacon	40410	DAYMK IMCH	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

https://www.navcen.uscg.gov/msi

Ponce De Leon Cut - Halifax	Bridges	General/Bridges/Rehabilitation From: 2025-01-31 To: 2025-06-16 Location: 29.22316° N / 81.0176° W Bridge Name: Main Street Bridge -	Lat:
River/General/Bridges/Rehabilitation		AICW The bridge will undergo a rehabilitation beginning 2/11/2025 and end approximately 6/15/2025. Work hours are scheduled 7am -	29° 13' 23"
		6pm Monday through Friday; No work on Holidays/weekends- equipment to be removed from channel daily. The channel will be	Lon:
		partially obstructed beneath the closed leaf, leaving approximately 45 feet of horizontal clearance. The bridge will operate under a	-081° 01'
		temporary deviation to the drawbridge operating regulation as follows: - From 7 a.m. on February 17, 2025, through 6 p.m. on April 4,	03"
		2025, single-leaf only openings will be provided upon request From 7 a.m. on April 21, 2025, through 6 p.m. on May 23, 2025, single-	
		leaf only openings will be provided upon request During the single-leaf only times, a full channel passing will be accommodated with a	
		1-hour notice to move equipment from the waterway. This is only for vessels that need more than 45 feet of horizontal clearance but can	
		pass without an opening.	

Hampton River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hampton River Daybeacon 12	5975	STRUCT DEST/TRUB	FD

Hillsboro Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Inlet Entrance Light 2	10293	DBD DEST	FD

Hillsboro River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro River Light 73	47225	DBD DMGD	FD
Pompano Beach Light 76	47235	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Moran Dock North Light	47175	LT IMCH	PA
Moran Dock Center Light	47180	LT IMCH	PA
Moran Dock South Light	47185	LT EXT	PA

Hillsborough Cut C Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut C Channel Inbound Range Front Light	23435	LT EXT	FD
Hillsborough Cut C Channel Lighted Buoy 26	23450	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hookers Point North Warning Daybeacon	23515	STRUCT DEST/HAZ NAV	PA
Tampa Yacht & Country Club Daybeacon 4	23454	STRUCT DEST	PA

Additional MSI Categories

Additional more dicegories					
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION		
Big Bend Channel - Hillsborough Cut C Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change From: 2024-11-15 To: 2025-05-14 Location: 27.90797° N / 82.43823° W Aid Name: Hillsborough Cut C Channel Inbound Range Front Light LLNR: 23435 Action: CHANGE Action Type Change Light Characteristic Hillsborough Cut C Channel Inbound Range Front Light (LLNR 23435) characteristic will change to Iso W 2s (NIGHT) and Iso W 2s (Day).	Lat: 27° 54' 29" Lon: -082° 26' 18"		
Big Bend Channel - Hillsborough Cut C Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change From: 2024-12-06 To: 2025-06-04 Location: 27.92022° N / 82.43696° W Aid Name: Hillsborough Cut C Channel Inbound Range Rear Light LLNR: 23440 Action: CHANGE Action Type Change Light Characteristic Hillsborough Cut C Channel Inbound Range Rear Light (LLNR 23440) characteristic will change to Iso W 6s (NIGHT) and Iso W 6s (Day).	Lat: 27° 55' 13" Lon: -082° 26' 13"		

https://www.navcen.uscg.gov/msi

Big Bend Channel - Hillsborough Cut C Channel/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Marine Construction (Excluding Bridges) General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Orion Marine Group is currently contracted by the Tampa Bay Port Authority, operating as Port Tampa Bay, to construct the new berth (Berth 218 Wharf) at the Titan America facility. Orion respectfully requests that a revised Notice to Mariners be issued concerning our construction operations at 4231 Maritime Boulevard, Tampa, FL, specifically for Berth 218 Wharf. The construction activities will be conducted using the ORION IS-1505 Barge, a rental material barge from McDonough Marine Services (unnamed), as well as the ORION BRAVE. Floating equipment will be positioned within the designated Jobsite Working Limits, as delineated in the attached drawing of the Berth 218 project site. Orion will deploy spuds on the ORION IS-1505 Barge, which will be equipped with illuminating lights to enhance visibility. All floating equipment will be staged east of the channel inlet and equipped with marine lights. The ORION BRAVE will operate under the "WDM4416" call sign and actively monitor channels 13, 16, and 74 for communications. Construction is scheduled from October 21, 2024, to November 15, 2025. During this timeframe, operations will occur from 6 a.m. to 6 p.m., six days per week (Monday through Saturday). The floating equipment will remain onsite for the duration of the project. Orion respectfully advises all mariners to exercise heightened caution when navigating the construction area. We kindly request that vessels reduce speed while transiting through the Port Tampa Bay channel at Berth 218.

Hillsborough Cut D Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut D Channel Outbound Range Rear Light	23505	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bulk Liquid Cargo Dolphin 4 Obstruction Light	23530	STRUCT DEST	PA

Hollywood Beach

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE	
Hollywood Beach Daybeacon 39	47595	WATCHING PROPERLY	FD	2025-04-30	

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.07538° N / 80.11411° W Continental Heavy Civil Corp. will be conducting marine construction, dredging, barge operations and pile driving in the ICW from 1,300 feet south of the Dania Beach Cutoff Channel to Sheridan Street west of the ICW. From 26-03-37.17N/080-06-53.74W to 26-03-37.17N/080-06-53.74W. Operations are expected to commence July 3, 2023 with an estimated completion date of July 3, 2025. Operations will be conducted Monday through Saturday 6 a.m. to 7 p.m. Navigation will not be impeded. Mariners are urged to proceed with caution while operating in the vicinity of the vessels. There will be multiple vessels onscene and they will be monitoring VHF-FM channel 69. For further information contact: Jose Galicia, project manager jgalicia@chcivil.com	Lat: 26° 04' 31" Lon: -080° 06' 51"
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes		General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To: 2025-04-18 Location: 26.05735° N / 80.11538° W Continental Heavy Civil Corp. will be Installing wood piles and rip-rap stone to protect mangroves and the shoreline from erosion. Land clearing and removal of invasive trees of the islands. Work is scheduled to commence February 5, 2024, Monday to Friday from 6 a.m. to 6 p.m. with an estimated completion date of July 1, 2025. Work will be done approximately 1,300 feet South of Dania Boulevard Bridge on the West side of the ICWW limits, adjacent to the West Lake Park Islands. Northern point of work: 26-03-08.73N/80-06-56.33W Southern point of work: 26-02-55.31N/80-06-57.51W For further information contact the project manager: Jose Galicia at Jgalicia@chcivil.com.	-080° 06'
Port Everglades - Hollywood Beach/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 26.03806° N / 80.11733° W Continental Heavy Civil Corp. will be conducting dredging in the vicinity of West Lake Park Segment 4 along the FL ICW, approximately 1,600 feet South of Dania Boulevard Bridge. Dredging is anticipated to begin September 15, 2023, to July 15, 2025. There will be a 30 foot by 90 foot barge spud down and a 100 foot by 30 foot wide material barge moored on each side anchor lights will be marking the 4 corners. Four Buoys with Danger Keep out labels to be installed outlining the four corners of the mooring area. Buoy 1: 26-02-54.44N/080-07-02.33W Buoy 2: 26-02-55.15N/080-06-58.49W Buoy 3: 26-02-56.78N/080-06-59.21W Buoy 4: 26-02-56.31N/080-07-02.62W For further information contact: Jose Galicia, project manager jgalicia@chcivil.com.	Lon:

Homosassa River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Homosassa River Buoy 47A	28527	MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Homosassa River Daybeacon 2	28715	STRUCT DEST/HAZ NAV	PA

Horseshoe Beach

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Horseshoe Beach Approach Daybeacon 4	30365	STRUCT MISSING/TRUB	FD
Horseshoe Beach Approach Light 7	30375	STRUCT MISSING/TRLB	FD
Horseshoe Beach Approach Light 9	30380	STRUCT MISSING/TRLB	FD

Horseshoe Beach Channel Light 10	30385	TRLB/MISSING/STRUCT DEST/HAZ NAV	FD
Horseshoe Beach Channel Daybeacon 11	30390	STRUCT MISSING/HAZ NAV	FD
Horseshoe Beach Channel Daybeacon 12	30395	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 13	30400	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 14	30410	HAZ NAV/STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 15	30420	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Light 16A	30425	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Daybeacon 21	30445	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 23	30450	STRUCT MISSING	FD

Indian Key Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian Key Pass Light 4	15980	STRUCT DEST	FD
Indian Key Pass Daybeacon 13	16020	STRUCT DEST/TRUB	FD

Indian River North Section

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River (North Section) Light 1	41100	STRUCT DEST/TRLB	FD
Indian River (North Section) Light 7	41130	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 34	41315	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 44	41415	STRUCT DEST/TRUB	FD
ndian River (North Section) Daybeacon 49	41430	DAYMK MISSING	FD
ndian River (North Section) Daybeacon 71	42090	STRUCT DEST/TRUB	FD
ndian River (North Section) Daybeacon 79	42175	STRUCT DMGD	FD
ndian River (North Section) Daybeacon 81	42185	STRUCT DEST/TRUB	FD
Indian River (North Section) Light 83	42190	LT EXT	FD
ndian River (North Section) Daybeacon 91	42270	STRUCT DEST/TRUB	FD
ndian River (North Section) Daybeacon 94	42280	STRUCT DEST/TRUB	FD

Private Discrepancies

LLNR	STATUS	AID TYPE		
41495	MISSING	PA		
41500	MISSING	PA		
42254	DAYMK MISSING	PA		
42254.3	DAYMK MISSING	PA		
42254.4	DAYMK MISSING	PA		
42286	DAYMK DMGD	PA		
42286.200000000004	DAYMK MISSING	PA		
42286.3	DAYMK MISSING	PA		
42286.4	HAZ NAV/DAYMK MISSING	PA		
	41495 41500 42254 42254.3 42254.4 42286 42286.20000000004	41495 MISSING 41500 MISSING 42254 DAYMK MISSING 42254.3 DAYMK MISSING 42254.4 DAYMK MISSING 42286 DAYMK DMGD 42286.200000000004 DAYMK MISSING 42286.3 DAYMK MISSING		

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Banana River - Indian River North	Bridges	General/Bridges/Construction From: 2024-11-12 To: 2026-04-30 Location: 28.527349° N / 80.765526° W Bridge Name: NASA Causeway	Lat:
Section/General/Bridges/Construction		Bridges Construction continues on the new high-level bridges which is expected to be completed April 2026. The fixed navigational	28° 31' 38"
		clearances provide a vertical clearance of 66 feet at MHW and 125 feet between the new fender system. UPDATE 3/12/2025: The	Lon:
		installation of the fender system requires a partial blockage of the channel resulting in approximately 60-70 feet of horizontal clearance	-080° 45'
		available for the passage of vessels. A 2-hour advance notice will be needed to clear channel. Orion has advised that it is preferred that	56"
		any vessels requesting full navigation channel access during normal operation hours do so between the hours of 7 a.m. and 8 a.m. if	
		practical. The construction vessels on the project will monitor channels 13, 16 and Working Channel 1. Mariners are urged to use	
		extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made.	

Indian River South Section

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River (South Section) Daybeacon 10	43265	STRUCT DEST/TRUB	FD
Indian River (South Section) Light 14	43275	DAYMK MISSING	FD
Indian River (South Section) Daybeacon 17	43290	DAYMK MISSING	FD
Indian River (South Section) Daybeacon 32	43415	STRUCT DEST/TRUB	FD
Indian River (South Section) Light 53	43520	HAZ NAV/STRUCT DEST/TRLB	FD

43860	DBD DEST	FD
43920	DAYMK DMGD	FD
44150	STRUCT DEST	FD
44385	STRUCT DEST/TRUB	FD
44595	DBD DEST	FD
44830	STRUCT DMGD	FD
44830	STRUCT DEST/TRUB	FD
45115	STRUCT DEST/HAZ NAV/TRLB	FD
45195	STRUCT MISSING/TRUB	FD
45270	LT EXT/DAYMK MISSING/STRUCT DMGD/TRLB	FD
45390	STRUCT MISSING/TRUB	FD
	43920 44150 44385 44595 44830 44830 45115 45195	43920 DAYMK DMGD 44150 STRUCT DEST 44385 STRUCT DEST/TRUB 44595 DBD DEST 44830 STRUCT DMGD 44830 STRUCT DEST/TRUB 45115 STRUCT DEST/HAZ NAV/TRLB 45195 STRUCT MISSING/TRUB 45270 LT EXT/DAYMK MISSING/STRUCT DMGD/TRLB

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turkey Creek Daybeacon 22	43272.200000000004	STRUCT DEST	PA
River Run Daybeacon 5	43720	DAYMK MISSING	PA
Tidewater Island Club Channel Daybeacon 3	44390.3	STRUCT MISSING	PA
Queens Cove Daybeacon 10	44945	STRUCT DEST/HAZ NAV	PA
Rigels Cove Channel Daybeacon 7	45615	DAYMK IMCH	PA
Outrigger Harbour Daybeacon 1	45710	STRUCT DEST	PA
Ind River Plantation Marina Channel Daybeacon 2	45825	STRUCT DMGD	PA
Breakwater Danger Daybeacon A	45863	DAYMK MISSING	PA
Breakwater Danger Daybeacon B	45863.1	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Repairs, Painting, Or Fender Replacement	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-10-29 To: 2028-01-31 Location: 27.632319° N / 80.371113° W Bridge Name: 17th St Bridge Vecellio Grogan, on behalf of the bridge owner, Florida Department of Transportation, will be conducting bridge repairs on the 17th street (SR 656) Bridge over the AICW (Indian River) mile marker 952.9 at Vero Beach, FL beginning November 13, 2023, with an estimated completion during January 2028. The project will remove and replace 400 feet of the eastern portion of the bridge beginning with the north section before continuing with the south section. The contractor will utilize in water equipment which will remain on site, all vessels are advised to transit the area with caution. For further information, contact: Kyle Tatum at (407) 361- 6506. For waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil.	Lat: 27° 37' 56" Lon: -080° 22' 16"
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Conversion	Bridges	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 27.47199° N / 80.32452° W Bridge Name: A1A State Route Bridge Vecellio & Grogan, Inc. ("V&G"), on behalf of the bridge owner, FDOT, are conducting construction operations for the replacement of the A1A North Causeway Drawbridge across the AICW, mile 964.8, at Ft. Pierce, FL. A temporary work trestle (platform) has been installed on the northeast side of the existing A1A North Causeway Bridge. In water work continues directly adjacent to and across the navigable waterway with barge(s) in order to perform other associated construction activities. In April 2025, new bridge beams will be installed over the channel which will permanently limit the vertical clearance to 85 ft. at mean high water. The existing drawbridge will remain in use until sometime in late 2026. During bridge beam setting operations in April and May 2025, there will be intermittent closures of the channel for 3-4 hours at a time for safety. Vessels needing a full channel passage are required to provide the bridge tender with a 2-hour advance notice to allow for the barges to clear the channel. During the evening/overnight hours the channel will be unobstructed. All in-water equipment will be properly lighted. All mariners are requested to use caution and transit the area at a slow speed. For waterways questions or drawbridge operating issues, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	Lat: 27° 28' 19" Lon: -080° 19' 28"
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-12-06 To: 2025-05-31 Location: 27.87748° N / 80.45263° W 27.86838° N / 80.44851° W 27.86277° N / 80.46756° W 27.87566° N / 80.47151° W 27.87748° N / 80.45263° W ATL Diversified, Inc. will be dredging for a beach renourishment project. Operations are expected to begin December 23, 2024, with an estimated completion date of May 31, 2025. Dredge hours will be from dawn to dusk but dredge equipment will always be in place. All local boat traffic will need to take extreme caution. 215,000 CY of material will be hydraulically dredged from within the Sebastian Inlet. Material will be dredged and pumped by dredge pipeline out of the inlet and onto the beach. Material will be placed on the South side of the inlet for beach restoration. Piping within the inlet channel will be submerged and held by anchors, floating pipe will travel the length of the South side of inlet to the beach. Staged and stored piping, barges and work vessels will be staged on the South Side of the inlet. All boat traffic needs to take caution of floating dredge pipelines.	
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Miscellaneous	Miscellaneous	General/Miscellaneous Ft. Pierce Harbor: Waterway Analysis and Management System Review. The U.S. Coast Guard is conducting a Waterway Analysis and Management System (WAMS) review of the navigable waters in Ft. Pierce Harbor, Florida. The review focuses on the area's aids to navigation, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routing and emergency communication capabilities, and future development projects. Input regarding the waterway and aids to navigation system must be received by May 23, 2025. Input may be provided using the survey link below or directly to the point of contact listed. https://www.surveymonkey.com/r/X39BJ6S Send comments to: U.S. Coast Guard Sector Miami Attn: CWO3 R. L. Seymour Prevention Department Waterways Management 100 MacArthur Causeway Miami Beach, FL 33139 Phone: 305-535-4307 or 786-295-9051 Email: SectorMiamiWAMS@uscg.mil	

Intracoastal Waterway Florida Seventh District

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Okeechobee (Rt 2) Daybeacon 13	51445	STRUCT MISSING	FD

https://www.navcen.uscg.gov/msi 25/71

Isla De Vieques

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Isla De	Hazards To	The U.S. NAVY is advising all mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to	
Vieques/General/Hazards To	Navigation	Punta Este and on the Southeast on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it	
Navigation/Hazards		contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For	
		more information, contact Mrs. Maria Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

<u>Isla Magueyes</u>

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla De Mona Light	32295	LT EXT/STRUCT DMGD	FD

Jekyll Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jekyll Creek Jetty Warning Daybeacon 8	37305	DAYMK MISSING	FD
Jekyll Creek Light 20A	37346	STRUCT DEST/TRLB	FD
Jekyll Creek Light 29	37370	STRUCT DEST/TRLB	FD

Johns Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johns Pass Channel Daybeacon 1	25580	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Treasure Island North Terminal Groin Obstruction Light	25600.010000000002	STRUCT DEST	PA

Jug Creek Shoal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jug Creek Shoal Daybeacon 9	56375	STRUCT MISSING	FD

Jupiter Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jupiter Inlet Buoy 2	46240	OFF STATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) - Jupiter Inlet/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2024-11-15 To: 2025-09-30 Location: 26.94755° N / 80.08495° W Bridge Name: Jupiter Federal Northbound Bridge CDR Maguire Engineering, on behalf of Florida Department of Transportation (FDOT) has been contracted to replace the US1 Jupiter Federal Bridge across the Atlantic Intracoastal Waterway mile 1004.8, Jupiter. The old bascule bridge has been removed from the waterway and the new northbound bascule bridge has been constructed along the same alignment. The new navigational clearances will be 42ft of vertical clearance at the center and 125ft of horizontal clearance between the fenders when the project is complete. In-water equipment will continue to be present in the vicinity of construction of the new bridge through the end of 2024. All vessels are advised to transit the area with caution. For waterways questions or issues, call or e-mail Coast Guard Sector Miami, FL, Waterways Management Division, telephone 305-535-4317, email SectorMiamiWaterways@uscg.mil.	-080° 05'
Sector Miami, Submerged Land Act (SLA) - Jupiter Inlet/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2025-02-19 To: 2025-08-18 Location: 26,94754° N / 80.07894° W 26,94603° N / 80.07891° W 26,9452° N / 80.08029° W 26,94754° N / 80.07894° W The U.S. Coast Guard received a report of shoaling within the Intracoastal Waterway near Jupiter Lighthouse Park extending from the southeast corner toward Jupiter Inlet Buoy 2 (LLNR 46240) and extending south-southeast towards Jupiter Inlet Light 1 (LLNR 46235). Depth of water has been reported as low as 4 feet throughout the channel. The deepest water is located on the south side of the channel near Jupiter Inlet Light 1. Mariners are advised to reduce speed to bare steerageway and transit the area with extreme caution.	

Jupiter Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jupiter Sound Daybeacon 48	46180	STRUCT MISSING/TRUB	FD

Keaton Beach

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Keaton Beach Daybeacon 2	30600	HAZ NAV/STRUCT DEST/TRLB	FD
Keaton Beach Light 5	30620	STRUCT MISSING/TRLB	FD
Keaton Beach Daybeacon 6	30625	HAZ NAV/STRUCT DEST	FD
Keaton Beach Daybeacon 10	30635	STRUCT MISSING/TRLB	FD
Keaton Beach Light 11	30640	STRUCT DEST/TRLB	FD
Keaton Beach Daybeacon 13	30650	STRUCT MISSING/TRLB	FD
Keaton Beach Daybeacon 18	30675	STRUCT DEST/HAZ NAV/TRLB	FD

Key Biscayne Yacht Club

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Key Biscayne Yacht Club Light 4	49085	DAYMK MISSING	PA

Kings Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Bay Light 48	7000	STRUCT DEST/TRLB	FD
Kings Bay Light 50	7005	STRUCT DEST	FD
Kings Bay Light 52	7010	STRUCT DEST	FD
Kings Bay Light 53	7015	STRUCT DMGD	FD
Kings Bay Light 54	7020	STRUCT DEST	FD
Kings Bay Light 56	7025	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kings Bay/General/Marine	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-03-06 To: 2026-	
Construction (Excluding	Construction	04-10 Location: 30.7818° N / 81.49075° W 30.77592° N / 81.49028° W 30.77585° N / 81.49391° W 30.7815° N / 81.4947° W 30.7818°	
Bridges)/Facilities, Barriers, Manmade	(Excluding Bridges)	N / 81.49075° W UMX Crew will be starting dredging and underwater diving repairs work at MSF Facility (East River), Kings Bay Base,	
Reefs, Riprap, Jetties/Dikes		GA (30-46-45.5N / 81-29-29.5W). The crew will have a 120' x 45' Crane barge and 60' x 70' ton crane barge on-site. No wake is allowed	
		near the job location. The project is scheduled to start on March 17, 2025, and is estimated to finish on March 17, 2026.	

Kings Island Turning Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Island Turning Basin Light 16	5065	STRUCT MISSING/TRLB	FD

Kingsley Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kingsley Creek Daybeacon 13	38010	STRUCT DEST/TRUB	FD

Lake Boca Raton

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Mile Daybeacon 1	47151	STRUCT DEST	PA
Hillsboro Mile Daybeacon 3	47152	STRUCT DEST	PA
Hillsboro Mile Daybeacon 7	47153	STRUCT DEST	PA

Lake Dexter

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

St Johns River - Lake	Miscellaneous	General/Miscellaneous From: 2025-02-11 To: 2025-08-10 Location: 32.27263° N / 80.53829° W 30.4907° N / 80.25264° W 24.57149° N /	
Dexter/General/Miscellaneous		78.80245° W 23.97058° N / 83.32882° W 29.25227° N / 84.25167° W 32.24011° N / 81.43367° W 32.27263° N / 80.53829° W PUBLICATION—	
		National Oceanic and Atmospheric Administration (NOAA) – U.S. Coast Pilot 5, Gulf Coast, Puerto Rico, and Virgin Islands, 53rd Edition, 2025,	
		has been issued and is ready for free download and weekly updates at nauticalcharts.noaa.gov/publications/coast-pilot/index.html. Only Print-	
		on-Demand (POD) bound copies are available for purchase; visit nauticalcharts.noaa.gov/publications/print-agents.html#coast-pilot. The 2025	
		Edition cancels the preceding 2024 Edition, and incorporates all previous corrections.	

Lake George

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Silver Glen Springs Run Buoy 1	8595	MISSING	PA
Silver Glen Springs Run Buoy 24	8695	MISSING	PA
Silver Glen Springs Run Buoy 25	8700	OFF STA	PA
Silver Glen Springs Run Buoy 2A	8715	SINKING/BUOY DMGD	PA
Silver Glen Springs Run Buoy 9A	8740	MISSING	PA
Silver Glen Springs Run Pref Buoy A	8750	MISSING	PA

Lake Monroe

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Monroe Bar Light 1	9240	STRUCT DEST/HAZ NAV/TRLB	FD

Lake Okeechobee Route 1

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Okeechobee (Rt 1) Daybeacon 3	51195	DBD DEST	FD

Lake Worth Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth Creek Daybeacon 7	46375	STRUCT DEST/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Jupiter Inlet - Lake Worth	Bridges	General/Bridges/Temp Deviation From: 2024-11-05 To: 2025-09-01 Location: 26.93383° N / 80.08399° W Bridge Name: Indiantown Road	Lat:
Creek/General/Bridges/Temp		Eastbound and Westbound Bridges The TIR is identified by docket number USCG-2023-0652 at https://www.regulations.gov. Additional	26° 56' 02"
Deviation		information is provided in the online document, please read. The U.S. Coast Guard has issued a TIR which amends drawbridge operation	Lon:
		regulation, 33 CFR 117.261(p) which will govern Indiantown Road Bridge, mile 1006.2, at Jupiter, Florida. The TIR is effective from 12:01 a.m. on	-080° 05'
		October 25, 2024, through 11:59 p.m. on August 31, 2025. You may submit comments identified by docket number USCG-2023-0652 using	02"
		Federal Decision Making Portal at https://www.regulations.gov. The comment period ends November 25, 2024. If you have questions on this	
		rulemaking, call or e-mail Ms. Jennifer Zercher, Bridge Management Specialist, Seventh Coast Guard District, telephone (305) 415-6740, email	
		Jennifer.N.Zercher@uscg.mil	

Lake Worth Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth Inlet Lighted Buoy 4	10200	OFF STATION	FD

Lake Worth North

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth North Light 36	46600	STRUCT DEST	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lake Worth	Bridges	General/Bridges/Construction From: 2025-01-14 To: 2027-01-31 Location: 26.808528° N / 80.056123° W Bridge Name: US Hwy 1/SR 5	Lat:
North/General/Bridges/Construction		Bridge - Earman River The waterway at the bridge will be obstructed and closed to navigation from 2/10/2025 through 1/7/2027 for the	26° 48' 31"
		replacement of the US Hwy 1/SR 5 Bridge. Mariners are advised to utilize the northern canal to access the Atlantic Intracoastal Waterway.	Lon:
		The Lighthouse Drive Bridge across the northern canal provides a vertical clearance of 14.5 feet and a horizontal clearance of 22.5 feet. For	-080° 03'
		waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	22"

Lake Worth South

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth South Daybeacon 4	46740	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Daybeacon 34	46965	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Light 35	46970	DAYMK MISSING	FD
Lake Worth South Daybeacon 40	46985	TRUB/STRUCT MISSING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lake Worth Inlet - Lake Worth South/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-29 To: 2025-06-02 Location: 26.51452° N / 80.05565° W Bridge Name: East Woolbright Road Bridge - AICW The bridge shall operate as follows: - From 5 p.m. on Saturday, May 17, 2025, until 8 a.m. on Sunday, May 18, 2025, an opening will be provided with a 2-hour advanced notice to the bridge tender From 5 p.m. on Saturday, May 31, 2025, until 8 a.m. on Sunday, June 1, 2025, an opening will be provided with a 2-hour advanced notice to the bridge tender. At all other times, the bridge will operate on demand. Public vessels of the United States, vessels declaring an emergency and tugs with tows shall be passed as soon as safely possible.	Lat: 26° 30' 52" Lon: -080° 03' 20"
Lake Worth Inlet - Lake Worth South/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2025-02-10 To: 2025-05-23 Location: 26.55226° N / 80.04977° W 26.55214° N / 80.04889° W 26.54673° N / 80.04987° W 26.5454° N / 80.04245° W 26.53986° N / 80.04426° W 26.5342° N / 80.04596° W 26.52976° N / 80.04646° W 26.52623° N / 80.04689° W 26.52625° N / 80.04741° W 26.53435° N / 80.04638° W 26.54560° N / 80.04281° W 26.54539° N / 80.04575° W 26.54406° N / 80.04509° W 26.54472° N / 80.05113° W 26.54562° N / 80.04575° W 26.54683° N / 80.05253° W 26.54683° N / 80.05133° W 26.54526° N / 80.04977° W Atlantic and Gulf Dredging and Marine, LLC (AGD) will be dredging and placing beach fill for the South Lake Worth Inlet maintenance dredging project. DREDGE COMMODORE, DREDGE COMMANDER, TUG LIEUTENANT, TUG KYLE C, SURVEY/CREW VESSEL BAYOU BUFF, SURVEY/CREW VESSEL LIL JOHN, SURVEY/CREW VESSEL MR. SHOAL and various barges will begin dredging on or about March 25, 2025, after four weeks of waterside mobilization that will commence on March 1, 2025. Full waterside demobilization is scheduled to complete by May 15, 2025. AGD will establish a waterside staging area to secure the submerged pipeline barge within the permitted Sand Trap limits, on the southern edge of the dig template. Rafted pipeline and equipment will be staged in this location during the mobilization and demobilization phases of the work. AGD will also secure a heavy lift barge into the waters adjacent to the Ocean Inlet Park western shore for mobilization/demobilization of equipment and pipeline onto shore. The Cutter Suction Dredge Commodore is scheduled to commence dredging/beach fill operations on. Dredging operations will commence on or about March 25, 2025 in the ICW P-50 Cut borrow area located west of South Lake Worth Inlet to remove material and hydraulically place the material via submerged/floating/shoreline along Ocean Ridge Hammock Park, south of the inlet between Florida Department of Environmental Protection (FDEP) reference monuments R-154 and R-158. Operations in the ICW P-50 Cut	

Largo Sound Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Newport Bay Daybeacon 7	11851.6	HAZ NAV/STRUCT DMGD	PA

Lemon Bay Channel

Federal Discrepancies

·				
NAME	LLNR	STATUS	AID TYPE	
Lemon Bay Channel Daybeacon 16	57275.5	STRUCT MISSING/TRUB	FD	
Lemon Bay Channel Light 24	57360	STRUCT MISSING	FD	
Lemon Bay Channel Daybeacon 26	57420	STRUCT MISSING/TRUB	FD	
Lemon Bay Channel Daybeacon 40	57625	STRUCT MISSING/TRUB	FD	
Lemon Bay Channel Light 47	57655	STRUCT DEST/HAZ NAV/TRLB	FD	

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gottfried Creek Daybeacon 5	57357.4	DAYMK DMGD	PA
Forked Creek Daybeacon 1	57617	STRUCT DEST/HAZ NAV	PA
Forked Creek West Obstruction Daybeacon	57618.9	STRUCT DEST	PA
Forked Creek North Obstruction Daybeacon	57619	STRUCT DEST	PA
Forked Creek East Obstruction Daybeacon	57619.3	STRUCT DEST	PA

Little Lake George

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Lake George Light 53	8435	LT EXT	FD

https://www.navcen.uscg.gov/msi 29/71

Little Lake George Daybeacon 54 8450 STRUCT DEST/TRLB FD

Little Manatee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Manatee River Approach Light LM	24481	STRUCT MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Shell Point Daybeacon 3	22698.2	STRUCT DEST	PA	
Shell Point Daybeacon 7	22698.600000000002	STRUCT DEST	PA	

Little Mud River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Mud River Daybeacon 189	36855	STRUCT DEST/TRUB	FD
Little Mud River Light 190	36865	STRUCT DEST/TRLB	FD
Little Mud River Light 196	36880	STRUCT DEST/TRLB	FD

Little River Winyah Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little River-Winyah Bay Obstruction Daybeacon B	33647	STRUCT MISSING/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Winyah Bay Channel - Little River Winyah Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-10 To: 2025-11-01 Location: 33.851704° N / 78.656302° W Bridge Name: Little River Bridge - AICW Effective from 12:01 a.m. on May 5, 2025, through 11:59 p.m. on October 31, 2025, the Little River Bridge shall open on signal except that from 7 a.m. to 9 a.m. and 4 p.m. to 6 p.m., Monday through Friday, except Federal holidays, the draw will open on the hour and half hour. Public vessels of the United States and tugs with tows, upon proper signal, will be passed through anytime. A notice of temporary deviation from regulations, request for comments will be published in the Federal Register. Comments may be submitted under docket number USCG-2025-0152 using Federal Decision-Making Portal at https://www.regulations.gov.	
Winyah Bay Channel - Little River Winyah Bay/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2025-07-28 Location: 33.7849° N / 78.7861° W 33.78451° N / 78.78545° W 33.77003° N / 78.80923° W 33.77049° N / 78.80979° W 33.7849° N / 78.7861° W Obstacle was reported about 1.5 miles north of mile 357 on the west bank of the waterway. There are 2 large trees that were knocked over from the bank and the trees are in the channel.	
Winyah Bay Channel - Little River Winyah Bay/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-03-13 To: 2025-05-20 Location: 33.82754° N / 78.70574° W The U.S. Coast Guard is proposing to make the following change in the Little River-Winyah Bay Channel, Intracoastal Waterway, to improve navigational safety and reliability. Little River-Winyah Bay Buoy 15B (LLNR 33660.1) will be permanently established in approximate position 33-49-39.137N, 078-42-20.648W. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or Andrew.m.engle@uscg.mil with Little River-Winyah Bay Buoy 15B as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by May 12, 2025.	Lat: 33° 49' 39" Lon: -078° 42' 21"

Little Shark River Entrance

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE		
Cormorant Pass Daybeacon 48	15870	DAYMK IMCH	PA		
Oyster Bay Daybeacon 53	15885	DAYMK MISSING	PA		
Oyster Bay Daybeacon 63	15915	DAYMK MISSING	PA		
Little Shark River Daybeacon 69	15940	DAYMK IMCH	PA		

Long Branch

Temporary Changes

. , ,			
NAME	LLNR	STATUS	AID TYPE
Long Branch Lighted Buoy 69	7575	RELOCATED FOR DREDGING	FD
Long Branch Lighted Buoy 71	7590	RELOCATED FOR DREDGING	FD

Long Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Long Key Daybeacon 1X	12385	STRUCT DEST/TRUB	FD

Long Key Cape Sable

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sprigger Bank Light 5	15605	HAZ NAV/STRUCT DEST/TRLB	FD

Lower Flats Range

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elba Island Light 39	4850	STRUCT DEST	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Lower Flats Range Front Light	4830	RELIGHTED	FD	2025-05-08

Loxahatchee River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Loxahatchee River Daybeacon 7	46280	DAYMK IMCH	PA
Loxahatchee River Daybeacon 15	46320	DAYMK IMCH	PA
Loxahatchee River South Channel Daybeacon 7	46373.5	STRUCT DMGD	PA

Mackay River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mackay River Cutoff Light 229	37090	STRUCT DEST/TRLB	FD
Mackay River Cutoff Light 231	37095	STRUCT DEST/TRLB	FD
Mackay River Light 239	37160	STRUCT DEST/HAZ NAV/TRLB	FD
Mackay River Light 241	37170	STRUCT DEST/TRLB	FD
Mackay River Light 244	37190	STRUCT DEST/TRLB	FD

Manatee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee River Daybeacon 21	22050	STRUCT MISSING	FD
Manatee River Daybeacon 28	22095	STRUCT DEST/TRUB	FD

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Tidewater Preserve Marina Daybeacon 2	22105.2	STRUCT DEST	PA
Colony Cove Daybeacon 2	22110	STRUCT DEST/TRUB	PA

Matanzas Pass Channel

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Matanzas Pass Channel Daybeacon 24	18290	STRUCT MISSING/TRUB	FD
Matanzas Pass Channel Daybeacon 26	18295	HAZ NAV/STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas Harbor Channel Daybeacon 3	18296.10000000002	STRUCT DEST/HAZ NAV	PA
North Estero Bay Daybeacon 63	18725	STRUCT DEST/TRUB	PA
Mullock Creek Daybeacon 13	18835	STRUCT DEST/HAZ NAV	PA
Hurricane Bay Marina West Channel Daybeacon 7	18160	STRUCT DEST/HAZ NAV	PA
Siesta Isles Daybeacon 4	18215	STRUCT DEST	PA
Matanzas Harbor Channel Daybeacon 5	18296.3	STRUCT DEST	PA
North Estero Bay Daybeacon 4	18315	STRUCT DEST	PA
North Estero Bay Daybeacon 5	18316	STRUCT MISSING	PA
Bayside Estates Channel Daybeacon 2	18405	STRUCT DEST	PA

Bayside Estates Channel Daybeacon 4	18415	HAZ NAV/STRUCT DEST	PA
Bayside Estates Channel Daybeacon 14	18450	STRUCT DEST	PA
North Estero Bay Daybeacon 19	18565	STRUCT DMGD	PA
North Estero Bay Daybeacon 35	18605	STRUCT DEST	PA
Mullock Creek Daybeacon 2A	18760	STRUCT DEST	PA
Mullock Creek Daybeacon 45	18920	STRUCT DEST	PA

Matanzas River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas River Light 1	39035	STRUCT DEST/TRLB	FD
Matanzas River Buoy 2	39040	OFF STA	FD
Matanzas River Daybeacon 5	39055	STRUCT MISSING	FD
Matanzas River Daybeacon 6A	39060.1	STRUCT DEST/TRUB	FD
Matanzas River Light 43	39330	STRUCT DEST	FD
Matanzas River Light 79	39520	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Salt Run Daybeacon 1	38915	STRUCT DEST	PA
Salt Run Daybeacon 3	38925	STRUCT DEST	PA
Salt Run Daybeacon 4	38930	STRUCT DEST	PA
Salt Run Daybeacon 6	38940	STRUCT MISSING	PA
Salt Run Daybeacon 7	38945	STRUCT DMGD	PA
Salt Run Daybeacon 11	38965	STRUCT DEST/HAZ NAV	PA
Fish Island Marina Daybeacon 1	39080	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Augustine Inlet -	Advanced Notice	ATON/Advanced Notice of Change From: 2024-11-18 To: 2025-05-17 Location: 29.90535° N / 81.29553° W Aid Name: Matanzas River Light 1	Lat:
Matanzas	of Change	LLNR: 39035 Action: CHANGE Action Type Change Aid Subtype The following change has been approved to the Aid to Navigation system in the	29° 54' 19"
River/ATON/Advanced		Matanzas River. Matanzas River Light 1 (LLNR 39035) will permanently be changed to Matanzas River Lighted Buoy 1 (LLNR 39035). Matanzas	Lon:
Notice of Change		River Light 1 has been destroyed on a few occasions over the last 10 years and it is currently being advertised as destroyed since 2020. In addition,	-081° 17'
		the water depth at its assigned position is 21 feet making it more difficult for a CG asset to spud and maintain position to rebuild the aid safely.	44"
		Converting the light to a floating aid will allow for a timelier response and consistent maintenance in the event the aid becomes discrepant.	
		Therefore, this change will provide mariners a more reliable signal while approaching the Matanzas River Channel entrance from the St. Augustine	
		Inlet and while exiting the channel.	

Matheny Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Venice Inlet-Siesta Key Daybeacon 49	58225	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snake Island Daybeacon A	57834	STRUCT DEST	PA
Snake Island Daybeacon B	57834.1	STRUCT DEST	PA
Snake Island Daybeacon C	57834.200000000004	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 4	58185	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 5	58190	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 7	58200	STRUCT DEST	PA
Midnight Pass Daybeacon 13	58205.3	STRUCT DMGD	PA
Midnight Pass Daybeacon 17	58205.5	STRUCT DEST	PA
Matheny Creek Daybeacon 1	58292	STRUCT DMGD	PA
Phillippi Creek Daybeacon 2	58365.200000000004	DAYMK MISSING	PA
Phillippi Creek Daybeacon 7	58365.6	DAYMK MISSING	PA
Phillippi Creek Daybeacon 11	58365.9	STRUCT DEST/HAZ NAV	PA
Phillippi Creek Daybeacon 13	58366	STRUCT DEST	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Venice Inlet - Matheny Creek/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-03-19 To: 2025-07-05 Location: 27.30273° N / 82.54467° W Bridge Name: Siesta Key Bridge - GICW The bridge need not open to navigation including tugs with tows, from 9:00 p.m. to 11:59 p.m. on Friday, July 4, 2025, to facilitate the Siesta Key 4th of July Community Fireworks.	Lat: 27° 18' 10" Lon: -082° 32' 41"
Venice Inlet - Matheny Creek/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-03-19 To: 2025-07-05 Location: 27.25448° N / 82.53152° W Bridge Name: Stickney Point Bridge - GICW The bridge need not open to navigation including tugs with tows, from 9:00 p.m. to 11:59 p.m. on Friday, July 4, 2025, to facilitate the Siesta Key 4th of July Community Fireworks.	Lat: 27° 15' 16" Lon: -082° 31' 53"
Venice Inlet - Matheny Creek/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 17465 Continental Heavy Civil Corp. will conduct shoreline reconstruction and coastal armoring. Work will be performed between 22 North Casey Key Road to 400 N Casey Key Road, and 526 to 840 N Casey Key Road. Staging and loading area will be the entire footprint of the Nokomis Beach "spillover" parking lot, located at 101 S Casey Key Road. Heavy equipment such as lattice-boom crawler cranes and heavy excavators will load onto barges from Albee Road and will route down to intercoastal to the Venice inlet, proceed to the Gulf and then up the coast to the jobsite and back. Continental Heavy Civil expects to work a regular schedule from 6am to 6pm Monday through Saturday, with some necessary Sundays. Estimated completion time for the entire project May 1st, 2027. All Vessels should use caution when transiting the work area. The crew at Casey Road will monitor VHF-FM channels 13 and 16.	

Mayport Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mayport Basin Range Front Light	7155	NIGHT LT BURNING DAY	FD
Mayport Basin Range Rear Light	7160	NIGHT LT BURNING DAY	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Mayport Basin Channel Lighted Buoy 1	7170	RELOCATED FOR DREDGING	FD

Miami Beach Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Channel Light 11	48015	STRUCT DEST/TRLB	FD

Miami Main Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Main Channel Lighted Buoy 10	10525	OFF STATION	FD
Miami Main Channel Lighted Buoy 12	10535	BUOY DMGD	FD

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Miami Beach Marina Breakwater North Light	10570	LT EXT	PA

Mile Point

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE		
Mile Point Lower Range Front Light	7260	REDUCED INT	FD		
Mile Point Light A	7281	DAYMK MISSING	FD		
Mile Point Light C	7283	STRUCT DEST	FD		
Mile Point Upper Range Front Light	7287	REDUCED INT	FD		
Mile Point Upper Range Rear Light	7290	LT EXT	FD		

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Mile Point/ATON/Advanced Notice of Change	Advanced Notice of Change	Mile Point Lower RFL (LLNR 7260) will be relocated to approximate position: 30-22-44.551N/081-27-11.480W to align with the newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 27' 11
St Johns River - Mile Point/ATON/Advanced Notice of Change	Advanced Notice of Change	newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 42" Lon: -081° 27' 14

St Johns River - Mile Point/ATON/Advanced Notice of Change	Change	Mile Point Upper RFL (LLNR 7287) will be relocated to approximate position: 30-22-44.266N/081-27-12.139W to align with the newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 27' 11"
St Johns River - Mile Point/ATON/Advanced Notice of Change		Mile Point Upper RRL (LLNR 7290) will be relocated to approximate position: 30-22-34.772N/081-26-58.725W to align with the newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 35" Lon: -081° 26' 58"

Mosquito Lagoon

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mosquito Lagoon Daybeacon 8	40925	STRUCT DEST/TRUB	FD

Mount Pleasant Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mount Pleasant Channel Daybeacon 3	3520	STRUCT MISSING/TRUB	FD

Mullet Key Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Mullet Key Channel Lighted Buoy 26	22395	WATCHING PROPERLY	FD	2025-05-06

Murphy Island

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Murphy Island Light 26	8305	DAYMK MISSING	FD

Myakka River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Gulf Cove Entrance Daybeacon 5	20175	DAYMK MISSING	PA
Upper Myakka River Daybeacon 12	20395	HAZ NAV/STRUCT DEST	PA

Naples Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Naples Bay Channel Daybeacon 22	17550	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Naples Yacht Club Daybeacon 5	17667	DAYMK MISSING	PA

Nassau Cutoff

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Nassau Cutoff Light 47	38175	STRUCT MISSING/TRLB	FD

New Channel Range

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
New Channel Range Front Light	4770	LT EXT	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Long Island Crossing - New Channel	Advanced Notice of	After completion of dredging and channel re-alignment, the water depth at the current assigned position for New Channel RFL	Lat:
Range/ATON/Advanced Notice of	Change	(LLNR 4770), makes it impossible for the Coast Guard to rebuild this range in its advertised position. Therefore, New Channel RFL	32° 02' 22"
Change		(LLNR 4770) will be permanently relocated to a new assigned position at approximately 32-02-21.801N/080-55-39.437W.	Lon:
			-080° 55'
			39"

New Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
New Pass Channel Light 13	21705	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anglers Club Reef Daybeacon AC	21701	STRUCT DEST	PA
City Island Breakwater Light	21710	STRUCT DEST	PA
Sarasota Basin Obstruction Light A	21752	STRUCT DEST	PA
Sarasota Basin Obstruction Daybeacon B	21754	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
New Pass/ATON/ATON	ATON Changes	ATON/ATON Changes From: 2025-05-12 To: 2025-11-08 Location: 27.33991° N / 82.56995° W Aid Name: New Pass Channel Daybeacon 15 LLNR:	Lat:
Changes		21715 Action: RELOCATE New position: 27-20-23.573N/08234-11.765W	27° 20' 24"
			Lon:
			-082° 34' 12"

New River Sound

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Stranahan River - New River	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-11-19 To: 2025-05-31 Location: 26.08395° N / 80.1844° W Bridge	Lat:
Sound/General/Bridges/Repairs,		Name: Interstate 595 Bridge - South New River Canal Freck Enterprises, Inc has commenced repair and re-installation of the existing bridge	26° 05' 02"
Painting, Or Fender Replacement		fenders, pilings, and beams on both the East and West fixed bridges. The contractor is utilizing a spud barge, skiff, and work boat, which are	Lon:
		expected to obstruct the navigable channel partially or completely from 7:00 am through 5:00 pm Monday – Friday and is requesting a 2-	-080° 11'
		hour notice to remove the equipment and clear the channel during this period. The equipment is planned to be removed from the location	04"
		at the end of each workday. To request a clear channel please contact Paul Freck at (321) 323-6006 or Joanne Freck at (321) 243-0000 with a	
		2-hour advance notice of arrival. Vessels on site on will monitor VHF FM 16. This portion of the project is expected to continue until an	
		estimated completion date of October 31, 2024. Upon completion of the fender system re-installation, Archer Western has additional work	
		to complete that will affect the navigable channel. This will be to install the bridge maintenance platforms on the pier caps facing the	
		channel. This work is expected to commence following the fender system re-installation and will run through May 2025. During this time the	
		Contractor will be partially obstructing the channel with work barges and will request a 1-hour advance notice of arrival. Boaters should	
		contact Cloyce Poling (561) 718-2129 to request passage. For waterways questions, call or e-mail Coast Guard Sector Miami, FL, Waterways	
		Management Division, telephone 305-535-4317, email SectorMiamiWaterways@uscg.mil.	

New Smyrna Beach

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
New Smyrna Beach Daybeacon 28	40645	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 51	40805	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 62	40845	STRUCT DEST/TRUB	FD

North Edisto River

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
North Edisto River Entrance Lighted Buoy 6	3865	LT EXT	FD
North Edisto River Inner Buoy 7	3880	MISSING	FD

North Newport River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Timmons Reef E Obstruction Daybeacon	36500	STRUCT DEST	PA

Ogeechee River

Federal Discrepancies

https://www.navcen.uscg.gov/msi 35/71

NAME	LLNR	STATUS	AID TYPE
Hell Gate Light 91	36285	STRUCT MISSING/TRLB	FD
Hell Gate Light 92	36290	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Mcallister Fishing Pier Light	36360	LT EXT	PA

Oglethorpe Range

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fig Island Jetty Light 56	5005	STRUCT MISSING/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Fort Jackson - Oglethorpe	Marine Construction	General/Marine Construction (Excluding Bridges)/Dredging 18245 Marinex Construction, Inc. will begin mobilizing equipment and	
Range/General/Marine Construction	(Excluding Bridges)	pipeline to commence work at Ocean Terminal. All pipeline for this work will be appropriately lighted and laid outside the channel on	
(Excluding Bridges)/Dredging		the South Carolina side of the river from the Talmadge Bridge to Back River. The Dredge WADMALAW will operate in this area	
		through approximately August 31, 2025. Operations will be conducted 24 hours a day / seven days a week and monitor VHF-FM channels 13 and 16.	

Okeechobee Waterway

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Daybeacon 6	51915	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dyess Canal Safewater Light DC	51980	STRUCT DEST	PA

Old Rhodes Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Old Rhodes Key Light 22	11165	DBD DEST	FD
Old Rhodes Key Daybeacon 24	11175	STRUCT DEST/TRLB	FD

Ossabaw Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ossabaw Sound Preferred Channel Buoy N	5740	MISSING	FD
Ossabaw Sound North Channel Daybeacon 10	5760	STRUCT DEST/TRUB	FD
Ossabaw Sound North Channel Buoy 11	5765	OFF STATION	FD
Ossabaw Sound North Channel Daybeacon 12	5770	STRUCT DEST/TRUB	FD
Ossabaw Sound South Channel Daybeacon 5	5780	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Delegal Creek Channel Light 1	36229	STRUCT DEST	PA
Delegal Creek Channel Buoy 2	36230	MISSING	PA
Delegal Creek Channel Buoy 4	36233	OFF STA	PA
Delegal Creek Channel Light 8	36241.1	LT EXT	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Sector Charleston, Submerged Land	Advanced Notice	ATON/Advanced Notice of Change From: 2025-03-12 To: 2026-09-08 Location: 31.86196° N / 81.03488° W Aid Name: Ossabaw Sound	Lat:
Act (SLA) - Ossabaw	of Change	North Channel Daybeacon 10 LLNR: 5760 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the	31° 51' 43'
Sound/ATON/Advanced Notice of		following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be	Lon:
Change		changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be	-081° 02'
		changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be	06"
	changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.		

Sector Charleston, Submerged Land	Advanced Notice	ATON/Advanced Notice of Change From: 2025-03-12 To: 2026-09-08 Location: 31.8645° N / 81.05731° W Aid Name: Ossabaw Sound	Lat:
Act (SLA) - Ossabaw	of Change	North Channel Daybeacon 12 LLNR: 5770 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the	31° 51' 52"
Sound/ATON/Advanced Notice of		following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be	Lon:
Change		changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be	-081° 03'
		changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be	26"
		changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.	
Sector Charleston, Submerged Land	Advanced Notice	ATON/Advanced Notice of Change From: 2025-03-12 To: 2026-09-08 Location: 31.82121° N / 81.03359° W Aid Name: Ossabaw Sound	Lat:
Act (SLA) - Ossabaw	of Change	South Channel Daybeacon 5 LLNR: 5780 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the	31° 49' 16"
Sound/ATON/Advanced Notice of		following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be	Lon:
Change		changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be	-081° 02'
		changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be	01"
		changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.	

Pablo Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pablo Creek Buoy 4	38355	MISSING	FD
Pablo Creek Light 17	38440	STRUCT MISSING/TRLB	FD
Pablo Creek Daybeacon 28	38480	DAYMK MISSING	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Pablo Creek Temporary Light 9	38380.200000000004	ESTABLISHED	FD

Palma Sola Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Palma Sola Park Channel Daybeacon 1	59890	HAZ NAV/DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 4	59905	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 5	59910	HAZ NAV/DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 6	59915	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 7	59920	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 8	59925	DAYMK IMCH	PA

Paradise Bay Estates Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Siesta Key-Tampa Bay Daybeacon 7	58480	STRUCT MISSING	FD
Sarasota Municipal Pier Channel Daybeacon 2	58495	STRUCT MISSING/TRUB	FD
Siesta Key-Tampa Bay Light 10	58535	STRUCT MISSING	FD
Siesta Key-Tampa Bay Daybeacon 16	58675	DAYMK MISSING	FD
Siesta Key-Tampa Bay Daybeacon 36	59325	HAZ NAV/STRUCT DEST/TRLB	FD
Siesta Key-Tampa Bay Daybeacon 40	59350	STRUCT MISSING/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Evans Artificial Reef Daybeacon	58480.5	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 3A	59641	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 6	59646	STRUCT DEST/HAZ NAV	PA
Holiday Inn Marina Daybeacon 3	22047.3	STRUCT DEST	PA
Holiday Inn Marina Daybeacon 6	22047.7	STRUCT DEST	PA
Bay Isles Perimeter Channel Daybeacon 2	58667	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 9	58667.25	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 15	58667.450000000004	STRUCT DEST	PA
Bay Isles Perimeter Channel Daybeacon 24	58667.75	DAYMK MISSING	PA
Coral Shores Channel Daybeacon 3	59375	STRUCT DEST	PA
Coral Shores Channel Daybeacon 9	59405	STRUCT DEST	PA
Coral Shores Channel Daybeacon 12	59420	DAYMK MISSING	PA
Coral Shores Channel Daybeacon 30	59510	STRUCT DEST	PA
Mt Vernon & Coral Shores Daybeacon 1N	59535	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 2	59636	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 3	59640	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 4	59642	STRUCT DEST	PA

Palma Sola Bay Channel Daybeacon 5	59645	STRUCT DEST	PA
Palma Sola Bay Channel Junction A	59647	STRUCT DEST	PA
Cove Sound Moorings Daybeacon 1	59650	OFF STA/HAZ NAV/DAYMK MISSING	PA
Cove Sound Moorings Daybeacon 2	59655	OFF STA/HAZ NAV/DAYMK MISSING	PA
Cove Sound Moorings Channel Daybeacon 3	59657	DAYMK MISSING	PA
Perico Bayou Channel Daybeacon 9	59720	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 2	59760	DAYMK MISSING	PA
San Remo Shore Channel Daybeacon 8	59785	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 13	59800	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 9	59815	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 10	59820	STRUCT DMGD	PA
alma Sola Bay Channel Daybeacon 11	59825	STRUCT DEST/HAZ NAV	PA
alma Sola Bay Channel Daybeacon 12	59830	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 15	59845	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 18	59860	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 19	59865	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 21	59870.5	DAYMK MISSING/STRUCT DMGD	PA
Bradenton Beach City Channel Daybeacon 1	59935	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 2	59940	STRUCT DEST	PA
Bradenton Beach City Channel Daybeacon 3	59945	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 5	59955	STRUCT DEST	PA
Bradenton Beach City Channel Junction Daybeacon A	59980	STRUCT DEST	PA
Anna Maria Channel Daybeacon 1	60190	STRUCT DMGD	PA
Anna Maria Channel Daybeacon 2	60195	DAYMK MISSING	PA
Anna Maria Channel Daybeacon 9	60230	STRUCT DEST/HAZ NAV	PA
Anna Maria Channel Daybeacon 11	60240	STRUCT DEST	PA

Pass-A-Grille

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pass-A-Grille Channel Daybeacon 2	25465	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dent Channel Daybeacon 2	25510.100000000002	STRUCT DEST	PA
Dent'S Channel Daybeacon 5	25520	STRUCT DEST	PA

Peace River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Peace River Light 4	20675	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Park Channel Daybeacon 4	20455	STRUCT DEST	PA
Ponce De Leon Park Channel Light 9	20470	LT EXT	PA
Ponce de Leon Park Channel Daybeacon 18	20474.5	STRUCT DEST	PA
Elkcam Waterway Light 1	20905	LT EXT	PA
Manchester Waterway Daybeacon 14	20981.5	STRUCT DEST	PA
Manchester Waterway Daybeacon 17	20981.9	STRUCT DEST	PA
Manchester Waterway Daybeacon 24	20982.8	STRUCT DEST	PA
Countryman Waterway Channel Daybeacon 3	20990	DAYMK MISSING	PA
Countryman Waterway Channel Daybeacon 6	20997	STRUCT DEST	PA
Countryman Waterway Channel Daybeacon 8	21003	STRUCT MISSING	PA
Sunrise Waterway Daybeacon 2	21020	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 21	21056.8	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 23	21056.9	STRUCT DMGD	PA
Spring Lake Waterway Daybeacon 27	21057.2	STRUCT DEST	PA
Peace River (North Section) Daybeacon 7	21210	OFF STA	PA
Peace River (North Section) Daybeacon 9	21215	OFF STA	PA
Peace River (North Section) Daybeacon 10	21220	STRUCT DEST	PA
Peace River (North Section) Daybeacon 11	21225	OFF STA	PA

https://www.navcen.uscg.gov/msi

Peace River (North Section) Daybeacon 14 21235 STRUCT DEST PA

Pine Island Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pine Island Sound Daybeacon 5	54825	STRUCT MISSING/TRUB	FD
Pine Island Sound Light 20	55425	STRUCT DEST/HAZ NAV/TRLB	FD
Pine Island Sound Daybeacon 28	55565	STRUCT MISSING	FD
Pine Island Sound Daybeacon 34	55590	STRUCT MISSING	FD
Pine Island Sound Light 45A	55900	DAYMK MISSING	FD
Pine Island Sound Daybeacon 50	55985	STRUCT MISSING	FD
Pine Island Sound Daybeacon 53	56000	STRUCT MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matlacha Pass Daybeacon 53	55130	STRUCT DEST	PA
Matlacha Pass Daybeacon 79	55225	DAYMK MISSING	PA
Matlacha Pass Daybeacon 81	55230	DAYMK MISSING	PA
Matlacha Pass Daybeacon 83	55235	DAYMK MISSING	PA
Matlacha Pass Daybeacon 85	55240	DAYMK MISSING	PA
Matlacha Pass Daybeacon 87	55245	DAYMK MISSING	PA
Matlacha Pass Daybeacon 89	55250	DAYMK MISSING	PA
Matlacha Pass Daybeacon 91	55255	DAYMK MISSING	PA
Matlacha Pass Daybeacon 92	55260	DAYMK MISSING	PA
Matlacha Pass Daybeacon 93	55265	DAYMK MISSING	PA
Paradise Canal Daybeacon 1	55310	DAYMK MISSING	PA
Paradise Canal Daybeacon 2	55315	DAYMK MISSING	PA
Paradise Canal Daybeacon 3	55320	STRUCT DEST	PA
Paradise Canal Daybeacon 5	55330	STRUCT DEST	PA
Long Cutoff Daybeacon 2	55370	STRUCT DEST/HAZ NAV	PA
Safety Harbor Channel Daybeacon 1	55915	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 3	55923	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 5	55925	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 4	55930	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 7	55933	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 9	55935	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 11	55940	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 12	55950	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 17	55960	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 19	55965	DAYMK MISSING	PA

Pithlachascotee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pithlachascotee River Daybeacon 23	26615	STRUCT DEST	FD

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Pithlachascottee River Daybeacon 43	26765	STRUCT DEST	PA
Pithlachascottee River Daybeacon 48	26780	STRUCT DEST/HAZ NAV	PA
Pithlachascottee River Daybeacon 51	26790	STRUCT DEST	PA
Pithlachascottee River Daybeacon 56	26805	STRUCT DEST	PA

Point Pinellas Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Point Pinellas Channel Light 2	24705	STRUCT DEST	FD
Point Pinellas Channel Light 6	24725	STRUCT MISSING	FD
Point Pinellas Channel Light 7	24735	STRUCT MISSING/TRLB	FD
Point Pinellas Channel Light 9	24735.100000000002	STRUCT MISSING	FD
Point Pinellas Channel Light 10	24735.2	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Bayou Approachroach Daybeacon 3	24765	DAYMK MISSING	PA
Little Bayou Approachroach Daybeacon 7	24775	STRUCT MISSING	PA
Little Bayou Approachroach Daybeacon 9	24780	STRUCT DEST	PA
Coquina Key Cut Daybeacon 3	24835	STRUCT DEST/HAZ NAV	PA

Ponce De Leon Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Cut Daybeacon 18	40610	STRUCT DEST/TRUB	FD

Ponce De Leon Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Inlet North Jetty Light	9520	STRUCT DEST	FD
Ponce De Leon Inlet Buoy 8A	9546	MISSING	FD
Ponce De Leon Inlet Light 12	9570	STRUCT DEST/TRLB	FD

Port Everglades

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Everglades Spoil Bank East Daybeacon	805	DAYMK MISSING	FD
Port Everglades South Regulatory Light	10349	STRUCT DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Miami, Submerged Land Act (SLA) -	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To:	Lat:
Port Everglades/General/Marine	Construction	2025-04-18 Location: 26.0961° N / 80.12005° W Orion Marine Construction, Inc. will be starting construction of the above	26° 05' 46"
Construction (Excluding Bridges)/Facilities,	(Excluding	referenced project from the water side using two crane loaded deck barges (999 crane on KS6019 barge and 1250 crane on	Lon:
Barriers, Manmade Reefs, Riprap,	Bridges)	KS6012 barge) along with four material barges (TBD1 through TBD4); all being serviced by a full-time push boat (TBD5). Orion will	-080° 07'
Jetties/Dikes		be on-site on July 15, 2024, and will start working on all activities related to the replacement of approximately 2300 feet of	12"
		bulkhead. Hours of operation will be from 7 a.m. to 7 p.m. The estimated completion date is July 1, 2026. All the barges are	
		intended to be spudded around the Port Everglades Berths 1-3 and 1A-1D area (26-05-53.68N / 080-07-12.11W) while working on	
		replacing the bulkhead in those locations. Vessels will be monitoring VHF-FM channel 11.	

Port Manatee Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Manatee Channel Outbound Range Rear Light	22558	STRUCT DEST/TRLB	FD
Port Manatee Channel Outbound Range Rear Passing Light	22559	STRUCT DEST	FD

Port Royal Sound

Private Discrepancies

·				
NAME	LLNR	STATUS	AID TYPE	
Mackay Creek Light 1	4170	LT IMCH/STRUCT DMGD	PA	

Port Sutton Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Sutton Channel Range Rear Light	23580	LT IMCH	FD

Ppg Industries

NAME	LLNR	STATUS	AID TYPE
Ppg Industries Lighted Buoy 1	32150	MISSING	PA
Ppg Industries Lighted Buoy 2	32155	MISSING	PA
PPG Industries Lighted Buoy 3	32160	OFF STA	PA

Puerto Del Rey Marina

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bajos Chinchorro Del Sur Light	31380	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Puerto Del Rey	Hazards To	The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros.	
Marina/General/Hazards To	Navigation	Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast	
Navigation/Hazards		Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Puerto Nuevo Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla Grande Pier 16 Southeast Light	30920	LT EXT	PA

Punta Gorda

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Punta Gorda East Jetty Light	31180	STRUCT DEST	PA
Punta Gorda West Jetty Light	31185	STRUCT DEST	PA
Punta Gorda East Seawall Light	31190	STRUCT DEST	PA
Punta Gorda West Seawall Light	31195	STRUCT DEST	PA

Radas Roosevelt Passage

Additional MSI Categories

	_		
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Radas Roosevelt	Hazards To	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2027-07-28 Location: 18.17261° N / 65.39295° W 18.15467° N / 65.30472° W	
Passage/General/Hazards To	Navigation	18.15924° N / 65.28892° W 18.13738° N / 65.25219° W 18.13445° N / 65.26798° W 18.14815° N / 65.28824° W 18.14162° N / 65.30128° W	
Navigation/Hazards		18.16218° N / 65.39432° W 18.15533° N / 65.44273° W 18.16283° N / 65.44548° W 18.17261° N / 65.39295° W The U.S. NAVY is advising all	
		mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to Punta Este and on the Southeast	
		on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance.	
		The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria	
		Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Redfish Pass

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redfish Pass Lighted Buoy 1	1255	BUOY DMGD	PA
Redfish Pass Buoy 2	1257	BUOY DMGD	PA
Redfish Pass Buoy 4	1260	BUOY DMGD	PA

Redhook Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redhook Bay Buoy 2	32425	OFF STA	PA

Riverside

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Riverside Daybeacon 43	8980	STRUCT DEST/TRUB	FD

Roberts Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Roberts Bay Channel Light 13	57760	DAYMK MISSING	FD

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Higel Park North Channel Buoy 1	57776	MISSING	PA
Dona Bay Channel Daybeacon 6	21455.600000000002	STRUCT DEST	PA
Dona Bay Channel Daybeacon 9	21455.9	STRUCT DEST	PA
Dona Bay Channel Daybeacon 10	21456	STRUCT DEST/HAZ NAV	PA
Higel Park North Channel Buoy 3	57777	MISSING	PA

Rockdedundy River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rockdedundy River Daybeacon 188	36850	TRUB/STRUCT MISSING	FD

Rocky Reef

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Reef Daybeacon 12	51235	STRUCT DEST	FD

San Carlos Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Carlos Bay Light SC	17990	DAYMK MISSING	FD
Punta Rassa Light 3	18020	STRUCT MISSING/TRLB	FD
San Carlos Bay Channel Light 10	18035	STRUCT MISSING/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
San Carlos Bay Light 14	18075	WATCHING PROPERLY	FD	2025-05-08

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE		
Punta Rassa Boat Ramp Channel Daybeacon 3	18050	STRUCT DEST	PA		
Port Sanibel Marina Daybeacon 12	18068.100000000002	HAZ NAV/DAYMK MISSING	PA		
Port Sanibel Marina Daybeacon 26	18069.3	DAYMK MISSING	PA		
Port Sanibel Marina Daybeacon 30	18069.5	DAYMK DMGD	PA		
Port Sanibel Marina Daybeacon 33	18069.7	DAYMK MISSING	PA		
Port Sanibel Marina Daybeacon 42	18069.98	DAYMK MISSING	PA		

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
San Carlos	Bridges	General/Bridges/Construction From: 2024-11-12 To: 2026-12-31 Location: 26.40435° N / 81.88092° W Bridge Name: Big Carlos Pass Bridge -	Lat:
Bay/General/Bridges/Construction		Big Carlos Pass Superior Construction, on behalf of the bridge owner Lee County, will be replacing the Big Carlos (SR 865) Bridge over the Big	26° 24' 16"
		Carlos Pass. The existing bascule bridge will be replaced with a higher-level fixed bridge. In-water work is expected to begin October 2023	Lon:
		and will continue through December 2026. A temporary work trestle will be installed oceanward of the bridge and will span the waterway	-081° 52'
		except across the main navigational channel. The work trestle will provide only 5 feet of vertical clearance throughout the structure. The	51"
		drawbridge will remain fully operational at this time. All mariners are requested to use extreme caution and proceed at slow speed when	
		transiting Big Carlos Pass and remain in the main channel when proceeding through the bridge. All in-water equipment is required to be	
		lighted at night. For further information please contact U.S. Coast Guard Sector St. Petersburg at 727-824-7506 or via email at D07-SMB-	
		Tampa-WWM@uscg.mil.	

San Sebastian River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Sebastian River Daybeacon 20	39170	STRUCT DEST	FD

Sand Key

NAME	LLNR	STATUS	AID TYPE
Bay Pines Channel Daybeacon 1	61225	STRUCT DEST	PA
Bay Pines Channel Daybeacon 7	61240	STRUCT DEST	PA
Bay Pines Channel Daybeacon 16	61265	STRUCT DEST	PA

Bay Pines Channel Daybeacon 19	61275	STRUCT DMGD	PA
Bay Pines Channel Daybeacon 31	61310	STRUCT DEST	PA

Sapelo River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo River Daybeacon 2	5875	STRUCT MISSING	FD

Sapelo Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Sound Buoy 2	5840	MISSING	FD
Sapelo Sound Buoy 5	5850	OFF STATION	FD
Sapelo Sound Light 138	36630.1	STRUCT DEST/TRLB	FD

Sawpit Creek

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Sawpit Creek Daybeacon 49A	38193	DISCONTINUED	FD
Sawpit Creek Daybeacon 50	38195	RELOCATED FOR DREDGING	FD
Sawpit Creek Temporary Daybeacon 50A	38195.1	ESTABLISHED	FD

Sector Charleston, Exclusive Economic Zone (EEZ)

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
NOAA Data Lighted Buoy 41002 (ODAS)	830	RESET ON STATION	FD	2025-05-01

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tybee Creek Fishing Pier Light	370	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
District 7, Oceanic boundary to EEZ - Sector Charleston, Exclusive Economic Zone (EEZ)/ATON/ATON Changes	_	ATON/ATON Changes From: 2025-05-06 To: 2025-11-02 Location: 31.74333° N / 74.955° W Aid Name: NOAA Data Lighted Buoy 41002 (ODAS) LLNR: 830 Action: RELOCATE Position: 31-44-36.000N, 074-57-18.000W	Lat: 31° 44' 36"
			Lon: -074° 57' 18"

Sector Charleston, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little River Inlet Daybeacon 19	1750.5	STRUCT MISSING/TRUB	FD
Murrells Inlet Light 10	1800	TRLB/STRUCT MISSING	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Little River Inlet South Jetty Light 1	30	WATCHING PROPERLY	FD	2025-05-01

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Wreck Temporary Lighted Buoy	37386	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Charleston, Territorial Sea	Marine	General/Marine Construction (Excluding Bridges)/Dredging From: 2025-01-21 To: 2025-06-16 Location: 33.82303° N / 78.65191° W Beginning	Lat:
- Sector Charleston, Submerged	Construction	on or about February 1, 2025 and until approximately June 1, 2025, Coastal Dredging Company's dredge, Charles G. Yopp, will begin	33° 49' 23"
Land Act (SLA)/General/Marine	(Excluding	maintenance dredging activities in the vicinity of House Creek, in the vicinity of Cherry Grove Beach which is located in the City of North	Lon:
Construction (Excluding	Bridges)	Myrtle Beach, South Carolina, and will be pumping dredged sediments, via pipeline, to the Upland Confined Disposal Facility located at the	-078° 39'
Bridges)/Dredging		Tidewater Basin which is adjacent to the AIWW. Hours of operation will be approximately 7 a.m. to 11 p.m., Monday through Sunday. During	07"
		this period all vessels operating in the vicinity of this area are requested to keep a sharp lookout for pipeline and dredge activity equipment	
		and operate their vessels at a safe speed. All vessels in this vicinity should monitor VHF Channel 16 or Channel 66 while approaching and	
		passing dredge activity. If you need additional information you may call Billy Jordan (captbillyjordan@gmail.com) 843-670-1209 or Jonathan	
		Yopp (coastaldredgingllc@yahoo.com) 910-389-7604.	

Sector Charleston, Territorial Sea

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Capers Island Lighted Buoy D	169	OFF STATION	PA
Charleston Sixty Foot Reef Buoy	230	OFF STA	PA
Folly Beach Fishing Pier Obstruction Light	235	LT EXT	PA
North Edisto Reef Lighted Buoy	260	MISSING	PA
Edisto Sixty Foot Reef Buoy	270	OFF STA	PA
General Gordon Wreck Fish Haven Buoy	305	OFF STA	PA
Whitewater Reef Buoy	335	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Charleston Light	195	Reduced Intensity	FD

Additional MSI Categories

Lighted Buoy C LLNR: 518 Action: RENAME Brunswick Spoil Area Lighted Buoy C (LLNR 518) will be changed to Brunswick Spoil Area Lighted Buoy D (LLNR 518). The name change is to alleviate confusion when the Brunswick Pilots instruct commercial vessels to rendezvous with the	Lat: 31° 02' 33" Lon:
Buoy D (LLNR 518). The name change is to alleviate confusion when the Brunswick Pilots instruct commercial vessels to rendezvous with the	31° 02' 33" Lon:
pilot boat at the "Sea Buoy" (St Simons Sound Lighted Buoy STS). The similarity in names between the two aids has caused confusion amongst	-081° 15'
	23"
atice ATON/Proposed Notice of Change Location: 32.75793° N / 79.84324° W Aid Name: Charleston Light LLNR: 195 Action: CHANGE Action Type	Lat:
Change Light Signals The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Charleston Harbor:	32° 45' 29"
Charleston Light (LLNR 195) will permanently have the nominal range reduced from 20NM to 17NM due to the installation of an LED optic. This	Lon:
optic will ensure the light is more reliable as parts and essential components become harder to source for the existing optic. Any part or	-079° 50'
component failure with the current equipment could potentially lead to an extended period where the light would be extinguished. The flash	36"
characteristic and color will remain the same. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or	
andrew.m.engle@uscg.mil with Charleston Light as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard	
l No e	mariners. With the Brunswick Spoil Area Lighted Buoy C marking a shoal, this confusion could lead to a potential grounding. Notice ATON/Proposed Notice of Change Location: 32.75793° N / 79.84324° W Aid Name: Charleston Light LLNR: 195 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Charleston Harbor: Charleston Light (LLNR 195) will permanently have the nominal range reduced from 20NM to 17NM due to the installation of an LED optic. This optic will ensure the light is more reliable as parts and essential components become harder to source for the existing optic. Any part or component failure with the current equipment could potentially lead to an extended period where the light would be extinguished. The flash characteristic and color will remain the same. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or

Sector Jacksonville, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. Johns Light	575	LT IMCH	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Jacksonville, Territorial Sea -	Marine	General/Marine Construction (Excluding Bridges)/Dredging 6783 Great Lakes Dredge and Dock Company, LLC will be conducting dredging	
Sector Jacksonville, Submerged	Construction	on or about December 25, 2024, with an estimated completion date of July 30, 2025. DREDGE ILLINOIS will be dredging approximately 1.5	
Land Act (SLA)/General/Marine	(Excluding	million cubic yards of beach compatible sand from the Sand Bypass Dredging Area (SBDA) and transporting the excavated material to the	
Construction (Excluding Bridges)/Dredging	Bridges)	beach placement area, approx. 0.5 to 9.5 miles south of the Cape Canaveral south jetty. The SBDA is located approximately 0.1 to 1.6 miles north of the Port Canaveral North Jetty and within Cape Canaveral Space Force Station (CCSFS). There are approximately 50 buoys marking different locations. Mariners are requested to transit the area with caution. Other vessels being used are Derrick GL 64, anchor Barge GL 117, crew Boat MUSKEGON RIVER, survey Boat PEARL RIVER, tug BAYOU BRAVE, tug LISTO, tug SMITH HUNTER, tug SYLVIE FAYE, multi cat CAPE CANAVERAL. Vessels will be monitoring VHF-FM channels 5, 13 and 16.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-12-30 To: 2025-06-28 Location: 30.70112° N / 81.42749° W 30.70053° N / 81.40072° W 30.61015° N / 81.35402° W 30.61074° N / 81.43779° W 30.70112° N / 81.42749° W Manson Construction Co. will be conducting hopper dredging (NEWPORT and GLENN EDWARDS) with beach disposal (Fort Clinch and North Beach) and nearshore/offshore disposal (south of Saint Marys Entrance) of dredged material. Operations are expected to commence on or about January 2, 2025, with an estimated completion date of March 15, 2025. Dredging operations to be conducted 7 days per week, 24 hours per day. Vessels will be monitoring VHF-FM channels 13, 16 and 66. Manson respectfully requests that all vessels transiting the dredging, disposal, and pipe assembly/disassembly areas reduce speed.	

https://www.navcen.uscg.gov/msi 44/71

710/20, 12.00 I W		Manufine Safety information i reducts Manufactor Contest	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 9374 From: 2025-01-21 To: 2025-11-07 Gator Dredging will be dredging Ponce Inlet and connecting ICW, disposing onto Ponce Inlet Beach. Operations are expected to commence on or about March 3, 2025, with an estimated completion date of November 7, 2025. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene (HDPE) and steel pipeline associated with the hydraulic dredging operations of the channel will be utilized. Pipeline, work vessels, dredge barge, booster pump barge(s) and buoys will be visibly lighted and marked according to coast guard regulations and will be in the area until all work is complete and can change configuration daily. Vessels BRITTYN B and DREDGE CLEARWATER and/or equipment will be in multiple locations at the same time and monitor VHF-FM channel 16.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Survey Operations	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Survey Operations Location: 28.42886° N / 80.10639° W 26.70514° N / 79.78779° W 25.66011° N / 79.93061° W 25.70095° N / 80.14827° W 25.79125° N / 80.11326° W 26.69042° N / 80.01301° W 28.23545° N / 80.58979° W 28.42886° N / 80.52387° W 28.42886° N / 80.10639° W Fugro USA Marine inc will be conducting hydrographic surveys from west of the Florida Keys up the east coast to Port Canaveral, FL. Operations are expected to begin on or about February 25, 2025, with an estimated completion date of May 22, 2025, and be conducted. R/V FUGRO BRASILIS will be operating Multi Beam Echo Sounders and deploying sound velocity profilers from stern 7 days a week, 24 hours day. They will be monitoring VHF-FM channel 16.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging Marinex Construction, Inc. will perform dredging work for the Nassau County Shore Protection Project, Beach Renourishment. The Dredge Savannah shall begin work as early as May 5, 2025, from the borrow site located 1 ½ Miles SE of the St. Mary's River Entrance (jetties). Dredge pipe and equipment will be staged and mobilized in the Amelia River near Tiger Island across from the Dee Dee Bartels County Boat Ramp. Installation of submerged pipeline will begin as early as April 25, 2025. The Dredge Savannah will operate 24-7 and monitor VHF-FM channels 13 and 16, from approximately May 5, 2025, through August 15, 2025, with demobilization of plant and equipment through September 1, 2025.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 18002 On or about May 14, 2025, Cashman Dredging and Marine Contracting Company, LLC will begin dredging operations on U.S. Naval Station Mayport Maintenance Dredging, Duval County, Florida. The work will be done in the entrance channel and turning basin. This work will be done by the Mechanical Dredge "DALE PYATT" and the Trailing Suction Hopper Dredge "NEWPORT". Support tugs will be the "BRINN CORTNEY", "STASINOS BOYS", and "AMY HEBERT". We will be using the following dump scows: "JOE VERROCHI", M.E.R.C. SHEVLIN", and "KURT SHULTE". The dredge(s) will be supported by the survey/crew vessel "Survey 7", drag barge "Dana", tug "Miss lla", and various other support vessels. All vessels will monitor VHF-FM channels 16,13,12 and use 74 as the working channel. Both Dredges will be using the ODMDS for open ocean disposal. Mariners are urged to transit at their slowest safe speed to minimize wake and proceed with caution after passing arrangements have been made. Dredges will operate 7 days a week, 24 hours a day. The work is scheduled to be completed on or before October 1, 2025.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Boring and Core Samples	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Boring and Core Samples 18252 Athena Technologies will be collecting vibracore samples from proposed borrow areas located offshore of Cape Canaveral, FL. The vibracore samples will be collected from the proposed borrow areas depicted in the attached location map, and we anticipated sampling to occur between 14 – 18 May 2025. Sampling operations will be conducted from the vessel MV THUNDERFORCE that will be operating during daylight hours only and will be available on VHF-FM channels 13/16, and via cell phone at (843)670-6246.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Safety Zones/COPT Restrictions	Safety Zones	General/Safety Zones/COPT Restrictions 17994 A safety zone will be activated in a specified area of the Atlantic Ocean around the Thunder on Cocoa Beach powerboat regatta, scheduled from May 16 through May 18, 2025. The safety zone will be enforced from 8 a.m. to 6:30 p.m. each day and will prohibit persons or vessels from entering this area unless authorized by the Captain of the Port or a designated representative. Mariners are required to contact the Coast Guard via VHF-FM channel 16 to arrange for this authorization. The safety zone is encompassed by a line connecting the following points: 28° 18.688′ N, 80° 36.345′ W, thence to 28° 18.685′ N, 80° 35.617′ W, thence to 28° 22.143′ N, 80° 35.225′ W, thence to 28° 22.330′ N, 80° 35.996′ W, thence back to the first point.	

Sector Key West, Exclusive Economic Zone (EEZ)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE			
Dry Tortugas Southeast Channel Light 1	15440	HAZ NAV/LT EXT/DAYMK MISSING	FD			
Dry Tortugas Southeast Channel Light 3	15450	STRUCT DEST/HAZ NAV/TRLB/MISSING	FD			
Dry Tortugas Southeast Channel Daybeacon 4	15455	DBD DEST	FD			
Dry Tortugas Southeast Middle Ground Daybeacon	15460	DBD DEST	FD			
Fort Jefferson West Channel Daybeacon 3	15530	DBD DEST	FD			
Fort Jefferson West Channel Daybeacon 10	15560	STRUCT DEST	FD			

Sector Key West, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Davis Reef Light 14	970	LT EXT	FD
Cosgrove Shoal Light	1070	LT EXT	FD
Halfmoon Shoal Light WR2	1085	STRUCT DEST	FD
New Ground Rocks Light	1190	HAZ NAV/LT EXT/STRUCT DMGD/TRLB	FD
Smith Shoal Light	1200	LT EXT	FD
Broad Creek Light 6	1215	DAYMK MISSING	FD
Turtle Harbor West Shoal Preferred Channel Light	11455	STRUCT DEST	FD
Key Largo Light 25	11485	STRUCT DEST	FD
Key Largo Light 25	11485	DBD DMGD	FD
Basin Hills Light 31BH	11500	STRUCT DEST	FD
Key Largo Daybeacon 32A	11675	STRUCT DEST/TRLB	FD
Mosquito Bank Light 2	11895	STRUCT DEST/HAZ NAV/TRLB	FD
Channel Key Daybeacon 7	12430	STRUCT MISSING/TRLB	FD
Porpoise Key Daybeacon 2	12685	HAZ NAV/DAYMK MISSING/TRLB	FD
Moser Channel South Daybeacon 5	13865	STRUCT DEST/TRLB/HAZ NAV	FD

https://www.navcen.uscg.gov/msi 45/71

Bahia Honda Key Light 49A	13875	DAYMK MISSING	FD
Niles Channel Daybeacon 6	13955	STRUCT DEST/HAZ NAV/TRLB	FD
Loggerhead Key Light 50A	13980	STRUCT DEST/TRLB	FD
Loggerhead Key Light 50A	13980	HAZ NAV/STRUCT DEST/TRLB	FD
Pirates Cove Daybeacon 10	14175	STRUCT DEST/HAZ NAV/TRLB	FD
Boca Chica Channel Light 1	14505	HAZ NAV/STRUCT MISSING/TRLB	FD
Key West Main Channel Range Front Light	14815	STRUCT DEST/TRLT	FD
Key West Northwest Channel Daybeacon 15	15230	STRUCT DEST/TRUB	FD
Calda Channel Light 1	15330	STRUCT DEST/HAZ NAV/TRLB	FD
Calda Channel Daybeacon 5	15340	HAZ NAV/STRUCT DEST/TRLB	FD
Calda Channel Daybeacon 6	15345	STRUCT DEST/HAZ NAV/TRLB	FD
Calda Channel Daybeacon 18	15400	STRUCT DEST/HAZ NAV/TRLB	FD
Calda Channel Daybeacon 22	15415	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson East Channel Daybeacon 3	15470	STRUCT DEST/HAZ NAV/TRLB/MISSING	FD
Fort Jefferson East Channel Daybeacon 5	15475	HAZ NAV/DAYMK MISSING/TRLB	FD
Fort Jefferson East Channel Daybeacon 6	15480	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson East Channel Daybeacon 7	15485	STRUCT DEST/HAZ NAV/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Calda Channel Buoy 12	15370	RESET ON STATION	FD	2025-05-08

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Broad Creek Daybeacon 13	11177.6	STRUCT DEST	PA
Newfound Harbor Key Buoy C	1003.4	MISSING	PA
Newfound Harbor Key Buoy D	1003.6	MISSING	PA
Nestern Sambo Buoy B	1024.2	MISSING	PA
Sand Key Buoy B	1054.2	MISSING	PA
ewis Cut Shoal West Buoy	10907.5	MISSING	PA
Broad Creek Daybeacon 2	11177.1	STRUCT DEST	PA
Dispatch Creek Channel Daybeacon 20	11435	DAYMK IMCH	PA
Harbor Course Creek Daybeacon 1	11440	DAYMK IMCH	PA
Harbor Course Creek Daybeacon 2	11445	DAYMK IMCH	PA
Garden Cove Daybeacon 22	11645	STRUCT DEST	PA
Port Largo Channel Light 7	11765.30000000001	STRUCT DEST	PA
lue Water Trailer Vill Daybeacon 2	12015	STRUCT DEST	PA
Red Bay Shoal Daybeacon A	12511	STRUCT DEST	PA
a Siesta Resort Daybeacon 2	12810	STRUCT DEST/HAZ NAV	PA
Jpper Matecumbe West Channel Daybeacon 1	12825	STRUCT DEST/HAZ NAV	PA
Caloosa Cove Channel Daybeacon 11	13385	STRUCT DMGD	PA
ouck Key Inlet Channel Light 1	13500	STRUCT DEST	PA
ouck Key Inlet Channel Daybeacon 2	13505	STRUCT DEST	PA
Ouck Key Inlet Channel Daybeacon 7	13525.5	STRUCT DEST	PA
Coco Plum Channel Daybeacon 2	13625	STRUCT DEST	PA
Coco Plum Channel Daybeacon 3	13630	STRUCT DEST	PA
Coco Plum Channel Daybeacon 4	13635	STRUCT DEST	PA
onefish Bay Channel Daybeacon 2	13670	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 4	13673	STRUCT DEST	PA
onefish Bay Channel Daybeacon 5	13675	STRUCT DEST	PA
onefish Bay Channel Daybeacon 7	13676	STRUCT DEST	PA
onefish Bay Channel Daybeacon 8	13676.30000000001	STRUCT DEST	PA
onefish Bay Shoal Daybeacon	13676.5	STRUCT DEST	PA
onefish Bay Channel Daybeacon 10	13676.7	STRUCT DEST	PA
onefish Bay Channel Daybeacon 11	13676.9	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 13	13677	STRUCT DEST	PA
Boat House Channel Buoy 3	13680.2	MISSING	PA
Oolphin Marina Channel Daybeacon 2	13936.2	STRUCT DEST	PA
emp Channel Daybeacon 2	13990	STRUCT DEST/HAZ NAV	PA
emp Channel Daybeacon 19	14073	STRUCT DEST	PA
Cemp Channel Daybeacon 24	14095	STRUCT DEST/HAZ NAV	PA
amarac Park Channel Obstruction E Daybeacon	14450	STRUCT DEST	PA
Cey West Oceanside Marina Daybeacon 2	14670	DAYMK MISSING	PA
Cow Key Channel Daybeacon 11	14740	STRUCT DMGD	PA
Cow Key Channel Daybeacon 13	14745	STRUCT DMGD	PA

https://www.navcen.uscg.gov/msi

14767.9	STRUCT DMGD	PA
14795	STRUCT DEST	PA
14887	LT EXT	PA
14980.1	LT EXT	PA
14980.2	LT EXT	PA
14980.300000000001	STRUCT DEST/HAZ NAV	PA
14980.4	LT EXT	PA
14980.5	LT EXT	PA
	14795 14887 14980.1 14980.2 14980.300000000001 14980.4	14795 STRUCT DEST 14887 LT EXT 14980.1 LT EXT 14980.2 LT EXT 14980.30000000001 STRUCT DEST/HAZ NAV 14980.4 LT EXT

Additional MSI Categorie			
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	Key West Main Channel Range Front Light (LLNR 14815) will be relocated to approximate position 24-32-17.396N/081-48-22.958W. The RFL will be changed to a day/night optic, continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 32' 17' Lon: -081° 48' 23"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	Key West Main Channel Range Rear Light (LLNR 14820) will be changed to a day/night optic, continuing to display an ISO G 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 32' 56" Lon: -081° 48' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change From: 2025-03-04 To: 2026-03-04 Location: 24.56043° N / 81.8144° W Aid Name: Key West Main Channel Cut B Range Front Light LLNR: 14870 Action: CHANGE Action Type Change Structure The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Main Channel Cut B Range Front Light (LLNR 14870) will be rebuilt at a new focal height of 40 feet. All other characteristics will remain the same. Key West Main Channel Cut B Range Rear Light (LLNR 14875) will be rebuilt at a new focal height of 65 feet. All other characteristics will remain the same.	Lon:
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change From: 2025-03-04 To: 2026-03-04 Location: 24.5629° N / 81.81427° W Aid Name: Key West Main Channel Cut B Range Rear Light LLNR: 14875 Action: CHANGE Action Type Change Structure The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Main Channel Cut B Range Front Light (LLNR 14870) will be rebuilt at a new focal height of 40 feet. All other characteristics will remain the same. Key West Main Channel Cut B Range Rear Light (LLNR 14875) will be rebuilt at a new focal height of 65 feet. All other characteristics will remain the same.	Lat: 24° 33' 46" Lon: -081° 48' 51"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.59918° N / 81.80971° W Aid Name: Calda Channel Daybeacon 22 LLNR: 15415 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	Lat: 24° 35' 57" Lon: -081° 48' 35"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.60718° N / 81.80627° W Aid Name: Calda Channel Daybeacon 18 LLNR: 15400 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guardhas approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.62495° N / 81.81523° W Aid Name: Calda Channel Daybeacon 6 LLNR: 15345 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	Lat: 24° 37' 30" Lon: -081° 48' 55"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.57937° N / 81.79983° W Aid Name: Key West Harbor Range Front Light LLNR: 14900 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Harbor Range Front Light (LLNR 14900) will be changed to a day/night optic, continuing to display Q W flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued. Key West Harbor Range Rear Light (LLNR 14905) will be rebuilt to a focal height of 46 feet and changed to a day/night optic, continuing to display ISO W 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lon:
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Notice of	ATON/Advanced Notice of Change Location: 24.58519° N / 81.79695° W Aid Name: Key West Harbor Range Rear Light LLNR: 14905 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Harbor Range Front Light (LLNR 14900) will be changed to a day/night optic, continuing to display Q W flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued. Key West Harbor Range Rear Light (LLNR 14905) will be rebuilt to a focal height of 46 feet and changed to a day/night optic, continuing to display ISO W 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lon:
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Bridges/Closure (Scheduled Or Emergency)	Bridges	General/Bridges/Closure (Scheduled Or Emergency) From: 2024-10-29 To: 2025-11-01 Location: 24.60464° N / 81.64066° W Bridge Name: Shark Key Pedestrian Bridge The Shark Channel pedestrian bridge is damaged with debris falling into the water. Mariners are advised to use caution in the area and avoid transiting under the bridge. For more information, contact Florida Keys Overseas Heritage Trail Assistant Park Manager, Jimmy Chandler at (305) 360-7958.	Lat: 24° 36' 17" Lon: -081° 38' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-12 To: 2025-09-01 Location: 24.60459° N / 81.64045° W Bridge Name: Florida Keys Overseas Historical Trial Pedestrian Bridge - Shark Channel The pedestrian bridge is undergoing a rehabilitation project. The contractor will have barges and associated in-water equipment in and around the bridge at all times. All in-water equipment should be lighted in accordance with Inland Navigation rules. Navigation through the structure will be limited during construction; at any time, four (4) arches will be obstructed and closed to navigation. Mariners are advised to proceed at a safe speed and use caution when transiting through the area. The rehabilitation project will begin on or around 3/13/2025 and be completed by 9/1/2025. For waterways related questions, contact, Coast Guard Sector Key West Waterways, 305-292-8768 or email: SKWWaterways@uscg.mil.	Lat: 24° 36' 17" Lon: -081° 38' 26"

https://www.navcen.uscg.gov/msi

Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Survey Operations	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Survey Operations Location: 25.71518° N / 80.08785° W 25.70528° N / 79.85714° W 24.84097° N / 80.15377° W 24.1712° N / 81.36226° W 24.1712° N / 83.60347° W 24.98047° N / 83.61446° W 24.75121° N / 81.4172° W 24.98047° N / 80.40645° W 25.71518° N / 80.08785° W Fugro USA Marine inc will be conducting hydrographic surveys from west of the Florida Keys up the east coast to Port Canaveral, FL. Operations are expected to begin on or about February 25, 2025, with an estimated completion date of May 22, 2025, and be conducted. R/V FUGRO BRASILIS will be operating Multi Beam Echo Sounders and deploying sound velocity profilers from stern 7 days a week, 24 hours day. They will be monitoring VHF-FM channel 16.	
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	General/Miscellaneous 18012 Mote Marine Laboratory and Aquarium will be launching an autonomous surface vessel for a gulf water quality survey and harmful algal bloom monitoring, traversing from Sarasota, FL to Key West, FL Operations are expected to being May 6, 2025, with an estimated completion date of May 21, 2025. Vessel is equipped with AIS transmit and receiving capabilities.	
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Naval Activity/Military Operations	Naval Activity	General/Naval Activity/Military Operations 18248 The US Navy will be conducting exercises in Key West Florida in the coming weeks of August 4 – 15, August 25 - September 5, September 15 – 26. All support vessels will be monitoring VHF-FM channels 16 and 81A. On Monday, August 11, 2025, September 1, 2025, and September 22, 2025, they will be conducting a dive down the Boca Chica Chanel to the harbor between 6 p.m. and 10 p.m. Divers will stay to the Eastern side of the channel, and they will have four boats plus two jet skis to deconflict with mariners and provide diver support and protection. On Tuesday August 12, 2025, September 2, 2025, and September 23, 2025, they will be conducting a day dive from 4 p.m. to 6:30 p.m. in Fleming Key Cut. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. Divers will be confined to transiting through the cut on only one side, leaving the other side open. Also, on Tuesday August 12, 2025, September 2, 2025, and September 23, 2025, they will be conducting a night dive from 7:30 p.m. to 10 p.m. along the western edge of Key West from the mouth of Key West Bight to Truman Waterfront Park. Divers will be no farther from shore than 50 meters and should pose a minimal obstruction to routine navigational operations. Depending on the weather and sea state, they may flex to doing an offset dive. They would splash the divers at either Key West Main Channel Daybeacon 21 (LLNR 4925) diving east into the Basin, or Key West Main Channel Lighted Buoy 15 (LLNR 14895) diving east into the Basin. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. On Wednesday, August 13, 2025, September 3, 2025, and September 24, 2025, they will be conducting a day into night dive from 7p.m. until 9:30 p.m. around Fleming Key Cut. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protectio	

Sector Key West, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pacific Reef Light	935	LT EXT/TRLT	FD
Elbow Reef Light 6	950	STRUCT DEST/LT IMCH/REDUCED INT/DAYMK MISSING/TRLT	FD
Molasses Reef Light 10	960	LT EXT/STRUCT DMGD	FD
Tennessee Reef Light	990	LT EXT/STRUCT DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Carysfort Reef Buoy C	947.4	MISSING	PA
The Elbow Buoy B	948.2	MISSING	PA
The Elbow Buoy C	948.4	MISSING	PA
The Elbow Buoy D	948.6	MISSING	PA
Dry Rocks Buoy A	953	MISSING	PA
Grecian Rocks Buoy D	954.6	MISSING	PA
Sombrero Key Buoy B	1002.2	MSLD SIG	PA
Looe Key Buoy C	1007.4	MISSING	PA
Looe Key Telemetering Lighted Buoy LR	1007.800000000001	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes		General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-11-26 To: 2024-11-27 Location: 24.88752° N / 81.7° W 24.88333° N / 81.7° W 24.88333° N / 81.70458° W 24.88752° N / 81.70458° N / 81.70458° W 24.88752° N / 81.70458° N / 81.70	
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes		General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Location: 24.88752° N / 81.7° W 24.88333° N / 81.7° W 24.88333° N / 81.70458° W 24.88752° N / 81.70 W Monroe County has continued adding to a new artificial reef site off Monroe County with a 10-year permit. The Gulfside Ten Mile Reef site is a 0.25 nautical mile by 0.25 nautical mile square, encompassing 53 acres of sand bottom of which less than one acre of artificial reef material footprint will be deployed during the lifetime of the permit. The site is located in the Gulf of America within federal waters and lies outside of the boundaries for the Florida Keys National Marine Sanctuary. The center of the site is located approximately 16.7 nautical miles at a bearing of 23° north of Key West at an average depth of 45 feet MLLW. All deployed material will retain at least a 25-ft navigational clearance.	
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous 17982 Location: 24.46495° N / 81.45885° W Florida Fish and Wildlife Research Institute, Florida Fish and Wildlife Conservation Commission will be temporarily establishing a data buoy from May 20, 2025, to May 22, 2025, with a flashing yellow light. For more information contact Nick Alcaraz at Nicholas.Alcaraz@MyFWC.com.	Lat: 24° 27' 54" Lon: -081° 27' 32"

https://www.navcen.uscg.gov/msi 48/71

Sector Miami, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
NSWC Lighted Buoy E	811	HAZ NAV/BUOY DMGD/LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jupiter Inlet Jetty Light 2	735	LT EXT	PA
Key Biscayne FAD Northwest Buoy	900	MISSING	PA
Key Biscayne FAD Northeast Buoy	905	MISSING	PA
Key Biscayne FAD Southwest Buoy	910	MISSING	PA
Key Biscayne FAD Southeast Buoy	915	MISSING	PA
Neptune Memorial Reef Buoy AA	915.1	STRUCT DEST	PA
Neptune Memorial Reef Buoy BB	915.2	STRUCT DEST	PA
Neptune Memorial Reef Buoy CC	915.300000000001	STRUCT DEST	PA
Neptune Memorial Reef Buoy DD	915.4	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Miami, Territorial Sea - Sector Miami, Submerged Land Act (SLA)/ATON/ATON Changes	ATON Changes	ATON/ATON Changes From: 2025-05-08 To: 2025-11-04 Location: 27.44195° N / 80.26208° W Aid Name: Oneka Desalination Data Lighted Buoy LLNR: 680 Action: DISCONTINUE Position: 27-26-31.019N/080-15-43.487W Light: FI Y 4s	Lat: 27° 26' 31" Lon: -080° 15' 43"
Sector Miami, Territorial Sea - Sector Miami, Submerged Land Act (SLA)/ATON/ATON Changes	ATON Changes	ATON/ATON Changes From: 2025-05-08 To: 2025-11-04 Location: 27.44105° N / 80.26202° W Aid Name: Oneka Desalination Wx Data Lighted Buoy W1 LLNR: 681 Action: RELOCATE Position: 27-26-27.780N/080-15-43.290W. Light: FI Y 2.5s	Lat: 27° 26' 28" Lon: -080° 15' 43"
Sector Miami, Territorial Sea - Sector Miami, Submerged Land Act (SLA)/ATON/ATON Changes	ATON Changes	ATON/ATON Changes From: 2025-05-08 To: 2025-11-04 Location: 27.44105° N / 80.26202° W Aid Name: Oneka Desalination Iceberg II Lighted Data Buoy I2 LLNR: 680.1 Action: RELOCATE Position: 27-26-31.800N/080-15-42.960W Light: FI Y 4s	Lat: 27° 26' 28" Lon: -080° 15' 43"
Miami, Submerged Land Act Guard Mooring B ML (LLNR 768) will be permanently established in approximate position 26-40-39.000N, 080-01-33.0 (SLA)/General/Miscellaneous buoy will be white in color with an all-around blue band at the top. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with CG Mooring Buoy ML as the subject line. Comment		Guard Mooring B ML (LLNR 768) will be permanently established in approximate position 26-40-39.000N, 080-01-33.000W. The mooring buoy will be white in color with an all-around blue band at the top. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with CG Mooring Buoy ML as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL. 33131-	Lat: 26° 40' 39" Lon: -080° 01' 33"

Sector Miami, Territorial Sea

Additional MSI Categories

Additional Wis	. dategoile		
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Miami, Territorial	Naval Activity	General/Naval Activity/Military Operations Location: 26.08417° N / 80.09583° W 26.08417° N / 80.01833° W 26.02417° N / 80.01833° W 26.02417° N /	
Sea/General/Naval		80.09583° W The U.S. Navy will be conducting operations in the water immediately South and East of Port Everglades inlet. The operations are scheduled	
Activity/Military		within a period beginning 6 a.m. May 6, 2025, to 6 a.m. May 16, 2025. A naval vessel will be conducting maneuvers between ¾ NM to 5 NM off shore,	
Operations		and from ½ NM south of the Port Everglades inlet to 2 NM south of the Dania Beach Pier. The vessel will be restricted in maneuverability and these	
		operations are considered a hazard to navigation. All traffic must remain clear of the area bounded by the coordinates below for the duration of the	
		operations. Local law enforcement, U.S. Navy security boats, and Tow Boat US small craft will provide security and range clearance for the naval vessel	
		during these operations. Ships entering/departing Port Everglades are requested to do so from the northeast thereby avoiding the waters south of the	
		channel. To allow for the safe operation of the naval vessel, all maritime traffic transiting the area is requested to stay 5 NM east of Port Everglades or	
		inshore of the Barracuda Reef mooring buoys. Any concerned vessels may contact U.S. Navy Fort Lauderdale on VHF-FM channel 16.	

Sector San Juan, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aguadilla Jetty Light 1	32405	LT EXT	FD

ADRIFT OFF STA	PA PA
OFF STA	PA
OFF STA	PA
OFF STA	PA
STRUCT DEST	PA

Krause Lagoon Channel Entrance Lighted Buoy 1 33210 TRLB PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector San Juan, Territorial	Hazards To	General/Hazards To Navigation/Obstructions From: 2024-10-20 To: 2025-04-18 Location: 18.093° N / 65.62092° W The United States Navy has	Lat:
Sea/General/Hazards To Navigation/Obstructions	Navigation	installed subsurface coral restoration structures offshore of Ilsa de Vieques within the boundaries of the former Navy training range (UXO-16), for a Navy environmental restoration project. The structures include 2 geodesic spheres that are 8 feet diameter, and will be moored to the seafloor such that the tops of the structures will sit at 24 feet below the surface. These structures will not be sitting directly on the seafloor - they will be in the mid-water, moored to the seafloor (which is approximately 55 feet deep at this location) with a 3-anchor system, without surface marker buoys. The structures are expected to remain in place until at least June 30, 2026 in the approximate coordinates: 18-06-01.49N/065-36-17.97W 18-05-59.94N/065-36-17.17W For further information contact: Jessica Carilli, US Navy (760) 815-2629.	18° 05' 35" Lon: -065° 37' 15"
Sector San Juan, Territorial Sea/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2027-07-28 Location: 18.26572° N / 65.57337° W 18.23996° N / 65.57028° W 18.23991° N / 65.60289° W 18.26574° N / 65.60444° W 18.26572° N / 65.57337° W The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	
Sector San Juan, Territorial Sea/General/Marine Events/Regatta (Race)	Marine Events	General/Marine Events/Regatta (Race) The U.S. Coast Guard will be enforcing a Special Local Regulation for the St. Thomas Carnival Boat Race 2025 described in Title 33 Code of Federal Regulations (CFR) 100.701 Table 1 on April 28, 2025, from 10 a.m. to 5 p.m. The regulated area encompasses all waters of St. Thomas Harbor encompassed within the following points: i. Race Area. All waters of the St. Thomas Harbor located around Hassel Island, St. Thomas, U.S. Virgin Island encompassed within the following points: Starting at Point 1 in position 18°20.2' N, 64°56.1' W; thence southeast to Point 2 in position 18°19.7' N, 64°55.7' W; thence southeast to Point 3 in position 18°19.4' N, 64°55.7' W; thence southwest to point 4 in position 18°19.3' N, 64°56.0' W; thence northwest to point 5 in position 18°19.9' N, 64°56.5' W; thence northeast to point 6 in position 18°20.2' N, 064°56.3' W; thence east back to origin. ii. Jet Ski Race Area. All waters encompassed the following points: Starting at Point 1 in position 18°20.1' N, 64°55.9' W; thence west to Point 2 in position 18°20.1' N, 64°55.9' W; thence west to Point 2 in position 18°20.1' N, 64°55.9' W; thence south back to origin. iii. Buffer Zone. All waters of the St. Thomas Harbor located around Hassel Island, encompassed within the following points: Starting at Point 1 in position 18°20.3' N, 64°55.9' W; thence south to Point 3 in position 18°19.3' N, 64°55.7' W; thence south to Point 3 in position 18°19.3' N, 64°55.7' W; thence south to Point 3 in position 18°19.3' N, 64°55.7' W; thence south to Point 3 in position 18°19.3' N, 64°55.7' W; thence southwest to Point 4 in position 18°19.2' N, 64°56.5' W; thence northwest to Point 5 in position 18°19.9' N, 64°55.7' W; thence northwest to Point 6 in position 18°20.3' N, 64°56.3' W; thence east back to origin. in position 18°20.3' N, 64°55.5' W; thence northwest to Point 1 in position 18°20.2' N, 64°55.5' W; thence northwest to Point 1 in position 18°20.2' N, 64°55.5' W; thence northwest to Point 2 in position 18°20.2'	

Sector St. Peterburg, Exclusive Economic Zone (EEZ)

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Scripps Wave Lighted Buoy A	1367	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
District 7, Oceanic boundary to EEZ - Sector St. Peterburg, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-11-19 To: 2025-05-18 Location: 25.79667° N / 81.97° W There is a submerged 200-foot barge, fully submerged, with only a few feet of clearance to the surface of the water. Wreck is marked with unlit buoys.	Lat: 25° 47' 48" Lon: -081° 58' 12"
District 7, Oceanic boundary to EEZ - Sector St. Peterburg, Exclusive Economic Zone (EEZ)/General/Marine Construction (Excluding Bridges)/Survey Operations	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Survey Operations Location: 28.735° N / 84.39833° W 28.735° N / 84.16° W 28.69333° N / 84.07333° W 28.255° N / 83.79° W 28.27167° N / 83.99667° W 28.16667° N / 83.96° W 28.16333° N / 84.13667° W 28.28667° N / 84.44333° W 28.735° N / 84.39833° W SAILDRONE, INC. will be conducting research with up to two Uncrewed Surface Vehicles (USVs), called SAILDRONE VOYAGERs, approximately 90 nautical miles northwest of St. Petersburg, FL. The vehicles are supporting the Florida Seafloor Mapping Initiative in partnership with the Florida Department of Environmental Protection to conduct a survey off the West Florida Shelf known as The Florida Middle Grounds. The vehicles are deployed from St. Petersburg, FL and are expected to make stops from the survey area to St. Petersburg throughout this period. These vehicles will conduct 24 hr operations for the aforementioned duration. Vehicles are monitored remotely 24/7 by the SAILDRONE Mission Control Team. SAILDRONE VOYAGERs are primarily wind-propelled Uncrewed Surface Vehicles (USVs) equipped with an electric thruster used for survey operations. Mariners are requested to remain clear from the research equipment. Questions regarding this notice can be directed to Saildrone Mission Control at missioncontrol@saildrone.com or via phone at +1-510-722-6070.	

Sector St. Petersburg, Submerged Land Act (SLA)

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage South Entrance Light 1	1535	HAZ NAV/STRUCT DEST/TRLB	FD
Seahorse Reef Light	1615	STRUCT DEST/HAZ NAV	FD
Capri Pass Light 3	16955	TRLB/STRUCT MISSING	FD

Private Discrepancies

LLNR	STATUS	AID TYPE		
17877	DAYMK DMGD	PA		
19150	STRUCT DEST/HAZ NAV	PA		
27015	LT EXT	PA		
27030	STRUCT DEST/TRDBN	PA		
	17877 19150	17877 DAYMK DMGD 19150 STRUCT DEST/HAZ NAV 27015 LT EXT		

https://www.navcen.uscg.gov/msi 50/71

0/10/20, 12.001 W	outery information	Trioddels Navigation Ochter	
Sea Pines Channel Daybeacon 3	27150	STRUCT DEST/HAZ NAV	PA
Long Key North Breakwater Obstruction Daybeacon	1410	STRUCT DEST	PA
Port of Islands Marina Daybeacon 3	16235	STRUCT DEST	PA
Port of Islands Marina Daybeacon 4	16240	STRUCT DEST	PA
Port of Islands Marina Daybeacon 5	16245	STRUCT DMGD	PA
Port of Islands Marina Daybeacon 6	16250	STRUCT DEST/HAZ NAV	PA
Port of Islands Marina Daybeacon 11	16265	DAYMK MISSING	PA
Port of Islands Marina Daybeacon 15	16280	STRUCT DEST	PA
Port of Islands Marina Daybeacon 26	16310	STRUCT DEST	PA
Port of Islands Marina Daybeacon 27	16315	STRUCT DEST	PA
Port of Islands Marina Daybeacon 42	16380	STRUCT DEST/HAZ NAV	PA
Port of Islands Marina Daybeacon 44	16390	STRUCT DEST	PA
Cape Romano Channel Daybeacon 2	16792	STRUCT DEST	PA
Cape Romano Channel Daybeacon 4	16792.1	STRUCT DEST	PA
Cape Romano Channel Daybeacon 17	16793	DAYMK MISSING	PA PA
Caxambas Breakwater North Obstruction Daybeacon	16917	STRUCT DEST	
Caxambas Breakwater South Obstruction Light	16918	LT EXT	PA
Caxambas Breakwater South Obstruction Daybeacon	16918.5	DAYMK MISSING	PA
Doctors Pass Light DP	17700	LT EXT	PA
Doctors Pass Daybeacon 16	17770	STRUCT DEST	PA
Barefoot Boat Club Daybeacon 10	17915	STRUCT DEST	PA
Barefoot Boat Club Daybeacon 12	17920	STRUCT DEST	PA
Big Carlos Pass Lighted Buoy 1	17975	MISSING	PA
Big Carlos Pass Buoy 2	17976	MISSING	PA
Big Carlos Pass Buoy 3	17977	MISSING	PA
Big Carlos Pass Buoy 4	17980	MISSING	PA
Big Carlos Pass Buoy 5	17985	MISSING	PA
Estero Pointe Channel Daybeacon 29	18996.07	STRUCT DEST/HAZ NAV	PA
Baywinds Channel Daybeacon 3	19347.3	STRUCT DEST	PA
Spring Creek Daybeacon 17	19400	STRUCT DEST	PA
South Estero Bay Daybeacon 37	19550	STRUCT DEST	PA
South Estero Bay Daybeacon 45	19585	STRUCT DEST	PA
Coconut Jacks Daybeacon 5	19786.2	STRUCT DEST	PA
Scripps Wave Data Lighted Buoy CDIP STA 214	22247	OFF STA	PA
Signal Cove Light 2	26945	LT EXT	PA
Signal Cove Daybeacon 4	26955	STRUCT DEST	PA
Signal Cove Daybeacon 5	26960	STRUCT DEST	PA
Hudson Creek Daybeacon 7	27040	STRUCT DEST/HAZ NAV/TRUB	PA
·	27085	STRUCT DEST/TRUB	PA
Hudson Creek Daybeacon 20	27095		PA
Hudson Creek Daybeacon 23		STRUCT DEST	
Hudson Beach Park Daybeacon 1	27110	STRUCT DEST	PA
Sea Pines Channel Daybeacon 23	27230	STRUCT DEST	PA
Sea Pines Channel Daybeacon 29	27265	STRUCT DEST	PA
Aripeka Daybeacon 7	27310	STRUCT DEST/HAZ NAV	PA
Hernando Beach Channel Daybeacon 6	27530	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 7	27535	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 10	27550	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 22	27610	STRUCT DEST	PA
Hernando Beach Channel Daybeacon 23	27615	STRUCT MISSING	PA
		STRUCT MISSING STRUCT DEST/HAZ NAV	PA PA
Hernando Beach Channel Daybeacon 23	27615		
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27	27615 27630.5	STRUCT DEST/HAZ NAV	PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40	27615 27630.5 27685	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV	PA PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44	27615 27630.5 27685 27705	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV	PA PA PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53	27615 27630.5 27685 27705 27737	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV	PA PA PA PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17	27615 27630.5 27685 27705 27737 27930	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST	PA PA PA PA PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3	27615 27630.5 27685 27705 27737 27930 28305 28960	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING	PA PA PA PA PA PA PA PA PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4	27615 27630.5 27685 27705 27737 27930 28305 28960 28965	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING	PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4 Florida Power Corporation Channel Light 6	27615 27630.5 27685 27705 27737 27930 28305 28960 28965 28975	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING LT EXT	PA
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4 Florida Power Corporation Channel Light 6 Florida Power Corporation Channel Light 8	27615 27630.5 27685 27705 27737 27930 28305 28960 28965 28975 28985	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING LT EXT	PA P
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4 Florida Power Corporation Channel Light 8 Florida Power Corporation Channel Light 13	27615 27630.5 27685 27705 27737 27930 28305 28960 28965 28975 28985 29005	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING LT EXT LT EXT STRUCT DEST	PA P
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4 Florida Power Corporation Channel Light 8 Florida Power Corporation Channel Light 13 Florida Power Corporation Channel Light 13 Florida Power Corporation Channel Light 13	27615 27630.5 27685 27705 27737 27930 28305 28960 28965 28975 28985 29005 29010	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING LT EXT LT EXT STRUCT DEST LT EXT	PA P
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4 Florida Power Corporation Channel Light 8 Florida Power Corporation Channel Light 13 Florida Power Corporation Channel Light 13 Florida Power Corporation Channel Light 14 Florida Power Corporation Channel Light 14	27615 27630.5 27685 27705 27737 27930 28305 28960 28965 28975 28985 29005 29010 29015	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING LT EXT LT EXT LT EXT LT EXT LT EXT	PA P
Hernando Beach Channel Daybeacon 23 Hernando Beach Channel Daybeacon 27 Hernando Beach Channel Daybeacon 40 Hernando Beach Channel Daybeacon 44 Hernando Beach Channel Light 53 Johnson Rock Obstruction Daybeacon Chassahowitzka Daybeacon 17 Florida Power Corporation Channel Light 3 Florida Power Corporation Channel Light 4 Florida Power Corporation Channel Light 8 Florida Power Corporation Channel Light 13 Florida Power Corporation Channel Light 13 Florida Power Corporation Channel Light 13	27615 27630.5 27685 27705 27737 27930 28305 28960 28965 28975 28985 29005 29010	STRUCT DEST/HAZ NAV STRUCT DEST/HAZ NAV STRUCT DEST STRUCT DEST/HAZ NAV STRUCT MISSING STRUCT DEST LT IMCH/DAYMK MISSING LT IMCH/DAYMK MISSING LT EXT LT EXT STRUCT DEST LT EXT	PA P

https://www.navcen.uscg.gov/msi 51/71

Florida Power Corporation Channel Light 32	29075	STRUCT DEST/HAZ NAV	PA
Florida Power Corporation Channel Light 47	29150	LT IMCH	PA
Florida Power Corporation Channel Light 48	29155	LT IMCH	PA
Waccasassa Bay And River Daybeacon 5	29665	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 9	29675	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 11	29680	STRUCT DMGD	PA
Waccasassa Bay And River Daybeacon 13	29685	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 15	29690	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 17	29695	STRUCT DMGD	PA
Waccasassa Bay And River Daybeacon 21	29705	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 23	29710	DAYMK DMGD	PA
Waccasassa Bay And River Daybeacon 25	29720	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 27	29725	DAYMK MISSING/STRUCT DMGD	PA
Waccasassa Bay And River Daybeacon 30	29735	STRUCT DEST/HAZ NAV	PA
Waccasassa Bay And River Daybeacon 32	29740	STRUCT DMGD	PA
Suwannee River Alligator Pass Light 2	30085	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 4	30090	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 5	30095	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 7	30100	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 9	30110	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 11	30115	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 13	30120	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 19	30140	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 27	30160	STRUCT DEST/HAZ NAV	PA
Suwannee River Alligator Pass Daybeacon 29	30165	STRUCT DEST	PA
Suwannee River McGriff Pass Daybeacon 1	30170	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 3	30180	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 5	30185	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 7	30200	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 8	30205	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 9	30210	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 20	30233	STRUCT DEST	PA
Salt Creek Daybeacon 15	30305	STRUCT DEST	PA
Salt Creek Daybeacon 16	30310	STRUCT DEST	PA
Salt Creek Daybeacon 17	30315	STRUCT DEST	PA
Salt Creek Daybeacon 18	30320	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector St. Petersburg, Territorial Sea - Sector St.		General/Hazards To Navigation/Shoaling Reported From: 2025-02-18 To: 2025-08-17 Location: 26.3744° N / 81.8762° W All	Lat:
Petersburg, Submerged Land Act		,	26° 22' 28"
(SLA)/General/Hazards To Navigation/Shoaling Reported		vicinity of New Pass Lighted Buoy 1 (LLNR 17964). All mariners are advised to use caution while transiting new pass due to the potentially hazardous conditions. For further information please contact U.S. Coast Guard Sector St. Petersburg at (727) 824-	-081° 52'
reported		7506.	34"

Sheephead Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sheephead Cut Daybeacon 7	40705	STRUCT DEST/TRUB	FD

Shell Key

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Race Channel Daybeacon 11B	13085	STRUCT DMGD	PA
Little Basin East Daybeacon 1	50540	DAYMK MISSING	PA
Little Basin East Daybeacon 2	50545	STRUCT DEST/HAZ NAV	PA
Little Basin East Daybeacon 4	50555	DAYMK MISSING	PA

Sherman Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sherman Cut Range Rear Light	7240	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Sherman Cut/ATON/Advanced Notice of Change	Advanced Notice of Change	Sherman Cut RFL (LLNR 7235) will be relocated to approximate position: 30-22-44.220N/081-26-46.188W to align with the newly dredged channel. In addition, Sherman Cut RFL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 26' 45'
St Johns River - Sherman Cut/ATON/Advanced Notice of Change	Advanced Notice of Change	Sherman Cut RRL (LLNR 7240) will be relocated to approximate position: 30-22-26.194N/081-27-03.893W to align with the newly dredged channel. In addition Sherman Cut RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 35" Lon: -081° 26' 55

Sim-Par Marina Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Marina Bay Channel Daybeacon 4	39715	STRUCT DEST	PA

Singer Island Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Singer Island Channel Daybeacon 6	10212.30000000001	STRUCT DEST/HAZ NAV/TRLB	FD

Sisters Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sisters Creek Daybeacon 80	38320	STRUCT DEST/TRUB	FD
Sisters Creek Light 82	38325	STRUCT DEST/TRLB/HAZ NAV	FD
Sisters Creek Light 83	38330	STRUCT DEST/HAZ NAV/TRLB	FD

Skidaway Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Skidaway Narrows Daybeacon 60	36140	STRUCT DEST/TRUB	FD

Snake Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snake Creek Daybeacon 4	12215	STRUCT DEST/TRUB	FD
Snake Creek Daybeacon 5	12225	STRUCT DEST/TRLB	FD
Snake Creek Daybeacon 7	12240	STRUCT DEST/TRUB	FD

Snapper Creek Marina

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Safety Valve Bank Light 1A	49530	STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snapper Creek Marina Daybeacon 2	49515	DAYMK MISSING	PA

Sonde De Vieques

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cayo Lobito Light	31525	STRUCT DEST	FD

NAME	LLNR	STATUS	AID TYPE
North St Thomas Lighted Buoy H	31683	OFF STA	PA

South Altamaha River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Altamaha River Daybeacon 4	36995	STRUCT MISSING/TRUB	FD

South Amelia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Amelia River Daybeacon 21	38050	STRUCT MISSING/TRUB	FD
South Amelia River Light 24	38060	DAYMK MISSING	FD

South Jupiter Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Jupiter Narrows Daybeacon 25	46085	STRUCT MISSING/TRUB	FD

South Newport River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Newport River Light 135	36620	STRUCT MISSING/TRLB	FD

Southwest Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southwest Channel Light 2 (Tampa Bay)	21840	STRUCT MISSING	FD

St Andrew Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Buoy 29A	37375	MISSING	FD
St Andrew Sound Lighted Buoy 30	37380	OFF STA	FD
St Andrew Sound Lighted Buoy 31	37383	LT EXT	FD
St Andrew Sound Lighted Buoy 32	37385	OFF STA	FD

St Augustine Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Augustine Inlet Buoy 3	9485	OFF STATION	FD
St Augustine Inlet Lighted Buoy 5	9495	MISSING	FD
St Augustine Inlet Buoy 10	9510	OFF STA	FD

St Catherines Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Catherines Sound Lighted Buoy 2	5795	MISSING	FD
St Catherines Sound Buoy 1	5800	MISSING	FD
St Catherines Sound Buoy 3	5805	MISSING	FD

St Helena Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Helena Sound Entrance Buoy 4	3965	MISSING	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Old House Creek Buoy 14	4038	RESET ON STATION	FD	2025-05-07

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hunting Island Pier Light	4070	STRUCT DEST/LT EXT	PA

St Johns River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pilot Town Cut Range Front Light	7200	LT EXT	FD
St Johns Bluff Light S	7335	STRUCT DEST/TRLB	FD
Quarantine Island Upper Range Front Light	7450	NIGHT LT BURNING DAY	FD
Winter Point Daybeacon	7670	STRUCT DEST/TRUB	FD
Winter Point Light 1	7675	STRUCT DEST/TRLB	FD
Winter Point Light 2	7680	STRUCT DEST/TRLB	FD
Ortega River Shoal Daybeacon	7685	STRUCT DEST/TRUB	FD
Christopher Point Light 5	7725	DAYMK MISSING	FD
Red Bay Point Light 22	7895	STRUCT DEST/TRLB	FD
Tocoi Cut Entrance Light 33	7935	HAZ NAV/STRUCT DMGD/TRLB	FD
Upper Palatka Light 1	8195	LT EXT	FD
Upper Palatka Light 2	8200	LT EXT	FD
Upper Palatka Daybeacon 3	8205	STRUCT MISSING/TRUB	FD
Rivercrest Light 10	8235	LT EXT	FD
Nashua Daybeacon 42A	8390	STRUCT DEST/TRUB	FD
Stephens Point Daybeacon 46	8415	STRUCT DEST/TRUB	FD
Adams Lake Daybeacon 23	8910	STRUCT DEST/HAZ NAV/TRLB	FD
Wekiva Cutoff Daybeacon 95	9155	STRUCT DEST	FD
Wekiva Bend Cutoff Light 96	9160	STRUCT DEST/HAZ NAV/TRLB	FD
Mothers Arms Daybeacon 4	9425	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Goodbys Creek Channel Buoy 4	7765.3	OFF STA	PA
Ortega River Lighted Buoy 2	7696	MISSING	PA
Ortega River Lighted Buoy 13	7697	MISSING	PA
Goodbys Creek Channel Buoy 5	7765.40000000001	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Dunn Creek Cut Lighted Buoy 55	7490	RELOCATED FOR DREDGING	FD
Mile Point Temporary Lower Range Front Light	7260.2	ESTABLISHED	FD
Mile Point Temporary Lower Range Rear Light	7265.2	ESTABLISHED	FD
Training Wall Temporary Range Front Light	7295.2	ESTABLISHED	FD
Drummond Creek Temporary Range Front Light	7515.2	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act	Advanced	St. Johns Bluff LB 30 (LLNR 7329) will be permanently relocated to 30-23-32.020N/081-29-29.730W. This change calls to relocate (6)	Lat:
(SLA) - St Johns River/ATON/Advanced	Notice of	lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These	30° 23' 32"
Notice of Change	Change	relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes	Lon:
		will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be	-081° 29'
		relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.	30"
Sector Jacksonville, Submerged Land Act	Advanced	Training Wall RFL (LLNR 7295) will be relocated to approximate position: 30-23-48.120N/081-28-41.707W to align with the newly	Lat:
(SLA) - St Johns River/ATON/Advanced	Notice of	dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be	30° 23' 47"
Notice of Change	Change	permanently discontinued.	Lon: -081° 28' 39"
Sector Jacksonville, Submerged Land Act	Advanced	Training Wall RRL (LLNR 7300) will be relocated to approximate position: 30-23-57.479N/081-28-54.848W to align with the newly	Lat:
(SLA) - St Johns River/ATON/Advanced	Notice of	dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be	30° 23' 58"
Notice of Change	Change	permanently discontinued.	Lon:
			-081° 28'
			55"

Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Public Notice	Bridges	Bridge - Browns Creek The Coast Guard has published a public notice after having received a bridge permit application from Florida Department of Transportation. The applicant is requesting approval of the location and plans for the replacement of SR105/Heckscher Drive Bridge across Browns Creek, Jacksonville, Duval County, FL. Public Notice 02-25 outlines the proposed bridge project and	Lat: 30° 25' 03" Lon: -081° 31' 52"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Construction	Bridges	Construction has begun on a new high-level fixed bridge and will continue until an estimated completion date of September 1, 2030. The new bridge will consist of a vertical clearance of 65 feet and a 150-Ft. horizontal clearance at the navigation channel. Construction will require the use of material storage barges and barge-mounted cranes; all in-water equipment is required to be lighted at night.	-081° 37' 08"

St Joseph Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Joseph Sound Daybeacon 1	61850	STRUCT MISSING	FD
St Joseph Sound Daybeacon 9	61885	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 15	61970	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 21	62035	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 38	62275	STRUCT DEST/HAZ NAV/TRLB	FD
St Joseph Sound Light 39	62280	STRUCT DEST/TRLB	FD
St Joseph Sound Daybeacon 40	62285	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE		
Safety Harbor Marina Light 2	24375	DAYMK MISSING	PA		
Safety Harbor Marina Daybeacon 3	24380	DAYMK DMGD	PA		
Safety Harbor Marina Daybeacon 4	24385	DAYMK MISSING	PA		
Hurricane Pass Daybeacon 1	25975	DBD DEST	PA		
Hurricane Pass Daybeacon 2	25980	STRUCT DEST	PA		
Hurricane Pass Daybeacon 4	25990	DBD DEST	PA		
Hurricane Pass Daybeacon 5A	25997	STRUCT DEST	PA		
Hurricane Pass Daybeacon 7	26005	DBD DEST/STRUCT DMGD	PA		
Hurricane Pass Daybeacon 7A	26007	STRUCT DMGD	PA		
Caladesi Island Channel Daybeacon 7	61935	DAYMK MISSING	PA		

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph Sound/General/Bridges/Temp Deviation	Bridges	2025, to facilitate the DRC Sports Run 2025.	Lat: 28° 03' 04" Lon: -082° 47' 44"
Clearwater Harbor - St Joseph Sound/General/Bridges/Temp Deviation		until 1:30 a.m. on Friday, July 4, 2025, to facilitate the 46th Annual Kiwanis Midnight Run. Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 28° 03' 04" Lon: -082° 47' 44"

St Lucie Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Canal Daybeacon 40A	51140	STRUCT DEST/TRUB	FD

St Lucie Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Light 3	10000	STRUCT MISSING/TRLB	FD

NAME	LLNR	STATUS	AID TYPE
Southern Port Salerno Daybeacon 2	10177	STRUCT DEST	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Buoy 5	10125	RELOCATED FOR DREDGING	FD
St Lucie Inlet Buoy 6	10130	RELOCATED FOR DREDGING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Miami, Submerged	Marine	General/Marine Construction (Excluding Bridges)/Dredging 8156 From: 2024-12-30 To: 2025-05-23 Location: 27.16491° N / 80.16239° W	
Land Act (SLA) - St Lucie	Construction	27.16407° N / 80.16656° W 27.16384° N / 80.17274° W 27.16457° N / 80.17703° W 27.1643° N / 80.1705° W 27.1643° N / 80.17029° W 27.16491°	
Inlet/General/Marine	(Excluding	N / 80.16239° W Dredging operations have been completed. Demobilization will be conducted until approximately 23 May 2025. Equipment and	
Construction (Excluding	Bridges)	pipeline rafts will be anchored along the right descending (south) bank of St. Lucie Inlet between St Lucie Inlet Light 9 (LLNR 10145) and St Lucie	
Bridges)/Dredging		Inlet Daybeacon 17 (LLNR 10170). Dredge pipeline and equipment will have all required lighting for night anchorage. The Staging Area will be	
		bound by following approximate positions: 27-09-51.663N / 80-09-55.501W 27-09-47.544N / 80-10-07.995W 27-09-46.661N / 80-10-23.686W	
		27-09-51.955N / 80-10-23.983W 27-09-51.642N / 80-10-06.473W 27-09-53.551N / 80-09-55.433W The staging area will be utilized for the	
		duration of the project. Operations will continue on a twenty-four (24) hours per day, seven days per week basis. Vessels, pipelines, and	
		equipment will have all required Coast Guard lighting for night operations. On-scene vessels will monitor marine VHF-FM channels 13 and 16.	
		Mariners are urged to use extreme caution and transit the area at their slowest safe speed to create minimum wake after passing arrangements	
		have been made.	

St Lucie River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River Daybeacon 5	50675	STRUCT DEST/TRUB	FD
St Lucie River Daybeacon 12A	50725.5	STRUCT DEST	FD
St Lucie River Light 13	50730	STRUCT DMGD/TRLB	FD
St Lucie River Light 17	50750	DBD DMGD	FD
St Lucie River Daybeacon 22A	50780	STRUCT DEST/TRUB	FD
St Lucie River Light 23A	50835	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Point Access Channel Daybeacon 1	50641	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 2	50677.1	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 10	50677.5	STRUCT DEST	PA
Manatee Pocket Channel North Extension Daybeacon 5	50678.200000000004	STRUCT DEST	PA
St. Lucie River Stuart Ext Daybeacon 1	50838	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Lucie Inlet - St Lucie River/ATON/Advanced Notice of Change		Woods Point Daybeacon 1 (LLNR 50760) will be changed to Woods Point Buoy 1 (LLNR 50760). This change will give mariners a more reliable signal when transiting this channel.	Lat: 27° 12' 18" Lon: -080° 12' 47"
St Lucie Inlet - St Lucie River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2024-12-31 To: 2025-06-01 Location: 27.20368° N / 80.26011° W Bridge Name: Florida East Coast Railroad Bridge The Temporary Interim Rule (TIR) has been extended through May 31, 2025. The railroad bridge will operate in accordance with 33 CFR 117.317(k).	Lat: 27° 12' 13" Lon: -080° 15' 36"

St Lucie River North Fork

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (North Fork) Daybeacon 7	50885	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Seagate Harbor Daybeacon 1	50861	STRUCT DEST/HAZ NAV	PA
St. Lucie River (North Fork) Daybeacon 11	50905	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Lucie River - St Lucie River North	Bridges	General/Bridges/Rehabilitation From: 2024-11-22 To: 2025-11-30 Location: 27.27175° N / 80.32449° W Bridge Name: Port St Lucie	Lat:
Fork/General/Bridges/Rehabilitation		Boulevard Bridge - Long Creek Seacoast Inc. will be conducting repairs on the bridges across Long Creek. The improvements under this	27° 16' 18"
		contract consist of structures, riprap, bedding stone, earthwork (excavation), clearing and grubbing, MOT, environmental protections,	Lon:
		and monitor existing structures along State Road 716 at Long Creek. In-water equipment will be present, the waterway will not be fully	-080° 19'
		obstructed at any time.	28"

St Lucie River - St Lucie River North Fork/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-22 To: 2025-11-30 Location: 27.27173° N / 80.32221° W Bridge Name: Port St Lucie Boulevard Bridge - North Fork St Lucie River Seacoast Inc. will be conducting repairs on the bridges across North Fork St Lucie River. The improvements under this contract consist of structures, riprap, bedding stone, earthwork (excavation), clearing and grubbing, MOT, environmental protections, and monitor existing structures along State Road 716 at North Fork St Lucie River. In-water equipment will be present, the waterway will not be fully obstructed at any time.	Lat: 27° 16' 18" Lon: -080° 19' 20"
St Lucie River - St Lucie River North Fork/ATON/Proposed Notice of Change	'	ATON/Proposed Notice of Change Location: 27.20914° N / 80.26947° W Aid Name: St Lucie River (North Fork) Daybeacon 5 LLNR: 50855 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard is proposing to make the following change in the St. Lucie River. St. Lucie River N. Fork DBN 5 (LLNR 50855) will be changed to St. Lucie River N. Fork LT 5, using the same LLNR. This aid is currently located near a bend on the St Lucie River (North Fork) and unlighted. Given the turn for the channel it is best to install a light on the aid to provide a better signal during nighttime hours. There are currently no lighted aids in the immediate area. Lighting this aid would keep the maritime community safer and assist with navigation while transiting the river. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or Andrew.m.engle@uscg.mil with St. Lucie River N. Fork LT 5 as the subject line. Comments can also be mailed to: Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by June 11, 2025.	Lat: 27° 12' 33" Lon: -080° 16' 10"

St Lucie River South Fork

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (South Fork) Daybeacon 24	51000	STRUCT DEST/TRUB	FD
St Lucie River (South Fork) Daybeacon 25A	51010	STRUCT DEST	FD

St Marys Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Marys South Jetty Buoy B	6615	MISSING	FD
St Marys North Jetty Buoy C	6620	MISSING	FD
St Marys South Jetty Buoy D	6625	OFF STATION	FD
St Marys Daybeacon N	6680	STRUCT DEST/HAZ NAV	FD

St Marys River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Marys River Daybeacon 8	6810	STRUCT DEST	FD

St Petersburg Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Petersburg Channel Light 7	24980	STRUCT DEST	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St Petersburg Mole Light A	25005	RELIGHTED	FD	2025-05-01

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snell Isle Daybeacon 4	25020.2	STRUCT DEST/HAZ NAV	PA
Snell Isle Daybeacon 5	25020.3	STRUCT DEST	PA
Coffee Pot Bayou Daybeacon 1	25021	STRUCT DEST	PA

St Petersburg Yacht Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Petersburg Yacht Basin Light 1	25015	STRUCT DMGD/TRLB	FD
St Petersburg Yacht Basin Light 2	25020	TRLB/STRUCT DEST	FD
St Petersburg Yacht Basin Light 2	25020	STRUCT DEST/TRLB	FD

NAME	LLNR	STATUS	AID TYPE
St. Petersburg Mooring Field Buoy B	25009.100000000002	MISSING	PA
St. Petersburg Mooring Field Buoy C	25009.2	MISSING	PA

St Simons Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Simons Sound Entrance Lighted Buoy 6	6060	SINKING/TRLB	FD
Plantation Creek Range Rear Light	6135	STRUCT DEST	FD
Cedar Hammock Outbound Range Front Light	6205	STRUCT DMGD/TRLT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Advanced Notice of Change	of Change	Cedar Hammock RFL (LLNR 6195) will be permanently relocated to approximate position 32-06-02.513N/081-27-57.935W. The RFL will be changed to a day/night optic and continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RFL Passing LT (LLNR 6195.1) will be permanently established to display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM.	Lat: 31° 06' 01" Lon: -081° 28' 05"
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Advanced Notice of Change	Advanced Notice of Change	Cedar Hammock RRL (LLNR 6200) will be permanently relocated to approximate position 31-05-58.956N/081-28-13.677W. The RRL will be changed to a day/night optic and continuing to display an Iso G 6s flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RRL Passing Light (LLNR 6200.1) will be permanently established by mounting (2) optics located on the NW and SE corners of the platform for Cedar Hammock RRL (LLNR 6200). The (2) optics will be synchronized and display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM. Due to the current location of Cedar Hammock RRL (LLNR 6200) being inaccessible for a CG asset to effectively repair the structure, it was determined by relocating both range structures it will not only offer an excellent range quality index for all mariners but be accessible to all CG assets to provide consistent maintenance to both structures.	Lat: 31° 05' 50" Lon: -081° 28' 52"

Steinhatchee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Steinhatchee River Light 9	30480	DBD DEST/STRUCT DEST/TRLB/HAZ NAV	FD
Steinhatchee River Daybeacon 14	30490.5	HAZ NAV/STRUCT DEST/TRLB	FD
Steinhatchee River Daybeacon 34	30570	STRUCT MISSING/HAZ NAV/TRLB	FD
Steinhatchee River Daybeacon 48	30580.9	STRUCT DEST/TRUB	FD

Stono River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stono River Daybeacon 20	34640	STRUCT DEST/HAZ NAV/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Stono River Buoy 40	34733	RESET ON STATION	FD	2025-05-01

Stranahan River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stranahan River Daybeacon 25	47410	STRUCT DMGD	FD

Sunset Harbour Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Flagler Monument Daybeacon 2	48145	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunset Harbour Channel Light 8	48110	LT EXT	PA

Sunshine Skyway Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunshine Skyway Channel Daybeacon 2	60320	STRUCT MISSING	FD
Sunshine Skyway Channel Daybeacon 22	60415	STRUCT DEST/TRUB	FD
Sunshine Skyway Channel Daybeacon 23	60420	STRUCT DEST/TRUB	FD

Suwannee Sound South Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Suwannee Sound South Entrance Daybeacon 2	30015	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 7	30030	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 11	30040	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 15	30050	STRUCT MISSING	FD

Tamp Bay Cut C Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut C Channel Outbound Range Front Light	22580	TRLT	FD
Tampa Bay Cut C Channel Outbound Range Rear Light	22585	TRLT	FD

Tampa Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cockroach Bay Channel Daybeacon 2	22635	HAZ NAV/DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 8	22665	DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 11	22680	DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 15	22696	STRUCT DEST	PA
Little Harbor Channel Daybeacon 4	24505	STRUCT DEST	PA
Little Harbor Channel Daybeacon 7	24515	STRUCT DEST	PA
Little Harbor Marina Daybeacon 3	24570	STRUCT DEST	PA
ittle Harbor Marina Daybeacon 6	24585	HAZ NAV/DAYMK MISSING	PA
Simmons Park Channel Daybeacon 3	24606.2	HAZ NAV/DAYMK MISSING	PA
Simmons Park Channel Daybeacon 4	24606.3	STRUCT DEST/HAZ NAV	PA
Simmons Park Channel Daybeacon 13	24607.2	STRUCT DEST	PA
Apollo Beach Daybeacon 4	24625	DAYMK DMGD	PA
Apollo Beach Daybeacon 9	24643	STRUCT DEST	PA
Harbor Channel Daybeacon 3	24663.2	STRUCT DEST	PA

Tampa Bay Cut B Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut B Channel Inbound Range Rear Light	22485	STRUCT DEST/HAZ NAV/TRLT	FD

Tampa Bay Cut D Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut D Channel Outbound Range Rear Light	22715	LT EXT	FD
Tampa Bay Cut D Channel Outbound Range Rear Passing Light	22715.100000000002	STRUCT DEST	FD

Tampa Bay Cut E Channel

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut E Channel Inbound Range Rear Light	22765	STRUCT DEST/HAZ NAV/TRLB	FD
Tampa Bay Cut E Channel Inbound Range Rear Light Passing Light	22765.5	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Yacht Basin Daybeacon 2	22786	STRUCT DEST	PA

Tampa Bay Cut F Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut F Channel Outbound Range Rear Passing Light	22803	LT IMCH	FD

https://www.navcen.uscg.gov/msi 60/71

Tampa Bay Cut F Inbound Range Rear Passing Light 22815.2 LT EXT FD

Tampa Bay Cut J Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut J Channel Outbound Range Front Light	23720	HAZ NAV/STRUCT DEST/TRLT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut J Channel Outbound Range Rear Light	23725	RELIGHTED	FD	2025-05-08

Tampa Bay Cut J-2 Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut J-2 Channel Outbound Range Front Light	23765	RELIGHTED	FD	2025-05-01
Tampa Bay Cut J-2 Channel Outbound Range Rear Light	23770	RELIGHTED	FD	2025-05-01

Taylor Creek Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Channel Daybeacon 3	45100	STRUCT DEST	FD

Terminal Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jacksonville Shipyards Pier 6 Light	7655	LT EXT	PA

The Bight Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Bight Channel Light 44	4920	STRUCT MISSING/TRLB	FD

Titusville Yacht Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Titusville Yacht Basin Daybeacon 1	41210	STRUCT DEST/TRUB	FD
Titusville Yacht Basin Daybeacon 3	41220	STRUCT DEST/TRUB	FD

Tolomato River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tolomato River Light 9	38645	STRUCT DEST/HAZ NAV/TRLB	FD
Tolomato River Light 36	38760	DAYMK MISSING	FD
Tolomato River Light 44	38790	STRUCT MISSING/TRLB	FD
Tolomato River Light 45	38800	STRUCT DEST/TRLB	FD
Tolomato River Light 57A	38885	STRUCT DEST	FD
Tolomato River Lighted Buoy 59	38905.5	MISSING	FD

Federal Discrepancies Corrected

-				
NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tolomato River Light 35	38755	WATCHING PROPERLY	FD	2025-04-30
Tolomato River Light 38	38770	WATCHING PROPERLY	FD	2025-04-30

Treasure Island

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE

Treasure Island Light 3	61050	HAZ NAV/STRUCT DEST/TRLB	FD
Treasure Island Light 9	61070	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jungle Beach Daybeacon 2	61170	STRUCT DEST/HAZ NAV/DAYMK MISSING	PA
Jungle Beach Daybeacon 4	61180	DAYMK DMGD	PA
Jungle Beach Daybeacon 11	61215	STRUCT DEST	PA

Trout River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Trout River Daybeacon 2	7550	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Maxwell Boat Ramp Channel Daybeacon 5	7557.900000000001	STRUCT DEST	PA
Ribault River Channel Lighted Buoy 1	7559	MISSING/HAZ NAV	PA
Ribault River Channel Lighted Buoy 3	7559.150000000001	ADRIFT	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Trout River Cut Lighted Buoy 63	7540	RELOCATED FOR DREDGING	FD

Turtle River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turtle River Lighted Buoy 2A	6322	LT EXT	FD
Turtle River Light 4	6325	STRUCT DEST/TRLB	FD
Turtle River Daybeacon 10	6385	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hermitage Island Plant Outfall Obstruction Light	6395	STRUCT DEST	PA

Umbrella Creek

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Umbrella Creek Daybeacon A9	37440	DAYMK MISSING	FD

<u>Unknown</u>

NAME	LLNR	STATUS	AID TYPE
Haig Point Light	4370	LT IMCH	PA
Big Sarasota Pass Buoy 7	21500.7	MISSING	PA
Plymouth Harbor East Obstruction Daybeacon	21547	STRUCT DEST/HAZ NAV	PA
Plymouth Harbor West Obstruction Daybeacon	21547.100000000002	STRUCT DEST/HAZ NAV	PA
South Lido North Obstruction Daybeacon	21555.100000000002	STRUCT DEST/HAZ NAV	PA
South Lido South Obstruction Daybeacon	21555.2	STRUCT DEST/HAZ NAV	PA
Baynard Cove Creek Daybeacon 2	4355	STRUCT DEST	PA
Sebastian Inlet Channel Daybeacon 1A	9730	STRUCT DEST	PA
Sebastian Inlet Channel Daybeacon 5	9750	STRUCT DEST	PA
Sebastian Inlet Channel Daybeacon 10	9775	HAZ NAV/DAYMK MISSING	PA
Sebastian Inlet Channel Daybeacon 17	9810	DAYMK MISSING	PA
Sebastian Inlet Channel Daybeacon 25	9810.9	DBD DEST	PA
Sebastian Inlet Channel Daybeacon 28	9812.2	STRUCT DEST/HAZ NAV	PA
Fisher Island Marina Channel North Obstruction Daybeacon	10605	DAYMK MISSING	PA
Fisher Island Breakwater East Obstruction Daybeacon	10650	DAYMK MISSING	PA
Msrc Boundary Shoal Daybeacon	10735	DAYMK MISSING	PA
Ohio Key Channel Daybeacon 4	12595	STRUCT DEST/HAZ NAV	PA
Stump Pass Marina Daybeacon 2	21390	STRUCT DEST/HAZ NAV	PA

/ 13/25, 12.30 PW	Manume Salety Information	on Products Navigation Center	
Stump Pass Marina Daybeacon 3	21395	STRUCT DEST/HAZ NAV	PA
Stump Pass Marina Daybeacon 4	21400	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 8	21500.8	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 11	21510	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 11A	21510.5	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 13	21515	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 15	21525	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 16	21570	STRUCT DEST	PA
North Siesta Key Daybeacon 1	21570.10000000002	STRUCT DEST	PA
North Siesta Key Daybeacon 9	21570.5	STRUCT DEST	PA
North Siesta Key Daybeacon 11	21570.60000000002	STRUCT MISSING	PA
Big Sarasota Pass Daybeacon 18	21577	STRUCT DEST/HAZ NAV	PA
Country Club Shores Daybeacon 2	21660	DAYMK MISSING	PA
Country Club Shores Daybeacon 4	21665	DAYMK DMGD	PA
MacDill Marina Channel Daybeacon 2	22975	STRUCT DEST	PA
Point Pinellas Daybeacon 1	24740	HAZ NAV/STRUCT DMGD	PA
Point Pinellas Daybeacon 3	24745	STRUCT DEST/HAZ NAV	PA
Isleta Marina Pier A Light	31240	LT EXT	PA
-	31245	LT EXT	PA PA
Isleta Marina Pier B Light			
Isleta Marina Pier C Light	31250	LT EXT	PA PA
Puerto Yabucoa Channel Range Front Light	31745	LT EXT/STRUCT DMGD	PA PA
Puerto Yabucoa Channel Range Rear Light	31750	LT EXT/STRUCT DMGD	PA
Las Mareas Range Front Light	31810	LT EXT	PA
Las Mareas Range Rear Light	31815	LT EXT	PA
Las Mareas Lighted Buoy 1	31820	OFF STA/LT EXT	PA
Las Mareas Lighted Buoy 2	31825	MISSING	PA
Las Mareas Light 4	31835	LT EXT	PA
Las Mareas Articulated Light 5	31840	LT EXT	PA
Las Mareas Light 6	31845	LT EXT	PA
Las Mareas Pier Light (3)	31850	LT EXT	PA
Water Island Channel Lighted Buoy 3	32626.2	LT EXT	PA
Marsh Harbor Marina Daybeacon 3	35420	DAYMK MISSING	PA
Marsh Harbor Marina Daybeacon 5	35430	DAYMK MISSING	PA
Fdot Villano Bridge South Breasting Light	38834	LT EXT	PA
Boat Works Channel Daybeacon 2	40135	DAYMK MISSING	PA
Boat Works Channel Daybeacon 3	40140	DAYMK MISSING	PA
Boat Works Channel Daybeacon 4	40145	DAYMK MISSING	PA
Boat Works Channel Daybeacon 5	40150	DAYMK MISSING	PA
Boat Works Channel Daybeacon 7	40160	DAYMK DMGD	PA
Boat Works Channel Daybeacon 9	40170	STRUCT DEST	PA
Matthews Marina Daybeacon 2	40255	STRUCT DEST	PA
Matthews Marina Daybeacon 3	40260	DAYMK IMCH	PA
Matthews Marina Daybeacon 5	40270	DAYMK MISSING	PA
Seven Seas Marina Daybeacon 11	40370		PA
•		DAYMK MISSING	
Harbor Towne Marina Daybeacon 2	41245	STRUCT DEST	PA PA
Harbor Towne Marina Daybeacon 4	41250	STRUCT DEST	PA PA
Harbor Towne Marina Daybeacon 9	41265	DAYMK MISSING	PA PA
Riverdeck Channel Daybeacon 1	41295	STRUCT DEST	PA
Riverdeck Channel Daybeacon 2	41300	STRUCT DEST	PA
Riverdeck Channel Daybeacon 3	41305	STRUCT DEST	PA
Riverdeck Channel Daybeacon 4	41310	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 1	41345	DAYMK MISSING	PA
Kennedy Yacht Club Channel Daybeacon 2	41350	DAYMK MISSING	PA
Kennedy Yacht Club Channel Daybeacon 3	41355	DAYMK IMCH	PA
Kennedy Yacht Club Channel Daybeacon 4	41360	DAYMK IMCH	PA
Kennedy Yacht Club Channel Daybeacon 5	41365	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 7	41375	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 8	41380	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 9	41385	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 10	41390	STRUCT DEST	PA
Orlando Utilities Comission Channel Buoy 2	41445	MISSING	PA
	41450	MISSING	PA
Oriando Utilities Comission Channel Bliov 4			1111
Orlando Utilities Comission Channel Buoy 4 Orlando Utilities Comission Channel Buoy 5	41455	MISSING	PA

https://www.navcen.uscg.gov/msi

63/71

/ 13/25, 12.30 PW	Mantime Salety informatio	in Products Navigation Center	
Orlando Utilities Comission Channel Buoy 7	41465	MISSING	PA
Orlando Utilities Comission Channel Buoy 8	41470	MISSING	PA
Indian Cove Marina Daybeacon 3	42140	DAYMK DMGD	PA
Indian Cove Marina Daybeacon 5	42150	DAYMK DMGD	PA
Indian Cove Marina Daybeacon 7	42160	DAYMK DMGD	PA
Jays Harbor Lights Marina Daybeacon 1	42205	HAZ NAV/DAYMK MISSING	PA
Jays Harbor Lights Marina Daybeacon 2	42210	HAZ NAV/DAYMK DMGD/STRUCT DMGD	PA
Jays Harbor Lights Marina Daybeacon 3	42215	DAYMK MISSING	PA
Jays Harbor Lights Marina Daybeacon 4	42220	HAZ NAV/DAYMK MISSING/STRUCT DMGD	PA
Diamond 99 Marina Daybeacon 1	42290	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 2	42295	DAYMK IMCH	PA
Diamond 99 Marina Daybeacon 3	42300	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 4	42305	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 5	42310	STRUCT DEST	PA
Diamond 99 Marina Daybeacon 6	42315	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 7	42320	DAYMK MISSING	PA
·	42325	STRUCT DEST	PA
Diamond 99 Marina Light 8			
Inlet Marina Daybeacon 1	43615	DAYMK MISSING	PA
Inlet Marina Daybeacon 2	43620	DAYMK MISSING	PA
Inlet Marina Daybeacon 4	43630	DAYMK MISSING	PA
Sembler Daybeacon 5	43655	DAYMK MISSING	PA
Channel 68 Marina Daybeacon 1 (Abandoned)	43685.1	STRUCT DEST/HAZ NAV	PA
Channel 68 Marina Daybeacon 2 (Abandoned)	43685.200000000004	STRUCT DEST	PA
Channel 68 Marina Daybeacon 6 (Abandoned)	43685.6	STRUCT DEST	PA
Loggerhead Marina Daybeacon 10	44015	DAYMK MISSING	PA
Village Marina Daybeacon 2	44985	STRUCT DEST	PA
Riverside Marina (Ft. Pierce) Daybeacon 1	45035	STRUCT DEST	PA
Riverside Marina(Ft. Pierce) Daybeacon 3	45045	STRUCT DEST	PA
Riverside Marina(Ft. Pierce) Daybeacon 4	45050	DAYMK IMCH	PA
Riverside Marina(Ft. Pierce) Daybeacon 5	45055	STRUCT DEST	PA
Riverside Marina(Ft. Pierce) Daybeacon 7	45065	DAYMK MISSING	PA
Riverside Marina(Ft. Pierce) Daybeacon 8	45070	DAYMK MISSING	PA
Faber Cove Daybeacon 3	45135	STRUCT DEST/HAZ NAV	PA
Faber Cove Daybeacon 10	45160	STRUCT MISSING	PA
Faber Cove Daybeacon 14	45185	STRUCT DEST	PA
Jensen Beach Channel Daybeacon 4	45495	STRUCT MISSING	PA
Jensen Beach Channel Daybeacon 5	45500	STRUCT MISSING	PA
Jensen Beach Channel Daybeacon 6	45505	STRUCT MISSING	PA
·	45980		PA
Miles Grant Daybeacon 2	45990	DAYMK IMCH DAYMK IMCH	PA
Miles Grant Daybeacon 4			
Miles Grant Daybeacon 6	45995	DAYMK IMCH	PA
New Port Cove Marine Ctr Daybeacon 2	46620	STRUCT DEST	PA
Old Slip Marina Daybeacon 4	46680	STRUCT DEST/HAZ NAV	PA
Manalapan Channel Buoy 1	47007	STRUCT DEST	PA
Manalapan Channel Daybeacon 2	47007.5	STRUCT DEST	PA
Manalapan Channel Buoy 2	47008	STRUCT DEST	PA
Manalapan Channel Daybeacon 3	47008.5	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 3	47050	MISSING	PA
Ocean Inlet Park Daybeacon 4	47055	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 5	47060	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 6	47065	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 7	47070	STRUCT DEST	PA
Ocean Inlet Park Daybeacon 8	47075	STRUCT DEST	PA
Williams Island Daybeacon 1	47645	STRUCT DEST	PA
Williams Island Daybeacon 3	47650	DAYMK MISSING/STRUCT DMGD	PA
Williams Island Daybeacon 4	47655	DAYMK IMCH/STRUCT DMGD	PA
Williams Island Daybeacon 5	47660	STRUCT DEST	PA
Williams Island Daybeacon 6	47665	STRUCT DEST	PA
Williams Island Light 1	47685	STRUCT DEST	PA
-			
Williams Island Light 2	47690 47737 1	STRUCT DEST	PA
Intracoastal Yacht Club Channel Daybeacon 7	47737.1	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 8	47737.2000000000004	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 9	47737.3	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 10	47737.4	DAYMK MISSING	PA

https://www.navcen.uscg.gov/msi 64/71

7 10/20, 12:00 I W	Manuffe Galety Information	Trioducis Navigation Ochici	
Intracoastal Yacht Club Channel Daybeacon 11	47737.5	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 12	47737.6	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 13	47737.700000000004	DAYMK MISSING	PA
Mariners Bay Daybeacon 1	47890	DAYMK DMGD/STRUCT DMGD	PA
Mariners Bay Daybeacon 3	47895	STRUCT DEST	PA
Mariners Bay Daybeacon 5	47900	DAYMK MISSING	PA
Jockey Club Marina Daybeacon 10	47953	DAYMK MISSING	PA
Jockey Club Marina Daybeacon 15	47960	STRUCT DEST	PA
Jockey Club Marina Daybeacon 17	47965	STRUCT DEST	PA
Mike Gordon Restaurant Daybeacon 1	48220	STRUCT DEST	PA
Mike Gordon Restaurant Daybeacon 2	48225	STRUCT DEST/HAZ NAV	PA
Mike Gordon Restaurant Daybeacon 3	48230	DAYMK MISSING	PA
-	48290	DAYMK MISSING DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 2			
Palm Bay Club Channel Daybeacon 4	48300	DAYMK MISSING	PA PA
Palm Bay Club Channel Daybeacon 5	48305	DAYMK IMCH	PA
Palm Bay Club Channel Daybeacon 6	48310	DAYMK DMGD	PA
Palm Bay Club Channel Daybeacon 7	48315	DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 8	48320	DAYMK MISSING	PA
Sea Isle Marina Daybeacon 1	48400	STRUCT DEST	PA
Sea Isle Marina Daybeacon 2	48405	STRUCT DEST	PA
Sea Isle Marina Daybeacon 3	48410	STRUCT DEST	PA
Sea Isle Marina Daybeacon 4	48415	STRUCT DEST	PA
Sea Isle Marina Daybeacon 5	48420	STRUCT DEST	PA
Sea Isle Marina Daybeacon 6	48425	STRUCT DEST	PA
Sea Isle Marina Daybeacon 7	48430	STRUCT DEST	PA
Deering Channel Daybeacon 1	48610	STRUCT DEST	PA
Deering Channel Light 2	48615	HAZ NAV/DAYMK MISSING	PA
Deering Channel Daybeacon 3	48620	DAYMK MISSING	PA
Deering Channel Daybeacon 4	48625	DAYMK MISSING	PA
Deering Channel Daybeacon 5	48630	HAZ NAV/DAYMK MISSING	PA
Deering Channel Daybeacon 6	48635	HAZ NAV/DAYMK MISSING	PA
Deering Channel Daybeacon 7	48640	DAYMK MISSING	PA
			PA
Deering Channel Daybeacon 8	48645	DAYMK MISSING	
Deering Channel Daybeacon 9	48650	HAZ NAV/DAYMK MISSING	PA
Grove Island Channel Daybeacon 1A	48665	STRUCT DEST	PA
Grove Island Channel Daybeacon 2	48670	STRUCT DEST	PA
Grove Island Channel Light 9	48705	LT EXT	PA
Grove Island Channel Light 10	48710	LT EXT	PA
Grove Island Channel Light 18	48745	LT EXT	PA
L'Hermitage Light 1	48750	DAYMK MISSING	PA
L'Hermitage Light 2	48755	DAYMK MISSING	PA
L'Hermitage Daybeacon 4	48765	DAYMK MISSING	PA
Crandon Park Marina Channel Light 14	48845	STRUCT DEST/HAZ NAV/TRLB	PA
John A Brennan Channel Daybeacon 2	48985	STRUCT DEST/HAZ NAV	PA
John A Brennan Channel Light 13	49040	LT EXT	PA
Dinner Key Mooring Field 4 Lighted Buoy AA	49051	STRUCT DEST	PA
Dinner Key Mooring Field 4 Buoy CC	49051.200000000004	MISSING	PA
Dinner Key Mooring Field 4 Buoy HH	49051.700000000004	MISSING	PA
Dinner Key Mooring Field 4 Lighted Buoy II	49051.8	MISSING	PA
Island E Channel Daybeacon 2	49055.1	STRUCT DEST	PA
Island E Channel Daybeacon 8	49055.70000000004	STRUCT DEST	PA
Island E Channel Daybeacon 12	49056	STRUCT DEST	PA
·	49100		PA
Four Way Entrance Channel Daybeacon 4		DAYMK MISSING	
Middle Ground Obstruction Buoy	49105	MISSING	PA PA
Four Way Channel Daybeacon 1	49150	DAYMK MISSING	PA PA
Four Way Channel Daybeacon 2	49155	DAYMK MISSING	PA
Anchorage Channel Daybeacon 2	49215	DAYMK IMCH	PA
Anchorage Channel Daybeacon 4	49220	DAYMK MISSING	PA
Deering Bay Channel Daybeacon 4	49585	STRUCT DEST/HAZ NAV	PA
Deering Bay Channel Daybeacon 6	49595	STRUCT MISSING	PA
Convoy Point Light 1	49865	LT EXT/STRUCT DMGD	PA
Convoy Point Light 2	49870	LT EXT	PA
Turkey Point Channel Buoy 3	49960	MISSING	PA
Turkey Point Channel Buoy 4A	49975	MISSING	PA
·			

https://www.navcen.uscg.gov/msi 65/71

713/23, 12.30 1 W	Maname Carety Information	Trioddets Navigation Center	
Turkey Point Channel Buoy 6	49985	OFF STA	PA
Turkey Point Channel Buoy 7	49990	OFF STA	PA
Turkey Point Channel Buoy 11	50010	OFF STA	PA
Turkey Point Channel Buoy 21	50060	MISSING	PA
Turkey Point Channel Buoy 23	50070	MISSING	PA
Turkey Point Channel Buoy 24	50075	MISSING	PA
Community Harbor Daybeacon 6	50535.4	DAYMK MISSING	PA -
Royal Palm Yacht Club Channel Daybeacon 1	52785	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 2	52790	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 3	52795	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 4	52800	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 4	52800	STRUCT DEST	PA
Royal Palm Yacht Club Channel Daybeacon 5	52805	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 6	52810	DBD DEST	PA
Paradise Yacht Club Daybeacon 5	52930	DAYMK MISSING	PA
Paradise Yacht Club Daybeacon 9	52950	DAYMK IMCH/STRUCT DMGD	PA
-			
Paradise Yacht Club Daybeacon 11	52960	DAYMK MISSING	PA
Paradise Yacht Club Daybeacon 12	52965	HAZ NAV/DAYMK MISSING	PA
Whiskey Creek Channel Daybeacon 3	53370	HAZ NAV/STRUCT DEST	PA
Caloosa Yacht Club Channel Daybeacon 1	53475	DAYMK MISSING	PA
McGregor Isles Daybeacon 13	53511	STRUCT DEST	PA
McGregor Isles Daybeacon 15	53515	STRUCT DEST	PA
McGregor Isles Daybeacon 17	53520	STRUCT DEST	PA
Riverside Marina(Ft. Myers) Daybeacon 3	53685	DAYMK MISSING	PA
	53755	DAYMK MISSING	PA
Landings Marina Daybeacon 6			
Cabbage Key Channel Daybeacon 6	56060	HAZ NAV/STRUCT DEST	PA
Fishery Restaurant Channel Daybeacon 3	56665	STRUCT DEST/HAZ NAV	PA
Uncle Henry's Marina Daybeacon 2	56785	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 3	56790	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 5	56800	STRUCT DEST/HAZ NAV	PA
Uncle Henry's Marina Daybeacon 7	56805	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 11	56825	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 12	56830	STRUCT DEST/HAZ NAV	PA
	56835		PA
Uncle Henry's Marina Daybeacon 13		STRUCT DEST/HAZ NAV	
Uncle Henry's Marina Daybeacon 15	56845	DAYMK MISSING/STRUCT DMGD	PA
Uncle Henry's Marina Daybeacon 16	56850	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 24	56890	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 27	56905	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 30	56920	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 31	56925	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 35	56945	STRUCT DMGD	PA
Uncle Henry'S Marina Daybeacon 36	56950	DAYMK MISSING	PA
	56955		PA
Uncle Henry's Marina Daybeacon 37		DAYMK MISSING	
Uncle Henry's Marina Daybeacon 40	56970	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 41	56975	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 42	56980	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 43	56985	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 47	57005	STRUCT DEST	PA
Englewood Channel Daybeacon 22	57359.13000000005	STRUCT DEST	PA
Englewood Channel Daybeacon 8	57359.5	STRUCT DEST	PA
Englewood Channel Daybeacon 10	57359.6	STRUCT DEST	PA
	57380		PA
Bayview Channel Daybeacon 3		DAYMK DMGD	
Bayview Channel Daybeacon 4	57385	STRUCT DEST	PA
Bayview Channel Daybeacon 6	57395	STRUCT DEST	PA
Bayview Channel Daybeacon 8	57405	STRUCT DEST	PA
Bayview Channel Daybeacon 9	57410	DAYMK MISSING	PA
Bayview Channel Daybeacon 10	57415	STRUCT DEST	PA
Bay Heights Daybeacon 1	57418	DAYMK MISSING	PA
Bay Heights Daybeacon 2	57418.1	DAYMK MISSING	PA
Venice Yacht Club Obstruction Light A	57779	STRUCT DEST	PA
Blackburn Point Channel Daybeacon 1	58101	DAYMK MISSING	PA PA
Blackburn Point Channel Daybeacon 2	58102	DAYMK MISSING	PA
San Remo Daybeacon 1	58446	STRUCT DEST	PA
San Remo Daybeacon 2	58447	STRUCT DEST	PA

https://www.navcen.uscg.gov/msi 66/71

Seminant Publishers Seminant Publishers	5/10/20, 12.00 1 W	Manume Galety Information i	Toddots Navigation Center	
Sim Brown Displaces (1) 54400 TRILITY DET (15T) A Sim Brown Displaces (1) 54401 STREET DET (15T) A Sim Brown Displaces (1) 54401 STREET DET (15T) ANN A Hallam Brown Such Discount On Operation (1) 54401 STREET DET (15T) ANN A Hallam Brown Displaces (1) 44901 STREET DES (15T) ANN ANN ANN ANN ANN ANN ANN ANN ANN AN	San Remo Daybeacon 2	58447	DAYMK IMCH	PA
Sam Perm Dephasers 58489 SINUS DIST N Sam Perm Dephasers 58481 SINUS COST/ALE ZWW A Sam Perm Dephasers 58481 SINUS COST/ALE ZWW A Sam Perm Dephasers 58481 SINUS COST/ALE ZWW A Hubbur Republishers 58481 SINUS COST/ALE ZWW A Hubbur Republishers 58481 SINUS COST/ALE ZWW A Bird Say Commod Dephasers 58481 Commod Misson A Bird Say Commod Dephasers 58481 Commod Misson A Gausser, Sail Squad Re Bury 58481 Misson Misson A Gausser, Sail Squad Re Bury 58488 Misson Misson A Gausser, Sail Squad Re Bury 58488 Misson Misson A Gausser, Sail Squad Re Bury 58488 Misson Misson A Gausser, Sail Squad Re Bury 58488 Misson Misson A Gausser, Sail Squad Re Bury 58488 Misson Misson A Gausser,	San Remo Daybeacon 3	58448	STRUCT DEST	PA
Sim Permi Anthro Claricoccian Displaces on Substantian Comment Control Control Displaces on Substantian Control Control Control Displaces on Substantian Control Contro	San Remo Daybeacon 5	58449	STRUCT DEST	PA
Sin Alerson Signal Explosioned Sin Alerson Signal Explosioned Name Allaction Signal Explosioned 5888.3 STRUCT MISSING IN Allaction Signal Explosioned 5888.3 STRUCT MISSING IN Bill Key Channel Degisteria 2 5810.0 DOWNK MISSING IN Bill Key Channel Degisteria 7 5820.0 DOWNK MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN School Sall Stand R Box PA 5830.0 MISSING IN Sc	San Remo Daybeacon 5	58449	STRUCT DEST	PA
Histon Repo. Oxylescen	San Remo North Obstruction Daybeacon	58449.1	STRUCT DEST/HAZ NAV	PA
Neson Septimen	San Remo South Obstruction Daybeacon	58449.20000000004	STRUCT DEST/HAZ NAV	PA
MISH NOT AMERICAN MISH	Hudson Bayou Daybeacon 1	58485.1	DAYMK IMCH	PA
MANE MERSONS PA MINESTRATE PA MINESTRA	Hudson Bayou Daybeacon 3	58485.3	STRUCT MISSING	PA
Bill for Cynamic Displacen 3 S815 DAMME MISSING MR Samed Sai Spaad Re Busy A \$880 MSSNIG 76 Samed Sai Spaad Re Busy A \$880 MSSNIG 76 Samed Sai Spaad Re Busy C \$880 MSSNIG 76 Samed Sai Spaad Re Busy C \$880 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 76 Samed Sai Spaad Re Busy E \$890 MSSNIG 78 </td <td></td> <td>58510</td> <td>DAYMK MISSING</td> <td>PA</td>		58510	DAYMK MISSING	PA
Bill Mey Church Depleacent 7				PA
Saments Saff Squart Re flavy A SMEDIC MISSING R Saments Saff Squart Re flavy C 55500 MISSING R Saments Saff Squart Re flavy C 55500 MISSING R Saments Saff Squart Re flavy F 55600 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Saments Saff Squart Re flavy F 5860 MISSING R Instruction Saff Squart Re flavy F 5860 MISSING R Instruction Saff Squart Re flavy F 5860 MISSING R Instruction Saff Squart Re flavy F 5860 MISSING R Instruction Saff Squart Re flavy F 5860 MISSING R Instruc	Bird Kev Channel Davbeacon 7	58525	DAYMK MISSING	PA
Sames San Bilgwald Ric Bury C 5860 MISSING PA Sames San Bilgwald Ric Bury C 5890 MISSING PA Sames San Bilgwald Ric Bury C 5895 MISSING PA Sames San Bilgwald Ric Bury P 5890 MISSING PA Sames San Bilgwald Ric Bury P 5800 MISSING PA Sames San Bilgwald Ric Bury P 5800 MISSING PA Sames San Bilgwald Ric Bury P 5800 MISSING PA Sames San Singwald Ric Bury P 5800 MISSING PA Sames San Singwald Ric Bury P 5800 MISSING PA Bay John Scholl Charmed Depleason I 5800 OWMM MISSING PA Bay John Scholl Charmed Depleason I 5800 OWMM MISSING PA Bay John Scholl Charmed Depleason I 5805 Demonstration Missing PA Bay John Scholl Charmed Depleason I 5805 Demonstration Missing PA Bay John Scholl Charmed Depleason I 5800 Demonstration Missing PA Bay John Scholl Charmed Depleason I 5800 Demo				
Samestern Salf Squard Ke Bury C 58600 MSSING PA Samestern Salf Squard Ke Bury E 58600 MSSING PA Samester Salf Squard Ke Bury E 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 MSSING PA Samester Salf Squard Ke Bury F 58600 DAYMON MSSING PA Samester Salf Squard Ke Bury F 58600 DAYMON MSSING PA Barterin Salf Squard Ke Bury F 58600 DAYMON MSSING PA				
Sameton Sulfgrand Re Busy 1 56495 MSSNNG PA Sameton Sulfgrand Re Busy 2 56605 MISSNNG PA Sameton Sulf Squard Re Busy 2 56605 MISSNNG PA Sameton Sulf Squard Re Busy 2 38815 MISSNNG PA Sameton Sulf Squard Re Busy 3 38802 MISSNNG PA Sameton Sulf Squard Re Busy 3 38802 MISSNNG PA Sameton Sulf Squard Re Busy 4 38802 MISSNNG PA Sameton Sulf Squard Re Busy 4 38802 MISSNNG PA Sameton Sulf Squard Re Busy 4 38802 DMNK DMIGO PA Say Isals Sauch Charmed Dipheson 1 38802 DMNK MISSNNG PA Say Isals Sauch Charmed Dipheson 8 38803 DMNK MISSNNG PA Burbonous Charmed Dipheson 9 38803 DMNK MISSNNG PA Burbonous Charmed Dipheson 13 38806 STRUCT DISTINAZ NAW PA Burbonous Charmed Dipheson 13 38916 DMNK MISSNNG PA Burbonous Charmed Dipheson 25 39805 DMNK MISSNNG PA				
Samotto Safi Squard Re Bury F 58000 MSSINC PA Samotto Safi Squard Re Bury F 6800 MSSINCS PA Samotto Safi Squard Re Bury F 5815 MSSINCS PA Samotto Safi Squard Re Bury F 58620 MSSINCS PA Samotto Safi Squard Re Bury S 58600 MSSINCS PA Samotto Safi Squard Re Bury S 58600 MSSINCS PA Samotto Safi Squard Re Bury S 58600 MSSINCS PA Samotto Safi Squard Re Bury S 58600 MSSINCS PA Samotto Safi Squard Re Bury S 58600 DAMM MSSINCS PA Bay Inter Scant Chamed Depleaces of G 5865 DAMM MSSINCS PA Bay Inter Scant Chamed Depleaces of G 5868 Inter Many Demonstration MSSINCS PA Buthomore All Saficial Chamed Depleaces of G 58600 DAMM MSSINCS PA Buthomore All Saficial Chamed Depleaces of G 58600 DAMM MSSINCS PA Buthomore All Saficial Chamed Depleaces of G 58600 DAMM MSSINCS PA Buthomore All Saficial Chamed Depleaces o				
Saraton Sail Squad Re Buoy F 58605 MISSING PA Screents Sail Squad Re Buoy I 58615 MISSING PA Screents Sail Squad Re Buoy I 58625 MISSING PA Screents Sail Squad Re Buoy I 58625 MISSING PA Saraton Sail Squad Re Buoy I 58626 MISSING PA Bay Intersouth Charmel Depletecen I 58620 DAYME MORD PA Bay Intersouth Charmel Depletecen I 58620 DAYME MORD PA Bay Intersouth Charmel Depletecen I 58625 DAYME MUSTING PA Longboar Key Moorings Light I 58600 STRUCT DEST/MAZ NOV PA Butterwoord Materia Charmel Depletecen I 58600 STRUCT DEST/MAZ NOV PA Butterwoord Materia Charmel Depletecen I 58900 STRUCT DEST/MAZ NOV PA Butterwoord Materia Charmel Depletecen I 58910 DAYME MUSTING PA Butterwoord Materia Charmel Depletecen I 58920 DAYME MUSTING PA Butterwoord Materia Depletecen I 59920 DAYME MUSTING PA Butterwoord Materi				
Sacasta Sail Squad Re Buoy H 58015 MISSING PA Sacasta Sail Squad Re Buoy I 58020 MISSING PA Sacasta Sail Squad Re Buoy I 58020 MISSING PA Sacasta Sail Squad Re Buoy I 58020 MISSING PA Sacasta Sail Squad Re Buoy I 58020 MISSING PA Sacasta Sail Squad Re Buoy I 58020 DAYMK MISSING PA Bay Iskis Scuth Charmel Daybeacon I 58020 DAYMK MISSING PA Bay Iskis Scuth Charmel Daybeacon I 58060 HANK MISSING PA Bay Iskis Scuth Charmel Daybeacon I 58060 STRUCT DESTACE NAW PA Bistoneoud Harbor Charmel Daybeacon I 58000 STRUCT DESTACE NAW PA Bistoneoud Harbor Charmel Daybeacon I 58000 DAYMK MISSING PA Buttoneoud Harbor Charmel Daybeacon I 58000 DAYMK MISSING PA Buttoneoud Harbor Charmel Daybeacon I 58050 DAYMK MISSING PA Buttoneoud Harbor Charmel Daybeacon I 58050 DAYMK MISSING PA Buttoneoud Harbor Charmel Daybea				
Sacenta Sa Siquard Re Buny I 58020 MISSING PA Sacenta Sa Siquard Re Buny K 58020 MISSING PA Sacenta Sa Siquard Re Buny K 58020 MISSING PA Sap has South Christon Dipolescore I 38680 STRUET DMED PA Bay has South Christon Dipolescore 6 38650 DAYKK MUSSING PA Bay has South Christon Dipolescore 10 38660 HAZ NAVI/JOANAM MISSING PA Longbast Kay Mecinings Light I 38600 STRUET DEST/MAZ PANY PA Bittonsood Harbor Channel Diplescore 18 38910 DAYKK MISSING PA Bittonsood Harbor Channel Ophescore 18 38910 DAYKK MISSING PA Bittonsood Harbor Channel Ophescore 24 38950 DAYKK MISSING PA Bittonsood Harbor Channel Diplescore 25 38950 DAYKK MISSING PA Bittonsood Harbor Channel Diplescore 24 38950 DAYKK MISSING PA Bittonsood Harbor Channel Diplescore 24 39950 DAYKK MISSING PA Bittonsood Harbor Channel Diplescore 24 39950 DAYKK MISSING PA				
Saratona Sail Squard Re Buay J 55025 MISSING PA Saratona Sail Squard Re Buay K 5630 MISSING PA Ilay Insis Scuth Channel Dephezora I 3640 STRACT DIMSO PA Bay Insis Scuth Channel Dephezora B 3660 DAYMK EMISON PA Bay Insis Scuth Channel Dephezora B 3665 DAYMK EMISON PA Bay Insis Scuth Channel Dephezora B 36860 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38800 STRUCT DESTACE ALIVA PA Bultonovoci Harton Channel Dephezora B 38910 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38910 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38915 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38915 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38915 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38915 DAYMK MISSING PA Bultonovoci Harton Channel Dephezora B 38915 DAYMK MISSING PA <td></td> <td></td> <td></td> <td></td>				
Samoute Sal Spoud Re Beary K 6860 MISSING PA Bay John Shath Channel Duybraccon 1 5860 SATIKET DIACO PA Bay John Shath Channel Duybraccon 6 5860 DANKK DIMED PA Bay John Shath Channel Duybraccon 10 5865 DANK MISSING PA Longboat Risk Monings Ught 1 5869 PA NAVIADAMK MISSING PA Bultomood Habro Channel Duybracon 18 5890 DANKK MISSING PA Bultomood Habro Channel Duybracon 13 58910 DANKK MISSING PA Bultomood Habro Channel Duybracon 23 58913 DANKK MISSING PA Bultomood Habro Channel Duybracon 23 58913 DANKK MISSING PA Bultomood Habro Channel Duybracon 24 58913 DANKK MISSING PA Bultomood Habro Channel Duybracon 24 58910 DANKK MISSING PA Bultomood Habro Channel Duybracon 34 58910 DANKK MISSING PA Bultomood Habro Channel Duybracon 34 58910 DANKK MISSING PA Bultomood Habro Channel Duybracon 35 58912 DANKK MISSING PA <				
Page				
Spy Ides South Channel Daybeacon 4 58850 DAMMK DMCD PA lagy Isia South Channel Daybeacon 6 58655 DATMK MISSING PA lagy Isia South Channel Daybeacon 10 58665 PAZ NAW/DWMM MISSING PA lactingbast Key Moorings Isight 1 58600 STRUCT DEST/HAZ NAW PA Buttomood Hashor Channel Daybeacon 8 58901 DAMMK MISSING PA Buttomood Hashor Channel Daybeacon 20 58935 DAMMK MISSING PA Buttomood Hashor Channel Daybeacon 23 58945 HAZ NAW/DAMM MISSING PA Buttomood Hashor Channel Daybeacon 24 58950 DAMMK MISSING PA Buttomood Hashor Channel Daybeacon 28 58955 DAMMK MISSING PA Buttomood Hashor Channel Daybeacon 29 59950 DAMMK MISSING PA Buttomood Hashor Channel Daybeacon 4 59900 DAMMK MISSING PA Longboat Hashor North Marina Daybeacon 13 59910 DAMMK MISSING PA Longboat Hashor North Marina Daybeacon 2 59150 DAMMK MISSING PA Longboat Hashor North Marina Daybeacon 3 59150 STRUCT				
Bey Isles South Channel Daybeacon 6 \$8655 DAYMK MISSING PA Bay Isles South Channel Daybeacon 10 \$8665 HAZ NUX/DAYMK MISSING PA Longbeat Key Mooring Light 1 \$8800 STRUCT DEST/NAZ NAW PA Buttomwood Harbor Channel Daybeacon 3 \$8905 DAYMK MISSING PA Buttomwood Harbor Channel Daybeacon 20 \$8915 DAYMK MISSING PA Buttomwood Harbor Channel Daybeacon 23 \$8945 HAZ NAV/DAYMK MISSING PA Buttomwood Harbor Channel Daybeacon 24 \$8950 DAYMK MISSING PA Buttomwood Harbor Channel Daybeacon 24 \$8950 DAYMK MISSING PA Buttomwood Harbor Channel Daybeacon 36 \$8955 DAYMK MISSING PA Buttomwood Harbor Channel Daybeacon 36 \$9950 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 38 \$9900 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 \$9150 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 \$9140 \$180CT DEST PA Longboat Harbor North Marina Daybeacon 3 \$9150 <td< td=""><td></td><td></td><td></td><td></td></td<>				
lay bles South Channel Diphescon 10 5865 HAZ NAW/DAWINK MISSING PA Longboat Key Moorings Light 1 5860 STRUCT DEST/HAZ NAW PA Bullstownood Harbor Channel Diphescon 13 5890 DAYME MISSING PA Bultstownood Harbor Channel Diphescon 20 5893 DAYME MISSING PA Bultstownood Harbor Channel Diphescon 23 58945 HAZ NAV/DAYMK MISSING PA Bultstownood Harbor Channel Diphescon 24 58950 DAYME MISSING PA Bultstownood Harbor Channel Diphescon 26 58955 DAYME MISSING PA Comptool Harbor Channel Diphescon 26 58955 DAYME MISSING PA Longboat Harbor Channel Diphescon 27 59070 DAYME MISSING PA Longboat Harbor Channel Diphescon 17 59070 DAYME MISSING PA Longboat Harbor North Marina Diphescon 2 59135 DAYME MISSING PA Longboat Harbor North Marina Diphescon 3 59140 STRUCT DEST PA Longboat Harbor North Marina Diphescon 4 59150 STRUCT DEST PA Longboat Harbor North Marina Diphescon 5 59255			DAYMK DMGD	
Longbook Key Moorings Light 1 58860 STRUCT DEST/HAZ NAV PA Buttomwood Harbor Channel Duybeacon 13 58905 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 20 58935 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 24 58935 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 24 58950 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 26 58955 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 26 58955 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 26 58955 DAYMK MISSING PA Buttomwood Harbor Channel Duybeacon 13A 59000 DAYMK MISSING PA Longboat Harbor North Mainina Duybeacon 14 59100 DAYMK MISSING PA Longboat Harbor North Mainina Duybeacon 6 59140 STRUCT DEST PA Longboat Harbor North Mainina Duybeacon 6 59140 STRUCT DEST PA Buccaneer Inn Duybeacon 154 59020 STRUCT DEST PA Buccaneer Inn Duybeacon 16 59220 DAYMK IMCH	Bay Isles South Channel Daybeacon 6	58655	DAYMK MISSING	PA
Buttorwood Harbor Channel Junction Daybeacon 13 \$8910 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 20 \$8935 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 20 \$8935 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 24 \$8935 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 26 \$8935 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 24 \$8930 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 24 \$8930 DAYMK MISSING PA Buttorwood Harbor Channel Daybeacon 13A \$8000 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 17 \$9970 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 \$9150 STRUCT DIST PA Longboat Harbor North Marina Daybeacon 4 \$9160 STRUCT DIST PA Longboat Harbor North Marina Daybeacon 6 \$9150 STRUCT DIST PA Buccaneer Inn Daybeacon 15 \$9220 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 \$9227 DAYMK IMCH <t< td=""><td>Bay Isles South Channel Daybeacon 10</td><td>58665</td><td>HAZ NAV/DAYMK MISSING</td><td>PA</td></t<>	Bay Isles South Channel Daybeacon 10	58665	HAZ NAV/DAYMK MISSING	PA
Buttonwood Harbor Channel Dybbeacon 13 58910 DAYMK MISSING PA Buttonwood Harbor Channel Dybbeacon 25 59935 DAYMK MISSING PA Buttonwood Harbor Channel Dybbeacon 24 59945 HAZ NAV/DAYMK MISSING PA Buttonwood Harbor Channel Dybbeacon 24 59950 DAYMK MISSING PA Buttonwood Harbor Channel Dybbeacon 13A 59900 DAYMK MISSING PA Longboat Harbor Channel Dybbeacon 12 59970 DAYMK MISSING PA Longboat Harbor Channel Dybbeacon 12 59930 DAYMK MISSING PA Longboat Harbor North Marina Duybeacon 4 59140 STRUCT DEST PA Longboat Harbor North Marina Duybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Duybeacon 8 59150 STRUCT DEST PA Buccaneer inn Duybeacon 16 59245 STRUCT DEST PA Buccaneer inn Duybeacon 16 59250 DAYMK MISCH PA Buccaneer inn Duybeacon 16 59265 DAYMK MISCH PA Buccaneer inn Duybeacon 2 59830 DAYMK MISCH PA	Longboat Key Moorings Light 1	58680	STRUCT DEST/HAZ NAV	PA
Buttonwood Harbor Channel Daybeacon 23 \$9935 DAYMK MISSING 9A Buttonwood Harbor Channel Daybeacon 23 \$9945 HAZ NAVDOWMK MISSING PA Buttonwood Harbor Channel Daybeacon 24 \$9950 DAYMK MISSING PA Buttonwood Harbor Channel Daybeacon 13A \$9050 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 17 \$9070 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 17 \$9070 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 2 \$9135 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 \$9140 \$1000 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 \$9150 \$1000 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 \$9150 \$1000 STRUCT DEST PA Buccaneer Inn Daybeacon 14 \$9200 DAYMK MISHOR PA Buccaneer Inn Daybeacon 15 \$9200 DAYMK MISHOR PA Buccaneer Inn Daybeacon 16 \$9200 STRUCT DEST PA Gallacaneer Inn Daybeacon 18 \$9200 STRUCT DEST PA	Buttonwood Harbor Channel Junction Daybeacon B	58905	DAYMK MISSING	PA
Buttornwood Harbor Charmel Daybeacon 23 58945 HAZ NAV/DAYMK MISSING PA Buttornwood Harbor Charmel Daybeacon 24 58950 DAYMK MISSING PA Buttornwood Harbor Charmel Daybeacon 36 58955 DAYMK MISSING PA Longboat Harbor Charmel Daybeacon 17 59070 DAYMK MISSING PA Longboat Harbor Korhm Marina Daybeacon 2 59135 DAYMK MISSING PA Longboat Harbor Korhf Marina Daybeacon 4 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59160 STRUCT DEST PA Buccaneer Inn Daybeacon 18 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 20 59285 DAYMK IMCH PA Buccaneer Inn Daybeacon 23 59300 DAYMK IMCH PA Buccaneer Inn Daybeacon 3 59620 STRUCT DEST PA Gallianc Channel Daybeacon 3 59620 STRUCT DEST PA <	Buttonwood Harbor Channel Daybeacon 13	58910	DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 26 58955 DAYMK MISSING PA Buttonwood Harbor Channel Daybeacon 26 58955 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 13A 50000 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 17 59070 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 2 59135 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Buccaneer In Daybeacon 14 59265 DAYMK MISCH PA Buccaneer In Daybeacon 16 59270 DAYMK MISCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 3 59620 STRUCT DEST PA Catalian Channel Daybeacon 3 59620 STRUCT DEST PA Backenner Inn Daybeacon 3 59620 STRUCT DEST PA Backenner Inn Daybeacon	Buttonwood Harbor Channel Daybeacon 20	58935	DAYMK MISSING	PA
Buttomwood Harbor Channel Daybeacon 26 59955 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 17A 59050 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 2 59135 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59150 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 3 59620 STRUCT DEST PA Catalian Channel Daybeacon 3 59620 STRUCT DEST PA Catalian Channel Daybeacon 3 59620 STRUCT DEST PA Catalian Channel Daybeacon 1 59630 STRUCT DEST PA Catalian Channel Daybeacon 3	Buttonwood Harbor Channel Daybeacon 23	58945	HAZ NAV/DAYMK MISSING	PA
Longboat Harbor Channel Daybeacon 13A 59950 DAYMK MISSING PA Longboat Harbor Channel Daybeacon 17 59070 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 59185 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 4 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalian Channel Daybeacon 3 59620 STRUCT DEST PA Gatlain Channel Daybeacon 3 59620 STRUCT DEST PA Gatlain Channel Daybeacon 3 59620 STRUCT DEST PA Gatlain Channel Daybeacon 3 59620 STRUCT DEST PA Bradetine Deach (ify South Channel Daybeacon 3 <td< td=""><td>Buttonwood Harbor Channel Daybeacon 24</td><td>58950</td><td>DAYMK MISSING</td><td>PA</td></td<>	Buttonwood Harbor Channel Daybeacon 24	58950	DAYMK MISSING	PA
Longboat Harbor Channel Daybeacon 17 59070 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 2 59135 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 6 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Bradentino Reach (ity South Channel Daybeacon 3 59960 STRUCT DEST PA Bradentino Reach (ity South Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway	Buttonwood Harbor Channel Daybeacon 26	58955	DAYMK MISSING	PA
Longboat Harbor Channel Daybeacon 17 59070 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 2 59135 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 6 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Bradentino Reach (ity South Channel Daybeacon 3 59960 STRUCT DEST PA Bradentino Reach (ity South Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway	Longboat Harbor Channel Daybeacon 13A	59050	DAYMK MISSING	PA
Longboat Harbor North Marina Daybeacon 4 59136 DAYMK MISSING PA Longboat Harbor North Marina Daybeacon 6 59146 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59266 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Buccaneer Inn Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60120 DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60120 DAYMK MISSING PA Bayway Isles Channel Da		59070	DAYMK MISSING	PA
Longboat Harbor North Marina Daybeacon 6 59140 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 6 59145 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 599630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 69630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60120 HAZ Navi/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Byway Isle			DAYMK MISSING	
Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Longboat Harbor North Marina Daybeacon 8 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59000 DAYMK IMCH PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59960 STRUCT DEST PA Perico Harbor Marina Daybeacon 3 59960 STRUCT DEST PA Bayway Isles Channel Daybeacon 3 59965 STRUCT DEST PA Bayway Isles Channel Daybeacon 1 60120 HAZ NAY/DAYMK MISSING PA Gulfport Yacht Basin Channel Range	•			PA
Longboat Harbor North Marina Daybeacon 18 59150 STRUCT DEST PA Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalina Channel Daybeacon 1 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60635 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Islae Channel Daybeacon 10 60635 STRUCT DEST PA Bayway Islae Channel Daybeacon 10 60635 STRUCT DEST PA Gul				
Buccaneer Inn Daybeacon 14 59265 DAYMK IMCH PA Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalina Channel Daybeacon 3 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 5 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bayway Isles Channel Daybeacon 1 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 10 6060 DAYMK MISSING PA Gulfpo				
Buccaneer Inn Daybeacon 16 59270 DAYMK IMCH PA Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalina Channel Daybeacon 1 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 5 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Bayyay Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Rear Light 60700 LT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA <	-			
Buccaneer Inn Daybeacon 20 59285 STRUCT DEST PA Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalina Channel Daybeacon 1 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 5 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Front Light 60700 LT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA <t< td=""><td>·</td><td></td><td></td><td></td></t<>	·			
Buccaneer Inn Daybeacon 24 59300 DAYMK IMCH PA Catalina Channel Daybeacon 1 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 5 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bayway Isles Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 3 60660 DAYMK MISSING PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Rear Light 60700 LT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LT EXT PA Pasadena Yacht Club Channel Daybeacon 6 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST ANA PA				
Catalina Channel Daybeacon 1 59620 STRUCT DEST PA Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 5 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 3 60660 DAYMK MISSING PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Vacht Basin Channel Range Front Light 60700 LT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LT EXT PA Gulfport Yacht Sasin Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST				
Catalina Channel Daybeacon 3 59625 STRUCT DEST PA Catalina Channel Daybeacon 5 59630 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 13 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Vacht Basin Channel Range Front Light 60700 LT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60705 LT EXT PA Gulfport Yacht Club Channel Daybeacon 6 60770 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 6 61140 STRUCT DEST PA <td></td> <td></td> <td></td> <td></td>				
Catalina Channel Daybeacon 5 Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Perico Harbor Marina Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Gulfport Yacht Basin Channel Range Front Light 60700 LIT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LIT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST/HAZ NAV PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 6170 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 Gezoo STRUCT DEST PA Tarpon Cove Daybeacon 18 62225 STRUCT DEST PA Tarpon Cove Daybeacon 23				
Bradenton Beach City South Channel Daybeacon 1 59960 STRUCT DEST PA Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Perico Harbor Marina Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Front Light 60700 LT EXT PA Gulfport Yacht Basin Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST PA Jungle Estates Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Tarpon Cove Daybeacon 6 62195 STRUCT DEST PA Tarpon Cove Daybeacon 16 Tarpon Cove Daybeacon 17 Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 23 FRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 23 STRUCT DEST PA Tarpon Cove Daybeacon 18 FRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 18 FRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 18 FRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 18 FRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA	·			
Bradenton Beach City South Channel Daybeacon 3 59965 STRUCT DEST PA Perico Harbor Marina Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Front Light 60700 LI EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LI EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62205 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 23 STRUCT DEST PA Tarpon Cove Daybeacon 23 STRUCT DEST PA Tarpon Cove Daybeacon 18 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA				
Perico Harbor Marina Daybeacon 13 60120 HAZ NAV/DAYMK MISSING PA Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Front Light 60700 LIT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LIT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA	Bradenton Beach City South Channel Daybeacon 1	59960	STRUCT DEST	PA
Bayway Isles Channel Daybeacon 3 60635 STRUCT DEST PA Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Front Light 60700 LT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 62115 STRUCT DEST PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA Tarpon Cove Daybeacon 18 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA	Bradenton Beach City South Channel Daybeacon 3	59965	STRUCT DEST	PA
Bayway Isles Channel Daybeacon 10 60660 DAYMK MISSING PA Gulfport Yacht Basin Channel Range Front Light 60700 LIT EXT PA Gulfport Yacht Basin Channel Range Rear Light 60705 LIT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 STRUCT DEST PA	Perico Harbor Marina Daybeacon 13	60120	HAZ NAV/DAYMK MISSING	PA
Gulfport Yacht Basin Channel Range Front Light Gulfport Yacht Basin Channel Range Rear Light Gulfport Yacht Basin Channel Range Rear Light Gulfport Yacht Club Channel Daybeacon 4 60705 LT EXT PA Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 G1140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 G200 STRUCT DEST PA Tarpon Cove Daybeacon 17 G200 STRUCT DEST PA Tarpon Cove Daybeacon 18 G200 STRUCT DEST PA Tarpon Cove Daybeacon 18 G205 STRUCT DEST PA Tarpon Cove Daybeacon 20 G215 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA	Bayway Isles Channel Daybeacon 3	60635	STRUCT DEST	PA
Gulfport Yacht Basin Channel Range Rear Light Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 Cove Daybeacon 18 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23	Bayway Isles Channel Daybeacon 10	60660	DAYMK MISSING	PA
Gulfport Yacht Club Channel Daybeacon 4 60745 STRUCT DEST PA Pasadena Yacht Club Channel Daybeacon 6 60770 STRUCT DEST/HAZ NAV PA Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 STRUCT DEST PA Tarpon Cove Daybeacon 20 STRUCT DEST PA	Gulfport Yacht Basin Channel Range Front Light	60700	LT EXT	PA
Pasadena Yacht Club Channel Daybeacon 660770STRUCT DEST/HAZ NAVPAPasadena Yacht Club Channel Daybeacon 960780STRUCT DESTPAJungle Estates Daybeacon 461140STRUCT DESTPAJungle Estates Daybeacon 661150STRUCT DESTPATarpon Cove Daybeacon 962165STRUCT DESTPATarpon Cove Daybeacon 1662195STRUCT DESTPATarpon Cove Daybeacon 1762200STRUCT DESTPATarpon Cove Daybeacon 1862205STRUCT DEST/HAZ NAVPATarpon Cove Daybeacon 2062215STRUCT DESTPATarpon Cove Daybeacon 2362225STRUCT DESTPA	Gulfport Yacht Basin Channel Range Rear Light	60705	LT EXT	PA
Pasadena Yacht Club Channel Daybeacon 660770STRUCT DEST/HAZ NAVPAPasadena Yacht Club Channel Daybeacon 960780STRUCT DESTPAJungle Estates Daybeacon 461140STRUCT DESTPAJungle Estates Daybeacon 661150STRUCT DESTPATarpon Cove Daybeacon 962165STRUCT DESTPATarpon Cove Daybeacon 1662195STRUCT DESTPATarpon Cove Daybeacon 1762200STRUCT DESTPATarpon Cove Daybeacon 1862205STRUCT DEST/HAZ NAVPATarpon Cove Daybeacon 2062215STRUCT DESTPATarpon Cove Daybeacon 2362225STRUCT DESTPA	Gulfport Yacht Club Channel Daybeacon 4	60745	STRUCT DEST	PA
Pasadena Yacht Club Channel Daybeacon 9 60780 STRUCT DEST PA Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA		60770	STRUCT DEST/HAZ NAV	PA
Jungle Estates Daybeacon 4 61140 STRUCT DEST PA Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST/HAZ NAV PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA	·			
Jungle Estates Daybeacon 6 61150 STRUCT DEST PA Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST/HAZ NAV PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA				
Tarpon Cove Daybeacon 9 62165 STRUCT DEST PA Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST/HAZ NAV PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA				
Tarpon Cove Daybeacon 16 62195 STRUCT DEST PA Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST/HAZ NAV PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA				
Tarpon Cove Daybeacon 17 62200 STRUCT DEST PA Tarpon Cove Daybeacon 18 62205 STRUCT DEST/HAZ NAV PA Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA				
Tarpon Cove Daybeacon 1862205STRUCT DEST/HAZ NAVPATarpon Cove Daybeacon 2062215STRUCT DESTPATarpon Cove Daybeacon 2362225STRUCT DESTPA				
Tarpon Cove Daybeacon 20 62215 STRUCT DEST PA Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA				
Tarpon Cove Daybeacon 23 62225 STRUCT DEST PA				
Iarpon Cove Daybeacon 28 62246 STRUCT MISSING/HAZ NAV PA				
	larpon Cove Daybeacon 28	62246	STRUCT MISSING/HAZ NAV	PA

https://www.navcen.uscg.gov/msi 67/71

Tarpon Cove Daybeacon 28	62246	STRUCT DMGD	PA	

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Unknown/General/Bridges/Construction		SAN JOSE CREEK-GOLETA SLOUGH: STATE ROUTE 217 HIGHWAY BRIDGE- Caltrans has resumed in-water construction for the bridge	Lat:
			34° 25' 15"
		An open navigable passage in the middle of the slough under the bridge will be available for mariners. Demolition of old bridge will	Lon:
		take place May 2025. Mariners are requested to transit the area with caution. For more information, contact the Coast Guard Bridge	-119° 49'
		Office at 571-607-2206 or by e-mail at D11Bridges@uscg.mil.	47"

Upper Savannah River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southern Nuclear Operating Co Obstruction Daybeacon A	5295	STRUCT DEST	PA
Southern Nuclear Operating Co Obstruction Daybeacon B	5295.1	STRUCT DEST	PA

Vernon River

Additional MSI Categories

•					
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION		
Ossabaw Sound - Vernon	Advanced Notice	ATON/Advanced Notice of Change From: 2024-11-25 To: 2025-05-24 Location: 31.87195° N / 81.07605° W Aid Name: Vernon River Light Wreck	Lat:		
River/ATON/Advanced Notice	of Change	86 LLNR: 36260 Action: CHANGE Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation	31° 52' 19"		
of Change		system in the Intracoastal Waterway the Vernon River, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from	Lon:		
		5NM to 4NM. The current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should	-081° 04'		
		be able to see two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate.	34"		
		more trian adequate.			

Villas Continental Club

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Villas Continental Club Daybeacon 2	7790	STRUCT DEST/HAZ NAV	PA
Villas Continental Club Daybeacon 3	7795	STRUCT DEST	PA
Villas Continental Club Daybeacon 4	7800	STRUCT DEST	PA
Villas Continental Club Daybeacon 5	7805	STRUCT DEST	PA

Volusia

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Volusia Light 23	8820	STRUCT DEST/TRLB	FD

Wadmalaw River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE		
Wadmalaw River Light 82	34870	STRUCT MISSING/TRLB	FD		
Wadmalaw River Daybeacon 87	34890	STRUCT DEST/TRUB	FD		
Wadmalaw River Daybeacon 95	34915	STRUCT MISSING/TRUB	FD		
Wadmalaw River Daybeacon 96	34920	STRUCT DEST/TRUB	FD		
Wadmalaw River Light 102	34940	LT EXT	FD		

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
North Edisto River -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.69507° N / 80.22075° W Aid Name: Wadmalaw River Daybeacon 87 LLNR: 34890 Action:	Lat:
Wadmalaw	of Change	CHANGE Action Type Change Aid Subtype The following changes have been approved in the Wadmalaw River to improve aids to navigation	32° 41' 42"
River/ATON/Advanced Notice		reliability. Wadmalaw River DBN 87 (LLNR 34890) and Wadmalaw River DBN 96 (LLNR 34920) will be changed to Wadmalaw River Buoy 87	Lon:
of Change		(Same LLNR) and Wadmalaw River Buoy 96 (Same LLNR). Both aids to navigation are currently destroyed and have a Temporary Unlighted Buoy	-080° 13'
		on station. Both assigned positions are presenting depths of over 28 feet. This depth makes it impossible for a CG asset to rebuild the structures.	15"
		Changing the aids to navigation from fixed to floating allows the CG primary servicing unit the flexibility to relocate the aid to mark safe water.	
North Edisto River -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.66553° N / 80.23956° W Aid Name: Wadmalaw River Daybeacon 96 LLNR: 34920 Action:	Lat:
Wadmalaw	of Change	CHANGE Action Type Change Aid Subtype The following changes have been approved in the Wadmalaw River to improve aids to navigation	32° 39' 56"
River/ATON/Advanced Notice		reliability. Wadmalaw River DBN 87 (LLNR 34890) and Wadmalaw River DBN 96 (LLNR 34920) will be changed to Wadmalaw River Buoy 87	Lon:
of Change		(Same LLNR) and Wadmalaw River Buoy 96 (Same LLNR). Both aids to navigation are currently destroyed and have a Temporary Unlighted Buoy	-080° 14'
		on station. Both assigned positions are presenting depths of over 28 feet. This depth makes it impossible for a CG asset to rebuild the structures.	. 22"
		Changing the aids to navigation from fixed to floating allows the CG primary servicing unit the flexibility to relocate the aid to mark safe water.	

https://www.navcen.uscg.gov/msi

Walls Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Walls Cut Light 42	35840	STRUCT MISSING/TRLB	FD

Wassaw Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wassaw Sound Lighted Buoy 8	5595	MISSING	FD

Waterway Name Not Found

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Channel Daybeacon A1	35920	STRUCT MISSING/TRUB	FD
South Channel Daybeacon A8	35940	STRUCT DMGD	FD
North River Light 178A	36800	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wexford Harbour Daybeacon 3	4420	MSLD SIG	PA
Wexford Harbour Daybeacon 4	4425	MSLD SIG	PA
Wexford Harbour Daybeacon 8	4445	MSLD SIG	PA
Palmetto Dunes Marina West Light 22	4520	DAYMK IMCH	PA

Western Gulf Intracoastal Waterway

Private Discrepancies

NAME		LLNR STATUS	
NAME	LLIVIK	SIAIOS	AID TYPE
Dunedin Pass Daybeacon 2	25850	STRUCT DEST	PA
Dunedin Pass Daybeacon 3	25855	STRUCT DEST	PA
Dunedin Pass Daybeacon 9	25875	STRUCT DEST	PA
Dunedin Pass Daybeacon 12	25885	STRUCT MISSING	PA
South Seas Boat Basin Daybeacon 3	55650	HAZ NAV/DAYMK MISSING	PA

Whale Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Whale Harbor Channel Daybeacon 6	12720	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Holiday Isle Marina Daybeacon 1	12765	STRUCT DEST	PA
Holiday Isle Marina Daybeacon 2	12770	STRUCT DEST	PA

White Shells Cut

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
White Shells Cut Lighted Buoy 27	7315	RELOCATED FOR DREDGING	FD
White Shells Temporary Range Rear Light	7325.2	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - White Shells Cut/ATON/Advanced Notice	Advanced Notice of Change	White Shells Cut LB 27 (LLNR 7315) will be permanently relocated to 30-23-36.040N/081-28-48.780W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	Lat: 30° 23' 36"
of Change		· · · · · · · · · · · · · · · · · · ·	Lon: -081° 28' 49"

St Johns River - White Shells	Advanced Notice	White Shells Cut LB 29 (LLNR 7316) will be permanently relocated to 30-23-32.900N/081-29-05.750W. This change calls to relocate (6) lighted	Lat:
Cut/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 33"
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation	Lon:
		for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All	-081° 29'
		positions listed are approximate. Permanent positions will be advertised when the work is completed.	06"

Wilmington River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Skidaway Island - Wilmington	Bridges	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 32.062044° N / 81.02951° W Bridge Name: CR 787 (Island	Lat:
River/General/Bridges/Conversion		Expressway) Drawbridges Construction on the first of the two high level fixed bridges is complete and now spans the waterway providing 65	
		feet of vertical clearance and 100 feet of horizontal clearance between the fender systems. Construction of the second high level fixed bridge	Lon:
		has begun. Work hours are 7 am 7 p.m., Monday through Saturday. During this time, there will be intermittent work inside and outside the	-081° 01'
		federal channel. Mariners operating commercial/recreational vessels greater than 50ft in breath/beam requiring full width of the federal	46"
		navigational channel, are strongly encouraged to call Myrick Marine at 912-210-6778 up to 24 hours in advance, but not less than one hour	
		before arrival to the construction area to coordinate safe passage. Once in the vicinity of the Causton Bluff Bridge, please contact the LONA	
		MYRICK or GRACE MYRICK by VHF to verify your scheduled passage. If applicable, please have your Automated Information System (AIS)	
		energized. In addition, there will be a Myrick Marine safety boat in the vicinity of the construction area for traffic management. The safety	
		boat can be reached on channel 10 or 13. The old bascule bridges have been removed from the waterway. Mariners are reminded to	
		proceed through the construction area at a safe speed, always maintain situational awareness, and monitor VHF radio channel 16 when in	
		the vicinity of the Causton Bluff Bridge. For further information regarding this MSIB, please contact the U.S. Coast Guard MSU Savannah	
		Waterways Management Division at SMB-MSUSavannah-WWM@uscg.mil or the Command Duty Officer at (912) 247-0073.	

Windward Passage

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johnson Reef Buoy JA	32680	OFF STA	PA
Johnson Reef Lighted Buoy JD	32680.3	LT EXT	PA

Winyah Bay Channel

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Winyah Bay Range A Front Light	1875	LT EXT	FD
Winyah Bay Range A Rear Light	1880	LT EXT	FD
Winyah Bay Range B Rear Light	1915	STRUCT DEST/HAZ NAV/TRLT	FD
Winyah Bay Channel Lighted Buoy 13	1950	OFF STATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Winyah	Advanced Notice of	The Coast Guard Mooring Buoy WB (LLNR 1958) will be permanently relocated to approximate position 33-14-	Lat:
Bay Channel/ATON/Advanced Notice of Change	Change	59.160N/079-12-47.580W. The new location will provide a more protected environment from the previous exposed	33° 13' 54"
		location for CG assets when moored to this buoy.	Lon:
			-079° 11'
			30"
Sector Charleston, Submerged Land Act (SLA) - Winyah	Advanced Notice of	Winyah Bay Channel LB 4 (LLNR 1885) will have the bell permanently removed.	Lat:
Bay Channel/ATON/Advanced Notice of Change	Change		33° 11' 37"
			Lon:
			-079° 07'
			13"

Winyah Bay Charleston Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Winyah Bay-Charleston Harbor Daybeacon 19	34180	STRUCT MISSING/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA)	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25	
- Winyah Bay Charleston	Construction	To: 2026-11-13 Location: 32.7602° N / 79.86088° W 32.75736° N / 79.85803° W 32.7566° N / 79.85931° W 32.75944° N /	
Harbor/General/Marine Construction	(Excluding Bridges)	79.86219° W 32.7602° N / 79.86088° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and	
(Excluding Bridges)/Facilities, Barriers,		rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and	
Manmade Reefs, Riprap, Jetties/Dikes		crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project	
		is 31October 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor	
		VHF-FM channels 13 and 16.	

https://www.navcen.uscg.gov/msi 70/71

Withlacoochee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Withlacoochee River Entrance Daybeacon 8	29410	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 16	29455	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 26	29520	STRUCT MISSING/TRUB	FD
Nithlacoochee River Entrance Daybeacon 29	29535	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 30	29545	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 31	29550	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Light 32	29555	STRUCT MISSING/TRLB	FD
Withlacoochee River Entrance Daybeacon 32B	29565	STRUCT DMGD	FD

https://www.navcen.uscg.gov/msi