Local Notice to Mariners for District 7 08/06/2025

Alafia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Alafia River Light 7	23275	STRUCT MISSING/TRLB	FD
Alafia River Light 15	23315	STRUCT DEST/TRLB/HAZ NAV	FD

Altamaha Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Altamaha Sound Daybeacon 197	36887	STRUCT DEST/TRUB	FD
Altamaha Sound Light 201	36905	STRUCT DEST/TRLB	FD
Altamaha Sound Light 202	36910	STRUCT DEST/TRLB	FD
Altamaha Sound Light 209	36930	STRUCT DEST/TRLB	FD
Altamaha Sound Range Front Light C	36935	STRUCT DEST	FD

Amelia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Amelia River Lighted Buoy 4	37940	ADRIFT	FD

Anclote Anchorage North Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage North Entrance Light 7	26130	STRUCT DEST/HAZ NAV/TRLB/OFF STATION	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sea Forest Cut Channel Daybeacon 9	26451.8	STRUCT DEST/HAZ NAV	PA
Upper Cross Bayou Daybeacon 1	26453	STRUCT DEST	PA
Gulf Harbors North Channel Daybeacon 10	26500	STRUCT DEST	PA
Gulf Harbors South Channel Light 1	26410	LT EXT	PA
Gulf Harbors North Channel Light 2	26460	STRUCT DEST	PA

Anclote River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote River Light 9	26180	STRUCT DEST/TRLB/SINKING	FD
Anclote River Daybeacon 11	26190 STRUCT DEST/TRLB/HAZ NAV		FD
Anclote River Daybeacon 12	26190.5	HAZ NAV/STRUCT DEST/TRLB	FD
Anclote River Turning Basin Shoal Daybeacon A	26360	STRUCT MISSING/TRUB	FD
Anclote River Turning Basin Shoal Daybeacon B	26365	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Village Marina Daybeacon 7	26233.7	DAYMK MISSING	PA

Angelfish Creek

•			
NAME	LLNR	STATUS	AID TYPE
Angelfish Creek Daybeacon 1	11185	STRUCT DEST/HAZ NAV/TRLB	FD
Angelfish Creek Daybeacon 4	11205	STRUCT DEST	FD
Angelfish Creek Light 6	11215	STRUCT DEST/TRLB	FD

Army Terminal Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Army Terminal Channel Lighted Buoy A	30845	LT EXT	FD

Ashepoo-Coosaw Cut-Off

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ashepoo-Coosaw Cutoff Daybeacon 169	35160	STRUCT MISSING/TRUB	FD

Ashley River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor South Channel -	Bridges	General/Bridges/Construction From: 2025-02-12 To: 2026-01-30 Location: 32.78257° N / 79.96052° W Bridge Name: Ashley River	Lat:
Ashley		Pedestrian Bridge Construction of the Ashley River Crossing Pedestrian Bridge has begun on the Ashley River, in Charleston, SC. The new	32° 46' 57"
River/General/Bridges/Construction		bridge will be constructed to the southeast (immediately adjacent) of the T. Allen Legare / US 17 Bridge. Construction barges will be	Lon:
		partially obstructing the channel, approximately 65-70 feet of the channel will be available to navigation. Vessels requiring a full channel	-079° 57'
		passage must contact Mr. Sean Lynch, 728-205-1580, at least 24 hours prior to the transit. Construction activities will be 24 hours a day,	38"
		seven days a week. The SE section of the T. Allen Legare / US 17 Bridge fender will be temporarily removed. The remaining section will	
		be properly lighted. One dolphin at the NE fender will be removed during the construction. Vessels should use caution and maintain	
		safe speeds while transiting the area.	

Atlantic IWW

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sebastian Inlet North Jetty Light	655	LT EXT	PA
Sailfish Point Marina Channel Daybeacon 1	10005	STRUCT DEST/HAZ NAV	PA
Sailfish Point Marina Channel Daybeacon 7	10035	STRUCT DEST	PA
Sailfish Point Marina Channel Daybeacon 2	10010	STRUCT DEST	PA
Sailfish Point Marina Channel Daybeacon 5	10025	STRUCT DEST/HAZ NAV	PA

Bahia De Boqueron

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bajo Enmedio South Lighted Buoy 1	32325	SINKING/TRLB	FD

Bahia De Guayanilla

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De Guayanilla Entrance Range Rear Light	32075	LT EXT	FD

Bahia De Jobos

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aguirre Power Plant Lighted Buoy 1	31890	OFF STA	PA
Aguirre Power Plant Lighted Buoy 2	31895	OFF STA	PA
Aguirre Power Plant Lighted Buoy 3	31900	OFF STA	PA
Aguirre Power Plant Lighted Buoy 4	31905	OFF STA	PA
Aguirre Power Plant Lighted Buoy 5	31910	OFF STA	PA
Aguirre Power Plant Lighted Buoy 6	31915	OFF STA	PA
Aguirre Power Plant Lighted Buoy 8	31920	OFF STA	PA

Bahia De Mayaguez

•			
NAME	LLNR	STATUS	AID TYPE
Bahia De Mayaguez Range Front Light	32355	VEGETATION	FD

Bahia De Ponce

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla De Cardona Light	31950	STRUCT DEST	FD
Bahia De Ponce Range Rear Light	31965	REDUCED INT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce Harbor Pier Obstruction Lights (4)	31985	STRUCT DMGD	PA

Bahia De Ponce And Approaches

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla Caja De Muertos Light	31925	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce Yacht & Disperial Purpose Buoy A	31927	MISSING	PA
Rio Bucana East Jetty Light	31940	STRUCT DEST	PA

Bahia De San Juan

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De San Juan Lighted Buoy 2	30760	BUOY DMGD/OFF STATION	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bahia De San Juan FAD Lighted Buoy E	30736.4	MISSING	PA
Bahia De San Juan FAD Lighted Buoy F	30736.5	OFF STA	PA

Temporary Changes

- P J J				
NAME	LLNR	STATUS	AID TYPE	
Army Terminal Channel Temporary Buoy 7A	30885.5	ESTABLISHED	FD	

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Bahia De San Juan/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 18.43499° N / 66.10732° W Aid Name: Army Terminal Channel Lighted Buoy 7 LLNR: 30885 Action: RELOCATE Army Terminal Channel Lighted Buoy 7 (LLNR 30885) will be permanently relocated to position 18-26-10.272N/066-06-27.668W. Army Terminal Channel Lighted Buoy 7A (LLNR 30885.5) will be permanently established in position 18-26-03.650N/066-06-25.656W.	Lat: 18° 26' 06" Lon: -066° 06' 26"
Bahia De San Juan/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 18.43435° N / 66.10713° W Aid Name: Army Terminal Channel Lighted Buoy 7A LLNR: 30885 .5 Action: ESTABLISH Army Terminal Channel Lighted Buoy 7 (LLNR 30885) will be permanently relocated to position 18-26-10.272N/066-06-27.668W. Army Terminal Channel Lighted Buoy 7A (LLNR 30885 .5) will be permanently established in position 18-26-03.650N/066-06-25.656W.	Lat: 18° 26' 04" Lon: -066° 06' 26"

Banana River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Banana River Daybeacon 7A	42490	STRUCT DEST/TRUB	FD
Banana River Daybeacon 15	42555	STRUCT DEST/TRUB	FD

Titale Distribution							
NAME	LLNR	STATUS	AID TYPE				
Tortoise Island Ctr Channel Daybeacon 2	42450	DAYMK IMCH	PA				
Tortoise Island Center Channel Daybeacon 4	42460	DAYMK IMCH	PA				
Tortoise Island Center Channel Daybeacon 5	42460.1	DAYMK IMCH	PA				
Tortoise Island Center Channel Daybeacon 6	42460.20000000004	DAYMK MISSING	PA				
Tortoise Island Center Channel Daybeacon 7	42460.3	DAYMK IMCH	PA				
Tortoise Island Center Channel Daybeacon 8	42460.4	DAYMK IMCH	PA				
Manatee Cove Marina Daybeacon 1	42490.1	STRUCT DEST/HAZ NAV	PA				
Manatee Cove Marina Daybeacon 4	42490.4	STRUCT DMGD	PA				

Pelican Creek Light 2	42615	STRUCT DEST	PA
Central Avenue Entrance Channel Light 2	42830	LT EXT	PA
Kelly Park Channel Daybeacon 3	43040	STRUCT DEST/HAZ NAV	PA
Kelly Park Channel Daybeacon 4	43045	STRUCT DEST	PA
Kelly Park Channel Daybeacon 5	43050	STRUCT DEST/HAZ NAV	PA
Tortoise Island Channel Daybeacon 1	42463	STRUCT DEST/HAZ NAV	PA
Hospital Cut Daybeacon 6	42611.5	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Canaveral Barge Canal -	Marine	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 28.2669° N / 80.6097° W 28.17191° N /	
Banana	Construction	80.61245° W 28.25602° N / 80.6612° W 28.2669° N / 80.6097° W Gator Dredging will continue muck removal operations within the Grand Canal	
River/General/Marine	(Excluding	and adjacent canals within a subdivision, north of Samson Island Park and south of Patrick Air Force Base. Operations will begin on or about	
Construction (Excluding	Bridges)	March 15, 2022 until approximately November 30, 2025 - Monday through Saturday, 30 minutes after sunrise until 30 minutes before sunset. The	
Bridges)/Dredging		dredge DANI L will monitor VHF-FM channels 16 and 68. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene	
		pipeline associated with the hydraulic dredging operations of the canals will be utilized. Pipeline, work vessels, dredge barge, booster pump	
		barges and buoys will be visibly lighted and will be in the area until all work is complete. The configuration will change daily and Vessels and/or	
		equipment will be in multiple locations at the same time. For further information, contact: Charlie Gertz (727) 902-6055.	

Banana River North

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Banana River North Daybeacon 34	41920	STRUCT DEST/TRUB	FD
Banana River North Light 35	41925	STRUCT DEST/TRLB	FD

Barnes Sound

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee Creek Daybeacon 5	50255	STRUCT DEST	PA
Manatee Creek Daybeacon 6	50260	STRUCT DEST	PA
Manatee Creek Daybeacon 7	50265	STRUCT DEST	PA
Manatee Creek Daybeacon 8	50270	STRUCT DEST	PA
Manatee Creek Daybeacon 8A	50275	STRUCT DEST	PA
Manatee Creek Daybeacon 9	50280	STRUCT DEST	PA
Manatee Creek Daybeacon 10	50285	STRUCT DEST	PA
Manatee Bay Daybeacon 2	50310	STRUCT DEST	PA
Manatee Bay Daybeacon 3	50315	STRUCT DEST	PA

Barron River Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Barron River Channel Daybeacon 37	16180	STRUCT DEST/TRUB	FD

Beaufort River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Broad Creek Daybeacon 13	4490	STRUCT DEST	PA
Broad Creek Daybeacon 19	4510	DAYMK IMCH	PA
Broad Creek Daybeacon 21	4515	DAYMK IMCH	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Royal Sound - Beaufort River/General/Bridges/Temp Deviation		General/Bridges/Temp Deviation From: 2024-10-29 To: 2024-11-29 Location: 32.42753° N / 80.66921° W Bridge Name: Lady's Island Woods Memorial Bridge The bridge need not open for navigation, including tugs with tows during the following: - September 11, 2025, from 8 p.m. to 9 p.m. to facilitate Patriot Day 2025 October 4, 2025, from 6:30 a.m. to 9:45 a.m. to facilitate the SC Shrimp Festival 5k 2025 November 1, 2025, from 7:15 a.m. to 9:45 a.m. to facilitate the Holy Trinity Classic Christian School Swing Bridge Run 2025 November 27, 2025, from 7:15 a.m. to 9:15 a.m. to facilitate the Habitat for Humanity Turkey Trot 5K 2025 January 17, 2026, from 7:15 a.m. to 10:15 a.m. to facilitate the Beaufort Area Hospitality Association Oyster Festival 5K 2026. Public Vessels, vessels in emergency situations, and vessels that may pass through the bridge without an opening should be passed at any time.	Lat: 32° 25' 39" Lon: -080° 40' 09"

https://www.navcen.uscg.gov/msi 4/73

Port Royal Sound - Beaufort Brid	idges	General/Bridges/Closure (Scheduled Or Emergency) From: 2025-03-11 To: 2025-09-07 Location: 32.42753° N / 80.66921° W Bridge Name:	Lat:
River/General/Bridges/Closure		Lady's Island Woods Memorial Bridge - AICW The southern channel is closed to navigation until further notice. All vessels are advised to	32° 25' 39"
(Scheduled Or Emergency)		transit through the swing bridge using the northern channel only. The northeastern section of the fender system is damaged and missing.	Lon:
		There is no pier lighting identifying the northeastern fender. All mariners are advised to use extreme caution when transiting.	-080° 40'
			09"

Big Bend Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Big Bend Channel Lighted Buoy 2	23045	RELIGHTED	FD	2025-07-28

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Apollo Beach Daybeacon 4	24675	STRUCT DEST	PA

Big Marco Pass Gordon Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
ig Marco Pass-Gordon Pass Daybeacon 2	17095	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 1A	17100	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 2A	17160	STRUCT MISSING/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 3	17165	STRUCT MISSING/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 17	17210	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 18A	17220	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 26	17255	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 28A	17275	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 33	17300	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 36	17310	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordan Pass Daybeacon 40	17320	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 46	17335	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 53	17370	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 56	17385	STRUCT MISSING/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 60	17400	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 65	17415	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 66	17420	STRUCT DEST/TRUB	FD
ig Marco Pass-Gordon Pass Daybeacon 67	17420.5	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Big Marco Pass Obstruction Daybeacon A	17087	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon B	17087.1	STRUCT DEST	PA
Big Marco Pass Obstruction Daybeacon C	17087.2	STRUCT DEST	PA
Big Marco Pass Obstruction Light E	17087.4	STRUCT DEST	PA
Isles Of Capri Daybeacon 6	17125	STRUCT MISSING	PA

Biscayne Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Bay Daybeacon 47	48385	HAZ NAV/STRUCT DEST/TRLB	FD
Biscayne Bay Daybeacon 57	48490	STRUCT DEST/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Bakers Haulover Smallboat Channel Daybeacon 2	47795	STRUCT DEST	PA
John A Brennan Channel Light 13	49040	LT EXT	PA
Coral Gables Waterway Light 1	49285	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 3	49295	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 4	49300	STRUCT DEST	PA
Coral Gables Waterway Daybeacon 6	49310	DAYMK IMCH	PA
Matheson Hammock South Channel Range Front Light	49445	DAYMK MISSING/STRUCT DMGD	PA
Matheson Hammock South Channel Range Rear Light	49450	DAYMK MISSING	PA
Matheson Hammock South Channel Light 2	49455	LT EXT	PA

Matheson Hammock South Channel Daybeacon 9	49485	DAYMK MISSING	PA
Black Point Channel Daybeacon 1	49735	STRUCT DEST	PA
Black Point Channel Daybeacon 6	49760	STRUCT DEST	PA
Black Point Channel Daybeacon 12	49790	STRUCT DEST	PA
Adams Key Light	50105	LT EXT/DAYMK MISSING	PA
Miami Seaquarium Inlet Pipe Obstruction Light	48600	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-08 To: 2027-12-31 Location: 25.80607° N / 80.25855° W Bridge Name: South Florida Rail Corridor Railroad Bridge - Miami River The draw of the FDOT Railroad Bridge, mile 5.3 at Miami, Florida need not open to navigation. This temporary interim rule (TIR) is effective April 4, 2025, through 11:59 p.m. on December 31, 2027. Documents are available in the docket, USCG-2025-0204. To view, go to https://www.regulations.gov. Type the docket number (USCG-2025-0204) in the "SEARCH" box and click "SEARCH". In the Document Type column, select "Supporting & Company Related Material".	Lat: 25° 48' 22" Lon: -080° 15' 31"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-19 To: 2025-08-30 Location: 25.78882° N / 80.23137° W Bridge Name: Northwest 22nd Avenue Bridge - Miami River - From 8 a.m. on Wednesday, May 28, 2025, through 5 p.m. on Friday, August 29, 2025, the drawbridge will provide single-leaf openings with a 2-hour notice for a full opening The bridge will continue to operate on demand, except during the curfew hours from 7:35 a.m. to 8:59 a.m. and 4:45 p.m. to 5:59 p.m., Monday through Friday, except Federal holidays, the bridge need not open to navigation. (33 CFR 117.305(b)) - When the southern leaf is left in the down position, approximately 20 ft of horizontal clearance is available for navigation. The northern leaf, when in the down position, provides approximately 40 ft of horizontal clearance Mariners are advised to contact the bridge tender at least 2 hours prior to transiting the Miami River if a full channel passage is necessary.	Lat: 25° 47' 20" Lon: -080° 13' 53"
Biscayne Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-07-01 To: 2025-09-29 Location: 25.79503° N / 80.24545° W Bridge Name: Tamiami Bridge - Miami River The bridge shall open on the quarter and three-quarter hour. Public vessels of the United States, vessels declaring an emergency and tugs with tows shall be passed at any time. This temporary deviation is effective from 8 a.m. on July 1, 2025, until 11:59 p.m. on September 29, 2025. This action is necessary to allow for repairs to machinery components.	25° 47' 42"
Biscayne Bay/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2025-07-17 To: 2025-12-31 Location: 25.76553° N / 80.18723° W Bridge Name: Brickell Key Bridge Bridge repairs to begin July 17, 2025, through December 31, 2025. A turbidity barrier will be installed around the bridge structure. In-water equipment will be and will be properly lighted. All mariners are advised to use caution when transiting the area.	Lat: 25° 45' 56" Lon: -080° 11' 14"
Biscayne Bay/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2024-10-20 To: 2025-04-18 Location: 25.6632° N / 80.24784° W Fincantieri Infrastructure Florida & Description of Biscayne Bay Aquatic Preserve and Government Cut at furture MSC berths 8 and 9 (25-46-21.1332N/080-9-25.5348W to 25-46-9.1848N/080-8-57.0084W). The estimated completion date is December 15, 2025, hours of operation are 6:30 a.m. to 6:30 p.m., 7 days a week. GLF Construction Corporation will be mobilizing a Crane Barge (54 feet x 150 feet), Service Barge (30 feet X 150 feet), and a Push Boat (15 feet x 25 feet) to the project site on or around June 16, 2022. The equipment is being mobilized to install and maintain the turbidity control system required to perform both land and water-based dredging works. During the installation of the system the above equipment will be operating in the area south of the north navigation channel adjacent to Port Miami. If and when necessary, the equipment will be moved along the southern edge of the north navigation channel to perform any maintenance. Upon arrival at the site the GLF equipment will be positioned inside the Turbidity Control System south of the Navigation Channel and will not move out until completion of the work. GLF will continuously monitor VHF-FM channel 16 and use Channel 9 to maneuver barge and vessels. For further information contact:Alejandro Brito (786) 821-4587 or Alejandro.brito@fl.fcinfrastructure.com.	Lat: 25° 39' 48" Lon: -080° 14' 52"
Biscayne Bay/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 18821 Miami-Dade County Parks, Recreation, and Open Spaces Department will have a contractor within the Haulover Park Boat Ramps and marina replacing the boat ramps and docks. In-water work is expected to begin May 2025 and will continue through July 31, 2025. A barge will be staged within the marina to carry out the marine scope of work. All mariners are requested to use extreme caution and proceed at slow speed (No Wake) when transiting to and from the open portion of boat ramps. The channel to access the marina will remain open to mariners 24 hours a day 7 days a week. All in-water equipment is required to be lighted at night. For further information please contact U.S. Coast Guard Sector Miami.	

Biscayne Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Biscayne Channel Light 3	10820	STRUCT DEST/TRLB	FD
Biscayne Channel Daybeacon 4	10825	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Springs Boat Club Shoal Buoy West	10886	MSLD SIG	PA
Miami Springs Boat Club Shoal Buoy North	10887	MISSING	PA
Miami Springs Boat Club Shoal Buoy South	10889	MISSING	PA

Blackwater Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater Sound Light 38	50365	LT EXT	FD

https://www.navcen.uscg.gov/msi 6/73

Bloody Point Range

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Bloody Point Range Front Light	4585	RELIGHTED	FD	2025-08-01

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Bloody Point Range Lighted Bell Buoy 8	4580	RELOCATED FOR DREDGING	FD
Bloody Point Range Lighted Buoy 13	4615	RELOCATED FOR DREDGING	FD

Blount Island

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Blount Island Turning Basin Lighted Buoy 45	7395	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy A	7396	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy B	7397	RELOCATED FOR DREDGING	FD
Blount Island Turning Basin Buoy C	7398	RELOCATED FOR DREDGING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Fulton Cutoff - Blount	Advanced Notice of	Blount Island Turning Basin LB 45 (LLNR 7395) will be permanently relocated to 30-23-08.280N/081-32-35.920W. The flash	Lat:
Island/ATON/Advanced Notice of Change	Change	characteristic will remain a FL G 4s, but the nominal range will be reduced from 5NM to 4NM.	30° 23' 08"
			Lon:
			-081° 32' 36"

Boca Chita Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Featherbeds Obstruction Daybeacon A	49703	DAYMK MISSING	PA
East Featherbed North Obstruction Daybeacon	49703.1	DAYMK MISSING	PA
East Featherbed West Obstruction Daybeacon	49703.3	STRUCT DEST	PA
East Featherbed Northeast Obstruction Daybeacon	49703.5	STRUCT DEST	PA
East Featherbed Southeast Obstruction Daybeacon	49703.6	DAYMK IMCH	PA
East Featherbed NNE Obstruction Daybeacon	49703.700000000004	STRUCT DEST	PA
Middle Featherbeds North Obstruction Daybeacon	49704	DAYMK MISSING	PA
Middle Featherbed NNE Obstruction Daybeacon	49704.3	DAYMK MISSING	PA
Featherbed Bank Shoal Daybeacon X	49725	STRUCT DEST/HAZ NAV	PA

Boca Ciega Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Ciega Bay Daybeacon 35	60915	STRUCT DEST/TRUB	FD

Boca Ciega Bay To Anclote Anchorage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Narrows Daybeacon 14	61535	STRUCT MISSING/TRUB	FD
The Narrows Daybeacon 25	61580	TRUB/STRUCT MISSING	FD
The Narrows Light 27B	61600	STRUCT MISSING/TRLB	FD
The Narrows Daybeacon 38	61660	STRUCT DEST/TRUB	FD

Boca Grande Yacht Basin Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Boca Grande Yacht Basin Channel Light 7	21340	STRUCT DEST/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

Gasparilla Sound Channel - Boca Grande Yacht Bridg	General/Bridges/Maintenance From: 2025-01-07 To: 2025-11-03 Location: 26.75371° N / 82.2584° W Bridge Name: Boca Grande	Lat:
Basin Channel/General/Bridges/Maintenance	Bayou Temporary Bridge Temporary Construction Bridge (TCB) across the Boca Grande Bayou is authorized to remain in place	26° 45' 13"
	through April 1, 2026, to allow for the completion of work at the Gasparilla Island Water Association Wastewater Treatment Plant.	Lon:
	Remaining work includes final site work, demolition of existing structures and removal of the TCB. The center span shall be	-082° 15'
	removed to allow for unrestricted boating traffic from January 1, 2025, through May 1, 2025, and again from January 1, 2026,	30"
	through the end of the project. The TCB shall be removed in its entirety by April 1, 2026.	

Bohicket Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bohicket Creek Daybeacon 5	3905	STRUCT MISSING	FD

Bowlegs Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lower Matecumbe Obstruction Daybeacon	12380	DAYMK MISSING	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Lower Matecumbe Light 2	12375	RELIGHTED	FD	2025-07-30

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bay Harbour Light	12378	LT EXT	PA

Braden River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Braden River Daybeacon 9	22097.8	STRUCT DEST/HAZ NAV	PA
Braden River Daybeacon 11	22098	STRUCT DEST	PA

Brills Cut

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Brills Cut Range Front Light	7475	RELIGHTED	FD	2025-08-01
Brills Cut Range Rear Light	7480	WATCHING PROPERLY	FD	2025-07-27

Brunswick River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Brunswick Point Cut Range Front Light 2	6230	REDUCED INT	FD
Brandy Point Jetty Daybeacon	6290	STRUCT DEST/HAZ NAV/TRUB	FD

Butchers Bend

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Butchers Bend Light 109	9200	STRUCT DEST/TRLB	FD

Buttermilk Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Buttermilk Sound Daybeacon 217	36967	STRUCT DEST/TRUB	FD
Buttermilk Sound Daybeacon 218	36975	DBD DEST	FD

Caesar Creek

Federal Discrepancies

reactar Discrepancies					
	NAME	LLNR	STATUS	AID TYPE	

https://www.navcen.uscg.gov/msi

Caesar Creek Daybeacon 14 11050 STRUCT DEST FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Elliott Key - Caesar	Advanced Notice	ATON/Advanced Notice of Change Location: 25.40402° N / 80.24117° W Aid Name: Caesar Creek Buoy 29 LLNR: 11125 Action: DISCONTINUE	Lat:
Creek/ATON/Advanced Notice of Change	of Change	The following changes have been approved to the aids to navigation system in Caesar Creek. Caesar Creek B 29 (LLNR 11125) and Caesar Creek B 30 (LLNR 11130) will be permanently discontinued. The immediate area surrounding these buoys has significant shoaling which reduces the effectiveness in desired navigational safety. Due to strong currents these buoys are constantly being drug off station. Due to the limitations of CG assets that can service this area, buoy mooring configuration is limited. Mariners have been observed entering or departing the channel in other areas due to the shoaling experienced.	25° 24' 14" Lon: -080° 14' 28"
Elliott Key - Caesar Creek/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 25.40427° N / 80.24105° W Aid Name: Caesar Creek Buoy 30 LLNR: 11130 Action: DISCONTINUE The following changes have been approved to the aids to navigation system in Caesar Creek. Caesar Creek B 29 (LLNR 11125) and Caesar Creek B 30 (LLNR 11130) will be permanently discontinued. The immediate area surrounding these buoys has significant shoaling which reduces the effectiveness in desired navigational safety. Due to strong currents these buoys are constantly being drug off station. Due to the limitations of CG assets that can service this area, buoy mooring configuration is limited. Mariners have been observed entering or departing the channel in other areas due to the shoaling experienced.	Lat: 25° 24' 15" Lon: -080° 14' 28"

Calibogue Sound

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Calibogue Sound Entrance -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.1499° N / 80.83043° W Aid Name: Calibogue Sound Light 32 LLNR: 35800 Action: CHANGE	Lat:
Calibogue	of Change	Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system in the Intracoastal	32° 08' 60"
Sound/ATON/Advanced Notice of		Waterway Calibogue Sound, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The	Lon:
Change		current nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see	-080° 49'
		two lighted aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than	50"
		adequate.	

Caloosahatchee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Caloosahatchee River Daybeacon 19	52210	STRUCT MISSING	FD
Caloosahatchee River Light 70	53725	STRUCT DEST/TRLB	FD
Caloosahatchee River Light 72	53790	STRUCT DEST/TRLB/HAZ NAV	FD
Caloosahatchee River Daybeacon 94	54760	STRUCT MISSING/TRUB	FD
Caloosahatchee River Daybeacon 99	54785	TRUB/STRUCT MISSING	FD

NAME	LLNR	STATUS	AID TYP
t Myers Yacht Basin Breakwater Light	52640	STRUCT DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 1	52641	STRUCT DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 2	52642	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 3	52643	DBD DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 4	52644	DAYMK MISSING	PA
Caloosahatchee River Mooring Channel Daybeacon 5	52644.1	DBD DEST	PA
Caloosahatchee River Mooring Channel Daybeacon 6	52644.200000000004	DAYMK MISSING	PA
t Myers Yacht Basin Breakwater West Light	52645	STRUCT DEST	PA
Marinatown Daybeacon 1	52655	DBD DEST	PA
Marinatown Daybeacon 3	52665	STRUCT DEST	PA
Marinatown Daybeacon 4	52670	STRUCT DEST	PA
Marinatown Daybeacon 5	52675	DBD DEST	PA
Marinatown Daybeacon 7	52685	DAYMK MISSING	PA
Marinatown Daybeacon 8	52690	DBD DEST	PA
Marinatown Daybeacon 12	52710	STRUCT DMGD	PA
Marinatown Daybeacon 13	52715	DBD DMGD	PA
Marinatown Daybeacon 22	52760	STRUCT DEST	PA
Marinatown Daybeacon 23	52765	DAYMK MISSING	PA
Marinatown Daybeacon 24	52770	DAYMK MISSING	PA
Marinatown Daybeacon 26	52780	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 1	52825	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 4	52840	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 5	52845	STRUCT DEST	PA
Gulf Acres Channel Daybeacon 9	52870	STRUCT DEST	PA
Cape Coral Rim Channel Daybeacon 23	53070	HAZ NAV/DAYMK MISSING	PA
Cape Coral Rim Channel Daybeacon 39	53110	STRUCT DEST	PA
Van Riper Channel Daybeacon 2	54296	DAYMK MISSING	PA

Van Riper Channel Daybeacon 4	54296.5	DAYMK MISSING	PA
Van Riper Channel Daybeacon 6	54297	DAYMK MISSING	PA
Van Riper Channel Daybeacon 8	54297.5	DAYMK MISSING	PA
Van Riper Channel Daybeacon 10	54298	DAYMK MISSING	PA
Van Riper Channel Daybeacon 12	54298.5	DAYMK MISSING	PA
Bimini Entrance Channel Daybeacon 2	54305	STRUCT DMGD	PA
Redfish Cove Channel Daybeacon 18	54445	STRUCT DEST	PA
Redfish Cove Channel Daybeacon 20	54455	STRUCT DEST	PA
Shell Point Obstruction Daybeacon A	54763	STRUCT DEST	PA

Canaveral Barge Canal

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sykes Creek Daybeacon 19	41620	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Construction		General/Bridges/Construction From: 2024-11-12 To: 2025-10-31 Location: 28.40575° N / 80.69424° W Bridge Name: Sea Ray Drive Bridge SEMA Construction, on behalf of the bridge owner, Brevard County, has commenced the demolition, removal, and replacement of Sea Ray Drive Bridge over Sykes Creek on Merritt Island. The contractor will have a small boat on-site, which will be removed from the water at end-of-day. Temporary work platforms may be utilized at future stages of the project. There are no proposed channel restrictions for the early part of this project but can be expected starting approximately early April 2025. For waterways related questions, contact Coast Guard Sector Jacksonville Waterways Management Division at (904) 714-7631 or via email at D07-DG-SECJAX-WATERWAYS@uscg.mil.	Lat: 28° 24' 21" Lon: -080° 41' 39"
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Temp Deviation	J	General/Bridges/Temp Deviation From: 2025-03-12 To: 2025-09-29 Location: 28.40925° N / 80.63224° W Bridge Name: 401 State Route Bridges From 7 a.m. on April 2, 2025, through 7 p.m. on September 28, 2025, the drawbridges will provide single-leaf openings with a 4-hour notice for a full opening, per its specific requirements 33 CFR 117.273(b). During this time, the channel will be partially obstructed under the spans painting is occurring. A one-hour advanced notice is required for vessels needing more than 45 feet of horizontal clearance but can safely pass with the spans in the down (closed) position.	Lat: 28° 24' 33" Lon: -080° 37' 56"
Canaveral Harbor - Canaveral Barge Canal/General/Bridges/Repairs, Painting, Or Fender Replacement	J	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2025-03-12 To: 2025-10-18 Location: 28.40925° N / 80.63224° W Bridge Name: 401 State Route Bridges A painting/repair project begins on April 1, 2025, and will be completed on or around October 18, 2025. During the time the bridges will be operating under a temporary deviation to drawbridges operations. The contractor will be on-site 24 hours a day. All in-water equipment should be lighted in accordance with Inland Navigation Rules. Mariners are advised to use caution when transiting through the bridges.	Lat: 28° 24' 33" Lon: -080° 37' 56"

Canaveral Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Canaveral Harbor Entrance Channel Light 14	9655	LT EXT	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Canaveral Harbor Entrance Channel Lighted Buoy 13	9650	RELOCATED FOR DREDGING	FD
Canaveral Harbor Entrance Channel Lighted Buoy 13	9650	RELOCATED FOR DREDGING	FD

Cape Haze Shoal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Haze Shoal Light 5	19990	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Burnt Store Marina Light 2	20000	LT EXT	PA
Burnt Store Marina Daybeacon 5	20015	STRUCT DEST	PA
Alligator Creek Daybeacon 23	20305	STRUCT DMGD	PA
Alligator Creek Daybeacon 24	20310	STRUCT DEST	PA
Pine Island West Channel Daybeacon 5	56510.1	STRUCT DEST/HAZ NAV	PA

Capri Pass

NAME	LLNR	STATUS	AID TYPE
Capri Pass Light 3	16955	TRLB/STRUCT MISSING	FD
Capri Pass Light 4	16960	STRUCT MISSING/TRLB	FD

Capri Pass Daybeacon C	16980	TRLB	FD
Capri Pass Shoal Daybeacon B	17050	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Addison Bay Daybeacon 1	16901.1	STRUCT DEST	PA
Addison Bay Daybeacon 2	16901.2	STRUCT DEST	PA
Addison Bay Daybeacon 4	16901.4	STRUCT DEST/HAZ NAV	PA
Addison Bay Daybeacon 5	16901.5	STRUCT DEST	PA
South Point North Obstruction Daybeacon	16961	STRUCT DEST/HAZ NAV	PA
South Point S. Obstruction Daybeacon	16962	STRUCT DEST/HAZ NAV	PA
Royal Marco Point North Obstruction Daybeacon	16986	STRUCT DEST	PA
Royal Marco Point S. Obst. Daybeacon	16987	STRUCT DEST	PA
Collier Bay Daybeacon 13	17021	DAYMK MISSING	PA
Collier Bay Daybeacon 15	17023	DAYMK MISSING	PA
Factory Bay E Channel Daybeacon 2	17070	DBD DMGD	PA
Factory Bay E Channel Daybeacon 4	17075	DBD DEST	PA

Captiva Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Captiva Channel Daybeacon 5	55620	STRUCT DEST	PA

Caxambas Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Blackwater River Daybeacon 10	16505	DAYMK MISSING	PA
Blackwater River Daybeacon 11	16510	STRUCT DEST/HAZ NAV	PA
Blackwater River Daybeacon 13	16520	STRUCT DEST	PA
Blackwater River Daybeacon 15	16530	STRUCT DEST	PA
Blackwater River Daybeacon 22	16555	STRUCT DEST	PA
Blackwater River Daybeacon 24	16565	STRUCT DEST/HAZ NAV	PA
Caxambas Bay South Approach Daybeacon 2	16675	STRUCT DEST	PA
Caxambas Bay Daybeacon 11	16715	DAYMK MISSING	PA
Horrs Island North Channel Daybeacon 8	16790	STRUCT DEST/HAZ NAV	PA
Snook Hole Channel Daybeacon 1	16790.010000000002	STRUCT DEST	PA
Snook Hole Channel Daybeacon 4	16790.04	STRUCT DEST/HAZ NAV	PA
Big Marco River Daybeacon 3	16800	STRUCT DEST	PA
Moran's Marina Channel Daybeacon 1	16835	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 2	16840	DAYMK MISSING	PA
Moran's Marina Channel Daybeacon 3	16845	DAYMK MISSING	PA
Big Marco River Daybeacon 16	16860	STRUCT DEST	PA
Big Marco River Daybeacon 21	16880	STRUCT DMGD	PA
Big Marco River Daybeacon 26	16900	STRUCT DEST/HAZ NAV	PA

Cedar Keys Main Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys Main Channel Daybeacon 8	29770	STRUCT MISSING/TRUB	FD
Cedar Keys Main Channel Light 14	29790	STRUCT MISSING/TRLB	FD
Cedar Keys Main Channel Light 18	29800	STRUCT MISSING/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Cedar Keys Main	Hazards To	General/Hazards To Navigation/Hazards From: 2024-12-06 To: 2025-06-04 Location: 29.11403° N / 83.04028° W Cedar Key Main	Lat:
Channel/General/Hazards To	Navigation	Channel 19A has been temporarily established to guide vessel traffic channel ward and away from submerged wreckage between Cedar	29° 06' 51"
Navigation/Hazards		Keys Main Channel Daybeacon 19 (LLNR 29805) and Cedar Keys Main Channel Light 21 (LLNR 29810). All mariners are advised to transit	Lon:
		the area with caution.	-083° 02'
			25"

https://www.navcen.uscg.gov/msi 11/73

Cedar Keys Northwest Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys Northwest Channel Daybeacon 14	29965	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Daybeacon 17	29980	STRUCT MISSING/TRUB	FD
Cedar Keys Northwest Channel Light 19	29995	STRUCT DEST/HAZ NAV/TRLB	FD
Cedar Keys Northwest Channel Daybeacon 21	30005	TRLB/STRUCT DEST/HAZ NAV	FD
Cedar Key Northwest Channel Daybeacon 22	30010	TRLB/HAZ NAV/STRUCT DEST	FD

Cedar Keys South Bar Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cedar Keys South Bar Channel Daybeacon 4	29900	STRUCT MISSING	FD

Charleston Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charleston Entrance Lighted Buoy C	200	RAC INOP	FD
Charleston Harbor Channel Lighted Buoy 17	2415	OFF STATION	FD
Charleston Harbor Channel Lighted Buoy 24	2470	OFF STATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Advanced Notice of Change		Charleston Harbor Channel LB 18 (LLNR 2420) will have the bell permanently removed.	Lat: 32° 43' 27" Lon: -079° 48' 37"
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/ATON/Advanced Notice of Change		Charleston Harbor Channel LB 22 (LLNR 2440) will have the bell permanently removed.	Lat: 32° 44' 26" Lon: -079° 50' 41"
Sector Charleston, Submerged Land Act (SLA) - Charleston Harbor/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.75328° N / 79.87473° W 32.75232° N / 79.87355° W 32.75075° N / 79.87546° W 32.75198° N / 79.87705° W 32.75328° N / 79.87473° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 31October 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.	

Charleston Harbor North Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bennis Reach Range Rear Light	2506	LT EXT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Bennis Reach Range Front Light	2505.5	RELIGHTED	FD	2025-07-24

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor - Charleston Harbor North Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	mounted on opposite corners of the platform with both lights synchronized.	Lat: 32° 47' 18" Lon: -079° 55' 29"
Charleston Harbor - Charleston Harbor North Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	Charleston. The flash characteristics of the optic will remain a R Iso 6s.	Lat: 32° 47' 24" Lon: -079° 55' 43"

https://www.navcen.uscg.gov/msi

Charleston Harbor - Charleston Harbor	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To:	
North Channel/General/Marine Construction	Construction	2026-11-13 Location: 32.78003° N / 79.92337° W 32.77867° N / 79.9233° W 32.77871° N / 79.92452° W 32.77997° N /	
(Excluding Bridges)/Facilities, Barriers,	(Excluding Bridges)	79.92455° W 32.78003° N / 79.92337° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and	
Manmade Reefs, Riprap, Jetties/Dikes		rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and	
		crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project	
		is 31October 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-	
		FM channels 13 and 16.	

Charleston Harbor Savannah River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ramshorn Creek Light 39	35825	STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parris Island Fish Haven Buoy	35600	MISSING	PA
Braddock Cove Creek Jetty Light	35815.5	LT IMCH	PA

Charleston Harbor South Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charleston Harbor South Channel Daybeacon 6	2685	STRUCT DEST/TRUB	FD

Charlotte Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Charlotte Harbor Channel Lighted Buoy 5	19935	MISSING	FD

Chokoloskee Bay Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
National Park Service Boat Basin South Channel Daybeacon 1	16105	STRUCT DEST	PA
National Park Service Boat Basin South Channel Daybeacon 5	16125	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 1	16135	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 2	16140	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 5	16150	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 6	16155	STRUCT DEST	PA
National Park Service Boat Basin West Channel Daybeacon 7	16160	STRUCT DEST	PA

Christiansted Harbor Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Christiansted Schooner Channel Lighted Buoy 5	32950	OFF STA/LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 6	32955	LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 10	32980	LT EXT	PA
Christiansted Schooner Lighted Buoy 11	32985	LT EXT	PA
Christiansted Schooner Channel Lighted Buoy 7	32965	BUOY DMGD	PA

Clarks Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clarks Creek Lighted Buoy 6	2247	MISSING	FD

Clearwater Harbor

NAME	LLNR	STATUS	AID TYPE
Clearwater Harbor Light 4	61725	STRUCT MISSING/TRLB	FD
Clearwater Wreck Light WR14A	61805	STRUCT MISSING/TRLB	FD

Clearwater Harbor Daybeacon 20 61847 STRUCT DEST/TRUB FD

Clearwater Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clearwater Pass Channel Light 7	25700	STRUCT DMGD	FD

Clewiston Channel Route 1B

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Clewiston Channel (Rt 1B) Daybeacon 5	51275	STRUCT DEST/TRLB	FD
Clewiston Channel (Rt 1B) Daybeacon 9	51295	STRUCT DEST	FD
Clewiston Channel (Rt 1b) Light 12	51340	STRUCT DMGD	FD
Clewiston Channel (Rt 1B) Daybeacon 14	51350	STRUCT DEST/TRUB	FD

Cooper River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cooper River Range B Rear Light	2970	LT EXT	FD
Cooper River Daybeacon 114	3243	STRUCT DMGD	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Cooper River Range A Rear Light	2940	RELIGHTED	FD	2025-08-03
Cooper River Lighted Buoy 75	3065	RELIGHTED	FD	2025-07-27

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Don Holt I-526 Bridge Racon	2905.5	RAC INOP	PA
Cooper River Ammunition Pier Light	3015	LT EXT	PA
South Carolina Gas & Dry Elec North Pier Light	3260	LT EXT	PA
South Carolina Gas & Dry Elec South Pier Light	3265	LT EXT	PA
Upper Cooper River Daybeacon 12	3287.8	STRUCT DEST	PA
Upper Cooper River Daybeacon 22	3288.5	DAYMK DMGD	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 2786 Location: 32.85289° N / 79.94381° W The USCG will be demolishing, rebuilding and dredging pier november in approximate position 32-51-09.7N/079-56-48.8W. The contractor is getting ready to remove the old Pier N "mega dolphin" which represents the old pier's closest point to the Clouter Creek Reach Channel. Operations are expected to commence January 15, 2024, with an estimated completion date of December 31, 2026. During the construction phase operations will be conducted Monday-Friday 7 a.m. to 7 p.m., during dredging operations may be continuous 24 hours a day/ 7 days a week. For further information contact: LCDR John Houk at John.R.Houk@uscg.mil.	Lat: 32° 51' 12" Lon: -079° 56' 45"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 9392 Location: 32.8512° N / 79.94134° W Demolition is now in progress and there are cut piles that may be difficult to see at higher tide within the footprint of the old Pier Romeo. The Manson Construction Team has posted (1) "Danger" Buoy and an Amber Light for demarcation on the outermost submerged piles and obstructions. These markers are attached to a 36-inch diameter steel pile that stands about 20 feet above the water line and among the submerged objects. Beginning October 30, 2024, and ending October 30, 2026, Manson Construction will be performing demolition of the existing pier and construction of a new pier, bulkhead, and shoreline at the Romeo Pier NOAA Facility on the Cooper River. There will be a crane barge, material barges, and support vessels in the area assisting construction operations from 7a.m. to 7p.m., 7 days a week. These activities could pose a hazard to vessels traveling within 900 feet from the bulkhead to the center of the river. Mariners need to take caution when transiting the area. Please watch for dive flags, stay clear of the construction area, and away from any working equipment. Crews will be monitoring VHF-FM channel 61. For more information, please contact Doug Lowe at (904) 465-1762.	Lat: 32° 51' 04" Lon: -079° 56' 29"
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 13304 SOUTHERN DREDGING CO. INC. DREDGE BRUNSWICK will be conducting maintenance dredging in Berth 1 and 2 of the Charleston Midstream Transfer Facility in Range A of the Charleston Naval Weapons Station Channel between Cooper River Lighted Buoy 62 (LLNR 2930) and Cooper River Lighted Buoy 64 (LLNR 2945) commencing on or about July 16, 2025. The dredge will have submerged pipeline along the West bank of Clouter Island to Cooper River Lighted Buoy 52 (LLNR 2855). The Dredge will operate on a 24 hour per day, 7 day per week basis until approximately August 2, 2025. To ensure safe passage in the vicinity of the operation, boaters should establish contact with the dredge on VHF marine channels 13 and 16 or by telephone at 843-729-1691.	
Charleston Harbor - Cooper River/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 18251 Orion Marine Construction, Inc. will begin construction work at the Hugh K. Leatherman, Sr. Terminal located along the western shore of the Cooper River, North Charleston, SC at (32° 50' 28N/079° 55' 58W). Within the scope of the jobsite, there will be temporary steel structures that will be periodically move as the job progresses. The structures will display a FL 2.5 W, 2NM lights. Operations will consist of dredging, armor stone slope protection installation, pile driving, and new wharf construction. Operations at the project site will commence in May 2025 and will extend through December 2026. Tugboats will monitor VHF channel 13. Mariners are urged to use extreme caution when transiting the work area. For more information, contact the Project Superintendent, Dustyn Fields at dfields@orionmarinegroup.com, or Project Manager, Tyler Satterfield at tsatterfield@orionmarinegroup.com.	

Charleston Harbor - Cooper River/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change Location: 32.9403° N / 79.92368° W Aid Name: Cooper River Range D Rear Light LLNR: 3045 Action: RELOCATE The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Cooper River: Cooper River Range D Rear Light (LLNR 3045) will be permanently relocated to approximate position 32-56-27.083N / 079-55-21.194W. Cooper River Range D/F Front Light (LLNR 3040) will have the flash characteristic changed from a Q W to a FL W 2.5s. The light will continue to be an all-around light. Due to the current location of Cooper River Range D Rear Light (LLNR 30465) being inaccessible for a Coast Guard asset to effectively repair the structure, it was determined by relocating the rear range approximately 400 feet further from its current location will offer a much improved range quality and allow CG personnel to service at any tidal state. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with Cooper River Range D/F as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL. 33131-3050 to be received by July 31, 2025.	
Charleston Harbor - Cooper River/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change Location: 32.93982° N / 79.92463° W Aid Name: Cooper River Range D/F Front Light LLNR: 3040 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard is proposing the following changes to the Aids to Navigation System in the Cooper River: Cooper River Range D Rear Light (LLNR 3045) will be permanently relocated to approximate position 32-56-27.083N / 079-55-21.194W. Cooper River Range D/F Front Light (LLNR 3040) will have the flash characteristic changed from a Q W to a FL W 2.5s. The light will continue to be an all-around light. Due to the current location of Cooper River Range D Rear Light (LLNR 30465) being inaccessible for a Coast Guard asset to effectively repair the structure, it was determined by relocating the rear range approximately 400 feet further from its current location will offer a much improved range quality and allow CG personnel to service at any tidal state. All comments should be emailed to: d07-smb-dpwpubliccomments@uscg.mil or andrew.m.engle@uscg.mil with Cooper River Range D/F as the subject line. Comments can also be mailed to Commander (dpw), Seventh Coast Guard District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Building, Miami, FL. 33131-3050 to be received by July 31, 2025.	

Coosaw River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Parrot Creek Daybeacon 3	35235	STRUCT DEST	PA

Cowpens

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cowpens Daybeacon 73A	50605	STRUCT DEST/HAZ NAV/TRLB	FD

Cranes Bayou

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dock On The Bay Daybeacon 7	59015	DAYMK MISSING	PA

Cross Florida Greenway

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cross Florida Greenway Daybeacon 27	29265	STRUCT DEST/TRUB	FD
Cross Florida Greenway Daybeacon 33	29295	STRUCT MISSING	FD
Cross Florida Greenway Daybeacon 36	29310	STRUCT DEST	FD

Cruz Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cruz Bay Light	32775	DAYMK MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cruz Bay Buoy 2	32785	OFF STA	PA

Crystal River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Crystal River Entrance Daybeacon 12	28845	DAYMK MISSING	FD
Crystal River Entrance Daybeacon 14	28855	STRUCT MISSING/TRUB	FD

NAME	LLNR	STATUS	AID TYPE
Crystal River Daybeacon 9	28912.60000000002	DBD DMGD	PA
Crystal River Daybeacon 25	28952.600000000002	STRUCT DEST	PA

Cumberland Dividings

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland Dividings Light 63A	37625	STRUCT DEST	FD

Cumberland River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland River Light 33	37390	STRUCT DEST/TRLB	FD
Cumberland River Light 35	37405	STRUCT MISSING/TRLB	FD
Cumberland River Light 46	37540	STRUCT MISSING/TRLB	FD
Cumberland River Daybeacon 51	37560	STRUCT DEST/TRUB	FD
Cumberland River Daybeacon 58A	37603	STRUCT DEST/HAZ NAV/TRLB	FD
Cumberland River Daybeacon 59A	37607	STRUCT DEST/TRUB	FD
Cumberland River Light 60	37610	STRUCT DEST/TRLB	FD
Cumberland River Daybeacon 63	37623	STRUCT DEST/TRUB	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Cumberland River Temporary Buoy 47A	null	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Andrew Sound - Cumberland	Advanced Notice	Cumberland River LT 35 (LLNR 37405) will be relocated due to the water depth at current location being too deep for CG assets to effect	Lat:
River/ATON/Advanced Notice of	of Change	repairs. The aid will be relocated approximately 453 yards south of its current location in a depth of 15 feet. This change will ensure safe	30° 57' 15"
Change		navigation and keep the same alignment with the surrounding aids in the Cumberland River. Cumberland River LT 35 (LLNR 37405) will	Lon:
		be relocated to approximate position 30-57-14.700N/081-25-44.460W.	-081° 25'
			44"

Cumberland Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cumberland Sound Upper Range A Rear Light	6695	STRUCT DEST	FD
Cumberland Sound Shoal Light A	6773	STRUCT DEST	FD
Cumberland Sound Shoal Light B	6837	STRUCT DEST	FD
Cumberland Sound Shoal Light D	6867	STRUCT DEST	FD
Cumberland Sound Shoal Light G	6892	STRUCT DEST	FD
Cumberland Sound Shoal Light H	6894	STRUCT DEST/TRLB/MISSING	FD
Cumberland Sound Range D Front Light	6905	HAZ NAV/STRUCT DEST/TRLT	FD
Cumberland Sound Shoal Light I	6927	STRUCT DEST	FD
Cumberland Sound Range F Front Light	37645	LT EXT	FD

Cut A Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Skyway Pier Southeast Light	22425	LT EXT	PA
Tampa Bay Skyway Pier Northeast Light	22430	LT EXT	PA

Cut G Channel

NAME	LLNR	STATUS	AID TYPE
Smacks Bayou Daybeacon 1	25025	STRUCT DEST	PA
Smacks Bayou Daybeacon 5	25025.4	STRUCT DEST	PA
Smacks Bayou Daybeacon 6	25025.5	DAYMK MISSING	PA
Smacks Bayou Daybeacon 8	25025.600000000002	STRUCT DEST	PA
Smacks Bayou Daybeacon 13	25025.9	STRUCT DEST	PA
Smacks Bayou Daybeacon 14	25026	HAZ NAV/DAYMK MISSING	PA
Smacks Bayou Daybeacon 15	25026.100000000002	DAYMK MISSING	PA
Smacks Bayou Daybeacon 16	25026.2	DAYMK MISSING	PA
Smacks Bayou Daybeacon 3	25025.2	STRUCT DEST	PA

Smacks Bayou Daybeacon 10	25025.7	STRUCT DEST/HAZ NAV	PA	

Cut K Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tampa Bay Cut K Channel Lighted Buoy 10K	23930	WATCHING PROPERLY	FD	2025-07-28

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rattlesnake Channel Daybeacon A	23814	DAYMK IMCH	PA
Westshore Yacht Club Light 2	23814.10000000002	STRUCT DEST	PA
Westshore Yacht Club Daybeacon 4	23814.2	STRUCT DEST	PA
Old Tampa Bay Pipeline West Light	23950.5	STRUCT DEST/HAZ NAV	PA
Culbreath Bayou North Daybeacon 3	24070	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 3	25045	DAYMK DMGD	PA
Bayou Grande Channel Daybeacon 9	25065	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 21	25105	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 30	25150	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 31	25155	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 41	25200	STRUCT DEST	PA
Bayou Grande Channel Daybeacon 48	25230	STRUCT DEST/HAZ NAV	PA
Mobel Americana Channel Daybeacon 3	25260.2	DAYMK MISSING	PA
Tanglewood Channel Daybeacon 1	25265	STRUCT DEST	PA
Bay Crest Daybeacon 5	24275	DAYMK MISSING	PA
Bayou Grande Channel Daybeacon 2	25040	STRUCT DEST	PA

Additional MSI Categories

	•						
TITLE	SUBCATEGORY	DESCRIPTION	LOCATION				
Tampa Bay Cut J Channel - Cut K Channel/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2024-11-19 To: 2025-09-30 Location: 27.92889° N / 82.58725° W Bridge Name: Howard Frankland I-275 Bridges Construction of the new I-275 Howard Frankland Bridge crossing Old Tampa Bay is ongoing. Bridge work will be performed 24 hours per day, Monday through Saturday, 7/30/2025 THROUGH 12/31/2025 CHANNEL TRAFFIC WILL BE OBSTRUCTED	Lat: 27° 55' 44" Lon:				
		DURING DEOMOLITION OF THE 60'S BRIDGE (SOUTHERN MOST BRIDGE). INSTALLATION OF THE FENDER SYSTEM ON THE NEW HOWARD FRANKLAND BRIDGE TO CONTINUE AS WELL. WE WILL HAVE TUGBOATS ACTIVELY WORKING EVERY SHIFT WHILE THE CHANNEL IS OBSTRUCTED AND BARGES CAN BE MOVED OUT OF THE CHANNEL WITHIN 30 MINUTES TO AN HOUR. DURING CONSTRUCTION THE CHANNEL WILL BE IMPEDED BY ~5'-0" ON BOTH SIDES OF THE CHANNEL FOR INSTALLATION OF A PILE TEMPLATE. THIS IMPEDENCE IS ON THE EAST AND WEST SIDE OF THE FENDER SYSTEM. TEMPLATES MAY BE INSTALLED UP TO 24 HOURS A DAY UNTIL CONSTRUCTION IS COMPLETE. VHF RADIO CHANNELS MONITORED: 13, 22A, AND 16	-082° 35'				

Darien River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Darien River Daybeacon 17	36826.70000000004	STRUCT DEST/TRUB	FD

Dawho River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dawho River Daybeacon 118	34975	TRUB/STRUCT DEST	FD

Derrick Key Gap Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Derrick Key Gap Channel Daybeacon 2	30055	STRUCT DEST	FD
Derrick Key Gap Channel Daybeacon 3	30060	TRLB/STRUCT MISSING	FD

District 7, Oceanic boundary to EEZ

NAME	LLNR	STATUS	AID TYPE
St Nicolas Point Channel Light 4	33400	STRUCT DEST/HAZ NAV/TRLB	FD
St Nicolas Point Channel Light 7	33415	STRUCT DEST/TRLB	FD
Guantanamo Bay Lighted Buoy 7	33455	LT EXT	FD
Radio Point Light 1	33490	LT EXT	FD

Evans Point Light 8	33530	DBD DEST	FD
Guantanamo Bay Lighted Buoy 9	33540	LT EXT	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Nicolas Point Channel Lighted Buoy 6	33410	RELOCATED FOR DREDGING	FD

Doboy Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Buoy 2	5920	OFF STA	FD
Doboy Sound Buoy 3	5925	MISSING	FD
Doboy Sound Buoy 4	5930	OFF STA	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Island LT	5946	LT EXT	PA

Drummond Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Range Front Light	7515	STRUCT DEST/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Drummond Creek Cut Lighted Buoy 59	7500	RESET ON STATION	FD	2025-07-28

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Drummond Creek Lighted Buoy 61	7525	RELOCATED FOR DREDGING	FD
Drummond Creek Lighted Buoy 58	7505	RELOCATED FOR DREDGING	FD

Additional MSI Categories

		_		
	TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
S	St Johns River - Drummond	Advanced Notice	Drummond Creek RFL (LLNR 7515) will be permanently relocated to approximate position 30-24-45.104N / 081-35-35.319W. The RFL will	Lat:
C	Creek/ATON/Advanced Notice	of Change	remain a nighttime optic only and flash characteristic will remain as a Q R. The RFL will continue to display daymarks for the day-time signal.	30° 24' 44"
С	of Change		Both Drummond Creek RFL and RRL will be upgraded with LED light signals to provide a much more reliable signal when using this channel.	Lon:
			An additional light will be established and mounted on top of the Drummond Creek RFL optic and synchronized with the RFL to display a Q R	-081° 35'
			flash characteristics during nighttime hours only, with a nominal range of 3NM.	38"

Dumfoundling Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dumfoundling Bay Daybeacon 50	47700	STRUCT DEST/TRUB	FD

Duplin River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Doboy Sound Light 178	36795	STRUCT MISSING/TRLB	FD

East Cape

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
East Cape Daybeacon 1A	15655	STRUCT DEST/HAZ NAV/TRUB	FD

Elba Island Cut

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Lower Flats Range - Elba	Advanced Notice	ATON/Advanced Notice of Change Location: 32.06387° N / 80.99495° W Aid Name: Elba Island Cut Light 10 LLNR: 35900 Action: CHANGE	Lat:
Island Cut/ATON/Advanced	of Change	Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system in the Intracoastal Waterway	32° 03' 50"
Notice of Change		Elba Island Cut Channel, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current	Lon:
		nominal range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted	-080° 59'
		aids to navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate.	42"

Elliott Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elliott Key Daybeacon 15	10935	STRUCT DEST/TRUB/HAZ NAV	FD
Elliott Key Light 16	10940	DAYMK MISSING/STRUCT DMGD/TRLB	FD
Elliott Key Daybeacon 19	10955	STRUCT DEST/HAZ NAV/TRLB	FD
Pacific Reef Daybeacon 3	10965	STRUCT DEST	FD

Entrada Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southwest Shoals Daybeacon	49280	HAZ NAV/STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Entrada Channel Daybeacon 1	49240	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 3	49245	STRUCT DEST/HAZ NAV	PA
Entrada Channel Daybeacon 5	49250	DAYMK MISSING	PA
Entrada Channel Daybeacon 7	49255	DAYMK MISSING	PA
Entrada Channel Daybeacon 9	49260	DAYMK MISSING	PA
Entrada Channel Daybeacon 11	49265	DAYMK MISSING	PA
Entrada Channel Daybeacon 13	49270	DAYMK MISSING	PA

Fields Cut

Additional MSI Categories

	y			
TITLE		SUBCATEGORY	DESCRIPTION	LOCATION
	Lower Flats Range - Fields Cut/General/Hazards To	Hazards To	General/Hazards To Navigation/Shoaling Reported 21052 Location: 32.08666° N / 80.9333° W	Lat:
	Navigation/Shoaling Reported	Navigation	Shoaling reported 3 FT at MLW	32° 05' 12"
				Lon:
				-080° 55' 60"

Fishermans Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fishermans Channel Light 11	10685	STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dodge Island Mooring Obstruction Light	10692	STRUCT DEST	PA

Florida Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Long Key Light 44	13495	STRUCT DEST/HAZ NAV/TRLB	FD
East Turtle Shoal Light 45	13610	STRUCT DEST/HAZ NAV/TRLB	FD

NAME	LLNR	STATUS	AID TYPE
Flamingo Channel Light 9	15680	DAYMK MISSING	PA
Flamingo Channel Light 15	15710	STRUCT DEST	PA
Flamingo Channel Daybeacon 16	15715	DAYMK MISSING	PA
Coot Bay Daybeacon 2	15730	STRUCT DEST	PA
Coot Bay Daybeacon 8	15755	DAYMK MISSING	PA

Florida Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Florida Passage Daybeacon 102	36385	STRUCT MISSING/TRUB	FD

Floyd Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Floyd Creek Daybeacon A27	37496	STRUCT DEST/TRUB	FD

Folly River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Folly River Buoy 19	3760	OFF STATION	FD

Fort Gates

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Gates Light 67	8525	STRUCT DEST/TRLB	FD

Fort Jackson

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Jackson Inbound Range Front Light	4955	STRUCT MISSING	FD

Frederica River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
		555	7.1.2
Frederica River Daybeacon 7	6165	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fredericka Yacht Club Obstruction Light	6170	LT EXT	PA

Fulton Cutoff

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fulton Cutoff Light 36	7360	STRUCT DEST/TRLB	FD

Additional MSI Categories

	-		
TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
St Johns River - Fulton	Advanced Notice	Fulton Cutoff LB 35 (LLNR 7345) will be permanently relocated to 30-23-24.090N/081-30-22.230W. This change calls to relocate (6) lighted	Lat:
Cutoff/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 24"
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe	Lon:
		navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this	-081° 30'
		change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.	22"
St Johns River - Fulton	Advanced Notice	Blount Island Turning Basin LB 43 (LLNR 7385) will be permanently relocated to 30-23-13.450N/081-32-05.380W. The flash characteristic will	Lat:
Cutoff/ATON/Advanced Notice	of Change	remain a FI G 6s, but the nominal range will be reduced from 5NM to 4NM.	30° 23' 13"
of Change			Lon:
			-081° 32'
			05"

Gables Estates

NAME	LLNR	STATUS	AID TYPE
Gables Estates Light 2	49340	LT EXT	PA
Gables Estates Daybeacon 2A	49345	STRUCT DEST/HAZ NAV	PA

Gadsden Point Cross Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gadsden Point Cross Channel Daybeacon 10	22965	STRUCT MISSING/TRUB	FD

Gadsden Point Cut

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Gadsden Point Cut Range Rear Light	22855	RELIGHTED	FD	2025-07-30
Gadsden Point Cut Lighted Buoy 6	22885	RELIGHTED	FD	2025-07-24

Garden Cove

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Garden Cove Daybeacon 3	11550	DAYMK MISSING	PA
Garden Cove Daybeacon 4	11555	DBD DEST	PA
Garden Cove Daybeacon 4	11555	DAYMK IMCH/STRUCT DMGD	PA
Garden Cove Daybeacon 6	11565	STRUCT DEST/HAZ NAV	PA
Garden Cove Daybeacon 8	11575	DAYMK IMCH	PA
Garden Cove Daybeacon 9	11580	DAYMK MISSING	PA
Garden Cove Daybeacon 11	11590	RBN IMCH	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Garden Cove/General/Marine	Marine Construction	General/Marine Construction (Excluding Bridges)/Survey Operations 21792 Fugro USA Marine inc will be conducting hydrographic surveys	
Construction (Excluding	(Excluding Bridges)	from the Florida Keys west and south coast up the east coast to Port Canaveral, FL. Operations are expected to begin on or about June 22,	
Bridges)/Survey Operations		2025, with an estimated completion date of December 31, 2025, and be conducted. R/V RENEGADE and R/V INVADER will be operating	
		Multi Beam Echo Sounders and deploying sound velocity profilers from stern 7 days a week, 24 hours day. They will be monitoring VHF-FM	
		channel 16. Average vessel speed will be 10-14 knots with sensor down. Maximum vessel speed is 24 knots during transits.	

Gasparilla Sound Channel

Federal Discrepancies

The state of the s			
NAME	LLNR	STATUS	AID TYPE
Gasparilla Sound Channel Light 20	56645	DBD DMGD	FD
Gasparilla Sound Channel Daybeacon 21	56650	STRUCT MISSING/TRUB	FD
Gasparilla Sound Channel Daybeacon 30	57070	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gasparilla Island South Obstruction Light	1305.2	LT EXT	PA
Gaparilla Island West Obstruction Light	1305.4	LT EXT	PA
Gasparilla Island North Obstruction Light	1305.6000000000001	LT EXT	PA
Gasparilla Marina Channel Daybeacon 6	56715	STRUCT DEST	PA

Gordon Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gordon Pass Channel Buoy 1	17453	MISSING	FD
Gordon Pass Channel Light 3	17460	STRUCT MISSING/TRLB	FD

Great Pocket

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Great Pocket Daybeacon 10	45970	STRUCT DEST/TRUB	FD

Grouper Creek

Federal Discrepancies

	NAME	LLNR	STATUS	AID TYPE
--	------	------	--------	----------

https://www.navcen.uscg.gov/msi 21/73

Grouper Creek Daybeacon 52A	50425	STRUCT DEST/HAZ NAV/TRLB	FD	

Gunnison Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gunnison Cut Daybeacon 59	38220	STRUCT DEST	FD

Halifax River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax River Daybeacon 40	40180	STRUCT DMGD	FD
Halifax River Daybeacon 48	40215	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 53	40235	STRUCT MISSING/TRUB	FD
Halifax River Daybeacon 56	40245	STRUCT MISSING/TRUB	FD
Halifax River Daybeacon 57	40335	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 60	40435	STRUCT DEST/TRUB	FD
Halifax River Daybeacon 72	40490	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Halifax Harbor Daybeacon 1	40055	DAYMK MISSING	PA
Halifax Harbor Daybeacon 4	40070	DAYMK MISSING	PA
Halifax Harbor Daybeacon 6	40080	DAYMK MISSING	PA
Halifax Harbor Daybeacon 8	40090	STRUCT DEST	PA
Halifax Harbor Daybeacon 9	40095	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 4	40365	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 6	40375	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 7	40380	STRUCT DEST	PA
Adventure Yacht Harbor Daybeacon 8	40385	DAYMK MISSING	PA
Adventure Yacht Harbor Daybeacon 9	40390	DAYMK MISSING	PA
Adventure Yacht Harbor Junction Daybeacon	40410	DAYMK IMCH	PA

Hampton River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hampton River Daybeacon 12	5975	STRUCT DEST/TRUB	FD

Hillsboro Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Inlet Entrance Light 2	10293	DBD DEST	FD

Hillsboro River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro River Light 73	47225	DBD DMGD	FD
Pompano Beach Light 76	47235	HAZ NAV/STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Moran Dock North Light	47175	LT IMCH	PA
Moran Dock Center Light	47180	LT IMCH	PA
Moran Dock South Light	47185	LT EXT	PA

Hillsborough Cut C Channel

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut C Channel Outbound Range Front Light	23185	LT EXT	FD

Hillsborough Cut C Channel Inbound Range Front Light 23435 LT EXT FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Yacht & Daybeacon 4	23454	STRUCT DEST	PA
Hookers Point North Warning Daybeacon	23515	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Big Bend Channel - Hillsborough Cut C Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 27.90797° N / 82.43823° W Aid Name: Hillsborough Cut C Channel Inbound Range Front Light LLNR: 23435 Action: CHANGE Action Type Change Light Characteristic Hillsborough Cut C Channel Inbound Range Front Light (LLNR 23435) characteristic will change to Iso W 2s (NIGHT) and Iso W 2s (Day).	Lat: 27° 54' 29" Lon: -082° 26' 18"
Big Bend Channel - Hillsborough Cut C Channel/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 27.92022° N / 82.43696° W Aid Name: Hillsborough Cut C Channel Inbound Range Rear Light LLNR: 23440 Action: CHANGE Action Type Change Light Characteristic Hillsborough Cut C Channel Inbound Range Rear Light (LLNR 23440) characteristic will change to Iso W 6s (NIGHT) and Iso W 6s (Day).	Lat: 27° 55' 13" Lon: -082° 26' 13"
Big Bend Channel - Hillsborough Cut C Channel/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Orion Marine Group is currently contracted by the Tampa Bay Port Authority, operating as Port Tampa Bay, to construct the new berth (Berth 218 Wharf) at the Titan America facility. Orion respectfully requests that a revised Notice to Mariners be issued concerning our construction operations at 4231 Maritime Boulevard, Tampa, FL, specifically for Berth 218 Wharf. The construction activities will be conducted using the ORION IS-1505 Barge, a rental material barge from McDonough Marine Services (unnamed), as well as the ORION BRAVE. Floating equipment will be positioned within the designated Jobsite Working Limits, as delineated in the attached drawing of the Berth 218 project site. Orion will deploy spuds on the ORION IS-1505 Barge, which will be equipped with illuminating lights to enhance visibility. All floating equipment will be staged east of the channel inlet and equipped with marine lights. The ORION BRAVE will operate under the "WDM4416" call sign and actively monitor channels 13, 16, and 74 for communications. Construction is scheduled from October 21, 2024, to November 15, 2025. During this timeframe, operations will occur from 6 a.m. to 6 p.m., six days per week (Monday through Saturday). The floating equipment will remain onsite for the duration of the project. Orion respectfully advises all mariners to exercise heightened caution when navigating the construction area. We kindly request that vessels reduce speed while transiting through the Port Tampa Bay channel at Berth 218.	

Hillsborough Cut D Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsborough Cut D Channel Outbound Range Front Light	23500	STRUCT DEST/HAZ NAV	FD
Hillsborough Cut D Channel Outbound Range Rear Light	23505	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bulk Liquid Cargo Dolphin 4 Obstruction Light	23530	STRUCT DEST	PA

Hillsborough River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Hillsborough Cut C Channel - Hillsborough River/General/Bridges/Repairs, Painting, Or Fender Replacement	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2025-06-30 To: 2025-11-01 Location: 27.9668° N / 82.47512° W Bridge Name: West Columbus Drive Bridge The replacement of the fender whales and nav lighting, is scheduled to begin August 11, 2025, through October 31, 2025. Work hours are Monday through Friday from 7 a.m. to 5 p.m. During this time, approximately 25 feet of the navigational channel will be available for navigation. Vessels needing the more than 25 feet or the full channel of 50 feet, will be required to provide a 2-hour notice. There will be no change to the drawbridge operating regulation. All in-water equipment will be properly lighted in accordance with Inland Navigation Rules. During non-work hours, all in-water equipment will not impede the navigational channel.	Lat: 27° 58' 00" Lon: -082° 28' 30"
Hillsborough Cut C Channel - Hillsborough River/General/Bridges/Public Notice	Bridges	General/Bridges/Proposal From: 2025-07-22 To: 2025-08-23 Location: 27.94295° N / 82.45892° W Bridge Name: Selmon Expressway Bridges The Coast Guard has issued a public notice announcing a bridge permit application from the Tampa Hillsborough Expressway Authority requesting approval of the location and plans for the modification of the South Selmon Expressway over the Hillsborough River, mile point 0.15, Hillsborough County, Florida. Public Notice 07-25 provides details of the proposed bridge project and solicits comments concerning the project. The public notice is available at: https://www.navcen.uscg.gov/bridge-notices	Lat: 27° 56' 35" Lon: -082° 27' 32"
Hillsborough Cut C Channel - Hillsborough River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-07-24 To: 2025-12-15 Location: 27.94174° N / 82.45855° W Bridge Name: Platt Street Bridge The bridge need not open to navigation during the following dates and times: - September 27, 2025, from 7 a.m. to 10 a.m. to facilitate the St. Jude Walk/Run October 11, 2025, from 7 a.m. to 10:30 a.m. to facilitate the TPD Memorial Run/Walk October 18, 2025, from 7:30 a.m. to 11 a.m. to facilitate the Walk to End Alzheimer's November 1, 2025, from 6:30 a.m. to 10 a.m. to 10 a.m. to facilitate the Bolt Run November 22, 2025, from 4 a.m. to 11 a.m. to facilitate Miles for Moffitt November 27, 2025, from 6 a.m. to 9 a.m. to facilitate the YMCA Turkey Gobble December 14, 2025, from 6:30 a.m. to 11 a.m. to facilitate the Hot Chocolate Runs. Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 27° 56' 30" Lon: -082° 27' 31"
Hillsborough Cut C Channel - Hillsborough River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-07-24 To: 2025-12-15 Location: 27.94343° N / 82.45907° W Bridge Name: Brorein Street Bridge The bridge need not open to navigation during the following dates and times: - September 27, 2025, from 7 a.m. to 10 a.m. to facilitate the St. Jude Walk/Run October 11, 2025, from 7 a.m. to 10:30 a.m. to facilitate the TPD Memorial Run/Walk October 18, 2025, from 7:30 a.m. to 11 a.m. to facilitate the Walk to End Alzheimer's November 1, 2025, from 6:30 a.m. to 10 a.m. to facilitate the Bolt Run November 22, 2025, from 4 a.m. to 11 a.m. to facilitate Miles for Moffitt November 27, 2025, from 6 a.m. to 9 a.m. to facilitate the YMCA Turkey Gobble December 14, 2025, from 6:30 a.m. to 11 a.m. to facilitate the Hot Chocolate Runs. Public vessels of the United States and vessels in distress shall be passed at any time.	Lat: 27° 56' 36" Lon: -082° 27' 33"

Hobe Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hobe Sound Daybeacon 44	46165	STRUCT DMGD	FD
Hobe Sound Daybeacon 38	46140	STRUCT DEST/TRLB/HAZ NAV	FD

Hollywood Beach

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Everglades - Hollywood	Bridges	General/Bridges/Temp Deviation From: 2025-07-16 To: 2025-08-09 Location: 26.03429° N / 80.11738° W Bridge Name: Sheridan Street	Lat:
Beach/General/Bridges/Temp Deviation		Bridge - AICW The bridge will provide single-leaf only openings on the quarter and three-quarter hour from 8 a.m. on Monday, August	26° 02' 03"
		4, 2025, through 7 p.m. on Friday, August 8, 2025. A full opening may be provided with a 24-hour advanced notice to the bridge	Lon:
		tender.	-080° 07'
			03"

Homosassa Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Homosassa Bay Buoy 7	28377	MISSING	FD
Homosassa Bay Buoy 11	28387	MISSING	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Homosassa Bay Light 18	28405	WATCHING PROPERLY	FD	2025-07-24
Homosassa Bay Light 26	28430	WATCHING PROPERLY	FD	2025-07-24

Homosassa River

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Homosassa River Daybeacon 28	28435	WATCHING PROPERLY	FD	2025-07-24
Homosassa River Lighted Buoy 30	28440	WATCHING PROPERLY	FD	2025-07-24

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Homosassa River Daybeacon 2	28715	STRUCT DEST/HAZ NAV	PA

Horseshoe Beach

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Horseshoe Beach Approach Daybeacon 4	30365	STRUCT MISSING/TRUB	FD
Horseshoe Beach Approach Light 7	30375	STRUCT MISSING/TRLB	FD
Horseshoe Beach Approach Light 9	30380	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Light 10	30385	TRLB/STRUCT DEST/HAZ NAV	FD
Horseshoe Beach Channel Daybeacon 12	30395	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 13	30400	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 14	30410	HAZ NAV/STRUCT DEST/TRUB	FD
Horseshoe Beach Channel Daybeacon 15	30420	STRUCT MISSING/TRLB	FD
Horseshoe Beach Channel Light 16A	30425	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 21	30445	STRUCT MISSING	FD
Horseshoe Beach Channel Daybeacon 23	30450	STRUCT MISSING	FD

Indian Key Pass

NAME	LLNR	STATUS	AID TYPE
Indian Key Pass Light 4	15980	STRUCT DEST	FD
Indian Key Pass Daybeacon 13	16020	STRUCT DEST/TRUB	FD

Indian River North Section

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Indian River (North Section) Light 1	41100	STRUCT DEST/TRLB	FD
Indian River (North Section) Light 7	41130	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 34	41315	STRUCT MISSING/TRUB	FD
Indian River (North Section) Daybeacon 44	41415	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 49	41430	DAYMK MISSING	FD
Indian River (North Section) Daybeacon 71	42090	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 79	42175	STRUCT DMGD	FD
Indian River (North Section) Daybeacon 81	42185	STRUCT DEST/TRUB	FD
Indian River (North Section) Light 83	42190	LT EXT	FD
Indian River (North Section) Daybeacon 91	42270	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 94	42280	STRUCT DEST/TRUB	FD
Indian River (North Section) Daybeacon 99	42335	STRUCT DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jones Point Channel Buoy 1	41495	MISSING	PA
Jones Point Channel Buoy 2	41500	MISSING	PA
POW-MIA Channel Danger Daybeacon A	42254	DAYMK MISSING	PA
POW-MIA Channel Danger Daybeacon D	42254.3	DAYMK MISSING	PA
POW-MIA Channel Danger Daybeacon E	42254.4	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 1	42286	DAYMK DMGD	PA
Grills Riverside Marina Daybeacon 3	42286.200000000004	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 4	42286.3	DAYMK MISSING	PA
Grills Riverside Marina Daybeacon 5	42286.4	HAZ NAV/DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Banana River - Indian River North	Bridges	General/Bridges/Construction From: 2024-11-12 To: 2026-04-30 Location: 28.527349° N / 80.765526° W Bridge Name: NASA	Lat:
Section/General/Bridges/Construction		Causeway Bridges - AICW Construction continues on the new high-level bridges which is expected to be completed April 2026. The	28° 31' 38"
		navigational clearances provide a fixed vertical clearance of 66 feet at mean high water and 125 feet between the new fender	Lon:
		system. Construction vessels on the project will monitor channels 13, 16 and Working Channel 1. Mariners are urged to use extreme	-080° 45'
		caution in the area, transit at their slowest safe speed to minimize wake.	56"

Indian River South Section

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
ndian River (South Section) Daybeacon 10	43265	STRUCT DEST/TRUB	FD
ndian River (South Section) Daybeacon 17	43290	DAYMK MISSING	FD
ndian River (South Section) Daybeacon 32	43415	STRUCT DEST/TRUB	FD
ndian River (South Section) Daybeacon 34	43425	STRUCT DEST	FD
ndian River (South Section) Light 53	43520	HAZ NAV/STRUCT DEST/TRLB	FD
ndian River (South Section) Light 96	43860	DBD DEST	FD
ndian River (South Section) Light 112	43920	DAYMK DMGD	FD
ndian River (South Section) Daybeacon 132	44150	STRUCT DEST	FD
ndian River (South Section) Daybeacon 143	44380	STRUCT DEST	FD
ndian River (South Section) Daybeacon 144	44385	STRUCT DEST/TRUB	FD
ndian River (South Section) Daybeacon 160	44595	DBD DEST	FD
ndian River (South Section) Daybeacon 170	44830	STRUCT DMGD	FD
ndian River (South Section) Daybeacon 170	44830	STRUCT DEST/TRUB	FD
ndian River (South Section) Light 187	45115	STRUCT DEST/HAZ NAV/TRLB	FD
ndian River (South Section) Daybeacon 188	45195	STRUCT MISSING/TRUB	FD
ndian River (South Section) Light 192	45270	LT EXT/DAYMK MISSING/STRUCT DMGD/TRLB	FD
ndian River (South Section) Daybeacon 212	45390	STRUCT MISSING/TRUB	FD
ndian River (South Section) Daybeacon 225	45785	HAZ NAV/STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turkey Creek Daybeacon 22	43272.200000000004	STRUCT DEST	PA
River Run Daybeacon 5	43720	DAYMK MISSING	PA
Tidewater Island Club Channel Daybeacon 3	44390.3	STRUCT MISSING	PA

https://www.navcen.uscg.gov/msi

Queens Cove Daybeacon 10	44945	STRUCT DEST/HAZ NAV	PA
Outrigger Harbour Daybeacon 1	45710	STRUCT DEST	PA
Ind River Plantation Marina Channel Daybeacon 2	45825	STRUCT DMGD	PA
Breakwater Danger Daybeacon A	45863	DAYMK MISSING	PA
Breakwater Danger Daybeacon B	45863.1	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Repairs, Painting, Or Fender Replacement	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-10-29 To: 2028-01-31 Location: 27.632319° N / 80.371113° W Bridge Name: 17th St Bridge Vecellio Grogan, on behalf of the bridge owner, Florida Department of Transportation, will be conducting bridge repairs on the 17th street (SR 656) Bridge over the AICW (Indian River) mile marker 952.9 at Vero Beach, FL beginning November 13, 2023, with an estimated completion during January 2028. The project will remove and replace 400 feet of the eastern portion of the bridge beginning with the north section before continuing with the south section. The contractor will utilize in water equipment which will remain on site, all vessels are advised to transit the area with caution. For further information, contact: Kyle Tatum at (407) 361- 6506. For waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil.	Lat: 27° 37' 56" Lon: -080° 22' 16"
Fort Pierce Inlet Inner Harbor - Indian River South Section/General/Bridges/Conversion	Bridges	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 27.47199° N / 80.32452° W Bridge Name: A1A State Route Bridge Vecellio & Drings Grogan, Inc. ("V& Drings"), on behalf of the bridge owner, FDOT, are conducting construction operations for the replacement of the A1A North Causeway Drawbridge across the AICW, mile 964.8, at Ft. Pierce, FL. A temporary work trestle (platform) has been installed on the northeast side of the existing A1A North Causeway Bridge. In water work continues directly adjacent to and across the navigable waterway with barge(s) in order to perform other associated construction activities. In April 2025, new bridge beams will be installed over the channel which will permanently limit the vertical clearance to 85 ft. at mean high water. The existing drawbridge will remain in use until sometime in late 2026. During bridge beam setting operations in April and May 2025, there will be intermittent closures of the channel for 3-4 hours at a time for safety. Vessels needing a full channel passage are required to provide the bridge tender with a 2-hour advance notice to allow for the barges to clear the channel. During the evening/overnight hours the channel will be unobstructed. All in-water equipment will be properly lighted. All mariners are requested to use caution and transit the area at a slow speed. For waterways questions or drawbridge operating issues, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	Lat: 27° 28' 19" Lon: -080° 19' 28"

Intracoastal Waterway Florida Seventh District

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Okeechobee (Rt 2) Daybeacon 13	51445	STRUCT MISSING	FD

Isla De Vieques

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Isla De Vieques/General/Hazards To	Navigation	The U.S. NAVY is advising all mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to Punta Este and on the Southeast on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it	
Navigation/Hazards		contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Isla Magueyes

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla De Mona Light	32295	LT EXT/STRUCT DMGD	FD

Jekyll Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jekyll Creek Jetty Warning Daybeacon 8	37305	DAYMK MISSING	FD
Jekyll Creek Light 20A	37346	STRUCT DEST/TRLB	FD
Jekyll Creek Light 29	37370	STRUCT DEST/TRLB	FD

Johns Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johns Pass Channel Daybeacon 1	25580	STRUCT DEST/TRUB	FD
Johns Pass Channel Light 4	25600	LT EXT	FD

Jug Creek Shoal

Federal Discrepancies

https://www.navcen.uscg.gov/msi 26/73

NAME	LLNR	STATUS	AID TYPE
Jug Creek Shoal Daybeacon 9	56375	STRUCT MISSING	FD

Jupiter Inlet

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Sector Miami, Submerged Land Act (SLA) - Jupiter Inlet/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2024-11-15 To: 2025-09-30 Location: 26.94755° N / 80.08495° W Bridge Name: US 1 Jupiter Federal Bridge New bascule bridges have been constructed and operate on demand. The new navigational clearances will provide 42ft of vertical clearance at the center and 125ft of horizontal clearance between the fenders when the project is complete. Inwater equipment will continue to be present in the vicinity of construction of the new bridge through the end of October 2025. UPDATE 7/24/2025 - 10/31/2025: Single-leaf only openings will be provided from 10 a.m. on July 24, 2025, through 11:59 p.m. on October 31, 2025. Approximately 60 feet of horizontal clearance is available during this time. All vessels are advised to transit the area with caution.	Lat: 26° 56' 51' Lon: -080° 05' 06"
Sector Miami, Submerged Land Act (SLA) - Jupiter Inlet/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2025-02-19 To: 2025-08-18 Location: 26.94754° N / 80.07894° W 26.94603° N / 80.07814° W 26.94603° N / 80.07891° W 26.94752° N / 80.08029° W 26.94754° N / 80.07894° W The U.S. Coast Guard received a report of shoaling within the Intracoastal Waterway near Jupiter Lighthouse Park extending from the southeast corner toward Jupiter Inlet Buoy 2 (LLNR 46240) and extending south-southeast towards Jupiter Inlet Light 1 (LLNR 46235). Depth of water has been reported as low as 4 feet throughout the channel. The deepest water is located on the south side of the channel near Jupiter Inlet Light 1. Mariners are advised to reduce speed to bare steerageway and transit the area with extreme caution.	

Jupiter Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jupiter Sound Daybeacon 56	46210	STRUCT DEST	FD
Jupiter Sound Daybeacon 48	46180	STRUCT MISSING/TRUB	FD
Jupiter Sound Light 53	46200	STRUCT DMGD/TRLB/HAZ NAV	FD

Keaton Beach

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Keaton Beach Daybeacon 2	30600	STRUCT DEST/TRUB	FD
Keaton Beach Daybeacon 4	30610	STRUCT DEST/TRUB	FD
Keaton Beach Daybeacon 4A	30615	STRUCT DEST/TRUB	FD
Keaton Beach Light 5	30620	TRLB/STRUCT DEST	FD
Keaton Beach Daybeacon 10	30635	TRUB/STRUCT DEST	FD
Keaton Beach Light 11	30640	STRUCT DEST/TRLB	FD
Keaton Beach Daybeacon 13	30650	TRUB/STRUCT DEST	FD
Keaton Beach Daybeacon 18	30675	STRUCT DEST/TRUB	FD

Key Biscayne Yacht Club

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Key Biscayne Yacht Club Light 4	49085	DAYMK MISSING	PA

Kings Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Bay Light 48	7000	STRUCT DEST/TRLB	FD
Kings Bay Light 50	7005	STRUCT DEST	FD
Kings Bay Light 52	7010	STRUCT DEST	FD
Kings Bay Light 53	7015	STRUCT DMGD	FD
Kings Bay Light 54	7020	STRUCT DEST	FD
Kings Bay Light 56	7025	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kings Bay/General/Marine	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-03-06 To: 2026-04-10	
Construction (Excluding	Construction	Location: 30.7818° N / 81.49075° W 30.77592° N / 81.49028° W 30.77585° N / 81.49391° W 30.78155° N / 81.4947° W 30.7818° N / 81.49075° W	
Bridges)/Facilities, Barriers,	(Excluding	UMX Crew will be starting dredging and underwater diving repairs work at MSF Facility (East River), Kings Bay Base, GA (30-46-45.5N / 81-29-29.5W).	
Manmade Reefs, Riprap,	Bridges)	The crew will have a 120' x 45' Crane barge and 60' x 70' ton crane barge on-site. No wake is allowed near the job location. The project is scheduled	
Jetties/Dikes		to start on March 17, 2025, and is estimated to finish on March 17, 2026.	

Kings Bay/General/Marine	Marine	General/Marine Construction (Excluding Bridges)/Dredging 23905 Cottrell Contracting Corporation of Chesapeake, Virginia advises that the DREDGE	
Construction (Excluding	Construction	NEWMARKET will be conducting dredging operations at Kings Bay Submarine Base, Camden County, GA. The work will be ongoing from July 21,	
Bridges)/Dredging	(Excluding	2025, through December 31, 2025, from Kings Bay Lighted Buoy 43 (LLNR 37735) to Kings Bay Light 60 (LLNR 37735). All mariners are requested to	
	Bridges)	stay clear of the dredge, pipelines, barge, derricks and operating wires about the dredge. All operators should be aware that the dredge and	
		pontoon lines are held in place by cables, which are attached to anchors some distance from the dredge and pontoons. Buoys are attached to the	
		anchors so that they may be moved as the dredge moves. Submerged lines should be avoided. Mariners are requested to exercise extreme caution	
		when approaching, passing, and leaving the dredging plant. The DREDGE NEWMARKET monitors VHF-FM channels 13 and 16. Mariners are	
		cautioned to strictly comply with the Inland Rules of the Road when approaching, passing and leaving the area of operations, and remain a safe	
		distance away from the dredge, booster, buoys, cables, pipeline, barges, derricks, wires and related equipment. Owners and lessees of fishnets, crab	
		pots and other structures that may be in the vicinity and that may hinder the free navigation of attending vessels and equipment must remove these	
		from the area where tugs, tender boats and other attendant equipment will be navigating. Dredging operations will be conducted twenty-four (24)	
		hours a day seven (7) days a week, all fishnets, crab pots and structures in the general area must be removed prior to commencement of any work, a	
		slow NO WAKE speed is requested of transiting vessels. All vessels are requested to contact the dredge prior to passing.	

Kings Island Turning Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kings Island Turning Basin Light 16	5065	STRUCT MISSING/TRLB	FD

Kingsley Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kingsley Creek Daybeacon 13	38010	STRUCT DEST/TRUB	FD

Kissimmee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kissimmee River Light 1	51930	LT EXT/TRLT	FD

Lake Boca Raton

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hillsboro Mile Daybeacon 1	47151	STRUCT DEST	PA
Hillsboro Mile Daybeacon 3	47152	STRUCT DEST	PA
Hillsboro Mile Daybeacon 7	47153	STRUCT DEST	PA

Lake Dexter

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Lake Dexter/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-02-11 To: 2025-08-10 Location: 32.27263° N / 80.53829° W 30.4907° N / 80.25264° W 24.57149° N / 78.80245° W 23.97058° N / 83.32882° W 29.25227° N / 84.25167° W 32.24011° N / 81.43367° W 32.27263° N / 80.53829° W PUBLICATION–National Oceanic and Atmospheric Administration (NOAA) – U.S. Coast Pilot 5, Gulf Coast, Puerto Rico, and Virgin Islands, 53rd Edition, 2025, has been issued and is ready for free download and weekly updates at nauticalcharts.noaa.gov/publications/coast-pilot/index.html. Only Print-on-Demand (POD) bound copies are available for purchase; visit nauticalcharts.noaa.gov/publications/print-agents.html#coast-pilot. The 2025 Edition cancels the preceding 2024 Edition, and incorporates all previous corrections.	
St Johns River - Lake Dexter/General/Miscellaneous	Miscellaneous	General/Miscellaneous 20018 HURRICANE INFORMATION: The hurricane season extends from June 1st through November 30th. Hurricanes can cause excessive damage to vessels and loss of life. To minimize these dangers, the following precautions should be taken by all mariners before getting underway during the hurricane season: (a) Instruction of crew and passengers in location of emergency equipment and emergency procedures; (b) Pre-sailing check of vessel, machinery, and equipment for seaworthiness; (c) Installation of strong ground tackle; (d) Review of storm center evasion procedures; (e) Knowledge of nearest hurricane shelter or port; and (f) Constant radio watches on channel 16 VHF-FM and frequent monitoring of weather broadcasts. The civilian hurricane warning service for the North Atlantic is provided by the National Hurricane Center, Miami, Florida. The center collates ship, aircraft, radar, and satellite data to produce and issue tropical cyclone warnings and forecasts for the North Atlantic Ocean, including the Caribbean Sea and the Gulf of Mexico. A Tropical Cyclone Public Advisory (TCP) is issued every six hours, with intermediate bulletins provided as needed. For tropical storms and hurricanes threatening to cross the coast of the U.S., coastal warnings are issued: (a) TROPICAL STORM WATCH – An announcement that sustained winds of 34 to 63 knots (39 to 73 mph or 63 to 118 km/hr) are possible within the specified area within 48 hours in association with a tropical, subtropical, or post-tropical cyclone. (b) TROPICAL STORM WARNING – An announcement that sustained winds of 34 to 63 knots (39 to 73 mph or 63 to 118 km/hr) are expected somewhere within the specified area within 36 hours in association with a tropical, subtropical, or post-tropical cyclone. (c) HURRICANE WATCH – An announcement that sustained winds of 64 knots (74 mph or 119 km/hr) or higher are possible within the specified area in association with a tropical, subtropical, or post-tropical cyclone. Because hurricane preparedness activities bec	

St Johns River - Lake Dexter/General/Miscellaneous

Miscellaneous General/Miscellaneous 20019 HURRICANE INFORMATION CONT: Additional information of interest to mariners is included in the Tropical Cyclone Forecast/Advisory (TCM) and the Tropical Cyclone Surface Wind Speed Probabilities (PWS) products. The TCM provides current and forecast storm positions, intensities, and wind fields out to 120 hours. The PWS provides probabilities of sustained wind speeds equal to or exceeding 34-, 50-, and 64-kt wind speed thresholds for select coastal and offshore locations Mariners are reminded that aids to navigation, particularly lighted and unlighted buoys, may be moved from charted position, damaged, destroyed, extinguished, or otherwise deemed discrepant as a result of hurricanes and storms. Mariners should not rely solely upon the position or operation of an aid to navigation, but also employ such other methods of determining position as may be available. Port Hurricane Conditions are set up by the COTP and will change as the threat of severe weather increases, or as a storm approaches a specific COTP Area of Responsibility. For COTP-specific Port Hurricane Conditions, you should review information provided under the Port Directory tab of http://homeport.uscq.mil Condition 4 - Hurricane Seasonal Alert. 01 June-30 November; port status: open. Condition Whiskey – Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 72 hours; port status: open, Condition X-Ray – Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 48 hours; port status; open, Condition Yankee - Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 24 hours; port status: restricted; vessel/facility control measures in effect. Condition Zulu – Sustained Gale Force winds associated with Tropical Cyclone activity are predicted within 12 hours; port status: closed to all vessel traffic and waterside activities except for activities approved by the COTP. Drawbridges along the coast may deviate from normal operating procedures. Drawbridges are authorized to remain closed upon approach of Gale Force winds of 34 knots or greater. Extended closure periods may be authorized up to 8 hours prior to arrival of Gale Force winds to facilitate evacuation of land traffic. Due to the uncertainty of hurricane movements and bridge closures, mariners are urged to seek passage through drawbridges well in advance of the arrival of Gale Force winds. http://www.nws.noaa.gov/com/weatherreadynation/hurricane_preparedness.html

Lake George

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Silver Glen Springs Run Buoy 1	8595	MISSING	PA
Silver Glen Springs Run Buoy 24	8695	MISSING	PA
Silver Glen Springs Run Buoy 25	8700	OFF STA	PA
Silver Glen Springs Run Buoy 2A	8715	SINKING/BUOY DMGD	PA
Silver Glen Springs Run Buoy 9A	8740	MISSING	PA
Silver Glen Springs Run Pref Buoy A	8750	MISSING	PA

Lake Monroe

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Monroe Bar Light 1	9240	STRUCT DEST/HAZ NAV/TRLB	FD

Lake Okeechobee Route 1

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Okeechobee (Rt 1) Daybeacon 3	51195	DBD DEST	FD

Lake Worth Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth Creek Daybeacon 7	46375	STRUCT DEST/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Jupiter Inlet - Lake Worth Creek/General/Bridges/Temp Deviation	J	General/Bridges/Temp Deviation From: 2024-11-05 To: 2025-09-01 Location: 26.93383° N / 80.08399° W Bridge Name: Indiantown Road Eastbound and Westbound Bridges The U.S. Coast Guard has issued a temporary interim rule (TIR) which amends drawbridge operation regulation, 33 CFR 117.261(p) which will govern Indiantown Road Bridge, mile 1006.2, at Jupiter, Florida. The TIR is effective through 11:59 p.m. on August 31, 2025.	

Lake Worth North

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth North Daybeacon 32	46515	STRUCT DEST/HAZ NAV	FD
Lake Worth North Light 36	46600	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

https://www.navcen.uscg.gov/msi

Lake Worth North/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2025-01-14 To: 2027-01-31 Location: 26.808528° N / 80.056123° W Bridge Name: US Hwy 1/SR 5 Bridge - Earman River The waterway at the bridge will be obstructed and closed to navigation from 2/10/2025 through 1/7/2027 for the replacement of the US Hwy 1/SR 5 Bridge. Mariners are advised to utilize the northern canal to access the Atlantic Intracoastal Waterway. The Lighthouse Drive Bridge across the northern canal provides a vertical clearance of 14.5 feet and a horizontal clearance of 22.5 feet. For waterways questions, please contact USCG Sector Miami Waterways Division at (305) 535-4317, email SectorMiamiWaterways@uscg.mil	Lat: 26° 48' 31" Lon: -080° 03' 22"
Lake Worth North/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 22452 Atlantic & Samp; Gulf Dredging & Samp; Marine, LLC will be conducting dredging and upland disposal. AGD will establish a waterside staging area to secure the submerged pipeline barge. Rafted pipeline and equipment will be staged in this location during the mobilization and demobilization phases of the work. The Cutter Suction DREDGE COMMODORE is scheduled to commence dredging/fill operations on July 16, 2025. Dredging operations will commence at the southern end of the dredge area and progress to the north. The material will be hydraulically placed via submerged/floating/shoreline into the FIND Peanut Island DMMA site. All operations are scheduled to be completed no later than December 4, 2025. All pipeline will be lit per USCG regulations. Periodic hydrographic surveys will be conducted within the dredge area and along the pipeline corridor. Dredging and survey operations will occur 7 days a week, 7 a.m. to 7 pm. Vessels should avoid the active dredge area during construction and proceed at slow speed in the area surrounding the Dredge, pipeline and other support equipment. Proceed with utmost caution in the dredging area. Please contact DREDGE COMMODORE on VHF-FM channel 1 for passing arrangements.	

Lake Worth South

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lake Worth South Daybeacon 3	46730	STRUCT DEST	FD
Lake Worth South Daybeacon 4	46740	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Daybeacon 34	46965	STRUCT DEST/HAZ NAV/TRLB	FD
Lake Worth South Daybeacon 40	46985	TRUB/STRUCT MISSING	FD

Largo Sound Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Newport Bay Daybeacon 7	11851.6	HAZ NAV/STRUCT DMGD	PA

Lemon Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lemon Bay Channel Daybeacon 2	57140	TRUB	FD
Lemon Bay Channel Daybeacon 16	57275.5	STRUCT MISSING/TRUB	FD
Lemon Bay Channel Daybeacon 17	57280	STRUCT DEST/TRUB	FD
Lemon Bay Channel Daybeacon 20A	57340	STRUCT DEST	FD
Lemon Bay Channel Light 24	57360	STRUCT MISSING/TRLB	FD
Lemon Bay Channel Daybeacon 26	57420	STRUCT MISSING/TRUB	FD
Lemon Bay Channel Daybeacon 40	57625	STRUCT MISSING/TRUB	FD
Lemon Bay Channel Light 47	57655	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Gottfried Creek Daybeacon 5	57357.4	DAYMK DMGD	PA
Forked Creek Daybeacon 1	57617	STRUCT DEST/HAZ NAV	PA
Forked Creek West Obstruction Daybeacon	57618.9	STRUCT DEST	PA
Forked Creek North Obstruction Daybeacon	57619	STRUCT DEST	PA
Forked Creek East Obstruction Daybeacon	57619.3	STRUCT DEST	PA

Little Lake George

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Lake George Light 53	8435	LT EXT	FD
Little Lake George Daybeacon 54	8450	STRUCT DEST/TRLB	FD

Little Manatee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Manatee River Approach Light LM	24481	STRUCT MISSING	FD

Private Discrepancies

https://www.navcen.uscg.gov/msi 30/73

NAME	LLNR	STATUS	AID TYPE
Shell Point Daybeacon 3	22698.2	STRUCT DEST	PA
Shell Point Daybeacon 7	22698.60000000002	STRUCT DEST	PA

Little Mud River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Mud River Daybeacon 189	36855	STRUCT DEST/TRUB	FD
Little Mud River Light 190	36865	STRUCT DEST/TRLB	FD
Little Mud River Light 195	36875	STRUCT MISSING/TRLB	FD
Little Mud River Light 196	36880	STRUCT DEST/TRLB	FD

Little River Winyah Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little River-Winyah Bay Obstruction Daybeacon B	33647	STRUCT MISSING/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Winyah Bay Channel - Little River Winyah Bay/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 33.76374° N / 78.81957° W Aid Name: Little River-Winyah Bay Daybeacon 21B LLNR: 33705.5 Action: RENAME Little River-Winyah Bay DBN 21C (LLNR 33705.5). Establish Little River-Winyah Bay LT 21B (LLNR 33705.3) in approximate position 33-46-56.075N, 078-47-21.582W. The light will display a flash characteristic of Q G, with a nominal range of 4 nautical miles.	Lat: 33° 45' 49" Lon: -078° 49' 10"
Winyah Bay Channel - Little River Winyah Bay/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change 19407 Location: 33.82754° N / 78.70574° W Aid Name: Little River-Winyah Bay Buoy 15B The U.S. Coast Guard has approved the following change in the Little River-Winyah Bay Channel, Intracoastal Waterway, to improve navigational safety and reliability. Little River-Winyah Bay Buoy 15B (LLNR 33660.1) will be permanently established in approximate position 33-49-39.137N, 078-42-20.648W.	Lat: 33° 49' 39" Lon: -078° 42' 21"
Winyah Bay Channel - Little River Winyah Bay/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-04-10 To: 2025-11-01 Location: 33.851704° N / 78.656302° W Bridge Name: Little River Bridge - AlCW Effective from 12:01 a.m. on May 5, 2025, through 11:59 p.m. on October 31, 2025, the Little River Bridge shall open on signal except that from 7 a.m. to 9 a.m. and 4 p.m. to 6 p.m., Monday through Friday, except Federal holidays, the draw will open on the hour and half hour. Public vessels of the United States and tugs with tows, upon proper signal, will be passed through anytime. A notice of temporary deviation from regulations was published in the Federal Register. Comments and related documents for this action can be found under docket number USCG-2025-0152 using Federal Decision-Making Portal at https://www.regulations.gov.	

Little Shark River Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Shark River Entrance Daybeacon 3	15955	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cormorant Pass Daybeacon 48	15870	DAYMK IMCH	PA
Oyster Bay Daybeacon 53	15885	DAYMK MISSING	PA
Oyster Bay Daybeacon 63	15915	DAYMK MISSING	PA
Little Shark River Daybeacon 69	15940	DAYMK IMCH	PA

Long Branch

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Long Branch Lighted Buoy 71	7590	RELOCATED FOR DREDGING	FD
Long Branch Lighted Buoy 69	7575	RELOCATED FOR DREDGING	FD

Long Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Long Key Daybeacon 1X	12385	STRUCT DEST/TRUB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

31/73

Long	Bridges	General/Bridges/Rehabilitation From: 2025-07-02 To: 2026-10-31 Location: 24.83801° N / 80.77337° W Bridge Name: US1/SR5 Highway	Lat:
Key/General/Bridges/Rehabilitation		Bridge - Channel 5 The bridge is undergoing a rehabilitation and repairs through October 2026. There will be barges, floating work	24° 50' 17"
		platforms and work boats in the area behind the fender systems, but no obstructions to navigation are expected. Beginning July 14, 2025,	Lon:
		through August 1, 2025, underwater work will begin with divers at two piers adjacent to the navigational channel, behind the fenders. All	-080° 46'
		mariners are advised to proceed with caution and transit the area at a minimum wake speed. For waterways related questions, contact,	24"
		Coast Guard Sector Key West Waterways, 305-292-8768 or email: SKWWaterways@uscg.mil	

Long Key Cape Sable

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sprigger Bank Light 5	15605	HAZ NAV/STRUCT DEST/TRLB	FD

Lower Flats Range

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elba Island Light 39	4850	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Long Island Crossing - Lower Flats Range/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change 24532 Location: 32.07292° N / 80.97514° W Aid Name: Elba Island Light 37 LLNR: 4845 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard is proposing to make the following changes in the Savannah River, Elba Island Channel to improve the waterway. Elba Island LT 37 (LLNR 4845) will be changed to Elba Island LB 37 (LLNR 4845) and relocated to 32-04-24.404N, 080-58-28.548W. Light characteristics for LB 37 will remain a FI G 4s. Elba Island LT 39 (LLNR 4850) will be changed to Elba Island LB 39 (LLNR 48450) and relocated to 32-04-34.342N, 080-58-54.089W. Light characteristics for LB 39 will remain a FI G 4s. Waterway changes associated with the Savannah Harbor Expansion Project (SHEP) have made the federal channel and surrounding areas too deep for Coast Guard assets to adequately mark the channel with fixed aids to navigation. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or Andrew.mengle@uscg.mil with Elba Island Channel Changes as the subject line. Comments can also be mailed to: Commander (dpw), U.S. Coast Guard Southeast District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by September 24, 2025.	Lat: 32° 04' 23" Lon: -080° 58' 31"
Long Island Crossing - Lower Flats Range/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change 24533 Location: 32.07583° N / 80.98202° W Aid Name: Elba Island Light 39 LLNR: 4850 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard is proposing to make the following changes in the Savannah River, Elba Island Channel to improve the waterway. Elba Island LT 37 (LLNR 4845) will be changed to Elba Island LB 37 (LLNR 4845) and relocated to 32-04-24.404N, 080-58-28.548W. Light characteristics for LB 37 will remain a FI G 4s. Elba Island LT 39 (LLNR 4850) will be changed to Elba Island LB 39 (LLNR 48450) and relocated to 32-04-34.342N, 080-58-54.089W. Light characteristics for LB 39 will remain a FI G 4s. Waterway changes associated with the Savannah Harbor Expansion Project (SHEP) have made the federal channel and surrounding areas too deep for Coast Guard assets to adequately mark the channel with fixed aids to navigation. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or Andrew.m.engle@uscg.mil with Elba Island Channel Changes as the subject line. Comments can also be mailed to: Commander (dpw), U.S. Coast Guard Southeast District, 909 SE 1st Ave (STE 406) Brickell Plaza Federal Bldg, Miami, FL. 33131-3050 to be received by September 24, 2025.	Lat: 32° 04' 33" Lon: -080° 58' 55"

Loxahatchee River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Loxahatchee River Daybeacon 7	46280	DAYMK IMCH	PA
Loxahatchee River Daybeacon 15	46320	DAYMK IMCH	PA
Loxahatchee River South Channel Daybeacon 7	46373.5	STRUCT DMGD	PA

Mackay River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mackay River Cutoff Light 229	37090	STRUCT DEST/TRLB	FD
Mackay River Cutoff Light 231	37095	STRUCT DEST/TRLB	FD
Mackay River Light 239	37160	STRUCT DEST/HAZ NAV/TRLB	FD
Mackay River Light 241	37170	STRUCT DEST/TRLB	FD
Mackay River Light 244	37190	STRUCT DEST/TRLB	FD

Manatee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Manatee River Daybeacon 3	21867	STRUCT DEST/TRUB	FD
Manatee River Daybeacon 21	22050	STRUCT MISSING	FD
Manatee River Daybeacon 28	22095	STRUCT DEST/TRUB	FD

NAME	LLNR	STATUS	AID TYPE

Fifty-Ninth Street Boat Ramp Daybeacon 5	21960	STRUCT DEST	PA
Tidewater Preserve Marina Daybeacon 2	22105.2	STRUCT DEST	PA
Colony Cove Daybeacon 2	22110	STRUCT DEST/TRUB	PA

Matanzas Pass Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas Pass Channel Daybeacon 24	18290	STRUCT MISSING/TRUB	FD
Matanzas Pass Channel Daybeacon 26	18295	HAZ NAV/STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas Harbor Channel Daybeacon 5	18296.3	STRUCT DEST	PA
North Estero Bay Daybeacon 4	18315	STRUCT DEST	PA
North Estero Bay Daybeacon 5	18316	STRUCT MISSING	PA
Bayside Estates Channel Daybeacon 2	18405	STRUCT DEST	PA
Bayside Estates Channel Daybeacon 4	18415	HAZ NAV/STRUCT DEST	PA
Bayside Estates Channel Daybeacon 14	18450	STRUCT DEST	PA
North Estero Bay Daybeacon 19	18565	STRUCT DMGD	PA
North Estero Bay Daybeacon 35	18605	STRUCT DEST	PA
Mullock Creek Daybeacon 2A	18760	STRUCT DEST	PA
Mullock Creek Daybeacon 45	18920	STRUCT DEST	PA
Hurricane Bay Marina West Channel Daybeacon 7	18160	STRUCT DEST/HAZ NAV	PA
Siesta Isles Daybeacon 4	18215	STRUCT DEST	PA
Matanzas Harbor Channel Daybeacon 3	18296.100000000002	STRUCT DEST/HAZ NAV	PA
North Estero Bay Daybeacon 63	18725	STRUCT DEST/TRUB	PA
Mullock Creek Daybeacon 13	18835	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
San Carlos Bay - Matanzas Pass	Marine	General/Marine Construction (Excluding Bridges)/Dredging 23056 Location: 26.46745° N / 81.97634° W 26.46292° N / 81.97303° W 26.45919° N	
Channel/General/Marine	Construction	/ 81.98637° W 26.46355° N / 81.98868° W 26.46745° N / 81.97634° W Great Lakes Dredge & Dredge & Company, LLC will be preparing for an	
Construction (Excluding	(Excluding	upcoming dredge project, Captiva Island Beach Renourishment Project. In preparation for this project, GLDD will mobilize 30-inch pipeline	
Bridges)/Dredging	Bridges)	raft(s), 2 boosters, and a mooring cube and float Hose in the Carlos Bay Staging area. This equipment will be assembled and ultimately towed	
		off-shore of Captiva Island where it will be installed just off the beach for dredging work to begin in mid-September. All vessel traffic should	
		avoid active work areas. Mariners are urged to use extreme caution in the area of operations. Mariners are urged to transit at their slowest safe	
		speed to minimize wake and proceed with caution after passing arrangements have been made. All pipelines and anchors will be marked via	
		lighted can buoy and orange Norwegian buoys. All submerged pipelines will be marked according to USCG regulations. Operations will be 12	
		hours/day, 7 days/week until dredging begins mid-September. Once dredging begins operations will be 24 hours/day, 7 days/week. TUG	
		BAYOU BAY, TUG SYLVIE FAYE and all other vessels will be monitoring VHF-FM channel 13 and 16. Operations are expected to be completed on	
		or about November 30, 2025.	

Matanzas River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matanzas River Light 1	39035	STRUCT DEST/TRLB	FD
Matanzas River Buoy 2	39040	OFF STA	FD
Matanzas River Daybeacon 5	39055	STRUCT MISSING	FD
Matanzas River Daybeacon 6A	39060.1	STRUCT DEST/TRUB	FD
Matanzas River Light 43	39330	STRUCT MISSING/TRLB	FD
Matanzas River Daybeacon 60	39455	STRUCT DEST/TRUB	FD
Matanzas River Light 72	39495	DAYMK MISSING	FD
Matanzas River Light 79	39520	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Salt Run Daybeacon 3	38925	STRUCT DEST	PA
Salt Run Daybeacon 4	38930	STRUCT DEST	PA
Salt Run Daybeacon 6	38940	STRUCT MISSING	PA
Salt Run Daybeacon 11	38965	STRUCT DEST/HAZ NAV	PA
Fish Island Marina Daybeacon 1	39080	DAYMK MISSING	PA
Salt Run Daybeacon 1	38915	STRUCT DEST	PA
Salt Run Daybeacon 7	38945	STRUCT DMGD	PA

Temporary Changes

https://www.navcen.uscg.gov/msi 33/73

NAME	LLNR	STATUS	AID TYPE
Matanzas River Wreck Buoy	null	ESTABLISHED	FD

Matheny Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Venice Inlet-Siesta Key Daybeacon 7	57870	DAYMK MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snake Island Daybeacon A	57834	STRUCT DEST	PA
Snake Island Daybeacon B	57834.1	STRUCT DEST	PA
Snake Island Daybeacon C	57834.200000000004	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 4	58185	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 5	58190	STRUCT DEST	PA
Midnight Pass Lagoon Daybeacon 7	58200	STRUCT DEST	PA
Midnight Pass Daybeacon 13	58205.3	STRUCT DMGD	PA
Midnight Pass Daybeacon 17	58205.5	STRUCT DEST	PA
Matheny Creek Daybeacon 1	58292	STRUCT DMGD	PA
Phillippi Creek Daybeacon 2	58365.200000000004	DAYMK MISSING	PA
Phillippi Creek Daybeacon 7	58365.6	DAYMK MISSING	PA
Phillippi Creek Daybeacon 11	58365.9	STRUCT DEST/HAZ NAV	PA
Phillippi Creek Daybeacon 13	58366	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
, , , , ,	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 17465 Continental Heavy Civil Corp. will conduct shoreline reconstruction and coastal armoring. Work will be performed between 22 North Casey Key Road to 400 N Casey Key Road, and 526 to 840 N Casey Key Road. Staging and loading area will be the entire footprint of the Nokomis Beach "spillover" parking lot, located at 101 S Casey Key Road. Heavy equipment such as lattice-boom crawler cranes and heavy excavators will load onto barges from Albee Road and will route down to intercoastal to the Venice inlet, proceed to the Gulf and then up the coast to the jobsite and back. Continental Heavy Civil expects to work a regular schedule from 6am to 6pm Monday through Saturday, with some necessary Sundays. Estimated completion time for the entire project May 1st, 2027. All Vessels should use caution when transiting the work area. The crew at Casey Road will monitor VHF-FM channels 13 and 16.	

Mayport Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mayport Basin Range Front Light	7155	NIGHT LT BURNING DAY	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Mayport Basin Channel Lighted Buoy 1	7170	RELOCATED FOR DREDGING	FD

Miami Beach Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Channel Light 11	48015	STRUCT DEST/TRLB	FD

Miami Main Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Miami Beach Marina Breakwater North Light	10570	LT EXT	PA

Miami Turning Basin

•				
NAME	LLNR	STATUS	AID TYPE	
Miami Turning Basin Articulated Light E	10770	STRUCT DEST/TRLB/HAZ NAV	FD	

Mile Point

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mile Point Lower Range Front Light	7260	REDUCED INT	FD
Mile Point Light A	7281	DAYMK MISSING	FD
Mile Point Light C	7283	STRUCT DEST	FD
Mile Point Upper Range Front Light	7287	REDUCED INT	FD
Mile Point Upper Range Rear Light	7290	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - Mile Point/ATON/Advanced Notice of Change	Advanced Notice of Change	Mile Point Lower RFL (LLNR 7260) will be relocated to approximate position: 30-22-44.551N/081-27-11.480W to align with the newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 27' 11"
St Johns River - Mile Point/ATON/Advanced Notice of Change	Advanced Notice of Change	Mile Point Lower RRL (LLNR 7265) will be relocated to approximate position: 30-22-43.316N/081-27-14.558W to align with the newly dredged channel. In addition, both Mile Point Lower RFL and Mile Point Lower RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 42" Lon: -081° 27' 14"
St Johns River - Mile Point/ATON/Advanced Notice of Change	Advanced Notice of Change	Mile Point Upper RFL (LLNR 7287) will be relocated to approximate position: 30-22-44.266N/081-27-12.139W to align with the newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 27' 11"
St Johns River - Mile Point/ATON/Advanced Notice of Change	Advanced Notice of Change	Mile Point Upper RRL (LLNR 7290) will be relocated to approximate position: 30-22-34.772N/081-26-58.725W to align with the newly dredged channel. In addition, both Mile Point Upper RFL and Mile Point Upper RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 35" Lon: -081° 26' 58"

Mosquito Lagoon

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mosquito Lagoon Daybeacon 8	40925	STRUCT DEST/TRUB	FD

Mount Pleasant Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mount Pleasant Channel Daybeacon 3	3520	STRUCT MISSING/TRUB	FD

Mullet Key Channel

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Mullet Key Channel/General/Marine Construction (Excluding Bridges)/Survey Operations	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Survey Operations 24014 Location: 27.62283° N / 82.65605° W 27.61898° N / 82.65328° W 27.61792° N / 82.655° W 27.62185° N / 82.65797° W Fugro USA Land, Inc will be conducting hydrographic surveying with vessel FUGRO ROOSTER. Operations are expected to take place between July 27, 2025, and August 9, 2025. FUGRO ROOSTER will be monitoring VHF-FM channel 16.	

Murphy Island

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Murphy Island Light 23	8295	LT EXT	FD
Murphy Island Light 26	8305	DAYMK MISSING	FD

Myakka River

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
South Gulf Cove Entrance Daybeacon 5	20175	DAYMK MISSING	PA
Upper Myakka River Daybeacon 12	20395	HAZ NAV/STRUCT DEST	PA

Naples Bay Channel

Federal Discrepancies

https://www.navcen.uscg.gov/msi 35/73

NAME	LLNR	STATUS	AID TYPE
Naples Bay Channel Daybeacon 22	17550	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Naples Yacht Club Daybeacon 5	17667	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Gordon Pass Channel - Naples Bay Channel/General/Hazards To	Hazards To	General/Hazards To Navigation/Shoaling Reported 22051 Location: 26.1285° N / 81.79073° W	Lat:
Navigation/Shoaling Reported	Navigation	Oyster bed encroaching into the channel.	26° 07' 43"
			Lon:
			-081° 47' 27"

Nassau Cutoff

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Nassau Cutoff Light 47	38175	STRUCT MISSING/TRLB	FD

New Channel Range

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Long Island Crossing - New Channel	Advanced Notice of	After completion of dredging and channel re-alignment, the water depth at the current assigned position for New Channel RFL	Lat:
Range/ATON/Advanced Notice of	Change	(LLNR 4770), makes it impossible for the Coast Guard to rebuild this range in its advertised position. Therefore, New Channel RFL	32° 02' 22"
Change		(LLNR 4770) will be permanently relocated to a new assigned position at approximately 32-02-21.801N/080-55-39.437W.	Lon:
			-080° 55'
			39"

New Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
New Pass Channel Light 13	21705	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anglers Club Reef Daybeacon AC	21701	STRUCT DEST	PA
Sarasota Basin Obstruction Light A	21752	STRUCT DEST	PA
Sarasota Basin Obstruction Daybeacon B	21754	STRUCT DEST	PA
City Island Breakwater Light	21710	STRUCT DEST	PA

New River Sound

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Stranahan River - New River	Bridges	General/Bridges/Repairs, Painting, Or Fender Replacement From: 2024-11-19 To: 2025-05-31 Location: 26.08395° N / 80.1844° W Bridge	Lat:
Sound/General/Bridges/Repairs,		Name: Interstate 595 Bridge - South New River Canal Construction for widening the I-595 Bridge continues. Impacts to navigation are	26° 05' 02"
Painting, Or Fender Replacement		expected. This will be to install bridge maintenance platforms on the pier caps facing the channel. During this time the Contractor will be	Lon:
		partially obstructing the channel with work barges and will request a 1-hour advance notice of arrival. Boaters should contact Leo	-080° 11'
		Villegas (561)334-9239 to request passage. Construction of this project is ongoing and is expected to continue until July 31st, 2025. For	04"
		waterways questions, call or e-mail Coast Guard Sector Miami, FL, Waterways Management Division, telephone 305-535-4317, email	
		SectorMiamiWaterways@uscg.mil.	

New Smyrna Beach

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
New Smyrna Beach Daybeacon 28	40645	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 51	40805	STRUCT DEST/TRUB	FD
New Smyrna Beach Daybeacon 62	40845	STRUCT DEST/TRUB	FD

North Edisto River

Federal Discrepancies

rederal Discrepancies			
NAME	LLNR	STATUS	AID TYPE

https://www.navcen.uscg.gov/msi 36/73

North Edisto River Entrance Lighted Buoy 6	3865	LT EXT	FD
North Edisto River Inner Buoy 7	3880	MISSING	FD

North Newport River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Timmons Reef E Obstruction Daybeacon	36500	STRUCT DEST	PA

Ogeechee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hell Gate Light 91	36285	STRUCT MISSING/TRLB	FD
Hell Gate Light 92	36290	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fort Mcallister Fishing Pier Light	36360	LT EXT	PA

Oglethorpe Range

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fig Island Jetty Light 56	5005	STRUCT MISSING/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
Fort Jackson - Oglethorpe Range/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 18245 Marinex Construction, Inc. will begin mobilizing equipment and pipeline to commence work at Ocean Terminal. All pipeline for this work will be appropriately lighted and laid outside the channel on the South Carolina side of the river from the Talmadge Bridge to Back River. The Dredge WADMALAW will operate in this area through approximately August 8, 2025. Operations will be conducted 24 hours a day / seven days a week and monitor VHF-FM channels 13 and 16.	
Fort Jackson - Oglethorpe Range/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 24677 Marinex Construction, Inc. will begin mobilizing equipment and pipeline to commence work at Gold Bond Building Products dock in the Savannah River. All pipeline for this work will be appropriately lighted and laid outside the channel on the South Carolina side of the river. The Dredge WADMALAW will operate in this area through approximately August 31, 2025. Operations will be conducted 24 hours a day / seven days a week and monitor VHF-FM channels 13 and 16.	

Okeechobee Waterway

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Daybeacon 6	51915	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dyess Canal Safewater Light DC	51980	STRUCT DEST	PA

Old Rhodes Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Old Rhodes Key Light 22	11165	DBD DEST	FD
Old Rhodes Key Daybeacon 24	11175	STRUCT DEST/TRLB	FD

Ossabaw Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ossabaw Sound Preferred Channel Buoy N	5740	MISSING	FD
Ossabaw Sound North Channel Daybeacon 10	5760	STRUCT DEST/TRUB	FD
Ossabaw Sound North Channel Buoy 11	5765	OFF STATION	FD
Ossabaw Sound North Channel Daybeacon 12	5770	STRUCT DEST/TRUB	FD
Ossabaw Sound South Channel Daybeacon 5	5780	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Delegal Creek Channel Buoy 4	36233	OFF STA	PA
Delegal Creek Channel Light 8	36241.1	LT EXT	PA
Delegal Creek Channel Light 1	36229	STRUCT DEST	PA
Delegal Creek Channel Buoy 2	36230	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - Ossabaw Sound/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 31.86196° N / 81.03488° W Aid Name: Ossabaw Sound North Channel Daybeacon 10 LLNR: 5760 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.	Lat: 31° 51' 43" Lon: -081° 02' 06"
Sector Charleston, Submerged Land Act (SLA) - Ossabaw Sound/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 31.8645° N / 81.05731° W Aid Name: Ossabaw Sound North Channel Daybeacon 12 LLNR: 5770 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.	Lat: 31° 51' 52" Lon: -081° 03' 26"
Sector Charleston, Submerged Land Act (SLA) - Ossabaw Sound/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change From: 2025-03-12 To: 2026-09-08 Location: 31.82121° N / 81.03359° W Aid Name: Ossabaw Sound South Channel Daybeacon 5 LLNR: 5780 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following change to the Aids to Navigation System in Ossabaw Sound. Ossabaw Sound North Channel DBN 10 (LLNR 5760) will be changed to Ossabaw Sound North Channel Buoy 10, using the same LLNR. Ossabaw Sound North Channel DBN 12 (LLNR 5770) will be changed to Ossabaw Sound North Channel Buoy 12, using the same LLNR. Ossabaw Sound South Channel DBN 5 (LLNR 5780) will be changed to Ossabaw Sound South Channel Buoy 5, using the same LLNR.	Lat: 31° 49' 16" Lon: -081° 02' 01"

Pablo Creek

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Pablo Creek Buoy 4	38355	MISSING	FD
Pablo Creek Light 5	38360	STRUCT DEST	FD
Pablo Creek Light 6	38365	STRUCT DEST/TRLB	FD
Pablo Creek Light 17	38440	STRUCT MISSING/TRLB	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Pablo Creek Temporary Light 9	38380.200000000004	ESTABLISHED	FD

Palma Sola Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Palma Sola Park Channel Daybeacon 1	59890	HAZ NAV/DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 4	59905	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 5	59910	HAZ NAV/DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 6	59915	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 7	59920	DAYMK MISSING	PA
Palma Sola Park Channel Daybeacon 8	59925	DAYMK IMCH	PA

Paradise Bay Estates Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Siesta Key-Tampa Bay Daybeacon 40	59350	STRUCT MISSING/TRUB	FD

Private Discrepancies

NAME	LIND	CTATUS	AID TVDE
NAME	LLNR	STATUS	AID TYPE
Holiday Inn Marina Daybeacon 3	22047.3	STRUCT DEST	PA
Holiday Inn Marina Daybeacon 6	22047.7	STRUCT DEST	PA
Bay Isles Perimeter Channel Daybeacon 2	58667	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 9	58667.25	DAYMK MISSING	PA
Bay Isles Perimeter Channel Daybeacon 15	58667.450000000004	STRUCT DEST	PA
Bay Isles Perimeter Channel Daybeacon 24	58667.75	DAYMK MISSING	PA
Coral Shores Channel Daybeacon 3	59375	STRUCT DEST	PA

38/73

https://www.navcen.uscg.gov/msi

Coral Shores Channel Daybeacon 12	59420	DAYMK MISSING	PA
Mt Vernon & Samp; Coral Shores Daybeacon 1N	59535	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 4	59642	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 5	59645	STRUCT DEST	PA
Cove Sound Moorings Daybeacon 1	59650	OFF STA/HAZ NAV/DAYMK MISSING	PA
Cove Sound Moorings Daybeacon 2	59655	OFF STA/HAZ NAV/DAYMK MISSING	PA
Perico Bayou Channel Daybeacon 9	59720	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 2	59760	DAYMK MISSING	PA
San Remo Shore Channel Daybeacon 8	59785	STRUCT DEST	PA
San Remo Shore Channel Daybeacon 13	59800	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 9	59815	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 11	59825	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 15	59845	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 18	59860	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 19	59865	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 21	59870.5	DAYMK MISSING/STRUCT DMGD	PA
Bradenton Beach City Channel Daybeacon 5	59955	STRUCT DEST	PA
Anna Maria Channel Daybeacon 1	60190	STRUCT DMGD	PA
Anna Maria Channel Daybeacon 2	60195	DAYMK MISSING	PA
Anna Maria Channel Daybeacon 9	60230	STRUCT DEST/HAZ NAV	PA
Anna Maria Channel Daybeacon 11	60240	STRUCT DEST	PA
Evans Artificial Reef Daybeacon	58480.5	STRUCT DEST/HAZ NAV	PA
Coral Shores Channel Daybeacon 30	59510	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 2	59636	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 3	59640	STRUCT DEST	PA
Palma Sola Bay Channel Daybeacon 3A	59641	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Daybeacon 6	59646	STRUCT DEST/HAZ NAV	PA
Palma Sola Bay Channel Junction A	59647	STRUCT DEST	PA
Cove Sound Moorings Channel Daybeacon 3	59657	DAYMK MISSING	PA
Palma Sola Bay Channel Daybeacon 10	59820	STRUCT DMGD	PA
Palma Sola Bay Channel Daybeacon 12	59830	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 1	59935	DAYMK MISSING	PA
Bradenton Beach City Channel Daybeacon 2	59940	STRUCT DEST	PA
Bradenton Beach City Channel Daybeacon 3	59945	DAYMK MISSING	PA
Bradenton Beach City Channel Junction Daybeacon A	59980	STRUCT DEST	PA

Pass-A-Grille

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pass-A-Grille Channel Daybeacon 1	25460	STRUCT MISSING/TRLB/HAZ NAV	FD
Pass-A-Grille Channel Daybeacon 2	25465	STRUCT DEST/HAZ NAV/TRLB	FD

Peace River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Peace River Light 4	20675	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Park Channel Daybeacon 4	20455	STRUCT DEST	PA
Ponce De Leon Park Channel Light 9	20470	LT EXT	PA
Elkcam Waterway Light 1	20905	LT EXT	PA
Manchester Waterway Daybeacon 14	20981.5	STRUCT DEST	PA
Manchester Waterway Daybeacon 17	20981.9	STRUCT DEST	PA
Manchester Waterway Daybeacon 24	20982.8	STRUCT DEST	PA
Countryman Waterway Channel Daybeacon 3	20990	DAYMK MISSING	PA
Countryman Waterway Channel Daybeacon 6	20997	STRUCT DEST	PA
Countryman Waterway Channel Daybeacon 8	21003	STRUCT MISSING	PA
Sunrise Waterway Daybeacon 2	21020	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 21	21056.8	STRUCT DEST/HAZ NAV	PA
Spring Lake Waterway Daybeacon 23	21056.9	STRUCT DMGD	PA
Spring Lake Waterway Daybeacon 27	21057.2	STRUCT DEST	PA

https://www.navcen.uscg.gov/msi 39/73

Peace River (North Section) Daybeacon 7	21210	OFF STA	PA
Peace River (North Section) Daybeacon 9	21215	OFF STA	PA
Peace River (North Section) Daybeacon 10	21220	STRUCT DEST	PA
Peace River (North Section) Daybeacon 11	21225	OFF STA	PA
Peace River (North Section) Daybeacon 14	21235	STRUCT DEST	PA
Ponce de Leon Park Channel Daybeacon 18	20474.5	STRUCT DEST	PA

Pine Island Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pine Island Sound Daybeacon 5	54825	STRUCT MISSING/TRUB	FD
Pine Island Sound Light 20	55425	STRUCT DEST/HAZ NAV/TRLB	FD
Pine Island Sound Daybeacon 28	55565	STRUCT MISSING	FD
Pine Island Sound Daybeacon 34	55590	STRUCT MISSING	FD
Pine Island Sound Daybeacon 50	55985	STRUCT MISSING	FD
Pine Island Sound Daybeacon 53	56000	STRUCT MISSING	FD
Pine Island Sound Light 54	56005	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Matlacha Pass Daybeacon 34	55050	STRUCT DEST/HAZ NAV	PA
Matlacha Pass Daybeacon 53	55130	STRUCT DEST	PA
Matlacha Pass Daybeacon 79	55225	DAYMK MISSING	PA
Matlacha Pass Daybeacon 81	55230	DAYMK MISSING	PA
Matlacha Pass Daybeacon 83	55235	DAYMK MISSING	PA
Matlacha Pass Daybeacon 85	55240	DAYMK MISSING	PA
Matlacha Pass Daybeacon 87	55245	DAYMK MISSING	PA
Matlacha Pass Daybeacon 89	55250	DAYMK MISSING	PA
Matlacha Pass Daybeacon 91	55255	DAYMK MISSING	PA
Matlacha Pass Daybeacon 92	55260	DAYMK MISSING	PA
Matlacha Pass Daybeacon 93	55265	DAYMK MISSING	PA
Matlacha Pass Daybeacon 99	55275.200000000004	STRUCT DEST	PA
Paradise Canal Daybeacon 1	55310	DAYMK MISSING	PA
Paradise Canal Daybeacon 2	55315	DAYMK MISSING	PA
Paradise Canal Daybeacon 3	55320	STRUCT DEST	PA
Paradise Canal Daybeacon 5	55330	STRUCT DEST	PA
Long Cutoff Daybeacon 2	55370	STRUCT DEST/HAZ NAV	PA
Safety Harbor Channel Daybeacon 1	55915	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 5	55925	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 4	55930	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 7	55933	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 9	55935	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 12	55950	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 19	55965	DAYMK MISSING	PA
Safety Harbor Channel Daybeacon 3	55923	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 11	55940	STRUCT DEST	PA
Safety Harbor Channel Daybeacon 17	55960	DAYMK MISSING	PA

Pithlachascotee River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pithlachascottee River Daybeacon 43	26765	STRUCT DEST	PA
Pithlachascottee River Daybeacon 51	26790	STRUCT DEST	PA
Pithlachascottee River Daybeacon 56	26805	STRUCT DEST	PA
Pithlachascottee River Daybeacon 48	26780	STRUCT DEST/HAZ NAV	PA

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Pithlachascotee	Bridges	General/Bridges/Public Notice From: 2025-07-28 To: 2025-08-29 Location: 28.24029° N / 82.71952° W Bridge Name: Grand Boulevard Bridge	Lat:
River/General/Bridges/Public		The Coast Guard has issued a public notice announcing a permit application from Pasco County, FL requesting approval of the location and	28° 14' 25"
Notice		plans for the reconstruction of the CR 595/Grand Boulevard Bridge over the Pithlachascotee River, at New Port Richey, Pasco County, Florida.	Lon:
		Public Notice 03-25 provides details of the proposed bridge project and solicits comments concerning the project. The public notice is available	-082° 43'
		at http://www.navcen.uscg.gov/?pageName=pnBridges&Active=1®ion=7.	10"

Plantation Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Plantation Creek Daybeacon 4	6265	STRUCT DEST	FD

Point Pinellas Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Point Pinellas Channel Light 9	24735.100000000002	STRUCT MISSING	FD	
Point Pinellas Channel Light 10	24735.2	STRUCT MISSING/TRLB	FD	

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little Bayou Approachroach Daybeacon 3	24765	DAYMK MISSING	PA
Little Bayou Approachroach Daybeacon 7	24775	STRUCT MISSING	PA
Little Bayou Approachroach Daybeacon 9	24780	STRUCT DEST	PA
Coquina Key Cut Daybeacon 3	24835	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Mullet Key Channel - Point Pinellas Channel/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change From: 2025-07-16 To: 2026-01-12 Location: 27.73145° N / 82.61035° W Aid Name: Point Pinellas Channel Light 10 LLNR: 24735.2 Action: DISCONTINUE The following change is being proposed to the aids to navigation system on the Pinellas Point Channel. Point Pinellas Channel LT 9 (LLNR 24735.1) will be converted to Point Pinellas Channel LB 9 (LLNR 24735). Point Pinellas Channel LT 10 (LLNR 24735.2) will be permanently discontinued. The two lights have experienced several allisions resulting in both lights being out of service for extended periods of time and being replaced by a small lighted temporary buoy. In addition, the depth of water in these locations exceeds the maximum water depth that a U.S. Coast Guard asset can safely rebuild the lights. Given these conditions the channel will be better served with one lighted buoy in this location. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or andrew.m.engle@uscg.mil with Point Pinellas Channel as the subject line and be received by September 16, 2025. Comments can also be mailed to Commander (DPW), U.S. Coast Guard Southeast District, 909 SE 1st Avenue (STE 406) Brickell Federal Plaza Bldg., Miami, FL. 33131.	Lat: 27° 43' 53" Lon: -082° 36' 37"
Mullet Key Channel - Point Pinellas Channel/ATON/Proposed Notice of Change		ATON/Proposed Notice of Change 23809 Location: 27.73143° N / 82.61106° W Aid Name: Point Pinellas Channel Light 9 LLNR: 24735.1 Action: CHANGE Action Type Change Aid Subtype The following change is being proposed to the aids to navigation system on the Pinellas Point Channel. Point Pinellas Channel LT 9 (LLNR 24735.1) will be converted to Point Pinellas Channel LB 9 (LLNR 24735). Point Pinellas Channel LT 10 (LLNR 24735.2) will be permanently discontinued. The two lights have experienced several allisions resulting in both lights being out of service for extended periods of time and being replaced by a small lighted temporary buoy. In addition, the depth of water in these locations exceeds the maximum water depth that a U.S. Coast Guard asset can safely rebuild the lights. Given these conditions the channel will be better served with one lighted buoy in this location. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or andrew.m.engle@uscg.mil with Point Pinellas Channel as the subject line and be received by September 16, 2025. Comments can also be mailed to Commander (DPW), U.S. Coast Guard Southeast District, 909 SE 1st Avenue (STE 406) Brickell Federal Plaza Bldg., Miami, FL. 33131.	Lat: 27° 43' 53" Lon: -082° 36' 40"

Ponce De Leon Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Cut Daybeacon 18	40610	STRUCT DEST/TRUB	FD

Ponce De Leon Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ponce De Leon Inlet North Jetty Light	9520	STRUCT DEST	FD
Ponce De Leon Inlet Buoy 7B	9544	OFF STATION	FD
Ponce De Leon Inlet Buoy 8A	9546	MISSING	FD
Ponce De Leon Inlet Lighted Buoy 9	9550	MISSING	FD
Ponce De Leon Inlet Light 12	9570	STRUCT DEST/TRLB	FD

Port Everglades

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Everglades South Regulatory Light	10349	STRUCT DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	
*****	000011100111	22011111111		

41/73

https://www.navcen.uscg.gov/msi

Sector Miami, Submerged Land Act (SLA) -	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-10-20 To:	Lat:
Port Everglades/General/Marine	Construction	2025-04-18 Location: 26.0961° N / 80.12005° W Orion Marine Construction, Inc. will be starting construction of the above	26° 05' 46"
Construction (Excluding Bridges)/Facilities,	(Excluding	referenced project from the water side using two crane loaded deck barges (999 crane on KS6019 barge and 1250 crane on	Lon:
Barriers, Manmade Reefs, Riprap,	Bridges)	KS6012 barge) along with four material barges (TBD1 through TBD4); all being serviced by a full-time push boat (TBD5). Orion will	-080° 07'
Jetties/Dikes		be on-site on July 15, 2024, and will start working on all activities related to the replacement of approximately 2300 feet of	12"
		bulkhead. Hours of operation will be from 7 a.m. to 7 p.m. The estimated completion date is July 1, 2026. All the barges are	
		intended to be spudded around the Port Everglades Berths 1-3 and 1A-1D area (26-05-53.68N / 080-07-12.11W) while working on	
		replacing the bulkhead in those locations. Vessels will be monitoring VHF-FM channel 11.	

Port Manatee Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Manatee Channel Outbound Range Rear Light	22558	STRUCT DEST/TRLB	FD
Port Manatee Channel Outbound Range Rear Passing Light	22559	STRUCT DEST	FD

Port Royal Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Royal Sound Channel Lighted Buoy 5	4095	MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mackay Creek Light 1	4170	LT IMCH/STRUCT DMGD	PA

Port Sutton Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Sutton Channel Range Rear Light	23580	LT IMCH	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Hillsborough Cut D Channel - Port Sutton Channel/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 23665 The Dutra Group has been contracted to perform maintenance dredging in Tampa Harbor Cut-C. Beginning on or around July 16, 2025, Orion's crane barge M-1702, Tug, Tender boat, Survey boat, and Off loader will begin operating in Tampa Harbor. The dredge has been contracted to remove material from Cut-C (HB) Channel beginning at Red Buoy 28 up to Green Buoy 31. The work area includes the fill site on 2-D island. The towing tugs will be moving the material scows between the dredge area from Cut-C and the pump off which is located at 2-D Island. Type of Operation: Mechanical Clamshell Dredging with Hydraulic Offloading of Scow Barges and Pumping Dredge Slurry to Disposal Island 2D. Hours of Operation: 12 hours per day (Daylight Hours) Days of Operation: Monday through Sunday (7 days per week) Name of Contact Vessel: M-1702 (HS Liebherr 895 HD) VHF-FM channels Monitored: Channels 13, 16 and Working Channel 79 and 78. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Floating rubber pipeline and submerged polyethylene pipeline associated with the hydraulic unloading operation(s) at the Disposal Island will be utilized. Pipeline, vessels, and mooring piles will be visibly lighted. Approximate Location of Temporary Features: BG1A Offloading Barge 230' x 60' w/ Spuds 27-53-16.90N/82-25-56.78W MP1A Mooring Pile #1A 24" Round Steel 27-53-16.65N/82-25'55.62W MP2A Mooring Pile #2A 24" Round Steel 27-53-16.65N/82-25'55.62W MP2A Mooring Pile #3A 24" Round Steel 27-53-16.65N/82-25'55.88W Pipeline Discharge on 2D 16" HDPE Pipe 27-53-00.00N/82-25'51.00W Beginning on or around September 1, 2025, Dutra's equipment Dredge Stuyvesant, Tug, Tender boat, Survey Gracey Jean, Crane Barge, Pipeline, and Spreader Barge will be operating in Tampa Harbor. The dredge has been contracted to remove material from Cut-C (HB) Channel beginning at Green Buoy 11	r

Ppg Industries

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
PPG Industries Lighted Buoy 3	32160	OFF STA	PA
Ppg Industries Lighted Buoy 1	32150	MISSING	PA
Ppg Industries Lighted Buoy 2	32155	MISSING	PA

Puerto Del Rey Marina

Federal Discrepancies

https://www.navcen.uscg.gov/msi 42/73

NAME	LLNR	STATUS	AID TYPE
Bajos Chinchorro Del Sur Light	31380	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Puerto Del Rey Marina/General/Hazards To		The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast	
Navigation/Hazards		Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Puerto Nuevo Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Isla Grande Pier 16 Southeast Light	30920	LT EXT	PA

Punta Gorda

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Punta Gorda East Seawall Light	31190	STRUCT DEST	PA
Punta Gorda West Seawall Light	31195	STRUCT DEST	PA

Radas Roosevelt Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Radas Roosevelt Passage Lighted Buoy 3	31565	SINKING/TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Radas Roosevelt	Hazards To	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2027-07-28 Location: 18.17261° N / 65.39295° W 18.15467° N / 65.30472° W	
Passage/General/Hazards To	Navigation	18.15924° N / 65.28892° W 18.13738° N / 65.25219° W 18.13445° N / 65.26798° W 18.14815° N / 65.28824° W 18.14162° N / 65.30128° W	
Navigation/Hazards		18.16218° N / 65.39432° W 18.15533° N / 65.44273° W 18.16283° N / 65.44548° W 18.17261° N / 65.39295° W The U.S. NAVY is advising all	
		mariners to refrain from entering the following areas in Vieques, Puerto Rico: Northeast from Puerto Diablo to Punta Este and on the Southeast	
		on Bahia Salinas Del Sur. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance.	
		The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria	
		Danois at: (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	

Redfish Pass

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redfish Pass Lighted Buoy 1	1255	BUOY DMGD	PA
Redfish Pass Buoy 2	1257	BUOY DMGD	PA
Redfish Pass Buoy 4	1260	BUOY DMGD	PA

Redhook Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Redhook Bay Buoy 2	32425	OFF STA	PA

Riverside

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Riverside Daybeacon 43	8980	STRUCT DEST/TRUB	FD

Roberts Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Roberts Bay Channel Light 13	57760	DAYMK MISSING	FD

Private Discrepancies

https://www.navcen.uscg.gov/msi 43/73

NAME	LLNR	STATUS	AID TYPE
Dona Bay Channel Daybeacon 6	21455.600000000002	STRUCT DEST	PA
Dona Bay Channel Daybeacon 9	21455.9	STRUCT DEST	PA
Dona Bay Channel Daybeacon 10	21456	STRUCT DEST/HAZ NAV	PA
Higel Park North Channel Buoy 3	57777	MISSING	PA
Higel Park North Channel Buoy 1	57776	MISSING	PA

Rockdedundy River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rockdedundy River Daybeacon 188	36850	TRUB/STRUCT MISSING	FD

Rocky Reef

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Reef Daybeacon 12	51235	STRUCT DEST	FD

San Carlos Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Carlos Bay Light SC	17990	DAYMK MISSING	FD
San Carlos Bay Channel Light 2	18000	LT EXT	FD
Punta Rassa Light 3	18020	STRUCT MISSING/TRLB	FD
San Carlos Bay Channel Light 10	18035	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Punta Rassa Boat Ramp Channel Daybeacon 3	18050	STRUCT DEST	PA
Port Sanibel Marina Daybeacon 26	18069.3	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 33	18069.7	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 42	18069.98	DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 12	18068.100000000002	HAZ NAV/DAYMK MISSING	PA
Port Sanibel Marina Daybeacon 30	18069.5	DAYMK DMGD	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
San Carlos	Bridges	General/Bridges/Construction From: 2024-11-12 To: 2026-12-31 Location: 26.40435° N / 81.88092° W Bridge Name: Big Carlos Pass Bridge	Lat:
Bay/General/Bridges/Construction		Big Carlos Pass The existing bascule bridge will be replaced with a higher-level fixed bridge. In-water work is expected through December	26° 24' 16"
		2026. A temporary work trestle will be installed oceanward of the bridge and will span the waterway except across the main navigational	Lon:
		channel. The work trestle will provide only 5 feet of vertical clearance throughout the structure. The installation of girder beams will set a	-081° 52'
		permanent fixed/limited vertical clearance of 49 feet at mean high water across the navigational channel. Temporary bridge lighting will be	51"
		installed on the new structure. The drawbridge will remain fully operational. All mariners are requested to use extreme caution and proceed	
		at slow speed when transiting Big Carlos Pass and remain in the main channel when proceeding through the bridge. All in-water equipment	
		is required to be lighted at night.	

San Sebastian River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
San Sebastian River Daybeacon 20	39170	STRUCT DEST	FD

Sand Key

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sand Key Daybeacon 25	61465	STRUCT DEST/DBD DEST/HAZ NAV/TRLB	FD

Sapelo River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo River Daybeacon 2	5875	STRUCT MISSING	FD

Sapelo River Buoy 8	5900	MISSING	FD
Sapelo River Daybeacon 150	36665	STRUCT DEST	FD

Sapelo Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sapelo Sound Buoy 2	5840	MISSING	FD
Sapelo Sound Buoy 5	5850	OFF STATION	FD
Sapelo Sound Light 138	36630.1	STRUCT DEST/TRLB	FD

Sawpit Creek

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Sawpit Creek Daybeacon 49A	38193	DISCONTINUED	FD
Sawpit Creek Temporary Daybeacon 50A	38195.1	ESTABLISHED	FD

Sector Charleston, Exclusive Economic Zone (EEZ)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
NOAA Data Lighted Buoy 41010 (ODAS)	845	ADRIFT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tybee Creek Fishing Pier Light	370	LT EXT	PA

Sector Charleston, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Little River Inlet Daybeacon 19	1750.5	STRUCT MISSING/TRUB	FD
Murrells Inlet Light 10	1800	TRLB/STRUCT MISSING	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Wreck Temporary Lighted Buoy	37386	ESTABLISHED	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Territorial Sea - Sector Charleston, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 19760 Location: 33.44887° N / 80.16122° W South Carolina Public Service Authority will be removing a land mass on the Santee River beginning May 1, 2025, until December 31, 2025, and May 1, 2026, until December 31, 2026. Hours of operation are Monday – Friday 6 a.m. to 6 p.m. Vessels will be monitoring VHF-FM channel 16.	Lat: 33° 26' 56" Lon: -080° 09' 40"
Sector Charleston, Territorial Sea - Sector Charleston, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 24099 Marinex Construction, Inc. will perform dredging work for the 2025 Beach Renourishment Project for the Town of Hilton Head, South Carolina. The DREDGE SAVANNAH plans to begin to mobilize July 25, 2025, into the staging area and installing submerged pipeline from the Baypoint Shoals Borrow Area to the three renourishment sites: Fish Haul/Spa; Pine Island; and The Heel/Port Royal. Baypoint Shoals Borrow Site is located approximately 1.5 miles offshore of Port Royal Sound, north of Port Royal Sound Channel Lighted Buoy 14 (LLNR 4130) and Port Royal Sound Lighted Buoy 19 (LLNR 4140). The dredge pipe and equipment will be staged in the Chechessee River southwest of Daws Island beginning on July 25, 2025. The Dredge Savannah will operate 24-7 and monitor VHF-FM channels 13 and 16, from approximately August 6, 2025, through November 30, 2025.	

Sector Charleston, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tybee Range Lighted Buoy 6	4570	OFF STATION	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
St. Simons Light	520	RELIGHTED	FD	2025-07-29

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE

Capers Island Lighted Buoy D	169	OFF STATION	PA
Charleston Sixty Foot Reef Buoy	230	OFF STA	PA
Folly Beach Fishing Pier Obstruction Light	235	LT EXT	PA
North Edisto Reef Lighted Buoy	260	MISSING	PA
Edisto Sixty Foot Reef Buoy	270	OFF STA	PA
Fripp Island Lighted Buoy E	297	OFF STATION	PA
General Gordon Wreck Fish Haven Buoy	305	OFF STA	PA
Whitewater Reef Buoy	335	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Charleston Light	195	Reduced Intensity	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Exclusive Economic Zone (EEZ) - Sector Charleston, Territorial Sea/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 31.04263° N / 81.25632° W Aid Name: Brunswick Spoil Area Lighted Buoy C LLNR: 518 Action: RENAME Brunswick Spoil Area Lighted Buoy C (LLNR 518) will be changed to Brunswick Spoil Area Lighted Buoy D (LLNR 518). The name change is to alleviate confusion when the Brunswick Pilots instruct commercial vessels to rendezvous with the pilot boat at the "Sea Buoy" (St Simons Sound Lighted Buoy STS). The similarity in names between the two aids has caused confusion amongst mariners. With the Brunswick Spoil Area Lighted Buoy C marking a shoal, this confusion could lead to a potential grounding.	Lat: 31° 02' 33" Lon: -081° 15' 23"
Sector Charleston, Exclusive Economic Zone (EEZ) - Sector Charleston, Territorial Sea/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change 22457 Location: 32.75793° N / 79.84324° W Aid Name: Charleston Light LLNR: 195 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following changes to the Aids to Navigation System in the Charleston Harbor: Charleston Light (LLNR 195) will permanently have the nominal range reduced from 20NM to 17NM due to the installation of an LED optic. This optic will ensure the light is more reliable as parts and essential components become harder to source for the existing optic. Any part or component failure with the current equipment could potentially lead to an extended period where the light would be extinguished. The flash characteristic and color will remain the same.	Lat: 32° 45' 29" Lon: -079° 50' 36"
Sector Charleston, Exclusive Economic Zone (EEZ) - Sector Charleston, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 22053 South Carolina Department of Natural Resources will be establishing an artificial fishing reef. Estimated completion date is December 31, 2028.	

Sector Jacksonville, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. Johns Light	575	LT IMCH	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 9374 From: 2025-01-21 To: 2025-11-07 Gator Dredging will be dredging Ponce Inlet and connecting ICW, disposing onto Ponce Inlet Beach. Operations are expected to commence on or about March 3, 2025, with an estimated completion date of November 7, 2025. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Floating and submerged high density polyethylene (HDPE) and steel pipeline associated with the hydraulic dredging operations of the channel will be utilized. Pipeline, work vessels, dredge barge, booster pump barge(s) and buoys will be visibly lighted and marked according to coast guard regulations and will be in the area until all work is complete and can change configuration daily. Vessels BRITTYN B and DREDGE CLEARWATER and/or equipment will be in multiple locations at the same time and monitor VHF-FM channel 16.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging Marinex Construction, Inc. will perform dredging work for the Nassau County Shore Protection Project, Beach Renourishment. The Dredge Savannah shall begin work as early as May 5, 2025, from the borrow site located 1 ½ Miles SE of the St. Mary's River Entrance (jetties). Dredge pipe and equipment will be staged and mobilized in the Amelia River near Tiger Island across from the Dee Dee Bartels County Boat Ramp. Installation of submerged pipeline will begin as early as April 25, 2025. The Dredge Savannah will operate 24-7 and monitor VHF-FM channels 13 and 16, from approximately May 5, 2025, through August 15, 2025, with demobilization of plant and equipment through September 1, 2025.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 18002 On or about May 14, 2025, Cashman Dredging and Marine Contracting Company, LLC will begin dredging operations on U.S. Naval Station Mayport Maintenance Dredging, Duval County, Florida. The work will be done in the entrance channel and turning basin. This work will be done by the Mechanical Dredge "DALE PYATT" and the Trailing Suction Hopper Dredge "NEWPORT". Support tugs will be the "BRINN CORTNEY", "STASINOS BOYS", and "AMY HEBERT". We will be using the following dump scows: "JOE VERROCH!", M.E.R.C. SHEVLIN", and "KURT SHULTE". The dredge(s) will be supported by the survey/crew vessel "Survey 7", drag barge "Dana", tug "Miss Ila", and various other support vessels. All vessels will monitor VHF-FM channels 16,13,12 and use 74 as the working channel. Both Dredges will be using the ODMDS for open ocean disposal. Mariners are urged to transit at their slowest safe speed to minimize wake and proceed with caution after passing arrangements have been made. Dredges will operate 7 days a week, 24 hours a day. The work is scheduled to be completed on or before October 1, 2025.	
Sector Jacksonville, Territorial Sea - Sector Jacksonville, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Survey Operations	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Survey Operations 21793 Fugro USA Marine inc will be conducting hydrographic surveys from Florida east coast from Jacksonville down to Cape Canaveral, FL. Operations are expected to begin on or about June 20, 2025, with an estimated completion date of March 15, 2026, and be conducted. R/V ANNA M will be operating Multi Beam Echo Sounders and deploying sound velocity profilers from stern 7 days a week, 24 hours day. They will be monitoring VHF-FM channel 16. Average vessel speed will be 10-14 knots with sensor down. Maximum vessel speed is 24 knots during transits.	

https://www.navcen.uscg.gov/msi 46/73

Sector Jacksonville, Territorial Sea - Sector	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 23228 The Burrell	
Jacksonville, Submerged Land Act	Construction	Navigational Lock will be dewatered and closed for maintenance from July 20, 2025, until approximately October 30, 2025. Burrell	
(SLA)/General/Marine Construction	(Excluding	Lock is in Haines Creek between Lake Eustis and Lake Griffin at 10401 Lock Road, in Leesburg, Lake County, FL. For further	
(Excluding Bridges)/Facilities, Barriers,	Bridges)	information contact: St. Johns River Water Management District at rtudeau@sjrwmd.com.	
Manmade Reefs, Riprap, Jetties/Dikes			
Sector Jacksonville, Territorial Sea - Sector	Miscellaneous	General/Miscellaneous 20295 The U.S. Space Force may choose to enforce a restricted area as specified in 33 CFR 329.525 and 33	
Jacksonville, Submerged Land Act		CFR 329.595. Primarily beginning 2 hours prior to the scheduled launch window of any rocket launches. The restricted area would	
(SLA)/General/Miscellaneous		remain in effect until suspended by Space Launch Delta 45.	

Sector Key West, Exclusive Economic Zone (EEZ)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Tortugas Southeast Channel Light 1	15440	HAZ NAV/LT EXT/DAYMK MISSING	FD
Dry Tortugas Southeast Channel Light 3	15450	STRUCT DEST/HAZ NAV/TRLB	FD
Fort Jefferson West Channel Daybeacon 10	15560	STRUCT DEST	FD

Sector Key West, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Davis Reef Light 14	970	LT EXT	FD
Cosgrove Shoal Light	1070	LT EXT	FD
Halfmoon Shoal Light WR2	1085	STRUCT DEST	FD
New Ground Rocks Light	1190	HAZ NAV/LT EXT/STRUCT DMGD/TRLB	FD
Smith Shoal Light	1200	LT EXT	FD
Broad Creek Light 6	1215	DAYMK MISSING	FD
Bache Shoal Daybeacon 9	10915	DAYMK MISSING	FD
urtle Harbor West Shoal Preferred Channel Light	11455	STRUCT DEST	FD
Cey Largo Light 25	11485	STRUCT DEST	FD
ey Largo Light 25	11485	DBD DMGD	FD
asin Hills Light 31BH	11500	STRUCT DEST	FD
ey Largo Daybeacon 32A	11675	STRUCT DEST/TRLB	FD
Mosquito Bank Light 2	11895	STRUCT DEST/HAZ NAV/TRLB	FD
Channel Key Daybeacon 7	12430	STRUCT MISSING/TRLB	FD
orpoise Key Daybeacon 2	12685	HAZ NAV/DAYMK MISSING/TRLB	FD
Noser Channel South Daybeacon 5	13865	STRUCT DEST/TRLB/HAZ NAV	FD
ahia Honda Key Light 49A	13875	DAYMK MISSING	FD
liles Channel Daybeacon 6	13955	STRUCT DEST/HAZ NAV/TRLB	FD
oggerhead Key Light 50A	13980	STRUCT DEST/TRLB	FD
oggerhead Key Light 50A	13980	HAZ NAV/STRUCT DEST/TRLB	FD
rirates Cove Daybeacon 10	14175	STRUCT DEST/HAZ NAV/TRLB	FD
loca Chica Channel Light 1	14505	HAZ NAV/TRLB/STRUCT DEST	FD
ey West Main Channel Range Front Light	14815	STRUCT DEST/TRLT	FD
ey West Northwest Channel Light 6	15165	STRUCT DEST/TRLB	FD
ey West Northwest Channel Daybeacon 8	15200	STRUCT DEST/TRLB	FD
ey West Northwest Channel Daybeacon 15	15230	STRUCT DEST/TRUB	FD
alda Channel Light 1	15330	STRUCT DEST/HAZ NAV/TRLB	FD
alda Channel Daybeacon 5	15340	HAZ NAV/STRUCT DEST/TRLB	FD
alda Channel Daybeacon 6	15345	STRUCT DEST/TRUB	FD
alda Channel Daybeacon 18	15400	STRUCT DEST	FD
alda Channel Daybeacon 22	15415	STRUCT DEST	FD
ort Jefferson East Channel Daybeacon 3	15470	STRUCT DEST/HAZ NAV/TRLB	FD
ort Jefferson East Channel Daybeacon 5	15475	HAZ NAV/DAYMK MISSING/TRLB	FD
ort Jefferson East Channel Daybeacon 6	15480	STRUCT DEST/HAZ NAV/TRLB	FD
ort Jefferson East Channel Daybeacon 7	15485	STRUCT DEST/HAZ NAV/TRLB	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Newfound Harbor Keys Light 50	13880	WATCHING PROPERLY	FD	2025-07-23

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Newfound Harbor Key Buoy C	1003.4	MISSING	PA
Broad Creek Daybeacon 2	11177.1	STRUCT DEST	PA
Dispatch Creek Channel Daybeacon 20	11435	DAYMK IMCH	PA

5/0/25, 12.20 PIVI	Manume Salety Information Produ	ucis Navigation Center	
Harbor Course Creek Daybeacon 1	11440	DAYMK IMCH	PA
Harbor Course Creek Daybeacon 2	11445	DAYMK IMCH	PA
Garden Cove Daybeacon 22	11645	STRUCT DEST	PA
Port Largo Channel Light 7	11765.30000000001	STRUCT DEST	PA
Blue Water Trailer Vill Daybeacon 2	12015	STRUCT DEST	PA
Red Bay Shoal Daybeacon A	12511	STRUCT DEST	PA
La Siesta Resort Daybeacon 2	12810	STRUCT DEST/HAZ NAV	PA
Upper Matecumbe West Channel Daybeacon 1	12825	STRUCT DEST/HAZ NAV	PA
Caloosa Cove Channel Daybeacon 11	13385	STRUCT DMGD	PA
Duck Key Inlet Channel Light 1	13500	STRUCT DEST	PA
Duck Key Inlet Channel Daybeacon 2	13505	STRUCT DEST	PA
Duck Key Inlet Channel Daybeacon 7	13525.5	STRUCT DEST	PA
Coco Plum Channel Daybeacon 2	13625	STRUCT DEST	PA
Coco Plum Channel Daybeacon 3	13630	STRUCT DEST	PA
Coco Plum Channel Daybeacon 4	13635	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 2	13670	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 4	13673	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 5	13675	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 7	13676	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 8	13676.30000000001	STRUCT DEST	PA
Bonefish Bay Shoal Daybeacon	13676.5	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 10	13676.7	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 11	13676.9	STRUCT DEST	PA
Bonefish Bay Channel Daybeacon 13	13677	STRUCT DEST	PA
Boat House Channel Buoy 3	13680.2	MISSING	PA
Dolphin Marina Channel Daybeacon 2	13936.2	STRUCT DEST	PA
Kemp Channel Daybeacon 2	13990	STRUCT DEST/HAZ NAV	PA
Summerland Key Daybeacon 2	14055	HAZ NAV/STRUCT DEST	PA
Kemp Channel Daybeacon 19	14073	STRUCT DEST	PA
Kemp Channel Daybeacon 24	14095	STRUCT DEST/HAZ NAV	PA
Tamarac Park Channel Obstruction E Daybeacon	14450	STRUCT DEST	PA
Cow Key Channel Daybeacon 11	14740	STRUCT DMGD	PA
Cow Key Channel Daybeacon 13	14745	STRUCT DMGD	PA
Cow Key Channel Daybeacon 25	14766.5	DAYMK MISSING	PA
Cow Key Channel Daybeacon 36	14767.9	STRUCT DMGD	PA
Casa Marina Daybeacon 4	14795	STRUCT DEST	PA
Fort Taylor West Obstruction Light	14887	LT EXT	PA
Key West Mooring Field Light A	14980.1	LT EXT	PA
Key West Mooring Field Light B	14980.2	LT EXT	PA
Key West Mooring Field Light C	14980.30000000001	STRUCT DEST/HAZ NAV	PA
Key West Mooring Field Light D	14980.4	LT EXT	PA
Key West Mooring Field Light E	14980.5	LT EXT	PA
Newfound Harbor Key Buoy D	1003.6	MISSING	PA
Western Sambo Buoy B	1024.2	MISSING	PA
Sand Key Buoy B	1054.2	MISSING	PA
Lewis Cut Shoal West Buoy	10907.5	MISSING	PA
Broad Creek Daybeacon 13	11177.6	STRUCT DEST	PA
Key West Oceanside Marina Daybeacon 2	14670	DAYMK MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	The RFL will be changed to a day/night optic, continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 32' 17" Lon: -081° 48' 23"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 32' 56" Lon: -081° 48' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	LLNR: 14870 Action: CHANGE Action Type Change Structure The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Main Channel Cut B Range Front Light (LLNR 14870) will be rebuilt at a new focal height of 40 feet. All other characteristics will remain the same. Key West Main Channel Cut B Range Rear Light (LLNR 14875)	Lat: 24° 33' 38" Lon: -081° 48' 52"

https://www.navcen.uscg.gov/msi 48/73

0/20, 12:20 1 W		Manufine Safety Information Frounds Navigation Softer	
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.5629° N / 81.81427° W Aid Name: Key West Main Channel Cut B Range Rear Light LLNR: 14875 Action: CHANGE Action Type Change Structure The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Main Channel Cut B Range Front Light (LLNR 14870) will be rebuilt at a new focal height of 40 feet. All other characteristics will remain the same. Key West Main Channel Cut B Range Rear Light (LLNR 14875) will be rebuilt at a new focal height of 65 feet. All other characteristics will remain the same.	Lat: 24° 33' 46" Lon: -081° 48' 51"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.59918° N / 81.80971° W Aid Name: Calda Channel Daybeacon 22 LLNR: 15415 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	Lat: 24° 35' 57" Lon: -081° 48' 35"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.60718° N / 81.80627° W Aid Name: Calda Channel Daybeacon 18 LLNR: 15400 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guardhas approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	Lat: 24° 36' 26" Lon: -081° 48' 23"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.62495° N / 81.81523° W Aid Name: Calda Channel Daybeacon 6 LLNR: 15345 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following changes to the Aids to Navigation System in Calda Channel: Discontinue Calda Channel Daybeacon 6 (LLNR 15345) and establish Calda Channel Buoy 6 (LLNR 15345) in approximate position 24-37-29.832N/081-48-54.830W. Discontinue Calda Channel Daybeacon 18 (LLNR 15400) and establish Calda Channel Buoy 18 (LLNR 15000) in approximate position 24-36-25.834N/081-48-22.586W. Discontinue Calda Channel Daybeacon 22 (LLNR 15415) and establish Calda Channel Buoy 22 (LLNR 15415) in approximate position 24-35-57.055N/081-48-34.971W.	Lat: 24° 37' 30" Lon: -081° 48' 55"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.57937° N / 81.79983° W Aid Name: Key West Harbor Range Front Light LLNR: 14900 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Harbor Range Front Light (LLNR 14900) will be changed to a day/night optic, continuing to display Q W flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued. Key West Harbor Range Rear Light (LLNR 14905) will be rebuilt to a focal height of 46 feet and changed to a day/night optic, continuing to display ISO W 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 34' 46" Lon: -081° 47' 59"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 24.58519° N / 81.79695° W Aid Name: Key West Harbor Range Rear Light LLNR: 14905 Action: CHANGE Action Type Change Light Signals The U.S. Coast Guard has approved the following change to the Aids to Navigation System in the Key West Main Channel: Key West Harbor Range Front Light (LLNR 14900) will be changed to a day/night optic, continuing to display Q W flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued. Key West Harbor Range Rear Light (LLNR 14905) will be rebuilt to a focal height of 46 feet and changed to a day/night optic, continuing to display ISO W 6s flash characteristic for a 24hr continuous cycle. The daymarks will be discontinued.	Lat: 24° 35' 07" Lon: -081° 47' 49"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Bridges/Closure (Scheduled Or Emergency)	Bridges	General/Bridges/Closure (Scheduled Or Emergency) From: 2024-10-29 To: 2025-11-01 Location: 24.60464° N / 81.64066° W Bridge Name: Shark Key Pedestrian Bridge The Shark Channel pedestrian bridge is damaged with debris falling into the water. Mariners are advised to use caution in the area and avoid transiting under the bridge. For more information, contact Florida Keys Overseas Heritage Trail Assistant Park Manager, Jimmy Chandler at (305) 360-7958.	Lat: 24° 36' 17" Lon: -081° 38' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-12 To: 2025-09-01 Location: 24.60459° N / 81.64045° W Bridge Name: Florida Keys Overseas Historical Trial Pedestrian Bridge - Shark Channel The pedestrian bridge is undergoing a rehabilitation project. The contractor will have barges and associated in-water equipment in and around the bridge at all times. All in-water equipment should be lighted in accordance with Inland Navigation rules. Navigation through the structure will be limited during construction; at any time, four (4) arches will be obstructed and closed to navigation. Mariners are advised to proceed at a safe speed and use caution when transiting through the area. The rehabilitation project will begin on or around 3/13/2025 and be completed by 9/1/2025. For waterways related questions, contact, Coast Guard Sector Key West Waterways, 305-292-8768 or email: SKWWaterways@uscg.mil.	Lat: 24° 36' 17" Lon: -081° 38' 26"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2025-07-31 To: 2029-03-31 Location: 24.65831° N / 81.28705° W Bridge Name: United States 1 Highway Bridge 8/11/2025 through 3/31/2029 Rehabilitation/maintenance/repair of the existing structure on SR 5 / US 1 Overseas Highway over Bahia Honda Channel. Project consists of Concrete Repair, Concrete Encapsulation, Pile Jacket Installation, Minor Painting, and Bearing Pad Replacement. The contractor will have work boats, barges and associated construction equipment in and around the bridge structure. Mariners are advised to transit the area with caution.	Lat: 24° 39' 30" Lon: -081° 17' 13"
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	General/Miscellaneous 18012 Mote Marine Laboratory and Aquarium will be launching an autonomous surface vessel for a gulf water quality survey and harmful algal bloom monitoring, traversing from Sarasota, FL to Key West, FL Operations are expected to being May 6, 2025, with an estimated completion date of May 21, 2025. Vessel is equipped with AIS transmit and receiving capabilities.	
Sector Key West, Territorial Sea - Sector Key West, Submerged Land Act (SLA)/General/Naval Activity/Military Operations	Naval Activity	General/Naval Activity/Military Operations 18248 The US Navy will be conducting exercises in Key West Florida in the coming weeks of August 4 – 15, August 25 – September 5, September 15 – 26. All support vessels will be monitoring VHF-FM channels 16 and 81A. On Monday, August 11, 2025, September 1, 2025, and September 22, 2025, they will be conducting a dive down the Boca Chica Chanel to the harbor between 6 p.m. and 10 p.m. Divers will stay to the Eastern side of the channel, and they will have four boats plus two jet skis to deconflict with mariners and provide diver support and protection. On Tuesday August 12, 2025, September 2, 2025, and September 23, 2025, they will be conducting a day dive from 4 p.m. to 6:30 p.m. in Fleming Key Cut. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. Divers will be confined to transiting through the cut on only one side, leaving the other side open. Also, on Tuesday August 12, 2025, September 2, 2025, and September 23, 2025, they will be conducting a night dive from 7:30 p.m. to 10 p.m. along the western edge of Key West from the mouth of Key West Bight to Truman Waterfront Park. Divers will be no farther from shore than 50 meters and should pose a minimal obstruction to routine navigational operations. Depending on the weather and sea state, they may flex to doing an offset dive. They would splash the divers at either Key West Main Channel Daybeacon 21 (LLNR 4925) diving east into the Basin, or Key West Main Channel Lighted Buoy 15 (LLNR 14895) diving east into the Basin. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protection. On Wednesday, August 13, 2025, September 3, 2025, and September 24, 2025, they will be conducting a day into night dive from 7p.m. until 9:30 p.m. around fleming Key Cut. They will have four boats and two jet skis on station to deconflict with other mariners and provide diver support and protectio	

Sector Key West, Territorial Sea

Federal Discrepancies

https://www.navcen.uscg.gov/msi 49/73

NAME	LLNR	STATUS	AID TYPE
Pacific Reef Light	935	LT EXT/TRLT	FD
Elbow Reef Light 6	950	STRUCT DEST/LT IMCH/REDUCED INT/DAYMK MISSING/TRLT	FD
Molasses Reef Light 10	960	LT EXT/STRUCT DMGD	FD
Tennessee Reef Light	990	LT EXT/STRUCT DMGD	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Carysfort Reef Buoy C	947.4	MISSING	PA
The Elbow Buoy B	948.2	MISSING	PA
The Elbow Buoy C	948.4	MISSING	PA
The Elbow Buoy D	948.6	MISSING	PA
Dry Rocks Buoy A	953	MISSING	PA
Grecian Rocks Buoy D	954.6	MISSING	PA
Sombrero Key Buoy B	1002.2	MSLD SIG	PA
Looe Key Telemetering Lighted Buoy LR	1007.800000000001	MISSING	PA
Looe Key Buoy C	1007.4	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/ATON/ATON Changes	ATON Changes	ATON/ATON Temporary Changes 24976 From: 2025-08-11 Location: 24.46495° N / 81.45885° W Aid Name: FWC Data Temporary Lighted Buoy LLNR: Not Provided Action: TEMP ESTABLISH	Lat: 24° 27' 54" Lon: -081° 27' 32"
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2024-11-26 To: 2024-11-27 Location: 24.88752° N / 81.7° W 24.88333° N / 81.7° W 24.88333° N / 81.70458° W 24.88752° N / 81.70458° N	
Sector Key West, Exclusive Economic Zone (EEZ) - Sector Key West, Territorial Sea/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes Location: 24.88752° N / 81.7° W 24.88333° N / 81.7° W 24.88333° N / 81.70458° W 24.88752° N /	

Sector Miami, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
NSWC Lighted Buoy E	811	HAZ NAV/BUOY DMGD/LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jupiter Inlet Jetty Light 2	735	LT EXT	PA
Key Biscayne FAD Northwest Buoy	900	MISSING	PA
Key Biscayne FAD Northeast Buoy	905	MISSING	PA
Key Biscayne FAD Southwest Buoy	910	MISSING	PA
Key Biscayne FAD Southeast Buoy	915	MISSING	PA
Neptune Memorial Reef Buoy AA	915.1	STRUCT DEST	PA
Neptune Memorial Reef Buoy BB	915.2	STRUCT DEST	PA
Neptune Memorial Reef Buoy CC	915.300000000001	STRUCT DEST	PA
Neptune Memorial Reef Buoy DD	915.4	STRUCT DEST	PA

Sector Mobile, Submerged Land Act (SLA)

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Mobile, Territorial Sea - Sector Mobile, Submerged Land Act	Miscellaneous	General/Miscellaneous 20969 Location: 26.89042° N / 82.34267° W Remove	Lat:
(SLA)/General/Miscellaneous		Wreck	26° 53' 26"
			Lon:
			-082° 20' 34"

https://www.navcen.uscg.gov/msi 50/73

Sector San Juan, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aguadilla Jetty Light 1	32405	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
CariCOOS Wave Buoy D	32401	ADRIFT	PA
Devcon International Channel Buoy 2	33000	OFF STA	PA
Devcon International Channel Buoy 3	33005	OFF STA	PA
Devcon International Channel Buoy 5	33015	OFF STA	PA
Lime Tree Bay Port Basin Light 15	33200	STRUCT DEST	PA
Krause Lagoon Channel Entrance Lighted Buoy 1	33210	TRLB	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector San Juan, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-20 To: 2025-04-18 Location: 18.093° N / 65.62092° W The United States Navy has installed subsurface coral restoration structures offshore of Ilsa de Vieques within the boundaries of the former Navy training range (UXO-16), for a Navy environmental restoration project. The structures include 2 geodesic spheres that are 8 feet diameter, and will be moored to the seafloor such that the tops of the structures will sit at 24 feet below the surface. These structures will not be sitting directly on the seafloor - they will be in the mid-water, moored to the seafloor (which is approximately 55 feet deep at this location) with a 3-anchor system, without surface marker buoys. The structures are expected to remain in place until at least June 30, 2026 in the approximate coordinates: 18-06-01.49N/065-36-17.97W 18-05-59.94N/065-36-17.17W For further information contact: Jessica Carilli, US Navy (760) 815-2629.	Lat: 18° 05' 35" Lon: -065° 37' 15"
Sector San Juan, Territorial Sea/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2025-01-29 To: 2027-07-28 Location: 18.26572° N / 65.57337° W 18.23996° N / 65.57028° W 18.23931° N / 65.60289° W 18.26474° N / 65.60444° W 18.26572° N / 65.57337° W The U.S. NAVY is advising all mariners to refrain from entering the following area in Ceiba, Puerto Rico: the waters surrounding Isla Piñeros. Mariners are advised to stay away from this danger zone until further notice, as it contains (UXO) Unexploded Ordnance. The U.S. Coast Guard may be contacted via VHF-FM Channel 16 or via landline at (787) 289-2041. For more information, contact Mrs. Maria Danois at (757) 412-7843 or email: maria.m.danois.civ@us.navy.mil.	
Sector San Juan, Territorial Sea/General/Marine Events/Regatta (Race)	Marine Events	General/Marine Events/Regatta (Race) The U.S. Coast Guard will be enforcing a Special Local Regulation for the St. Thomas Carnival Boat Race 2025 described in Title 33 Code of Federal Regulations (CFR) 100.701 Table 1 on April 28, 2025, from 10 a.m. to 5 p.m. The regulated area encompasses all waters of St. Thomas Harbor encompassed within the following points: i. Race Area. All waters of the St. Thomas Harbor located around Hassel Island, St. Thomas, U.S. Virgin Island encompassed within the following points: Starting at Point 1 in position 18°20.2′ N, 64°56.1′ W; thence southeast to Point 2 in position 18°19.7′ N, 64°55.7′ W; thence south to Point 3 in position 18°19.4′ N, 64°55.7′ W; thence southwest to point 4 in position 18°19.9′ N, 64°56.0′ W; thence northeast to point 6 in position 18°20.2′ N, 04°56.3′ W; thence east back to origin. ii. Jet Ski Race Area. All waters encompassed the following points: Starting at Point 1 in position 18°20.1′ N, 64°55.9′ W; thence west to Point 2 in position 18°20.1′ N, 64°56.1′ W; thence north to Point 3 in position 18°20.3′ N, 64°55.9′ W; thence east to Point 4 in position 18°20.1′ N, 64°55.7′ W; thence southeast to Point 3 in position 18°20.1′ N, 64°55.7′ W; thence southeast to Point 2 in position 18°19.9′ N, 64°55.7′ W; thence southeast to Point 3 in position 18°19.9′ N, 64°55.7′ W; thence southeast to Point 4 in position 18°19.9′ N, 64°55.7′ W; thence northwest to Point 5 in position 18°19.9′ N, 64°55.5′ W; thence northwest to Point 6 in position 18°20.3′ N, 64°56.3′ W; thence east back to origin. iv. Spectator Area. All waters of the St. Thomas Harbor located east of Hassel Island, encompassed within the following points: Starting at Point 1 in position 18°20.3′ N, 64°55.5′ W; thence southeast to Point 3 in position 18°20.2′ N, 64°55.5′ W; thence northwest to Point 6 in position 18°20.3′ N, 64°55.5′ W; thence southeast to Point 1 in position 18°20.3′ N, 64°55.5′ W; thence southeast to Point 1 in position 18°20.3′ N, 64°55.5′ W; thence southeast to Point 1 in position	
Sector San Juan, Territorial Sea/General/Safety Zones/COPT Restrictions	Safety Zones	General/Safety Zones/COPT Restrictions 23377 The U.S. Coast Guard will be enforcing a Special Local Regulation for the Cruce a Nado Internacional described in Title 33 Code of Federal Regulations (CFR) 100.701 Table 1 on August 31, 2025, from 12 p.m. to 5 p.m. The regulated area encompasses all waters of Ponce Harbor encompassed within the following points: I. Ponce Harbor, Bahia de Ponce, San Juan; All waters of Bahia de Ponce encompassed within the following points: Starting at Point 1 in position 17°58.9' N, 66°37.5' W; thence southwest to Point 2 in position 17°57.5' N, 66°38.2' W; thence southeast to Point 3 in position 17°57.4' N, 66°37.9' W; thence northeast to point 4 in position 17°58.7' N, 66°37.3' W; thence northwest along the northeastern shoreline of Bahia de Ponce to the origin. The U.S. Coast Guard may be contacted via VHF-FM channel 16. For more information, please contact Hector Merced 787-248-8541 or ccanponce@outlook.com.	

Sector St. Peterburg, Exclusive Economic Zone (EEZ)

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Scripps Wave Lighted Buoy A	1367	MISSING	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATIO
District 7, Oceanic boundary to	Marine	General/Marine Construction (Excluding Bridges)/Survey Operations Location: 28.735° N / 84.39833° W 28.735° N / 84.16° W 28.69333° N /	
EEZ - Sector St. Peterburg,	Construction	84.07333° W 28.255° N / 83.79° W 28.27167° N / 83.99667° W 28.16667° N / 83.96° W 28.16333° N / 84.13667° W 28.28667° N / 84.44333° W	
Exclusive Economic Zone	(Excluding	28.735° N / 84.39833° W SAILDRONE, INC. will be conducting research with up to two Uncrewed Surface Vehicles (USVs), called SAILDRONE	
(EEZ)/General/Marine	Bridges)	VOYAGERs, approximately 90 nautical miles northwest of St. Petersburg, FL. The vehicles are supporting the Florida Seafloor Mapping Initiative	
Construction (Excluding		in partnership with the Florida Department of Environmental Protection to conduct a survey off the West Florida Shelf known as The Florida	
Bridges)/Survey Operations		Middle Grounds. The vehicles are deployed from St. Petersburg, FL and are expected to make stops from the survey area to St. Petersburg	
		throughout this period. These vehicles will conduct 24 hr operations for the aforementioned duration. Vehicles are monitored remotely 24/7	
		by the SAILDRONE Mission Control Team. SAILDRONE VOYAGERs are primarily wind-propelled Uncrewed Surface Vehicles (USVs) equipped	
		with an electric thruster used for survey operations. Mariners are requested to remain clear from the research equipment. Questions regarding	
		this notice can be directed to Saildrone Mission Control at missioncontrol@saildrone.com or via phone at +1-510-722-6070.	

https://www.navcen.uscg.gov/msi 51/73

District 7, Oceanic boundary to	Marine	General/Marine Construction (Excluding Bridges)/Survey Operations 19366 Fugro USA Marine inc, will be conducting hydrographic surveys 24	
EEZ - Sector St. Peterburg,	Construction	hours a day, 7 days a week. M/V Renegade and M/V Anna M will be monitoring VHF-FM channel 16 and operating inside the following area	
Exclusive Economic Zone	(Excluding	with an estimated completion date of July 11, 2025. NW: 28-16-43.38N / 84-00-49.08W SW: 26-16-39.00N / 83-11-52.78W NE: 28-15-10.77N /	
(EEZ)/General/Marine	Bridges)	83-19-57.83W SE: 26-20-42.34N / 82-34-36.12W	
Construction (Excluding			
Bridges)/Survey Operations			

Sector St. Petersburg, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Anclote Anchorage South Entrance Light 1	1535	HAZ NAV/STRUCT DEST/TRLB	FD
Seahorse Reef Light	1615	STRUCT DEST/HAZ NAV	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TY
ort of Islands Marina Daybeacon 3	16235	STRUCT DEST	PA
ort of Islands Marina Daybeacon 4	16240	STRUCT DEST	PA
ort of Islands Marina Daybeacon 5	16245	STRUCT DMGD	PA
ort of Islands Marina Daybeacon 6	16250	STRUCT DEST/HAZ NAV	PA
ort of Islands Marina Daybeacon 11	16265	DAYMK MISSING	PA
ort of Islands Marina Daybeacon 15	16280	STRUCT DEST	PA
ort of Islands Marina Daybeacon 26	16310	STRUCT DEST	PA
ort of Islands Marina Daybeacon 27	16315	STRUCT DEST	PA
ort of Islands Marina Daybeacon 42	16380	STRUCT DEST/HAZ NAV	PA
ort of Islands Marina Daybeacon 44	16390	STRUCT DEST	PA
ape Romano Channel Daybeacon 2	16792	STRUCT DEST	PA
ape Romano Channel Daybeacon 4	16792.1	STRUCT DEST	PA
ape Romano Channel Daybeacon 17	16793	DAYMK MISSING	PA
axambas Breakwater North Obstruction Daybeacon	16917	STRUCT DEST	PA
axambas Breakwater South Obstruction Light	16918	LT EXT	PA
axambas Breakwater South Obstruction Daybeacon	16918.5	DAYMK MISSING	PA
octors Pass Daybeacon 16	17770	STRUCT DEST	PA
/ater Turkey Bay Channel Daybeacon 3	17830	STRUCT DEST/HAZ NAV	PA
arefoot Boat Club Daybeacon 10	17915	STRUCT DEST	PA
arefoot Boat Club Daybeacon 12	17920	STRUCT DEST	PA
g Carlos Pass Lighted Buoy 1	17975	MISSING	PA
g Carlos Pass Buoy 2	17976	MISSING	PA
g Carlos Pass Buoy 3	17977	MISSING	PA
g Carlos Pass Buoy 4	17980	MISSING	PA
g Carlos Pass Buoy 5	17985	MISSING	PA
stero Pointe Channel Daybeacon 29	18996.07	STRUCT DEST/HAZ NAV	PA
aywinds Channel Daybeacon 3	19347.3	STRUCT DEST	PA
pring Creek Daybeacon 17	19400	STRUCT DEST	PA
outh Estero Bay Daybeacon 37	19550	STRUCT DEST	PA
outh Estero Bay Daybeacon 45	19585	STRUCT DEST	PA
oconut Jacks Daybeacon 5	19786.2	STRUCT DEST	PA
cripps Wave Data Lighted Buoy CDIP STA 214	22247	OFF STA	PA
gnal Cove Light 2	26945	LT EXT	PA
ignal Cove Daybeacon 4	26955	STRUCT DEST	PA
gnal Cove Daybeacon 5	26960	STRUCT DEST	PA
udson Creek Daybeacon 7	27040	STRUCT DEST/HAZ NAV/TRUB	PA
udson Creek Daybeacon 20	27085	STRUCT DEST/TRUB	PA
udson Beach Park Daybeacon 1	27110	STRUCT DEST	PA
ea Pines Channel Daybeacon 23	27230	STRUCT DEST	PA
ea Pines Channel Daybeacon 29	27265	STRUCT DEST	PA
ripeka Daybeacon 7	27310	STRUCT DEST/HAZ NAV	PA
ernando Beach Channel Daybeacon 6	27530	STRUCT DEST	PA
ernando Beach Channel Daybeacon 7	27535	STRUCT DEST	PA
ernando Beach Channel Daybeacon 10	27550	STRUCT DEST	PA
ernando Beach Channel Daybeacon 22	27610	STRUCT DEST	PA
ernando Beach Channel Daybeacon 23	27615	STRUCT MISSING	PA
ernando Beach Channel Daybeacon 27	27630.5	STRUCT DEST/HAZ NAV	PA
ernando Beach Channel Daybeacon 40	27685	STRUCT DEST/HAZ NAV	PA
ernando Beach Channel Daybeacon 44	27705	STRUCT DEST	PA

https://www.navcen.uscg.gov/msi

10/20, 12:20 1 W	Manume Salety Information	Toddoto Mavigation Contor	
Hernando Beach Channel Light 53	27737	STRUCT DEST/HAZ NAV	PA
Johnson Rock Obstruction Daybeacon	27930	STRUCT MISSING	PA
Bayport Channel Daybeacon 15	28075	STRUCT DEST	PA
Bayport Channel Daybeacon 17	28095	STRUCT DEST/HAZ NAV	PA
Chassahowitzka Daybeacon 17	28305	STRUCT DEST	PA
Chassahowitzka Daybeacon 21	28320	STRUCT DEST	PA
Chassahowitzka Daybeacon 22	28325	STRUCT DEST	PA
Chassahowitzka Daybeacon 23	28330	STRUCT DEST	PA
Florida Power Corporation Channel Light 3	28960	LT IMCH/DAYMK MISSING	PA
Florida Power Corporation Channel Light 4	28965	LT IMCH/DAYMK MISSING	PA
Florida Power Corporation Channel Light 6	28975	LT EXT	PA
Florida Power Corporation Channel Light 8	28985	LT EXT	PA
Florida Power Corporation Channel Light 13	29005	STRUCT DEST	PA
Florida Power Corporation Channel Light 14	29010	LT EXT	PA
Florida Power Corporation Channel Light 16	29015	LT EXT	PA
Florida Power Corporation Channel Light 17	29020	LT IMCH	PA
Florida Power Corporation Channel Light 21	29035	LT EXT	PA
Florida Power Corporation Channel Light 32	29075	STRUCT DEST/HAZ NAV	PA
Florida Power Corporation Channel Light 47	29150	LT IMCH	PA
Florida Power Corporation Channel Light 48	29155	LT IMCH	PA
Waccasassa Bay And River Daybeacon 5	29665	STRUCT DEST	PA
· · · · · · · · · · · · · · · · · · ·			PA PA
Waccasassa Bay And River Daybeacon 9	29675	STRUCT DEST	PA PA
Waccasassa Bay And River Daybeacon 11 Waccasassa Bay And River Daybeacon 13	29680 29685	STRUCT DMGD	
*		STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 15	29690	STRUCT DAGE	PA
Waccasassa Bay And River Daybeacon 17	29695	STRUCT DMGD	PA
Waccasassa Bay And River Daybeacon 21	29705	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 23	29710	DAYMK DMGD	PA
Waccasassa Bay And River Daybeacon 25	29720	STRUCT DEST	PA
Waccasassa Bay And River Daybeacon 27	29725	DAYMK MISSING/STRUCT DMGD	PA
Waccasassa Bay And River Daybeacon 30	29735	STRUCT DEST/HAZ NAV	PA
Waccasassa Bay And River Daybeacon 32	29740	STRUCT DMGD	PA
Suwannee River Alligator Pass Light 2	30085	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 4	30090	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 5	30095	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 7	30100	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 9	30110	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 11	30115	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 13	30120	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 19	30140	STRUCT DEST	PA
Suwannee River Alligator Pass Daybeacon 27	30160	STRUCT DEST/HAZ NAV	PA
Suwannee River Alligator Pass Daybeacon 29	30165	STRUCT DEST	PA
Suwannee River McGriff Pass Daybeacon 1	30170	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 3	30180	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 5	30185	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 7	30200	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 8	30205	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 9	30210	STRUCT DEST	PA
Suwannee River Mcgriff Pass Daybeacon 20	30233	STRUCT DEST	PA
Salt Creek Daybeacon 15	30305	STRUCT DEST	PA
Salt Creek Daybeacon 16	30310	STRUCT DEST	PA
Salt Creek Daybeacon 17	30315	STRUCT DEST	PA
Salt Creek Daybeacon 18	30313	STRUCT DEST	PA PA
·			
Doctors Pass Light DP	17700	LT EXT	PA DA
Water Turkey Bay Daybeacon 13	17877	DAYMK DMGD	PA DA
South Estero Bay Daybeacon 12	19150	STRUCT DEST/HAZ NAV	PA PA
Hudson Creek Light 2	27015	LT EXT	PA
Hudson Creek Daybeacon 5	27030	STRUCT DEST/TRDBN	PA
Hudson Creek Daybeacon 23	27095	STRUCT DEST	PA
Sea Pines Channel Daybeacon 3	27150	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

https://www.navcen.uscg.gov/msi 53/73

Sector St. Petersburg, Territorial Sea - Sector St. Petersburg, Submerged Land Act (SLA)/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2025-02-18 To: 2025-08-17 Location: 26.3744° N / 81.8762° W All mariners are advised that shoaling and shallow water has developed at the entrance of New Pass in Lee County, Florida in vicinity of New Pass Lighted Buoy 1 (LLNR 17964). All mariners are advised to use caution while transiting new pass due to the potentially hazardous conditions. For further information please contact U.S. Coast Guard Sector St. Petersburg at (727) 824-7506.	
Sector St. Petersburg, Territorial Sea- Sector St. Petersburg, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging 24019 Gator Dredging will be conducting dredging near Gasparilla Island State Park for a beach fill project. Equipment Mobilization Start is expected to begin July 23, 2025. Dredging is estimated to begin July 28, 2025, with an estimated completion date of October 29, 2025. Operations will be conducted 24 hours a day, 7 days a week. DREDGE CLEARWATER will be monitoring VHF-FM channel 16. Mariners are urged to use extreme caution in the area, transit at their slowest safe speed to minimize wake, and proceed with caution after passing arrangements have been made. Work vessels, dredge barge, crane barge, tugboats, and buoys will be visibly lighted and marked according to Coast Guard regulations and will be in the area until all work is complete and can change configuration daily. Vessels and/or equipment will be in multiple locations at the same time.	
Sector St. Petersburg, Territorial Sea - Sector St. Petersburg, Submerged Land Act (SLA)/General/Marine Events/Regatta (Race)	Marine Events	General/Marine Events/Regatta (Race) 23667 The U.S. Coast Guard will be enforcing a temporary Safety Zone for the Clearwater AquaX Grand Prix in the vicinity of Sand Key Beach, Clearwater FL. The event will take place on August 23, 2025, and August 24, 2025, from 9 a.m. to 8 p.m. each day. Mariners are advised to exercise caution while transiting the area.	
Sector St. Petersburg, Territorial Sea Sector St. Petersburg, Submerged Land Act (SLA)/ATON/Proposed Notice of Change	Proposed Notice of Change	ATON/Proposed Notice of Change 22111 Location: 28.97534° N / 83.15369° W Aid Name: Seahorse Reef Light LLNR: 1615 Action: DISCONTINUE The following change is being proposed to the aids to navigation system in the Gulf of America off Cedar Key, FL. Seahorse Reef Light (LLNR 1615) will be permanently discontinued. The reef light was discovered as destroyed in April of 2025 by U.S. Coast Guard servicing personnel. Due to the reef light being in an exposed location, CG assets are not capable of rebuilding the structure. All comments should be emailed to: D07-SMB-DPWPublicComments@uscg.mil or andrew.m.engle@uscg.mil with Seahorse Reef Light as the subject line and be received by August 25, 2025. Comments can also be mailed to Commander (DPW), Seventh Coast Guard District 909 SE 1st Avenue (STE 406) Brickell Federal Plaza Bldg Miami FL 33131	Lat: 28° 58' 31" Lon: -083° 09' 13"

Sector St. Petersburg, Territorial Sea

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector St. Peterburg,	Marine	General/Marine Construction (Excluding Bridges)/Dredging 25356 Starting approximately August 12, 2025 and continuing until approximately	
Exclusive Economic Zone	Construction	September 15, 2025, Weeks Marine Inc. "Weeks" will be mobilizing dredge pipelines and equipment for the abovementioned project. During this	
(EEZ) - Sector St.	(Excluding	time Weeks will install submerged lines in the designed pipeline corridors. Anchorage Areas for dredge pipelines and equipment: An anchorage area	
Petersburg, Territorial	Bridges)	located South of Fort De Soto Park will be bound by the following approximate positions: Lat 27°37'3.68"N, Long 82°43'10.85"W Lat 27°38'44.64"N,	
Sea/General/Marine	J .	Long 82°41'2.06"W Lat 27°38'8.85"N, Long 82°40'16.87"W Lat 27°36'18.02"N, Long 82°42'26.34"W An anchorage area located West of Port Manatee	
Construction (Excluding		will be bound by the following approximate positions: Lat 27°38'28.52"N, Long 82°34'33.24"W Lat 27°38'28.58"N, Long 82°33'30.50"W Lat	
Bridges)/Dredging		27°37'29.36"N, Long 82°33'27.55"W Lat 27°37'30.12"N, Long 82°34'32.88"W An anchorage area located in the vicinity of Clearwater Pass will be	
		bound by the following approximate positions: Lat 27°57'58.97"N, Long 82°49'52.95"W Lat 27°57'43.57"N, Long 82°49'26.44"W Lat 27°57'38.96"N,	
		Long 82°49'29.79"W Lat 27°57'54.42"N, Long 82°49'56.43"W The staging areas will be utilized for the duration of the project. Work limits for the	
		pipeline corridors will be the perimeter bound by the following approximate positions: Lat 27°57'33.68"N, Long 82°49'57.38"W Lat 27°52'53.87"N,	
		Long 82°51'8.30"W Lat 27°50'57.77"N, Long 82°50'45.31"W Lat 27°48'31.78"N, Long 82°48'48.92"W Lat 27°47'49.93"N, Long 82°49'29.76"W Lat	
		27°49'42.87"N, Long 82°51'14.95"W Lat 27°52'33.86"N, Long 82°52'15.82"W Lat 27°57'49.78"N, Long 82°51'0.98"W And, Lat 27°46'23.20"N, Long	
		82°48'3.85"W Lat 27°42'57.87"N, Long 82°45'34.78"W Lat 27°43'29.86"N, Long 82°44'40.60"W Lat 27°46'35.72"N, Long 82°47'3.90"W The submerged	
		line(s) will be removed at the completion of dredging operations. Once underway, operations will continue on a twenty-four hours per day, seven	
		days per week basis. Vessels, pipelines, and equipment will have all required Coast Guard lighting for night operations. On-scene vessels will monitor	
		marine VHF channels 13 and 16. Mariners are urged to use extreme caution and transit the area at their slowest safe speed to create minimum wake	
		after passing arrangements have been made.	

Sheephead Cut

Federal Discrepancies

NAME		LLNR	STATUS	AID TYPE
	Sheephead Cut Daybeacon 7	40705	STRUCT DEST/TRUB	FD

Shell Key

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Race Channel Daybeacon 11B	13085	STRUCT DMGD	PA
Little Basin East Daybeacon 1	50540	DAYMK MISSING	PA
Little Basin East Daybeacon 2	50545	STRUCT DEST/HAZ NAV	PA
Little Basin East Daybeacon 4	50555	DAYMK MISSING	PA

Sherman Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sherman Cut Range Rear Light	7240	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION	

https://www.navcen.uscg.gov/msi 54/73

	Change	Sherman Cut RFL (LLNR 7235) will be relocated to approximate position: 30-22-44.220N/081-26-46.188W to align with the newly dredged channel. In addition, Sherman Cut RFL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 44" Lon: -081° 26' 45"	
	Change	Sherman Cut RRL (LLNR 7240) will be relocated to approximate position: 30-22-26.194N/081-27-03.893W to align with the newly dredged channel. In addition Sherman Cut RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 22' 35" Lon: -081° 26' 55"	

Sim-Par Marina Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Marina Bay Channel Daybeacon 4	39715	STRUCT DEST	PA

Singer Island Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Singer Island Channel Daybeacon 6	10212.30000000001	STRUCT DEST/HAZ NAV/TRLB	FD

Sisters Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sisters Creek Light 74	38300	STRUCT DEST/TRLB	FD
Sisters Creek Daybeacon 80	38320	STRUCT DEST/TRUB	FD
Sisters Creek Light 82	38325	STRUCT DEST/TRLB/HAZ NAV	FD
Sisters Creek Light 83	38330	STRUCT DEST/HAZ NAV/TRLB	FD

Skidaway Island

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Skidaway Island Light 25	5710	WATCHING PROPERLY	FD	2025-07-30

Skidaway Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Skidaway Narrows Daybeacon 60	36140	STRUCT DEST/TRUB	FD

Snake Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snake Creek Daybeacon 4	12215	STRUCT DEST/TRUB	FD
Snake Creek Daybeacon 5	12225	STRUCT DEST/TRLB	FD
Snake Creek Daybeacon 7	12240	STRUCT DEST/TRUB	FD

Snapper Creek Marina

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Safety Valve Bank Light 1A	49530	STRUCT DEST/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snapper Creek Marina Daybeacon 2	49515	DAYMK MISSING	PA

Sonde De Vieques

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cayo Lobito Light	31525	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
North St Thomas Lighted Buoy H	31683	LT EXT/OFF STATION	PA

South Altamaha River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Altamaha River Daybeacon 4	36995	STRUCT MISSING/TRUB	FD

South Amelia River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Amelia River Daybeacon 21	38050	STRUCT MISSING/TRUB	FD
South Amelia River Light 24	38060	DAYMK MISSING	FD

South Edisto River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fenwick Cut Daybeacon 162A	35140.5	STRUCT DMGD	FD

South Jupiter Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Jupiter Narrows Daybeacon 25	46085	STRUCT MISSING/TRUB/MISSING	FD

South Newport River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Newport River Light 135	36620	STRUCT MISSING/TRLB	FD

Southwest Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southwest Channel Light 2 (Tampa Bay)	21840	STRUCT MISSING	FD

St Andrew Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Andrew Sound Buoy 29A	37375	MISSING	FD
St Andrew Sound Lighted Buoy 30	37380	BUOY DMGD/HAZ NAV	FD
St Andrew Sound Lighted Buoy 32	37385	OFF STA	FD

St Augustine Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Augustine Inlet Lighted Buoy 5	9495	MISSING	FD
St Augustine Inlet Buoy 10	9510	OFF STA	FD

St Catherines Sound

Federal Discrepancies

·			
NAME	LLNR	STATUS	AID TYPE
St Catherines Sound Lighted Buoy 2	5795	MISSING	FD
St Catherines Sound Buoy 1	5800	MISSING	FD
St Catherines Sound Buoy 3	5805	MISSING	FD

St Helena Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Helena Sound Entrance Buoy 4	3965	MISSING	FD

Private Discrepancies

	NAME	LLNR	STATUS	AID TYPE
Hunting Island Pier Light		4070	STRUCT DEST/LT EXT	PA

St Johns River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pilot Town Cut Range Front Light	7200	LT EXT	FD
St Johns Bluff Light S	7335	STRUCT DEST/TRLB	FD
Quarantine Island Upper Range Front Light	7450	NIGHT LT BURNING DAY	FD
Trapac Turning Basin Buoy C	7463	SINKING	FD
Winter Point Daybeacon	7670	STRUCT DEST/TRUB	FD
Winter Point Light 1	7675	STRUCT DEST/TRLB	FD
Winter Point Light 2	7680	STRUCT DEST/TRLB	FD
Ortega River Shoal Daybeacon	7685	STRUCT DEST/TRUB	FD
Christopher Point Light 5	7725	DAYMK MISSING	FD
Red Bay Point Light 22	7895	STRUCT DEST/TRLB	FD
Tocoi Cut Entrance Light 33	7935	HAZ NAV/STRUCT DMGD/TRLB	FD
Upper Palatka Light 1	8195	LT EXT	FD
Upper Palatka Light 2	8200	LT EXT	FD
Upper Palatka Daybeacon 3	8205	STRUCT MISSING/TRUB	FD
Rivercrest Light 10	8235	LT EXT	FD
Nashua Daybeacon 42A	8390	STRUCT DEST/TRUB	FD
Stephens Point Daybeacon 46	8415	STRUCT DEST/TRUB	FD
Adams Lake Daybeacon 23	8910	STRUCT DEST/HAZ NAV/TRLB	FD
Wekiva Cutoff Daybeacon 95	9155	STRUCT DEST	FD
Mothers Arms Daybeacon 4	9425	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Ortega River Lighted Buoy 2	7696	MISSING	PA
Ortega River Lighted Buoy 13	7697	MISSING	PA
Goodbys Creek Channel Buoy 5	7765.400000000001	OFF STA	PA
Goodbys Creek Channel Buoy 4	7765.3	OFF STA	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Mile Point Temporary Lower Range Front Light	7260.2	ESTABLISHED	FD
Mile Point Temporary Lower Range Rear Light	7265.2	ESTABLISHED	FD
Training Wall Temporary Range Front Light	7295.2	ESTABLISHED	FD
Drummond Creek Temporary Range Front Light	7515.2	ESTABLISHED	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	St. Johns Bluff LB 30 (LLNR 7329) will be permanently relocated to 30-23-32.020N/081-29-29.730W. This change calls to relocate (6) lighted buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All positions listed are approximate. Permanent positions will be advertised when the work is completed.	Lat: 30° 23' 32" Lon: -081° 29' 30"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	Training Wall RFL (LLNR 7295) will be relocated to approximate position: 30-23-48.120N/081-28-41.707W to align with the newly dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 23' 47" Lon: -081° 28' 39"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	Training Wall RRL (LLNR 7300) will be relocated to approximate position: 30-23-57.479N/081-28-54.848W to align with the newly dredged channel. In addition, both Training Wall RFL and Training Wall RRL will be changed to a 24-hour optic. All day marks will be permanently discontinued.	Lat: 30° 23' 58" Lon: -081° 28' 55"

Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/ATON/Advanced Notice of Change	Advanced Notice of Change	ATON/Advanced Notice of Change Location: 28.88295° N / 81.36595° W Aid Name: Wekiva Cutoff Daybeacon 95 LLNR: 9155 Action: DISCONTINUE Wekiva Cutoff DBN 95 (LLNR 9155) will be permanently discontinued. The current location of this structure is located very close to the shoreline, this presents a misleading signal due to more space and plenty of safe water presented on the opposite side of the aid.	Lat: 28° 52' 59" Lon: -081° 21' 57"
Sector Jacksonville, Submerged Land Act (SLA) - St Johns River/General/Bridges/Construction	Bridges	General/Bridges/Construction From: 2025-05-06 To: 2026-06-01 Location: No coordinates available Bridge Name: Shands Bridge Construction has begun on a new high-level fixed bridge and will continue until an estimated completion date of September 1, 2030. The new bridge will consist of a vertical clearance of 65 feet and a 150-Ft. horizontal clearance at the navigation channel. Construction will require the use of material storage barges and barge-mounted cranes; all in-water equipment is required to be lighted at night. Work activities on the new bridge will include pier construction, girder erection, fender system installation, and overhead deck operations that could present a hazard to marine traffic. This phase will require periodic channel restrictions or short-term closures and is tentatively scheduled to take place in 2027. Short-term channel closures will also be required during the demolition of the existing structure tentatively scheduled to take place in 2029. Work barges and associated in-water equipment will be in the vicinity of the bridge. All mariners are advised to transit the area with caution.	-081° 37' 08"

St Joseph Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Joseph Sound Daybeacon 1	61850	STRUCT MISSING	FD
St Joseph Sound Daybeacon 9	61885	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 15	61970	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 21	62035	STRUCT DEST/TRUB	FD
St Joseph Sound Daybeacon 38	62275	STRUCT DEST/HAZ NAV/TRLB	FD
St Joseph Sound Light 39	62280	STRUCT DEST/TRLB/HAZ NAV	FD
St Joseph Sound Daybeacon 40	62285	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Safety Harbor Marina Light 2	24375	DAYMK MISSING	PA
Safety Harbor Marina Daybeacon 3	24380	DAYMK DMGD	PA
Safety Harbor Marina Daybeacon 4	24385	DAYMK MISSING	PA
Caladesi Island Channel Daybeacon 7	61935	DAYMK DMGD	PA
Caladesi Island Channel Daybeacon 7	61935	DAYMK MISSING	PA
Caladesi Island Channel Daybeacon 8	61940	DAYMK DMGD	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Clearwater Harbor - St Joseph	Hazards To	General/Hazards To Navigation/Shoaling Reported 20402 All mariners are advised that extreme shoaling and shallow water has developed	
Sound/General/Hazards To	Navigation	throughout Hurricane Pass Channel in between Caladesi and Honeymoon Islands in Pinellas County, FL, specifically in the vicinity when	
Navigation/Shoaling Reported		transiting between Hurricane Pass Channel Daybeacons 8 through 11. All mariners are advised to use extreme caution while transiting	
		Hurricane Pass Channel to the potentially hazardous conditions. For further information please contact U.S. Coast Guard Sector St.	
		Petersburg at (727) 824-7506.	

St Lucie Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Canal Daybeacon 38	51120	STRUCT DEST	FD
St Lucie Canal Daybeacon 40A	51140	STRUCT DEST/TRUB	FD

St Lucie Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie Inlet Light 3	10000	STRUCT MISSING/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southern Port Salerno Daybeacon 2	10177	STRUCT DEST	PA

St Lucie River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River Daybeacon 5	50675	STRUCT DEST/TRUB	FD
St Lucie River Light 11	50720	STRUCT DEST/HAZ NAV/TRLB	FD
St Lucie River Daybeacon 12A	50725.5	STRUCT DEST	FD

St Lucie River Light 13	50730	STRUCT DMGD/TRLB	FD
St Lucie River Light 17	50750	DBD DMGD	FD
St Lucie River Daybeacon 22A	50780	STRUCT DEST/TRUB	FD
St Lucie River Light 23A	50835	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Rocky Point Access Channel Daybeacon 1	50641	STRUCT DEST	PA
Manatee Pocket Channel North Extension Daybeacon 5	50678.200000000004	STRUCT DEST	PA
St. Lucie River Stuart Ext Daybeacon 1	50838	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 2	50677.1	STRUCT DEST	PA
Manatee Pocket Channel Daybeacon 10	50677.5	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Lucie Inlet - St Lucie River/ATON/Advanced Notice of Change			Lat: 27° 12' 18" Lon: -080° 12' 47"
St Lucie Inlet - St Lucie River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2024-12-31 To: 2025-06-01 Location: 27.20368° N / 80.26011° W Bridge Name: Florida East Coast Railroad Bridge The Temporary Interim Rule (TIR) has been extended through September 30, 2025. The railroad bridge will operate in accordance with 33 CFR 117.317(k).	Lat: 27° 12' 13" Lon: -080° 15' 36"

St Lucie River North Fork

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (North Fork) Daybeacon 7	50885	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Seagate Harbor Daybeacon 1	50861	STRUCT DEST/HAZ NAV	PA
St. Lucie River (North Fork) Daybeacon 11	50905	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Lucie River - St Lucie River North	Advanced Notice	ATON/Advanced Notice of Change 22880 Location: 27.20914° N / 80.26947° W Aid Name: St Lucie River (North Fork) Daybeacon 5	Lat:
Fork/ATON/Advanced Notice of Change	of Change	LLNR: 50855 Action: CHANGE Action Type Change Aid Subtype The U.S. Coast Guard has approved the following change in the St. Lucie River. St. Lucie River N. Fork DBN 5 (LLNR 50855) will be changed to St. Lucie River N. Fork LT 5, using the same LLNR. This aid is currently located near a bend on the St Lucie River (North Fork) and unlighted. Given the turn for the channel it is best to install a light on the aid to provide a better signal during nighttime hours. There are currently no lighted aids in the immediate area. Lighting this aid would keep the maritime community safer and assist with navigation while transiting the river.	27° 12' 33" Lon: -080° 16' 10"
St Lucie River - St Lucie River North Fork/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-22 To: 2025-11-30 Location: 27.27175° N / 80.32449° W Bridge Name: Port St Lucie Boulevard Bridge - Long Creek Seacoast Inc. will be conducting repairs on the bridges across Long Creek. The improvements under this contract consist of structures, riprap, bedding stone, earthwork (excavation), clearing and grubbing, MOT, environmental protections, and monitor existing structures along State Road 716 at Long Creek. In-water equipment will be present, the waterway will not be fully obstructed at any time.	Lat: 27° 16' 18" Lon: -080° 19' 28"
St Lucie River - St Lucie River North Fork/General/Bridges/Rehabilitation	Bridges	General/Bridges/Rehabilitation From: 2024-11-22 To: 2025-11-30 Location: 27.27173° N / 80.32221° W Bridge Name: Port St Lucie Boulevard Bridge - North Fork St Lucie River Seacoast Inc. will be conducting repairs on the bridges across North Fork St Lucie River. The improvements under this contract consist of structures, riprap, bedding stone, earthwork (excavation), clearing and grubbing, MOT, environmental protections, and monitor existing structures along State Road 716 at North Fork St Lucie River. In-water equipment will be present, the waterway will not be fully obstructed at any time.	Lat: 27° 16' 18" Lon: -080° 19' 20"

St Lucie River South Fork

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Lucie River (South Fork) Daybeacon 24	51000	STRUCT DEST/TRUB	FD
St Lucie River (South Fork) Daybeacon 25A	51010	STRUCT DEST	FD

St Marys Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Marys Entrance Range Rear Light	6530	LT EXT	FD
St Marys South Jetty Buoy B	6615	MISSING	FD

St Marys North Jetty Buoy C	6620	MISSING	FD
St Marys South Jetty Buoy D	6625	OFF STATION	FD
St Marys Daybeacon N	6680	STRUCT DEST/HAZ NAV	FD

St Marys River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Marys River Daybeacon 8	6810	STRUCT DEST	FD

St Petersburg Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Snell Isle Daybeacon 5	25020.3	STRUCT DEST	PA
Coffee Pot Bayou Daybeacon 1	25021	STRUCT DEST	PA
Snell Isle Daybeacon 4	25020.2	STRUCT DEST/HAZ NAV	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Point Pinellas Channel - St Petersburg	Marine Events	General/Marine Events/Regatta (Race) 25355 The U.S. Coast Guard will be enforcing a Special Local Regulation for the duration of the St	
Channel/General/Marine		Petersburg Powerboat Grand Prix of Tampa Bay in the vicinity of the St. Pete pier, St. Petersburg, FL from 8:00 a.m. September 5, 2025, until	
Events/Regatta (Race)		6:30 p.m. September 7, 2025. No vessels may enter the area within the special local regulation without prior approval of the Patrol	
		Commander. The Patrol Commander may be contacted on VHF-FM channel 16. For further information please contact U.S. Coast Guard	
		Sector St. Petersburg at (727) 824-7506.	

St Petersburg Yacht Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Petersburg Yacht Basin Light 1	25015	STRUCT DMGD/TRLB	FD
St Petersburg Yacht Basin Light 2	25020	TRLB/STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. Petersburg Mooring Field Buoy B	25009.10000000002	MISSING	PA
St. Petersburg Mooring Field Buoy C	25009.2	MISSING	PA

St Simons Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St Simons Sound Entrance Lighted Buoy 6	6060	SINKING/TRLB	FD
Plantation Creek Range Rear Light	6135	STRUCT DEST	FD
Cedar Hammock Outbound Range Front Light	6205	STRUCT DMGD/TRLT	FD
Cedar Hammock Outbound Range Front Light	6205	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Advanced Notice of Change	of Change	Cedar Hammock RFL (LLNR 6195) will be permanently relocated to approximate position 32-06-02.513N/081-27-57.935W. The RFL will be changed to a day/night optic and continuing to display a Q G flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RFL Passing LT (LLNR 6195.1) will be permanently established to display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM.	Lat: 31° 06' 01" Lon: -081° 28' 05"
Sector Charleston, Submerged Land Act (SLA) - St Simons Sound/ATON/Advanced Notice of Change	of Change	Cedar Hammock RRL (LLNR 6200) will be permanently relocated to approximate position 31-05-58.956N/081-28-13.677W. The RRL will be changed to a day/night optic and continuing to display an Iso G 6s flash characteristic for a 24hr continuous cycle. The daymarks will be permanently discontinued. Cedar Hammock RRL Passing Light (LLNR 6200.1) will be permanently established by mounting (2) optics located on the NW and SE corners of the platform for Cedar Hammock RRL (LLNR 6200). The (2) optics will be synchronized and display a FI W 2.5s flash characteristic during nighttime hours only, with a nominal range of 4NM. Due to the current location of Cedar Hammock RRL (LLNR 6200) being inaccessible for a CG asset to effectively repair the structure, it was determined by relocating both range structures it will not only offer an excellent range quality index for all mariners but be accessible to all CG assets to provide consistent maintenance to both structures.	Lat: 31° 05' 50" Lon: -081° 28' 52"

Steinhatchee River

Federal Discrepancies

NAME LLNR STATUS AID	/PE
----------------------	-----

https://www.navcen.uscg.gov/msi 60/73

Steinhatchee River Light 9	30480	DBD DEST/STRUCT DEST/TRLB/HAZ NAV	FD
Steinhatchee River Daybeacon 14	30490.5	HAZ NAV/STRUCT DEST/TRLB	FD
Steinhatchee River Daybeacon 34	30570	STRUCT MISSING/HAZ NAV/TRLB	FD
Steinhatchee River Daybeacon 48	30580.9	STRUCT DEST/TRUB	FD

Stono River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stono River Daybeacon 20	34640	STRUCT DEST/HAZ NAV/TRLB	FD

Stranahan River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stranahan River Daybeacon 25	47410	STRUCT DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Everglades - Stranahan River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-05-22 To: 2025-11-29 Location: 26.10057° N / 80.11856° W Bridge Name: Southeast 17th Street Bridge - AlCW The Coast Guard has issued a temporary deviation to test a proposed change to the drawbridge operating schedule. This temporary deviation is effective from 6 a.m. on June 2, 2025, through 11:59 p.m. on November 28, 2025. Under the temporary deviation, the bridge shall open on the hour and half-hour; except that from 6:50 a.m. to 9:10 a.m. and from 3:50 p.m. to 6:10 p.m., Monday through Friday, except Federal holidays, the drawbridge shall open once an hour at the top of the hour. You may submit comments identified by docket number USCG-2025-0464 using the Federal Decision Making Portal at https://www.regulations.gov. Comments and related material must reach the Coast Guard on or before August 25, 2025.	Lat: 26° 06' 02" Lon: -080° 07' 07"
Port Everglades - Stranahan River/General/Bridges/Temp Deviation	Bridges	General/Bridges/Temp Deviation From: 2025-08-05 To: 2025-08-13 Location: 26.08522° N / 80.18404° W Bridge Name: 84 State Route Bridge - South Fork New River From 1 p.m. on August 5, 2025, through 10 a.m. on August 12, 2025, the SR 84 Bridge need not open to marine traffic between 10 a.m. and 7 p.m., daily. From 7 p.m. to 10 a.m., daily, an opening will be provided with a 24-hour advance notice.	
Port Everglades - Stranahan River/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards 20853 Location: 26.11168° N / 80.11807° W Large concrete block just below the waterline at low tide.	Lat: 26° 06' 42" Lon: -080° 07' 05"

Sunset Harbour Channel

Federal Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Flagler Monument Daybeacon 2	48145	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sunset Harbour Channel Light 8	48110	LT EXT	PA

Suwannee Sound South Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Suwannee Sound South Entrance Daybeacon 2	30015	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 7	30030	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 11	30040	STRUCT MISSING	FD
Suwannee Sound South Entrance Daybeacon 15	30050	STRUCT MISSING	FD

Tamp Bay Cut C Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut C Channel Outbound Range Front Light	22580	TRLT	FD
Tampa Bay Cut C Channel Outbound Range Rear Light	22585	TRLT	FD
Tampa Bay Cut C Channel Lighted Buoy 2C	22595	SINKING/TRLB	FD

Tampa Bay

Private Discrepancies

https://www.navcen.uscg.gov/msi 61/73

NAME	LLNR	STATUS	AID TYPE
Cockroach Bay Channel Daybeacon 2	22635	HAZ NAV/DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 8	22665	DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 11	22680	DAYMK MISSING	PA
Cockroach Bay Channel Daybeacon 15	22696	STRUCT DEST	PA
Little Harbor Channel Daybeacon 7	24515	STRUCT DEST	PA
Little Harbor Marina Daybeacon 6	24585	HAZ NAV/DAYMK MISSING	PA
Simmons Park Channel Daybeacon 3	24606.2	HAZ NAV/DAYMK MISSING	PA
Simmons Park Channel Daybeacon 4	24606.3	STRUCT DEST/HAZ NAV	PA
Apollo Beach Daybeacon 4	24625	DAYMK DMGD	PA
Apollo Beach Daybeacon 9	24643	STRUCT DEST	PA
Harbor Channel Daybeacon 3	24663.2	STRUCT DEST	PA
Little Harbor Channel Daybeacon 4	24505	STRUCT DEST	PA
Little Harbor Marina Daybeacon 3	24570	STRUCT DEST	PA
Simmons Park Channel Daybeacon 13	24607.2	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Paradise Bay Estates Channel -	Marine	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes 22438 Archer Western/Traylor Bros. JV	
Tampa Bay/General/Marine	Construction	will be conducting demolition of the Existing Northbound HFB Bridge (The 60's Bridge - Southernmost Bridge of the 3 Howard Frankland	
Construction (Excluding	(Excluding	Bridges). The project is estimated to begin on July 11, 2025, with an estimated completion date of December 31, 2025. Operations will be	
Bridges)/Facilities, Barriers,	Bridges)	conducted 7 days a week 5 a.m. to 5 p.m. There will be various Crane/Material Barges, Manlift Barges, Dive Support Barges, Tugboats, and Crew	
Manmade Reefs, Riprap,		boats inside a 1,000-foot work zone south of the bridge and 500-foot north of the bridge. Prior to the start of Demolition, 7 to 8 Mooring	
Jetties/Dikes		Buoy's will be anchored on the South Side of the Bridge about 1,000' off the South Bridge. 2 to 3 Mooring Buoy's will be kept on the North Side	
		of the Bridge. During the removal of the Main Spans, demolition equipment will need to occupy the navigational channel between Pier 161 and	
		162 of Bridge No. 150107. Also, work will continue on the Fender System as demolition begins. Main Channel to be impeded during Fender	
		Work. Updated Notices to Mariners to be sent out. We will have tugboats actively working every shift while the channel is obstructed and barges	
		can be moved out of the channel within 30 minutes to an hour. Tugboats will be bringing Material Barges to and from the Mooring Fleet to the	
		Tyson Yard, passing through the Gandy Bridge. VHF-FM channels monitored: 13, 22A, and 16.	

Tampa Bay Cut D Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut D Channel Outbound Range Rear Light	22715	STRUCT DEST	FD
Tampa Bay Cut D Channel Outbound Range Rear Passing Light	22715.100000000002	STRUCT DEST	FD

Tampa Bay Cut E Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut E Channel Inbound Range Rear Light	22765	STRUCT DEST/HAZ NAV/TRLB	FD
Tampa Bay Cut E Channel Inbound Range Rear Light Passing Light	22765.5	STRUCT DEST	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
North Yacht Basin Daybeacon 2	22786	STRUCT DEST	PA

Tampa Bay Cut F Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tampa Bay Cut F Inbound Range Rear Passing Light	22815.2	LT EXT	FD

Tavernier Creek

Private Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Tavernier Creek Daybeacon 18	12150	REBUILT/RECOVERED	PA	2025-07-31

Taylor Creek Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Taylor Creek Channel Daybeacon 3	45100	STRUCT DEST	FD

Terminal Channel

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Jacksonville Shipyards Pier 6 Light	7655	LT EXT	PA

Terra Ceia Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Terra Ceia Bay Daybeacon 3	22150	STRUCT DEST	FD

The Bight Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Bight Channel Light 44	4920	STRUCT MISSING/TRLB	FD

Titusville Yacht Basin

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Titusville Yacht Basin Daybeacon 1	41210	STRUCT DEST/TRUB	FD
Titusville Yacht Basin Daybeacon 3	41220	STRUCT DEST/TRUB	FD

Tolomato River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tolomato River Light 9	38645	STRUCT DEST/HAZ NAV/TRLB	FD
Tolomato River Light 44	38790	STRUCT MISSING/TRLB	FD
Tolomato River Light 45	38800	STRUCT DEST/TRLB	FD
Tolomato River Light 57A	38885	STRUCT DEST	FD
Tolomato River Lighted Buoy 59	38905.5	MISSING	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Palm Valley Daybeacon 2	38620	WATCHING PROPERLY	FD	2025-07-23

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Fdot Villano Bridge South Breasting Light	38834	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Matanzas River - Tolomato	ATON Changes	ATON/ATON Changes From: 2025-08-06 Location: 29.91733° N / 81.30618° W Aid Name: Camachee Cove Daybeacon 5 LLNR: 38875	Lat:
River/ATON/ATON Changes		Action: RELOCATE Position: 29-55-02.386N / 081-18-22.261W	29° 55' 02"
			Lon:
			-081° 18' 22"
Matanzas River - Tolomato	ATON Changes	ATON/ATON Changes From: 2025-08-06 Location: 29.91775° N / 81.30618° W Aid Name: Camachee Cove Daybeacon 6 LLNR: 38880	Lat:
River/ATON/ATON Changes		Action: RELOCATE Position: 29-55-03.886N / 081-18-22.261W	29° 55' 04"
			Lon:
			-081° 18' 22"

Treasure Island

Private Discrepancies

•			
NAME	LLNR	STATUS	AID TYPE
Jungle Beach Daybeacon 11	61215	STRUCT DEST	PA
Jungle Beach Daybeacon 2	61170	STRUCT DEST/HAZ NAV/DAYMK MISSING	PA
Jungle Beach Daybeacon 4	61180	DAYMK DMGD	PA

Trout River

Federal Discrepancies

https://www.navcen.uscg.gov/msi 63/73

NAME	LLNR	STATUS	AID TYPE
Trout River Daybeacon 2	7550	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Maxwell Boat Ramp Channel Daybeacon 5	7557.90000000001	STRUCT DEST	PA
Ribault River Channel Lighted Buoy 1	7559	MISSING/HAZ NAV	PA
Ribault River Channel Lighted Buoy 3	7559.150000000001	ADRIFT	PA

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Trout River Cut Lighted Buoy 63	7540	RELOCATED FOR DREDGING	FD

Turtle River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turtle River Lighted Buoy 2A	6322	LT EXT	FD
Turtle River Light 4	6325	STRUCT DEST/TRLB	FD
Turtle River Daybeacon 10	6385	STRUCT DEST/TRUB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hermitage Island Plant Outfall Obstruction Light	6395	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Simons Sound - Turtle	Marine Construction	General/Marine Construction (Excluding Bridges)/Dredging 25171 Marinex Construction, Inc. will mobilize August 14, 2025, into the	
River/General/Marine Construction	(Excluding Bridges)	staging area upriver of the East River Turning Basin as shown in the attached. Crews will install submerged pipeline from the Colonel's	
(Excluding Bridges)/Dredging		Island Disposal Area across the Turtle River with a head section near the Turtle River Lower Range Front Light. The Dredge WADMALAW	
		will operate in this area through approximately October 31, 2025. Operations will be conducted 24 hours a day / seven days a week and	
		monitor VHF-FM channels 13 and 16.	

Umbrella Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE	
Umbrella Creek Daybeacon A9	37440	DAYMK MISSING	FD	

<u>Unknown</u>

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Baynard Cove Creek Daybeacon 2	4355	STRUCT DEST	PA
Haig Point Light	4370	LT IMCH	PA
Sebastian Inlet Channel Daybeacon 5	9750	STRUCT DEST	PA
Sebastian Inlet Channel Daybeacon 10	9775	HAZ NAV/DAYMK MISSING	PA
Sebastian Inlet Channel Daybeacon 17	9810	DAYMK MISSING	PA
sebastian Inlet Channel Daybeacon 25	9810.9	DBD DEST	PA
Sebastian Inlet Channel Daybeacon 28	9812.2	STRUCT DEST/HAZ NAV	PA
isher Island Marina Channel North Obstruction Daybeacon	10605	DAYMK MISSING	PA
isher Island Breakwater East Obstruction Daybeacon	10650	DAYMK MISSING	PA
Asrc Boundary Shoal Daybeacon	10735	DAYMK MISSING	PA
Dhio Key Channel Daybeacon 4	12595	STRUCT DEST/HAZ NAV	PA
Stump Pass Marina Daybeacon 4	21400	STRUCT DEST	PA
lig Sarasota Pass Daybeacon 8	21500.8	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 11	21510	STRUCT DEST	PA
tig Sarasota Pass Daybeacon 11A	21510.5	STRUCT DEST	PA
lig Sarasota Pass Daybeacon 13	21515	STRUCT DEST	PA
Big Sarasota Pass Daybeacon 15	21525	STRUCT DEST	PA
lymouth Harbor East Obstruction Daybeacon	21547	STRUCT DEST/HAZ NAV	PA
lymouth Harbor West Obstruction Daybeacon	21547.100000000002	STRUCT DEST/HAZ NAV	PA
outh Lido North Obstruction Daybeacon	21555.100000000002	STRUCT DEST/HAZ NAV	PA
sig Sarasota Pass Daybeacon 16	21570	STRUCT DEST	PA
North Siesta Key Daybeacon 1	21570.100000000002	STRUCT DEST	PA

https://www.navcen.uscg.gov/msi

70/20, 12.20 I W	Martine Galety Information	1 Toddets Navigation Center	
North Siesta Key Daybeacon 9	21570.5	STRUCT DEST	PA
North Siesta Key Daybeacon 11	21570.600000000002	STRUCT MISSING	PA
Big Sarasota Pass Daybeacon 18	21577	STRUCT DEST/HAZ NAV	PA
Big Sarasota Pass Daybeacon 19	21580	STRUCT DEST	PA
Country Club Shores Daybeacon 2	21660	DAYMK MISSING	PA
MacDill Marina Channel Daybeacon 2	22975	STRUCT DEST	PA
Point Pinellas Daybeacon 3	24745	STRUCT DEST/HAZ NAV	PA
Isleta Marina Pier A Light	31240	LT EXT	PA
Isleta Marina Pier B Light	31245	LT EXT	PA
Isleta Marina Pier C Light	31250	LT EXT	PA
Puerto Yabucoa Channel Range Front Light	31745	LT EXT/STRUCT DMGD	PA
Puerto Yabucoa Channel Range Rear Light	31750	LT EXT/STRUCT DMGD	PA
Las Mareas Range Front Light	31810	LT EXT	PA
Las Mareas Range Rear Light	31815	LT EXT	PA
Las Mareas Lighted Buoy 1	31820	OFF STA/LT EXT	PA PA
Las Mareas Lighted Buoy 2	31825	MISSING	
Las Mareas Light 4	31835	LT EXT	PA -
Las Mareas Articulated Light 5	31840	LT EXT	PA
Las Mareas Light 6	31845	LT EXT	PA
Las Mareas Pier Light (3)	31850	LT EXT	PA
Water Island Channel Lighted Buoy 3	32626.2	LT EXT	PA
Marsh Harbor Marina Daybeacon 3	35420	DAYMK MISSING	PA
Marsh Harbor Marina Daybeacon 5	35430	DAYMK MISSING	PA
Boat Works Channel Daybeacon 2	40135	DAYMK MISSING	PA
Boat Works Channel Daybeacon 3	40140	DAYMK MISSING	PA
Boat Works Channel Daybeacon 4	40145	DAYMK MISSING	PA
Boat Works Channel Daybeacon 5	40150	DAYMK MISSING	PA
Boat Works Channel Daybeacon 7	40160	DAYMK DMGD	PA
Boat Works Channel Daybeacon 9	40170	STRUCT DEST	PA
Matthews Marina Daybeacon 2	40255	STRUCT DEST	PA
Matthews Marina Daybeacon 3	40260	DAYMK IMCH	PA
Matthews Marina Daybeacon 5	40270	DAYMK MISSING	PA
Seven Seas Marina Daybeacon 11	40330	DAYMK MISSING	PA
Harbor Towne Marina Daybeacon 2	41245	STRUCT DEST	PA
Harbor Towne Marina Daybeacon 4	41250	STRUCT DEST	PA
Harbor Towne Marina Daybeacon 9	41265	DAYMK MISSING	PA
Riverdeck Channel Daybeacon 1	41295	STRUCT DEST	PA
	41300		PA
Riverdeck Channel Daybeacon 2		STRUCT DEST	PA PA
Riverdeck Channel Daybeacon 3	41305	STRUCT DEST	
Riverdeck Channel Daybeacon 4	41310	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 1	41345	DAYMK MISSING	PA
Kennedy Yacht Club Channel Daybeacon 2	41350	DAYMK MISSING	PA
Kennedy Yacht Club Channel Daybeacon 3	41355	DAYMK IMCH	PA
Kennedy Yacht Club Channel Daybeacon 4	41360	DAYMK IMCH	PA
Kennedy Yacht Club Channel Daybeacon 5	41365	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 7	41375	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 8	41380	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 9	41385	STRUCT DEST	PA
Kennedy Yacht Club Channel Daybeacon 10	41390	STRUCT DEST	PA
Orlando Utilities Comission Channel Buoy 2	41445	MISSING	PA
Orlando Utilities Comission Channel Buoy 4	41450	MISSING	PA
Orlando Utilities Comission Channel Buoy 5	41455	MISSING	PA
Orlando Utilities Comission Channel Buoy 6	41460	MISSING	PA
Orlando Utilities Comission Channel Buoy 7	41465	MISSING	PA
Orlando Utilities Comission Channel Buoy 8	41470	MISSING	PA
Indian Cove Marina Daybeacon 3	42140	DAYMK DMGD	PA
Indian Cove Marina Daybeacon 5	42150	DAYMK DMGD	PA
Indian Cove Marina Daybeacon 7	42160	DAYMK DMGD	PA PA
Diamond 99 Marina Daybeacon 1	42290 4230E	DAYMK MISSING	PA DA
Diamond 99 Marina Daybeacon 2	42295	DAYMK IMCH	PA
Diamond 99 Marina Daybeacon 3	42300	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 4	42305	DAYMK MISSING	PA
Diamond 99 Marina Daybeacon 5	42310	STRUCT DEST	PA
Diamond 99 Marina Daybeacon 6	42315	DAYMK MISSING	PA

https://www.navcen.uscg.gov/msi 65/73

Dissert of Montes Septiment 7 4070 6040 6050 705	10/20, 12.20 I WI	mantime carety information	11 Toddets Navigation Ochter	
inite Manto Qupocani 7 4102 COMMO MISSING M inite Manto Qupocani 2 4102 COMMO MISSING M inite Manto Qupocani 4 4102 COMMO MISSING M Commo Ral Aplancia Operator 14 4105 COMMO MISSING M Commo Ral Antino Qupocanor 1 Academond 4105 STACTURE TOTA M Commo Ral Antino Qupocanor 1 Academond 4103 STACTURE TOTA M Commo Ral Antino Qupocanor 1 Academond 4103 STACTURE TOTA M Commo Ral Antino Qupocanor 2 Academond 4103 STACTURE TOTA M Commo Ral Antino Qupocanor 2 Academond 4103 STACTURE TOTA M Commo Ral Antino Qupocanor 3 4035 STACTURE TOTA M Recommo Ramilla Frenz Depasora 3 4035 STACTURE TOTA M Recommo Ramilla Frenz Depasora 3 4031 STACTURE TOTA M Recommo Ramilla Frenz Depasora 4 4030 STACTURE TOTA M Recommo Ramilla Frenz Depasora 3 4031 STACTURE TOTA M Recommo Ramilla Frenz Depasora 4 4030<	Diamond 99 Marina Daybeacon 7	42320	DAYMK MISSING	PA
Intel Martin Deposen 2	Diamond 99 Marina Light 8	42325	STRUCT DEST	PA
Intel Marie Specians Asiac	Inlet Marina Daybeacon 1	43615	DAYMK MISSING	PA
Samble Displaces In Source (Samble Displaces) 4,865 Control and Markers (Deplaces) 4,865 Control Control Control 4,865 Control Control Control 4,865 Control Control Control 4,865 Control Control Control 4,865 Control Contro	Inlet Marina Daybeacon 2	43620	DAYMK MISSING	PA
Clamen Displacement Obsorberiered 4,686.5.3. STACKET DISPLAYER AWN A Chamen Gil Abhrest Displacement Obsorberiered 4,686.5. STACKET DISPLAYER AWN A Chamen Gil Abhrest Displacement Obsorberiered 4,686.6. STACKET DISPLAYER AWN A Village Markert Displacement A 4,888.6. STACKET DISPLAYER AWN A Village Markert Displacement A 4,888.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,898.6. STACKET DISPLAYER AWN A Revision Markers Prevent Displacement A 4,998.6. STACKET DISPLAYER AWN	Inlet Marina Daybeacon 4	43630	DAYMK MISSING	PA
Channel SM Markur Supplacency F (Alvancharden) 4,885.530000000000 NELL TORT A Longer Beat Markur Supplacency F (Alvancharden) 4,985.5 STEUT DETT A Longer Beat Markur Supplacency F (Alvancharden) 4,985.6 STEUT DETT A Komes Markur R F responsible Agency S (Alvancharden) 4,986.6 STEUT DETT A Rowers Markur R F responsible Agency S (Alvancharden) 4,985.6 DANKE DETT DETT A Rowers Markur R F responsible Agency S (Alvancharden) 4,985.6 DANKE DETT DETT DETT DETT DETT DETT DETT DE	Sembler Daybeacon 5	43655	DAYMK MISSING	PA
Chamaté di Marris Deplescon 2 (Wandercell) 4,886.00,000,000 5 INCC DEST M Chamaté di Marris Deplescon 5 (Wandercell) 4,886.00 SECT DEST M Linggerhard Marie Deplescon 1 4815 CARTIS DEST M Foresta Marian El Friesco Deplescon 1 4835 STINCT DEST M Foresta Marian El Friesco Deplescon 2 4830 STINCT DEST M Foresta Marian El Friesco Deplescon 3 4830 CONTRA MARIAN EL FRIED (Septions) M Foresta Marian El Friesco Deplescon 3 4830 DATIS DEST DEST M Foresta Marian El Friesco Deplescon 6 4830 DATIS DEST DEST DEST DEST M Foresta Marian El Friesco Deplescon 7 4830 DATIS DEST DEST DEST DEST DEST DEST DEST DES		43685.1	STRUCT DEST/HAZ NAV	PA
Channel Gibbanescon (Abardanosel) 44806 S STRUCT DESI R Village Marian Ordenanos 2 44905 S STRUCT DESI R Village Marian Ordenanos 2 44905 S STRUCT DESI R Roserato Marian SE, Proces Depleacen 5 44905 S STRUCT DESI R Roserato Marian SE, Proces Depleacen 6 44905 S STRUCT DESI R Roserato Marian SE, Proces Depleacen 5 44905 S STRUCT DESI R Roserato Marian SE, Proces Depleacen 5 44905 S DANIAR MISSING R Roserato Marian SE, Proced Depleacen 6 44905 S STRUCT DESI PROVIDED R Roserato Marian SE, Proced Depleacen 6 44905 S STRUCT DEST PROVIDED R Roserato Marian SE, Proced Depleacen 6 44906 S STRUCT DEST PROVIDED R Roserato Marian SE, Proced Depleacen 1 44906 S STRUCT DEST PROVIDED R Roserato Depleacen 16 44906 S STRUCT DEST PROVIDED R Roserato Depleacen 2 44906 S STRUCT DEST PROVIDED R Roserato Depleacen 2 45906 S STRUCT DEST PROVIDED R <td>Channel 68 Marina Daybeacon 2 (Abandoned)</td> <td>43685.200000000004</td> <td>STRUCT DEST</td> <td>PA</td>	Channel 68 Marina Daybeacon 2 (Abandoned)	43685.200000000004	STRUCT DEST	PA
Locyalmenta Meria Derivation 10 4015 DAMES MISSING PA Willings Marins Springer 4886 SINLE DISKI 12 PA Breast Medical FT, Percel Debesson 3 4693 STRUCT DIST PA Breast Markanis FT, Percel Debesson 3 4695 SINLE DIST PA Breast Markanis FT, Percel Debesson 5 4695 SINLE DIST PA Miserate Markanis FT, Percel Debesson 7 4856 DAME MISSING PA Markanis Markanis FT, Percel Debesson 6 4607 DAME MISSING PA Markanis Markanis FT, Percel Debesson 3 4618 SINLE DISTANA PA Markanis Markanis FT, Percel Debesson 4 4695 SINLE DISTANA PA Markanis Markanis FT, Percel Debesson 3 4600 SINLE DISTANA PA Markanis Markanis FT, Percel Debesson 3 4600 SINLE DISTANA PA Markanis Charrel Debesson 3 4600 SINLE DISTANA PA Males Canta Debesson 3 4600 MARKANICA PA Miles Canta Debesson 3 4600 MARKANICA PA Miles Canta Debesson 4				
Wiley Debtace Large Common (1) 44816 STRUCT DEST 84 Remarked Mark In Experical Debtacents 1 4505 STRUCT DEST 94 Remarked Mark In Experical Debtacents 3 4505 STRUCT DEST 94 Remarked Mark In Experical Debtacents 3 4505 COMMER MEDITARY 94 Remarked Marken Experical Debtacents 3 4505 COMMA MEDITARY 94 Remarked Marken Experical Debtacents 4 4505 COMMA MEDITARY 94 Please Cover Debtacents 3 4505 STRUCT DEST/DEAL 94 Please Cover Debtacents 4 4505 STRUCT DEST/DEAL 94 Please Research Channel Debtacents 4 4505 STRUCT DESS/DEAL 94 Research Channel Debtacents 6 4505 STRUCT DESS/DEAL 94 Miles Serial Debtacents 6 4505 STRUCT DESS/DEAL 94 Miles Serial Debtacent 7 4600 STRUCT DESS/DEAL 94 Miles Serial Debtacent 8 4505 DAMMA INCHIA 94 Miles Serial Debtacent 9 4505 DAMMA INCHIA 94 Miles Serial Debtacent 9				
Richard Standard RF, Patrical Displaces on 3 44818 STRICT DISTL A Richards Markell, Patrical Displaces on 3 4494 STRICT DISTL R Richards Markell, Patrical Displaces on 4 4595 DMM MICH R Richards Markell, Patrical Displaces on 7 4496 DMM MISSING R Research Markell, Patrical Displaces on 8 45973 DMM MISSING R Place Clove Displaces on 3 45973 STRUCT DISTURA PARIA R Place Clove Displaces on 4 45973 STRUCT DISTURA PARIA R Place Clove Displaces on 4 45983 STRUCT MISSING R Place Clove Displaces on 4 45983 STRUCT MISSING R Research Charmel Displaces on 4 45983 CAMM MISCOL R Mills Court Displaces on 2 45983 CAMM MISCOL R Mills Court Displaces on 3 45983 CAMM MISCOL R Mills Court Displaces on 4 44980 DMM MISCOL R Mills Court Displaces on 3 45916 CAMM MISCOL R Mills Court Displaces on 3 4	3			
Remarks Harmal F. Perent Depleasent 3 4545 STRUCT DIST PA Remarks Harmal F. Devel Depleasent 4 4505 OWNA MUDIC 1 PA Remarks Harmal F. Devel Depleasent 5 4555 STRUCT DEST PA Remarks Harmal F. Perent Depleasent 7 4555 STRUCT DEST NAT PA Reacted Marrand F. Perent Depleasent 8 4510 STRUCT DEST NAT PA Flace Crew Depleasent 3 4510 STRUCT DEST NAT PA Flace Crew Depleasent 4 4556 STRUCT MISSING PA Flace Crew Depleasent 3 4506 STRUCT MISSING PA Flace Depleasent 4 4556 STRUCT MISSING PA Flace Depleasent 6 4556 STRUCT MISSING PA Flace Depleasent 6 4556 STRUCT MISSING PA Flace Depleasent 7 4550 STRUCT DESIGN PA Miller Grand Depleasent 6 4550 STRUCT DESIGN PA Miller Grand Depleasent 7 4620 STRUCT DEST PA Miller Grand Depleasent 6 4550 STRUCT DEST PA				
Sincetted Martina (Fig. Ferren Dephasens 6 4500 DANA DUCK 1 94 Ricential Martina (Fig. Ferran Dephasens 7 4505 STRUCT EST ST 94 Ricential Martina (Fig. Ferral Dephasens 7 4505 DANA MUSSING 94 Ricential Martina (Fig. Ferral Dephasens 8 4505 STRUCT EST/ARZ NW 94 Faller Core Dephasens 1 4515 STRUCT EST/ARZ NW 94 Faller Core Dephasens 1 4515 STRUCT EST/ARZ NW 94 Faller Core Dephasens 1 4515 STRUCT EST/ARZ NW 94 Faller Core Dephasens 1 4500 STRUCT EST/ARZ NW 94 Faller Core Dephasens 2 4590 STRUCT MISSING 94 Miles Grant Dephasens 2 4590 DANK RICH 94 Miles Grant Dephasens 2 4590 DANK RICH 94 Miles Grant Dephasens 2 4590 STRUCT EST/ARZ NAW 94 Miles Grant Dephasens 2 4500 STRUCT EST/ARZ NAW 94 Miles Grant Dephasens 2 4500 STRUCT EST/ARZ NAW 94 Miles Grant Dephasens 2 4500 <				
Remails Marmall's, Ferrica Oppiesson 5 4595 STRUCT DEST PA Risenside Marmall's, Ferrica Oppiesson 7 4505 DAYMAK MSSING PA Risenside Marmall's, Ferrica Oppiesson 3 4513 STRUCT DEST/HAZ NAW PA Ferrica Cordo Dipolascon 14 45185 STRUCT DEST/HAZ NAW PA Jennes Roch Charmel Displaces 4 4595 STRUCT MISSING PA Jennes Roch Charmel Displaces 6 4505 STRUCT MISSING PA Jennes Roch Charmel Displaces 6 4505 STRUCT MISSING PA Miss Grand Displaces 7 4509 OPAN RINGH PA Miss Grand Displaces 7 4509 OPAN RINGH PA Miss Grand Displaces 7 4509 OPAN RINGH PA Miss Grand Displaces 7 4500 OPAN RINGH PA Miss Grand Displaces 7 4500 OPAN RINGH PA Miss Grand Displaces 7 4500 STRUCT DEST PA Miss Grand Displaces 7 4500 STRUCT DEST PA Miss Grand Displaces 7 4500 STRUCT DEST PA <td></td> <td></td> <td></td> <td></td>				
Serestiel Maries Figure Depleacen 7 4505 Demokins Casimina (Assimation) PA Filter Core Diphetero 3 4515 STRUCT DEST/HZ NAV PA Filter Core Diphetero 1 4515 STRUCT DEST/HZ NAV PA Filter Core Diphetero 1 4515 STRUCT MISSING PA Jenne Beach Charmel Diphetero 5 4500 STRUCT MISSING PA Jenne Beach Charmel Diphetero 6 4500 STRUCT MISSING PA Jenne Beach Charmel Diphetero 7 4590 Damins Misch PA Milles Control Diphetero 7 4590 Demokin Mich PA Milles Control Diphetero 7 4590 Demokin Mich PA Milles Control Diphetero 7 4590 Demokin Mich PA Milles Control Diphetero 7 4590 STRUCT DEST/HZ NAV PA PA PA PA PA Milles Control Diphetero 7 4680 STRUCT DEST/HZ NAV PA OU SIJI Ministra Diphetero 1 4680 STRUCT DEST/HZ NAV PA OU Siji Ministra Diphetero 1 4790 STRUCT DEST/HZ NAV	·			
Sience See Marmiell's Pencor Dipolessoon 3 45070 DAYM MESING PA Filter Crow Dipolessoon 3 41955 STRUCT DIST A Falter Crow Dipolessoon 4 4595 STRUCT DIST A Incenne Risch Charmed Disphaces 4 4595 STRUCT MISSING A Jessen Risch Charmed Disphaces 5 4590 STRUCT MISSING A Jessen Resch Charmed Disphaces 6 4590 DAYMK INCH A Miles Grant Disphaces 7 4590 DAYMK INCH A Miles Grant Disphaces 7 4590 DAYMK INCH A Nee Ford Crow Marine CT Disphaces 7 4620 STRUCT DISTA ARAW A Nee Ford Crow Marine CT Disphaces 7 4620 STRUCT DISTA ARAW A Nee Ford Cro Charmed Disphaces 7 4620 STRUCT DISTA ARAW A Nee Ford Cro Charmed Disphaces 7 4620 STRUCT DISTA ARAW A Nee Crow Disphaces Cro Charmed Disphaces 7 4620 STRUCT DISTA ARAW A Nee Crow Charmed Disphaces 7 4620 STRUCT DISTA ARAW A Nee Crow Charmed Disphaces 7 <t< td=""><td>-</td><td></td><td></td><td></td></t<>	-			
Fisher Come Dippleacons 1 45135 STRUCT DESTAMAZ NAW PA Jenson Beach Charmel Dippleacon 1 45195 STRUCT MISSING PA Jenson Beach Charmel Dippleacon 5 45200 STRUCT MISSING PA Jenson Beach Charmel Dippleacon 6 45935 STRUCT MISSING PA Milles Grant Dippleacon 7 45980 DATME MICH PA Milles Grant Dippleacon 6 45980 DATME MICH PA Milles Grant Dippleacon 7 45980 DATME MICH PA Milles Grant Dippleacon 6 45995 DATME MICH PA Milles Grant Dippleacon 7 45995 DATME MICH PA VIS SIM Milles Dippleacon 1 45996 STRUCT DIST PA VIS SIM Milles Dippleacon 2 45900 STRUCT DIST PA Mysorich Spencer Scott Charmel Dippleacon 3 45700 STRUCT DIST PA Mysorich Spencer Scott Charmel Dippleacon 3 45700 STRUCT DIST PA Mundapar Charmel Dippleacon 3 45700 STRUCT DIST PA Mundapar Charmel Guyle 47000 STRU				
Faber Conc Diphotocom 14 45196 STRICT DIST PA Jearns Boach Charmel Diphotocom 5 45500 STRICT MISSING PA Jearns Boach Charmel Diphotocom 5 45500 STRICT MISSING PA Jearns Boach Charmel Diphotocom 6 45500 DAMK MICH PA Milles Grant Diphotocom 6 45900 DAMK MICH PA Milles Grant Diphotocom 6 45900 DAMK MICH PA Nov-Port Core Marine CP Diphotocom 7 46000 STRICT DIST, MAN MICH PA Nov-Port Core Marine CP Diphotocom 3 46200 STRICT DIST, MAN MICH PA Nyborich Spencer Cir Charmel Diphotocom 3 46790 STRICT DIST, MAN MICH PA Nyborich Spencer Cir Charmel Diphotocom 3 46790 STRICT DIST, MAN MICH PA Nyborich Spencer Strict Charmel Diphotocom 3 46100 STRICT DIST, MAN MICH PA Nyborich Spencer Strict Charmel Diphotocom 3 46100 STRICT DIST, MAN MICH PA Nyborich Spencer Strict Charmel Diphotocom 3 47000 STRICT DIST, MAN MICH PA Nomalipan Charmel Diphotocom 2 47000 STRICT				
senem Beach Chromel Depleacon 4 4585 STRUCT MISSING PA Jernen Brach Chromel Depleacon 5 4500 STRUCT MISSING PA James Brach Chromel Depleacon 5 4500 STRUCT MISSING PA James Grand Depleacon 6 4500 DAYME MICH PA Miller Grand Depleacon 6 4500 DAYME MICH PA Miller Grand Depleacon 1 4500 DAYME MICH PA Miller Grand Depleacon 2 4500 STRUCT DIST PA Old Sils Marria Depleacon 3 4500 STRUCT DIST PA Ripborich Spencer Stort Chamel Depleacon 3 4670 STRUCT DIST PA Ripborich Spencer Stort Chamel Depleacon 3 4670 STRUCT DIST PA Ripborich Spencer Stort Chamel Depleacon 3 4670 STRUCT DIST PA Ripborich Spencer Stort Chamel Depleacon 3 4670 STRUCT DIST PA Ripborich Spencer Stort Chamel Depleacon 3 4670 STRUCT DIST PA Ripborich Spencer Stort Chamel Depleacon 3 4700 STRUCT DIST PA Manulagan Chamel Booy 1				
stemen Beach Channell Depheacen 5 4550 STRUCT MISSING PA levene Beach Channell Depheacen 6 4590 DAMM MICH PA Milles Grant Depheacen 4 4590 DAMM MICH PA Milles Grant Depheacen 5 4590 DAMM MICH PA New Port Core Mariner CP Depheacen 2 4620 STRUCT DEST PA Old Sip Marina Depheacen 3 4620 STRUCT DEST PA Rybowich Spericer Cir Channel Depheacen 3 4620 STRUCT DEST PA Rybowich Spericer Cir Channel Depheacen 3 4620 STRUCT DEST PA Rybowich Spericer Cir Channel Depheacen 3 4620 STRUCT DEST PA Rybowich Spericer Cir Channel Depheacen 3 4620 STRUCT DEST PA Rybowich Spericer Stant Channel Depheacen 3 4620 STRUCT DEST PA Rybowich Spericer Stant Channel Depheacen 3 4700 STRUCT DEST PA Manalapan Channel Depheacen 2 4700 STRUCT DEST PA Manalapan Channel Depheacen 3 4700 STRUCT DEST PA Manalapan Channel Depheacen 3<	· · · · · · · · · · · · · · · · · · ·			
sixes in seach Chronical Diphesion 6 4550 STRUCT MISSING PR Miles Grant Diphesion A 45980 DAMM IMCH PR Miles Grant Diphesion A 45990 DAMM IMCH PR Miles Grant Diphesion A 45990 DAMM IMCH PR Miles Grant Diphesion B 45990 STRUCT DEST PR Old Sing Marine Diphesion B 46800 STRUCT DEST PR Old Sing Marine Diphesion B 46790 STRUCT DEST PR Rybork Sperier Since Cruchinal Diphesion B 46790 STRUCT DEST PR Rybork Sperier Since Channel Diphesion B 46790 STRUCT DEST PR Rybork Sperier Since Channel Diphesion B 46810 STRUCT DEST PR Manalapar Channel Buyl S 47007 STRUCT DEST PR Manalapar Channel Buyl S 47007 STRUCT DEST PR Manalapar Channel Buyl S 47008 STRUCT DEST PR Manalapar Channel Buyl S 47009 STRUCT DEST PR Manalapar Channel Buyl S 47009 STRUCT DEST PR				
Miss Garnt Dybeacon 1 4980 DAYMK IMCH PA Miss Garnt Dybeacon 4 4599 DAYMK IMCH PA Miss Garnt Dybeacon 1 4500 DAYMK IMCH PA New Port Cew Marine CP Dybeacon 2 4600 STRUCT DEST PA Ribork 15 Spearer CR Channel Dybeacon 1 4600 STRUCT DEST PA Rybork 15 Spearer CR Channel Dybeacon 1 4600 STRUCT DEST PA Rybork 15 Spearer South Channel Dybeacon 1 4600 STRUCT DEST PA Rybork 15 Spearer South Channel Dybeacon 3 4600 STRUCT DEST PA Rybork 15 Spearer South Channel Dybeacon 3 4600 STRUCT DEST PA Rybork 15 Spearer South Channel Dybeacon 3 4700 STRUCT DEST PA Manulapar Channel Dybeacon 2 4700 STRUCT DEST PA Manulapar Channel Dybeacon 3 4700 STRUCT DEST PA Manulapar Channel Dybeacon 3 4700 STRUCT DEST PA Coen Institute Rib Dybeacon 3 4700 STRUCT DEST PA Coen Institute Rib Dybeacon 5 4700	-		STRUCT MISSING	
Miles Grant Daybeacon 4 45999 DAYMK INCH PA Miles Grant Daybeacon 6 45995 DAYMK INCH PA No Ship Marina Daybeacon 4 46600 STRUCT DEST/HAZ PAW PA DOS Ship Marina Daybeacon 1 46600 STRUCT DEST/HAZ PAW PA Rybookh Spencer Channel Daybeacon 1 47600 STRUCT DEST PA Rybookh Spencer Scruth Channel Daybeacon 3 48700 STRUCT DEST PA Rybookh Spencer South Channel Daybeacon 3 48900 STRUCT DEST PA Rybookh Spencer South Channel Daybeacon 3 48900 STRUCT DEST PA Rybookh Spencer South Channel Daybeacon 3 47007 STRUCT DEST PA Manalapan Channel Buye 47008 STRUCT DEST PA Manalapan Channel Buye 47008 STRUCT DEST PA Manalapan Channel Buye 47008 STRUCT DEST PA Coan Infel Park Daybeacon 3 47008 STRUCT DEST PA Coan Infel Park Daybeacon 4 47008 STRUCT DEST PA Coan Infel Park Daybeacon 5 47009				
Miles Grant Daybeacon 6 4895 DAMM MUCH PA New Port Core Marinet Cir Daybeacon 1 4660 STRUCT DEST/MAZ NAW PA R Spoorling Spearcy Cir Charnet Daybeacon 1 4660 STRUCT DEST/MAZ NAW PA R Spoorling Spearcy Cir Charnet Daybeacon 3 4670 STRUCT DEST PA R Spoorling Spearcy Cir Charnet Daybeacon 1 4680 STRUCT DEST PA R Spoorling Spearcy Cir Charnet Daybeacon 3 4680 STRUCT DEST PA Manalapan Charnet Daybeacon 2 47007 STRUCT DEST PA Manalapan Charnet Daybeacon 3 47008 STRUCT DEST PA Manalapan Charnet Daybeacon 3 47008 STRUCT DEST PA Manalapan Charnet Daybeacon 3 47008 MISSING PA Ocean Infel Park Daybeacon 3 4705 STRUCT DEST PA Cean Infel Park Daybeacon 3 4705 STRUCT DEST PA Cean Infel Park Daybeacon 4 4705 STRUCT DEST PA Cean Infel Park Daybeacon 5 4705 STRUCT DEST PA Cean Infel Park Daybeacon 6	Miles Grant Daybeacon 2	45980	DAYMK IMCH	PA
New Port Core Nativine Cur Depheson 2 6600 STRUCT DEST/HAZ NAV PA Old Sip Marina Depheson 4 46600 STRUCT DEST/HAZ NAV PA Rybowich Spencer Cr Channel Daybeacon 3 46700 STRUCT DEST/HAZ NAV PA Rybowich Spencer South Channel Daybeacon 3 46900 STRUCT DEST PA Rybowich Spencer South Channel Daybeacon 3 4800 STRUCT DEST PA Rybowich Spencer South Channel Daybeacon 3 4800 STRUCT DEST PA Manalapan Channel Boy 1 47007 STRUCT DEST PA Manalapan Channel Boy 2 47008 STRUCT DEST PA Menalapan Channel Boy 2 47008 STRUCT DEST PA Menalapan Channel Boy 2 47008 STRUCT DEST PA Menalapan Channel Boy 2 47008 STRUCT DEST PA Cean infel Park Daybeacon 3 4705 STRUCT DEST PA Cean infel Park Daybeacon 4 4705 STRUCT DEST PA Cean infel Park Daybeacon 5 4705 STRUCT DEST PA Cean infel Park Daybeacon 6 4705	Miles Grant Daybeacon 4	45990	DAYMK IMCH	PA
Old Sip Marina Daybeacon 1 46680 STRUCT DEST/HAZ NAY PRI Nijovokiń Spencer Cir Chameria Daybeacon 1 46780 STRUCT DEST A Rybodyń Spencer Cir Chameria Daybeacon 1 46800 STRUCT DEST PA Rybodyń Spencer South Chameria Daybeacon 1 46800 STRUCT DEST PA Manalapan Chameria Daybeacon 2 47007 STRUCT DEST PA Manalapan Chameria Daybeacon 2 47008 STRUCT DEST PA Manalapan Chameria Daybeacon 3 47008 STRUCT DEST PA Manalapan Chameria Daybeacon 3 47008 STRUCT DEST PA Manalapan Chameria Daybeacon 3 47008 STRUCT DEST PA Ocean Iniel Park Daybeacon 3 47008 STRUCT DEST PA Ocean Iniel Park Daybeacon 4 47008 STRUCT DEST PA Ocean Iniel Park Daybeacon 5 4700 STRUCT DEST PA Ocean Iniel Park Daybeacon 6 4700 STRUCT DEST PA Ocean Iniel Park Daybeacon 7 4700 STRUCT DEST PA Malians Island Daybeacon 1 47660 <td>Miles Grant Daybeacon 6</td> <td>45995</td> <td>DAYMK IMCH</td> <td>PA</td>	Miles Grant Daybeacon 6	45995	DAYMK IMCH	PA
Ryborich Spencer Cr Channel Daybeacon 1 46780 STRUCT DEST PA Ryborich Spencer Cr Channel Daybeacon 3 46790 STRUCT DEST A Ryborich Spencer South Channel Daybeacon 3 4880 STRUCT DEST A Ryborich Spencer South Channel Daybeacon 3 48810 STRUCT DIST A Manalapan Channel Buty 1 47007 STRUCT DEST A Manalapan Channel Buty 2 47008 STRUCT DEST A Manalapan Channel Buyes 2 4708 STRUCT DEST A Ocean Infel Park Daybeacon 3 47093 STRUCT DEST A Ocean Infel Park Daybeacon 4 47050 STRUCT DEST A Ocean Infel Park Daybeacon 5 4706 STRUCT DEST A Ocean Infel Park Daybeacon 6 4705 STRUCT DEST A Ocean Infel Park Daybeacon 7 47070 STRUCT DEST A Williams Stand Daybeacon 1 4765 STRUCT DEST A Williams Stand Daybeacon 3 4766 STRUCT DEST A Williams Stand Daybeacon 5 4766 STRUCT DEST	New Port Cove Marine Ctr Daybeacon 2	46620	STRUCT DEST	PA
Rybowich Spencer Ctr Channel Daybeacon 1 6790 STRUCT DEST M Rybowich Spencer South Channel Daybeacon 1 46800 STRUCT DEST A Rybowich Spencer South Channel Daybeacon 3 46810 STRUCT DEST A Manalapan Channel Busy 1 47007.5 STRUCT DEST A Manalapan Channel Busy 2 47008.0 STRUCT DEST A Manalapan Channel Daybeacon 3 47008.0 STRUCT DEST A Ocean Intel Park Daybeacon 3 47009.0 STRUCT DEST A Ocean Intel Park Daybeacon 4 47050.0 STRUCT DEST A Ocean Intel Park Daybeacon 5 47050.0 STRUCT DEST A Ocean Intel Park Daybeacon 6 47050.0 STRUCT DEST A Ocean Intel Park Daybeacon 7 47070.0 STRUCT DEST A Ocean Intel Park Daybeacon 8 47050.0 STRUCT DEST A Williams Island Daybeacon 3 47650.0 STRUCT DEST A Williams Island Daybeacon 6 47650.0 STRUCT DEST A Williams Island Daybeacon 1 47650.0 <	Old Slip Marina Daybeacon 4	46680	STRUCT DEST/HAZ NAV	PA
Ryborich Spencer South Channel Daybeacon 3 46800 STRUCT DEST 9A Ryborich Spencer South Channel Daybeacon 3 46810 STRUCT DEST PA Manalapan Channel Buyle 1 47007 STRUCT DEST PA Manalapan Channel Buyle 2 47008 STRUCT DEST PA Manalapan Channel Buyle 2 47008 STRUCT DEST PA Ocean Inder Park Daybeacon 3 47008 STRUCT DEST PA Ocean Inder Park Daybeacon 3 47050 MISSING PA Ocean Inder Park Daybeacon 3 47050 MISSING PA Ocean Inder Park Daybeacon 4 47050 STRUCT DEST PA Ocean Inder Park Daybeacon 6 47060 STRUCT DEST PA Ocean Inder Park Daybeacon 6 47055 STRUCT DEST PA Ocean Inder Park Daybeacon 8 47070 STRUCT DEST PA Williams Stand Daybeacon 9 47075 STRUCT DEST PA Williams Stand Daybeacon 1 47645 STRUCT DEST PA Williams Stand Daybeacon 5 47650 DAYMK MISSING	Rybovich Spencer Ctr Channel Daybeacon 1	46780	STRUCT DEST	PA
Rybowich Spencer South Channel Daybeacon 3 48610 STRUCT DEST A Manalapan Channel Buoy 1 47007 STRUCT DEST A Manalapan Channel Buoye 2 47008 STRUCT DEST A Manalapan Channel Buoye 2 47008 STRUCT DEST A Manalapan Channel Buoyeacon 3 47008 MISCINE A Ocean Inlet Park Daybeacon 4 4705 STRUCT DEST A Ocean Inlet Park Daybeacon 5 4706 STRUCT DEST A Ocean Inlet Park Daybeacon 6 47065 STRUCT DEST A Ocean Inlet Park Daybeacon 7 47070 STRUCT DEST A Ocean Inlet Park Daybeacon 8 47070 STRUCT DEST A Ocean Inlet Park Daybeacon 1 47070 STRUCT DEST A Ocean Inlet Park Daybeacon 3 4765 STRUCT DEST A Williams Island Daybeacon 1 4766 STRUCT DEST A Williams Island Daybeacon 4 4766 STRUCT DEST A Williams Island Daybeacon 5 47660 STRUCT DEST A	Rybovich Spencer Ctr Channel Daybeacon 3	46790	STRUCT DEST	PA
Manalapan Channel Buoy 1 47007 STRUCT DEST 9A Manalapan Channel Buoy 2 47007 STRUCT DEST 9A Manalapan Channel Buoy 2 47008 STRUCT DEST 9A Manalapan Channel Buoy 2 47008 STRUCT DEST 9A Manalapan Channel Daybeacon 3 47008 STRUCT DEST 9A Ocean Intel Park Daybeacon 4 47050 STRUCT DEST 9A Ocean Intel Park Daybeacon 5 47060 STRUCT DEST 9A Ocean Intel Park Daybeacon 6 47055 STRUCT DEST 9A Ocean Intel Park Daybeacon 7 47070 STRUCT DEST 9A Williams Island Daybeacon 8 47655 STRUCT DEST 9A Williams Island Daybeacon 9 47650 DAYMK MISSING/STRUCT DMGD 9A Williams Island Daybeacon 4 47650 DAYMK MISSING/STRUCT DMGD 9A Williams Island Daybeacon 5 47660 STRUCT DEST 9A Williams Island Daybeacon 6 47665 STRUCT DEST 9A Williams Island Light 1 47665 STRUCT DEST 9A </td <td>Rybovich Spencer South Channel Daybeacon 1</td> <td>46800</td> <td>STRUCT DEST</td> <td>PA</td>	Rybovich Spencer South Channel Daybeacon 1	46800	STRUCT DEST	PA
Manalapan Channel Buoy 1 47007 STRUCT DEST 9A Manalapan Channel Buoy 2 47007 STRUCT DEST 9A Manalapan Channel Buoy 2 47008 STRUCT DEST 9A Manalapan Channel Buoy 2 47008 STRUCT DEST 9A Manalapan Channel Daybeacon 3 47008 STRUCT DEST 9A Ocean Intel Park Daybeacon 4 47050 STRUCT DEST 9A Ocean Intel Park Daybeacon 5 47060 STRUCT DEST 9A Ocean Intel Park Daybeacon 6 47055 STRUCT DEST 9A Ocean Intel Park Daybeacon 7 47070 STRUCT DEST 9A Williams Island Daybeacon 8 47655 STRUCT DEST 9A Williams Island Daybeacon 9 47650 DAYMK MISSING/STRUCT DMGD 9A Williams Island Daybeacon 4 47650 DAYMK MISSING/STRUCT DMGD 9A Williams Island Daybeacon 5 47660 STRUCT DEST 9A Williams Island Daybeacon 6 47665 STRUCT DEST 9A Williams Island Light 1 47665 STRUCT DEST 9A </td <td>Rybovich Spencer South Channel Daybeacon 3</td> <td>46810</td> <td>STRUCT DEST</td> <td>PA</td>	Rybovich Spencer South Channel Daybeacon 3	46810	STRUCT DEST	PA
Manalapan Channel Buybeacon 2 47007.5 STRUCT DEST PA Manalapan Channel Buyo 2 47008 STRUCT DEST PA Manalapan Channel Buyobacon 3 47008 STRUCT DEST PA Ocean Inlet Park Daybeacon 3 47050 MISSING PA Ocean Inlet Park Daybeacon 4 47050 STRUCT DEST PA Ocean Inlet Park Daybeacon 5 47060 STRUCT DEST PA Ocean Inlet Park Daybeacon 6 47070 STRUCT DEST PA Ocean Inlet Park Daybeacon 7 47070 STRUCT DEST PA Williams Island Daybeacon 1 47650 STRUCT DEST PA Williams Island Daybeacon 3 47660 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47660 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 6 47660 STRUCT DEST PA Williams Island Daybeacon 6 47660 STRUCT DEST PA Williams Island Daybeacon 7 47737 WIRLIAM SISING PA Williams Island Light 2 47737 WIRLIAM SISING		47007	STRUCT DEST	PA
Manalapan Channel Buoy 2 47008 STRUCT DEST PA Manalapan Channel Buoybeacon 3 47008.5 STRUCT DEST PA Ocean Inlet Park Daybeacon 4 4705.0 MSSING PA Ocean Inlet Park Daybeacon 5 4706.0 STRUCT DEST PA Ocean Inlet Park Daybeacon 6 4706.0 STRUCT DEST PA Ocean Inlet Park Daybeacon 7 4707.0 STRUCT DEST PA Ocean Inlet Park Daybeacon 8 4707.0 STRUCT DEST PA Williams Island Daybeacon 1 4765.0 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 3 4766.0 DAYMK IMCH/ISTRUCT DMGD PA Williams Island Daybeacon 4 4765.0 DAYMK IMCH/ISTRUCT DMGD PA Williams Island Daybeacon 5 4766.0 STRUCT DEST PA Williams Island Daybeacon 6 4766.5 STRUCT DEST PA Williams Island Light 1 4766.5 STRUCT DEST PA Williams Island Light 2 4769.0 STRUCT DEST PA Williams Island Light 2 4766.5 STRUCT DES		47007.5	STRUCT DEST	PA
Manalapan Channel Daybeacon 3 47008-5 STRUCT DEST PA Ocean Inlet Park Daybeacon 4 47050 MISSING PA Ocean Inlet Park Daybeacon 5 47060 STRUCT DEST PA Ocean Inlet Park Daybeacon 6 47060 STRUCT DEST PA Ocean Inlet Park Daybeacon 6 47060 STRUCT DEST PA Ocean Inlet Park Daybeacon 8 47075 STRUCT DEST PA Williams Island Daybeacon 1 47064 STRUCT DEST PA Williams Island Daybeacon 3 47665 STRUCT DEST PA Williams Island Daybeacon 3 47660 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 3 47660 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47660 STRUCT DEST PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 19 47737.2<				
Ocean Inlet Park Daybeacon 3 47055 STRUCT DEST PA Ocean Inlet Park Daybeacon 4 47055 STRUCT DEST PA Ocean Inlet Park Daybeacon 5 47060 STRUCT DEST PA Ocean Inlet Park Daybeacon 6 47065 STRUCT DEST PA Ocean Inlet Park Daybeacon 7 47070 STRUCT DEST PA Ocean Inlet Park Daybeacon 8 47056 STRUCT DEST PA Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47650 DAYMK MISSING CONTROLL PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Light 1 47660 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 8 47372.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 4	·			
Ocean Inlet Park Daybeacon 4 47055 STRUCT DEST PA Ocean Inlet Park Daybeacon 5 47060 STRUCT DEST PA Ocean Inlet Park Daybeacon 6 47065 STRUCT DEST PA Ocean Inlet Park Daybeacon 7 47070 STRUCT DEST PA Ocean Inlet Park Daybeacon 8 47075 STRUCT DEST PA Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47660 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA	· · · · · · · · · · · · · · · · · · ·			
Ocean Intelt Park Daybeacon 5 47060 STRUCT DEST PA Ocean Intelt Park Daybeacon 6 47065 STRUCT DEST PA Ocean Intelt Park Daybeacon 7 47070 STRUCT DEST PA Ocean Intelt Park Daybeacon 8 47075 STRUCT DEST PA Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Ught 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 8 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel	,			
Ocean Inlet Park Daybeacon 6 47076 STRUCT DEST PA Ocean Inlet Park Daybeacon 7 47070 STRUCT DEST PA Ocean Inlet Park Daybeacon 8 47075 STRUCT DEST PA Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47650 STRUCT DEST PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47660 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Injet 2 47690 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.2 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12				
Ocean Inlet Park Daybeacon 7 47070 STRUCT DEST PA Ocean Inlet Park Daybeacon 8 47075 STRUCT DEST PA Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47655 DAYMK IMCH/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Light 1 47660 STRUCT DEST PA Williams Island Light 2 47660 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47680 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 8 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA In				
Ocean Inlet Park Daybeacon 8 47075 STRUCT DEST PA Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47655 DAYMK IMCH/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Light 1 47665 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Vacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 8 47737.200000000004 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 12 47737.00000000004 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 13 47737.00000000004				
Williams Island Daybeacon 1 47645 STRUCT DEST PA Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47655 DAYMK IMCH/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Vacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 8 47737.2 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Vacht Club Channel Daybeacon 13 47787.0000000000 DAYMK MISSING				
Williams Island Daybeacon 3 47650 DAYMK MISSING/STRUCT DMGD PA Williams Island Daybeacon 4 47655 DAYMK IMCH/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 8 47737.2000000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.700000000004 DAYMK MISSING PA Mariners Bay Daybeacon 3 47890 DAYMK				
Williams Island Daybeacon 4 47655 DAYMK IMCH/STRUCT DMGD PA Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 8 47737.20000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.5 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.70000000004 DAYMK MISSING PA Mariners Bay Daybeacon 3 47890 DAYMK MISSING PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA				
Williams Island Daybeacon 5 47660 STRUCT DEST PA Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 8 47737.200000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.700000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 1 47890 DAYMK MISSING PA Mariners Bay Daybeacon 3 47890 DAYMK MISSING PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA				
Williams Island Daybeacon 6 47665 STRUCT DEST PA Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 8 47737.200000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 11 47737.5 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.700000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 10 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST				
Williams Island Light 1 47685 STRUCT DEST PA Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 8 47737.20000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 11 47737.5 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.70000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK MISSING PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47963 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST <td< td=""><td></td><td></td><td></td><td></td></td<>				
Williams Island Light 2 47690 STRUCT DEST PA Intracoastal Yacht Club Channel Daybeacon 7 47737.1 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 8 47737.200000000004 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 9 47737.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 11 47737.5 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.700000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRU		47665	STRUCT DEST	PA
Intracoastal Yacht Club Channel Daybeacon 7 Intracoastal Yacht Club Channel Daybeacon 8 Intracoastal Yacht Club Channel Daybeacon 8 Intracoastal Yacht Club Channel Daybeacon 9 Intracoastal Yacht Club Channel Daybeacon 9 Intracoastal Yacht Club Channel Daybeacon 10 Intracoastal Yacht Club Channel Daybeacon 10 Intracoastal Yacht Club Channel Daybeacon 11 Intracoastal Yacht Club Channel Daybeacon 11 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Channel Daybeacon 14 Intracoastal Yacht Club Channel Daybeacon 15 Intracoastal Yacht Club Channel Daybeacon 15 Intracoastal Yacht Club Channel Daybeacon 17 Intracoastal Yacht Club Channel Daybeacon 17 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Channel Daybeacon 14 Intracoastal Yacht Club Channel Daybeacon 15 Intracoastal Yacht Club Cha	Williams Island Light 1	47685	STRUCT DEST	PA
Intracoastal Yacht Club Channel Daybeacon 8 Intracoastal Yacht Club Channel Daybeacon 9 Intracoastal Yacht Club Channel Daybeacon 9 Intracoastal Yacht Club Channel Daybeacon 10 Intracoastal Yacht Club Channel Daybeacon 10 Intracoastal Yacht Club Channel Daybeacon 10 Intracoastal Yacht Club Channel Daybeacon 11 Intracoastal Yacht Club Channel Daybeacon 11 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Channel Daybeacon 14 Intracoastal Yacht Club Channel Daybeacon 15 Intracoastal Yacht Club Channel Daybeacon 15 Intracoastal Yacht Club Channel Daybeacon 16 Intracoastal Yacht Club Channel Daybeacon 17 Intracoastal Yacht Club Channel Daybeacon 16 Intracoastal Yacht Club Channel Daybeacon 16 Intracoastal Yacht Club Channel Daybeacon 16 Intracoastal Yacht Club Channel Daybeacon 17 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 19 Intracoastal Yacht Club	Williams Island Light 2	47690	STRUCT DEST	PA
Intracoastal Yacht Club Channel Daybeacon 9 4773.3 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 10 4773.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 11 4773.5 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 4773.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 4773.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 4773.7.0000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 10 Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2	Intracoastal Yacht Club Channel Daybeacon 7	47737.1	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 10 47737.4 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 11 47737.5 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 12 A7737.700000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 A7890 DAYMK MISSING PA Mariners Bay Daybeacon 3 A7895 STRUCT DEST PA Mariners Bay Daybeacon 5 A7900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 A7953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 A7960 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 A8220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2	Intracoastal Yacht Club Channel Daybeacon 8	47737.200000000004	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Channel Daybeacon 1 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Channel Daybeacon 12 Intracoastal Yacht Club Channel Daybeacon 13 Intracoastal Yacht Club Chann	Intracoastal Yacht Club Channel Daybeacon 9	47737.3	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.70000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA	Intracoastal Yacht Club Channel Daybeacon 10	47737.4	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 12 47737.6 DAYMK MISSING PA Intracoastal Yacht Club Channel Daybeacon 13 47737.70000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA	Intracoastal Yacht Club Channel Daybeacon 11	47737.5	DAYMK MISSING	PA
Intracoastal Yacht Club Channel Daybeacon 13 4773.70000000004 DAYMK MISSING PA Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA		47737.6		PA
Mariners Bay Daybeacon 1 47890 DAYMK DMGD/STRUCT DMGD PA Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA	·			
Mariners Bay Daybeacon 3 47895 STRUCT DEST PA Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA				
Mariners Bay Daybeacon 5 47900 DAYMK MISSING PA Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 4825 STRUCT DEST/HAZ NAV PA				
Jockey Club Marina Daybeacon 10 47953 DAYMK MISSING PA Jockey Club Marina Daybeacon 15 47960 STRUCT DEST PA Jockey Club Marina Daybeacon 17 47965 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA				
Jockey Club Marina Daybeacon 1547960STRUCT DESTPAJockey Club Marina Daybeacon 1747965STRUCT DESTPAMike Gordon Restaurant Daybeacon 148220STRUCT DESTPAMike Gordon Restaurant Daybeacon 248225STRUCT DEST/HAZ NAVPA				
Jockey Club Marina Daybeacon 1747965STRUCT DESTPAMike Gordon Restaurant Daybeacon 148220STRUCT DESTPAMike Gordon Restaurant Daybeacon 248225STRUCT DEST/HAZ NAVPA				
Mike Gordon Restaurant Daybeacon 1 48220 STRUCT DEST PA Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA				
Mike Gordon Restaurant Daybeacon 2 48225 STRUCT DEST/HAZ NAV PA				
·				
Mike Gordon Restaurant Daybeacon 3 48230 DAYMK MISSING PA				
	Mike Gordon Restaurant Daybeacon 3	48230	DAYMK MISSING	PA

https://www.navcen.uscg.gov/msi 66/73

70/20, 12:20 1 W	,	oddots Navigation Ochter	
Palm Bay Club Channel Daybeacon 2	48290	DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 4	48300	DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 5	48305	DAYMK IMCH	PA
Palm Bay Club Channel Daybeacon 6	48310	DAYMK DMGD	PA
Palm Bay Club Channel Daybeacon 7	48315	DAYMK MISSING	PA
Palm Bay Club Channel Daybeacon 8	48320	DAYMK MISSING	PA
Sea Isle Marina Daybeacon 1	48400	STRUCT DEST	PA
Sea Isle Marina Daybeacon 2	48405	STRUCT DEST	PA
Sea Isle Marina Daybeacon 3	48410	STRUCT DEST	PA
Sea Isle Marina Daybeacon 4	48415	STRUCT DEST	PA
Sea Isle Marina Daybeacon 5	48420	STRUCT DEST	PA
Sea Isle Marina Daybeacon 6	48425	STRUCT DEST	PA
Sea Isle Marina Daybeacon 7	48430	STRUCT DEST	PA
Deering Channel Daybeacon 1	48610	STRUCT DEST	PA
Deering Channel Light 2	48615	HAZ NAV/DAYMK MISSING	PA
Deering Channel Daybeacon 3	48620	DAYMK MISSING	PA
Deering Channel Daybeacon 4	48625	DAYMK MISSING	PA
Deering Channel Daybeacon 5	48630	HAZ NAV/DAYMK MISSING	PA
Deering Channel Daybeacon 6	48635	HAZ NAV/DAYMK MISSING	PA
	48640		PA
Deering Channel Daybeacon 7		DAYMK MISSING	
Deering Channel Daybeacon 8	48645	DAYMK MISSING	PA
Deering Channel Daybeacon 9	48650	HAZ NAV/DAYMK MISSING	PA
Grove Island Channel Daybeacon 1A	48665	STRUCT DEST	PA
Grove Island Channel Daybeacon 2	48670	STRUCT DEST	PA
Grove Island Channel Light 9	48705	LT EXT	PA
Grove Island Channel Light 10	48710	LT EXT	PA
Grove Island Channel Light 18	48745	LT EXT	PA
L'Hermitage Light 1	48750	DAYMK MISSING	PA
L'Hermitage Light 2	48755	DAYMK MISSING	PA
L'Hermitage Daybeacon 4	48765	DAYMK MISSING	PA
John A Brennan Channel Daybeacon 2	48985	STRUCT DEST/HAZ NAV	PA
-	49051	STRUCT DEST	PA
Dinner Key Mooring Field 4 Lighted Buoy AA	43031	STRUCT DEST	FA
Discour Key Mary day Field A Bress CC	40051 20000000004	MICCINIC	DA
Dinner Key Mooring Field 4 Buoy CC	49051.200000000004	MISSING	PA
Dinner Key Mooring Field 4 Buoy HH	49051.700000000004	MISSING	PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II	49051.700000000004 49051.8	MISSING MISSING	PA PA
Dinner Key Mooring Field 4 Buoy HH	49051.700000000004	MISSING	PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II	49051.700000000004 49051.8	MISSING MISSING	PA PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8	49051.70000000004 49051.8 49055.700000000004	MISSING MISSING STRUCT DEST	PA PA PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12	49051.700000000004 49051.8 49055.70000000004 49056	MISSING MISSING STRUCT DEST STRUCT DEST	PA PA PA PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2	49051.700000000004 49051.8 49055.70000000004 49056 49090	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST	PA PA PA PA PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD	PA PA PA PA PA PA PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING	PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING	PA
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105 49110	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49110 49111	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105 49110 49115 49120	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105 49110 49115 49120 49150	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DBD DMGD DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105 49110 49115 49120 49150 49155	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49150 49155 49215	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DBD DMGD DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105 49110 49115 49120 49150 49155	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49150 49155 49215	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49105 49110 49115 49120 49150 49155 49215 49220	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6	49051.700000000004 49051.8 49055.700000000004 49096 49090 49095 49100 49100 49110 49115 49120 49150 49155 49215 49220 49595	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT MISSING STRUCT MISSING STRUCT MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1	49051.700000000004 49051.8 49055.700000000004 49096 49090 49095 49100 49100 49110 49115 49120 49150 49155 49220 49595 49865	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING DAYMK MISSING DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING STRUCT MISSING STRUCT MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3	49051.70000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49100 49115 49110 49115 49120 49150 49155 49215 49220 49595 49865 49870 49960	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING DAYMK MISSING DAYMK MISSING STRUCT MISSING LT EXT/STRUCT DMGD LT EXT	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 4A	49051.70000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49150 49155 49215 49220 49595 49865 49870 49960 49975	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING STRUCT MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 6	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49150 49155 49215 49220 49595 49865 49870 49960 49975 49985	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 6 Turkey Point Channel Buoy 7	49051.70000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49150 49155 49215 49220 49595 49865 49870 49985 49990	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING DAYMK MISSING DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3 Turkey Point Channel Buoy 6 Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 7	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD LTEXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA OFF STA	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 21	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA OFF STA	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 21 Turkey Point Channel Buoy 23	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060 50070	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING OFF STA OFF STA MISSING MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 21	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA OFF STA	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 21 Turkey Point Channel Buoy 23	49051.700000000004 49051.8 49055.700000000004 49056 49090 49095 49100 49105 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060 50070	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING OFF STA OFF STA MISSING MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 1 Convoy Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 24	49051.700000000004 49051.8 49055.700000000004 49096 49090 49095 49100 49100 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060 50070 50075	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA OFF STA MISSING MISSING MISSING MISSING MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Light 2 Turkey Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 24 Community Harbor Daybeacon 6	49051.700000000004 49051.8 49055.700000000004 49096 49090 49095 49100 49100 49115 49110 49115 49120 49150 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060 50070 50075 50535.4	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD LYMK MISSING DAYMK MISSING DAYMK MISSING STRUCT MISSING STRUCT MISSING LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA OFF STA OFF STA MISSING MISSING MISSING MISSING MISSING MISSING MISSING MISSING MISSING	PA P
Dinner Key Mooring Field 4 Buoy HH Dinner Key Mooring Field 4 Lighted Buoy II Island E Channel Daybeacon 8 Island E Channel Daybeacon 12 Four Way Entrance Channel Light 2 Four Way Entrance Channel Daybeacon 3 Four Way Entrance Channel Daybeacon 4 Four Way Entrance Channel Daybeacon 4 Middle Ground Obstruction Buoy Four Way Entrance Channel Daybeacon 5 Four Way Entrance Channel Daybeacon 6 Four Way Entrance Channel Daybeacon 7 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 1 Four Way Channel Daybeacon 2 Anchorage Channel Daybeacon 2 Anchorage Channel Daybeacon 4 Deering Bay Channel Daybeacon 6 Convoy Point Light 1 Convoy Point Channel Buoy 3 Turkey Point Channel Buoy 4A Turkey Point Channel Buoy 7 Turkey Point Channel Buoy 11 Turkey Point Channel Buoy 21 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 23 Turkey Point Channel Buoy 24 Community Harbor Daybeacon 6 Royal Palm Yacht Club Channel Daybeacon 1	49051.700000000004 49051.8 49055.700000000004 49096 49090 49095 49100 49100 49115 49110 49115 49120 49155 49215 49220 49595 49865 49870 49960 49975 49985 49990 50010 50060 50070 50075 50535.4 52785	MISSING MISSING STRUCT DEST STRUCT DEST STRUCT DEST DAYMK MISSING STRUCT DMGD DAYMK MISSING MISSING DBD DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD DAYMK MISSING STRUCT DMGD LYMK MISSING DAYMK MISSING STRUCT MISSING STRUCT MISSING STRUCT MISSING LT EXT/STRUCT DMGD LT EXT MISSING MISSING OFF STA OFF STA OFF STA MISSING DAYMK MISSING DAYMK MISSING	PA P

https://www.navcen.uscg.gov/msi 67/73

/0/25, 12.20 PW	Manume Salety Informatio	in Products Navigation Center	
Royal Palm Yacht Club Channel Daybeacon 4	52800	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 4	52800	STRUCT DEST	PA
Royal Palm Yacht Club Channel Daybeacon 5	52805	DBD DEST	PA
Royal Palm Yacht Club Channel Daybeacon 6	52810	DBD DEST	PA
Paradise Yacht Club Daybeacon 5	52930	DAYMK MISSING	PA
Paradise Yacht Club Daybeacon 9	52950	DAYMK IMCH/STRUCT DMGD	PA
Paradise Yacht Club Daybeacon 11	52960	DAYMK MISSING	PA
Paradise Yacht Club Daybeacon 12	52965	HAZ NAV/DAYMK MISSING	PA
Whiskey Creek Channel Daybeacon 3	53370	HAZ NAV/STRUCT DEST	PA
Caloosa Yacht Club Channel Daybeacon 1	53475	DAYMK MISSING	PA
McGregor Isles Daybeacon 13	53511	STRUCT DEST	PA
McGregor Isles Daybeacon 15	53515	STRUCT DEST	PA
McGregor Isles Daybeacon 17	53520	STRUCT DEST	PA
Riverside Marina(Ft. Myers) Daybeacon 3	53685	DAYMK MISSING	PA
Cabbage Key Channel Daybeacon 6	56060		PA
	56665	HAZ NAV/STRUCT DEST	PA PA
Fishery Restaurant Channel Daybeacon 3		STRUCT DEST/HAZ NAV	
Uncle Henry's Marina Daybeacon 2	56785	STRUCT DEST	PA -
Uncle Henry's Marina Daybeacon 3	56790	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 5	56800	STRUCT DEST/HAZ NAV	PA
Uncle Henry's Marina Daybeacon 7	56805	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 11	56825	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 12	56830	STRUCT DEST/HAZ NAV	PA
Uncle Henry's Marina Daybeacon 13	56835	STRUCT DEST/HAZ NAV	PA
Uncle Henry's Marina Daybeacon 15	56845	DAYMK MISSING/STRUCT DMGD	PA
Uncle Henry's Marina Daybeacon 16	56850	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 24	56890	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 27	56905	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 30	56920	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 31	56925	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 35	56945	STRUCT DMGD	PA
Uncle Henry'S Marina Daybeacon 36	56950	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 37	56955	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 40	56970	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 41	56975	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 42	56980	DAYMK MISSING	PA
Uncle Henry's Marina Daybeacon 43	56985	STRUCT DEST	PA
Uncle Henry's Marina Daybeacon 47	57005	STRUCT DEST	PA
		STRUCT DEST	PA PA
Englewood Channel Daybeacon 22	57359.130000000005		PA PA
Englewood Channel Daybeacon 10	57359.6	STRUCT DEST	
Bayview Channel Daybeacon 3	57380	DAYMK DMGD	PA
Bayview Channel Daybeacon 4	57385	STRUCT DEST	PA
Bayview Channel Daybeacon 6	57395	STRUCT DEST	PA
Bayview Channel Daybeacon 8	57405	STRUCT DEST	PA
Bayview Channel Daybeacon 9	57410	DAYMK MISSING	PA
Bayview Channel Daybeacon 10	57415	STRUCT DEST	PA
Bay Heights Daybeacon 1	57418	DAYMK MISSING	PA
Bay Heights Daybeacon 2	57418.1	DAYMK MISSING	PA
Venice Yacht Club Obstruction Light A	57779	STRUCT DEST	PA
San Remo Daybeacon 1	58446	STRUCT DEST	PA
San Remo Daybeacon 2	58447	STRUCT DEST	PA
San Remo Daybeacon 2	58447	DAYMK IMCH	PA
San Remo Daybeacon 3	58448	STRUCT DEST	PA
San Remo Daybeacon 5	58449	STRUCT DEST	PA
San Remo Daybeacon 5	58449	STRUCT DEST	PA
San Remo North Obstruction Daybeacon	58449.1	STRUCT DEST/HAZ NAV	PA
San Remo South Obstruction Daybeacon	58449.200000000004	STRUCT DEST/HAZ NAV	PA
Hudson Bayou Daybeacon 1	58485.1	DAYMK IMCH	PA
	58485.3	STRUCT MISSING	PA PA
Hudson Bayou Daybeacon 3			
Bird Key Channel Daybeacon 2	58510	DAYMK MISSING	PA
Bird Key Channel Daybeacon 3	58515	DAYMK MISSING	PA PA
Bird Key Channel Daybeacon 7	58525	DAYMK MISSING	PA
Bay Isles South Channel Daybeacon 1	58640	STRUCT DMGD	PA
Bay Isles South Channel Daybeacon 4	58650	DAYMK DMGD	PA
Bay Isles South Channel Daybeacon 6	58655	DAYMK MISSING	PA

https://www.navcen.uscg.gov/msi 68/73

0/20, 12:20 1 W	Martinio Galety Inform	ation i roddoto į ridvigation Contei	
Bay Isles South Channel Daybeacon 10	58665	HAZ NAV/DAYMK MISSING	PA
Longboat Key Moorings Light 1	58680	STRUCT DEST/HAZ NAV	PA
Buttonwood Harbor Channel Daybeacon 13	58910	DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 20	58935	DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 23	58945	HAZ NAV/DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 24	58950	DAYMK MISSING	PA
Buttonwood Harbor Channel Daybeacon 26	58955	DAYMK MISSING	PA
ongboat Harbor Channel Daybeacon 13A	59050	DAYMK MISSING	PA
ongboat Harbor Channel Daybeacon 17	59070	DAYMK MISSING	PA
ongboat Harbor North Marina Daybeacon 4	59140	STRUCT DEST	PA
ongboat Harbor North Marina Daybeacon 6	59145	STRUCT DEST	PA
ongboat Harbor North Marina Daybeacon 8	59150	STRUCT DEST	PA
Catalina Channel Daybeacon 5	59630	STRUCT DEST	PA
Gradenton Beach City South Channel Daybeacon 1	59960	STRUCT DEST	PA
	59965	STRUCT DEST	PA
tradenton Beach City South Channel Daybeacon 3	60120		PA PA
Perico Harbor Marina Daybeacon 13		HAZ NAV/DAYMK MISSING	
ayway Isles Channel Daybeacon 3	60635	STRUCT DEST	PA PA
ayway Isles Channel Daybeacon 10	60660	DAYMK MISSING	PA
Gulfport Yacht Basin Channel Range Front Light	60700	LT EXT	PA
Gulfport Yacht Basin Channel Range Rear Light	60705	LT EXT	PA
sulfport Yacht Club Channel Daybeacon 4	60745	STRUCT DEST	PA
ungle Estates Daybeacon 6	61150	STRUCT DEST	PA
ebastian Inlet Channel Daybeacon 1A	9730	STRUCT DEST	PA
tump Pass Marina Daybeacon 2	21390	STRUCT DEST/HAZ NAV	PA
tump Pass Marina Daybeacon 3	21395	STRUCT DEST/HAZ NAV	PA
ig Sarasota Pass Buoy 7	21500.7	MISSING	PA
outh Lido South Obstruction Daybeacon	21555.2	STRUCT DEST/HAZ NAV	PA
ountry Club Shores Daybeacon 4	21665	DAYMK DMGD	PA
oint Pinellas Daybeacon 1	24740	HAZ NAV/STRUCT DMGD	PA
ays Harbor Lights Marina Daybeacon 1	42205	HAZ NAV/DAYMK MISSING	PA
ays Harbor Lights Marina Daybeacon 2	42210	HAZ NAV/DAYMK DMGD/STRUCT DMGD	PA
ays Harbor Lights Marina Daybeacon 3	42215	DAYMK MISSING	PA
ays Harbor Lights Marina Daybeacon 4	42220	HAZ NAV/DAYMK MISSING/STRUCT DMGD	PA
randon Park Marina Channel Light 14	48845	STRUCT DEST/HAZ NAV/TRLB	PA
sland E Channel Daybeacon 2	49055.1	STRUCT DEST	PA
Deering Bay Channel Daybeacon 4	49585	STRUCT DEST/HAZ NAV	PA
			PA
andings Marina Daybeacon 6	53755	DAYMK MISSING	
nglewood Channel Daybeacon 8	57359.5	STRUCT DEST	PA
lackburn Point Channel Daybeacon 1	58101	DAYMK MISSING	PA
lackburn Point Channel Daybeacon 2	58102	DAYMK MISSING	PA
arasota Sail Squad Rc Buoy A	58580	MISSING	PA
arasota Sail Squad Rc Buoy B	58585	MISSING	PA
arasota Sail Squad Rc Buoy C	58590	MISSING	PA
arasota Sail Squad Rc Buoy D	58595	MISSING	PA
arasota Sail Squad Rc Buoy E	58600	MISSING	PA
arasota Sail Squad Rc Buoy F	58605	MISSING	PA
arasota Sail Squad Rc Buoy H	58615	MISSING	PA
arasota Sail Squad Rc Buoy I	58620	MISSING	PA
arasota Sail Squad Rc Buoy J	58625	MISSING	PA
arasota Sail Squad Rc Buoy K	58630	MISSING	PA
uttonwood Harbor Channel Junction Daybeacon B	58905	DAYMK MISSING	PA
ongboat Harbor North Marina Daybeacon 2	59135	DAYMK MISSING	PA
uccaneer Inn Daybeacon 14	59265	DAYMK IMCH	PA
uccaneer Inn Daybeacon 16	59270	DAYMK IMCH	PA
uccaneer Inn Daybeacon 20	59285	STRUCT DEST	PA
·	59300		PA
uccaneer Inn Daybeacon 24		DAYMK IMCH	
atalina Channel Daybeacon 1	59620	STRUCT DEST	PA
atalina Channel Daybeacon 3	59625	STRUCT DEST	PA
asadena Yacht Club Channel Daybeacon 6	60770	STRUCT DEST/HAZ NAV	PA
asadena Yacht Club Channel Daybeacon 9	60780	STRUCT DEST	PA
ungle Estates Daybeacon 4	61140	STRUCT DEST	PA

Additional MSI Categories

		TITLE SUBCATEGORY		CATION	
--	--	-------------------	--	--------	--

https://www.navcen.uscg.gov/msi 69/73

Unknown/General/Bridges/Construction Bridges	SAN JOSE CREEK-GOLETA SLOUGH: STATE ROUTE 217 HIGHWAY BRIDGE- Caltrans has resumed in-water construction for the bridge	Lat:
	replacement project, scheduled to be completed by 31 October, 2025. Nets will be installed in the slough to prevent fish from the area.	34° 25' 15"
	An open navigable passage in the middle of the slough under the bridge will be available for mariners. Demolition of old bridge will	Lon:
	take place May 2025. Mariners are requested to transit the area with caution. For more information, contact the Coast Guard Bridge	-119° 49'
	Office at 571-607-2206 or by e-mail at D11Bridges@uscg.mil.	47"

Upper Savannah River

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Southern Nuclear Operating Co Obstruction Daybeacon A	5295	STRUCT DEST	PA
Southern Nuclear Operating Co Obstruction Daybeacon B	5295.1	STRUCT DEST	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Port Wentworth Channel - Upper Savannah River/General/Miscellaneous	Miscellaneous	General/Miscellaneous 20921 Location: 33.3492° N / 81.93818° W Delete: Upper Savannah River Buoy 92	Lat: 33° 20' 57"
			Lon: -081° 56' 17"

Vernon River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Ossabaw Sound - Vernon	Advanced Notice	ATON/Advanced Notice of Change Location: 31.87195° N / 81.07605° W Aid Name: Vernon River Light Wreck 86 LLNR: 36260 Action: CHANGE	Lat:
River/ATON/Advanced Notice	of Change	Action Type Change Light Characteristic The following change has been approved to the Aid to Navigation system in the Intracoastal Waterway	31° 52' 19"
of Change		the Vernon River, part of the Intracoastal Waterway (ICW). The nominal range permanently reduced from 5NM to 4NM. The current nominal	Lon:
		range of 5NM is not necessary. Based on the design of the Short-Range Aids System (SRA), mariners should be able to see two lighted aids to	-081° 04'
		navigation forward of the aid from which they are alongside. Based on this data, a nominal range of 4NM is more than adequate.	34"

Villas Continental Club

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Villas Continental Club Daybeacon 2	7790	STRUCT DEST/HAZ NAV	PA
Villas Continental Club Daybeacon 3	7795	STRUCT DEST	PA
Villas Continental Club Daybeacon 4	7800	STRUCT DEST	PA
Villas Continental Club Daybeacon 5	7805	STRUCT DEST	PA

Volusia

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Volusia Light 23	8820	STRUCT DEST/TRLB	FD

Wadmalaw River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wadmalaw River Light 82	34870	STRUCT MISSING/TRLB	FD
Wadmalaw River Daybeacon 87	34890	STRUCT DEST/TRUB	FD
Wadmalaw River Daybeacon 95	34915	STRUCT MISSING/TRUB	FD
Wadmalaw River Daybeacon 96	34920	STRUCT DEST/TRUB	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
North Edisto River -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.69507° N / 80.22075° W Aid Name: Wadmalaw River Daybeacon 87 LLNR: 34890 Action:	Lat:
Wadmalaw	of Change	CHANGE Action Type Change Aid Subtype The following changes have been approved in the Wadmalaw River to improve aids to navigation	32° 41' 42"
River/ATON/Advanced Notice		reliability. Wadmalaw River DBN 87 (LLNR 34890) and Wadmalaw River DBN 96 (LLNR 34920) will be changed to Wadmalaw River Buoy 87	Lon:
of Change		(Same LLNR) and Wadmalaw River Buoy 96 (Same LLNR). Both aids to navigation are currently destroyed and have a Temporary Unlighted Buoy	-080° 13'
		on station. Both assigned positions are presenting depths of over 28 feet. This depth makes it impossible for a CG asset to rebuild the structures.	15"
		Changing the aids to navigation from fixed to floating allows the CG primary servicing unit the flexibility to relocate the aid to mark safe water.	
North Edisto River -	Advanced Notice	ATON/Advanced Notice of Change Location: 32.66553° N / 80.23956° W Aid Name: Wadmalaw River Daybeacon 96 LLNR: 34920 Action:	Lat:
Wadmalaw	of Change	CHANGE Action Type Change Aid Subtype The following changes have been approved in the Wadmalaw River to improve aids to navigation	32° 39' 56"
River/ATON/Advanced Notice		reliability. Wadmalaw River DBN 87 (LLNR 34890) and Wadmalaw River DBN 96 (LLNR 34920) will be changed to Wadmalaw River Buoy 87	Lon:
of Change		(Same LLNR) and Wadmalaw River Buoy 96 (Same LLNR). Both aids to navigation are currently destroyed and have a Temporary Unlighted Buoy	-080° 14'
		on station. Both assigned positions are presenting depths of over 28 feet. This depth makes it impossible for a CG asset to rebuild the structures.	22"
		Changing the aids to navigation from fixed to floating allows the CG primary servicing unit the flexibility to relocate the aid to mark safe water.	

Walls Cut

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Walls Cut Light 42	35840	STRUCT MISSING/TRLB	FD

Wando River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wando River Daybeacon 23	3390	STRUCT DEST/TRUB	FD

Wappoo Creek

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wappoo Creek Daybeacon 5	34615	STRUCT DEST/TRUB	FD

Wassaw Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wassaw Sound Lighted Buoy 8	5595	MISSING	FD

Waterway Name Not Found

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Channel Daybeacon A1	35920	STRUCT MISSING/TRUB	FD
South Channel Daybeacon A8	35940	STRUCT DMGD	FD
North River Light 178A	36800	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wexford Harbour Daybeacon 3	4420	MSLD SIG	PA
Wexford Harbour Daybeacon 4	4425	MSLD SIG	PA
Wexford Harbour Daybeacon 8	4445	MSLD SIG	PA
Palmetto Dunes Marina West Light 22	4520	DAYMK IMCH	PA

Western Gulf Intracoastal Waterway

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
South Seas Boat Basin Daybeacon 3	55650	HAZ NAV/DAYMK MISSING	PA
Roosevelt Channel Daybeacon 21	55725	HAZ NAV/STRUCT DEST	PA

Whale Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Whale Harbor Channel Daybeacon 6	12720	STRUCT DEST/HAZ NAV/TRLB	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Holiday Isle Marina Daybeacon 1	12765	STRUCT DEST	PA
Holiday Isle Marina Daybeacon 2	12770	STRUCT DEST	PA

White Shells Cut

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
White Shells Temporary Range Rear Light	7325.2	ESTABLISHED	FD

8/6/25, 12:20 PM

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
St Johns River - White Shells	Advanced Notice	White Shells Cut LB 27 (LLNR 7315) will be permanently relocated to 30-23-36.040N/081-28-48.780W. This change calls to relocate (6) lighted	Lat:
Cut/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 36"
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation	Lon:
		for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All	-081° 28'
		positions listed are approximate. Permanent positions will be advertised when the work is completed.	49"
St Johns River - White Shells	Advanced Notice	White Shells Cut LB 29 (LLNR 7316) will be permanently relocated to 30-23-32.900N/081-29-05.750W. This change calls to relocate (6) lighted	Lat:
Cut/ATON/Advanced Notice	of Change	buoys in the White Shells, St. Johns Bluff, Fulton Cutoff, and Blount Island Turning Basin channels of the St. Johns River. These relocations are	30° 23' 33"
of Change		needed as a result of channel deepening and widening, as part of the JaxPort expansion project. The position changes will allow safe navigation	Lon:
		for vessels transiting the St. Johns River. The following aids to navigation are being proposed to be relocated to facilitate this change. All	-081° 29'
		positions listed are approximate. Permanent positions will be advertised when the work is completed.	06"

Wilmington River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Skidaway Island - Wilmington	Bridges	General/Bridges/Conversion From: 2024-10-29 To: 2025-04-27 Location: 32.062044° N / 81.02951° W Bridge Name: CR 787 (Island	Lat:
River/General/Bridges/Conversion		Expressway) Drawbridges Construction on the first of the two high level fixed bridges is complete and now spans the waterway providing 65	32° 03' 43"
		feet of vertical clearance and 100 feet of horizontal clearance between the fender systems. Construction of the second high level fixed bridge	Lon:
		has begun. Work hours are 7 am 7 p.m., Monday through Saturday. During this time, there will be intermittent work inside and outside the	-081° 01'
		federal channel. Mariners operating commercial/recreational vessels greater than 50ft in breath/beam requiring full width of the federal	46"
		navigational channel, are strongly encouraged to call Myrick Marine at 912-210-6778 up to 24 hours in advance, but not less than one hour	
		before arrival to the construction area to coordinate safe passage. Once in the vicinity of the Causton Bluff Bridge, please contact the LONA	
		MYRICK or GRACE MYRICK by VHF to verify your scheduled passage. If applicable, please have your Automated Information System (AIS)	
		energized. In addition, there will be a Myrick Marine safety boat in the vicinity of the construction area for traffic management. The safety	
		boat can be reached on channel 10 or 13. The old bascule bridges have been removed from the waterway. Mariners are reminded to	
		proceed through the construction area at a safe speed, always maintain situational awareness, and monitor VHF radio channel 16 when in	
		the vicinity of the Causton Bluff Bridge. For further information regarding this MSIB, please contact the U.S. Coast Guard MSU Savannah	
		Waterways Management Division at SMB-MSUSavannah-WWM@uscg.mil or the Command Duty Officer at (912) 247-0073.	

Windward Passage

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Johnson Reef Lighted Buoy JD	32680.3	LT EXT	PA

Winyah Bay Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Winyah Bay Range A Front Light	1875	LT EXT	FD
Winyah Bay Range A Rear Light	1880	LT EXT	FD
Winyah Bay Range B Rear Light	1915	STRUCT DEST/HAZ NAV/TRLT	FD
Winyah Bay Channel Lighted Buoy 13	1950	OFF STATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
	Advanced Notice of Change	The Coast Guard Mooring Buoy WB (LLNR 1958) will be permanently relocated to approximate position 33-14-59.160N/079-12-47.580W. The new location will provide a more protected environment from the previous exposed location for CG assets when moored to this buoy.	Lat: 33° 13' 54" Lon: -079° 11' 30"
	Advanced Notice of Change		Lat: 33° 11' 37" Lon: -079° 07' 13"

Winyah Bay Charleston Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Winyah Bay-Charleston Harbor Daybeacon 19	34180	STRUCT MISSING/TRUB	FD
Winyah Bay-Charleston Harbor Daybeacon 90	34410	STRUCT DEST/TRUB	FD

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Charleston, Submerged Land Act (SLA) - Winyah Bay Charleston Harbor/General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Facilities, Barriers, Manmade Reefs, Riprap, Jetties/Dikes From: 2025-02-25 To: 2026-11-13 Location: 32.7602° N / 79.86088° W 32.75736° N / 79.85803° W 32.7566° N / 79.85931° W 32.75944° N / 79.86219° W 32.7602° N / 79.86088° W Cape Romain Contractors will be replacing Fort Sumter and Fort Moultrie Docks and rehabilitate Liberty Square Pier. They will have a crane barge starting March 3, 2025, until May 31, 2026, at Fort Moultrie and crane barges at Fort Sumter and Liberty Square Pier as the project progresses. Estimated completion date of the entire project is 31October 31, 2026. All Vessels should use caution when transiting the work area. The crew at Fort Moultrie will monitor VHF-FM channels 13 and 16.
Sector Charleston, Submerged Land Act (SLA) - Winyah Bay Charleston Harbor/General/MSIB	MSIB	General/MSIB 25170 Three safety zones will be in place August 4th at 8 a.m. through August 8th at 6 p.m., the U.S. Navy will be conducting dive and Unmanned Underwater Vehicle (UUV) operations in conjunction with a Charleston Area Maritime Security Exercise. The safety zones will include all waters within 250 yards of USN dive operations and supporting vessels. The dive operation areas will be west of Drum Island and on each side of the entrance to Charleston Harbor, outside of the commercial channel. The safety zones will be in effect intermittently during daylight hours and while law enforcement vessels are on-scene. Safety boats can be contacted via VHF Channel 65 to make any necessary passing arrangements. Mariners should use caution and maintain safe speeds while transiting the area.For questions or concerns regarding this MSIB, please contact the Sector Charleston 24-hour Command Center at (843) 740-7050.

Withlacoochee River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Withlacoochee River Entrance Daybeacon 8	29410	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 16	29455	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 26	29520	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 29	29535	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 30	29545	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Daybeacon 31	29550	STRUCT MISSING/TRUB	FD
Withlacoochee River Entrance Light 32	29555	STRUCT MISSING/TRLB	FD
Withlacoochee River Entrance Daybeacon 32B	29565	STRUCT DEST/TRUB	FD

https://www.navcen.uscg.gov/msi 73/73