

Local Notice to Mariners for Arctic District 04/29/2026

Alitak Bay.

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Alitak Light	26920	DAYMK MISSING	FD

Bechevin Bay.

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bechevin Bay Entrance Buoy BB	27250	MISSING	FD
Bechevin Bay Buoy 1	27255	MISSING	FD
Bechevin Bay Buoy 2	27260	MISSING	FD
Bechevin Bay Buoy 3	27265	DAYMK MISSING	FD
Bechevin Bay Buoy 4	27270	MISSING	FD
Bechevin Bay Buoy 5	27275	MISSING	FD
Bechevin Bay Buoy 5	27275	MISSING	FD
Bechevin Bay Buoy 8	27290	MISSING	FD
Isanotski Strait Light 3	27410	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Bechevin Bay/General/Miscellaneous	Miscellaneous	IN THE VICINITY OF BECHEVIN BAY AND FALSE PASS: LOCAL KNOWLEDGE AND EXPERIENCE IS REQUIRED TO TRANSIT THE AREA DUE TO HIGH NUMBER OF MISSING AND DISCREPANT AIDS TO NAVIGATION IN THE WATERWAY: BECHEVIN BAY BUOY BB (LLNR 27250), BECHEVIN BAY BUOY 1 (LLNR 27255), BECHEVIN BAY BUOY 2 (LLNR 27260), BECHEVIN BAY BUOY 3 (LLNR 27265), BECHEVIN BAY BUOY 4 (LLNR 27270), BECHEVIN BAY BUOY 5 (LLNR 27275), AND BECHEVIN BAY BUOY 8 (LLNR 27290)ARE ALL REPORTED MISSING. ISANOTSKI STRAIT LIGHT 3 (LLNR 27410) IS EXTINGUISHED. MARINERS ARE ADVISED TO USE EXTREME CAUTION WHEN NAVIGATING IN THE AREA.	

Behm Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Knudson Cove Daybeacon	22315	DBD DEST	FD

Bering Sea Eastern Part

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 62.5925° N / 164.908° W A 6' by 6' by 15' metal tower was destroyed and partially submerged in this position in June of 2021. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Western Alaska and U.S. Arctic at 907-428-4100.	Lat: 62° 35' 33" Lon: -164° 54' 29"
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.15927° N / 166.58292° E Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 33" Lon: 166° 34' 59"

Captains Bay.

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bailey Ledge Light	27505	LT EXT/STRUCT DMGD	FD

Chatham Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kenasnow Rocks Lighted Buoy 2	24040	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
-------	-------------	-------------	----------

Sector Southeast Alaska, Submerged Land Act (SLA) - Chatham Strait/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 57.84975° N / 135.02875° W The F/V BAILEY BAY sank in this position in approximately 30 feet of water in October of 2022. The F/V BAILEY BAY is a 33' fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel.	Lat: 57° 50' 59" Lon: -135° 01' 44"
---	-----------------------	--	--

Chilkoot Inlet

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Lynn Canal - Chilkoot Inlet/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 59.24033° N / 135.43087° W An anchor and 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor.	Lat: 59° 14' 25" Lon: -135° 25' 51"

Clarence Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Narrow Point Light	22455	LT EXT	FD
Bushy Island Light	22510	LT EXT	FD
Snow Passage Lighted Buoy SP	22515	LT EXT	FD
Bay Point Daybeacon BP	22525	DAYMK DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Dixon Entrance - Clarence Strait/General/Miscellaneous	Miscellaneous	The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of Snow Passage, Clarence Strait, and Thorne Bay. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects. Any interested company or individual wishing to provide comments or participate in a user survey may do so at https://forms.osi.apps.mil/r/ZAUvnfa1eA or contact USCG waterways division at: USCG Sector Southeast Alaska Waterways Management Division P.O. Box 25517 Juneau, AK 99801 (907) 463-2715 SEAKWaterways@uscg.mil	

District 13, Oceanic boundary to EEZ

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Miscellaneous	Miscellaneous	Buoy Adrift, Hull Number 2.6D62 (46415) Approx. 247 NM WSW of Federick is. BC, Canada	Lat: 52° 58' 17" Lon: -139° 48' 33"

Dixon Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lord Rock Light	21835	LT EXT	FD

Dry Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Pass Daybeacon 3	24790	STRUCT DEST	FD

Eastern Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mitchell Rock Daybeacon	24957	STRUCT DEST	FD

Elfin Cove

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elfin Cove Daybeacon 5	24260	STRUCT DEST	FD

Erlington Passage**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9911° N / 148.0963° W Submerged Data Mooring Name: EP03 Water Depth: 207' Top Float Depth: 190' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 28" Lon: -148° 05' 47"
Sector Anchorage, Submerged Land Act (SLA) - Erlington Passage/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9951° N / 148.101° W Submerged Data Mooring Name: EP04 Water Depth: 276' Top Float Depth: 259' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 42" Lon: -148° 06' 04"

Frederick Sound**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Chatham Strait - Frederick Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 56.91133° N / 132.94483° W A 47 foot wood fishing vessel was reported sunk in this position in 2023.	Lat: 56° 54' 41" Lon: -132° 56' 41"

Gastineau Channel**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Sheep Creek Light 2	23665	LT EXT	FD
Rock Dump Lighted Buoy 2A	23685	LT EXT	FD
Rock Dump Lighted Buoy 2A	23685	LT EXT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Sheep Creek Light 2	23665	WATCHING PROPERLY	FD	2026-04-20
Juneau Isle Light	23675	WATCHING PROPERLY	FD	2026-04-20
Mendenhall Bar Channel Buoy 7	23730	WATCHING PROPERLY	FD	2026-04-21

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Stephens Passage - Gastineau Channel/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 58.27098° N / 134.37045° W A 22' white sailboat sank in this position. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 58° 16' 16" Lon: -134° 22' 14"

Geese Channel**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Aiaktalik Island Light 5	26910	DAYMK MISSING	FD
Aiaktalik Island Light 5	26910	DAYMK MISSING	FD

Glacier Bay**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Icy Strait - Glacier Bay/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-11-12 To: 2026-11-12 Location: 58.67719° N / 136.16049° W Submerged Data Mooring Name: Glacier Bay Oceanographic Mooring Water Depth: 1017' Top Float Depth: 82' POC: Mathew Cahill Phone: 907-697-2230 Email: mathew_cahill@nps.gov	Lat: 58° 40' 38" Lon: -136° 09' 38"

Icy Strait**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
-------	-------------	-------------	----------

Cross Sound - Icy Strait/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 58.30225° N / 135.37292° W A dangerous rock was reported in this position. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	Lat: 58° 18' 08" Lon: -135° 22' 23"
--	-----------------------	--	--

Kachemak Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sixty Foot Rock Light	26190	DAYMK DMGD	FD
Sixty Foot Rock Light	26190	DAYMK DMGD	FD
Halibut Point Daybeacon	26245	STRUCT DEST	FD

Kake Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kake Entrance Light 2	23315	LT EXT	FD

Keku Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Keku Strait Entrance Light	23305.100000000002	STRUCT DEST	FD
Keku Strait Daybeacon 2	23305.2	STRUCT DEST	FD
Keku Strait Daybeacon 4	23305.3	STRUCT DEST	FD
Keku Strait Daybeacon 15	23306	STRUCT DEST	FD
Keku Strait Daybeacon 18	23306.2	STRUCT DEST	FD
Keku Strait Daybeacon 25	23306.7	STRUCT DEST	FD
Keku Strait Daybeacon 37	23307.600000000002	STRUCT DEST	FD
Keku Strait Daybeacon 39	23307.7	STRUCT DEST	FD
Keku Strait Daybeacon 41	23307.8	STRUCT DEST	FD

Kuskokwim River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Yukon River South Entrance Light	27860	DAYMK MISSING	FD
Okwega Pass Light OP	27872	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.78583° N / 161.692° W The barge SHANKS ARK was reported sunk and abandoned in this position in March of 2017. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no maritime traffic is present.	Lat: 60° 47' 09" Lon: -161° 41' 31"

Lisianski Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lisianski Inlet Daybeacon 4	24300	STRUCT DEST	FD

Lynn Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sentinel Island Light	23850	LT EXT	FD
Point Sherman Light	23865	LT EXT	FD
Funter Bay Entrance Light 1	23975	LT EXT	FD

Marmot Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Shakmanof Point Light	26495	LT EXT	FD
Hanin Rock Light	26560	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 57.78583° N / 152.40568° W A dangerous rock was reported in this position approximately 20' off of the K&I Pier. This rock was reported struck by a vessel with a 16' draft at low tide, approximately +.085'. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	Lat: 57° 47' 09" Lon: -152° 24' 20"

Naknek River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kvichak Bay - Naknek River/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2025-04-26 Location: 58.71287° N / 157.03408° W A large metal ramp was reported to be visible during low tide and completely submerged during high tide.	Lat: 58° 42' 46" Lon: -157° 02' 03"

Nichols Passage

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Clarence Strait - Nichols Passage/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 55.05° N / 131.64883° W The F/V JACI GRACE sank in Canoe Cove in this position. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 55° 03' 00" Lon: -131° 38' 56"

Ogden Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dippy Island Rock Daybeacon 3	25355	STRUCT DEST	FD

Orca Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hanks Island Rock Light 5	25550	STRUCT DEST	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Hanks Island Rock Light 5	25550	TRLB	FD
Hanks Island Rock Light 5	25550	ESTABLISHED	FD

Orca Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Orca Inlet Channel Light 12	25575	STRUCT DEST	FD
NOAA Data Lighted Buoy 46060	25646	ADRIFT	FD

Passage Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Whittier Breakwater Light 1	25900	LT EXT/DBD DEST/STRUCT DEST	FD

Port Alexander

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Alexander Light	23465	REDUCED INT	FD

Port Graham

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2025-11-04 To: 2026-05-03 Location: 59-22-23.484N/151-52-33.060W Awash unlit pile. Area is shallower than surrounding shoal. Danger is visible at +3 tide. At MLLW danger rises approximately 3 ft above the water. Isolated danger for small craft transiting between marked channel and shore at higher tides when danger is submerged. POC: LTJG Liam Long Liam.M.Long@uscg.mil	Lat: 59° 22' 23" Lon: -151° 52' 33"

Port Valdez

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Valdez Servs Dock Lights (2)	25822	OFF STA	PA

Portage Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Portage Pass Daybeacon 11	23355	STRUCT DEST	FD

Portland Canal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Reef Island Light	21875	LT EXT	FD

Prince William Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Schooner Rock Light 1	25525	LT EXT	FD
Lone Island Shoal Lighted Bell Buoy 2	25855	LT EXT	FD
Lone Island Shoal Lighted Bell Buoy 2	25855	LT EXT	FD
Lone Island Shoal Lighted Bell Buoy 2	25855	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.61318° N / 147.19993° W Submerged Data Mooring Name: PWSSC-15 Water Depth: 722' Top Float Depth: 197' ***Surfaces twice daily*** POC: Dr. Rob Campbell Phone: 907-424-5800 Email: rcampbell@pwssc.org	Lat: 60° 36' 47" Lon: -147° 11' 60"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3425° N / 146.7304° W Submerged Data Mooring Name: H01 Water Depth: 98' Top Float Depth: 66' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 33" Lon: -146° 43' 49"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.34° N / 146.742° W Submerged Data Mooring Name: H02 Water Depth: 879' Top Float Depth: 791' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 24" Lon: -146° 44' 31"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3349° N / 146.7329° W Submerged Data Mooring Name: HB Water Depth: 830' Top Float Depth: 747' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 06" Lon: -146° 43' 58"

Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3352° N / 146.7661° W Submerged Data Mooring Name: H04 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 07" Lon: -146° 45' 58"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3328° N / 146.7785° W Submerged Data Mooring Name: H05 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 58" Lon: -146° 46' 43"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3302° N / 146.7903° W Submerged Data Mooring Name: H06 Water Depth: 896' Top Float Depth: 806' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 49" Lon: -146° 47' 25"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3278° N / 146.8023° W Submerged Data Mooring Name: H07 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 40" Lon: -146° 48' 08"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3245° N / 146.8159° W Submerged Data Mooring Name: H08 Water Depth: 935' Top Float Depth: 842' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 28" Lon: -146° 48' 57"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.322° N / 146.8297° W Submerged Data Mooring Name: H09 Water Depth: 1,007' Top Float Depth: 906' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 19" Lon: -146° 49' 47"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3198° N / 146.8418° W Submerged Data Mooring Name: H10 Water Depth: 1,060' Top Float Depth: 954' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 11" Lon: -146° 50' 30"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3123° N / 146.8776° W Submerged Data Mooring Name: H13 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 44" Lon: -146° 52' 39"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3098° N / 146.889° W Submerged Data Mooring Name: H14 Water Depth: 522' Top Float Depth: 470' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 35" Lon: -146° 53' 20"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3078° N / 146.8999° W Submerged Data Mooring Name: H15 Water Depth: 276' Top Float Depth: 244' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 28" Lon: -146° 53' 60"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.302° N / 146.8928° W Submerged Data Mooring Name: HC Water Depth: 449' Top Float Depth: 404' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 07" Lon: -146° 53' 34"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3168° N / 146.8538° W Submerged Data Mooring Name: H11 Water Depth: 1,135' Top Float Depth: 1,022' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 00" Lon: -146° 51' 14"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.309° N / 146.9092° W Submerged Data Mooring Name: H16 Water Depth: 85' Top Float Depth: 53' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 32" Lon: -146° 54' 33"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.2997° N / 146.9056° W Submerged Data Mooring Name: HD Water Depth: 151' Top Float Depth: 119' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 17' 59" Lon: -146° 54' 20"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3376° N / 146.7544° W Submerged Data Mooring Name: H03 Water Depth: 876' Top Float Depth: 860' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 15" Lon: -146° 45' 16"

Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3148° N / 146.8653° W Submerged Data Mooring Name: H12 Water Depth: 1,194' Top Float Depth: 1,079' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 53" Lon: -146° 51' 55"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 60.50373° N / 146.51368° W A submerged mooring was reported lost in 315 feet of water in this position in 02/23. This mooring may be an obstruction to operations on the sea floor.	Lat: 60° 30' 13" Lon: -146° 30' 49"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-28 To: 2026-10-28 Location: 61.13408° N / 147.54442° W An uncharted and dangerous rock was reported in this position in June or 2019.	Lat: 61° 08' 03" Lon: -147° 32' 40"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.796° N / 148.05517° W The F/V SONG II sank in this position in August 2018.	Lat: 60° 47' 46" Lon: -148° 03' 19"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2024-10-28 To: 2029-10-27 Location: 61.17206° N / 148.475° W 61.17074° N / 148.05752° W 61.03802° N / 148.05752° W 60.93011° N / 148.48324° W 61.17206° N / 148.475° W The State of Alaka is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm and has the potential to create a tsunami if/when a landslide is generated that impacts the water in Barry Arm. If/when this occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following an event. The geologic makeup of the area is similar to Alaskan locations where two previous landslides caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of the potential results of a slide. Additional information is available at https://dggs.alaska.gov/hazards/barry-arm-landslide.html .	

Resurrection Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Thumb Cove Light	26000	DAYMK MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
4th of July Channel LT 1	26005	STRUCT DEST	PA
Seward Marine Dock Light	26010	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Resurrection Bay/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.85045° N / 149.50063° W Submerged Data Mooring Name: GAK1-24 Water Depth: 860' Top Float Depth: 65' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 51' 02" Lon: -149° 30' 02"

Revillagigedo Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Twin Islands Light Tl	21945	RBN IMCH	FD

Salisbury Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Brad Rock Buoy 3	25175	LT EXT	FD

Sector Anchorage, Exclusive Economic Zone (EEZ)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. George Harbor Entrance Light 1	27827	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 75.10005° N / 168.00007° W Submerged Data Mooring Name: AIM16-1 Water Depth: 535' Top Float Depth: 142' POC: Dr. Humfrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 75° 06' 00" Lon: -168° 00' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2025-04-01 Location: 66.61013° N / 164.63417° W Submerged Data Mooring Name: XA23-ST-KS04 Water Depth: 49' Top Float Depth: 42' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 36' 36" Lon: -164° 38' 03"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 62.20477° N / 174.67642° W Submerged Data Mooring Name: AL23-AU-M08 Water Depth: 230' Top Float Depth: 197' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 62° 12' 17" Lon: -174° 40' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 58.26188° N / 163.55735° W Submerged Data Mooring Name: 24KUM-2A Water Depth: 131' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 58° 15' 43" Lon: -163° 33' 26"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2025-04-13 Location: 71.67308° N / 154.9998° W Submerged Data Mooring Name: BCE-22 Water Depth: 384' Top Float Depth: 62' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 40' 23" Lon: -154° 59' 59"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.73445° N / 155.164° W Submerged Data Mooring Name: BCC-22 Water Depth: 951' Top Float Depth: 66' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 44' 04" Lon: -155° 09' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.79635° N / 155.34687° W Submerged Data Mooring Name: BCW-22 Water Depth: 554' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 47' 47" Lon: -155° 20' 49"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 70.834° N / 163.126° W Submerged Data Mooring Name: AL24-AU-IC01 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 02" Lon: -163° 07' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.754° N / 154.475° W Submerged Data Mooring Name: AL24-AU-BF02 Water Depth: 344' Top Float Depth: 312' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 45' 14" Lon: -154° 28' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.30823° N / 152.13573° W Submerged Data Mooring Name: AON-BS1 Water Depth: 554' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 18' 30" Lon: -152° 08' 09"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3941° N / 152.05118° W Submerged Data Mooring Name: AON-BS3a Water Depth: 479' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 23' 39" Lon: -152° 03' 04"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3968° N / 152.0032° W Submerged Data Mooring Name: AON-BS3b Water Depth: 502' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 23' 48" Lon: -152° 00' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.21467° N / 164.2485° W Submerged Data Mooring Name: AL23-AU-IC02 Water Depth: 141' Top Float Depth: 108' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 53" Lon: -164° 14' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.831° N / 166.018° W Submerged Data Mooring Name: AL24-AU-IC03 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 49' 52" Lon: -166° 01' 05"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.204° N / 157.999° W Submerged Data Mooring Name: AL24-AU-PB01 Water Depth: 157' Top Float Depth: 131' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 14" Lon: -157° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59952° N / 161.50698° W Submerged Data Mooring Name: CEM1-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 58" Lon: -161° 30' 25"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59965° N / 161.52747° W Submerged Data Mooring Name: CEM2-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 59" Lon: -161° 31' 39"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.58373° N / 161.49948° W Submerged Data Mooring Name: CEO1-24 Water Depth: 154' Top Float Depth: 111' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 01" Lon: -161° 29' 58"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.60063° N / 161.5408° W Submerged Data Mooring Name: CEO2-24 Water Depth: 151' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 36' 02" Lon: -161° 32' 27"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 66.327° N / 168.949° W Submerged Data Mooring Name: A3-24 Water Depth: 190' Top Float Depth: 23' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 66° 19' 37" Lon: -168° 56' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.746° N / 168.2625° W Submerged Data Mooring Name: A4-24 Water Depth: 161' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 65° 44' 46" Lon: -168° 15' 45"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.12937° N / 168.313° W Submerged Data Mooring Name: AL24-AU-PC01 Water Depth: 561' Top Float Depth: 535' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 07' 46" Lon: -168° 18' 47"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 64.858° N / 168.448° W Submerged Data Mooring Name: AL24-AU-NM01 Water Depth: 144' Top Float Depth: 118' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 64° 51' 29" Lon: -168° 26' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.16° N / 166.582° W Submerged Data Mooring Name: AL24-AU-BS10 Water Depth: 384' Top Float Depth: 358' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 36" Lon: -166° 34' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 61.084° N / 170.264° W Submerged Data Mooring Name: AL24-AU-BS11 Water Depth: 161' Top Float Depth: 135' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 61° 05' 02" Lon: -170° 15' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.702° N / 152.187° W Submerged Data Mooring Name: GA24-AU-SE01 Water Depth: 423' Top Float Depth: 384' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 42' 07" Lon: -152° 11' 13"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.04167° N / 145.17° W Submerged Data Mooring Name: UWAPL24 Water Depth: Unknown Top Float Depth: Surface POC: Joe Talbert Phone: 907-409-4627 Email: talbertj@uw.edu	Lat: 50° 02' 30" Lon: -145° 10' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.0267° N / 148.6707° W Submerged Data Mooring Name: GEO2-24 Water Depth: 758' Top Float Depth: 82' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 01' 36" Lon: -148° 40' 15"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.02322° N / 144.36115° W Submerged Data Mooring Name: FLMA Water Depth: 9,361' Top Float Depth: 68' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 01' 24" Lon: -144° 21' 40"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.37608° N / 144.51397° W Submerged Data Mooring Name: FLMB Water Depth: 9,523' Top Float Depth: 68' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 22' 34" Lon: -144° 30' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.1143° N / 144.91743° W Submerged Data Mooring Name: HYPM Water Depth: 9,664' Top Float Depth: 342' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 06' 51" Lon: -144° 55' 03"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 77.49333° N / 140.18° W Submerged Data Mooring Name: AMOS-VLF-1 Water Depth: 12,264' Top Float Depth: 230' POC: Craig Lee Email: craiglee@uw.edu	Lat: 77° 29' 36" Lon: -140° 10' 48"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.41333° N / 142.47° W Submerged Data Mooring Name: AMOS-C Water Depth: 12,326' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu	Lat: 76° 24' 48" Lon: -142° 28' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.14667° N / 145.28333° W Submerged Data Mooring Name: AMOS-NW Water Depth: 12,441' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 76° 08' 48" Lon: -145° 16' 60"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 75.77333° N / 141.51333° W Submerged Data Mooring Name: AMOS-NE Water Depth: 12,251' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 75° 46' 24" Lon: -141° 30' 48"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.875° N / 143.08667° W Submerged Data Mooring Name: AMOS-SE Water Depth: 12,241' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 74° 52' 30" Lon: -143° 05' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.58833° N / 145.545° W Submerged Data Mooring Name: AMOS-A Water Depth: 12,339' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu	Lat: 74° 35' 18" Lon: -145° 32' 42"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.52292° N / 161.94227° W Submerged Data Mooring Name: NAP-23t Water Depth: 5,528' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 74° 31' 23" Lon: -161° 56' 32"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 68.98622° N / 105.88383° W Submerged Data Mooring Name: ACW16-30 Water Depth: 242' Top Float Depth: 231' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 68° 59' 10" Lon: -105° 53' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33385° N / 133.73948° W Submerged Data Mooring Name: IBO16-1a Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 20' 02" Lon: -133° 44' 22"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33392° N / 133.74087° W Submerged Data Mooring Name: IBO16-1b Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 20' 02" Lon: -133° 44' 27"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.98932° N / 133.74393° W Submerged Data Mooring Name: IBO16-2 Water Depth: 365' Top Float Depth: 146' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 59' 22" Lon: -133° 44' 38"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.0589° N / 133.7153° W Submerged Data Mooring Name: IBO16-9a Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 03' 32" Lon: -133° 42' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.05835° N / 133.71562° W Submerged Data Mooring Name: IBO16-9b Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 03' 30" Lon: -133° 42' 56"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.77472° N / 137.04595° W Submerged Data Mooring Name: SIC16-11 Water Depth: 117' Top Float Depth: 107' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 69° 46' 29" Lon: -137° 02' 45"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.65473° N / 138.92132° W Submerged Data Mooring Name: HI16 Water Depth: 134' Top Float Depth: 125' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 69° 39' 17" Lon: -138° 55' 17"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.198° N / 174.663° W Submerged Data Mooring Name: 24BS-8A Water Depth: 242' Top Float Depth: 59' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 11' 53" Lon: -174° 39' 47"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.205° N / 174.676° W Submerged Data Mooring Name: 24BSP-8A Water Depth: 242' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 18" Lon: -174° 40' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.2012° N / 174.6819° W Submerged Data Mooring Name: 24BST-8A Water Depth: 242' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 04" Lon: -174° 40' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.202° N / 174.66° W Submerged Data Mooring Name: 24BSITAER-8A Water Depth: 242' Top Float Depth: 66' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 07" Lon: -174° 39' 36"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 70.837° N / 163.126° W Submerged Data Mooring Name: 24CKP-1A Water Depth: 148' Top Float Depth: 115' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 70° 50' 13" Lon: -163° 07' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2157° N / 164.2494° W Submerged Data Mooring Name: 24CKP-2A Water Depth: 148' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 57" Lon: -164° 14' 58"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.831° N / 166.0145° W Submerged Data Mooring Name: 24CKP-3A Water Depth: 144' Top Float Depth: 121' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 49' 52" Lon: -166° 00' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.0453° N / 160.48823° W Submerged Data Mooring Name: 24CKP-4A Water Depth: 167' Top Float Depth: 135' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 02' 43" Lon: -160° 29' 18"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2082° N / 158° W Submerged Data Mooring Name: 24CKP-5A Water Depth: 167' Top Float Depth: 144' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 30" Lon: -158° 00' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.47007° N / 156.5697° W Submerged Data Mooring Name: 24CKP-9A Water Depth: 3,054' Top Float Depth: 886' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 28' 12" Lon: -156° 34' 11"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 67.91° N / 168.181° W Submerged Data Mooring Name: 24CKP-12A Water Depth: 190' Top Float Depth: 141' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 67° 54' 36" Lon: -168° 10' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.3099° N / 167.272° W Submerged Data Mooring Name: 24CKP-15A Water Depth: 161' Top Float Depth: 131' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 18' 36" Lon: -167° 16' 19"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 56.86687° N / 164.04302° W Submerged Data Mooring Name: 25BSP-2A Water Depth: 72 m Top Float Depth: 62 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 56° 52' 01" Lon: -164° 02' 35"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.08299° N / 163.50042° W Submerged Data Mooring Name: AL25_AU_UN04 Water Depth: 100 m Top Float Depth: 87 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 04' 59" Lon: -163° 30' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-06 To: 2027-05-06 Location: 57.87733° N / 168.88367° W Submerged Data Mooring Name: 25BSP-4A Water Depth: 72 m Top Float Depth: 61 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 52' 38" Lon: -168° 53' 01"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.12698° N / 168.31173° W Submerged Data Mooring Name: AL25_AU_PC01 Water Depth: 169 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 07' 37" Lon: -168° 18' 42"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 55.572° N / 154.975° W Submerged Data Mooring Name: GA24_AU_CR01 Water Depth: 400 m Top Float Depth: 70 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 55° 34' 19" Lon: -154° 58' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 53.971° N / 161.663° W Submerged Data Mooring Name: GA24-AU-SN01 Water Depth: 436 m Top Float Depth: 86 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 58' 16" Lon: -161° 39' 47"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 56.15927° N / 166.58292° W Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 33" Lon: -166° 34' 59"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25-AU-PO01 Water Depth: 116 m Top Float Depth: 105 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 33' 59" Lon: -149° 59' 28"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 64.85793° N / 168.44803° W Name: AL25_AU_NM01 Water Depth: 44 m Top Float Depth: 34 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 64° 51' 29" Lon: -168° 26' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.75395° N / 154.47518° W Name: AL25_AU_BF02 Water Depth: 105 m Top Float Depth: 99 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 45' 14" Lon: -154° 28' 31"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 71.83082° N / 166.01868° W Name: AL25_AU_IC03 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 49' 51" Lon: -166° 01' 07"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: AL25_AU_IC01 Position: (70.83413, -163.12628) water depth 45m, top of float at 39m (recovered AL24_AU_IC01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 03" Lon: -163° 07' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring AL25_AU_PB01 Position: (71.20405, -157.99865) water depth 49m, top of float at 41m (recovered AL24_AU_PB01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 15" Lon: -157° 59' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SN01 Position: (53.96871, -161.66364) water depth 431 m, top of float at 83 m (recovered GA24_AU_SN01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 58' 07" Lon: -161° 39' 49"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSP-8A Position: (62.19812, -174.66308) water depth 74m, top of float 61m (recovered 24BSP-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 11' 53" Lon: -174° 39' 47"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSST-8A Position: (62.20464, -174.6760) water depth 73m, top of float 26m (recovered 24BSST-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 17" Lon: -174° 40' 34"

General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSR-8A Position: (62.20115,-174.6823) water depth 74, top of float 20m (recovered 24BSR-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 04" Lon: -174° 40' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-12A Position: (67.90664,-168.18142) water depth 59m, top of float 44m (recovered 24CKP-12A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 67° 54' 24" Lon: -168° 10' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-1A Position: (70.8364,-163.1189) water depth 45m, top of float 35m (recovered 24CKP-1A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 70° 50' 11" Lon: -163° 07' 08"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-2A Position: (71.21562,-164.24901) water depth 42m, top of float 33m (recovered 24CKP-2A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 56" Lon: -164° 14' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-3A Position: (71.82707,-166.01816) water depth 45m, top of float 37m (recovered 24CKP-3A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 49' 37" Lon: -166° 01' 05"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-4A Position: (71.04505,-160.48967) water depth 52m, top of float 40m (recovered 24CKP-4A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 02' 42" Lon: -160° 29' 23"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-9A Position: (72.47871, -156.74174) water depth 920m, top of float 270m (recovered 24CKP-9A approx 4 nm to the E) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 28' 43" Lon: -156° 44' 30"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-15A Position: (72.30807,-167.27204) water depth 49m, top of float 41m (recovered 24CKP-15A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 18' 29" Lon: -167° 16' 19"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	General/Naval Activity From: 2026-02-23 To: 2026-08-28 Location: 58-43-26.400N/150-46-54.588W HAZARDOUS OPERATIONS-A GUNNERY AND PYROTECHNICS EXERCISE WILL BE CONDUCTED IN APPROX. POSITION 58-43.44N 150-46.91W, APPROXIMATELY 29NM SOUTH FROM GORE POINT, FROM 27 1600 FEB 26 TO 27 2300 FEB 26 UTC WHICH IS 0700 TO 1400 ALASKA TIME, 27 FEB 26. DANGER RADIUS 20,000 YDS, DANGER ALTITUDE 17,000 FT.	Lat: 58° 43' 26" Lon: -150° 46' 55"

Sector Anchorage, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Pankof Breaker Buoy 1	1205	OFF STATION	FD
Cape Etolin Light	1287	DAYMK MISSING	FD
East Chugach Light	26065	LT EXT	FD
Perl Island Light 1	26070	MISSING	FD
Perl Rock Light	26095	LT EXT	FD
Kalgin Island Light	26300	DBD DEST	FD
Smoky Point Light	27760	DAYMK MISSING	FD
Unalakleet River Buoys (About 6)	27915	Status Unreported	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.2289° N / 162.16302° W Submerged Data Mooring Name: XA23-ST-KS07 Water Depth: 46' Top Float Depth: 39' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 13' 44" Lon: -162° 09' 47"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 57.72427° N / 152.28335° W Submerged Data Mooring Name: 23CB-1A Water Depth: 545' Top Float Depth: 472' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 43' 27" Lon: -152° 17' 00"

Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.91099° N / 149.3493° W Submerged Data Mooring Name: GAKOA Water Depth: 171' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: Natalie Monacci Phone: 907-474-7956 Email: nmonacci@alaska.edu	Lat: 59° 54' 40" Lon: -149° 20' 57"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9247° N / 147.8105° W Submerged Data Mooring Name: M01 Water Depth: 295' Top Float Depth: 263' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 55' 29" Lon: -147° 48' 38"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9308° N / 147.8179° W Submerged Data Mooring Name: M02 Water Depth: 446' Top Float Depth: 401' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 55' 51" Lon: -147° 49' 04"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9363° N / 147.8253° W Submerged Data Mooring Name: M03 Water Depth: 509' Top Float Depth: 458' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 11" Lon: -147° 49' 31"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9426° N / 147.8326° W Submerged Data Mooring Name: M04 Water Depth: 577' Top Float Depth: 519' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 33" Lon: -147° 49' 57"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9481° N / 147.8397° W Submerged Data Mooring Name: M05 Water Depth: 640' Top Float Depth: 576' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 53" Lon: -147° 50' 23"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9807° N / 147.8811° W Submerged Data Mooring Name: M11 Water Depth: 472' Top Float Depth: 425' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 51" Lon: -147° 52' 52"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9753° N / 147.8892° W Submerged Data Mooring Name: MD Water Depth: 614' Top Float Depth: 553' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 31" Lon: -147° 53' 21"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.1149° N / 148.2353° W Submerged Data Mooring Name: BP07 Water Depth: 171' Top Float Depth: 154' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 06' 54" Lon: -148° 14' 07"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0464° N / 148.1247° W Submerged Data Mooring Name: POWP05 Water Depth: 315' Top Float Depth: 299' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 02' 47" Lon: -148° 07' 29"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0465° N / 148.12982° W Submerged Data Mooring Name: POWP06 Water Depth: 154' Top Float Depth: 138' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 02' 47" Lon: -148° 07' 47"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9808° N / 148.0319° W Submerged Data Mooring Name: LP01 Water Depth: 112' Top Float Depth: 95' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 51" Lon: -148° 01' 55"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9847° N / 148.03698° W Submerged Data Mooring Name: LP02 Water Depth: 144' Top Float Depth: 128' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 05" Lon: -148° 02' 13"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9537° N / 147.8473° W Submerged Data Mooring Name: M06 Water Depth: 702' Top Float Depth: 686' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 13" Lon: -147° 50' 50"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9643° N / 147.8605° W Submerged Data Mooring Name: M08 Water Depth: 758' Top Float Depth: 741' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 51" Lon: -147° 51' 38"

Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9691° N / 147.8668° W Submerged Data Mooring Name: M09 Water Depth: 643' Top Float Depth: 617' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 09" Lon: -147° 52' 00"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9752° N / 147.8739° W Submerged Data Mooring Name: M10 Water Depth: 784' Top Float Depth: 768' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 31" Lon: -147° 52' 26"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 54.12848° N / 165.77305° W An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in this position on the sea floor in approximately 138 feet. This anomaly has not been positively identified and mariners are requested to transit the area with caution.	Lat: 54° 07' 43" Lon: -165° 46' 23"
General/Hazards To Navigation/Hazards	Hazards To Navigation	Cold temperatures are causing a significant buildup of ice in the Upper Cook Inlet that poses extreme danger to vessels. To assist mariners, the Coast Guard Sector Western Alaska COTP is implementing the Operating Guidelines for Ice Conditions for Upper Cook Inlet, effective December 09, 2025. All vessels scheduled to arrive in areas north of Homer, AK in the Cook Inlet must submit a voyage plan no less than 24 hours prior to arrival at the Kachemak Bay Pilot Station. The Pre-Arrival Checklist, enclosure (1), Exam Form, enclosure (2), and Voyage Plan, enclosure (3) should be used as necessary and are also attached to the Ice Guidelines as enclosures and can be accessed via the USCG Captain of the Port. While use of the voyage plan template is not mandatory, your voyage plan must include all information listed in the template. Voyage plans must be emailed to sectorwesternak@uscg.mil Based on information in your voyage plan, we will determine if the vessel needs an exam prior to entry into Cook Inlet and will notify the submitter if an exam is required. Vessel agents can coordinate with Marine Safety Detachment Homer at (907) 690-2098	
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Hazards	Hazards To Navigation	ALASKA-COOK INLET- NAVIGATION ADVISORY THE CAPTAIN OF THE PORT WESTERN ALASKA HAS ESTABLISHED THE 2025-2026 COOK INLET ICE GUIDELINES. THESE GUIDELINES WERE ACTIVATED IN DECEMBER AND WILL REMAIN IN EFFECT UNTIL ICE CONDITIONS IMPROVE. MARINERS ARE TO NAVIGATE WITH CAUTION WHILE TRANSITING NEAR THE COOK INLET DURING THE ICE SEASON. ANY CONCERNED TRAFFIC CAN CONTACT THE US COAST GUARD WESTERN ALASKA AND US ARCTIC COMMAND CENTER AT 907-428-4100 OR VHF CHANNEL 16	
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	ALASKA – SOUTHCENTRAL – COOK INLET – PORT OF ALASKA – MARINE CONSTRUCTION Dredging, demolition, pile driving, wharf construction, and other miscellaneous marine construction will be conducted at the Port of Alaska from 01 April through 31 October 2026. Three temporary mooring buoys with flashing white lights will be established northwest of Terminal 3 in positions: 61-15-05.4N 149-53-45.4W 61-15-14.3N 149-53-23.0W 61-15-25.9N 149-53-39.2W During operations, VHF-FM channel 8 will be monitored. Derrick barges will have anchors deployed and submerged anchor cables will be marked by crown buoys over each submerged anchor. Mariners are advised to maintain a minimum closest point of approach of 1,000 feet, transit at slow speed, and exercise caution when transiting this area. For additional information, mariners can contact the U.S. Coast Guard on VHF-FM channel 16, by phone to Sector Western Alaska and U.S. Arctic Command Center at 907-428-4100, or by email at SECTORWESTERNAK@USCG.MIL	
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 70.83413° N / 154.47628° W Name: AL25_AU_JC01 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 03" Lon: -154° 28' 35"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKFPR-2A Position: (71.21072,-164.27086) water depth 42m, float on surface (New surface buoy with flashing yellow light every 4s) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 60° 34' 29" Lon: -150° 32' 46"
General/Miscellaneous	Miscellaneous	ALASKA-SOUTHCENTRAL-COOK INLET THE FOLLOWING NAVIGATIONAL AIDS HAVE BEEN DECOMMISSIONED FOR THE SEASON: LOWER COOK INLET JUNCTION LBB CI LLNR 26270EAST FORELAND B 2 LLNR 26360MIDDLE GROUND SHOAL LB 3 LLNR 26367COOK INLET LBB 6 LLNR 26384	
General/Miscellaneous	Miscellaneous	THE FOLLOWING NAVIGATIONAL AIDS HAVE BEEN DECOMMISSIONED FOR THE SEASON:LOWER COOK INLET JUNCTION LBB CI LLNR 26270EAST FORELAND B 2 LLNR 26360MIDDLE GROUND SHOAL LB 3 LLNR 26367COOK INLET LBB 6 LLNR 26384	

Sector Anchorage, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Stag Point Light	27180	DAYMK DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 67.0705° N / 164.2485° W Submerged Data Mooring Name: ZA23-ST-KS01 Water Depth: 55' Top Float Depth: 48' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 67° 04' 14" Lon: -164° 14' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.68353° N / 164.45487° W Submerged Data Mooring Name: XA23-ST-KS03 Water Depth: 59' Top Float Depth: 52' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 41' 01" Lon: -164° 27' 18"

Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.78135° N / 163.75167° W Submerged Data Mooring Name: XA23-ST-KS02 Water Depth: 80' Top Float Depth: 73' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 46' 53" Lon: -163° 45' 06"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.7805° N / 168.568° W Submerged Data Mooring Name: A2-24 Water Depth: 184' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 65° 46' 50" Lon: -168° 34' 05"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.434° N / 165.274° W Submerged Data Mooring Name: AL24-AU-UN01b Water Depth: 528' Top Float Depth: 502' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 26' 02" Lon: -165° 16' 26"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.6° N / 156.999° W Submerged Data Mooring Name: GA24-AU-SU01 Water Depth: 469' Top Float Depth: 443' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 36' 00" Lon: -156° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.85295° N / 158.99135° W Submerged Data Mooring Name: 23SH-1A Water Depth: 256' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 51' 11" Lon: -158° 59' 29"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9697° N / 146.8812° W Submerged Data Mooring Name: MC Water Depth: 745' Top Float Depth: 671' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 11" Lon: -146° 52' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.30669° N / 164.75179° W Submerged Data Mooring Name: 25UPP-3A Water Depth: 74 m Top Float Depth: 66 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 18' 24" Lon: -164° 45' 06"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.43427° N / 165.2728° W Submerged Data Mooring Name: AL25_AU_UN01 Water Depth: 160 m Top Float Depth: 146 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 26' 03" Lon: -165° 16' 22"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 53.63045° N / 167.40012° W Submerged Data Mooring Name: AL25_AU_UM01 Water Depth: 89 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 37' 50" Lon: -167° 24' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 57.023° N / 152.999° W Submerged Data Mooring Name: GA24-AU-BT01 Water Depth: 84 m Top Float Depth: 74 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 01' 23" Lon: -152° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.20405° N / 154.48198° W Name: AL25_AU_PB01 Water Depth: 49 m Top Float Depth: 41 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 15" Lon: -154° 28' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SU01 Position: (56.59892, -156.99752) water depth 135 m, top of float at 127 m (recovered GA24_AU_SU01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 35' 56" Lon: -156° 59' 51"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_BT01 Position: (57.02326, -153.00059) water depth 82 m, top of float at 74 m (recovered GA24_AU_BT01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 01' 24" Lon: -153° 00' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_BT01 Position: (57.02326, -153.00059) water depth 82 m, top of float at 74 m (recovered GA24_AU_BT01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 01' 24" Lon: -153° 00' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SE01 Position: (58.70259, -152.18696) water depth 129m, top of float at 117 m (recovered GA24_AU_SE01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 42' 09" Lon: -152° 11' 13"

Sector Southeast Alaska, Submerged Land Act (SLA)**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.93223° N / 139.60566° W Submerged Data Mooring Name: DB1-24 Water Depth: 754' Top Float Depth: 164' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 55' 56" Lon: -139° 36' 20"
Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.12272° N / 136.5934° W Submerged Data Mooring Name: 20CSP-4A Water Depth: 1,099' Top Float Depth: 1,069' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 58° 07' 22" Lon: -136° 35' 36"

Sitka Sound**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Vitskari Island Light	24915	RAC INOP	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - Sitka Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 57.04345° N / 135.20597° W The F/V DRAGON LADY sank in Canoe Cove in this position. The F/V DRAGON LADY is a 76 foot wooden fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 57° 02' 36" Lon: -135° 12' 21"

St Paul Harbor**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
St. Paul Harbor Entrance Light	26680	STRUCT DEST	FD

Stephens Passage**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Hobart Bay Light 2	23595	DAYMK MISSING	FD
Hobart Bay Light 2	23595	SS WEAK	FD
Middle Point Light	23785	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Frederick Sound - Stephens Passage/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2024-10-28 To: 2026-10-28 Location: 58.37614° N / 134.72318° W The U.S. Coast Guard has established a temporary mooring buoy in this location. This mooring buoy has been established for official use and should not be used without authorization from the Coast Guard.	Lat: 58° 22' 34" Lon: -134° 43' 23"

Stikine Strait**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Vank Island Light	22720	LT EXT	FD

Sumner Strait**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
The Eye Opener Light	23290	LT EXT	FD

Sweeper Cove**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Sweeper Cove Range Front Light	27542	DAYMK DMGD	FD

Tatitlek Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tatitlek Narrows Daybeacon 1	25675	DAYMK MISSING	FD

Tongass Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tongass Narrows Buoy 9	22230	LT EXT	FD
Refuge Cove Daybeacon 3	22270	STRUCT DEST	FD

Uganik Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Noisy Island Light	26995	LT EXT	FD
Northeast Arm Light 1	27000	DAYMK MISSING	FD

Wrangell Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wrangell Narrows Channel Light 10	22915	LT EXT	FD
Wrangell Narrows Channel Light 14	22935	LT EXT	FD
Wrangell Narrows Channel Light 17	22960	LT EXT	FD
Wrangell Narrows Channel Light 21	22975	LT EXT	FD
Wrangell Narrows Channel Light 37	23055	LT EXT	FD
Wrangell Narrows Channel Light 38	23060	LT EXT	FD
Wrangell Narrows Channel Light 40	23070	LT EXT	FD
Wrangell Narrows Channel Lighted Buoy 42	23075	LT EXT	FD
Wrangell Narrows Channel Light 43	23080	LT EXT	FD
Wrangell Narrows Channel Light 48	23100	LT EXT	FD
Wrangell Narrows Channel Light 49	23105	LT EXT	FD
Wrangell Narrows Channel Light 52	23125	LT EXT	FD
Wrangell Narrows Channel Light 56	23155	LT EXT	FD
Petersburg Bar Range Front Light	23165	LT EXT	FD

Zimovia Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Found Island Rock Daybeacon	22550	DAYMK DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sumner Strait - Zimovia Strait/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 56.19921° N / 132.49282° W The F/V PAMELA RAE LADY sank in Canoe Cove in this position. The F/V PAMELA RAE LADY is a 58 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 56° 11' 57" Lon: -132° 29' 34"