

Local Notice to Mariners for Arctic District

08/12/2026

Adak Island

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Finger Shoal Lighted Bell Buoy 3	27520	MISSING	FD

Alitak Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Alitak Light	26920	LT EXT	FD

Bar Harbor

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Bar Harbor Entrance Light 2	22210	DISCONTINUED	FD
Bar Harbor Entrance Daybeacon 3	22215	DISCONTINUED	FD
Bar Harbor North Entrance Light 2N	22220	DISCONTINUED	FD

Bechevin Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Krenitzen Light 7	27285	LT IMCH	FD
Bechevin Bay Buoy 28	27390	MISSING	FD

Bering Sea Eastern Part

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 62.5925° N / 164.908° W A 6' by 6' by 15' metal tower was destroyed and partially submerged in this position in June of 2021. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Western Alaska and U.S. Arctic at 907-428-4100.	Lat: 62° 35' 33" Lon: -164° 54' 29"
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.15927° N / 166.58292° E Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 33" Lon: 166° 34' 59"

Captains Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bailey Ledge Light	27505	LT EXT/STRUCT DMGD	FD

Chatham Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Washington Bay Light	23515	DAYMK MISSING	FD
Morris Reef Lighted Buoy 35	24035	MISSING	FD
Morris Reef Lighted Buoy 35	24035	MISSING	FD
Point Augusta Light	24105	NIGHT LT BURNING DAY	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Southeast Alaska, Submerged Land Act (SLA) - Chatham Strait/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 57.84975° N / 135.02875° W The F/V BAILEY BAY sank in this position in approximately 30 feet of water in October of 2022. The F/V BAILEY BAY is a 33' fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel.	Lat: 57° 50' 59" Lon: -135° 01' 44"
---	-----------------------	--	-------------------------------------

Chilkoot Inlet

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
LynnCanal - Chilkoot Inlet/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 59.24033° N / 135.43087° W An anchor and 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor.	Lat: 59° 14' 25" Lon: -135° 25' 51"

Clarence Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bushy Island Light	22510	LT EXT	FD
Bushy Island Light	22510	LT EXT	FD
Snow Passage Lighted Buoy SP	22515	LT EXT	FD
Bay Point Daybeacon BP	22525	DAYMK DMGD	FD

Dixon Entrance

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lord Rock Light	21835	LT EXT	FD

Dry Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Pass Daybeacon 3	24790	STRUCT DEST	FD

Eastern Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mitchell Rock Daybeacon	24957	STRUCT DEST	FD

Elfin Cove

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Elfin Cove Daybeacon 5	24260	STRUCT DEST	FD

Elrington Passage

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9911° N / 148.0963° W Submerged Data Mooring Name: EP03 Water Depth: 207' Top Float Depth: 190' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 28" Lon: -148° 05' 47"
Sector Anchorage, Submerged Land Act (SLA) - Elrington Passage/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9951° N / 148.101° W Submerged Data Mooring Name: EP04 Water Depth: 276' Top Float Depth: 259' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 42" Lon: -148° 06' 04"

Frederick Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Cape Fanshaw Light	23260	LT IMCH	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Chatham Strait - Frederick Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 56.91133° N / 132.94483° W A 47 foot wood fishing vessel was reported sunk in this position in 2023.	Lat: 56° 54' 41" Lon: -132° 56' 41"

Gastineau Channel

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Stephens Passage - Gastineau Channel/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 58.27098° N / 134.37045° W A 22' white sailboat sank in this position. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 58° 16' 16" Lon: -134° 22' 14"

Geese Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Aiaktalik Island Light 5	26910	LT EXT	FD

Glacier Bay

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Icy Strait - Glacier Bay/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-11-12 To: 2026-11-12 Location: 58.67719° N / 136.16049° W Submerged Data Mooring Name: Glacier Bay Oceanographic Mooring Water Depth: 1017' Top Float Depth: 82' POC: Mathew Cahill Phone: 907-697-2230 Email: mathew_cahill@nps.gov	Lat: 58° 40' 38" Lon: -136° 09' 38"

Icy Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
The Sisters Light	24135	VEGETATION	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Cross Sound - Icy Strait/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 58.30225° N / 135.37292° W A dangerous rock was reported in this position. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	Lat: 58° 18' 08" Lon: -135° 22' 23"

Kachemak Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sixty Foot Rock Light	26190	DAYMK DMGD	FD

Kake Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Kake Entrance Light 2	23315	LT EXT	FD

Keku Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Keku Strait Entrance Light	23305.100000000002	STRUCT DEST	FD
Keku Strait Daybeacon 2	23305.2	STRUCT DEST	FD
Keku Strait Daybeacon 4	23305.3	STRUCT DEST	FD
Keku Strait Daybeacon 15	23306	STRUCT DEST	FD
Keku Strait Daybeacon 18	23306.2	STRUCT DEST	FD
Keku Strait Daybeacon 25	23306.7	STRUCT DEST	FD
Keku Strait Daybeacon 37	23307.600000000002	STRUCT DEST	FD
Keku Strait Daybeacon 39	23307.7	DAYMK DMGD	FD
Keku Strait Daybeacon 39	23307.7	STRUCT DEST	FD
Keku Strait Daybeacon 41	23307.8	STRUCT DEST	FD

Klawock Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Klawock Tow Channel Daybeacon 3TC	24600	STRUCT DMGD	FD

Kuskokwim River

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Okwega Pass Light OP	27872	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.78583° N / 161.692° W The barge SHANKS ARK was reported sunk and abandoned in this position in March of 2017. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no maritime traffic is present.	Lat: 60° 47' 09" Lon: -161° 41' 31"

Lisianski Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lisianski Inlet Daybeacon 4	24300	STRUCT DEST	FD

LynnCanal

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Poundstone Rock Lighted Bell Buoy PR	23845	LT EXT	FD
Sentinel Island Light	23850	LT EXT	FD
False Point Retreat Light 4	23960	DAYMK MISSING	FD
False Point Retreat Light 4	23960	DAYMK MISSING	FD
Funter Bay Entrance Light 1	23975	LT EXT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Sentinel Island Light	23850	WATCHING PROPERLY	FD	2026-08-04

Marmot Bay.

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hanin Rock Light	26560	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 57.78583° N / 152.40568° W A dangerous rock was reported in this position approximately 20' off of the K&I Pier. This rock was reported struck by a vessel with a 16' draft at low tide, approximately +.085'. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	Lat: 57° 47' 09" Lon: -152° 24' 20"
---	-----------------------	--	--

Mendenhall Bar

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Mendenhall Bar Buoy 8	23735	ADRIFT	FD
Mendenhall Bar Buoy 8	23735	OFF STATION	FD

Naknek River

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kvichak Bay - Naknek River/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2025-04-26 Location: 58.71287° N / 157.03408° W A large metal ramp was reported to be visible during low tide and completely submerged during high tide.	Lat: 58° 42' 46" Lon: -157° 02' 03"

NAVAREA XII

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
NAVAREA XII/General/Miscellaneous	Miscellaneous	Submerged Data Mooring 26BS-2A Position: (56.8625,-164.04335), water depth 72m, top of float at 10m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 56° 51' 45" Lon: -164° 02' 36"
NAVAREA XII/General/Miscellaneous	Miscellaneous	Submerged Data Mooring 26BS-4A Position: (57.8672,-168.8836) water depth 73m, top of float at 10m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 52' 02" Lon: -168° 53' 01"
NAVAREA XII/General/Miscellaneous	Miscellaneous	Submerged Data Mooring 26BSP-4A Position: (57.87753,-168.88387) water depth 73m, top of float at 59m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 21' 19" Lon: -168° 53' 02"
NAVAREA XII/General/Miscellaneous	Miscellaneous	Submerged Data Mooring 26BSP-5A Position: (59.92059,-171.71541) water depth 70m, top of float at 59m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 59° 55' 14" Lon: -171° 42' 55"
NAVAREA XII/General/Miscellaneous	Miscellaneous	Submerged Data Mooring 26UPP-3A Position: (54.30723,-164.751629) water depth 75m, top of float at 65m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 18' 26" Lon: -164° 45' 06"

Nichols Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Walden Rock Light 6	22125	DAYMK MISSING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Clarence Strait - Nichols Passage/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 55.05° N / 131.64883° W The F/V JACI GRACE sank in Canoe Cove in this position. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 55° 03' 00" Lon: -131° 38' 56"

Nome Harbor

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Nome Harbor Range Rear Light	27973	WATCHING PROPERLY	FD	2026-07-30

Ogden Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dippy Island Rock Daybeacon 3	25355	STRUCT DEST	FD

Orca Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hanks Island Rock Light 5	25550	STRUCT DEST	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Hanks Island Rock Light 5	25550	ESTABLISHED	FD

Orca Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Orca Inlet Channel Light 12	25575	STRUCT DEST	FD
NOAA Data Lighted Buoy 46060	25646	ADRIFT	FD

Peril Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sergius Narrows Buoy 8	25195	OFF STATION	FD

Port Alexander

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Alexander Light	23465	REDUCED INT	FD

Port Valdez

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Valdez Boat Harbor Light 2	25815	LT EXT	FD
Valdez Boat Harbor Light 3	25820	LT EXT	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Valdez Servs Dock Lights (2)	25822	OFF STA	PA

Portage Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Portage Pass Daybeacon 11	23355	STRUCT DEST	FD

Prince William Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Schooner Rock Light 1	25525	LT EXT	FD
Applegate Shoals Light	25845	DAYMK MISSING	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.61318° N / 147.19993° W Submerged Data Mooring Name: PWSSC-15 Water Depth: 722' Top Float Depth: 197' ***Surfaces twice daily*** POC: Dr. Rob Campbell Phone: 907-424-5800 Email: rcampbell@pwssc.org	Lat: 60° 36' 47" Lon: -147° 11' 60"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3425° N / 146.7304° W Submerged Data Mooring Name: H01 Water Depth: 98' Top Float Depth: 66' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 33" Lon: -146° 43' 49"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.34° N / 146.742° W Submerged Data Mooring Name: H02 Water Depth: 879' Top Float Depth: 791' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 24" Lon: -146° 44' 31"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3349° N / 146.7329° W Submerged Data Mooring Name: HB Water Depth: 830' Top Float Depth: 747' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 06" Lon: -146° 43' 58"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3352° N / 146.7661° W Submerged Data Mooring Name: H04 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 07" Lon: -146° 45' 58"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3328° N / 146.7785° W Submerged Data Mooring Name: H05 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 58" Lon: -146° 46' 43"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3302° N / 146.7903° W Submerged Data Mooring Name: H06 Water Depth: 896' Top Float Depth: 806' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 49" Lon: -146° 47' 25"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3278° N / 146.8023° W Submerged Data Mooring Name: H07 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 40" Lon: -146° 48' 08"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3245° N / 146.8159° W Submerged Data Mooring Name: H08 Water Depth: 935' Top Float Depth: 842' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 28" Lon: -146° 48' 57"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.322° N / 146.8297° W Submerged Data Mooring Name: H09 Water Depth: 1,007' Top Float Depth: 906' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 19" Lon: -146° 49' 47"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3198° N / 146.8418° W Submerged Data Mooring Name: H10 Water Depth: 1,060' Top Float Depth: 954' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 11" Lon: -146° 50' 30"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3123° N / 146.8776° W Submerged Data Mooring Name: H13 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 44" Lon: -146° 52' 39"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3098° N / 146.889° W Submerged Data Mooring Name: H14 Water Depth: 522' Top Float Depth: 470' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 35" Lon: -146° 53' 20"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3078° N / 146.8999° W Submerged Data Mooring Name: H15 Water Depth: 276' Top Float Depth: 244' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 28" Lon: -146° 53' 60"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.302° N / 146.8928° W Submerged Data Mooring Name: HC Water Depth: 449' Top Float Depth: 404' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 07" Lon: -146° 53' 34"

Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3168° N / 146.8538° W Submerged Data Mooring Name: H11 Water Depth: 1,135' Top Float Depth: 1,022' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 00" Lon: -146° 51' 14"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.309° N / 146.9092° W Submerged Data Mooring Name: H16 Water Depth: 85' Top Float Depth: 53' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 32" Lon: -146° 54' 33"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.2997° N / 146.9056° W Submerged Data Mooring Name: HD Water Depth: 151' Top Float Depth: 119' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 17' 59" Lon: -146° 54' 20"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3376° N / 146.7544° W Submerged Data Mooring Name: H03 Water Depth: 876' Top Float Depth: 860' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 15" Lon: -146° 45' 16"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3148° N / 146.8653° W Submerged Data Mooring Name: H12 Water Depth: 1,194' Top Float Depth: 1,079' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 53" Lon: -146° 51' 55"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 60.50373° N / 146.51368° W A submerged mooring was reported lost in 315 feet of water in this position in 02/23. This mooring may be an obstruction to operations on the sea floor.	Lat: 60° 30' 13" Lon: -146° 30' 49"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-28 To: 2026-10-28 Location: 61.13408° N / 147.54442° W An uncharted and dangerous rock was reported in this position in June or 2019.	Lat: 61° 08' 03" Lon: -147° 32' 40"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.796° N / 148.05517° W The F/V SONG II sank in this position in August 2018.	Lat: 60° 47' 46" Lon: -148° 03' 19"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2024-10-28 To: 2029-10-27 Location: 61.17206° N / 148.475° W 61.17074° N / 148.05752° W 61.03802° N / 148.05752° W 60.93011° N / 148.48324° W 61.17206° N / 148.475° W The State of Alaka is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm and has the potential to create a tsunami if/when a landslide is generated that impacts the water in Barry Arm. If/when this occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following an event. The geologic makeup of the area is similar to Alaskan locations where two previous landslide caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of the potential results of a slide. Additional information is available at https://dggs.alaska.gov/hazards/barry-arm-landslide.html .	

Resurrection Bay

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
4th of July Channel LT 1	26005	STRUCT DEST	PA
Seward Marine Dock Light	26010	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Resurrection Bay/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.85045° N / 149.50063° W Submerged Data Mooring Name: GAK1-24 Water Depth: 860' Top Float Depth: 65' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 51' 02" Lon: -149° 30' 02"

Revillagigedo Channel

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Twin Islands Light TI	21945	RBN IMCH	FD

Sector Anchorage, Exclusive Economic Zone (EEZ).

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. George Harbor Entrance Light 1	27827	STRUCT DEST	FD
St. George Harbor Daybeacon 2	27828	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 75.10005° N / 168.00007° W Submerged Data Mooring Name: AIM16-1 Water Depth: 535' Top Float Depth: 142' POC: Dr. Humfrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 75° 06' 00" Lon: -168° 00' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2025-04-01 Location: 66.61013° N / 164.63417° W Submerged Data Mooring Name: XA23-ST-KS04 Water Depth: 49' Top Float Depth: 42' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 36' 36" Lon: -164° 38' 03"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 62.20477° N / 174.67642° W Submerged Data Mooring Name: AL23-AU-M08 Water Depth: 230' Top Float Depth: 197' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 62° 12' 17" Lon: -174° 40' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2025-04-13 Location: 71.67308° N / 154.9998° W Submerged Data Mooring Name: BCE-22 Water Depth: 384' Top Float Depth: 62' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 40' 23" Lon: -154° 59' 59"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.73445° N / 155.164° W Submerged Data Mooring Name: BCC-22 Water Depth: 951' Top Float Depth: 66' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 44' 04" Lon: -155° 09' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.79635° N / 155.34687° W Submerged Data Mooring Name: BCW-22 Water Depth: 554' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 47' 47" Lon: -155° 20' 49"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 70.834° N / 163.126° W Submerged Data Mooring Name: AL24-AU-IC01 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 02" Lon: -163° 07' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.754° N / 154.475° W Submerged Data Mooring Name: AL24-AU-BF02 Water Depth: 344' Top Float Depth: 312' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 45' 14" Lon: -154° 28' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.30823° N / 152.13573° W Submerged Data Mooring Name: AON-BS1 Water Depth: 554' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 18' 30" Lon: -152° 08' 09"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3941° N / 152.05118° W Submerged Data Mooring Name: AON-BS3a Water Depth: 479' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 23' 39" Lon: -152° 03' 04"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3968° N / 152.0032° W Submerged Data Mooring Name: AON-BS3b Water Depth: 502' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 23' 48" Lon: -152° 00' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.21467° N / 164.2485° W Submerged Data Mooring Name: AL23-AU-IC02 Water Depth: 141' Top Float Depth: 108' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 53" Lon: -164° 14' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.831° N / 166.018° W Submerged Data Mooring Name: AL24-AU-IC03 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 49' 52" Lon: -166° 01' 05"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.204° N / 157.999° W Submerged Data Mooring Name: AL24-AU-PB01 Water Depth: 157' Top Float Depth: 131' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 14" Lon: -157° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59952° N / 161.50698° W Submerged Data Mooring Name: CEM1-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 58" Lon: -161° 30' 25"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59965° N / 161.52747° W Submerged Data Mooring Name: CEM2-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 59" Lon: -161° 31' 39"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.58373° N / 161.49948° W Submerged Data Mooring Name: CEO1-24 Water Depth: 154' Top Float Depth: 111' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 01" Lon: -161° 29' 58"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.60063° N / 161.5408° W Submerged Data Mooring Name: CEO2-24 Water Depth: 151' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 36' 02" Lon: -161° 32' 27"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 66.327° N / 168.949° W Submerged Data Mooring Name: A3-24 Water Depth: 190' Top Float Depth: 23' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 66° 19' 37" Lon: -168° 56' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.746° N / 168.2625° W Submerged Data Mooring Name: A4-24 Water Depth: 161' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 65° 44' 46" Lon: -168° 15' 45"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.12937° N / 168.313° W Submerged Data Mooring Name: AL24-AU-PC01 Water Depth: 561' Top Float Depth: 535' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 07' 46" Lon: -168° 18' 47"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 64.858° N / 168.448° W Submerged Data Mooring Name: AL24-AU-NM01 Water Depth: 144' Top Float Depth: 118' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 64° 51' 29" Lon: -168° 26' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.16° N / 166.582° W Submerged Data Mooring Name: AL24-AU-BS10 Water Depth: 384' Top Float Depth: 358' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 36" Lon: -166° 34' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 61.084° N / 170.264° W Submerged Data Mooring Name: AL24-AU-BS11 Water Depth: 161' Top Float Depth: 135' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 61° 05' 02" Lon: -170° 15' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.702° N / 152.187° W Submerged Data Mooring Name: GA24-AU-SE01 Water Depth: 423' Top Float Depth: 384' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 42' 07" Lon: -152° 11' 13"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.04167° N / 145.17° W Submerged Data Mooring Name: UWAPL24 Water Depth: Unknown Top Float Depth: Surface POC: Joe Talbert Phone: 907-409-4627 Email: talbertj@uw.edu	Lat: 50° 02' 30" Lon: -145° 10' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.0267° N / 148.6707° W Submerged Data Mooring Name: GEO2-24 Water Depth: 758' Top Float Depth: 82' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 01' 36" Lon: -148° 40' 15"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.02322° N / 144.36115° W Submerged Data Mooring Name: FLMA Water Depth: 9,361' Top Float Depth: 68' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 01' 24" Lon: -144° 21' 40"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.37608° N / 144.51397° W Submerged Data Mooring Name: FLMB Water Depth: 9,523' Top Float Depth: 68' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 22' 34" Lon: -144° 30' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.1143° N / 144.91743° W Submerged Data Mooring Name: HYPM Water Depth: 9,664' Top Float Depth: 342' POC: Derek Buffitt Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 06' 51" Lon: -144° 55' 03"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 77.49333° N / 140.18° W Submerged Data Mooring Name: AMOS-VLF-1 Water Depth: 12,264' Top Float Depth: 230' POC: Craig Lee Email: craiglee@uw.edu	Lat: 77° 29' 36" Lon: -140° 10' 48"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.41333° N / 142.47° W Submerged Data Mooring Name: AMOS-C Water Depth: 12,326' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu	Lat: 76° 24' 48" Lon: -142° 28' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.14667° N / 145.28333° W Submerged Data Mooring Name: AMOS-NW Water Depth: 12,441' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 76° 08' 48" Lon: -145° 16' 60"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 75.77333° N / 141.51333° W Submerged Data Mooring Name: AMOS-NE Water Depth: 12,251' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 75° 46' 24" Lon: -141° 30' 48"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.875° N / 143.08667° W Submerged Data Mooring Name: AMOS-SE Water Depth: 12,241' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 74° 52' 30" Lon: -143° 05' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.58833° N / 145.545° W Submerged Data Mooring Name: AMOS-A Water Depth: 12,339' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu	Lat: 74° 35' 18" Lon: -145° 32' 42"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.52292° N / 161.94227° W Submerged Data Mooring Name: NAP-23t Water Depth: 5,528' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 74° 31' 23" Lon: -161° 56' 32"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 68.98622° N / 105.88383° W Submerged Data Mooring Name: ACW16-30 Water Depth: 242' Top Float Depth: 231' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 68° 59' 10" Lon: -105° 53' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33385° N / 133.73948° W Submerged Data Mooring Name: IBO16-1a Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 20' 02" Lon: -133° 44' 22"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33392° N / 133.74087° W Submerged Data Mooring Name: IBO16-1b Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 20' 02" Lon: -133° 44' 27"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.98932° N / 133.74393° W Submerged Data Mooring Name: IBO16-2 Water Depth: 365' Top Float Depth: 146' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 59' 22" Lon: -133° 44' 38"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.0589° N / 133.7153° W Submerged Data Mooring Name: IBO16-9a Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 03' 32" Lon: -133° 42' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.05835° N / 133.71562° W Submerged Data Mooring Name: IBO16-9b Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 03' 30" Lon: -133° 42' 56"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.77472° N / 137.04595° W Submerged Data Mooring Name: SIC16-11 Water Depth: 117' Top Float Depth: 107' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 69° 46' 29" Lon: -137° 02' 45"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.65473° N / 138.92132° W Submerged Data Mooring Name: HI16 Water Depth: 134' Top Float Depth: 125' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 69° 39' 17" Lon: -138° 55' 17"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.2012° N / 174.6819° W Submerged Data Mooring Name: 24BSST-8A Water Depth: 242' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 04" Lon: -174° 40' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.831° N / 166.0145° W Submerged Data Mooring Name: 24CKP-3A Water Depth: 144' Top Float Depth: 121' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 49' 52" Lon: -166° 00' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.0453° N / 160.48823° W Submerged Data Mooring Name: 24CKP-4A Water Depth: 167' Top Float Depth: 135' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 02' 43" Lon: -160° 29' 18"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2082° N / 158° W Submerged Data Mooring Name: 24CKP-5A Water Depth: 167' Top Float Depth: 144' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 30" Lon: -158° 00' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.47007° N / 156.5697° W Submerged Data Mooring Name: 24CKP-9A Water Depth: 3,054' Top Float Depth: 886' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 28' 12" Lon: -156° 34' 11"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 56.86687° N / 164.04302° W Submerged Data Mooring Name: 25BSP-2A Water Depth: 72 m Top Float Depth: 62 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 56° 52' 01" Lon: -164° 02' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.08299° N / 163.50042° W Submerged Data Mooring Name: AL25_AU_UN04 Water Depth: 100 m Top Float Depth: 87 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 04' 59" Lon: -163° 30' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-06 To: 2027-05-06 Location: 57.87733° N / 168.88367° W Submerged Data Mooring Name: 25BSP-4A Water Depth: 72 m Top Float Depth: 61 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 52' 38" Lon: -168° 53' 01"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.12698° N / 168.31173° W Submerged Data Mooring Name: AL25_AU_PC01 Water Depth: 169 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 07' 37" Lon: -168° 18' 42"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 55.572° N / 154.975° W Submerged Data Mooring Name: GA24_AU_CR01 Water Depth: 400 m Top Float Depth: 70 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 55° 34' 19" Lon: -154° 58' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 53.971° N / 161.663° W Submerged Data Mooring Name: GA24-AU-SN01 Water Depth: 436 m Top Float Depth: 86 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 58' 16" Lon: -161° 39' 47"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 56.15927° N / 166.58292° W Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 33" Lon: -166° 34' 59"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25-AU-PO01 Water Depth: 116 m Top Float Depth: 105 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 33' 59" Lon: -149° 59' 28"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 64.85793° N / 168.44803° W Name: AL25_AU_NM01 Water Depth: 44 m Top Float Depth: 34 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 64° 51' 29" Lon: -168° 26' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.75395° N / 154.47518° W Name: AL25_AU_BF02 Water Depth: 105 m Top Float Depth: 99 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 45' 14" Lon: -154° 28' 31"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 71.83082° N / 166.01868° W Name: AL25_AU_IC03 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 49' 51" Lon: -166° 01' 07"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: AL25_AU_IC01 Position: (70.83413, -163.12628) water depth 45m, top of float at 39m (recovered AL24_AU_IC01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 03" Lon: -163° 07' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring AL25_AU_PB01 Position: (71.20405, -157.99865) water depth 49m, top of float at 41m (recovered AL24_AU_PB01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 15" Lon: -157° 59' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SN01 Position: (53.96871, -161.66364) water depth 431 m, top of float at 83 m (recovered GA24_AU_SN01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 58' 07" Lon: -161° 39' 49"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSP-8A Position: (62.19812,-174.66308) water depth 74m, top of float 61m (recovered 24BSP-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 11' 53" Lon: -174° 39' 47"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSST-8A Position: (62.20464, -174.6760) water depth 73m, top of float 26m (recovered 24BSST-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 17" Lon: -174° 40' 34"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSR-8A Position: (62.20115,-174.6823) water depth 74, top of float 20m (recovered 24BSR-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 04" Lon: -174° 40' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-2A Position: (71.21562,-164.24901) water depth 42m, top of float 33m (recovered 24CKP-2A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 56" Lon: -164° 14' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-9A Position: (72.47871, -156.74174) water depth 920m, top of float 270m (recovered 24CKP-9A approx 4 nm to the E) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 28' 43" Lon: -156° 44' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA26_ST_AB01 Position: 57.49970 N x 150.64863 W Water depth: 103m, top of float depth at 96m (new mooring location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 29' 59" Lon: -150° 38' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Naval Activity/Naval Gunnery Exercises	Naval Activity	General/Naval Activity From: 2026-02-23 To: 2026-08-28 Location: 58-43-26.400N/150-46-54.588W HAZARDOUS OPERATIONS-A GUNNERY AND PYROTECHNICS EXERCISE WILL BE CONDUCTED IN APPROX. POSITION 58-43.44N 150-46.91W, APPROXIMATELY 29NM SOUTH FROM GORE POINT, FROM 27 1600 FEB 26 TO 27 2300 FEB 26 UTC WHICH IS 0700 TO 1400 ALASKA TIME, 27 FEB 26. DANGER RADIUS 20,000 YDS, DANGER ALTITUDE 17,000 FT.	Lat: 58° 43' 26" Lon: -150° 46' 55"

Sector Anchorage, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Point Romanof Light	27895	DAYMK DMGD	FD
Unalakleet River Buoys (About 6)	27915	Status Unreported	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.2289° N / 162.16302° W Submerged Data Mooring Name: XA23-ST-KS07 Water Depth: 46' Top Float Depth: 39' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 13' 44" Lon: -162° 09' 47"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 57.72427° N / 152.28335° W Submerged Data Mooring Name: 23CB-1A Water Depth: 545' Top Float Depth: 472' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 43' 27" Lon: -152° 17' 00"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.91099° N / 149.3493° W Submerged Data Mooring Name: GAKOA Water Depth: 171' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: Natalie Monacci Phone: 907-474-7956 Email: nmonacci@alaska.edu	Lat: 59° 54' 40" Lon: -149° 20' 57"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9247° N / 147.8105° W Submerged Data Mooring Name: M01 Water Depth: 295' Top Float Depth: 263' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 55' 29" Lon: -147° 48' 38"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9308° N / 147.8179° W Submerged Data Mooring Name: M02 Water Depth: 446' Top Float Depth: 401' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 55' 51" Lon: -147° 49' 04"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9363° N / 147.8253° W Submerged Data Mooring Name: M03 Water Depth: 509' Top Float Depth: 458' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 11" Lon: -147° 49' 31"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9426° N / 147.8326° W Submerged Data Mooring Name: M04 Water Depth: 577' Top Float Depth: 519' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 33" Lon: -147° 49' 57"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9481° N / 147.8397° W Submerged Data Mooring Name: M05 Water Depth: 640' Top Float Depth: 576' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 53" Lon: -147° 50' 23"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9807° N / 147.8811° W Submerged Data Mooring Name: M11 Water Depth: 472' Top Float Depth: 425' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 51" Lon: -147° 52' 52"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9753° N / 147.8892° W Submerged Data Mooring Name: MD Water Depth: 614' Top Float Depth: 553' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 31" Lon: -147° 53' 21"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.1149° N / 148.2353° W Submerged Data Mooring Name: BP07 Water Depth: 171' Top Float Depth: 154' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 06' 54" Lon: -148° 14' 07"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0464° N / 148.1247° W Submerged Data Mooring Name: POWP05 Water Depth: 315' Top Float Depth: 299' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 02' 47" Lon: -148° 07' 29"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0465° N / 148.12982° W Submerged Data Mooring Name: POWP06 Water Depth: 154' Top Float Depth: 138' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 02' 47" Lon: -148° 07' 47"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9808° N / 148.0319° W Submerged Data Mooring Name: LP01 Water Depth: 112' Top Float Depth: 95' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 51" Lon: -148° 01' 55"

Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9847° N / 148.03698° W Submerged Data Mooring Name: LP02 Water Depth: 144' Top Float Depth: 128' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 05" Lon: -148° 02' 13"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9537° N / 147.8473° W Submerged Data Mooring Name: M06 Water Depth: 702' Top Float Depth: 686' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 13" Lon: -147° 50' 50"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9643° N / 147.8605° W Submerged Data Mooring Name: M08 Water Depth: 758' Top Float Depth: 741' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 51" Lon: -147° 51' 38"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9691° N / 147.8668° W Submerged Data Mooring Name: M09 Water Depth: 643' Top Float Depth: 617' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 09" Lon: -147° 52' 00"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9752° N / 147.8739° W Submerged Data Mooring Name: M10 Water Depth: 784' Top Float Depth: 768' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 31" Lon: -147° 52' 26"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 54.12848° N / 165.77305° W An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in this position on the sea floor in approximately 138 feet. This anomaly has not been positively identified and mariners are requested to transit the area with caution.	Lat: 54° 07' 43" Lon: -165° 46' 23"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	ConocoPhillips Alaska, Inc. (CPAI) plans to conduct marine ocean and seabed characterization studies near Oliktok Point. Studies will include buoy installation, tide gauge installation, bathymetric surveys, and navigational hazard surveys during the open water seasons of 2024, 2025, 2026, and 2027. Temporary monitoring equipment will be placed in the area to support the studies. This request is specific to activities planned for the 2026 season; an LMN will be submitted in subsequent years as needed. Buoy installation includes the deployment and recovery of three wave buoys offshore of Oliktok Point during the 2026 open water season. Preliminary buoy locations are included in Table 1 and shown on the attached map; final buoy locations may vary by about 1 nautical mile from the preliminary locations based on planning with local vessel operators and conditions encountered in the field. Buoy 1 will be installed in shallow water, approximately 5 to 10 feet deep. Buoys 2 and 3 will be installed in deeper water, approximately 25 to 30 feet deep. All buoys will float on the surface. Final buoy locations, depths, and water depth will be recorded and submitted within two days of deployment. Each Spotter buoy will be moored to the seafloor and will have a spar buoy equipped with an LED strobe light to alert mariners. Buoys will be deployed in late-July or early- August and recovered in late-September to mid-October. One tide gauge will be installed at or near the Oliktok Point during the 2026 open water season. The tide gauge will consist of a pressure transducer located in a water depth of three to five feet, a cable to shore, and a data recorder onshore. The pressure transducer will be located about 20 feet from shore and will be mounted on a ¾ inch pipe that sticks up above the water approximately 3 feet. The pipe will be driven 2 to 3 feet into the seabed using a post drive and will be clearly marked for safety. The onshore data recorder will be kept in a weather resistant container (e.g. cooler or bucket) and secured to the gravel bag jetty on the west side of Oliktok Point. A survey staff will be installed next to the pressure transducer to provide manual readout. The staff will also be attached to a ¾ inch pipe driven into the seabed in the same manner as the pressure transducer. The tide gauge will be installed at the beginning of the open-water season. The tide gauge and associated materials will be removed prior to freeze up. The stake on which the tide gauge is mounted could present a hazard for small boats transiting near the beach. Mariners should reduce wake when transiting the area and maintain a distance of at least 100 feet from the stake in the water and the data recorder on shore. Work is planned to begin as early as July 10, 2026. Please contact Miranda Buckmaster at (907) 263-4868 or miranda.buckmaster@conocophillips.com should you have any questions or require additional information.	
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	ALASKA – SOUTHCENTRAL – COOK INLET – PORT OF ALASKA – MARINE CONSTRUCTION Dredging, demolition, pile driving, wharf construction, and other miscellaneous marine construction will be conducted at the Port of Alaska from 01 April through 31 October 2026. Three temporary mooring buoys with flashing white lights will be established northwest of Terminal 3 in positions: 61-15-05.4N 149-53-45.4W 61-15-14.3N 149-53-23.0W 61-15-25.9N 149-53-39.2W During operations, VHF-FM channel 8 will be monitored. Derrick barges will have anchors deployed and submerged anchor cables will be marked by crown buoys over each submerged anchor. Mariners are advised to maintain a minimum closest point of approach of 1,000 feet, transit at slow speed, and exercise caution when transiting this area. For additional information, mariners can contact the U.S. Coast Guard on VHF-FM channel 16, by phone to Sector Western Alaska and U.S. Arctic Command Center at 907-428-4100, or by email at SECTORWESTERN@USCG.MIL	
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 70.83413° N / 154.47628° W Name: AL25_AU_IC01 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 03" Lon: -154° 28' 35"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKFPR-2A Position: (71.21072,-164.27086) water depth 42m, float on surface (New surface buoy with flashing yellow light every 4s) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 60° 34' 29" Lon: -150° 32' 46"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	ConocoPhillips Oliktok Point Buoy 1 Deployed August 5, 2026 10:05am AKDT 70.5330167°,-149.8672333°	Lat: 70° 31' 59" Lon: -149° 52' 02"

Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	ConocoPhillips Oliktok Point Buoy 2 Deployed August 5, 2026 10:27am AKDT 70.5676°, -149.9409°	Lat: 70° 34' 03" Lon: -149° 56' 27"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	ConocoPhillips Oliktok Point Buoy 3 Deployed August 5, 2026 11:04am AKDT 70.5233667°, -150.0814667°	Lat: 70° 31' 24" Lon: -150° 04' 53"

Sector Anchorage, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Seal Cape Light	27130	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 67.0705° N / 164.2485° W Submerged Data Mooring Name: ZA23-ST-KS01 Water Depth: 55' Top Float Depth: 48' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 67° 04' 14" Lon: -164° 14' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.68353° N / 164.45487° W Submerged Data Mooring Name: XA23-ST-KS03 Water Depth: 59' Top Float Depth: 52' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 41' 01" Lon: -164° 27' 18"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.78135° N / 163.75167° W Submerged Data Mooring Name: XA23-ST-KS02 Water Depth: 80' Top Float Depth: 73' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 46' 53" Lon: -163° 45' 06"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.7805° N / 168.568° W Submerged Data Mooring Name: A2-24 Water Depth: 184' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 65° 46' 50" Lon: -168° 34' 05"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.434° N / 165.274° W Submerged Data Mooring Name: AL24-AU-UN01b Water Depth: 528' Top Float Depth: 502' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 26' 02" Lon: -165° 16' 26"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.6° N / 156.999° W Submerged Data Mooring Name: GA24-AU-SU01 Water Depth: 469' Top Float Depth: 443' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 36' 00" Lon: -156° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.85295° N / 158.99135° W Submerged Data Mooring Name: 23SH-1A Water Depth: 256' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 51' 11" Lon: -158° 59' 29"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9697° N / 146.8812° W Submerged Data Mooring Name: MC Water Depth: 745' Top Float Depth: 671' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 11" Lon: -146° 52' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.30669° N / 164.75179° W Submerged Data Mooring Name: 25UPP-3A Water Depth: 74 m Top Float Depth: 66 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 18' 24" Lon: -164° 45' 06"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.43427° N / 165.2728° W Submerged Data Mooring Name: AL25_AU_UN01 Water Depth: 160 m Top Float Depth: 146 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 26' 03" Lon: -165° 16' 22"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 53.63045° N / 167.40012° W Submerged Data Mooring Name: AL25_AU_UN01 Water Depth: 89 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 37' 50" Lon: -167° 24' 00"

8/12/26, 12:24 PM				Maritime Safety Information Products Navigation Center			
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 57.023° N / 152.999° W Submerged Data Mooring Name: GA24-AU-BT01 Water Depth: 84 m Top Float Depth: 74 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov			Lat: 57° 01' 23" Lon: -152° 59' 56"		
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.20405° N / 154.48198° W Name: AL25_AU_PB01 Water Depth: 49 m Top Float Depth: 41 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov			Lat: 71° 12' 15" Lon: -154° 28' 55"		
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SU01 Position: (56.59892, -156.99752) water depth 135 m, top of float at 127 m (recovered GA24_AU_SU01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov			Lat: 56° 35' 56" Lon: -156° 59' 51"		
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_BT01 Position: (57.02326, -153.00059) water depth 82 m, top of float at 74 m (recovered GA24_AU_BT01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov			Lat: 57° 01' 24" Lon: -153° 00' 02"		
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_BT01 Position: (57.02326, -153.00059) water depth 82 m, top of float at 74 m (recovered GA24_AU_BT01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov			Lat: 57° 01' 24" Lon: -153° 00' 02"		
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SE01 Position: (58.70259, -152.18696) water depth 129m, top of float at 117 m (recovered GA24_AU_SE01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov			Lat: 58° 42' 09" Lon: -152° 11' 13"		

Sector Southeast Alaska, Submerged Land Act (SLA)

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.93223° N / 139.60566° W Submerged Data Mooring Name: DB1-24 Water Depth: 754' Top Float Depth: 164' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 55' 56" Lon: -139° 36' 20"
Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.12272° N / 136.5934° W Submerged Data Mooring Name: 20CSP-4A Water Depth: 1,099' Top Float Depth: 1,069' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 58° 07' 22" Lon: -136° 35' 36"

Sitka Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Vitskari Island Light	24915	RAC INOP	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - Sitka Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 57.04345° N / 135.20597° W The F/V DRAGON LADY sank in Canoe Cove in this position. The F/V DRAGON LADY is a 76 foot wooden fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 57° 02' 36" Lon: -135° 12' 21"

St Paul Harbor

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. Paul Harbor Entrance Light	26680	STRUCT DEST	FD

Stephens Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE

False Point Pybus Daybeacon	23585	DAYMK MISSING	FD
Hobart Bay Light 2	23595	DAYMK MISSING	FD
Middle Point Light	23785	LT EXT	FD
Portland Island Light	23805	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Frederick Sound - Stephens Passage/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2024-10-28 To: 2026-10-28 Location: 58.37614° N / 134.72318° W The U.S. Coast Guard has established a temporary mooring buoy in this location. This mooring buoy has been established for official use and should not be used without authorization from the Coast Guard.	Lat: 58° 22' 34" Lon: -134° 43' 23"

Sukkwana Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hydaburg Daybeacon	24392	DAYMK MISSING	FD
Hydaburg Daybeacon	24392	DAYMK MISSING	FD

Sumner Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Point Baker Light	23295	DBD DMGD	FD

Tlevak Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tlevak Narrows Light 2	24440	DAYMK MISSING	FD

Tongass Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Vallenar Rock Light	22295	LT EXT	FD

Uganik Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Northeast Arm Light 1	27000	DAYMK MISSING	FD

Zimovia Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Found Island Rock Daybeacon	22550	DAYMK DMGD	FD
Found Island Rock Daybeacon	22550	DAYMK MISSING/STRUCT DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sumner Strait - Zimovia Strait/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 56.19921° N / 132.49282° W The F/V PAMELA RAE LADY sank in Canoe Cove in this position. The F/V PAMELA RAE LADY is a 58 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 56° 11' 57" Lon: -132° 29' 34"