

Local Notice to Mariners for District 17 11/26/2025**Adak Island****Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Finger Shoal Lighted Bell Buoy 3	27520	OFF STATION	FD

Akutan Harbor**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Akutan Point Light 2	27440	LT EXT	FD

Alaska Peninsula**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Alaska Peninsula/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2025-06-25 To: 2025-12-22 A newly installed fiber optic submarine cable by GCI has been laid from Chignik Lagoon to Chignik Bay, Alaska. This cable is an extension to an already charted cable. Mariners are advised to avoid anchoring in the middle of the channel to prevent entanglements. Any concerned traffic can contact Coast Guard Sector Western Alaska and US Arctic Command Cetner at 9074284100. All vessels are requested to transit the area with caution and report all sightings to the Coast Guard.	

Alitak Bay**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Cape Alitak Light	26920	DAYMK MISSING	FD

Bechevin Bay**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Bechevin Bay Entrance Buoy BB	27250	MISSING	FD
Isanotski Strait Light 3	27410	LT EXT	FD

Bering Sea Eastern Part**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 62.5925° N / 164.908° W A 6' by 6' by 15' metal tower was destroyed and partially submerged in this position in June of 2021. Mariners are requested to transit the area with caution and make sighting reports to the Coast Guard Sector Western Alaska and U.S. Arctic at 907-428-4100.	Lat: 62° 35' 33" Lon: -164° 54' 29"
Sector Anchorage, Submerged Land Act (SLA) - Bering Sea Eastern Part/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.15927° N / 166.58292° E Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 33" Lon: 166° 34' 59"

Captains Bay**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Bailey Ledge Light	27505	Status Unreported	FD
Bailey Ledge Light	27505	LT EXT/STRUCT DMGD	FD

Temporary Changes

NAME	LLNR	STATUS	AID TYPE
Bailey Ledge Light	27505	TRUB	FD

Chatham Strait**Federal Discrepancies Corrected**

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Cape Ommaney Light	23460	WATCHING PROPERLY	FD	2025-11-19

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - Chatham Strait/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 57.84975° N / 135.02875° W The F/V BAILEY BAY sank in this position in approximately 30 feet of water in October of 2022. The F/V BAILEY BAY is a 33' fiberglass fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel.	Lat: 57° 50' 59" Lon: -135° 01' 44"

Chilkoot Inlet

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
LynnCanal - Chilkoot Inlet/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 59.24033° N / 135.43087° W An anchor and 1 shot of chain from a 120 foot vessel was reported as lost and sitting on the sea floor. All vessels anchoring in the vicinity are requested to remain clear of the lost anchor.	Lat: 59° 14' 25" Lon: -135° 25' 51"

Chiniak Bay

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Chiniak Bay/General/Marine Events/Regatta (Race)	Marine Events	LOCAL NOTICE TO MARINERS Kodiak Harbor Lights Festival and Boat Parade Date/Time: December 20, 2025, from 6:00 pm to 7:00 pm AKST Location: Kodiak, Alaska Mariners are advised that the Kodiak Harbor Lights Festival and Boat Parade will take place on December 20, 2025, from 6:00 pm to 7:00 pm AKST. The parade will begin approximately 1 mile north of the Near Island Bridge and proceed single file through the Near Island Channel, under the Near Island Bridge, and disburse in outer St. Paul Harbor between Uski Island and Pier II of the City of Kodiak. Mariners and recreational spectators are advised to exercise caution while transiting the area during the event. Vessel operators should maintain a safe speed, keep a sharp lookout, and avoid impeding the parade or other vessel traffic. For additional information, contact the event organizers or the U.S. Coast Guard Marine Safety Unit Kodiak. Chart Affected: NOAA Chart 16595 This notice is issued for the safety of all mariners and participants. Thank you for your cooperation. U.S. Coast Guard Local Notice to Mariners	

Clarence Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Bay Point Daybeacon BP	22525	DAYMK DMGD	FD

Copper River Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Strawberry Channel Entrance Lighted Whistle Buoy SC	25485	Status Unreported	FD
Strawberry Channel Entrance Lighted Whistle Buoy SC	25485	Status Unreported	FD

District 13, Oceanic boundary to EEZ

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Miscellaneous	Miscellaneous	Buoy Adrift, Hull Number 2.6D62 (46415) Approx. 247 NM WSW of Federick is. BC, Canada	Lat: 52° 58' 17" Lon: -139° 48' 33"

Dry Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dry Pass Daybeacon 3	24790	STRUCT DEST	FD

East Channel

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Nichols Passage East Channel Daybeacon 2	22040	WATCHING PROPERLY	FD	2025-11-12

Eastern Channel**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Mitchell Rock Daybeacon	24957	STRUCT DEST	FD

Elfin Cove**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Elfin Cove Daybeacon 5	24260	STRUCT DEST	FD

Elrington Passage**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9911° N / 148.0963° W Submerged Data Mooring Name: EP03 Water Depth: 207' Top Float Depth: 190' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 28" Lon: -148° 05' 47"
Sector Anchorage, Submerged Land Act (SLA) - Elrington Passage/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9951° N / 148.101° W Submerged Data Mooring Name: EP04 Water Depth: 276' Top Float Depth: 259' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 42" Lon: -148° 06' 04"

Frederick Sound**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Chatham Strait - Frederick Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 56.91133° N / 132.94483° W A 47 foot wood fishing vessel was reported sunk in this position in 2023.	Lat: 56° 54' 41" Lon: -132° 56' 41"

Gastineau Channel**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Stephens Passage - Gastineau Channel/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 58.27098° N / 134.37045° W A 22' white sailboat sank in this position. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 58° 16' 16" Lon: -134° 22' 14"

Geese Channel**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Aiaktalik Island Light 5	26910	DAYMK MISSING	FD
Aiaktalik Island Light 5	26910	DAYMK MISSING	FD

Glacier Bay**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Icy Strait - Glacier Bay/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-11-12 To: 2026-11-12 Location: 58.67719° N / 136.16049° W Submerged Data Mooring Name: Glacier Bay Oceanographic Mooring Water Depth: 1017' Top Float Depth: 82' POC: Mathew Cahill Phone: 907-697-2230 Email: matthew_cahill@nps.gov	Lat: 58° 40' 38" Lon: -136° 09' 38"

Icy Strait**Temporary Changes**

NAME	LLNR	STATUS	AID TYPE
Pinta Rock Lighted Bell Buoy 2	24165	TRLB	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Cross Sound - Icy Strait/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 58.30225° N / 135.37292° W A dangerous rock was reported in this position. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	Lat: 58° 18' 08" Lon: -135° 22' 23"

Kachemak Bay**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Sixty Foot Rock Light	26190	DAYMK DMGD	FD
Halibut Point Daybeacon	26245	STRUCT DEST	FD

Karheen Passage**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Tonowek Narrows Daybeacon 2T	24680	DAYMK IMCH	FD

Keku Strait**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Keku Strait Entrance Light	23305.100000000002	STRUCT DEST	FD
Keku Strait Daybeacon 4	23305.3	STRUCT DEST	FD
Keku Strait Daybeacon 15	23306	STRUCT DEST	FD
Keku Strait Daybeacon 18	23306.2	STRUCT DEST	FD
Keku Strait Daybeacon 25	23306.7	STRUCT DEST	FD
Keku Strait Daybeacon 37	23307.600000000002	STRUCT DEST	FD
Keku Strait Daybeacon 39	23307.7	STRUCT DEST	FD
Keku Strait Daybeacon 41	23307.8	STRUCT DEST	FD

Kupreanof Strait**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Dry Spruce Island Rock Light 7	27025	LT EXT	FD

Kuskokwim River**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Kuskokwim River Buoy 36	27849.7	Status Unreported	FD
Yukon River South Entrance Light	27860	DAYMK MISSING	FD
Okwega Pass Light OP	27872	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.78583° N / 161.692° W The barge SHANKS ARK was reported sunk and abandoned in this position in March of 2017. A portion of the vessel remains visible above the level of high-tide, but the majority of the vessel remains below the waterline. The vessel is marked by an all-round white light and one ball dayshape when Steamboat Slough is ice free but the markers are removed during freeze up as no maritime traffic is present.	Lat: 60° 47' 09" Lon: -161° 41' 31"
Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-06-04 To: 2025-12-01 The Kwigillingok Water Buoys have been commissioned for the season on June 1, 2025. Buoy Positions are as follows: Buoy 1 - N 59°51.0418 W 163°07.2280 Buoy 2 - N 59°50.7120 W 163°07.4363 Buoy 3 - N 59°50.0614 W 163°06.4928 Buoy 4 - N 59°49.6795 W 163°05.5144 Buoy 5 - N 59°49.2769 W 163°06.3849 Buoy 6 - N 59°48.9255 W 163°05.7493 Buoy 7 - N 59°48.2362 W 163°05.3509 POC: John Darrel 907-588-2133	
Sector Anchorage, Submerged Land Act (SLA) - Kuskokwim River/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-10-17 To: 2026-04-15 THE FOLLOWING AIDS HAVE BEEN DISESTABLISHED FOR THE SEASON: KUSKOKWIM RIVER BUOY 23 (LLNR 27846.5) KUSKOKWIM RIVER BUOY 25 (LLNR 27847) KUSKOKWIM RIVER BUOY 37 (LLNR 27850) KUSKOKWIM RIVER BUOY 39 (LLNR 27850.5) KUSKOKWIM RIVER BUOY 41 (LLNR 27851) KUSKOKWIM RIVER BUOY 42 (LLNR 27851.2) KUSKOKWIM RIVER BUOY 44 (LLNR 27851.7) KUSKOKWIM RIVER BUOY 45 (LLNR 27852) KUSKOKWIM RIVER BUOY 46 (LLNR 27852.2) KUSKOKWIM RIVER BUOY 47 (LLNR 27852.5) KUSKOKWIM RIVER BUOY 49 (LLNR 27853) KUSKOKWIM RIVER BUOY 50 (LLNR 27853.2) KUSKOKWIM RIVER BUOY 51 (LLNR 27853.5) KUSKOKWIM RIVER BUOY 53 (LLNR 27854) KUSKOKWIM RIVER BUOY 55 (LLNR 27854.5) KUSKOKWIM RIVER BUOY 60 (LLNR 27855.7).	

Lisianski Inlet**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Lisianski Inlet Daybeacon 4	24300	STRUCT DEST	FD

LynnCanal**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
LynnCanal/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-07-18 To: 2026-01-14 DUE TO SCHEDULED MAINTENANCE THE COAST GUARD MAY BE UNABLE TO LISTEN OR RESPOND TO DISTRESS CALLS ON CH16 STARTING JULY 21ST THROUGH JULY 22ND FROM 0600 TO 1400Z OR 2200 TO 0600 AKST IN THE FOLLOWING AREAS: LYNN CANAL, CHILKOOT INLET, AND CHILKAT INLET. ALL MARINERS ARE REQUESTED TO RELAY ANY UNANSWERED DISTRESS CALLS IN THESE AREAS TO THE NEAREST COAST GUARD UNIT OR CONTACT COAST GUARD SECTOR SEAK AT 907-463-2980.	

Marmot Bay**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Hanin Rock Light	26560	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Marmot Bay/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-25 To: 2029-10-24 Location: 57.78583° N / 152.40568° W A dangerous rock was reported in this position approximately 20' off of the K'Pier. This rock was reported struck by a vessel with a 16' draft at low tide, approximately +.085'. Mariners are advised to transit the area with caution. Questions/concerns/updates should be directed to Todd Buck with the Coast Guard District 17 Waterways Management Office at (907) 463-2269 or by email to todd.r.buck@uscg.mil.	Lat: 57° 47' 09" Lon: -152° 24' 20"

Mendenhall Bar**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Mendenhall Bar Buoy 11	23735.4	Status Unreported	FD

Nakat Bay**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Tongass Reef Daybeacon	21910	DBD DMGD	FD

Naknek River**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Kvichak Bay - Naknek River/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2025-04-26 Location: 58.71287° N / 157.03408° W A large metal ramp was reported to be visible during low tide and completely submerged during high tide.	Lat: 58° 42' 46" Lon: -157° 02' 03"

Nichols Passage**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Clarence Strait - Nichols Passage/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 55.05° N / 131.64883° W The F/V JACI GRACE sank in Canoe Cove in this position. The F/V JACI GRACE is a 52 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 55° 03' 00" Lon: -131° 38' 56"

Nushagak Bay**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2025-10-23 To: 2026-04-22 Location: 58-50-28.608N/158-34-48.288W 4FT BLACK MOORING BALL SUMBERGED IN NUSHAGAK BAY IN POSN 58-50-28.608N/158-34-48.288W, 0.75NM WEST OF CLARKS POINT.	Lat: 58° 50' 29" Lon: -158° 34' 48"
--	-----------------------	---	-------------------------------------

Ogden Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Dippy Island Rock Daybeacon 3	25355	STRUCT DEST	FD

Orca Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hanks Island Rock Light 5	25550	STRUCT DEST	FD

Orca Inlet

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Orca Inlet Channel Light 12	25575	STRUCT DEST	FD
NOAA Data Lighted Buoy 46060	25646	ADRIFT	FD
Glacier Island Light	25665	VEGETATION/MISSING	FD

Peril Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sergius Narrows Buoy 8	25195	DAYMK DMGD	FD

Port Alexander

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Alexander Light	23465	REDUCED INT	FD

Port Chester

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Metlakatla Boat Harbor Light 2	22065	WATCHING PROPERLY	FD	2025-11-12

Port Graham

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2025-11-04 To: 2026-05-03 Location: 59-22-23.484N/151-52-33.060W Awash unlit pile. Area is shallower than surrounding shoal. Danger is visible at +3 tide. At MLLW danger rises approximately 3 ft above the water. Isolated danger for small craft transiting between marked channel and shore at higher tides when danger is submerged. POC: LTJG Liam Long Liam.M.Long@uscg.mil	Lat: 59° 22' 23" Lon: -151° 52' 33"

Port Valdez

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
Port Valdez Servs Dock Lights (2)	25822	OFF STA	PA

Portage Pass

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Portage Pass Daybeacon 11	23355	STRUCT DEST	FD

Prince William Sound**Federal Discrepancies**

NAME	LLNR	STATUS	AID TYPE
Seal Rocks Light	25515	DBD DMGD	FD
Schooner Rock Light 1	25525	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Hazards	Hazards To Navigation	General/Hazards To Navigation/Hazards From: 2024-10-28 To: 2029-10-27 Location: 61.17206° N / 148.475° W 61.17074° N / 148.05752° W 61.03802° N / 148.05752° W 60.93011° N / 148.48324° W 61.17206° N / 148.475° W The State of Alaska is issuing routine updates on the Barry Arm Landslide Tsunami risk. This threat is located in Barry Arm and has the potential to create a tsunami if/when a landslide is generated that impacts the water in Barry Arm. If/when this occurs localized wave heights will be very hazardous in Barry Arm and Harriman Fjord. Port Wells and Passage Canal will also see inundation and strong, unusual currents for hours following an event. The geologic makeup of the area is similar to Alaskan locations where two previous landslides caused tsunamis occurred, in Lituya Bay (1958) and Icy Bay (2015), both causing extremely large but localized tsunamis. Mariners should maintain vigilance when in the vicinity of Barry Arm or nearby waters and be prepared to depart the area if any unusual geologic activity is observed. Studies are being conducted and the situation is being monitored to allow for a better understanding of the potential results of a slide. Additional information is available at https://dggs.alaska.gov/hazards/barry-arm-landslide.html .	
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.61318° N / 147.19993° W Submerged Data Mooring Name: PWSSC-15 Water Depth: 722' Top Float Depth: 197' ***Surfaces twice daily*** POC: Dr. Rob Campbell Phone: 907-424-5800 Email: rcampbell@pwssc.org	Lat: 60° 36' 47" Lon: -147° 11' 60"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3425° N / 146.7304° W Submerged Data Mooring Name: H01 Water Depth: 98' Top Float Depth: 66' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 33" Lon: -146° 43' 49"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.34° N / 146.742° W Submerged Data Mooring Name: H02 Water Depth: 879' Top Float Depth: 791' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 24" Lon: -146° 44' 31"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3349° N / 146.7329° W Submerged Data Mooring Name: HB Water Depth: 830' Top Float Depth: 747' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 06" Lon: -146° 43' 58"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3352° N / 146.7661° W Submerged Data Mooring Name: H04 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 07" Lon: -146° 45' 58"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3328° N / 146.7785° W Submerged Data Mooring Name: H05 Water Depth: 886' Top Float Depth: 797' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 58" Lon: -146° 46' 43"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3302° N / 146.7903° W Submerged Data Mooring Name: H06 Water Depth: 896' Top Float Depth: 806' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 49" Lon: -146° 47' 25"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3278° N / 146.8023° W Submerged Data Mooring Name: H07 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 40" Lon: -146° 48' 08"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3245° N / 146.8159° W Submerged Data Mooring Name: H08 Water Depth: 935' Top Float Depth: 842' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 28" Lon: -146° 48' 57"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.322° N / 146.8297° W Submerged Data Mooring Name: H09 Water Depth: 1,007' Top Float Depth: 906' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 19" Lon: -146° 49' 47"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3198° N / 146.8418° W Submerged Data Mooring Name: H10 Water Depth: 1,060' Top Float Depth: 954' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 11" Lon: -146° 50' 30"

Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3123° N / 146.8776° W Submerged Data Mooring Name: H13 Water Depth: 909' Top Float Depth: 818' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 44" Lon: -146° 52' 39"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3098° N / 146.889° W Submerged Data Mooring Name: H14 Water Depth: 522' Top Float Depth: 470' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 35" Lon: -146° 53' 20"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3078° N / 146.8999° W Submerged Data Mooring Name: H15 Water Depth: 276' Top Float Depth: 244' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 28" Lon: -146° 53' 60"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.302° N / 146.8928° W Submerged Data Mooring Name: HC Water Depth: 449' Top Float Depth: 404' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 07" Lon: -146° 53' 34"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3168° N / 146.8538° W Submerged Data Mooring Name: H11 Water Depth: 1,135' Top Float Depth: 1,022' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 19' 00" Lon: -146° 51' 14"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.309° N / 146.9092° W Submerged Data Mooring Name: H16 Water Depth: 85' Top Float Depth: 53' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 32" Lon: -146° 54' 33"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.2997° N / 146.9056° W Submerged Data Mooring Name: HD Water Depth: 151' Top Float Depth: 119' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 17' 59" Lon: -146° 54' 20"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3376° N / 146.7544° W Submerged Data Mooring Name: H03 Water Depth: 876' Top Float Depth: 860' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 20' 15" Lon: -146° 45' 16"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.3148° N / 146.8653° W Submerged Data Mooring Name: H12 Water Depth: 1,194' Top Float Depth: 1,079' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 18' 53" Lon: -146° 51' 55"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 60.50373° N / 146.51368° W A submerged mooring was reported lost in 315 feet of water in this position in 02/23. This mooring may be an obstruction to operations on the sea floor.	Lat: 60° 30' 13" Lon: -146° 30' 49"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Shoaling Reported	Hazards To Navigation	General/Hazards To Navigation/Shoaling Reported From: 2024-10-28 To: 2026-10-28 Location: 61.13408° N / 147.54442° W An uncharted and dangerous rock was reported in this position in June or 2019.	Lat: 61° 08' 03" Lon: -147° 32' 40"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-28 To: 2026-10-28 Location: 60.796° N / 148.05517° W The F/V SONG II sank in this position in August 2018.	Lat: 60° 47' 46" Lon: -148° 03' 19"
Sector Anchorage, Submerged Land Act (SLA) - Prince William Sound/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-06-13 To: 2025-12-10 Location: 60°47.243'N 147°40.0'W Scuttling of a Barge was conducted on 1/24/2025 at 60°47.243'N 147°40.0'W in a depth of 252 fathoms.	Lat: 60° 51' 03" Lon: -147° 40' 00"

Resurrection Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Caines Head Light	25995	LT EXT	FD
Thumb Cove Light	26000	DAYMK MISSING	FD

Private Discrepancies

NAME	LLNR	STATUS	AID TYPE
------	------	--------	----------

4th of July Channel LT 1	26005	STRUCT DEST	PA
Seward Marine Dock Light	26010	LT EXT	PA

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Submerged Land Act (SLA) - Resurrection Bay/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.85045° N / 149.50063° W Submerged Data Mooring Name: GAK1-24 Water Depth: 860' Top Float Depth: 65' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 51' 02" Lon: -149° 30' 02"

Sector Anchorage, Exclusive Economic Zone (EEZ)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
St. George Harbor Entrance Light 1	27827	STRUCT DEST	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 75.10005° N / 168.00007° W Submerged Data Mooring Name: AIM16-1 Water Depth: 535' Top Float Depth: 142' POC: Dr. Humfrey Mellings Phone: 250-363-6552 Email: humfrey.mellings@dfmo-mpo.gc.ca	Lat: 75° 06' 00" Lon: -168° 00' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2025-04-01 Location: 66.61013° N / 164.63417° W Submerged Data Mooring Name: XA23-ST-KS04 Water Depth: 49' Top Float Depth: 42' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 36' 36" Lon: -164° 38' 03"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 62.20477° N / 174.67642° W Submerged Data Mooring Name: AL23-AU-M08 Water Depth: 230' Top Float Depth: 197' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 62° 12' 17" Lon: -174° 40' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-04 To: 2026-10-04 Location: 58.26188° N / 163.55735° W Submerged Data Mooring Name: 24KUM-2A Water Depth: 131' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 58° 15' 43" Lon: -163° 33' 26"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2025-04-13 Location: 71.67308° N / 154.9998° W Submerged Data Mooring Name: BCE-22 Water Depth: 384' Top Float Depth: 62' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 40' 23" Lon: -154° 59' 59"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.73445° N / 155.164° W Submerged Data Mooring Name: BCC-22 Water Depth: 951' Top Float Depth: 66' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 44' 04" Lon: -155° 09' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.79635° N / 155.34687° W Submerged Data Mooring Name: BCW-22 Water Depth: 554' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 71° 47' 47" Lon: -155° 20' 49"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 70.834° N / 163.126° W Submerged Data Mooring Name: AL24-AU-IC01 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 02" Lon: -163° 07' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.754° N / 154.475° W Submerged Data Mooring Name: AL24-AU-BF02 Water Depth: 344' Top Float Depth: 312' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 45' 14" Lon: -154° 28' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.30823° N / 152.13573° W Submerged Data Mooring Name: AON-BS1 Water Depth: 554' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 18' 30" Lon: -152° 08' 09"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3941° N / 152.05118° W Submerged Data Mooring Name: AON-BS3a Water Depth: 479' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 23' 39" Lon: -152° 03' 04"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.3968° N / 152.0032° W Submerged Data Mooring Name: AON-BS3b Water Depth: 502' Top Float Depth: 115' POC: Dr. Robert Pickart Phone: 508-289-2858 Email: rpickart@whoi.edu	Lat: 71° 23' 48" Lon: -152° 00' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.21467° N / 164.2485° W Submerged Data Mooring Name: AL23-AU-IC02 Water Depth: 141' Top Float Depth: 108' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 53" Lon: -164° 14' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.831° N / 166.018° W Submerged Data Mooring Name: AL24-AU-IC03 Water Depth: 148' Top Float Depth: 121' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 49' 52" Lon: -166° 01' 05"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.204° N / 157.999° W Submerged Data Mooring Name: AL24-AU-PB01 Water Depth: 157' Top Float Depth: 131' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 14" Lon: -157° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59952° N / 161.50698° W Submerged Data Mooring Name: CEM1-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 58" Lon: -161° 30' 25"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.59965° N / 161.52747° W Submerged Data Mooring Name: CEM2-24 Water Depth: 154' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 59" Lon: -161° 31' 39"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.58373° N / 161.49948° W Submerged Data Mooring Name: CEO1-24 Water Depth: 154' Top Float Depth: 111' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 35' 01" Lon: -161° 29' 58"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-15 To: 2026-10-15 Location: 71.60063° N / 161.5408° W Submerged Data Mooring Name: CEO2-24 Water Depth: 151' Top Float Depth: 108' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 71° 36' 02" Lon: -161° 32' 27"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 66.327° N / 168.949° W Submerged Data Mooring Name: A3-24 Water Depth: 190' Top Float Depth: 23' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 66° 19' 37" Lon: -168° 56' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.746° N / 168.2625° W Submerged Data Mooring Name: A4-24 Water Depth: 161' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 65° 44' 46" Lon: -168° 15' 45"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.12937° N / 168.313° W Submerged Data Mooring Name: AL24-AU-PC01 Water Depth: 561' Top Float Depth: 535' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 07' 46" Lon: -168° 18' 47"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 64.858° N / 168.448° W Submerged Data Mooring Name: AL24-AU-NM01 Water Depth: 144' Top Float Depth: 118' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 64° 51' 29" Lon: -168° 26' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.16° N / 166.582° W Submerged Data Mooring Name: AL24-AU-BS10 Water Depth: 384' Top Float Depth: 358' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 36" Lon: -166° 34' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 61.084° N / 170.264° W Submerged Data Mooring Name: AL24-AU-BS11 Water Depth: 161' Top Float Depth: 135' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 61° 05' 02" Lon: -170° 15' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.702° N / 152.187° W Submerged Data Mooring Name: GA24-AU-SE01 Water Depth: 423' Top Float Depth: 384' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 42' 07" Lon: -152° 11' 13"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.04167° N / 145.17° W Submerged Data Mooring Name: UWAPL24 Water Depth: Unknown Top Float Depth: Surface POC: Joe Talbert Phone: 907-409-4627 Email: talbertj@uw.edu	Lat: 50° 02' 30" Lon: -145° 10' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.0267° N / 148.6707° W Submerged Data Mooring Name: GEO2-24 Water Depth: 758' Top Float Depth: 82' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 01' 36" Lon: -148° 40' 15"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.02322° N / 144.36115° W Submerged Data Mooring Name: FLMA Water Depth: 9,361' Top Float Depth: 68' POC: Derek Buffit Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 01' 24" Lon: -144° 21' 40"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.37608° N / 144.51397° W Submerged Data Mooring Name: FLMB Water Depth: 9,523' Top Float Depth: 68' POC: Derek Buffit Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 22' 34" Lon: -144° 30' 50"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 50.1143° N / 144.91743° W Submerged Data Mooring Name: HYPM Water Depth: 9,664' Top Float Depth: 342' POC: Derek Buffit Phone: 508-548-1401 Email: dbuffitt@whoi.edu	Lat: 50° 06' 51" Lon: -144° 55' 03"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 77.49333° N / 140.18° W Submerged Data Mooring Name: AMOS-VLF-1 Water Depth: 12,264' Top Float Depth: 230' POC: Craig Lee Email: craiglee@uw.edu	Lat: 77° 29' 36" Lon: -140° 10' 48"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.41333° N / 142.47° W Submerged Data Mooring Name: AMOS-C Water Depth: 12,326' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu	Lat: 76° 24' 48" Lon: -142° 28' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 76.14667° N / 145.28333° W Submerged Data Mooring Name: AMOS-NW Water Depth: 12,441' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 76° 08' 48" Lon: -145° 16' 60"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 75.77333° N / 141.51333° W Submerged Data Mooring Name: AMOS-NE Water Depth: 12,251' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 75° 46' 24" Lon: -141° 30' 48"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-04-16 Location: 75.5° N / 144.14° W Submerged Data Mooring Name: AMOS-B Water Depth: 12,379' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 75° 30' 00" Lon: -144° 08' 24"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.875° N / 143.08667° W Submerged Data Mooring Name: AMOS-SE Water Depth: 12,241' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 74° 52' 30" Lon: -143° 05' 12"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-04-16 Location: 75.21667° N / 146.67667° W Submerged Data Mooring Name: AMOS-SW Water Depth: 12,464' Top Float Depth: 328' POC: Craig Lee Email: craiglee@uw.edu	Lat: 75° 13' 00" Lon: -146° 40' 36"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.58833° N / 145.545° W Submerged Data Mooring Name: AMOS-A Water Depth: 12,339' Top Float Depth: 131' POC: Craig Lee Email: craiglee@uw.edu	Lat: 74° 35' 18" Lon: -145° 32' 42"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 74.52292° N / 161.94227° W Submerged Data Mooring Name: NAP-23t Water Depth: 5,528' Top Float Depth: 115' POC: Motoyo ITOH Phone: +81-46-867-9488 Email: motoyo@jamstec.go.jp	Lat: 74° 31' 23" Lon: -161° 56' 32"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 68.98622° N / 105.88383° W Submerged Data Mooring Name: ACW16-30 Water Depth: 242' Top Float Depth: 231' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 68° 59' 10" Lon: -105° 53' 02"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-04-16 Location: 70.56283° N / 127.69517° W Submerged Data Mooring Name: CB12 Water Depth: 125' Top Float Depth: 116' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 33' 46" Lon: -127° 41' 43"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33385° N / 133.73948° W Submerged Data Mooring Name: IBO16-1a Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 20' 02" Lon: -133° 44' 22"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.33392° N / 133.74087° W Submerged Data Mooring Name: IBO16-1b Water Depth: 180' Top Float Depth: 171' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 20' 02" Lon: -133° 44' 27"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.98932° N / 133.74393° W Submerged Data Mooring Name: IBO16-2 Water Depth: 365' Top Float Depth: 146' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 59' 22" Lon: -133° 44' 38"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.0589° N / 133.71513° W Submerged Data Mooring Name: IBO16-9a Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 03' 32" Lon: -133° 42' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 70.05835° N / 133.71562° W Submerged Data Mooring Name: IBO16-9b Water Depth: 116' Top Float Depth: 106' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 70° 03' 30" Lon: -133° 42' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.77472° N / 137.04595° W Submerged Data Mooring Name: SIC16-11 Water Depth: 117' Top Float Depth: 107' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 69° 46' 29" Lon: -137° 02' 45"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-18 To: 2026-10-18 Location: 69.65473° N / 138.92132° W Submerged Data Mooring Name: HI16 Water Depth: 134' Top Float Depth: 125' POC: Dr. Humphrey Melling Phone: 250-363-6552 Email: humfrey.melling@dfo-mpo.gc.ca	Lat: 69° 39' 17" Lon: -138° 55' 17"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.198° N / 174.663° W Submerged Data Mooring Name: 24BS-8A Water Depth: 242' Top Float Depth: 59' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 11' 53" Lon: -174° 39' 47"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.205° N / 174.676° W Submerged Data Mooring Name: 24BSP-8A Water Depth: 242' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 18" Lon: -174° 40' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.202° N / 174.6819° W Submerged Data Mooring Name: 24BSST-8A Water Depth: 242' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 04" Lon: -174° 40' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 62.202° N / 174.66° W Submerged Data Mooring Name: 24BSITAER-8A Water Depth: 242' Top Float Depth: 66' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 07" Lon: -174° 39' 36"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 70.837° N / 163.126° W Submerged Data Mooring Name: 24CKP-1A Water Depth: 148' Top Float Depth: 115' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 70° 50' 13" Lon: -163° 07' 34"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2157° N / 164.2494° W Submerged Data Mooring Name: 24CKP-2A Water Depth: 148' Top Float Depth: 118' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 57" Lon: -164° 14' 58"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.831° N / 166.0145° W Submerged Data Mooring Name: 24CKP-3A Water Depth: 144' Top Float Depth: 121' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 49' 52" Lon: -166° 00' 52"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.0453° N / 160.48823° W Submerged Data Mooring Name: 24CKP-4A Water Depth: 167' Top Float Depth: 135' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 02' 43" Lon: -160° 29' 18"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 71.2082° N / 158° W Submerged Data Mooring Name: 24CKP-5A Water Depth: 167' Top Float Depth: 144' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 30" Lon: -158° 00' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.47007° N / 156.5697° W Submerged Data Mooring Name: 24CKP-9A Water Depth: 3,054' Top Float Depth: 886' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 28' 12" Lon: -156° 34' 11"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 67.91° N / 168.181° W Submerged Data Mooring Name: 24CKP-12A Water Depth: 190' Top Float Depth: 141' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 67° 54' 36" Lon: -168° 10' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-12-02 To: 2026-12-02 Location: 72.3099° N / 167.272° W Submerged Data Mooring Name: 24CKP-15A Water Depth: 161' Top Float Depth: 131' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 18' 36" Lon: -167° 16' 19"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 56.86687° N / 164.04302° W Submerged Data Mooring Name: 25BSP-2A Water Depth: 72 m Top Float Depth: 62 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 56° 52' 01" Lon: -164° 02' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.08299° N / 163.50042° W Submerged Data Mooring Name: AL25_AU_UN04 Water Depth: 100 m Top Float Depth: 87 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 04' 59" Lon: -163° 30' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-06 To: 2027-05-06 Location: 57.87733° N / 168.88367° W Submerged Data Mooring Name: 25BSP-4A Water Depth: 72 m Top Float Depth: 61 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 52' 38" Lon: -168° 53' 01"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 56.12698° N / 168.31173° W Submerged Data Mooring Name: AL25_AU_PC01 Water Depth: 169 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 07' 37" Lon: -168° 18' 42"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 55.572° N / 154.975° W Submerged Data Mooring Name: GA24_AU_CRO1 Water Depth: 400 m Top Float Depth: 70 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 55° 34' 19" Lon: -154° 58' 30"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 53.971° N / 161.663° W Submerged Data Mooring Name: GA24-AU-SN01 Water Depth: 436 m Top Float Depth: 86 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 58' 16" Lon: -161° 39' 47"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 56.15927° N / 166.58292° W Submerged Data Mooring Name: AL25_AU_BS10 Water Depth: 110 m Top Float Depth: 102 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 09' 33" Lon: -166° 34' 59"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25-AU-PO01 Water Depth: 116 m Top Float Depth: 105 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 33' 59" Lon: -149° 59' 28"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 64.85793° N / 168.44803° W Name: AL25_AU_NM01 Water Depth: 44 m Top Float Depth: 34 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 64° 51' 29" Lon: -168° 26' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.75395° N / 154.47518° W Name: AL25_AU_BF02 Water Depth: 105 m Top Float Depth: 99 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 45' 14" Lon: -154° 28' 31"

Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 71.83082° N / 166.01868° W Name: AL25_AU_IC03 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 49' 51" Lon: -166° 01' 07"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: AL25_AU_IC01 Position: (70.83413, -163.12628) water depth 45m, top of float at 39m (recovered AL24_AU_IC01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 03" Lon: -163° 07' 35"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring AL25_AU_PB01 Position: (71.20405, -157.99865) water depth 49m, top of float at 41m (recovered AL24_AU_PB01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 15" Lon: -157° 59' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SN01 Position: (53.96871, -161.66364) water depth 431 m, top of float at 83 m (recovered GA24_AU_SN01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 58' 07" Lon: -161° 39' 49"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_CR01 Position: (55.57024, -154.97519) water depth 400 m, top of float at 70 m (recovered GA24_AU_CR01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 55° 34' 13" Lon: -154° 58' 31"
General/Miscellaneous	Miscellaneous	From: 2025-10-15 To: 2026-04-13 Location: 56-52-01.416N/164-03-36.360W NOAA Submerged Data Mooring: 25BS-2C Position: (56.86706, -164.0601) water depth 71m, top of float at 10m (recovered 25BS-2A from same location) POC: David Strausz 206-526-4510	Lat: 56° 52' 01" Lon: -164° 03' 36"
General/Miscellaneous	Miscellaneous	25BS-5A Position: (59.92817, -171.70361) water depth 68m, top of float at 13m (recovered 24BS-4A from same location)	Lat: 59° 55' 41" Lon: -171° 42' 13"
General/Miscellaneous	Miscellaneous	NOAA Submerged Data Mooring: 25BSP-5A Position: (59.92064, -171.71648) water depth 69m, top of float 58m (recovered 24BSP-5A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 59° 55' 14" Lon: -171° 42' 59"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25BSV-8A Position: (62.20619, -174.66568) water depth 73m, top of float 47m (recovered 24BSV-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 22" Lon: -174° 39' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25BSV-8B Position: (62.21004, -174.64728) water depth 73m, top of float 47m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 36" Lon: -174° 38' 50"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25BSP-14A Position: (63.98727, -168.04814) water depth 36m, top of float 28m (recovered 24BSP-14A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 63° 59' 14" Lon: -168° 02' 53"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25BSFPR-14A Position: (63.97854, -168.05827) water depth 36m, float on surface (New surface buoy with flashing yellow light every 4s) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 63° 58' 43" Lon: -168° 03' 30"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25BS-8A Position: (62.20177, -174.66122) water depth 74m, top of float 18m (recovered 24BS-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 06" Lon: -174° 39' 40"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSP-8A Position: (62.19812, -174.66308) water depth 74m, top of float 61m (recovered 24BSP-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 11' 53" Lon: -174° 39' 47"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSST-8A Position: (62.20464, -174.6760) water depth 73m, top of float 26m (recovered 24BSST-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 17" Lon: -174° 40' 34"

General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25BSR-8A Position: (62.20115,-174.6823) water depth 74, top of float 20m (recovered 24BSR-8A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 62° 12' 04" Lon: -174° 40' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-12A Position: (67.90664,-168.18142) water depth 59m, top of float 44m (recovered 24CKP-12A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 67° 54' 24" Lon: -168° 10' 53"
Sector Anchorage, Exclusive Economic Zone (EEZ)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-1A Position: (70.8364,-163.1189) water depth 45m, top of float 35m (recovered 24CKP-1A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 70° 50' 11" Lon: -163° 07' 08"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-2A Position: (71.21562,-164.24901) water depth 42m, top of float 33m (recovered 24CKP-2A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 12' 56" Lon: -164° 14' 56"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-3A Position: (71.82707,-166.01816) water depth 45m, top of float 37m (recovered 24CKP-3A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 49' 37" Lon: -166° 01' 05"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-4A Position: (71.04505,-160.48967) water depth 52m, top of float 40m (recovered 24CKP-4A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 71° 02' 42" Lon: -160° 29' 23"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-9A Position: (72.47871, -156.74174) water depth 920m, top of float 270m (recovered 24CKP-9A approx 4 nm to the E) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 28' 43" Lon: -156° 44' 30"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKP-15A Position: (72.30807,-167.27204) water depth 49m, top of float 41m (recovered 24CKP-15A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 72° 18' 29" Lon: -167° 16' 19"

Sector Anchorage, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sealion Rocks Light	1245	LT EXT	FD
Cape Etolin Light	1287	DAYMK MISSING	FD
Kalgin Island Light	26300	DBD DEST	FD
Whirlpool Point Light	26915	LT EXT	FD
Smoky Point Light	27760	DAYMK MISSING	FD
Unalakleet River Buoys (About 6)	27915	Status Unreported	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.2289° N / 162.16302° W Submerged Data Mooring Name: XA23-ST-KS07 Water Depth: 46' Top Float Depth: 39' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 13' 44" Lon: -162° 09' 47"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 57.72427° N / 152.28335° W Submerged Data Mooring Name: 23CB-1A Water Depth: 545' Top Float Depth: 472' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 43' 27" Lon: -152° 17' 00"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.91099° N / 149.3493° W Submerged Data Mooring Name: GAKOA Water Depth: 171' Top Float Depth: Surface Light Characteristic: Fl Y 4s POC: Natalie Monacci Phone: 907-474-7956 Email: nmonacci@alaska.edu	Lat: 59° 54' 40" Lon: -149° 20' 57"
General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9247° N / 147.8105° W Submerged Data Mooring Name: M01 Water Depth: 295' Top Float Depth: 263' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 55' 29" Lon: -147° 48' 38"

Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9308° N / 147.8179° W Submerged Data Mooring Name: M02 Water Depth: 446' Top Float Depth: 401' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 55' 51" Lon: -147° 49' 04"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9363° N / 147.8253° W Submerged Data Mooring Name: M03 Water Depth: 509' Top Float Depth: 458' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 11" Lon: -147° 49' 31"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9426° N / 147.8326° W Submerged Data Mooring Name: M04 Water Depth: 577' Top Float Depth: 519' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 33" Lon: -147° 49' 57"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9481° N / 147.8397° W Submerged Data Mooring Name: M05 Water Depth: 640' Top Float Depth: 576' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 56' 53" Lon: -147° 50' 23"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-04-15 Location: 59.9591° N / 147.8539° W Submerged Data Mooring Name: M07 Water Depth: 741' Top Float Depth: 667' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 33" Lon: -147° 51' 14"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9807° N / 147.8811° W Submerged Data Mooring Name: M11 Water Depth: 472' Top Float Depth: 425' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 51" Lon: -147° 52' 52"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9753° N / 147.8892° W Submerged Data Mooring Name: MD Water Depth: 614' Top Float Depth: 553' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 31" Lon: -147° 53' 21"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.1149° N / 148.2353° W Submerged Data Mooring Name: BP07 Water Depth: 171' Top Float Depth: 154' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 06' 54" Lon: -148° 14' 07"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0464° N / 148.1247° W Submerged Data Mooring Name: POWP05 Water Depth: 315' Top Float Depth: 299' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 02' 47" Lon: -148° 07' 29"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 60.0465° N / 148.1298° W Submerged Data Mooring Name: POWP06 Water Depth: 154' Top Float Depth: 138' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 60° 02' 47" Lon: -148° 07' 47"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9808° N / 148.0319° W Submerged Data Mooring Name: LP01 Water Depth: 112' Top Float Depth: 95' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 51" Lon: -148° 01' 55"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9847° N / 148.03698° W Submerged Data Mooring Name: LP02 Water Depth: 144' Top Float Depth: 128' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 59' 05" Lon: -148° 02' 13"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9537° N / 147.8473° W Submerged Data Mooring Name: M06 Water Depth: 702' Top Float Depth: 686' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 13" Lon: -147° 50' 50"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9643° N / 147.8605° W Submerged Data Mooring Name: M08 Water Depth: 758' Top Float Depth: 741' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 57' 51" Lon: -147° 51' 38"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9691° N / 147.8668° W Submerged Data Mooring Name: M09 Water Depth: 643' Top Float Depth: 617' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 09" Lon: -147° 52' 00"

Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9752° N / 147.8739° W Submerged Data Mooring Name: M10 Water Depth: 784' Top Float Depth: 768' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 31" Lon: -147° 52' 26"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-28 To: 2026-10-28 Location: 54.12848° N / 165.77305° W An unknown marine anomaly was discovered during underwater survey operations in Akutan Harbor in this position on the sea floor in approximately 138 feet. This anomaly has not been positively identified and mariners are requested to transit the area with caution.	Lat: 54° 07' 43" Lon: -165° 46' 23"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Marine Construction (Excluding Bridges)/Dredging	Marine Construction (Excluding Bridges)	General/Marine Construction (Excluding Bridges)/Dredging From: 2025-09-01 To: 2026-02-06 Alaska Marine Excavation, LLC. will be conducting dredging operations at the Cruise Ship Terminal Dock starting September 15th, 2025 thru January 31st 2026. Dredging operations will continue 24 hours a day. The dredge COMMANDER is a 58' cutter head suction dredge, red and yellow in color, with a partially submerged pipeline. The pipeline will extend approx. 3000ft South and terminate in open water. Dredge pipeline will be marked with yellow buoys and termination scow. The dredge COMMANDER and tug Growler will be working on VHF/FM channel 79 and monitoring VHF/FM channels 13 and 16. Questions/concerns can also be directed to Brok Shafer with Alaska Marine Excavation, LLC at (907) 399-4549 or by email to brok@akmx.com.	
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&subdistrict=n This pipeline is the Sagavanirktok River-Main Channel (Sag), mile 8.9, approximately 9.5 miles east of Deadhorse, Alaska (70.224550°N, -147.955285°W)	Lat: 70° 13' 28" Lon: -147° 57' 19"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	"A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&subdistrict=n This pipeline is the Tolvana River, mile 143.4, approximately 5 miles southwest of Livengood, Alaska (65.461173°N, -148.633068° W).	Lat: 65° 27' 40" Lon: -148° 37' 59"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	""A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&subdistrict=n This pipeline is the Middle Fork Chulitna River, mile 11.2, approximately 17 miles southwest of Cantwell, Alaska (63.211826°N, -149.326663°W).	Lat: 63° 12' 43" Lon: -149° 19' 36"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	"A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&subdistrict=n This pipeline is the East Fork Chulitna River, mile 8.3, approximately 19.8 miles southwest of Cantwell, Alaska (63.172206°N, -149.360919°W).	Lat: 63° 10' 20" Lon: -149° 21' 39"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	"A public notice has been issued for five proposed pipeline crossings, as part of the AKLNG natural gas pipeline project. The public notice can be viewed on the U.S. Coast Guard Navigation Center website through the following link: https://www.navcen.uscg.gov/public-notices-for-bridges-active-by-district?district=17&subdistrict=n This pipeline is the Deshka River, 8.9, approximately 10.6 miles northwest of Willow, Alaska (61.793293°N, -150.34713°W).	Lat: 61° 47' 36" Lon: -150° 20' 50"
Sector Anchorage, Territorial Sea - Sector Anchorage, Submerged Land Act (SLA)/General/Miscellaneous	Miscellaneous	Submerged Data Mooring From: 2025-09-08 To: 2027-09-08 Location: 70.83413° N / 154.47628° W Name: AL25_AU_IC01 Water Depth: 45 m Top Float Depth: 39 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 70° 50' 03" Lon: -154° 28' 35"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25CB-1A Position: (57.72303, -152.28397) water depth 175m, top of float 157m (recovered 24CB-1A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 57° 43' 23" Lon: -152° 17' 02"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: 25CKFPR-2A Position: (71.21072, -164.27086) water depth 42m, float on surface (New surface buoy with flashing yellow light every 4s) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 60° 34' 29" Lon: -150° 32' 46"
General/Miscellaneous	Miscellaneous	ALASKA-SOUTHCENTRAL-COOK INLET THE FOLLOWING NAVIGATIONAL AIDS HAVE BEEN DECOMMISSIONED FOR THE SEASON: LOWER COOK INLET JUNCTION LBB CI LLNR 26270EAST FORELAND B 2 LLNR 26360MIDDLE GROUND SHOAL LB 3 LLNR 26367COOK INLET LBB 6 LLNR 26384	
General/Miscellaneous	Miscellaneous	THE FOLLOWING NAVIGATIONAL AIDS HAVE BEEN DECOMMISSIONED FOR THE SEASON:LOWER COOK INLET JUNCTION LBB CI LLNR 26270EAST FORELAND B 2 LLNR 26360MIDDLE GROUND SHOAL LB 3 LLNR 26367COOK INLET LBB 6 LLNR 26384	
General/Miscellaneous	Miscellaneous	THE FOLLOWING NAVIGATIONAL AIDS HAVE BEEN DECOMMISSIONED FOR THE SEASON:KASILOF ENTRANCE CHANNEL BUOY 2 (LLNR 26315)KASILOF ENTRANCE CHANNEL BUOY 3 (LLNR 26315.1)KASILOF ENTRANCE CHANNEL BUOY 4 (LLNR 26315.2)KASILOF ENTRANCE CHANNEL BUOY 5 (LLNR 26315.3)KASILOF ENTRANCE CHANNEL BUOY 6 (LLNR 26315.4)KASILOF ENTRANCE CHANNEL BUOY 7 (LLNR 26315.5)KASILOF ENTRANCE CHANNEL BUOY 8 (LLNR 26315.6)KASILOF ENTRANCE CHANNEL BUOY 9 (LLNR 26315.65)KASILOF ENTRANCE CHANNEL BUOY 10 (LLNR 26315.7)KASILOF ENTRANCE CHANNEL BUOY 11 (LLNR 26315.8)KASILOF ENTRANCE CHANNEL BUOY 13 (LLNR 26315.9)MARINERS ARE REQUESTED TO TRANSIT THE AREA WITH CAUTION.	
General/Miscellaneous	Miscellaneous	The Northstar Artificial Island Lights (4) (LLC LLNR 28001.80, 28001.81, 28001.82, and 28001.83) have been turned off (decommissioned). The location is North of Prudhoe Bay, Ak in Stefansson Sound.	

Sector Anchorage, Territorial Sea

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE

Stag Point Light	27180	DBD DMGD	FD
------------------	-------	----------	----

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 67.0705° N / 164.2485° W Submerged Data Mooring Name: ZA23-ST-KS01 Water Depth: 55' Top Float Depth: 48' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 67° 04' 14" Lon: -164° 14' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.68353° N / 164.45487° W Submerged Data Mooring Name: XA23-ST-KS03 Water Depth: 59' Top Float Depth: 52' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 41' 01" Lon: -164° 27' 18"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-03 To: 2026-10-03 Location: 66.78135° N / 163.75167° W Submerged Data Mooring Name: XA23-ST-KS02 Water Depth: 80' Top Float Depth: 73' POC: Dr. Manuel Castellote Phone: 206-526-6866 Email: manuel.castellote@noaa.gov	Lat: 66° 46' 53" Lon: -163° 45' 06"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 65.7805° N / 168.568° W Submerged Data Mooring Name: A2-24 Water Depth: 184' Top Float Depth: 49' POC: Rebecca Woodgate Phone: 206-221-3268 Email: woodgate@uw.edu	Lat: 65° 46' 50" Lon: -168° 34' 05"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.434° N / 165.274° W Submerged Data Mooring Name: AL24-AU-UN01b Water Depth: 528' Top Float Depth: 502' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 26' 02" Lon: -165° 16' 26"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 56.6° N / 156.999° W Submerged Data Mooring Name: GA24-AU-SU01 Water Depth: 469' Top Float Depth: 443' POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 36' 00" Lon: -156° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 54.85295° N / 158.99135° W Submerged Data Mooring Name: 23SH-1A Water Depth: 256' Top Float Depth: 203' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 51' 11" Lon: -158° 59' 29"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.9697° N / 146.8812° W Submerged Data Mooring Name: MC Water Depth: 745' Top Float Depth: 671' POC: Mary Anne Bishop Phone: 907-424-5800 x228 Email: mbishop@pwssc.org	Lat: 59° 58' 11" Lon: -146° 52' 52"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.30669° N / 164.75179° W Submerged Data Mooring Name: 25UPP-3A Water Depth: 74 m Top Float Depth: 66 m POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 18' 24" Lon: -164° 45' 06"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-02 To: 2027-05-02 Location: 54.43427° N / 165.2728° W Submerged Data Mooring Name: AL25_AU_UN01 Water Depth: 160 m Top Float Depth: 146 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 54° 26' 03" Lon: -165° 16' 22"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-16 To: 2027-05-16 Location: 53.63045° N / 167.40012° W Submerged Data Mooring Name: AL25_AU_UM01 Water Depth: 89 m Top Float Depth: 82 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 53° 37' 50" Lon: -167° 24' 00"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-05-20 To: 2027-05-20 Location: 57.023° N / 152.999° W Submerged Data Mooring Name: GA24-AU-BT01 Water Depth: 84 m Top Float Depth: 74 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 01' 23" Lon: -152° 59' 56"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2025-09-08 To: 2027-09-08 Location: 71.20405° N / 154.48198° W Name: AL25_AU_PB01 Water Depth: 49 m Top Float Depth: 41 m POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 71° 12' 15" Lon: -154° 28' 55"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SU01 Position: (56.59892, -156.99752) water depth 135 m, top of float at 127 m (recovered GA24_AU_SU01 from same location POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 56° 35' 56" Lon: -156° 59' 51"

Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_BT01 Position: (57.02326, -153.00059) water depth 82 m, top of float at 74 m (recovered GA24_AU_BT01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 01' 24" Lon: -153° 00' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_BT01 Position: (57.02326, -153.00059) water depth 82 m, top of float at 74 m (recovered GA24_AU_BT01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 57° 01' 24" Lon: -153° 00' 02"
Sector Anchorage, Exclusive Economic Zone (EEZ) - Sector Anchorage, Territorial Sea/General/Miscellaneous	Miscellaneous	Submerged Data Mooring Name: GA25_AU_SE01 Position: (58.70259, -152.18696) water depth 129m, top of float at 117 m (recovered GA24_AU_SE01 from same location) POC: Catherine Berchok Phone: 206-526-6331 Email: catherine.berchok@noaa.gov	Lat: 58° 42' 09" Lon: -152° 11' 13"
General/Miscellaneous	Miscellaneous	Submerged Data Mooring 25SH-1A Position: (54.84722, -158.99398) water depth 74m, top of float 60m (recovered 24SH-1A from same location) POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 54° 50' 50" Lon: -158° 59' 38"

Sector Southeast Alaska, Submerged Land Act (SLA)

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Lowrie Island Light	995	DBD DMGD/DAYMK DMGD	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 59.93223° N / 139.60566° W Submerged Data Mooring Name: DB1-24 Water Depth: 754' Top Float Depth: 164' POC: Peter Shipton Phone: 907-224-4319 Email: pshipton@alaska.edu	Lat: 59° 55' 56" Lon: -139° 36' 20"
Sector Southeast Alaska, Submerged Land Act (SLA)/General/Hazards To Navigation/Obstructions	Hazards To Navigation	General/Hazards To Navigation/Obstructions From: 2024-10-17 To: 2026-10-17 Location: 58.12272° N / 136.5934° W Submerged Data Mooring Name: 20CSP-4A Water Depth: 1,099' Top Float Depth: 1,069' POC: David Strausz Phone: 206-526-4510 Email: david.strausz@noaa.gov	Lat: 58° 07' 22" Lon: -136° 35' 36"

Sitka Sound

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Vitskari Island Light	24915	RAC INOP	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sector Southeast Alaska, Submerged Land Act (SLA) - Sitka Sound/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 57.04345° N / 135.20597° W The F/V DRAGON LADY sank in Canoe Cove in this position. The F/V DRAGON LADY is a 76 foot wooden fishing vessel and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 57° 02' 36" Lon: -135° 12' 21"

Stephens Passage

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Hobart Bay Light 2	23595	SS WEAK	FD
Hobart Bay Light 2	23595	DAYMK MISSING	FD
Holkham Bay Buoy 1	23631	Status Unreported	FD
Holkham Bay Buoy 1	23631	Status Unreported	FD
Holkham Bay Buoy 1	23631	MISSING	FD
Holkham Bay Buoy 2	23632	Status Unreported	FD
Holkham Bay Buoy 2	23632	MISSING	FD
Middle Point Light	23785	LT EXT	FD

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION

Frederick Sound - Stephens Passage/General/Miscellaneous	Miscellaneous	General/Miscellaneous From: 2024-10-28 To: 2026-10-28 Location: 58.37614° N / 134.72318° W The U.S. Coast Guard has established a temporary mooring buoy in this location. This mooring buoy has been established for official use and should not be used without authorization from the Coast Guard.	Lat: 58° 22' 34" Lon: -134° 43' 23"
--	---------------	---	-------------------------------------

Sukkwan Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Turn Rock Daybeacon	24415	DBD DMGD/DAYMK MISSING	FD

Sumner Strait

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Five Fathom Shoal Lighted Buoy F	23285	LT EXT	FD

Sweeper Cove

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Sweeper Cove Range Front Light	27542	DAYMK DMGD	FD

Tlevak Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Tlevak Narrows Light 2	24440	DAYMK MISSING	FD

Tongass Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Refuge Cove Daybeacon 3	22270	DAYMK MISSING	FD
Refuge Cove Daybeacon 3	22270	STRUCT DEST	FD

Uganik Bay

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Noisy Island Light	26995	LT EXT	FD
Northeast Arm Light 1	27000	STRUCT DEST	FD

Unalaska Island

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Unalaska Channel Lighted Buoy 5	27470	LT EXT	FD

Valdez Arm

Additional MSI Categories

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Orca Inlet - Valdez Arm/General/Miscellaneous	Miscellaneous	GPS TESTING DETAILS BELOW: 1. Name: AFCAK GPS 25-09 2. Event near: AREA FREQUENCY COORDINATOR, AK 3. GPS: 63-49.05000 N, -145-52.30000 W 4. Date: 22 SEP 2025 – 04 OCT 2025 5. Range @ 50ft AGL/ 104 NM's 6. Time 22 SEP 25 – 4 OCT 25 1600Z-2200Z	Lat: 63° 49' 03" Lon: -145° 52' 18"

Wrangell Narrows

Federal Discrepancies

NAME	LLNR	STATUS	AID TYPE
Wrangell Narrows Daybeacon 10A	22916	VEGETATION	FD
Petersburg Bar Range Front Light	23165	LT EXT	FD

Federal Discrepancies Corrected

NAME	LLNR	STATUS	AID TYPE	CORRECTION DATE
Wrangell Narrows North Entrance Lighted Bell Buoy WN	23210	WATCHING PROPERLY	FD	2025-11-24

Zimovia Strait**Additional MSI Categories**

TITLE	SUBCATEGORY	DESCRIPTION	LOCATION
Sumner Strait - Zimovia Strait/General/Hazards To Navigation/Wrecks	Hazards To Navigation	General/Hazards To Navigation/Wrecks From: 2024-10-25 To: 2026-10-25 Location: 56.19921° N / 132.49282° W The F/V PAMELA RAE LADY sank in Canoe Cove in this position. The F/V PAMELA RAE LADY is a 58 foot seiner and there may be fishing gear or debris attached to or in the vicinity of the vessel. Questions/concerns/updates should be directed to the Coast Guard Sector Southeast Command Center at 907-463-2980.	Lat: 56° 11' 57" Lon: -132° 29' 34"